

492

492: Cat D9T Dozer

Service History

Own Plant

Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
26/05/2012	Scheduled Maintenance	- Carry out 2000hr service, check all screens and filters OK - Install jump start receptacle - Activate Cat Vision Link - Remove and clean out all belly guards - Replace broken RHS door wipers - Replace main engine wiring harness - Clean out battery box a	12860
21/09/2012	Scheduled Maintenance	- Carry out 500hr service	13545
03/12/2012	Scheduled Maintenance	- Carry out 2000hr service - Carry out valve and injector set - Replace undercarriage with genuine Cat includes complete idlers,complete rollers,new sprocket segments and MTO track groups fitted with super extreme service 24" track shoes - Replace all min	13885
06/12/2012	Scheduled Maintenance	- Replace transmission suction hose	13892
13/12/2012	Scheduled Maintenance	- Replace fuel hose to rear of cylinder head	13907
02/04/2013	Scheduled Maintenance	- Carry out 250hr service - Replace broken bolt in handrail	13967
11/04/2013	Scheduled Maintenance	- Remove intercooler for cleaning as it was externally blocked, cleaned core and re-installed at MRM by Kinley Thompson	14001

492

492: Cat D9T Dozer

Service History

Own Plant

Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
24/06/2013	Scheduled Maintenance	- Repair coolant leak	14606
20/08/2013	Scheduled Maintenance	- Carry out 1000hr service - Adjust tracks	15031
17/06/2014	Scheduled Maintenance	- Carry out 500hr service. Service carried out by Impact Mechanical at MRM NT	15561
26/11/2014	Scheduled Maintenance	- Carry out 2000hr service - Replace all main and big end bearings as a precaution. All old bearing in good condition - Replace engine oil pan due to being cracked	16029
30/05/2015	Scheduled Maintenance	- Carry out 500hr service	16295
11/07/2015	Scheduled Maintenance	- Carry out 500hr service - Weld broken hand rail - Replace wiper motor LHS door	16492

492

492: Cat D9T Dozer

Service History

Own Plant

Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
18/07/2015	Scheduled Maintenance	- Replace hydraulic hose from pump to control valve - Reseal engine oil filter housing - Reseal both transmission filter housings - Replace wiper blades on doors	16513
05/12/2015	Scheduled Maintenance	- Carry out 1000hr service - Replace final drive oils	17019
02/02/2016	Scheduled Maintenance	- Reseal RHS blade lift cylinder - Replace corner tips and turn cutting edges	17151
08/03/2016	Scheduled Maintenance	- Carry out 250hr service - Remove transmission and reseal transmission mounting - Replace blade sidearm trunnions and trunnion bearings - Reseal ripper tilt cylinder RHS - Replace work lamp on blade lift cylinder LHS - Weld on wear package to blade and sidearms - Rectify steer motor fault - Weld on wear package to ripper box - Replace broken tag link cover bolts	17266

- Replace lift cylinder mount bearings
- Remove radiator cores and clean thoroughly
- Replace engine door seals
- Replace front and rear wiper motors and blades
- Reseal transmission pump
- Repair pin puller
- Replace cab roof lining
- Repair grease lines on ripper
- Replace centre equalizer pin, bearings and seals
- Reseal engine sump
- Replace radiator cap
- Replace transmission pump drive shaft uni's
- Reseal RHS ripper lift cylinder
- Replace window washer motor
- Replace reverse quacker alarm
- Replace transmission speed sensors and internal harness
- Replace steer motor sensor
- Replace LHS master link bolt
- Replace missing belly guard bolts
- Check sheet and plant photos

492

492: Cat D9T Dozer

Service History

Own Plant

Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
21/05/2016	Scheduled Maintenance	- Carry out 500hr service - Replace rotating beacon	17496
28/05/2016	Scheduled Maintenance	- Replace oil feed line to turbo	17513
12/10/2016	Scheduled Maintenance	- Replace wiper motor LHS door - Repair all work lights - Repair and replace grease lines to ripper - Replace missing hose guard on blade tag link - Replace broken/ missing bolts on hose guards on blade tag link - Secure loose hand rails - Replace missing bolts in engine covers - Install reverse camera - Reseal both ripper tilt cylinders - Service fire suppression - Replace 1 transmission hose to torque convertor - Repair window washers - Checksheet	17861

492

492: Cat D9T Dozer

Service History

Own Plant

Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
18/10/2016	Scheduled Maintenance	- Replace cutting edges and corner tips - Seal rear window - Replace broken wire in fire suppression harness	17894
03/11/2016	Scheduled Maintenance	- Carry out 2000hr service	17987
15/12/2016	Scheduled Maintenance	- Replace muffler and exhaust stack/dust ejector - Replace engine belt and adjuster	18245
02/02/2017	Scheduled Maintenance	- Carry out 500hr service - Reseal RHS ripper tilt cylinder	18494
06/04/2017	Scheduled Maintenance	- Rewire implement lockout solenoid - Replace cutting edges and corner tips - Replace faulty E stop	18849
12/04/2017	Scheduled Maintenance	- Replace broken idler cap bolts LHS rear inner	18865

492

492: Cat D9T Dozer

Service History

Own Plant

Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
17/05/2017	Scheduled Maintenance	- Carry out 2000hr service - Turn pins and bushes in track chains and fit new Cat 24" super extreme track shoes with all new hardware - Repair all non functioning wipers - Replace cab door strikers - Replace #3 injector with Cat Reman - Repair all non functioning work lights - Replace lockable cover for battery isolator - Replace wiper blades - Repair cracks in blade - Reseal both blade tilt cylinders - Reseal RHS ripper tilt cylinder - Replace both accessory drive seals rear of engine - Repair oil leak at sump (loose Bolts) - Replace torque convertor temperature switch - Checksheet	19003

492

492: Cat D9T Dozer

Service History

Own Plant

Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
06/06/2017	Scheduled Maintenance	- Replace hi idle switch - Replace both springs in blade tilt spool	19087
30/06/2017	Scheduled Maintenance	- Replace RHS ripper tilt cylinder with recond' unit supplied by DGI	19103
13/07/2017	Scheduled Maintenance	- Repair A/C - Repair rear window washers - Tighten rear work light - Replace missing bolt in transmission guard - Replace missing belly guard bolts - Replace missing grease lines on ripper - Replace seal on auxiliary drive on rear of engine - Repair oil leak on implement pump - Checksheet/ plant photos	19105
26/07/2017	Scheduled Maintenance	- Replace batteries with genuine Cat	19160
15/11/2017	Scheduled Maintenance	- Replace transmission hose	19263

492

492: Cat D9T Dozer

Service History

Own Plant

Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
18/11/2017	Scheduled Maintenance	- Repair exhaust leak - Repair wiring causing blade tilt fault	19276
25/11/2017	Scheduled Maintenance	- Carry out 250hr service - Replace turbo exhaust outlet pipe and coupling	19315
21/12/2017	Scheduled Maintenance	- Carry out 500hr service - Repair A/C fan	19482
10/05/2018	Scheduled Maintenance	- Carry out 250 hr service - Replace all radiator cores - Replace 2 LED worklights on blade lift cylinder	19741
22/05/2018	Scheduled Maintenance	- Replace bearings, pins and seals in the outer ends of the equalizer bar.	19763

492

492: Cat D9T Dozer

Service History

Own Plant

Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
12/09/2018	Scheduled Maintenance	- Rebuild engine Reman cylinder packs fitted, crankshaft tunnel bore bored back to standard, cylinder block top surface ground and insert under liners fitted (all machining work carried out by HM Gem engines Ingleburn) new crankshaft fitted, all main, big end and thrust bearings fitted back to standard, Reman cylinder head fitted, all oil coolers replace with Cat Reman, Reman oil pump fitted, Reman turbo fitted Reman injectors fitted, all valve and injector rockers replaced with Cat Reman, all bearings replaced in front and rear structure auxilliary drive, Reman water pump fitted, all cam bearings replaced. Engine rebuilt in Robson workshop with Westrac fitter Mark Elliott rebuilding the engine with the help of Robson fitters - Rerace and reseal transmission, bevel gear and torque convertor with all U/S components replace as per Cat reusabilty guide lines - Rerace and reseal both final drives - Rerace and reseal both brake packs - Replace all equalizer bar bearings, pins and seals (including centre) - Repair crack in equalizer bar cross member on chassis - Carry out Mt Arthur spec - Repaint machine in 2 pack - Checksheet	19851
12/09/2018	Scheduled Maintenance	- The following hoses were replaced whilst the engine was removed - 224 4275 hyd' hose 62c249135 - 242 6235 A/C hose 62c249135	19851

- 215 1374 A/C hose 62c249135
- 242 6236 A/C hose 62c249135
- 215 1372 A/C hose 62c249135
- 242 6238 A/C hose 62c249135
- 208 1478 hyd' hose 62c249135
- 208 1540 hyd hose 62c249135
- 208 1539 hyd' hose 62c249135
- 208 1545 hyd' hose 62c249135
- 208 1547 hyd' hose 62c249135
- 226 2499 hyd' hose 62c249135
- 211 5436 hyd' hose 62c249135
- 215 1368 fuel hose 62s732343b
- 215 1369 fuel hose 62s732343c
- 215 1370 fuel hose 62s732343d
- 215 1371 fuel hose 62s732343e
- 228 4176 fuel hose 62s732343a
- 313 9115 hyd' hose 54s013870a
- 026 7752 hyd' hose 62s726587d
- 118 1030 hyd; hose 62s726587b
- 192 1298 hyd' hose 62s726587a

		- 215 1374 A/C hose 62c249135 - 242 6236 A/C hose 62c249135 - 215 1372 A/C hose 62c249135 - 242 6238 A/C hose 62c249135 - 208 1478 hyd' hose 62c249135 - 208 1540 hyd hose 62c249135 - 208 1539 hyd' hose 62c249135 - 208 1545 hyd' hose 62c249135 - 208 1547 hyd' hose 62c249135 - 226 2499 hyd' hose 62c249135 - 211 5436 hyd' hose 62c249135 - 215 1368 fuel hose 62s732343b - 215 1369 fuel hose 62s732343c - 215 1370 fuel hose 62s732343d - 215 1371 fuel hose 62s732343e - 228 4176 fuel hose 62s732343a - 313 9115 hyd' hose 54s013870a - 026 7752 hyd' hose 62s726587d - 118 1030 hyd; hose 62s726587b - 192 1298 hyd' hose 62s726587a	
23/12/2018	Scheduled Maintenance	- Carry out 2000 hr service	20007

492

492: Cat D9T Dozer

Service History

Own Plant

Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
08/04/2019	Scheduled Maintenance	- Carry out 500 hr service	20514
03/06/2019	Scheduled Maintenance	- Replace transmission steering and directional handle - Calibrate transmission fill times - Calibrate blade and ripper solenoids - Calibrate brake touch ups	20801
18/07/2019	Scheduled Maintenance	- Carry out 1000 hr service - Reseal cab including cab pressurizer box - Clean out radiator and coolers - Repair grease line on RHS blade tilt cylinder	20951
07/08/2019	Scheduled Maintenance	- Replace muffler (Mammoth)	21055
21/10/2019	Scheduled Maintenance	- Replace fan compensation valve and adjust to spec'	21321
24/10/2019	Scheduled Maintenance	- Repair air leak at seat compressor	21344
29/11/2019	Scheduled Maintenance	- Carry out 500 hr service	21444

492

492: Cat D9T Dozer

Service History

Own Plant

Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
17/12/2019	Scheduled Maintenance	- Repair corroded E stops, stripped and cleaned	21487
22/01/2020	Scheduled Maintenance	- Replace engine belt and tensioner	21560
28/02/2020	Scheduled Maintenance	- Replace priority valve solenoid - Repair RHS cab door latch	21575
13/03/2020	Scheduled Maintenance	- Replace directional switch in propolsion handle	21594
25/06/2020	Scheduled Maintenance	- Carry out 2000 hr service - Tighten clamp on exhaust side of turbo	21976
16/07/2020	Scheduled Maintenance	- Carry out valve and injector set - Replace cutting edges and corner tips (Cat)	22035
07/08/2020	Scheduled Maintenance	- Replace seat base with new	22097
03/09/2020	Scheduled Maintenance	- Carry out 250 hr service	22228

17/12/2020	Scheduled Maintenance	- Repair ripper grease lines - Adjust movement out of blade - Resecure exhaust lagging - Clean out battery box - Repair E stop on ripper - Repair window washers - Repair wipers - Clean out belly guards - Flush out radiator externally - Straighten rear belly guard - Clean out A/C box, replace evaporator core and dryer. Recharge A/C system - Replace starter isolator - Replace seat base - Replace missing tag link guard - Replace front crankshaft seal - Replace 2 hydraulic pipes on tag link - Replace 4 hydraulic hoses from radiator guard to tag link. Part #'s 1 x 8E9427 Doco' # 62C815375C 1 x 8E9428 Doco' # 62C815375A 1 x 112 2671 Doco' # 62C815375D 1 x 118 8138 Doco' # 62C815375E - Check sheet	22363
------------	-----------------------	--	-------

492

492: Cat D9T Dozer

Service History

Own Plant

Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
04/03/2021	Scheduled Maintenance	- Carry out 500 hr service - Replace rear window - Repair and refit handrails - Reseal RHS blade lift cylinder - Reseal both blade tilt cylinders - Replace missing bolts in blade tag link guards - Repair cracked mountings for fire suppression bottle - Replace mounting rubbers for fuel/ water separator - Repair work lights on blade lift cylinders - Replace hydraulic hose on blade tilt cylinder - Checksheet	22489
17/06/2021	Scheduled Maintenance	- Replace hydraulic fan motor with Cat Reman (Westrac)	22554

492

492: Cat D9T Dozer

Service History

Own Plant

Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
16/07/2021	Scheduled Maintenance	- Replace broken roller cap bolts - Tighten exhaust stack - Repair wiring for work lights - Repair rotating beacon - Repair ripper pin puller	22690
25/08/2021	Scheduled Maintenance	- Repair pin puller mechanism - Repair E stop on ripper - Repair hydraulic oil leak in hell hole - Carry out CTS inspection - Checksheet	22863
15/09/2021	Scheduled Maintenance	- Carry out 1000 hr service (except engine)	22936
24/09/2021	Scheduled Maintenance	- Carry out 250 hr service (Balance of 1000 hr service at 22936 hrs)	22977

492: Cat D9T Dozer

Dozers

Service History

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
07/02/2022	Scheduled Maintenance	- Carry out 500 hr service - Rebuild and line bore idler mounting bores LHS rear bogie - Line bore bearing bores rear of chassis for bottom ripper pins - Replace pins, bearings and seals in ripper - Shim up ripper to eliminate all sideways movement - Reseal LHS ripper lift and tilt cylinders - Weld additional wear package to blade, side arms and access steps - Weld GPS bracket on back of blade - Replace turbo clamp on exhaust side of turbo snail - Fire suppression service (United Safety) - Replace engine belt - Replace torque convertor scavenge hose - Replace transmission cooler hose - Reseal transmission priority valve - Reseal diff steer charge pump hose - Hose part number 205 8369 on Doco'# 62c103686 - Hose part number 135 6414 on Doco"# 62c101464 - Hose part number 205 8367 on Doco'# 62c100645 - Checksheet	23428

492

492: Cat D9T Dozer

Service History

Own Plant

Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
14/05/2022	Scheduled Maintenance	- Replace corner tips and turn cutting edges	23702
20/05/2022	Scheduled Maintenance	- Replace RHS wiper motor - Repair grease lines and grease machine	23737
25/07/2022	Scheduled Maintenance	- Carry out 2000 hr service (Except Engine)	23925
08/09/2022	Scheduled Maintenance	- Carry out 250 hr service	23974
07/11/2022	Scheduled Maintenance	- Repair rear belly guards - Repair grease lines to ripper - Replace E stop on ripper - Repair ripper pin puller - Repair leaking sight glass on radiator - Replace rotating beacon - Replace bearings in radiator guard for blade lift cylinder yokes - Replace ripper shin guard - Replace full exhaust lagging kit - Malabar check sheet	23975

492

492: Cat D9T Dozer

Service History

Own Plant

Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
23/11/2022	Scheduled Maintenance	- Replace batteries with Cat	24049
11/01/2023	Scheduled Maintenance	- Reseal transmission filter housing - Replace cab blower fan - Adjust tracks	24378
23/01/2023	Scheduled Maintenance	- Carry out 500 hr service - Replace sprocket segments with used to prolong track life	24507
01/06/2023	Scheduled Maintenance	- Carry out 1000 hr service - Replace gland O ring on RHS ripper tilt cylinder - Repair/ replace grease hoses on ripper as required - Repair transmission oil filter housing leak - Repair wipers/ washers - Repair all inoperative work lights - Repair E stop on ripper - Repair wiring to A/C compressor - Repair oil leak at bevel gear manifold - Adjust track tension	24993

492
492: Cat D9T Dozer
Service History

Own Plant
Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
23/06/2023	Scheduled Maintenance	- Replace harmonic balancer - Repair guard and mountings under radiator grill	25061
14/07/2023	Scheduled Maintenance	- Replace engine fan - Replace 3 radiator cores - Replace elbow for turbo inlet	25171

492

492: Cat D9T Dozer

Service History

Own Plant

Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
25/08/2023	Scheduled Maintenance	- Replace all undercarriage with genuine Cat. Track groups HDXL with 24"super extreme service shoes fitted - Replace all track guides - Replace all major and minor bogie pins (OFM HD) - Replace radiator guard mounting pins and bearings - Repair guard mounts front bottom of radiator - Replace aftercooler - Repair fuel fast fill - Repair coolant leak - Carry out valve and injector set - Repair ripper pin puller linkages - Repair cracked bogies - Repair cracked battery box - Adjust shims in blade - Replace cutting edges and corner tips - Check sheet	25282
15/09/2023	Scheduled Maintenance	- Replace wiggans fast fuel hose - repaired	25337

492
492: Cat D9T Dozer
Service History

Own Plant
Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
13/10/2023	Scheduled Maintenance	- Replace belt tensioner, idler pulley and engine belt	25452
14/11/2023	Scheduled Maintenance	- Carry out 500 hr service - Replace throttle position sensor	25551
11/12/2023	Scheduled Maintenance	- Replace spring in torque converter outlet valve and adjust to spec	25676
20/12/2023	Scheduled Maintenance	- Replace one radiator core - Refit engine fan the right way (was fitted the wrong way)	25640
19/03/2024	Scheduled Maintenance	- Carry out 2000 hr service	26008
15/10/2024	Scheduled Maintenance	- Carry out 500 hr service - Repair grease lines on ripper	26483

492

492: Cat D9T Dozer

Service History

Own Plant

Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
22/10/2024	Scheduled Maintenance	- Repair grease fittings on ripper - Replace end bits and turn cutting edges - Replace RHS door wiper and shafts - Adjust tracks - Check sheet	26484

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
05/02/2025	Scheduled Maintenance	- Reseal both blade lift cylinders both with Reman rods - Reclaim bearings bores both ends of equalizer bar - Replace bearings and seals both ends of equalizer bar - Replace ripper grease lines ripper bed to chassis - Replace ripper shin guard - Replace LHS track frame pivot shaft seal - Replace forward/reverse switches - Replace fuel hose from filter to back of cylinder head - Carry out 12 monthly fire suppression service - Replace reverse camera - Weld partial skin to blade - Reseal blade tilt cylinder with a new rod (Heathwood) - Replace draft arm knuckles and pins - Replace draft arm bearings - Replace spherical bearing LHS blade tilt cylinder - Adjust all blade joints - Reseal auxillary drive plates on flywheel housing - Replace broken bolts in tag link - Repair side grill on bonnet - Replace rotating beacon - Check sheet	26836

492

492: Cat D9T Dozer

Service History

Own Plant

Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
05/03/2025	Scheduled Maintenance	- Carry out 1000 hr service - Replace 3 ripper grease lines - Adjust both tracks	26980
18/03/2025	Scheduled Maintenance	- Repair coolant leaks at heater hoses - Replace gasket on engine oil cooler pipe - Replace diff steer hydraulic hoses	27034
22/07/2025	Scheduled Maintenance	- Carry out 500 hr service	27497
09/10/2025	Scheduled Maintenance	Replace AM/FM radio and antenna	27725
18/12/2025	Scheduled Maintenance	- Carry out 2000 hr service	27976
30/06/2026	Scheduled Maintenance	- Replace cutting edges and corner tips (Cat)	28249
07/07/2026	Scheduled Maintenance	- Replace turbo coolant tube assemblies	28259

492
492: Cat D9T Dozer
Service History

Own Plant
Dozers

Repair Date	Service Performed	Service Description (incl line details)	Meter Reading
07/10/2026	Scheduled Maintenance	- Repair oil leak at hydraulic cooler - Replace fuel fast fill receiver - Replace engine air filters - Replace cab filters - Replace rotating beacon - Replace fire extinguishers	28250
08/10/2026	Scheduled Maintenance	- Replace batteries	28292