Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
P0292		**Cat 773F Dump Truck**		
	60003	January/February R&M - Replace rear left tyre @ Tyre Doctor - Flat tyre POS 4 - Replace hyd hoses - Replace brake cooling hose - Replace strut bolts - 6 MONTHLY FIRE SUPPRESSION TEST/INSPECTION	13/02/2026	Hours
	59417	December R&M E-stops Re route rubbing hyd hose Engine shutdown system fault Blown transmission hose, Fit transmission hose Fill fluids & check over Replace trans hose Top up engine, trans & hyd oils	16/12/2025	Hours
	59162	November R&M Pump up struts Fit mine tape, pre-start book, fit shruder caps on all struts Speed limit truck, test machine operation and send to work	19/11/2025	Hours
	59092	Tyre CO due to rock caught in duals - side wall cut. Tyre onsite C/O by Marathon. Purchasing - Tyre will need to be added to this job	11/11/2025	Hours
	58665	Pre hire repairs as per inspection, WO 57985	11/11/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
		5 yearly FS service Lake Cowal FFP		
	58079	October R & M Monthly WO USO: Fire suppression tank re-certification. Prep for demob	30/10/2025	Hours
	56655	INTRODUCTION TO SITE - USO	29/10/2025	Hours
	58013	POS 5 tyre damage SWC to be assessed by Marathon Tyres	28/10/2025	Hours
	57467	September R & M - Emergency steer not working 01/09 15130hrs - not shifting gear, found rub through in chassis harness, repair harness and test 17/09/2025 - pos 5 flat 30/09 - Fire supression alarm going off intermitedly. Inspect gas pressure, found broken press switch wire, secondary steering staying on. Carried out diagnostic tests, foud magnetic switch staying open. Remove part from P1206 order new magnetic switch	28/10/2025	Hours
	57985	HME Inspection - Rigid Dump Truck Quote #: 418 15294 hrs	28/10/2025	Hours
	57777	Rigid Dump Truck - 250hr Service 15252hrs	26/09/2025	Hours
	56709	August R&M Monthly: HRS: 15084 Check all rear tyre pressures & Adjust Remove old hand piece and replace for 2 way Repair wire 958 and test Oil leak at hoist pump Park brake fault, repair wire and test Check pos 3 & 4 tyre pressures Repair loss of power to park brake solenoid Adjust pressure on fire system fault, still has fault, united safety to replace pressure switch Carry out greasing & inspection Replace oring on transmission	27/08/2025	Hours
	56507	Rigid Dump Truck - 1000hr Service 14940 hrs - 14988 hrs	4/08/2025	Hours
	56045	July R&M - Electrical fault in wet weather, worked with sparky found rubbed harness 23/07 - Fit new door seal to emergency exit door - Replace radio and aerial, degas and C/O LHS strut - regas, diagnose fault start isolator - Put seals back in main harness and dent wrap	30/07/2025	Hours

Asset	W/O No	Description	Finished	Done Reading	
		- Truck loses prime over night, inspected check valves at filter head, reassembled and primed fuel system - Prime and prestart			
	55457	Rigid Dump Truck - 250hr Service and to do list 14824hrs	2/07/2025	14824	Hours
	55328	June R&M USO - Chase electrical fault, repair corroded electrical components, pin out harness chasing repaired a dead wire - Clean out trans harness plugs from dirt and moisture, deso tape trans plugs - Coasting in nuetral 25km, output speed sensor fault returned. Checked/cleaned all earth/ power supplies. Checked over harness. Got water cart and went along wetting harness. Found fault in plugs going into cab. Damaged seals and corroded pins. Repaired pins. Repaired pins. Denso connectors. Cleaned up - truck back together - Connected new ECM up, had wrong flash file, organise Westrac Mudgee to new flash file and config -Daily grease - Fit ECM. Calibrate trans. road test with operator. - Fit new ECM, trans calibrations, enable hoist hydraulic - sent to work, update hr meter - Headlights not working - found faulty switch swapped with P282and replaced. - Inspect electrical harness connections after machine was washed. Cleaned plug. Test/drive/ sent back to work. - Order parts & organise ECM Repair - Fit new emergency exit door - Replace halogen light with LED - Similar fault to above by the time got to loading fault had cleared. Tested & returned to work - Top up trans oil - trans fault 14811hrs- remove tran harness plug and clean water out and seal best as possible	26/06/2025	14811	Hours
	54971	May R&M USO. Grease, set speed limit and gear Plug AM/FM antenna in Check tyre pressure Unlock 7th and speed limit to 50km/h. Check remaining trucks	31/05/2025		Hours
	54056	Charge front struts. Flip access steps. Protrack completed this work.	30/05/2025		Hours
	52159	Pre-Hire Repairs - HME. Report any additional works to supervisor. USO spec - Dubbo Ward: Remove fuel wiggins receiver and adaptor plate, replace o-ring on adaptor plate, found wiggins locator broken, jump-start, replace pivot center pin and bushes, replace battery, reseal accumulator valve, reseal POS 4 brake cooling hoses, wash for transport, replace R/H side radiator mounts, replace steering column, pivot bolts and bushes, pressed bushes in with old bolts, fit adjusting cylinder cable had come off	17/04/2025	14559	Hours

Asset	W/O No	Description	Finished	Done Reading	
		09/02: Pull exhaust, lagging back to fuel exhaust leak 20/02: Reseal HMU, tested 21/02: Clean seal to HMU, looks to be residual oil weeping, undo all hardware to L/H side exhaust elbow, seized 22/02: Remove L/H side exhaust elbow, had to open flange seized in, fit new elbow, fit clamp, fit wiggins fuel nozzle Dawson: Assist replacing center pivot pin and bushes, assist resealing accumulator valve USO OIL CHARGE OUT. *Finish 14,559hrs - Carry out 12 monthly suppression and fire extinguisher service			
	18415	Jump start machine & check over	25/06/2024		Hours
	11171	Inspection	23/05/2024		Hours
	9896	DE-MOBILISATION / Remove handrails HOURS- 13600	22/04/2024		Hours
	8516	Rigid Dump Truck - 500hr Service	18/01/2024	14390	Hours
	8343	Replace mirror	26/12/2023	14361	Hours
	8012	Tested electrical issue, checking power from key to ECM going through horn start up circuit Tested power from ECM to start solenoid, had power *Found to be faulty start solenoid Wired in new one and tested All ok, refitted all panels	11/12/2023	14290	Hours
	7824	Replace damaged front access step. Check not starting fault. replaced 2 x contacts. check remote start switch ok. checked all E stops ok. checked all fuses ok. Continue with electrical fault. Traced wiring from starter motor to inginition barrel. Low voltage supply to ignition barrel.	10/12/2023	14290	Hours
	7710	Rigid Dump Truck - 250hr Service Clean out window washers Replace engine cover rubber latch	3/12/2023	14272	Hours
	7534	Carry out machine checks as required Check and adjust reverse camera	3/12/2023	14271	Hours
	7130	Replace US steps. Blew out cabin and engine air filters as required, pre-shift	26/11/2023	14255	Hours
	6920	Remove and replace faulty E-stop Check brake light fault. Daily machine inspections	11/11/2023	14227	Hours
	6826	Check over machine, check and clear fault codes Diagnose Engine cutting out issue.	5/11/2023	13763	Hours
	4782	Pre hire repairs	25/08/2023		Hours
	4182	Top up and paint new body pin safety hoops. Fit new hyd tank breather.	12/06/2023		Hours

Asset	W/O No	Description	Finished	Done Reading	
	2056	Wash and clean all rock out of walkway and steps and load mounts rear dump body and park on go-line.	1/06/2023		Hours
	2053	Fit new exhaust elbow, had to cut out broken bolts and refit with nuts and bolts. Remove RH door latch assembly, clean up and reglue door latch to glass and let set. Door has been damaged and repaired at some time and doesn't fit into frame properly. Remove door and drill out mounting holes to allow some adjustment. Refit and adjust as best I could. Fit new brake filter restriction sensors and tidy wiring. Fit new fire extinguishers. Wash machine. Carry out pre-hire checks and do paperwork	31/05/2023		Hours
	2052	Pull apart pos 3 tyre assembly and clean up for tyre fitter to patch puncture. Assist with reassembly and refit to truck	30/05/2023		Hours
	2042	Get fire exits stamped, organise fire suppression works, clean up work areas and pack away tooling	19/05/2023		Hours
	1264	Jump start machine and moving around for labors to wash. Remove battery covers and put batteries on charge over night.	2/05/2023		Hours
	565	Load up strut rod - take to aust chrome to get re-chromed	24/03/2023		Hours
	554	Pack away all tooling and clean up work area. Fit new strut & dog bone bolts. Fit new AM/FM aerial.	23/03/2023	13752	Hours
	553	Continue with A-frame refit. Fit 2 new lift cylinder hoses to control valve. Fit new tranny harnesses and new temp sensor. Refit hyd tank & hoses. Refit RH strut and dog bone and lift off stands. Bleed hyd system and drop tub. Top up hyd oil levels	22/03/2023	13752	Hours
	552	Set up, jack off brakes and pull axle back into position. Fit new pin, bolt and spacer. Loctite bolt and torque to spec. All brake cooling pipes got bent from pin coming out. Reclamp and straighten as best I could so hoses dont rub. Refit all brake cooling hoses and tranny hoses.	21/03/2023	13752	Hours
	551	Modify Aframe nut tool. Tighten nut and fit lock	20/03/2023	13752	Hours
	549	Replace a-frame bearing.	19/03/2023		Hours
	548	Assist boily with machine set up and move for him to work on. Strip down strut to reseal.	18/03/2023		Hours

Service History Report for - P292 Caterpillar 773F Rigid DT

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
25-Sep-22	Shane	14188	$100.00	Inspect oil leak A-frame pin has come out & damaged 2 hoses	
20-Sep-22	Shane	14138	$450.00	Transmisson solenoid faults. Check all harnesses, remove & clean plugs. Found cannon plug into side of tanny loose. Tighten & check. OK.	
19-Sep-22	Shane	14138	$150.00	Electrical faults. Brakes filter plugged, change filter & check, still alive. Bypass sensor. Ok. Order new sensor	
14-Sep-22	Shane		$100.00	Check out electrical faults, brake filter plugged. Check wiring & found exhaust leak	
10-Sep-22	Michael		$250.00	Battery level for battery died charging at 26.6v	
09-Sep-22	Rhys	14110	$350.00	Placed a-frame pin back in fix loose & detached exhaust & found fault with becon short replaced	
08-Sep-22	Michael		$300.00	Finish hydraulic fitter in 1000hr service Check strut heights, check tray signed	
08-Sep-22	Rhys	14110	$700.00	1000hr service	
06-Sep-22	Shane		$100.00	Fit rock ejector	
06-Sep-22	Toddy		$200.00	Replaced rock injector	
29-Aug-22	Shane	14026	$100.00	Fit new lower strut bolt & washers to RHS	
24-Aug-22	Jack	13953	$200.00	Damaged head light	
19-Aug-22	Shane		$200.00	Repair pos 4 tyre	
19-Aug-22	Sean	13903	$150.00	250hr service	
02-Aug-22	Shane	13662	$400.00	Put a frame pin back in Repair bolt	
31-Jul-22	Jack	13639	$165.00	Brake cooling hose A frame pin	
29-Jul-22	Shane		$55.00	A-fraiye pin	
24-Jul-22	Xander	13605	$165.00	500hr service	
24-Jul-22	Sean	13605	$200.00	500hr service	
12-Jul-22	Jack	13494	$200.00	RHR lower strut pin bolt Crake cooling hose	
10-Jul-22	Jack	13473	$100.00	A/C fault	
10-Jul-22	Sean	13473	$100.00	A/C fault	
08-Jul-22	Sean	13439	$150.00	Oil leak	
02-Jul-22	Rhys	13392	$250.00	250hr service	
02-Jul-22	Jack	13392	$250.00	250hr service	
01-Jul-22	Sean	13322	$100.00	Upgrade lights for nightshift	
09-Jun-22	Lain	13270	$165.00	Replaced and refit new flashing light Altered bracket to fit new light Regased A/C system	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
08-Jun-22	Lain	13270	$165.00	Topped up hydraulic tank Fixed leaking hydraulic hose Inspected faulty flashing light Tested A/C	
14-May-22	Alex	13184	$165.00	Drain oil from cooler hose Remove hose Empty drain tubs	
13-May-22	Lain		$82.50	Inspected and diagnosed oil leak on transmission cooler hose	
14-Apr-22	Zumbo		$280.00	On hire paperwork, fill with fuel, removee lift lugs from side hanger boards, fill cab with parts for site.	
14-Apr-22	Lleyton H		$82.50	Remove old stickers and install new.	
13-Apr-22	Seb Zumbo		$308.00	On hire paperwork Fill with fuel Remove lift lugs from side boards Fill cab with parts for site	
12-Apr-22	Connor M		$123.75	Fitted maas stickers to top of tub.	
12-Apr-22	Jim N		$82.50	Peeld off and fitted new stickers	
11-Apr-22	Connor M		$96.25	Cab safety stickers.	
11-Apr-22	Jim N		$55.00	Removed old stickers, installed new ones.	
18-Mar-22	Dave M		$640.00	fit head boards.	
16-Mar-22	Dave M		$520.00	paint sideboards and prep for fitting.	
10-Mar-22	Harry D		$137.50	undercoat hanger board.	
09-Mar-22	Harry D		$536.25	Started to weld them up, cut out 8mm sheets to go on the side put taps on the side to be bolted down and weld them on.	
09-Mar-22	Harry D		$178.75	Finished putting LH steer cylinder in, replaced grease line, fitted rH strut bearing, fitted RH Strut, fitted dog bone, tagged extingushers	
08-Mar-22	Harry D		$522.50	Started to tack one up,cut out steel for other side.	
07-Mar-22	John	13143	$220.00	Fit new transmission hose.	
07-Mar-22	Harry D		$577.50	Weld crack up under cap and crack on back axle. Started to build hnger bracket, cut out all of the steel for one.	
05-Mar-22	Harry D		$206.25	Weld cracks up underneath cab and put a plate over it and welded cracks up on fire bottle.	
04-Mar-22	Harry D		$288.75	Weld up crcks under cab.	
01-Mar-22	John	13143	$275.00	Refit LH tyre rock guard, remove eyebrows, remove steps and LH walkway.	
01-Mar-22	Craig	13193	$27.50	assist with removal of cab access walkway.	
01-Mar-22	Lleyton		$27.50	Install seat covers.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
28-Feb-22	John	13143	$495.00	refit dog bone, secure all grease lines , fill oils, remoe broken bolts from rock guard.	
28-Feb-22	Lleyton		$110.00	grease lines.	
26-Feb-22	Harry		$275.00	Finished putting a frame together Fit finished putting suspension cylindder pins in Put hydraulic tank together	
25-Feb-22	Shane	13143	$123.75	Assist with A Frame bearing install.	
25-Feb-22	John	13143	$385.00	Refit a-frame	
24-Feb-22	Harry		$55.00	Changed reverse camera, found exhaust leak - started to fix leak Fixed exhaust and replace suspension cylinder bearings Get ready to refit a frame	
24-Feb-22	John	13143	$110.00	Fit a-frame bearing	
23-Feb-22	John	13143	$330.00	Remove a-frame bearing	
22-Feb-22	John	13143	$522.50	Fit new ball studs, start to remove A-frame bearing	
22-Feb-22	Harry		$550.00	Fixed front drive cover, removed hoses around a frame Helped John remove dog bone pins Put steer cylinder and tie rod end back together and back in machine Tightened bolts	
21-Feb-22	John	13143	$440.00	250hr service, fit new ball studs	
21-Feb-22	harry		$155.00	Tagged extinguishers, cleaned cab, filled washer bottle, gave John a hand to fit steer cylinders	
17-Feb-22	Zumbo		$88.00	Check over for repairs	
22-Jan-22	John C	13141	$82.50	Demobe	
12-Dec-21	John	13046	$55.00	Adjust mirrors	
12-Dec-21	Jackson	13046	$55.00	Adjust mirrors	
05-Dec-21	J Ciappara	12981	$55.00	Hyd oil	
20-Nov-21	Jackson	12956	$275.00	1000hr service	
20-Nov-21	JohnCiappara	12956	$275.00	1000hr Service	
14-Nov-21	JohnCiappara	12954	$55.00	Fit P Clamps to brake lines Pos 3/4	
22-Oct-21	JohnCiappara	12852	$55.00	Check tyre pressures	
14-Sep-21	Zumbo		$165.00	Rebuild 2 hoist cylinders	
13-Sep-21	John C	12763	$110.00	Repair RH door / glass	
10-Sep-21	John C	12763	$165.00	Mobilise	
09-Sep-21	John C	12763	$110.00	Check over Start to mobilise	
15-Jul-21	Duncan	12608	$137.50	Complete FFP inspection Checked front tyre pressures & pumped up	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
30-Jun-21	A Mills	12558	$165.00	Truck stuck in 1st gear lost sensor wires torn and rubbing.	
30-Jun-21	John C	12556	$137.50	Diagnose trans temp sensor faulty Glue window	
27-Jun-21	John C	12530	$82.50	Repair fire suppression wires	
24-Jun-21	John C	12500	$110.00	Fire suppression	
22-Jun-21	John C	12487	$55.00	Fit new LH mirror	
16-Jun-21	Duncan	12487	$220.00	Complete 500hr Service	
13-Jun-21	John	12481	$82.50	Check tyre pressures	
13-Jun-21	John	12471	$55.00	Reset fire suppression	
10-Jun-21	B Swan	12462	$55.00	FFP checks & repairs	
10-Jun-21	John	12455	$110.00	Finish off RHR strut	
09-Jun-21	B Swan	12455	$165.00	Reseal RHR strut assembly	
09-Jun-21	John	12455	$385.00	Check codes Reseal RHR strut	
01-Jun-21	Duncan S	13317	$55.00	Trim step rubbers and repair step	
25-May-21	John	12332	$55.00	Check codes	
19-May-21	John	12402	$82.50	Weld up under fire sup	
18-May-21	John	12317	$110.00	250hr service Replace blown lights	
14-May-21	B Swan	12290	$165.00	Reseal transline and repair steps.	
29-Apr-21	John	12188	$165.00	Remove hungry boards	
17-Apr-21	John	12118	$27.50	Grease	
13-Apr-21	John	12088	$55.00	Quarterly	
01-Apr-21	John	12006	$27.50	Grease	
01-Apr-21	A Mills	12027	$110.00	Rear strut pin missing nut replace & tighten	
11-Mar-21	John	14133	$82.50	Fit new trans pump drive shaft rubbers	
09-Mar-21	John	11925	$55.00	Fit O-rings to hoist pump hoses Check leaks	
09-Mar-21	A Mills		$82.50	Reseal hoist seal on valve	
06-Mar-21	John	11889	$137.50	Fit new O-ring to hoist pump hose - get out of bog	
22-Feb-21	John	11819	$41.25	Check over Grease	
21-Feb-21	John	11814	$110.00	Remove step Check codes	
18-Feb-21	John	11787	$55.00	Grease - check over	
17-Feb-21	John	11783	$55.00	Check tub sensor	
10-Feb-21	John	11759	$55.00	Grease	
09-Feb-21	A Mills	11755	$82.50	Trans fault test run	
09-Feb-21	John	11755	$55.00	Try to get transmission fault to happen	
08-Feb-21	John		$165.00	Fit new torque converter hose	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
08-Feb-21	A Mills		$275.00	Hose bust from cooler to T/C Collect parts for truck Fit hose to truck	
07-Feb-21	A Mills		$27.50	Grease & check over	
07-Feb-21	John		$27.50	Grease Check over	
05-Feb-21	John	11738	$82.50	Check transmission codes	
05-Feb-21	A Mills	11738	$110.00	Transmission code faults	
05-Feb-21	Brandon B		$96.25	Help fitters	
04-Feb-21	A Mills	12089	$192.50	Replace a/c pump Truck inspect - wheel nuts & track	
04-Feb-21	John	12089	$137.50	Fit new A/C compressor and gas up	
03-Feb-21	A Mills		$247.50	Remove valve on 283 - swap over to 292	
03-Feb-21	John	11727	$82.50	Fit new steering column Test horn	
03-Feb-21	Brandon B-T	11727	$82.50	Assist change retarder valve	
02-Feb-21	John	11727	$123.75	Test horn Remove steering shaft Gas rear struts	
30-Jan-21	John		$55.00	Set up	
27-Jan-21	Ted Van		$82.50	NPM - FFP - Clear actions & defects	
22-Jan-21	Zumbo		$522.50	Burst protection on oil cooling hoses Paint grab rails to cab Decals, hi vis strips Trans calibration P clamp hosing & spiral wrap	
20-Jan-21	Ted Van		$82.50	HV pass out for NPM	
15-Jan-21	Zumbo	11723	$192.50	Fit handrails & repair mount bolt threads	
13-Jan-21	Zumbo	11723	$82.50	Paint tow points Move truck & clean up mess	
12-Jan-21	Zumbo	11723	$82.50	Finish hose clamping & zip tie grease lines & electrical	
12-Jan-21	Lindsay	11723	$82.50	Remove hand rails	
11-Jan-21	Jackson	11723	$165.00	North Parkes FFP, sleeve hosing with burst protection	
11-Jan-21	Lindsay		$261.25	Hydraulic steering Safety decals Terminal covers where needed Paint tow points Take handrails off	
06-Jan-21	Shane	11723	$55.00	Test Fire Supression & remobe bottle for testing	
18-Dec-20	Zumbo		$137.50	Install muffler and exhaust piping	
17-Dec-20	Zumbo		$27.50	Cover missed fuel lines in burst protection	
27-Nov-20	Ryan Morris		$55.00	Pre hire repairs	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
27-Nov-20	Ted Van	11721	$192.50	Replace bottom pin & bearing in LH rear strut Replace headlight switch Replace RH Horn Move out of shed and clean up bay	
26-Nov-20	Ted Van	11721	$605.00	Organise parts Complete 1000hr service, Replace diff & final drive assy. Check & tag fire supression system Check & tag extinguishers Check A/C system - air flow restricted Clean out cab, replace air filters, clean out outside air filter housing Retest system. Ok	
26-Nov-20	Ryan Morris		$192.50	Pre Hire Repairs	
26-Nov-20	Will Paull	11721	$481.25	Reseal & change brake filters & housings Drain t/c Check screen Drive for Ted - 1000hr service Assist	
25-Nov-20	Will Paull	11723	$82.50	Go over with Ted	
25-Nov-20	Ted Van	11721	$110.00	Condition report Diagnose oil leak Check struts	
29-Sep-20	Greg M		$55.00	Carry out engine service.	
07-Jul-20	Greg	11312	$110.00	Carry out service Replace speed sensor	
26-May-20	Greg Mills		$220.00	Carry out 1000hr service.	
01-Apr-20	Greg		$247.50	Diagnose trans fault Speed sensor intermuttant fault	
30-Mar-20	Greg		$110.00	Carry out engine service Fit handrail	
18-Mar-20	Greg	10805	$110.00	Pump up all stints	
15-Mar-20	Duncan	10804	$137.50	Check over for galong Started and ram track Replaces front strip	
03-Dec-19	D Stevens	10766	$130.00	Assist to remove truck from dry bog on stock pile	
02-Dec-19	D Stevens	10783	$65.00	Replace steer pressure sensor Checked steer oil	
19-Oct-19	Jacob	10514	$227.50	250hrs service Greased Machine	
29-Sep-19	Duncan	10408	$137.50	Grease and general check over	
05-Jul-19	Ted	10200	$110.00	Repair lights. Move out of shed. Check speed senser wiring Calibrate transmission.	
05-Jul-19	Harry		$440.00	Finished 1000 HR Service; tyre report, checked for leaks, filled diff and hubs pumped up tires for pre-hire inspection	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
04-Jul-19	Ted	10200	$412.50	Set up for front wheel hub, final drive and diff oil change. Replace missig main mirror and operators manual off spare trucks out the back. Replace cab filters - clean out excessive build up in outside filter. Remove lower cab panels, replace u/s steer column strut, reassemble dash.	
04-Jul-19	Harry	10202	$522.50	Started 1000HR Service; Diff, transmissionh, fuel filters, all screens and filters, hubs.	
03-Jul-19	Ted	10200	$275.00	Condition report, diagnose leaks and organise parts. Start 1000HR Service.	
07-Oct-17	Swanling	9131	$317.00	Fit walkway and eyebrow mirrors	
29-Sep-17	Swanling		$90.75	pump up front struts, fit strut guards	
02-Aug-17	Ted Van	9634	$130.00	Reseal and refit transmission speed sensor assy. Top up trans oil	
01-Aug-17	Ted Van	9634	$325.00	Split transfer case from transmission and reseal. Refit trasnfer case. Fit driveshaft and covers.	
01-Aug-17	j Ciappara	9634	$325.00	Tag Extinguisher. Fit new tranny suction hose. Reseal brake filter housing. Fit new timing sensor.	
31-Jul-17	Ted Van	9634	$325.00	Remove P2 brake caliper, clean up pistons and reseat dust seals, push pinions back, refit caliper with new brake pads.	
31-Jul-17	RLW	9634	$495.00	250hr service	
31-Jul-17	J Ciappara	9634	$162.50	Drain transmission. Remove transmission suction hose.	
27-Jul-17	Dave Oleary	9634	$130.00	Check over and make list	
09-Jan-17	RAM Diesel	9579	$41.00	Check fleet for first day back	
09-Jan-17	RAM Diesel	9384	$247.00	Perform 250hr service Dispose of waste oils & filters	
29-Nov-16	RAM Diesel	9476	$82.00	Travel to machine Fit new boost clamps Replace grease nipples Prime grease gun	
31-Oct-16	RAM Diesel	9271	$495.00	Organise franna, JHA/lift plan Get ladder from workshop Unload tub & assemble machine Charge struts, fit mirrors & wiring harness Perform site inspection & pass out Escort truck to go line	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
27-Oct-16	Brandon Ross	9295	$552.50	Re-sealed starter motor. Tensioned bolts. Brake filter housing has oil leak in hydraulic hose. New one made and fit back to machine. Repaired LH little high beam light. Recharged fire supression. Leaking hydraulic fitting re-sealed and tensioned. Tagged fire extinguishers. Test machine for faults.	
27-Oct-16	acob Seymor	9295	$130.00	Washed	
26-Oct-16	g wykes		$341.05	repairs for hire	
26-Oct-16	Brandon Ross	9295	$666.25	Removed exhaust tip, replaced bolts. Repaired windscreen washer. Applied first aid kit and sticker in cab. Cleaned out cab. Replaced brake pressure switch. Replaced RHS and LHS top lift cylinder bearings and pins. Complete 250hr service. Step was bent so banel beated and replaced broken rubber. Moved machine over to shed. E-stop broken in cab, is now repaired.	
25-Oct-16	g wykes		$383.65	repairs for hire	
25-Oct-16	Jacob Seymor	9095	$130.00	Removed side walk and step out of back tub removed eyebrows willed window wiper fluid. Check all lights	
25-Oct-16	c ford		$56.85	remover stopper	
24-Oct-16	Greg Mills		$162.50	Strip for transport	
23-Sep-16	Greg Mills	9160	$325.00	Carry out transmission service. Fit mirror. Replace hose.	
22-Sep-16	Greg Mills	9160	$130.00	Repair wiper.	
07-Sep-16	Greg Mills	9067	$97.50	Carry out engine service.	
06-Sep-16	Greg Mills	9067	$65.00	Top up a/c	
21-Jul-16	Greg Mills	8792	$35.00	Carry out service, replace leaking trans hose.	
21-Jun-16	A Warren	8569	$71.00	Checkover & grease	
17-May-16	C Ford		$468.00	Weld repairs	
16-May-16	C Ford		$500.00	Weld repairs	
16-May-16	D.Lundholm	8562	$65.00	Remove fuel tank bracket and refit.	
12-May-16	A Warren	8562	$482.00	Complete 500hr service & checkover Straighten guards Removed broken bolts in guards Tapped out threads & secured guards Complete prehire paperwork Replaced tie rod end Greased truck Cleaned up work area	
12-May-16	D.Lundholm	8562	$357.50	New inner tie rod end bearings. Fire extinguisher clean cab. Separate assist wazza repair step tap threads grease	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
11-May-16	D.Lundholm	8562	$471.25	Check for defects. 500hr servcie as manufacture recommends. Replace o-ring on block on top of block. Replace tie rod end bearings. Tag extinguishers. Check all levels. Clean.	
11-May-16	A Warren	8562	$554.00	Check & report defects Replaced two tie rod ends Started 500hr service Replaced transmission sequence oring	
10-May-16	Crank Mechan	8561	$264.00	Remove tyre from POS 3 & fit to P293 POS for watercart	
07-Oct-15	G Wykes		$63.00	Repair tank brackets	
24-Jul-15	Andrew		$35.00	check over for defects.	
28-May-15	Greg Mills	8061	$162.50	finish 1000hr service as per manufacturer recommdendations. Change hyd filters brake filters steer filters trans oil check screens	
19-May-15	Greg Mils	79889	$195.00	Fit new fan belts, fit fan and belt shroud start 1000hr service as manufacturers specifications. Change engine oil, filters, fuel filters, clean cab and cab and air filters	
18-May-15	Greg Mills	7989	$227.50	Travel to narrabri, remove fan shroud and belt shroud. Try to fit new belts, wrong belts supplied.	
20-Apr-15	Greg Mills		$32.50	Pump up front struts	
16-Apr-15	Josh Hewett	7899	$130.00	Wash Machine	
16-Apr-15	Andrew W		$150.00	washed machine. Completed pre hire paperwork. Fitted safety stickers. Topped up oils.	
15-Apr-15	Andrew W		$25.00	organied parts & pressure washer to do repairs & wash machine.	
11-Apr-15	Andrew W		$35.00	complete pre hire site paperwork / checks.	
11-Apr-15	G Wykes		$211.25	Fit hungry boards.	
10-Apr-15	Andrew W		$75.00	fitup hungry boards.	
10-Apr-15	Josh Hewett		$65.00	Fit hungry boards to machine	
09-Apr-15	Josh Hewett	7899	$292.50	Repalce tie rod ends.	
09-Apr-15	Andrew W	7899	$337.50	replaced tie rod ends. Replaced cracked LH mirror.	
05-Dec-14	Greg Mills	7899	$32.50	Straighten LH mudguard	
04-Dec-14	Greg Mills	7899	$65.00	Repair wiring to RH head lights	
03-Dec-14	Greg Mills	7899	$97.50	Replace LH brake pads.	
16-Oct-14	Greg Mills	7899	$32.50	Check over machine	
30-Sep-14	Dave O'Leary	7642	$97.50	remove broken bolt from fire supression bottle mount, fit new mount	
11-Sep-14	Ted Van	7754	$32.50	Check tyres and pressures	
08-Sep-14	Ted Van	7729	$32.50	Tighten bolts on handrail, check fire supression bottle mounts	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
07-Sep-14	Greg Mills	7725	$32.50	Remove wheel chocks and bracket after being damaged	
05-Sep-14	Greg Mills	7690	$32.50	Tighten up RH bumper	
03-Sep-14	Greg Mills	7670	$32.50	Replace UHF from spare machine	
02-Sep-14	Greg mills	7677	$65.00	Repair oil leak at brake filter	
07-Aug-14	Greg Mills		$32.50	Turn RH step upside down and fit chain across handrail.	
21-Jul-14	Greg Mills	7491	$32.50	Repalce step brackets, fit fuse to flashing light wiring.	
17-Jul-14	Ted Van	7490	$227.50	Change engine oil and filters/fuel filters/outer air filters, return and top up engine oil.	
07-Jul-14	Greg Mills	7417	$32.50	Fit flashing light to machine.	
04-Jul-14	G Wykes		$20.00	fab flashing light brackets.	
29-Jun-14	Greg Mills	7379	$65.00	Check e-stops - one pushed in.	
30-May-14	Greg Mills		$97.50	Fit steps and mirrors, gas up struts	
16-May-14	Jono Pittin	7250	$585.00	Refit POS 6 tyre and tension with torque multi and fit eyebrows on tub and cab platform, complete leightons and Maas pre-hire paperwork	
15-May-14	Jono Pittin	7250	$162.50	Jack up and remove POS 6 tyre, top up engine oil.	
15-May-14	Shane	7250	$337.50	Dis-assemble machine ready for Transport.	
13-May-14	Shane	7240	$150.00	Remove belt guards & belts. Remove fan & replace retaining bolt. Re-assemble & fit new bolts.	
06-May-14	Shane	7179	$75.00	Assist with fitting of new tranny hose.	
06-May-14	Greg mills	7179	$260.00	Remove blown hose, go to town and get new one made, travel back to site and fit hose to machine	
05-May-14	Dave O'Leary		$536.25	Travel to burrendong, remove u/s bulldozer control valve to ripper control valve hose, remove 2 x ripper tilt hoses, travel to stevos to get remade, travel back to dam fit hoses, fill oil and test OK.	
02-May-14	Shane		$75.00	fit new relay & refit all covers.	
24-Apr-14	Greg Mills	7176	$357.50	fit mirror, fit bolts into mirror mounts. Fit batteries & new clamp. Fit front handrails. Adjust rear strut heights, fit A-frame retainer bolt. Fit A-frame grease line. Make up fire supression mount out of nylon. Bolt down fire suppression bottle.	
21-Apr-14	Shane		$225.00	fit 2 new front tyres.	
14-Apr-14	Greg Mills	7176	$325.00	Fit all hoses around a-frame and transmission, fit driveshaft, fill oils, start and run - check for leaks and clean up work area.	
10-Apr-14	Greg Mills	7176	$422.50	Fit a-frame to machine	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
06-Apr-14	Shane	7176	$225.00	sling up A-frame ready to lift into position. Fit new bearing. Was tight to go past new thread & burred up tread. Tried to clean up tread but nut locks up after about 3 turns. Remove A-frame & load onto truck to take back to town.	
05-Apr-14	Shane	7176	$225.00	remove A-frame from trailer & drag into position under machine ready to refit to machine.	
01-Apr-14	Shane	7176	$187.50	remoe A-frame from machine & load onto trailer.	
01-Apr-14	Greg Mills	7176	$227.50	Remove a-frame from machine, load onto trailer and strap down, tighten up fire supression mount bolts.	
31-Mar-14	Shane	7176	$300.00	remove bottom strut pins, track rod & brake hoses. Jack off parking brakes & pull axle hosing back as far as we can. Remove old A-frame bearing & found A-frame damaged & A-frame has to be removed. Remove axle cooling hoses & mount bolt ready for removal.	
31-Mar-14	Greg Mills	7176	$260.00	Pull back diff, remove bottom strut pins and track rod.	
30-Mar-14	Greg Mills		$682.50	Remove hoses from a-frame and transmission, remove driveshaft, remove pin from a-frame, set track up ono blocks, let gas out of struts.	
24-Mar-14	Shane		$337.50	fit tyre to pos 6 on truck so we can drive it to w/shop for A-frame repairs. Repair broken steps.	
24-Mar-14	Greg Mills		$130.00	Jack up machine, fit POS 6 wheel, tighten fit new front steps	
11-Mar-14	Shane	7111	$75.00	Replace quickfill breather on fuel tank.	
10-Mar-14	Shane	7100	$75.00	make up new pin for quarter window latch.	
07-Mar-14	Greg Mills	7076	$65.00	Change e-stop, diagnose fault light	
07-Mar-14	shane	7076	$75.00	reports of warning lights coming on. Check over, could not fault.	
23-Feb-14	Shane	6046	$75.00	Replace LH mirror.	
18-Feb-14	Greg Mills	7019	$65.00	Pump up rear struts check over machine	
15-Feb-14	Shane	7007	$150.00	Finish off 1000 hr service.	
13-Feb-14	Shane	6981	$187.50	fit RH rear strut & charge both rear struts.	
12-Feb-14	G Wykes		$422.50	Fit hungry boards.	
12-Feb-14	Andy William	6981	$162.50	1000hr service	
12-Feb-14	Shane	6981	$337.50	Assist with fitting hungry boards & 1000 hr service. Disassemble RH rear strut, found rock damage. Remove strut from P281 in yard.	
11-Feb-14	G Wykes		$89.40	Fab hungry boards.	
10-Feb-14	G Wykes		$81.25	Fab hungry boards.	
07-Feb-14	Greg Mills	6920	$65.00	Repair lights, replace steps	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
07-Feb-14	G Wykes		$30.00	Fab hungry boards.	
06-Feb-14	G Wykes		$75.00	Fab hungry boards.	
05-Feb-14	G Wykes		$90.00	Fab hungry boards.	
04-Feb-14	G Wykes		$95.00	Fab hungry boards	
31-Jan-14	G Wykes		$146.25	Fab hungry boards.	
30-Jan-14	Andy William		$32.50	clean out cab filters	
24-Jan-14	Shane	6795	$75.00	Repair electrical fault at engine shut down switch. Fit new headlights.	
23-Jan-14	G Wykes		$10.00	fab hungry boards.	
22-Jan-14	G Wykes		$30.00	fab hungry boards.	
17-Jan-14	Shane	6735	$112.50	check RHR shock & order seal kit. Pump up RHF shock to level machine.	
17-Jan-14	G Wykes		$81.50	fab hungry boards.	
16-Jan-14	Jono Pittin		$32.50	Replace torn rubber steps	
16-Jan-14	G Wykes		$81.50	fab hungry boards.	
15-Jan-14	G Wykes		$81.50	fab hungry boards.	
14-Jan-14	Ted Van	6703	$65.00	Remove front wiper assy, reconnect separated drive linkage and secure with loctite and refit and test	
14-Jan-14	G Wykes		$81.50	fab hungry boards.	
13-Jan-14	G Wykes		$32.50	Fab hungry boards.	
10-Jan-14	Shane	6658	$115.00	check engine light on. Remote shutdown irregular signeal code. Found remote shutdown switch bracket broken. Weld up & fit new bolts.	
05-Jan-14	Andy William	6627	$227.50	R&R LH rear strut	
04-Jan-14	Andy William	6627	$113.75	Lh head light missing mount bolts, put in new bolts and adjust, clean cab filters.	
03-Jan-14	Andy William	6462	$97.50	Check A/C operation, clean cab filters.	
02-Jan-14	Andy William	6650	$65.00	repalaced LH side step rubbers and brackets	
02-Jan-14	Andy William	6597	$48.75	replaced RH front step rubbers and straighten step	
30-Dec-13	Ted Van	6573	$97.50	Change engine oil and filters, replace batteries.	
30-Dec-13	Jono Pittin	6573	$97.50	Service engine replace batteries	
16-Nov-13	Greg Mills	6351	$130.00	Fit mirror clamps, adjust mirrors, check brake shudder.	
13-Nov-13	Shane	6351	$225.00	fit walkway, rock deflecters, step & gas struts.	
13-Nov-13	Greg Mills	6351	$357.50	Pump up struts, fit walkway/stairs/eyebrows and mudflaps	
12-Nov-13	Ted Van	6351	$455.00	Check over, remove unused monitor cables, repair suspect wiring at transmission, fit sqaurker reverse alarm, change fuel filter to all metal type, repair tub restraint hangers, check segregation.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
12-Nov-13	Steve Grant		$32.50	Stamped rim numbers into rims.	
23-Oct-13	WMS - A		$400.00	load onto float.	
15-Oct-13	WMS - T		$600.00	load on float & wait & load tyres.	
09-Oct-13	WMS - T		$600.00	strip down for transport.	
02-Oct-13	WMS - T		$300.00	repair trans wiring fault.	
03-Sep-13	WMS		$300.00	Carried out 250 hour service.	
20-Aug-13	WMS - Tom	6133	$300.00	250 hr service.	
03-Aug-13	WMS	6030	$100.00	unseized battery isolator switch.	
23-May-13	WMS	5515	$180.00	Finish off 500 hour service.	
19-May-13	WMS		$360.00	250 hour service APS, repair both steps.	
24-Apr-13	WMS	4114	$270.00	Change out A/C belt.	
24-Mar-13	WMS	5296	$300.00	carry out 250 hr service as per service sheet.	
22-Feb-13	WMS		$100.00	top up steer & hyd oil.	
28-Jan-13	WMS	5028	$600.00	carry out 1000 hr service as per service sheet.	
14-Jan-13	Mark Unwin	4973	$71.25	find rock ejector & fit to pos 5/5.	
12-Dec-12	Mark Unwin	4593	$380.00	make up cut grease hoses, both grease manifolds & fit 90o fittings to all tie rod ends. Fit straight fittings to adaptors on relay arm housing. Plumb up system & secure with zip ties.	
12-Dec-12	WMS	4913	$99.00	change out broken step rubbers.	
03-Dec-12	mark unwin	4856	$46.00	LH step & ext's due.	
30-Nov-12	WMS	4830	$450.00	Service as per sheet.	
09-Nov-12	MS		$198.00	finish off 250 hr service & change steer silter.	
06-Nov-12	Mark Unwin	4743	$170.00	Assessed broken mirror, made bracket for LH mirror extracted broken bolt and fitted new bolt to existing bracket.	
02-Nov-12	WMS		$135.00	Machine Inspection	
31-Oct-12	Mark Unwin	4716	$95.00	replace broken brake clamps & fit missing clamps & bolts.	
24-Oct-12	Mark Unwin	4671	$85.00	Tyre report	
25-Sep-12	WMS	4533	$135.00	Tighten up mirror and check over machine.	
20-Sep-12	Mark Unwin	4493	$190.00	finish 250hr service & strut boots.	
19-Sep-12	Mark Unwin	4492	$190.00	250hr service. Fit rear strut covers.	
19-Sep-12	WMS	4492	$225.00	Service machine, replaced damaged step rubbers.	
04-Sep-12	WMS	5070	$95.00	call out - no start, end up finding Estop pressed in.	
21-Aug-12	WMS		$95.00	fit up fast fill kit.	
19-Aug-12	Hast/Deering		$150.00	Cleared codes, updated ECM's, fitted new fuel filters.	
17-Aug-12	Hast/Deering		$525.00	Reflash all ecm's test machine for fault codes all OK.	

Service Date	Tech Name	Service Hrs	Labour $	Service Notes	Next Service Notes
09-Aug-12	wms	4241	$142.50	finish off tidy up of area from day before.	
08-Aug-12	wms	4241	$190.00	Tick & flick sheet, tidy up lost bit of assemble. Clean out cab.	
07-Aug-12	WMS		$95.00	Gas & oil up struts.	
04-Aug-12	WMS		$630.00	Cont with 773F build.	
02-Aug-12	WMS		$270.00	Cont build 773F's ready to hand over.	
01-Aug-12	WMS		$180.00	Fit up walkways and rock deflectors.	
06-Jun-12	WMS		$170.00	Fit up painted hand rails	
05-Jun-12	WMS		$255.00	Prepare hand rails and paint yellow	
04-Jun-12	WMS		$170.00	Fit up camera rear and in cab and cables, fit up air cleaners and safety stickers	
25-May-12	WMS		$680.00	Fit up guards and mudflaps etc, fit up rear wheels & rock ejectors.	
	John	11951	$55.00	Clean tray temp sensor plug	