Service/ repair History DZ08
Current Hours 12085.1

Date	Plant	Fitter/Contractor	Hours	Type Service OR Repai	Job/Invoice #	Workbench PSO	Description
24/07/2026	DZ08	ARB EARTHMOVING	12085	Service			250HR service replace engine oil/filter and fuel filters and check over machine all good 3HR
20/03/2026	DZ08	HMD auto electrical	12028	Repair			remove and replace faulty ac compressor and reciever dryer nitro charge and check for leaks none present vacum and recharge replace cab filters working correctly system all good=3HR
31/01/2026	DZ08	HMD auto electrical		Repair			inspect ac compressor and reciever druyer need replacing replace blower fan
30/09/2025	DZ08	Harley arb	12009	Repair			found ac not working connect guages and found pressure is too high remove covers to condensor fans and found fans were unplugged replug and test found ac is working but blower fan is cutting out test found Faulty blower fanneeds replaCING
9/09/2025	DZ08	Dave newman Machinery	11991	Repair	2978		removed all covers and found blown engine fuse checked codes , unpluged all ecu's andmain plugs in gngine harness checked all plugs checked all wires put back together replaced fuse tested working
15/05/2025	DZ08	Dave newman Machinery	11989	Service			1000HR service check over machine all good replace all filtersengine oil Hydraulic/trans and final drive oils
27/02/2025	DZ08	Hydraulink		Repair	160005092		Travel to site & remove and replace -2 hoses from left hand drive on dozer
25/02/2025	DZ08	Andrews Auto Electrics	11924	Repair	48242		Go to jobsite. Dead short in a/c circuit. Test & disconnect compenents to narrow down short. Remove steel cover on roof to gain access to condensor fans., Right-hand fan shorting internally & drawing too much current. Quote to supply and fit new fan
22/01/2025	DZ08	The maintenance shed	11887	Repair	51453		remove and replace track idlers and wear platres reseal adjusters 6HR labour-$858+gst-wear plates failed worn throuh idler mounting. Have auot electrician come to yard and test air conditioner in dozer check operation presures seemed ok , wash condenser checked vent temps ok, removed cabin filter and cleaned out dust removed side plate and cleaned side filter and wash out evaporator due to dust build up replace thermostat on suspect reassembled and test operation adjusted thermostst , had compressor cycling as it should vent temp 11degrees=$751.82
7/11/2024	DZ08	GC Lester	11789	Repair	22727		DZ08 finish off check list grease service and parts replace 4HR
5/11/2024	DZ08	GC Lester	11789	Repair	22723		DZ08 wash down machine clean out belly plates check tracks idler wearing , wear stripps sent from morisset diag nose air con issue, replace any grease points not taking grease , engine and cab filters coming from hastings, replace bolts engine bay panellscheck track tension 5.5 hr
10/10/2024	DZ08	kristian/lester	11781	Repair	079		Drive to ootann , Diag gfault and repair wiring E stop-Lester 3HR
1/10/2024	DZ08	kristian	11727	Inspection	079		Blow out filters and cab 0.5HR
19/09/2024	DZ08	Tristian	11682	Service			250HR service replace engine oil and filter replace fuel filter and seperatror blow ot air
7/08/2024	DZ08	CG Jayden	11447.3	Service			500HR service replace engne oil and filter r, replace fuel filter and seperators , replace engine primary air filter , replace cabin filter
23/07/2024	DZ08	Kristian	11384	Repair		inv066	7:30-9:00 park brake fault Diag faulty switch
16/02/2024	DZ08	Dave Newman Machinery	11236	Repair	2905		removed floor in cab to find second battery tested -batter y fail removed and replaced with new battery Tested all good 3HR
30/11/2023	DZ08	Pacific steel fabrication	11233	Repair	7837		repairs to Dozer Blade 50mm strips 6 mm thick bisalloy steel fully welded using 5 mm fillet
19/09/2023	DZ08	Dave newman Machinery	11106	Service			1000 HR service flipped cutting edges Blow out Radiator Because hydraulic was
22/07/2023	DZ08	Dave newman Machinery	10837	Service			250Hr service replaced fan Belt exhaust leak at Turbo Manifold-repairs compelte
25/05/2023	DZ08	Jayden/ Ben	10580	repair	2745		remove and replace Hhdraulic hose for lower connection for angling ram RH side back to metal U shaped pipe Ix hose 4x orings 2 hr

14/05/2023	DZ08	Jayden	10560	Service		500HR Service fann belt ordered +air filter secondary +cabin filter
3/04/2023	DZ08	DAVID WGL MECHANICAL	10351.6	Repair	2722	Replaced last pin & bush on Dozer blade at 2312 1 hr
24/03/2023	DZ08	DAVID WGL MECHANICAL	10333	Repair	2725	Replaced pins and Bushes on Dozer blade at Glendale site greased all Bearings 4 hr
14/03/2023	DZ08	Anthony GC	10291	Service		250 HR service oil filter /cab ac filter /outer air filter.. Pins/ Bushes on dozer blade side worn need replacing wet conditions when servicing-- repairs complete
20/01/2023	DZ08	Dave	10000	Repair	2124	Fit NetStar Gps to Dozer 2HR
5/01/2023	DZ08	GC	9998	Repair	2712	undercarriage rebuild replaced all idlers, rollers, carrier rollers, sprocket segments and tracks includes all bolts/nuts 9.5 hr
4/01/2023	DZ08	DAVID WGL MECHANICAL	9967	Service		2000 hr service as per schedule - replace final drive oils
5/12/2022	DZ08	GC	9902.2	Repair	2704	collect parts from JAS/ century-replace alternator and battery,20 amp fuse test for voltage charging 14.8 volts Ben
19/11/2022	DZ08	DAVID WGL MECHANICAL	9795	Service	2118	250HR Service +ac filters tension RH track
10/11/2022	DZ08	Harley Premier mobile welding and	9629.4	Repair		Wear plate on dozer DZ08 removed,
7/11/2022	DZ08	WesTrac	9701	Repair	1670852	Travel to site Inspect machine
4/11/2022	DZ08	DAVID WGL MECHANICAL	9701	Repair	2115	ac bypass heater valve ac working. Fault light on came up checked all levels and for leaks
21/10/2022	DZ08	DAVID WGL MECHANICAL	9638.8	Repair	2112	split tracks replace idlers and wear strips
29/08/2022	DZ08	David	9487	Service	42999	500 hrs Service Adjusted tracks 3 hrs labour