PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No [redacted]	Internal Used Stock No [redacted]	**Invoice Number:** [redacted]
		Invoice Date: 12/16/2025
		Location:
		Work Order Number: [redacted]
		Payment Type: Account
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	Page: 1 of 6

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9560R	5981	1RW9560RECP002773	277778K	

JGL4WD JD ALL Internal
COMPLAINT:
01 4WD TRACTOR VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

CORRECTION:
VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKLIST
****
HOURS: _____5981 HRS_____
TRACTOR DYNOED AT: _____
****
DOES THIS UNIT GET A VALUEMAX STICKER __ YES _X_NO
HAS STICKER BEEN INSTALLED __ YES _Z_ NO
CAB HAS BEEN COMPLETELY CLEANED ___MP/GL___(INITIAL)
THIS UNIT HAS HAD A FINAL CHECKOVER _____CO_____(INITIAL)
THIS UNIT HAS HAD A COMPLETE GREASE JOB ___CO_____(INITIAL)
****
THINGS NOTED BUT NOT REPAIRED ON CUSTOMER'S INSTRUCTIONS:

SEE ATTACHED QUOTE
****
WARRANTY DATES ON REPAIRS COMPLETED:
START: DECEMBER 16, 2025
END: DECEMBER 16, 2026
****



Job Total: $1,875.00

JPWTRNDIAG1 JD ALL Internal
COMPLAINT:
02 REPLACE HEAD BOLTS WITH RUBBER SEALS

CORRECTION:
REPLACED HEAD BOLTS WITH RUBBER SEALS
FLUSHED COOLANT SYSTEM MULTIPLE TIMES WITH RESTORE
TOPPED UP WITH COOLANT

20260258
C02-117

CONTINUED ON NEXT PAGE->
Work order

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2535
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [redacted]	Internal Used Stock No. [redacted]	**Invoice Number:** [redacted]
		Invoice Date: 12/16/2025
		Location: [redacted]
		Work Order Number: [redacted]
		Payment Type: Account
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	Page: 2 of 6

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9560R	5981	1RW9560RECP002773	277778K	

JPWTRNDIAG1 JD ALL Internal

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ128752	GASKET	1.00	31.35	31.35	$31.35	N
PMCC2610X	RESTORE - COOLING SYSTEM FLUSH	1.00	83.88	83.88	$83.88	N
R528578	M10x80 12.9 Flg Bolt	4.00	17.03	17.03	$68.12	N
R528620	Turbo Flange Ring	1.00	122.90	122.90	$122.90	N
R531550	Oil Cooler Gasket	1.00	109.50	109.50	$109.50	N
R531581	Front Rocker Cover Gasket	2.00	90.48	90.48	$180.96	N
R531582	Rear Rocker Cover Gasket	1.00	91.30	91.30	$91.30	N
RE312969	Coolant Filler Cap	1.00	61.91	61.91	$61.91	N
T77613	-6FF O-ring	2.00	3.04	3.04	$6.08	N
T77814	-4FF O-ring	1.00	2.81	2.81	$2.81	N
TY26575	COOL-GARDII 3.78L 50/50 PREMIX	1.00	26.38	26.38	$26.38	N
TY26576	COOL-GARD II 50/50 PRE-MIX JUG 9.46L	6.00	63.12	63.12	$378.72	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF150	ENVIRO FEE	6.00	1.50	1.50	$9.00	N
EF25	ENVIRO FEE	1.00	0.25	0.25	$0.25	N
FRT	FREIGHT	1.00	35.00	35.00	$35.00	N

Labor: $2,474.00 **Parts: $1,163.91** **OL&M: $0.00** **Misc: $44.25** **Sub-Total: $3,682.16**

JUSED4WDWASH Internal
COMPLAINT:
03 WASH USED 4WD TRACTOR. READY FOR DISPLAY.

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No [redacted]

Bus Phone:
Prv Phone:

Internal Used Stock No [redacted]

Bus Phone:
Prv Phone:

Invoice Number: [redacted]
Invoice Date: 12/16/2025
Location: [redacted]
Work Order Number: [redacted]
Payment Type: Account

Page: 3 of 6

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9560R	5981	1RW9560RECP002773	277778K	

JUSED4WDWASH Internal
INCLUDES THE FOLLOWING:
-WASH COMPLETE EXTERIOR.
-VACUUM CAB AND WASH FLOOR MAT.
-WASH ALL CAB INTERIOR SURFACES
-CLEAN WINDOWS

Labor: $1,035.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $1,035.00**

JPWTRNDIAG2 JD ALL Internal
COMPLAINT:
04 DIAGNOSE ENG OIL IN COOLANT

CORRECTION:
DRAINED COOLANT
REMOVED OIL COOLER
PRESSURE TESTED OIL COOLER
OIL COOLER TESTED GOOD
REINSTALLED OIL COOLER WITH NEW GASKET
REMOVED PARTS ON TOP OF ENGINE TO GAIN ACCESS TO VALVE COVERS
REMOVED VALVE COVERS
REMOVED TWO HEAD BOLTS WITH SEALS
SEALS WERE RIPPED
NEED TO REDO HEAD BOLT PIP

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
19M7866	M8x20 FLG 10.9 BOLT	1.00	1.81	1.81	$1.81	N
DZ120878	M16x225 Head Bolt -Rubber Overmold	2.00	266.24	266.24	$532.48	N

Labor: $1,200.00 **Parts: $534.29** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $1,734.29**

JADBULKFUEL JD ALL Internal
COMPLAINT:
05 ADD BULK FUEL TO UNIT.

CORRECTION:

CONTINUED ON NEXT PAGE->>

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [redacted]	Internal Used Stock No. [redacted]	**Invoice Number:** [redacted]
		Invoice Date: 12/16/2025
		Location:
		Work Order Number: [redacted]
		Payment Type: Account
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	Page: 4 of 6

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9560R	5981	1RW9560RECP002773	277778K	

JADBULKFUEL JD ALL Internal
DATE : OCTOBER 8, 2025
LITERS ADDED : 150L
ADDED BY : LUKE MILLER

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
BULKFUEL	BULK FUEL CHARGE	150.00	1.79	1.79	$268.50	N

Labor: $0.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $268.50** **Sub-Total: $268.50**

J01030120 JD 9560R Internal
COMPLAINT:
06 R & R THERMOSTAT

CORRECTION:



CONTINUED ON NEXT PAGE->>

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [redacted]

Bus Phone:
Prv Phone:

Internal Used Stock No. [redacted]

Bus Phone:
Prv Phone:

Invoice Number: [redacted]
Invoice Date: 12/16/2025
Location:
Work Order Number: [redacted]
Payment Type: Account

Page: 5 of 6

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9560R	5981	1RW9560RECP002773	277778K	

J01030120 JD 9560R Internal
DRAINED COOLANT.
REMOVED THERMOSTATS AND GASKETS.
INSTALLED NEW THERMOSTATS AND GASKET.
FILLED WITH COOLANT.
CHECKED OPERATION AND CHECKED FOR LEAKS.
REMOVED INNER GASKETS OF THERMOSTAT AS WELL AND REPLACED ALL 3
WHILE REMOVING EGR PIPE DELTA SENSOR TO MOVE OUT OF WAY OF THERMOSTAT COVER, THE FITTING BROKE OFF INSIDE THE EGR PIPE
TRIED TO HEAT AROUND THE FITTING AND USE AN EXTRACTOR BUT THE REST OF THE FITTING WOULDN'T COME OUT
HAD TO REMOVE EGR PIPE FROM EGR COOLER/ EXHAUST MANIFOLD
ALL THREE BOLTS SNAPPED OFF ON THE EXHAUST MANIFOLD
GOT WELDER AND WELDED NUTS TO THE STUDS TO TRY AND EXTRACT THEM
ONLY ONE BOLT CAME OUT, OTHER TWO STUDS WOULDN'T COME OUT
HAD TO DRILL OTHER TWO STUDS OUT OF THE EXHAUST MANIFOLD AND RE TAP THE THREADS
DRILLED HOLE ALMOST SAME SIZE AS THE THREADS IN THE EGR PIPE AND RE TAPPED THE THREADS
INSTALLED NEW FITTING IN THE EGR PIPE
REINSTALLED THE EGR PIPE TO EGR COOLER/ EXHAUST MANIFOLD WITH NEW HARDWARE
REMOVED COOLANT TUBE FROM THE EGR COOLER AND REPLACED THE O-RING AND GASKET BECAUSE THE O-RINGS LIKELY GOT HEAT TREATED DUE TO ALL OF THE TORCHING
RE INSTALLED COOLANT TUBE ONTO EGR COOLER
INSTALLED NEW O-RINGS ON COOLANT BYPASS TUBE FROM THERMOSTAT HOUSING TO COOLANT PUMP AS WELL BECAUSE THE O-RINGS WERE VERY STRETCHED
REINSTALLED SHIELDS AND RAN MACHINE TO CYCLE THERMOSTATS
MACHINE NOW OPERATES AT ITS PROPER TEMPERATURE
TOPPED UP COOLANT AND RAN MACHINE ONE MORE TIME

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
51M7040	O-RING M12	1.00	4.09	4.09	$4.09	N
R27346	-5mJIC_-2mNPT	1.00	13.67	13.67	$13.67	N
R526831	EGR Gasket -triangle	2.00	21.89	21.89	$43.78	N
R529398	Seal, Thermostat Cover	3.00	35.81	35.81	$107.43	N
R530142	O-Ring	2.00	4.18	4.18	$8.36	N
R531530	Thermostat Gasket	1.00	31.59	31.59	$31.59	N
R532305	O-Ring	1.00	9.95	9.95	$9.95	N

CONTINUED ON NEXT PAGE->>

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [redacted]	Internal Used Stock No. [redacted]	**Invoice Number:** [redacted]
		Invoice Date: 12/16/2025
		Location:
		Work Order Number: [redacted]
		Payment Type: Account
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	Page: 6 of 6

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9560R	5981	1RW9560RECP002773	277778K	

J01030120 JD 9560R Internal

R536559	EGR Coolant Gasket	1.00	38.60	38.60	$38.60	N
R542509	M8x25 Flg SS Bolt	5.00	4.45	4.45	$22.25	N
RE554015	Thermostat	3.00	76.52	76.52	$229.56	N
T77613	-6FF O-ring	1.00	3.04	3.04	$3.04	N

Labor: $2,340.00 **Parts: $512.32** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $2,852.32**

Miscellaneous Charges:
SERVICE ACCESSORIES $150.00

Customer PO No:
Tax Exempt No:
Advisor: KADE TROFIMENKOFF

*** DOCUMENT COPY ***

Job Total: $11,597.27
Grand Total: $11,597.27

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE -- MIN $35 ON EMERGENCY/UNIT DOWN ORDERS -- 25% RESTOCKING FOR RET

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: ..... Date: .....