

PATTISON AGRICULTURE LIMITED  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

Swift Current, SK (306) 773-9351  
Maple Creek, SK (306) 662-2233  
Kindersley, SK (306) 463-2683  
Kyle, SK (306) 375-2302  
Leader, SK (306) 628-3889  
Unity, SK (306) 228-2696  
North Battleford, SK (306) 445-4468  
Humboldt, SK (306) 682-2572  
Kelvington, SK (306) 327-4355  
Shaunavon, SK (306) 297-2639  
Yorkton, SK (306) 783-9459  
Balcarres, SK (306) 334-2492  
Moosomin, SK (306) 435-3301  
Preeceville, SK (306) 547-2007  
Russell, MB (204) 773-2149  
Wynyard, SK (306) 554-2536  
Kamsack, SK (306) 542-2814  
Swan River, MB (204) 734-3466



JOHN DEERE

Invoice To Account No: [REDACTED]

Deliver To:

## SERVICE INVOICE

|                                    |                                    |                               |
|------------------------------------|------------------------------------|-------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | Invoice Number: [REDACTED]    |
| Bus Phone:                         | Bus Phone:                         | Invoice Date: 3/27/2026       |
| Prv Phone:                         | Prv Phone:                         | Location: [REDACTED]          |
|                                    |                                    | Work Order Number: [REDACTED] |
|                                    |                                    | Payment Type: [REDACTED]      |
|                                    |                                    | Page: 1 of 22                 |

|                    |        |                   |        |           |
|--------------------|--------|-------------------|--------|-----------|
| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

EXPERT-1000000321701 Internal

COMPLAINT:

01 X9 SERIES COMBINE VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

CORRECTION:

VALUEMAX GREEN LIGHT SELF PROPELLED COMBINE CHECKLIST

\*\*\*\*\*  
HEADER SERIAL # \_\_\_\_\_  
ENGINE HOURS \_\_\_\_\_ 885 HRS  
SEPARATOR HOURS \_\_\_\_\_ 520 HRS  
\*\*\*\*\*

DOES THIS UNIT GET A VALUEMAX STICKER \_X\_ YES \_\_\_ NO  
HAS THE STICKER BEEN INSTALLED \_X\_ YES \_\_\_ NO  
THIS UNIT HAS HAD THE CAB CLEANED \_\_\_MP/GL\_\_\_\_\_(INITIAL)  
THIS UNIT HAS HAD A FINAL CHECKOVER \_\_\_JF\_\_\_\_\_(INITIAL)  
THIS UNIT HAS HAD A COMPLETE GREASE JOB \_\_\_MM\_\_\_\_\_(INITIAL)  
\*\*\*\*\*

THINGS NOTED BUT NOT REPAIRED ON CUSTOMERS INSTRUCTIONS:

SEE ATTACHED QUOTE

\*\*\*\*\*  
WARRANTY DATES ON REPAIRS COMPLETED:

START DATE: AUGUST 1, 2026

END DATE: AUGUST 1, 2027  
\*\*\*\*\*

Job Total: \$3,963.00

JADBULKFUEL JD ALL Internal

COMPLAINT:

03 ADD BULK FUEL TO UNIT.

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                                     |                                  |
|-------------------------------------|----------------------------------|
| Swift Current, SK (306) 773-9351    | Yorkton, SK (306) 783-9459       |
| Maple Creek, SK (306) 662-2233      | Balcarres, SK (306) 334-2492     |
| Kindersley, SK (306) 463-2683       | Moosomin, SK (306) 435-3301      |
| Kyle, SK (306) 375-2302             | Prescaveville, SK (306) 547-2007 |
| Leader, SK (306) 628-3889           | Russell, MB (204) 773-2149       |
| Unity, SK (306) 228-2696            | Wynyard, SK (306) 554-2536       |
| North Battleford, SK (306) 445-4468 | Kamsack, SK (306) 542-2814       |
| Humboldt, SK (306) 682-2572         | Swan River, MB (204) 734-3466    |
| Kelvington, SK (306) 327-4355       |                                  |
| Shaunavon, SK (306) 297-2639        |                                  |



**JOHN DEERE**

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                    |                                    |                               |
|------------------------------------|------------------------------------|-------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | Invoice Number: [REDACTED]    |
|                                    |                                    | Invoice Date: 3/27/2026       |
|                                    |                                    | Location: [REDACTED]          |
|                                    |                                    | Work Order Number: [REDACTED] |
|                                    |                                    | Payment Type: [REDACTED]      |
| Bus Phone:                         | Bus Phone:                         | Page: 2 of 22                 |
| Prv Phone:                         | Prv Phone:                         |                               |

| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
|--------------------|--------|-------------------|--------|-----------|
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

### JADBULKFUEL JD ALL Internal

#### CORRECTION:

USED SLIP TANK

DATE : FEBRUARY 22, 2026

LITERS ADDED : 25L

ADDED BY : KADE

| Miscellaneous | Description      | Quantity      | List Price   | Net Price     | Extended Price     | Taxed Ind |
|---------------|------------------|---------------|--------------|---------------|--------------------|-----------|
| BULKFUEL      | BULK FUEL CHARGE | 25.00         | 1.79         | 1.79          | \$44.75            | N         |
| Labor: \$0.00 |                  | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$44.75 | Sub-Total: \$44.75 |           |

### JSOFTWARE JD X9 1100 Internal

#### COMPLAINT:

04 UPDATE ALL CONTROLLER SOFTWARE - CRITICAL

#### CORRECTION:

UPDATED ALL REQUIRED SOFTWARE

|                 |               |              |              |                     |
|-----------------|---------------|--------------|--------------|---------------------|
| Labor: \$420.00 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$420.00 |
|-----------------|---------------|--------------|--------------|---------------------|

### J06001040 JD X9 1100 Internal

#### COMPLAINT:

05 REMOVE HALF LINK AND ADJUST FEEDERHOUSE CONVEYOR CHAIN TENSION - CRITICAL

#### CORRECTION:

DETENSIONED CHAIN  
REMOVED JOINER LINK  
REMOVED HALF LINK  
REPEATED FOR ALL 4 CHAINS  
REJOINED CHAIN  
INSTALLED NUTS  
TENSIONED CHAIN TO SPEC  
INSTALLED FRONT COVER

**PATTISON AGRICULTURE LIMITED**

Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459  
Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492  
Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301  
Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007  
Leader, SK (306) 628-3889 Russell, MB (204) 773-2149  
Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536  
North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814  
Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466  
Kelvington, SK (306) 327-4355  
Shaunavon, SK (306) 297-2639

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No: [REDACTED]

Deliver To:

|                                    |                                    |                               |
|------------------------------------|------------------------------------|-------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | Invoice Number: [REDACTED]    |
|                                    |                                    | Invoice Date: 3/27/2026       |
|                                    |                                    | Location: [REDACTED]          |
|                                    |                                    | Work Order Number: [REDACTED] |
|                                    |                                    | Payment Type: [REDACTED]      |
| Bus Phone:                         | Bus Phone:                         | Page: 3 of 22                 |
| Prv Phone:                         | Prv Phone:                         |                               |

| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
|--------------------|--------|-------------------|--------|-----------|
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

**J06001040 JD X9 1100 Internal**

|                 |               |              |              |                     |
|-----------------|---------------|--------------|--------------|---------------------|
| Labor: \$315.00 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$315.00 |
|-----------------|---------------|--------------|--------------|---------------------|

**EXPERT-1000000128273 Internal**

COMPLAINT:

06 REPLACE LATERAL TILT FRAME SEAL - RECOMMENDED

**CORRECTION:**

REMOVED SELF TAPPING SCREW ON LH SIDE  
REMOVED AND REPLACED LATERAL TILT FRAME SEAL ON LH SIDE  
REASSEMBLED IN REVERSE ORDER  
REMOVED SELF TAPPING SCREW ON RH SIDE  
BOTTOM SELF SCREW BRAKE OFF AND STUCK IN BOTTOM TILT FRAME  
BROUGHT WELDER OVER AND WELDED THE NUT TO THE BROKEN SCREW  
TRIED TO REMOVE BUT IT BROKE OFF  
FOUND ANOTHER NUT AND WELDED TO SCREW AND IT AGAIN BROKE OFF  
TRIED 10 TIMES MORE TO WELD DIFFERENT SIZE NUT AND WASHER AND EVERY TIME THEY BROKE OFF  
WELDED WASHER TO BROKEN SCREW  
FOUND M12 NUT AND WELDED TO THE WASHER  
REMOVED BROKEN SCREW  
CLEANED THREADS IN BOTTOM TILT FRAME  
INSTALLED NEW SEAL AND STRAP  
SECURED WITH SELF TAPPING SCREWS AS REQUIRED

| Part Number | Description    | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-------------|----------------|----------|------------|-----------|----------------|-----------|
| 14M7303     | M6-1.0 FLG NUT | 1.00     | 0.86       | 0.86      | \$0.86         | N         |
| 24M7100     | Washer M6.6x22 | 1.00     | 1.06       | 1.06      | \$1.06         | N         |
| 37M7453     | Screw          | 1.00     | 34.47      | 34.47     | \$34.47        | N         |
| HXE154135   | Seal           | 2.00     | 37.61      | 37.61     | \$75.22        | N         |

|                |                 |              |              |                     |
|----------------|-----------------|--------------|--------------|---------------------|
| Labor: \$52.50 | Parts: \$111.61 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$164.11 |
|----------------|-----------------|--------------|--------------|---------------------|

**JGEN05- Internal**

COMPLAINT:

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                                     |                                |
|-------------------------------------|--------------------------------|
| Swift Current, SK (306) 773-9351    | Yorkton, SK (306) 783-9459     |
| Maple Creek, SK (306) 662-2233      | Balcarres, SK (306) 334-2492   |
| Kindersley, SK (306) 463-2683       | Moosomin, SK (306) 435-3301    |
| Kyle, SK (306) 375-2302             | Preeceville, SK (306) 547-2007 |
| Leader, SK (306) 628-3889           | Russell, MB (204) 773-2149     |
| Unity, SK (306) 228-2696            | Wynyard, SK (306) 554-2536     |
| North Battleford, SK (306) 445-4468 | Kamsack, SK (306) 542-2814     |
| Humboldt, SK (306) 682-2572         | Swan River, MB (204) 734-3466  |
| Kelvington, SK (306) 327-4355       |                                |
| Shaunavon, SK (306) 297-2639        |                                |



**JOHN DEERE**

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                    |                                    |                                                                                                                                                                               |
|------------------------------------|------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | <b>Invoice Number:</b> [REDACTED]<br><b>Invoice Date:</b> 3/27/2026<br><b>Location:</b> [REDACTED]<br><b>Work Order Number:</b> [REDACTED]<br><b>Payment Type:</b> [REDACTED] |
| Bus Phone:                         | Bus Phone:                         |                                                                                                                                                                               |
| Prv Phone:                         | Prv Phone:                         |                                                                                                                                                                               |
|                                    |                                    | Page: 4 of 22                                                                                                                                                                 |

| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
|--------------------|--------|-------------------|--------|-----------|
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

**JGEN05- Internal**  
07 REPAIR DRUM WHERE CONVEYOR CHAIN RUNS - CRITICAL  
- 2 DENTS

**CORRECTION:**  
REMOVED FEEDER HOUSE DRIVE CHAIN  
REMOVED CONNECTORS FOR CONVEYOR CHAIN  
WELDED READY ROD TO DENTED SPOTS  
HEATED WITH A TORCH AND PULLED OUT DENT UNIT IT WAS FLUSH  
CUT OFF READY ROD AND WELD ANY LOW SPOTS AN GRINDED THEM FLUSH  
REPEATED FOR ALL DENTS  
RETURNED WELDER AND TORCH BACK TO HOME  
RECONNECTED CONVEYOR CHAIN  
INSTALLED FEEDER HOUSE DRIVE CHAIN TENSIONED CONVEYOR CHAIN

|                        |                      |                         |                     |                            |
|------------------------|----------------------|-------------------------|---------------------|----------------------------|
| <b>Labor: \$840.00</b> | <b>Parts: \$0.00</b> | <b>OL&amp;M: \$0.00</b> | <b>Misc: \$0.00</b> | <b>Sub-Total: \$840.00</b> |
|------------------------|----------------------|-------------------------|---------------------|----------------------------|

**JELECDIAG1 JD ALL Internal**  
**COMPLAINT:**  
08 DIAGNOSE AND REPAIR LEAKING FEED HOSE VALVE BLOCK STEPPER MOTOR - CRITICAL

**CORRECTION:**  
REMOVED VALVE BLOCK AND STEPPER MOTOR  
REMOVED STEPPER MOTOR FROM VALVE BLOCK  
LEAKING FROM STEPPER MOTOR O-RING, ADJUSTMENT KNOB AND ELECTRICAL CONNECTOR  
INSTALLED NEW STEPPER MOTOR TO VALVE BLOCK  
REINSTALLED VALVE BLOCK TO FEEDERHOUSE  
CALIBRATED STEPPER MOTOR  
CHECKED STEPPER MOTOR FOR LEAKS  
NO LEAKS FOUND

| Part Number | Description                | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-------------|----------------------------|----------|------------|-----------|----------------|-----------|
| 19M8851     | M6x12 FLG HEXSOC 10.9 BOLT | 4.00     | 1.61       | 1.61      | \$6.44         | N         |

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459  
Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492  
Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301  
Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007  
Leader, SK (306) 628-3889 Russell, MB (204) 773-2149  
Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536  
North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814  
Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466  
Kelvington, SK (306) 327-4355  
Shaunavon, SK (306) 297-2639



JOHN DEERE

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                    |                                    |                               |
|------------------------------------|------------------------------------|-------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | Invoice Number: [REDACTED]    |
|                                    |                                    | Invoice Date: 3/27/2026       |
|                                    |                                    | Location: [REDACTED]          |
| Bus Phone:                         | Bus Phone:                         | Work Order Number: [REDACTED] |
| Prv Phone:                         | Prv Phone:                         | Payment Type: [REDACTED]      |
|                                    |                                    | Page: 5 of 22                 |

| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
|--------------------|--------|-------------------|--------|-----------|
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

**JELECDIAG1 JD ALL Internal**  
AXE75609 ELEC.PROPO 1.00 1,701.82 1,701.82 \$1,701.82 N

Labor: \$315.00 Parts: \$1,708.26 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$2,023.26

### EXPERT-1000000090242 Internal

#### COMPLAINT:

09 REPLACE MULTICOUPLER SHEAR BOLTS - RECOMMENDED  
- CLEAN OUT DIRT AND DEBRIS FROM HEADER LOCKING PINS

#### CORRECTION:

RAISE FEEDERHOUSE AND ENGAGE CYLINDER STOP.  
UNHOOK CABLE, UNBOLT AND REMOVE HEADER LOCK PINS.  
CLEAN DEBRIS OUT FROM AROUND THE PINS.  
LUBRICATE AND RE-INSTALL PINS, RE-ATTACH CABLE AND ADJUST AS NECESSARY.

| Part Number | Description            | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-------------|------------------------|----------|------------|-----------|----------------|-----------|
| 14M7264     | M4-0.75 NYLOCK NUT     | 2.00     | 0.52       | 0.52      | \$1.04         | N         |
| 19M9326     | M4x30 HEXSOC 12.9 BOLT | 2.00     | 2.08       | 2.08      | \$4.16         | N         |

Labor: \$210.00 Parts: \$5.20 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$215.20

### JGEN08- Internal

#### COMPLAINT:

10 TIGHTEN CLAMP ON MAIN ENGINE GEAR CASE , MAIN HYD. PUMP STACK AND HYD. SYSTEM - RECOMMENDED  
- CLAMPS LOOSE. (4 LEAKING)  
- HYD HOSE RUBBING, ZIP TIES BROKEN.

#### CORRECTION:

TIGHTENED ALL HOSE CLAMPS ON MAIN ENGINE GEARCASE AND PUMP STACK

Labor: \$315.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$315.00

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                                     |                                |
|-------------------------------------|--------------------------------|
| Swift Current, SK (306) 773-9351    | Yorkton, SK (306) 783-9459     |
| Maple Creek, SK (306) 662-2233      | Balcarres, SK (306) 334-2492   |
| Kindersley, SK (306) 463-2683       | Moosomin, SK (306) 435-3301    |
| Kyle, SK (306) 375-2302             | Preeceville, SK (306) 547-2007 |
| Leader, SK (306) 628-3889           | Russell, MB (204) 773-2149     |
| Unity, SK (306) 228-2696            | Wynyard, SK (306) 554-2536     |
| North Battleford, SK (306) 445-4468 | Kamsack, SK (306) 542-2814     |
| Humboldt, SK (306) 682-2572         | Swan River, MB (204) 734-3466  |
| Kelvington, SK (306) 327-4355       |                                |
| Shaunavon, SK (306) 297-2639        |                                |



**JOHN DEERE**

## SERVICE INVOICE

|                                   |                      |               |                      |                            |            |
|-----------------------------------|----------------------|---------------|----------------------|----------------------------|------------|
| Invoice To Account No: [REDACTED] |                      | Deliver To:   |                      | Invoice Number: [REDACTED] |            |
| Internal Used                     | Stock No. [REDACTED] | Internal Used | Stock No. [REDACTED] | Invoice Date:              | 3/27/2026  |
|                                   |                      |               |                      | Location:                  | [REDACTED] |
|                                   |                      |               |                      | Work Order Number:         | [REDACTED] |
|                                   |                      |               |                      | Payment Type:              | [REDACTED] |
| Bus Phone:                        |                      | Bus Phone:    |                      | Page:                      | 6 of 22    |
| Prv Phone:                        |                      | Prv Phone:    |                      |                            |            |
| Make/Model:                       |                      | Meter:        | Serial Number:       | Eq ID:                     | Fleet No:  |
| JOHN DEERE X9 1100                |                      | 885           | 1H0X911XAN0820336    | 100315                     |            |

### JGEN09- Internal

#### COMPLAINT:

11 REPLACE LEAKING O-RING ON TRANS. SCAVENGER PUMP - RECOMMENDED

#### CORRECTION:

REMOVED TRANSMISSION SHIELD  
CLEANED AREA AROUND THE PROPORTIONAL MOTOR  
REMOVED MOTOR CASE DRAIN LINE  
REMOVED SCREW FROM MOTOR  
SEPARATED MOTOR FROM LUBE PUMP  
REMOVED O-RING  
CLEANED ALL MATING SURFACES  
CLEANED MOUNTING CAP SCREWS  
LUBRICATED O-RING AND INSTALL AS REQUIRED  
TIGHTENED MOUNTING CAP SCREWS TO 31 FT/LBS  
REINSTALLED CASE DRAIN LINE AND TIGHT TO SPEC  
REINSTALLED SHIELD  
RAN UNIT AND CHECKED FOR LEAKS  
REPAIR VERIFIED

| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Incl |
|-------------|-------------|----------|------------|-----------|----------------|------------|
| H80821      | O-Ring      | 1.00     | 4.93       | 4.93      | \$4.93         | N          |

|                 |               |              |              |                     |
|-----------------|---------------|--------------|--------------|---------------------|
| Labor: \$315.00 | Parts: \$4.93 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$319.93 |
|-----------------|---------------|--------------|--------------|---------------------|

### EXPERT-1000000136406 Internal

#### COMPLAINT:

12 CLEAN OUT UNLOADING AUGER SUMP - RECOMMENDED

#### CORRECTION:

UNLATCHED UNLOAD AUGER SUMP DOOR AND CLEANED OUT DEBRIS

|                 |               |              |              |                     |
|-----------------|---------------|--------------|--------------|---------------------|
| Labor: \$105.00 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$105.00 |
|-----------------|---------------|--------------|--------------|---------------------|

### JGEN11- Internal

#### COMPLAINT:

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                                     |                                |
|-------------------------------------|--------------------------------|
| Swift Current, SK (306) 773-9351    | Yorkton, SK (306) 783-9459     |
| Maple Creek, SK (306) 662-2233      | Balcarres, SK (306) 334-2492   |
| Kindersley, SK (306) 463-2683       | Moosomin, SK (306) 435-3301    |
| Kyle, SK (306) 375-2302             | Preeceville, SK (306) 547-2007 |
| Leader, SK (306) 628-3889           | Russell, MB (204) 773-2149     |
| Unity, SK (306) 228-2696            | Wynyard, SK (306) 554-2536     |
| North Battleford, SK (306) 445-4468 | Kamsack, SK (306) 542-2814     |
| Humboldt, SK (306) 682-2572         | Swan River, MB (204) 734-3466  |
| Kelvington, SK (306) 327-4355       |                                |
| Shaunavon, SK (306) 297-2639        |                                |



**JOHN DEERE**

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                                                                |                                                                                |                                                                                                                                                                 |
|--------------------------------------------------------------------------------|--------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Internal Used Stock No. [REDACTED]<br><br><br><br><br>Bus Phone:<br>Prv Phone: | Internal Used Stock No. [REDACTED]<br><br><br><br><br>Bus Phone:<br>Prv Phone: | Invoice Number: [REDACTED]<br>Invoice Date: 3/27/2026<br>Location: [REDACTED]<br>Work Order Number: [REDACTED]<br>Payment Type: [REDACTED]<br><br>Page: 7 of 22 |
|--------------------------------------------------------------------------------|--------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|

|                    |        |                   |        |           |
|--------------------|--------|-------------------|--------|-----------|
| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

### JGEN11- Internal

13 STRAIGHTEN BENT CLEANING FAN SAFETY SHIELD - RECOMMENDED  
- CLEANING FAN BLADE HOSE CLAMP LOOSE, LEFT INNER FAN BLADE  
- CLEANING FAN SAFETY SHIELD UNDER THE FAN BENT AND DAMAGED ON LH SIDE

### CORRECTION:

REMOVED CROSS BAR SUPPORT  
REMOVED SHIELDS  
TIGHTENED CLEANING FAN HOSE CLAMP  
STRAIGHTENED TWO MASH SHIELDS AS BEST AS COULD  
REINSTALLED SHIELDS  
REINSTALLED CROSS BAR SUPPORT  
TIGHTENED HARDWARE TO SPEC

|                 |               |              |              |                     |
|-----------------|---------------|--------------|--------------|---------------------|
| Labor: \$210.00 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$210.00 |
|-----------------|---------------|--------------|--------------|---------------------|

### J06180021 JD X9 1100 Internal

#### COMPLAINT:

14 REPAIR CONCAVES ON LHS - 5 CONCAVES - CRITICAL

### CORRECTION:

STRAIGHTENED AND WELDED CRACKS ON CONCAVES  
INSTALLED STIFFENERS INTO CONCAVES

| Part Number       | Description         | Quantity        | List Price   | Net Price    | Extended Price        | Taxed Ind |
|-------------------|---------------------|-----------------|--------------|--------------|-----------------------|-----------|
| 19M7865           | M8x16 FLG 10.9 BOLT | 1.00            | 1.57         | 1.57         | \$1.57                | N         |
| 24M7178           | Washer M10.5x30     | 1.00            | 0.94         | 0.94         | \$0.94                | N         |
| STIFFENER         | CONCAVE STIFFENER   | 190.00          | 0.62         | 0.62         | \$117.80              | N         |
| Labor: \$1,050.00 |                     | Parts: \$120.31 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$1,170.31 |           |

### J06180512 JD X9 1100 Internal

#### COMPLAINT:

15 CONCAVE LEVEL AND ADJUST - CRITICAL

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                                     |                                 |
|-------------------------------------|---------------------------------|
| Swift Current, SK (306) 773-9351    | Yorkton, SK (306) 783-9459      |
| Maple Creek, SK (306) 662-2233      | Balcarres, SK (306) 334-2492    |
| Kindersley, SK (306) 463-2683       | Moosomin, SK (306) 435-3301     |
| Kyle, SK (306) 375-2302             | Prescoveille, SK (306) 547-2007 |
| Leader, SK (306) 628-3889           | Russell, MB (204) 773-2149      |
| Unity, SK (306) 228-2696            | Wynyard, SK (306) 554-2536      |
| North Battleford, SK (306) 445-4468 | Kamsack, SK (306) 542-2814      |
| Humboldt, SK (306) 682-2572         | Swan River, MB (204) 734-3466   |
| Kelvington, SK (306) 327-4355       |                                 |
| Shaunavon, SK (306) 297-2639        |                                 |



**JOHN DEERE**

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                    |                                    |                               |
|------------------------------------|------------------------------------|-------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | Invoice Number: [REDACTED]    |
|                                    |                                    | Invoice Date: 3/27/2026       |
|                                    |                                    | Location: [REDACTED]          |
|                                    |                                    | Work Order Number: [REDACTED] |
|                                    |                                    | Payment Type: [REDACTED]      |
| Bus Phone:                         | Bus Phone:                         | Page: 8 of 22                 |
| Prv Phone:                         | Prv Phone:                         |                               |

|                    |        |                   |        |           |
|--------------------|--------|-------------------|--------|-----------|
| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

**J06180512 JD X9 1100 Internal**

**CORRECTION:**

INSTALLED CONCAVES  
REMOVED SEPARATOR GRATE  
LOOSENED OFF JAM NUTS  
SPUN ROTOR AND TIGHTENED REAR EYE BOLT UNTIL ROTOR MADE A 'TICK NOISE'  
BACKED OFF NUT ONE FULL TURN  
UNTIL ROTOR MADE NO TICK NOISE  
REPEATED PROCESS FOR FRONT EYE BOLT  
TIGHTENED REAR EYE BOLT UNTIL ROTOR MADE TICK NOISE  
BACKED OFF JAM NUT HALF TURN  
REPEATED PROCESS FOR FRONT EYE BOLT  
REPEATED PROCESS FOR RIGHT SIDE CONCAVES  
TIGHTENED JAM NUTS  
CALIBRATED CONCAVES  
SPUN ROTOR TO VERIFY ROTOR NOT HITTING CONCAVES  
REINSTALLED SEPARATOR GRATE

|                 |               |              |              |                     |
|-----------------|---------------|--------------|--------------|---------------------|
| Labor: \$525.00 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$525.00 |
|-----------------|---------------|--------------|--------------|---------------------|

**EXPERT-1000000075500 Internal**

**COMPLAINT:**

16 REPLACE LEFT-HAND CONCAVE ISOLATION CYLINDER BOOT - CRITICAL  
- HYDRAULIC CYLINDER RUBBER BOOT IS TORN FRONT AND REAR  
- PIVOT IS WORN (EYES BOLT), SEAL FELL OUT

**CORRECTION:**

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                                     |                                |
|-------------------------------------|--------------------------------|
| Swift Current, SK (306) 773-9351    | Yorkton, SK (306) 783-9459     |
| Maple Creek, SK (306) 662-2233      | Balcarres, SK (306) 334-2492   |
| Kindersley, SK (306) 463-2683       | Moosomin, SK (306) 435-3301    |
| Kyle, SK (306) 375-2302             | Preeceville, SK (306) 547-2007 |
| Leader, SK (306) 628-3889           | Russell, MB (204) 773-2149     |
| Unity, SK (306) 228-2696            | Wynyard, SK (306) 554-2536     |
| North Battleford, SK (306) 445-4468 | Kamsack, SK (306) 542-2814     |
| Humboldt, SK (306) 682-2572         | Swan River, MB (204) 734-3466  |
| Kelvington, SK (306) 327-4355       |                                |
| Shaunavon, SK (306) 297-2639        |                                |



JOHN DEERE

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                    |                                    |                               |
|------------------------------------|------------------------------------|-------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | Invoice Number: [REDACTED]    |
|                                    |                                    | Invoice Date: 3/27/2026       |
|                                    |                                    | Location: [REDACTED]          |
|                                    |                                    | Work Order Number: [REDACTED] |
|                                    |                                    | Payment Type: [REDACTED]      |
| Bus Phone:                         | Bus Phone:                         | Page: 9 of 22                 |
| Prv Phone:                         | Prv Phone:                         |                               |

| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
|--------------------|--------|-------------------|--------|-----------|
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

### EXPERT-1000000075500 Internal

STARTED ENGINE AND PRESSED THRESHING CLEARANCE ADJUST SWITCH  
ROTATED THE SELECTION DIAL AND SET THRESHING CLEARANCE TO 0  
REMOVED SEPARATOR INSPECTION COVERS FROM BOTH SIDES OF MACHINE  
INSTALLED WOODEN BLOCK TO SUPPORT CONCAVE ASSEMBLY  
REMOVED NUT FROM THE SENSOR ARM  
LOOSENED CLAMPS ON THE RUBBER SEAL  
REMOVED NUTS, CAP SCREWS, AND CYLINDER MOUNT  
REMOVED COTTER PIN AND PIN  
REMOVED HYDRAULIC HOSES AND LIFT THE CYLINDER OUT TOP OF RAIL  
REMOVED AND REPLACED THE CONCAVE ISOLATION CYLINDER BOOT  
INSTALLED IN REVERSE ORDER - TIMES TWO  
REMOVED CYLINDER EYE BOLT AND INSTALLED NEW EYE BOLT

| Part Number     | Description | Quantity        | List Price   | Net Price    | Extended Price      | Taxed Ind |
|-----------------|-------------|-----------------|--------------|--------------|---------------------|-----------|
| AXE82208        | Link End    | 1.00            | 350.96       | 350.96       | \$350.96            | N         |
| HXE158744       | Boot        | 2.00            | 38.07        | 38.07        | \$76.14             | N         |
| Labor: \$157.50 |             | Parts: \$427.10 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$584.60 |           |

### JGEN15- Internal

#### COMPLAINT:

17 FRONT END DRIVE TENSIONER ROD BENT - CRITICAL

#### CORRECTION:

REMOVED OLD TENSIONER ROD  
INSTALLED NEW TENSIONER ROD  
INSTALLED COTTER PIN  
TENSIONED ROD  
REINSTALLED JAM NUTS

| Part Number | Description      | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-------------|------------------|----------|------------|-----------|----------------|-----------|
| 11M7023     | M4x32 COTTER PIN | 1.00     | 0.72       | 0.72      | \$0.72         | N         |
| 14M7275     | M12-1.75 NUT     | 2.00     | 1.73       | 1.73      | \$3.46         | N         |

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                                     |                                |
|-------------------------------------|--------------------------------|
| Swift Current, SK (306) 773-9351    | Yorkton, SK (306) 783-9459     |
| Maple Creek, SK (306) 662-2233      | Balcarres, SK (306) 334-2492   |
| Kindersley, SK (306) 463-2683       | Moosomin, SK (306) 435-3301    |
| Kyla, SK (306) 375-2302             | Preeceville, SK (306) 547-2007 |
| Leader, SK (306) 628-3889           | Russell, MB (204) 773-2149     |
| Unity, SK (306) 228-2696            | Wynyard, SK (306) 554-2536     |
| North Battleford, SK (306) 445-4468 | Kamsack, SK (306) 542-2814     |
| Humboldt, SK (306) 682-2572         | Swan River, MB (204) 734-3466  |
| Kelvington, SK (306) 327-4355       |                                |
| Shaunavon, SK (306) 297-2639        |                                |



**JOHN DEERE**

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                    |                                    |                               |
|------------------------------------|------------------------------------|-------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | Invoice Number: [REDACTED]    |
|                                    |                                    | Invoice Date: 3/27/2026       |
|                                    |                                    | Location: [REDACTED]          |
|                                    |                                    | Work Order Number: [REDACTED] |
|                                    |                                    | Payment Type: [REDACTED]      |
| Bus Phone:                         | Bus Phone:                         | Page: 10 of 22                |
| Prv Phone:                         | Prv Phone:                         |                               |


| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
|--------------------|--------|-------------------|--------|-----------|
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

**JGEN15- Internal**  
AXE88279 Rod 1.00 152.06 152.06 \$152.06 N

**Labor: \$105.00 Parts: \$156.24 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$261.24**

**EXPERT-1000000075561 Internal**  
COMPLAINT:  
18 REPLACE SEPARATOR GRATE - RECOMMENDED

**CORRECTION:**  
REMOVED SEPARATOR COVERS  
REMOVED OUTSIDE SEPARATOR GRATE  
REMOVED MIDDLE SEPARATOR GRATE  
REMOVED INNER SEPARATOR GRATE  
INSTALLED NEW INNER SEPARATOR GRATE  
REINSTALLED MIDDLE SEPARATOR GRATE  
REINSTALLED OUTER SEPARATOR GRATE  
REINSTALLED SEPARATOR COVER



| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-------------|-------------|----------|------------|-----------|----------------|-----------|
| HXE108431   | SEPARATOR   | 1.00     | 377.72     | 377.72    | \$377.72       | N         |

**Labor: \$220.50 Parts: \$377.72 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$598.22**

**EXPERT-1000000291865 Internal**  
COMPLAINT:  
19 TAILINGS ELEVATOR PADDLE CHAIN - CRITICAL

**CORRECTION:**

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                                     |                                |
|-------------------------------------|--------------------------------|
| Swift Current, SK (306) 773-9351    | Yorkton, SK (306) 783-9459     |
| Maple Creek, SK (306) 662-2233      | Balcarres, SK (306) 334-2492   |
| Kindersley, SK (306) 463-2683       | Moosomin, SK (306) 435-3301    |
| Kyle, SK (306) 375-2302             | Preeceville, SK (306) 547-2007 |
| Leader, SK (306) 628-3889           | Russell, MB (204) 773-2149     |
| Unity, SK (306) 228-2696            | Wynyard, SK (306) 554-2536     |
| North Battleford, SK (306) 445-4468 | Kamsack, SK (306) 542-2814     |
| Humboldt, SK (306) 682-2572         | Swan River, MB (204) 734-3466  |
| Kelvington, SK (306) 327-4355       |                                |
| Shaunavon, SK (306) 297-2639        |                                |



JOHN DEERE

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                    |                                    |                               |
|------------------------------------|------------------------------------|-------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | Invoice Number: [REDACTED]    |
|                                    |                                    | Invoice Date: 3/27/2026       |
|                                    |                                    | Location: [REDACTED]          |
| Bus Phone:                         | Bus Phone:                         | Work Order Number: [REDACTED] |
| Prv Phone:                         | Prv Phone:                         | Payment Type: [REDACTED]      |
|                                    |                                    | Page: 11 of 22                |

| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
|--------------------|--------|-------------------|--------|-----------|
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

### EXPERT-1000000291865 Internal

RELEASED THE LATCH AND OPENED THE LOWER DOOR  
REMOVED THE NUTS FROM THE BEARING COVER  
LOOSENED THE NUTS AND USED THEM TO ADJUST THE CHAIN BY MOVING THE BEARING CARRIER DOWNWARD TO  
TIGHTENED THE CHAIN  
ENSURED THE CHAIN IS ADJUSTED PROPERLY BY CHECKING THAT THE LOWER END CAN MOVE SIDE-TO-SIDE ON  
THE SPROCKET BUT CANNOT BE PULLED AWAY FROM IT IF THE CHAIN LOOSENS UP TO 6 MM (1/4 IN) FROM THE  
SPROCKET, READJUST THE CHAIN  
INSTALLED THE BEARING COVER AND SECURED IT WITH NUTS  
CLOSED AND LATCHED THE LOWER DOOR

|                |               |              |              |                    |
|----------------|---------------|--------------|--------------|--------------------|
| Labor: \$52.50 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$52.50 |
|----------------|---------------|--------------|--------------|--------------------|


### JGEN18- Internal

#### COMPLAINT:

20 REPLACE LEAKING CHOPPER GEAR CASE UNION - CRITICAL

#### CORRECTION:

REMOVED LUBE LINE TO CHOPPER UNION  
REMOVED UNION  
LUBED O-RINGS  
INSTALLED NEW UNION  
REINSTALLED LUBE LINE



| Part Number    | Description      | Quantity     | List Price   | Net Price           | Extended Price | Taxed Ind |
|----------------|------------------|--------------|--------------|---------------------|----------------|-----------|
| AH218190       | Hyd Rotary Union | 1.00         | 747.62       | 747.62              | \$747.62       | N         |
| Labor: \$73.50 | Parts: \$747.62  | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$821.12 |                |           |

### JADJCHAFSIEV JD X911 Internal

#### COMPLAINT:

21 FACTORY CALIBRATION OF SIEVE AND CHAFFER - CRITICAL

#### CORRECTION:

PERFORMED FACTORY CALIBRATION AS PER SERVICE ADVISOR

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                                     |                                |
|-------------------------------------|--------------------------------|
| Swift Current, SK (306) 773-9351    | Yorkton, SK (306) 783-9459     |
| Maple Creek, SK (306) 662-2233      | Balcarres, SK (306) 334-2492   |
| Kindersley, SK (306) 463-2683       | Moosomin, SK (306) 435-3301    |
| Kyle, SK (306) 375-2302             | Preeceville, SK (306) 547-2007 |
| Leader, SK (306) 628-3889           | Russell, MB (204) 773-2149     |
| Unity, SK (306) 228-2696            | Wynyard, SK (306) 554-2536     |
| North Battleford, SK (306) 445-4468 | Kamsack, SK (306) 542-2814     |
| Humboldt, SK (306) 682-2572         | Swan River, MB (204) 734-3466  |
| Kelvington, SK (306) 327-4355       |                                |
| Shaunavon, SK (306) 297-2639        |                                |



**JOHN DEERE**

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                    |                                    |                               |
|------------------------------------|------------------------------------|-------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | Invoice Number: [REDACTED]    |
|                                    |                                    | Invoice Date: 3/27/2026       |
|                                    |                                    | Location: [REDACTED]          |
| Bus Phone:                         | Bus Phone:                         | Work Order Number: [REDACTED] |
| Prv Phone:                         | Prv Phone:                         | Payment Type: [REDACTED]      |
|                                    |                                    | Page: 12 of 22                |

| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
|--------------------|--------|-------------------|--------|-----------|
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

**JADJCHAFSIEV JD X911 Internal**

|                 |               |              |              |                     |
|-----------------|---------------|--------------|--------------|---------------------|
| Labor: \$210.00 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$210.00 |
|-----------------|---------------|--------------|--------------|---------------------|

**JGEN20- Internal**

COMPLAINT:

22 ADJUST LOOSE LEFT HAND STEERING STOP - RECOMMENDED

CORRECTION:

REMOVED STOP BOLT

FOUND BENT BOLT

INSTALLED NEW STOP BOLT

| Part Number    | Description         | Quantity     | List Price   | Net Price          | Extended Price | Taxed Ind |
|----------------|---------------------|--------------|--------------|--------------------|----------------|-----------|
| 19M7597        | M20x50 HH 10.9 BOLT | 1.00         | 10.47        | 10.47              | \$10.47        | N         |
| Labor: \$63.00 | Parts: \$10.47      | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$73.47 |                |           |

**EXPERT-1000000335110 Internal**

COMPLAINT:

23 REPLACE VACUUM FAN ISOLATOR - CRITICAL

- VACUUM FAN SEAL SQUISHED, NOT SEALING PROPERLY

CORRECTION:

OPEN RH ENGINE CLEANING FAN ACCESS DOOR.

REMOVE DAMAGED VACUUM FAN SEAL.

INSTALL NEW VACUUM SEAL.

CHECK THE ALIGNMENT OF VACUUM FAN TO PANEL DOOR, ADJUST IF NECESSARY.

CLOSE RH ACCESS DOOR.

| Part Number     | Description    | Quantity     | List Price   | Net Price           | Extended Price | Taxed Ind |
|-----------------|----------------|--------------|--------------|---------------------|----------------|-----------|
| HXE38720        | Weatherstrip   | 1.00         | 92.98        | 92.98               | \$92.98        | N         |
| Labor: \$157.50 | Parts: \$92.98 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$250.48 |                |           |

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                                     |                                |
|-------------------------------------|--------------------------------|
| Swift Current, SK (306) 773-9351    | Yorkton, SK (306) 783-9459     |
| Maple Creek, SK (306) 662-2233      | Balcarres, SK (306) 334-2492   |
| Kindersley, SK (306) 463-2683       | Moosomin, SK (306) 435-3301    |
| Kyle, SK (306) 375-2302             | Preeceville, SK (306) 547-2007 |
| Leader, SK (306) 628-3889           | Russell, MB (204) 773-2149     |
| Unity, SK (306) 228-2696            | Wynyard, SK (306) 554-2536     |
| North Battleford, SK (306) 445-4468 | Kamsack, SK (306) 542-2814     |
| Humboldt, SK (306) 682-2572         | Swan River, MB (204) 734-3466  |
| Kelvington, SK (306) 327-4355       |                                |
| Shaunavon, SK (306) 297-2639        |                                |



**JOHN DEERE**

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                    |                                    |                               |
|------------------------------------|------------------------------------|-------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | Invoice Number: [REDACTED]    |
|                                    |                                    | Invoice Date: 3/27/2026       |
|                                    |                                    | Location: [REDACTED]          |
| Bus Phone:                         | Bus Phone:                         | Work Order Number: [REDACTED] |
| Prv Phone:                         | Prv Phone:                         | Payment Type: [REDACTED]      |
|                                    |                                    | Page: 13 of 22                |

| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
|--------------------|--------|-------------------|--------|-----------|
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

### JGEN22- Internal

#### COMPLAINT:

24 REPLACE MISSING SHOE DRIVE TENSIONER ROD NUT - RECOMMENDED

#### CORRECTION:

INSTALLED NEW JAM NUT  
TENSIONED ROD

| Part Number           | Description  | Quantity             | List Price              | Net Price           | Extended Price            | Taxed Ind |
|-----------------------|--------------|----------------------|-------------------------|---------------------|---------------------------|-----------|
| 14M7275               | M12-1.75 NUT | 1.00                 | 1.73                    | 1.73                | \$1.73                    | N         |
| <b>Labor: \$52.50</b> |              | <b>Parts: \$1.73</b> | <b>OL&amp;M: \$0.00</b> | <b>Misc: \$0.00</b> | <b>Sub-Total: \$54.23</b> |           |

### EXPERT-1000000147071 Internal

#### COMPLAINT:

25 ADJUST CLEAN GRAIN ELEVATOR PADDLE CHAIN - CRITICAL

#### CORRECTION:

LOOSENED OFF CLEAN GRAIN ELEVATOR CHAIN BEARING HOUSING BOLTS SO IT CAN MOVE FREELY  
LOOSENED OFF JAM NUTS ON ADJUSTMENT ROD  
TENSIONED CLEAN GRAIN ELEVATOR CHAIN  
TIGHTENED JAM NUTS  
TIGHTENED BEARING HOUSING BOLTS

|                       |                      |                         |                     |                           |
|-----------------------|----------------------|-------------------------|---------------------|---------------------------|
| <b>Labor: \$52.50</b> | <b>Parts: \$0.00</b> | <b>OL&amp;M: \$0.00</b> | <b>Misc: \$0.00</b> | <b>Sub-Total: \$52.50</b> |
|-----------------------|----------------------|-------------------------|---------------------|---------------------------|

### JGEN24- Internal

#### COMPLAINT:

26 REPLACE O-RING ON FEED ACCELERATOR GEAR CASE PLUG - CRITICAL

#### CORRECTION:

CLEANED AREA AROUND LEVEL PLUG  
REMOVED LEVEL PLUG  
REMOVED AND REPLACED O- RING ON LEVEL PLUG AS REQUIRED  
REINSTALLED LEVEL PLUG AND TIGHTENED TO SPEC  
CLEANED AREA FROM RESIDUE OIL

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                                     |                                |
|-------------------------------------|--------------------------------|
| Swift Current, SK (306) 773-9351    | Yorkton, SK (306) 783-9459     |
| Maple Creek, SK (306) 662-2233      | Balcarres, SK (306) 334-2492   |
| Kindersley, SK (306) 463-2683       | Moosomin, SK (306) 435-3301    |
| Kyle, SK (306) 375-2302             | Preeceville, SK (306) 547-2007 |
| Leader, SK (306) 628-3889           | Russell, MB (204) 773-2149     |
| Unity, SK (306) 228-2696            | Wynyard, SK (306) 554-2536     |
| North Battleford, SK (306) 445-4468 | Kamsack, SK (306) 542-2814     |
| Humboldt, SK (306) 682-2572         | Swan River, MB (204) 734-3466  |
| Kelvington, SK (306) 327-4355       |                                |
| Shaunavon, SK (306) 297-2639        |                                |



**JOHN DEERE**

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                    |                                    |                                                                                                                                                                                                        |
|------------------------------------|------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | <b>Invoice Number:</b> [REDACTED]<br><b>Invoice Date:</b> 3/27/2026<br><b>Location:</b> [REDACTED]<br><b>Work Order Number:</b> [REDACTED]<br><b>Payment Type:</b> [REDACTED]<br><b>Page:</b> 14 of 22 |
| Bus Phone:                         | Bus Phone:                         |                                                                                                                                                                                                        |
| Prv Phone:                         | Prv Phone:                         |                                                                                                                                                                                                        |

| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
|--------------------|--------|-------------------|--------|-----------|
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

### JGEN24- Internal

| Part Number           | Description        | Quantity             | List Price              | Net Price           | Extended Price            | Taxed Ind |
|-----------------------|--------------------|----------------------|-------------------------|---------------------|---------------------------|-----------|
| R26448                | O-Ring -06 HP Orb  | 1.00                 | 2.56                    | 2.56                | \$2.56                    | N         |
| R34557                | Clamp              | -1.00                | 2.70                    | 2.70                | (\$2.70)                  | N         |
| R44302                | Tie Band 8" 100/pk | 5.00                 | 0.54                    | 0.54                | \$2.70                    | N         |
| XCL-9                 | Hose Clamp .50     | 1.00                 | 2.80                    | 2.31                | \$2.31                    | N         |
| <b>Labor: \$52.50</b> |                    | <b>Parts: \$4.87</b> | <b>OL&amp;M: \$0.00</b> | <b>Misc: \$0.00</b> | <b>Sub-Total: \$57.37</b> |           |

### JGEN25- Internal

#### COMPLAINT:

27 TIGHTEN HOSE CLAMPS ON COOLING SYSTEM - RECOMMENDED

#### CORRECTION:

TIGHTENED HOSES ON COOLING PACKAGE

|                        |                      |                         |                     |                            |
|------------------------|----------------------|-------------------------|---------------------|----------------------------|
| <b>Labor: \$105.00</b> | <b>Parts: \$0.00</b> | <b>OL&amp;M: \$0.00</b> | <b>Misc: \$0.00</b> | <b>Sub-Total: \$105.00</b> |
|------------------------|----------------------|-------------------------|---------------------|----------------------------|

### J06030020 JD X9 1100 Internal

#### COMPLAINT:

28 REPLACE ROTARY SCREEN DRIVE BELT

#### CORRECTION:

REMOVED NUT ON FAN DUST BRUSH  
SLID BELT THROUGH DUST BRUSH  
ROUTED BELT  
TENSIONED BELT  
REINSTALLED NUT ONTO FAN DUST BRUSH

| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-------------|-------------|----------|------------|-----------|----------------|-----------|
|-------------|-------------|----------|------------|-----------|----------------|-----------|

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                                     |                                |
|-------------------------------------|--------------------------------|
| Swift Current, SK (306) 773-9351    | Yorkton, SK (306) 783-9459     |
| Maple Creek, SK (306) 662-2233      | Balcarres, SK (306) 334-2492   |
| Kindersley, SK (306) 463-2683       | Moosomin, SK (306) 435-3301    |
| Kyle, SK (306) 375-2302             | Preeceville, SK (306) 547-2007 |
| Leader, SK (306) 628-3889           | Russell, MB (204) 773-2149     |
| Unity, SK (306) 228-2696            | Wynyard, SK (306) 554-2536     |
| North Battleford, SK (306) 445-4468 | Kamsack, SK (306) 542-2814     |
| Humboldt, SK (306) 682-2572         | Swan River, MB (204) 734-3466  |
| Kelvington, SK (306) 327-4355       |                                |
| Shaunavon, SK (306) 297-2639        |                                |



**JOHN DEERE**

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                    |                                    |                                                                                                                                                                                                        |
|------------------------------------|------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | <b>Invoice Number:</b> [REDACTED]<br><b>Invoice Date:</b> 3/27/2026<br><b>Location:</b> [REDACTED]<br><b>Work Order Number:</b> [REDACTED]<br><b>Payment Type:</b> [REDACTED]<br><b>Page:</b> 15 of 22 |
| Bus Phone:                         | Bus Phone:                         |                                                                                                                                                                                                        |
| Prv Phone:                         | Prv Phone:                         |                                                                                                                                                                                                        |

| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
|--------------------|--------|-------------------|--------|-----------|
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

|                                      |                         |                         |                     |                            |           |
|--------------------------------------|-------------------------|-------------------------|---------------------|----------------------------|-----------|
| <b>J06030020 JD X9 1100 Internal</b> |                         |                         |                     |                            |           |
| HXE168680                            | Rotary Screen V-Belt X9 | 1.00                    | 94.60               | 94.60                      | \$94.60 N |
| <b>Labor: \$91.58</b>                | <b>Parts: \$94.60</b>   | <b>OL&amp;M: \$0.00</b> | <b>Misc: \$0.00</b> | <b>Sub-Total: \$186.18</b> |           |

### JGEN27- Internal

#### COMPLAINT:

29 REPLACE MISSING OR DAMAGED LEFT HAND HARNESS LOOM - RECOMMENDED

#### CORRECTION:

CLEANED LOOM FROM DEBRIS  
INSPECTED HARNESS FOR DAMAGE  
REINSTALLED WIRING HARNESS INTO LOOM  
USED ELECTRICAL TAPE AND TAPED LOOM AS NEEDED  
INSTALLED NEW BOLT ON CLAMP  
SECURED WIRING HARNESS WITH BOLT ON CLAMP AND ZIP TIE

| Part Number           | Description          | Quantity                | List Price          | Net Price                 | Extended Price | Taxed Ind |
|-----------------------|----------------------|-------------------------|---------------------|---------------------------|----------------|-----------|
| R34557                | Clamp                | 1.00                    | 3.77                | 3.77                      | \$3.77         | N         |
| <b>Labor: \$63.00</b> | <b>Parts: \$3.77</b> | <b>OL&amp;M: \$0.00</b> | <b>Misc: \$0.00</b> | <b>Sub-Total: \$66.77</b> |                |           |

### JGEN28- Internal

#### COMPLAINT:

30 REPLACE BROKEN AIR DUCT VENT - RECOMMENDED

#### CORRECTION:

REMOVED OLD AIR DUCT VENT  
INSTALLED NEW AIR DUCT VENT

| Part Number           | Description           | Quantity                | List Price          | Net Price                 | Extended Price | Taxed Ind |
|-----------------------|-----------------------|-------------------------|---------------------|---------------------------|----------------|-----------|
| AXE66602              | LOUVER                | 1.00                    | 26.05               | 26.05                     | \$26.05        | N         |
| <b>Labor: \$52.50</b> | <b>Parts: \$26.05</b> | <b>OL&amp;M: \$0.00</b> | <b>Misc: \$0.00</b> | <b>Sub-Total: \$78.55</b> |                |           |

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                                     |                                 |
|-------------------------------------|---------------------------------|
| Swift Current, SK (306) 773-9351    | Yorkton, SK (306) 783-9459      |
| Maple Creek, SK (306) 662-2233      | Balcarres, SK (306) 334-2492    |
| Kindersley, SK (306) 463-2683       | Moosomin, SK (306) 435-3301     |
| Kyle, SK (306) 375-2302             | Preecerville, SK (306) 547-2007 |
| Leader, SK (306) 628-3889           | Russell, MB (204) 773-2149      |
| Unity, SK (306) 228-2696            | Wynyard, SK (306) 554-2536      |
| North Battleford, SK (306) 445-4468 | Kamsack, SK (306) 542-2814      |
| Humboldt, SK (306) 682-2572         | Swan River, MB (204) 734-3466   |
| Kelvington, SK (306) 327-4355       |                                 |
| Shaunavon, SK (306) 297-2639        |                                 |



JOHN DEERE

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                    |                                    |                               |
|------------------------------------|------------------------------------|-------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | Invoice Number: [REDACTED]    |
|                                    |                                    | Invoice Date: 3/27/2026       |
|                                    |                                    | Location: [REDACTED]          |
| Bus Phone:                         | Bus Phone:                         | Work Order Number: [REDACTED] |
| Prv Phone:                         | Prv Phone:                         | Payment Type: [REDACTED]      |
|                                    |                                    | Page: 16 of 22                |

| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
|--------------------|--------|-------------------|--------|-----------|
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

EXPERT-1000000076484 Internal

COMPLAINT:

31 FUEL PRECLEANER FILTER - RECOMMENDED

CORRECTION:

CLOSED THE VALVE ON THE FUEL PRE-CLEANER  
REMOVED THE FUEL PRE-CLEANER FILTER AND CLEANED THE SCREEN  
INSTALLED THE SCREEN AND FUEL PRE-CLEANER FILTER  
OPENED THE VALVE ON THE FUEL PRE-CLEANER TO FILL THE BOWL

|                |               |              |              |                    |
|----------------|---------------|--------------|--------------|--------------------|
| Labor: \$25.00 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$25.00 |
|----------------|---------------|--------------|--------------|--------------------|

JENGAIRFILT JD X9 11 Internal

COMPLAINT:

32 REPLACE PRIMARY AND SECONDARY ENGINE AIR FILTERS

CORRECTION:

REMOVED FILTERS  
CLEANED HOUSING  
INSTALLED PRIMARY/ SECONDARY FILTERS  
MARKED DATE AND HOURS ON FILTERS

| Part Number    | Description               | Quantity        | List Price   | Net Price    | Extended Price      | Taxed Ind |
|----------------|---------------------------|-----------------|--------------|--------------|---------------------|-----------|
| HXE11090       | Primary Engine Air Filter | 1.00            | 461.37       | 461.37       | \$461.37            | N         |
| HXE11091       | Secondary EngAir Filter   | 1.00            | 325.55       | 325.55       | \$325.55            | N         |
| Labor: \$50.00 |                           | Parts: \$786.92 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$836.92 |           |

JENGOILCHNG JD X9 11 Internal

COMPLAINT:

33 REPLACE ENGINE OIL AND FILTER

CORRECTION:

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                                     |                                |
|-------------------------------------|--------------------------------|
| Swift Current, SK (306) 773-9351    | Yorkton, SK (306) 783-9459     |
| Maple Creek, SK (306) 662-2233      | Balcarres, SK (306) 334-2492   |
| Kindersley, SK (306) 463-2683       | Moosomin, SK (306) 435-3301    |
| Kyle, SK (306) 375-2302             | Preeceville, SK (306) 547-2007 |
| Leader, SK (306) 628-3889           | Russell, MB (204) 773-2149     |
| Unity, SK (306) 228-2696            | Wynyard, SK (306) 554-2536     |
| North Battleford, SK (306) 445-4468 | Kamsack, SK (306) 542-2814     |
| Humboldt, SK (306) 682-2572         | Swan River, MB (204) 734-3466  |
| Kelvington, SK (306) 327-4355       |                                |
| Shaunavon, SK (306) 297-2639        |                                |



**JOHN DEERE**

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                                                    |                                                                    |                                                                                                                                                                  |
|--------------------------------------------------------------------|--------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Internal Used Stock No. [REDACTED]<br><br>Bus Phone:<br>Prv Phone: | Internal Used Stock No. [REDACTED]<br><br>Bus Phone:<br>Prv Phone: | Invoice Number: [REDACTED]<br>Invoice Date: 3/27/2026<br>Location: [REDACTED]<br>Work Order Number: [REDACTED]<br>Payment Type: [REDACTED]<br><br>Page: 17 of 22 |
|--------------------------------------------------------------------|--------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------|

| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
|--------------------|--------|-------------------|--------|-----------|
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

**JENGOILCHNG JD X9 11 Internal**  
DRAINED ENGINE OIL  
REMOVED OLD OIL FILTER  
LUBED O-RING  
INSTALLED NEW FILTER  
MARKED FILTER WITH MACHINE HOURS AND DATE  
FILLED ENGINE WITH OIL  
WAITING TO RUN ENGINE  
FEEDER HOUSE VALVE REMOVED AND LINES CAPPED CANNOT START MACHINE  
MARKED HOURS AND DATE ON FILTER

| Part Number            | Description       | Quantity               | List Price              | Net Price           | Extended Price             | Taxed Ind |
|------------------------|-------------------|------------------------|-------------------------|---------------------|----------------------------|-----------|
| RE572785               | ENGINE OIL FILTER | 1.00                   | 137.80                  | 137.80              | \$137.80                   | N         |
| TY26656B               | 15/40 II BULK OIL | 57.00                  | 8.26                    | 8.26                | \$470.82                   | N         |
| Miscellaneous          | Description       | Quantity               | List Price              | Net Price           | Extended Price             | Taxed Ind |
| EF100                  | ENVIRO FEE        | 1.00                   | 1.25                    | 1.25                | \$1.25                     | N         |
| EF15                   | ENVIRO FEE        | 57.00                  | 0.15                    | 0.15                | \$8.55                     | N         |
| <b>Labor: \$125.00</b> |                   | <b>Parts: \$608.62</b> | <b>OL&amp;M: \$0.00</b> | <b>Misc: \$9.80</b> | <b>Sub-Total: \$743.42</b> |           |

**J10030100 JD X9 1100 Internal**  
COMPLAINT:  
34 REPLACE ENGINE FUEL FILTERS.

**CORRECTION:**  
REPLACED PRIMARY AND SECONDARY FUEL FILTERS  
REMOVED AND CLEANED FUEL STRAINER  
BLED FUEL SYSTEM  
FUNCTION AND LEAK CHECKED  
MARKED HOURS AND DATE ON FILTERS

| Part Number   | Description                 | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|---------------|-----------------------------|----------|------------|-----------|----------------|-----------|
| DZ124761      | Primary Fuel Filter 13.6L   | 1.00     | 155.99     | 155.99    | \$155.99       | N         |
| DZ124786      | Secondary Fuel Filter 13.6L | 1.00     | 149.84     | 149.84    | \$149.84       | N         |
| Miscellaneous | Description                 | Quantity | List Price | Net Price | Extended Price | Taxed Ind |

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                                     |                                 |
|-------------------------------------|---------------------------------|
| Swift Current, SK (306) 773-9351    | Yorkton, SK (306) 783-9459      |
| Maple Creek, SK (306) 662-2233      | Balcarres, SK (306) 334-2492    |
| Kindersley, SK (306) 463-2683       | Moosomin, SK (306) 435-3301     |
| Kyle, SK (306) 375-2302             | Preecerville, SK (306) 547-2007 |
| Leader, SK (306) 628-3889           | Russell, MB (204) 773-2149      |
| Unity, SK (306) 228-2696            | Wynyard, SK (306) 554-2536      |
| North Battleford, SK (306) 445-4468 | Kamsack, SK (306) 542-2814      |
| Humboldt, SK (306) 682-2572         | Swan River, MB (204) 734-3466   |
| Kelvington, SK (306) 327-4355       |                                 |
| Shaunavon, SK (306) 297-2639        |                                 |



**JOHN DEERE**

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                    |                                    |                               |
|------------------------------------|------------------------------------|-------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | Invoice Number: [REDACTED]    |
| Bus Phone:                         | Bus Phone:                         | Invoice Date: 3/27/2026       |
| Prv Phone:                         | Prv Phone:                         | Location: [REDACTED]          |
|                                    |                                    | Work Order Number: [REDACTED] |
|                                    |                                    | Payment Type: [REDACTED]      |
|                                    |                                    | Page: 18 of 22                |

| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
|--------------------|--------|-------------------|--------|-----------|
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

J10030100 JD X9 1100 Internal  
EF100 ENVIRO FEE 2.00 1.25 1.25 \$2.50 N

Labor: \$80.00 Parts: \$305.83 OL&M: \$0.00 Misc: \$2.50 Sub-Total: \$388.33

J06070005 JD X9 1100 Internal  
COMPLAINT:  
35 REPLACE TRANSMISSION FILTER

CORRECTION:  
REMOVED OLD FILTER  
REMOVED OLD CRUSH WASHER  
INSTALLED NEW CRUSH WASHER  
INSTALLED NEW FILTER  
MARKED HOURS AND DATE ON FILTER  
RAN CHECKED FOR LEAKS  
NO LEAKS

| Part Number | Description          | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-------------|----------------------|----------|------------|-----------|----------------|-----------|
| R567277     | RING                 | 1.00     | 13.65      | 13.65     | \$13.65        | N         |
| RE577250    | Hydraulic Oil Filter | 1.00     | 152.64     | 152.64    | \$152.64       | N         |

Labor: \$45.00 Parts: \$166.29 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$211.29

JCABFILTER JD X9 11 Internal  
COMPLAINT:  
36 REPLACE CAB AIR FILTERS

CORRECTION:  
REMOVED CAB AIR FILTERS  
CLEANED FILTER HOUSING  
INSTALLED NEW AIR FILTERS

| Part Number | Description           | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-------------|-----------------------|----------|------------|-----------|----------------|-----------|
| AXE70605    | Cab Recirc Air Filter | 1.00     | 40.66      | 40.66     | \$40.66        | N         |

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                                     |                                |
|-------------------------------------|--------------------------------|
| Swift Current, SK (306) 773-9351    | Yorkton, SK (306) 783-9459     |
| Maple Creek, SK (306) 662-2233      | Balcarres, SK (306) 334-2492   |
| Kindersley, SK (306) 463-2683       | Moosomin, SK (306) 435-3301    |
| Kyle, SK (306) 375-2302             | Preeceville, SK (306) 547-2007 |
| Leader, SK (306) 628-3889           | Russell, MB (204) 773-2149     |
| Unity, SK (306) 228-2696            | Wynyard, SK (306) 554-2536     |
| North Battleford, SK (306) 445-4468 | Kamsack, SK (306) 542-2814     |
| Humboldt, SK (306) 682-2572         | Swan River, MB (204) 734-3466  |
| Kelvington, SK (306) 327-4355       |                                |
| Shaunavon, SK (306) 297-2639        |                                |



**JOHN DEERE**

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                    |                                    |                               |
|------------------------------------|------------------------------------|-------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | Invoice Number: [REDACTED]    |
|                                    |                                    | Invoice Date: 3/27/2026       |
|                                    |                                    | Location: [REDACTED]          |
|                                    |                                    | Work Order Number: [REDACTED] |
|                                    |                                    | Payment Type: [REDACTED]      |
| Bus Phone:                         | Bus Phone:                         | Page: 19 of 22                |
| Prv Phone:                         | Prv Phone:                         |                               |

| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
|--------------------|--------|-------------------|--------|-----------|
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

|                              |                     |      |        |        |          |   |
|------------------------------|---------------------|------|--------|--------|----------|---|
| JCABFILTER JD X9 11 Internal |                     |      |        |        |          |   |
| TA32591                      | Cab FreshAir Filter | 1.00 | 121.63 | 121.63 | \$121.63 | N |

Labor: \$50.00      Parts: \$162.29      OL&M: \$0.00      Misc: \$0.00      Sub-Total: \$212.29

### JGEN36- Internal

#### COMPLAINT:

37 REPLACE DAMAGED LATERAL TILT HARNESS CONNECTOR - RECOMMENDED

#### CORRECTION:

DISSEMBLED CONNECTOR  
REMOVED PINS FROM CONNECTOR  
REPINNED IN NEW CONNECTOR  
ASSEMBLED CONNECTOR AGAIN

| Part Number   | Description                | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|---------------|----------------------------|----------|------------|-----------|----------------|-----------|
| 57M9786       | Housing 6pin.Male Red Tyco | 1.00     | 11.39      | 11.39     | \$11.39        | N         |
| Miscellaneous | Description                | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
| FRT           | FREIGHT                    | 1.00     | 35.00      | 35.00     | \$35.00        | N         |

Labor: \$210.00      Parts: \$11.39      OL&M: \$0.00      Misc: \$35.00      Sub-Total: \$256.39

### EXPERT-1000000290200 Internal

#### COMPLAINT:

38 QUALITY CONTROL FINAL CHECK LIST

JEREMY COMPLETED FINAL CHECK ON MARCH 24, 2026

#### CORRECTION:

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                      |                |                 |                |
|----------------------|----------------|-----------------|----------------|
| Swift Current, SK    | (306) 773-9351 | Yorkton, SK     | (306) 783-9459 |
| Maple Creek, SK      | (306) 662-2233 | Balcarres, SK   | (306) 334-2492 |
| Kindersley, SK       | (306) 463-2683 | Moosomin, SK    | (306) 435-3301 |
| Kyle, SK             | (306) 375-2302 | Preeseville, SK | (306) 547-2007 |
| Leader, SK           | (306) 628-3889 | Russell, MB     | (204) 773-2149 |
| Unity, SK            | (306) 228-2696 | Wynyard, SK     | (306) 554-2536 |
| North Battleford, SK | (306) 445-4468 | Kamsack, SK     | (306) 542-2814 |
| Humboldt, SK         | (306) 682-2572 | Swan River, MB  | (204) 734-3466 |
| Kelvington, SK       | (306) 327-4355 |                 |                |
| Shaunavon, SK        | (306) 297-2639 |                 |                |



**JOHN DEERE**

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                    |                                    |                               |
|------------------------------------|------------------------------------|-------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | Invoice Number: [REDACTED]    |
|                                    |                                    | Invoice Date: 3/27/2026       |
|                                    |                                    | Location: [REDACTED]          |
|                                    |                                    | Work Order Number: [REDACTED] |
|                                    |                                    | Payment Type: [REDACTED]      |
| Bus Phone:                         | Bus Phone:                         | Page: 20 of 22                |
| Prv Phone:                         | Prv Phone:                         |                               |

| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
|--------------------|--------|-------------------|--------|-----------|
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

### EXPERT-1000000290200 Internal

- |                                        |      |
|----------------------------------------|------|
| 1. OIL LEAKS, CHECK                    | OK   |
| 2. SHIELDS, CHECK                      | OK   |
| 3. TIRE INFLATION, CHECK               | OK   |
| 4. COOLANT, CHECK                      | OK   |
| 5. ENGINE OIL, CHECK                   | OK   |
| 6. TRANSMISSION / HYDRAULIC OIL, CHECK | OK   |
| 7. 15 MINUTE, RUN UP                   | OK   |
| 8. CAB FUNCTIONS, CHECK                | OK   |
| 9. CODES, CHECK                        | OK   |
| 10. CAB, CLEAN                         | OK   |
| 11. QUALITY CONTROL TAG, INSTALL       | DONE |

|               |               |              |              |                   |
|---------------|---------------|--------------|--------------|-------------------|
| Labor: \$0.00 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$0.00 |
|---------------|---------------|--------------|--------------|-------------------|

### JPWRGRD JD ALL Internal

#### COMPLAINT:

39 POWERGARD DEDUCTIBLE CUSTOMER PORTION - \$500.00 DEDUCTIBLE

FAILED WATER PUMP

CORRECTION:

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                                     |                                |
|-------------------------------------|--------------------------------|
| Swift Current, SK (306) 773-9351    | Yorkton, SK (306) 783-9459     |
| Maple Creek, SK (306) 662-2233      | Balcarres, SK (306) 334-2492   |
| Kindersley, SK (306) 463-2683       | Moosomin, SK (306) 435-3301    |
| Kyle, SK (306) 375-2302             | Preeceville, SK (306) 547-2007 |
| Leader, SK (306) 628-3889           | Russell, MB (204) 773-2149     |
| Unity, SK (306) 228-2696            | Wynyard, SK (306) 554-2536     |
| North Battleford, SK (306) 445-4468 | Kamsack, SK (306) 542-2814     |
| Humboldt, SK (306) 682-2572         | Swan River, MB (204) 734-3466  |
| Kelvington, SK (306) 327-4355       |                                |
| Shaunavon, SK (306) 297-2639        |                                |



**JOHN DEERE**

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                    |                                    |                               |
|------------------------------------|------------------------------------|-------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | Invoice Number: [REDACTED]    |
|                                    |                                    | Invoice Date: 3/27/2026       |
|                                    |                                    | Location: [REDACTED]          |
|                                    |                                    | Work Order Number: [REDACTED] |
|                                    |                                    | Payment Type: [REDACTED]      |
| Bus Phone:                         | Bus Phone:                         | Page: 21 of 22                |
| Prv Phone:                         | Prv Phone:                         |                               |


| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
|--------------------|--------|-------------------|--------|-----------|
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

**JPWRGRD JD ALL Internal**

POWERGARD WARRANTY - WATER PUMP LEAKING FROM WEEP HOLE

DRAINED COOLANT  
REMOVED AUX, FAN BELT AND JACK SHAFT BELT  
INSTALLED PINS FOR FAN HUB ASSEMBLY TO SLIDE OUT TO BE ABLE TO REPLACE PUMP  
LOOSENED OFF PUMP  
TOOK A BIT TO WORK PUMP OUT OF THE BLOCK  
ONCE OUT CLEANED SEALING SURFACE  
PREPARED PUMP TO BE INSTALLED

INSTALLED PUMP IN PLACE TORQUING BOLTS TO SPEC  
INSTALLED HUB ASSEMBLY BACK IN PLACE TORQUING BOLTS TO SPEC  
INSTALLED BELTS  
INSTALLED FAN TORQUING BOLTS TO SPEC  
INSTALLED SOME SHIELDING  
FILLED WITH COOLANT  
LET UNIT RUN FOR 20 MIN THEN CHECK FOR LEAKS  
NO LEAKS  
INSTALLED REST OF SHIELDING AND TOPPED UP WITH COOLANT  
REPAIR VERIFIED



| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|----------------------|--------------------|-----------------|-------------------|------------------|-----------------------|------------------|
|----------------------|--------------------|-----------------|-------------------|------------------|-----------------------|------------------|

**PATTISON AGRICULTURE LIMITED**  
Hwy 8 South  
Kamsack, SK S0A 1S0  
Phone: (306) 542-2814  
Fax: (306) 542-2178  
Http://www.pattisonag.com  
GST Number 818708372

|                                     |                                |
|-------------------------------------|--------------------------------|
| Swift Current, SK (306) 773-9351    | Yorkton, SK (306) 783-9459     |
| Maple Creek, SK (306) 662-2233      | Balcarres, SK (306) 334-2492   |
| Kindersley, SK (306) 463-2683       | Moosomin, SK (306) 435-3301    |
| Kyle, SK (306) 375-2302             | Preeceville, SK (306) 547-2007 |
| Leader, SK (306) 628-3889           | Russell, MB (204) 773-2149     |
| Unity, SK (306) 228-2696            | Wynyard, SK (306) 554-2536     |
| North Battleford, SK (306) 445-4468 | Kamsack, SK (306) 542-2814     |
| Humboldt, SK (306) 682-2572         | Swan River, MB (204) 734-3466  |
| Kelvington, SK (306) 327-4355       |                                |
| Shaunavon, SK (306) 297-2639        |                                |



**JOHN DEERE**

## SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To:

|                                    |                                    |                               |
|------------------------------------|------------------------------------|-------------------------------|
| Internal Used Stock No. [REDACTED] | Internal Used Stock No. [REDACTED] | Invoice Number: [REDACTED]    |
|                                    |                                    | Invoice Date: 3/27/2026       |
|                                    |                                    | Location: [REDACTED]          |
|                                    |                                    | Work Order Number: [REDACTED] |
|                                    |                                    | Payment Type: [REDACTED]      |
| Bus Phone:                         | Bus Phone:                         | Page: 22 of 22                |
| Prv Phone:                         | Prv Phone:                         |                               |

| Make/Model:        | Meter: | Serial Number:    | Eq ID: | Fleet No: |
|--------------------|--------|-------------------|--------|-----------|
| JOHN DEERE X9 1100 | 885    | 1H0X911XAN0820336 | 100315 |           |

**JPWRGRD JD ALL Internal**  
**OTHERPG POWERGARD DEDUCTIBLE** 1.00 500.00 500.00 \$500.00 N

**Labor: \$0.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$500.00 Sub-Total: \$500.00**

INVOICE CONTAINS \$0.49 DISCOUNT

**Miscellaneous Charges:**

SERVICE ACCESSORIES

\$150.00

|                        |             |
|------------------------|-------------|
| <b>Customer PO No:</b> |             |
| <b>Tax Exempt No:</b>  |             |
| <b>Advisor:</b>        | Rocky Anaka |

**Job Total: \$17,406.43**  
**Grand Total: \$17,406.43**

\*\*\* DOCUMENT COPY \*\*\*

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE – MIN \$35 ON EMERGENCY/UNIT DOWN ORDERS – 25% RESTOCKING FOR RET

### TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by

Date: