

PATTISON AGRICULTURE LIMITED
 Box 910
 Balcarres, SK S0G 0C0
 Phone: (306) 334-2492
 Fax: (306) 334-2991
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kinderley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeseville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

Invoice To Account No: [REDACTED]

Deliver To: *** PROFORMA INVOICE ***

SERVICE INVOICE

Internal Used [REDACTED]

Bus Phone:

Prv Phone:

[REDACTED]

Bus Phone:

Prv Phone:

Invoice Number:

Invoice Date: 10/15/2026

Location: 13

Work Order Number: [REDACTED]

Payment Type: Account

Page: 1 of 13

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9570R PTO	4414	1RW9570RAFP016811	W117143	

Service Reminders:
JGL4WD JD ALL Internal

COMPLAINT:

01 4WD TRACTOR VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

CORRECTION:

VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKLIST

HOURS: _____
 TRACTOR DYNOED AT: _____

DOES THIS UNIT GET A VALUEMAX STICKER ☒ YES ☐ NO
 HAS STICKER BEEN INSTALLED ☒ YES ☐ NO
 CAB HAS BEEN COMPLETELY CLEANED _____ (INITIAL)
 THIS UNIT HAS HAD A FINAL CHECKOVER _____ (INITIAL)
 THIS UNIT HAS HAD A COMPLETE GREASE JOB _____ (INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMER'S INSTRUCTIONS:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE56098	CLAMP	1.00	25.98	\$25.98	N
TY26859	INSPECTION+ 3 FLUID TEST KIT	1.00	87.97	\$87.97	N

Labor: **\$2,625.00** Parts: **\$113.95** OL&M: **\$0.00** Misc: **\$0.00** Sub-Total: **\$2,738.95**

JELECDIAG1 JD ALL Internal

COMPLAINT:

02 DIAGNOSE STORES CODES - B
 * ECM 2791.05 (26 OCCURRENCES)
 * ECM 91.09 (30 OCCURRENCES)

CORRECTION:

searched 91.09 on DTAC as code was unclear
 found its related to failed start attempts (208009) tractor has bad starter so its related to that

2791.05 is open or low current to EGR valve
 inspected connections at GR valve, they are good
 ohm tested wires from ECM to EGR valve and they test good
 EGR valve is likely issue

PATTISON AGRICULTURE LIMITED
 Box 910
 Balcarres, SK S0G 0C0
 Phone: (306) 334-2492
 Fax: (306) 334-2991
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 654-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: *** PROFORMA INVOICE ***

Internal Used [REDACTED]
 Bus Phone:
 Prv Phone:

[REDACTED]
 Bus Phone:
 Prv Phone:

Invoice Number:
 Invoice Date: 10/15/2026
 Location: 13
 Work Order Number:
 Payment Type:
 Page: 2 of 13

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9570R PTO	4414	1RW9570RAFP016811	W117143	

Service Reminders:
 ordered new EGR valve

Labor: \$315.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$315.00
-----------------	---------------	--------------	--------------	---------------------

JGEN03- Internal

COMPLAINT:

03 REPLACE FRONT L-H SHIELD MOUNT - B

CORRECTION:

drilled out the rivets for the old mount
 removed the old mount
 riveted the new mount in place

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
R552520	Isolator	1.00	45.45	\$45.45	N
R68332	RIVET	2.00	2.23	\$4.46	N

Labor: \$52.50	Parts: \$49.91	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$102.41
----------------	----------------	--------------	--------------	---------------------

JEMISSDIAG1 JD ALL Internal

COMPLAINT:

04 REPLACE HOOD GUIDE AT EGR VALVE - A

CORRECTION:

removed the four bolts holding the broken hood guide
 installed the new style hood guide with new hardware
 torqued hardware to spec

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
19M7868	M8x30 FLG 10.9 BOLT	2.00	1.93	\$3.86	N
19M7873	M8x110 FLG 10.9 BOLT	2.00	5.59	\$11.18	N
24M7238	Washer M8.7x17	4.00	0.91	\$3.64	N
R556089	Bracket	1.00	443.74	\$443.74	N

Labor: \$210.00	Parts: \$462.42	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$672.42
-----------------	-----------------	--------------	--------------	---------------------

J01020100 JD 9570R Internal

PATTISON AGRICULTURE LIMITED
Box 910
Balcarres, SK S0G 0C0
Phone: (306) 334-2492
Fax: (306) 334-2991
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 654-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

Invoice To Account No: [REDACTED]

Deliver To: *** PROFORMA INVOICE ***

SERVICE INVOICE

Internal Used [REDACTED]	[REDACTED]	Invoice Number:	
Bus Phone:	Bus Phone:	Invoice Date:	10/15/2026
Prv Phone:	Prv Phone:	Location:	13
		Work Order Number:	[REDACTED]
		Payment Type:	Account
		Page:	3 of 13

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
-------------	-------	----------------	--------	-----------

2015 JOHN DEERE 9570R PTO	4414	1RW9570RAFP016811	W117143	
---------------------------	------	-------------------	---------	--

Service Reminders:

COMPLAINT:

05 REPLACE REAR ENGINE TORSIONAL DAMPER - A

CORRECTION:

RAISE HOOD, REMOVE REAR HINGE AND HEADLIGHT WIRING, FOLD HOOD FORWARD AND SUPPORT IN PLACE.
DRAINED 30L ENGINE COOLANT.

REMOVED BOTH COOLANT TANKS FROM TOP OF ENGINE COMPARTMENT.

REMOVED ALL INTAKE PLUMBING FROM TURBO TO AIR BOX.

REMOVED COVER FROM EXHAUST.

REMOVED EXHAUST FROM TURBO TO MUFFLER.

REMOVED COOLANT TANK BRACKET.

MARKED AND REMOVED MISC HYDRAULIC LINES AND FITTINGS FROM STEERING AT REAR OF ENGINE TO CLEAR FENDER MOUNTING BRACKET.

REMOVED WIRING FROM REAR OF ENGINE FOR HEADLIGHTS AND COOLANT TANKS.

REMOVED HEATER HOSES FROM REAR OF ENGINE TO CAB.

REMOVED FENDER MOUNTING BRACKET FROM REAR OF ENGINE.

REMOVED THREADED UNION FROM TRANS TO ENGINE.

REMOVED CAST BRACKET FROM BELL HOUSING.

REMOVED BOLTS FROM ENGINE OUTPUT SHAFT TO LORDS COUPLER, COLLAPSED SHAFT TOWARDS TRANS TO CLEAR LORDS COUPLER.

MARKED AND REMOVED SEVERAL MORE MISC HYDRAULIC LINES TO CLEAR LORDS COUPLER.

REMOVED BOLTS FROM LORDS COUPLER TO ENGINE FLYWHEEL AND REMOVED LORDS COUPLER.

CLEANED ENGINE FLYWHEEL AND PREPPED FOR NEW LORDS COUPLER.

INSTALLED NEW LORDS COUPLER COMPLETE WITH NEW BOLTS AND TORQUED AS PER SA.

RE-INSTALLED OUTPUT SHAFT TO LORDS COUPLER WITH NEW BOLTS AND TORQUED AS PER SA.

RE-INSTALLED ALL REMOVED COMPONENTS.

RE-FILLED COOLING SYSTEM AND TEST RAN TRACTOR.

unhooked and lifted the hood of the tractor out of the way

Drained cooling system into pales and set them aside

removed all the connectors and hoses to the coolants charge tanks

removed both intake pipes and the exhaust pipe

removed the coolant charge tank and support bracket

labeled all the hydraulic lines that go to the three valve blocks underneath the charge tank

took pictures of all the lines for reassembly

removed and capped all the hydraulic lines

removed the three main hydraulic valves and set them aside

removed the rear drive shaft cover and the upper dampener gaurd

unbolted the driveshaft and removed it

unbolted the worn out dampener and removed it

cleaned up the transmission yoke and the flywheel for assembly

installed the ne dampener and torqued it to spec

removed the old u-joint from the driveshaft and replaced it with a new one

torqued the u-joint bolts to spec

PATTISON AGRICULTURE LIMITED
 Box 910
 Balcarres, SK S0G 0C0
 Phone: (306) 334-2492
 Fax: (306) 334-2991
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: *** PROFORMA INVOICE ***

Internal Used [REDACTED]
 Bus Phone:
 Prv Phone:

[REDACTED]
 Bus Phone:
 Prv Phone:

Invoice Number:
 Invoice Date 10/15/2026
 Location: 13
 Work Order Number: [REDACTED]
 Payment Type: Account
 Page: 4 of 13

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9570R PTO	4414	1RW9570RAFP016811	W117143	

Service Reminders:

reinstalled the driveshaft into the tractor
 torqued the driveshaft to transmission bolts to spec and torqued the driveshaft to dampener bolts to spec
 reinstalled the rear driveshaft cover and torqued the hardware
 mounted the dampener cover and torqued the hardware to spec
 reinstalled all three valve blocks and torqued them into place
 reinstalled all hydraulic lines back into the right locations
 tightened all the fittings
 reinstalled the charge tank and support into place
 reinstalled the intake and exhaust pipes
 hooked up all the coolant lines and connectors
 filled the system with coolant
 ran tractor and topped the system back up with coolant

doug

strained coolant and filled engine with coolant

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AR69444	HY-GARD J20C 18.9L PAIL	1.00	193.85	\$193.85	N
R114105	1/2x2.5UNF 12pt Gr8+	8.00	11.07	\$88.56	N
R151762	7/16x1" FlgBoltGr8	12.00	3.06	\$36.72	N
R45693	5/8x1.5 boltGr5	12.00	4.84	\$58.08	N
R564047	RING	1.00	128.02	\$128.02	N
RE154966	PressureSensor	1.00	91.38	\$91.38	N
RE40113	UNIVERSAL	1.00	964.48	\$964.48	N
RE584547	TORSIONAL DAMPER	1.00	4,860.37	\$4,860.37	N
TY22485	HOSE CLAMP	1.00	4.32	\$4.32	N
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF300	ENVIRO FEE	1.00	3.00	\$3.00	N

Labor: \$5,250.00 Parts: \$6,425.78 OL&M: \$0.00 Misc: \$3.00 Sub-Total: \$11,678.78

J01030070 JD 9570R Internal

COMPLAINT:

06 REPLACE ENGINE VARIABLE SPEED FAN BELT - A

CORRECTION:

removed old belt
 routed and installed new belt

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
------------	-------------	----------	-----------	----------------	-----------

PATTISON AGRICULTURE LIMITED

Box 910

Balcarres, SK S0G 0C0

Phone: (306) 334-2492

Fax: (306) 334-2991

Http://www.pattisonag.com

GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
 Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
 Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
 Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
 Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
 Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
 North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
 Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639

**PATTISON**
AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: *** PROFORMA INVOICE ***

Internal Used [REDACTED]	[REDACTED]	Invoice Number:	
Bus Phone:	[REDACTED]	Invoice Date:	10/15/2026
Prv Phone:	[REDACTED]	Location:	13
		Work Order Number:	[REDACTED]
		Payment Type:	Account
		Page:	5 of 13

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9570R PTO	4414	1RW9570RAFP016811	W117143	

Service Reminders:

REC369126500	V-Belt	1.00	165.23	\$165.23	N
Labor: \$105.00	Parts: \$165.23	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$270.23	

JENGDIAG1 JD ALL Internal

COMPLAINT:

07 REPLACE SERPENTINE BELT IDLER PULLEY - A

CORRECTION:

Belt was already off
 removed the old pulley
 installed and torqued the new pulley into place
 reinstalled belt

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AXE21206	PULLEY	1.00	367.45	\$367.45	N
Labor: \$105.00	Parts: \$367.45	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$472.45	

JEMISSDIAG2 JD ALL Internal

COMPLAINT:

09 TIE UP HEAT SHIELD BY TURBO - B

CORRECTION:

ordered metal zip ties to hold up shield
 used the metal zip ties to hold up the shield

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
232501PK	5" SS BEAD CABLE TIE	1.00	67.02	\$67.02	N
Labor: \$105.00	Parts: \$67.02	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$172.02	

J01030040 JD 9570R Internal

COMPLAINT:

10 WATER PUMP, R&R - A
 * REPLACE RAD CAPS

PATTISON AGRICULTURE LIMITED
 Box 910
 Balcarres, SK S0G 0C0
 Phone: (306) 334-2492
 Fax: (306) 334-2991
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeseville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: *** PROFORMA INVOICE ***

Internal Used [REDACTED]

Bus Phone:

Prv Phone:

Internal Used [REDACTED]

Bus Phone:

Prv Phone:

Invoice Number:

Invoice Date: 10/15/2026

Location: 13

Work Order Number: [REDACTED]

Payment Type: Account

Page: 6 of 13

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9570R PTO	4414	1RW9570RAFP016811	W117143	

Service Reminders:

CORRECTION:

DRAIN COOLANT.
 REMOVE WATER PUMP.
 CLEAN AND INSPECT COMPONENTS.
 REPLACE WATER PUMP.
 REFILL COOLANT.
 TEST RUN UNIT AND CHECK FOR LEAKS.

drained coolant into clean pails
 removed both the water pump belt and the fan drive belt
 loosened off the water pump bolts and propped the water pump off the housing so any residual coolant can drain out
 removed the water pump
 installed a new o-ring onto the new water pump
 prepped the housing by cleaning the mounting surface and o-ring surface
 lubed the new water pump o-ring and installed the waterpump
 installed the water pump bolts with 243 blue loctite
 torqued the water pump to spec
 refilled cooling system
 reinstalled both drive belts

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE312969	Coolant Cap-Black15psi	2.00	60.92	\$121.84	N
REC368438400	O-Ring	1.00	28.56	\$28.56	N
REC571977100	WATER PUMP	1.00	1,255.52	\$1,255.52	N
TY26576	COOL-GARD II 50/50 PRE-MIX JUG 9.46L	1.00	63.43	\$63.43	N
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF150	ENVIRO FEE	1.00	1.50	\$1.50	N

Labor: \$1,365.00 Parts: \$1,469.35 OL&M: \$0.00 Misc: \$1.50 Sub-Total: \$2,835.85

J01001091 JD 9570R Internal

COMPLAINT:

11 BATTERY SERVICE - A
 * CLEAN BATTERY COMPARTMENT
 * REPLACE POSITIVE CLAMP BOLTS

CORRECTION:

REMOVED BATTERY CABLES.
 CLEANED BATTERY POSTS AND CABLES.
 INSTALLED CABLES ONTO BATTERY POSTS.
 INSTALLED PROTECTIVE CONNECTION COATING.

PATTISON AGRICULTURE LIMITED
 Box 910
 Balcarres, SK S0G 0C0
 Phone: (306) 334-2492
 Fax: (306) 334-2991
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: *** PROFORMA INVOICE ***

Internal Used: [REDACTED]

 Bus Phone:
 Prv Phone:

[REDACTED]
 Bus Phone:
 Prv Phone:

Invoice Number:
 Invoice Date: 10/15/2026
 Location: 13
 Work Order Number: [REDACTED]
 Payment Type: Account
 Page: 7 of 13

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9570R PTO	4414	1RW9570RAFP016811	W117143	

Service Reminders:

opened the battery compartment
 removed all the battery connections
 cleaned up the cables and replaced the four positive cable bolts
 cleaned the battery studs
 reinstalled battery cables
 closed the battery compartment

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
TY25099	Battery Bolt & Nut	4.00	0.70	\$2.80	N
Labor: \$210.00	Parts: \$2.80	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$212.80	

J01040011 JD 9570R Internal

COMPLAINT:

12 REMOVE AND REPLACE STARTER MOTOR - A

CORRECTION:

took a picture of starter area for re installment
 removed the three wires to the starter
 unbolted the starter from the engine
 removed the starter
 cleaned all the connections for the starter
 installed new starter and torqued the mounting bolts to spec
 connected all the wired to the new starter
 marked starter with replacement date

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE589156	12V STARTER MOTOR 15L	1.00	1,670.50	\$1,670.50	N
RE589156-CR	CORE for:Starter Motor	-1.00	71.00	-\$71.00	N
Labor: \$525.00	Parts: \$1,599.50	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,124.50	

J01070026 JD 9570R Internal

COMPLAINT:

16 REPLACE SELECTIVE CONTROL VALVE BARREL (#4) - A

CORRECTION:

removed SCV 4s cover

PATTISON AGRICULTURE LIMITED
 Box 910
 Balcarres, SK S0G 0C0
 Phone: (306) 334-2492
 Fax: (306) 334-2991
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: ***PROFORMA INVOICE***

Internal Used Stock No. 268896 (Sold)

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number:

Invoice Date 10/15/2026

Location: 13

Work Order Number: [REDACTED]

Payment Type: Account

Page: 8 of 13

Make/Model:

Meter

Serial Number:

EQ Id:

Fleet No:

2015 JOHN DEERE 9570R PTO

4414

1RW9570RAFP016811

W117143

Service Reminders:

cleaned out the SCV
 removed both retaining rings from the old barrels
 removed both old barrels
 cleaned the inner barrels housing
 installed new barrels
 reinstalled the retaining rings and cover

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE577560	-8 1/2 FEM SCV BREAKAWAY CPLR	2.00	177.28	\$354.56	N

Labor: \$126.00 Parts: \$354.56 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$480.56

JHYDDIAG2 JD ALL Internal

COMPLAINT:

17 HOSE LEAKING TO FRONT SUSPENSION, REPLACE - A

CORRECTION:

removed the lower fan shroud to get at the valve block that the hose was connected to
 removed the hose from the lower valve block and capped it
 removed the hose from the upper fitting and capped it
 removed the upper and lower rubber frame blocks that hold the hose in place
 pulled the old hose out and fished the new hose in place
 reinstalled both rubber frame blocks
 hooked up the upper hose connection
 the lower lave block had the wrong hose fitting, it had a 45* fitting and it needed a 90* fitting

doug

removed the 45 fitting and installed the 90 fitting
 hooked the hose back up
 reinstalled the fan shroud
 reinstalled the rubber hold down and the metal bracket to secure it

Technician Comments:

removed the lower fan shroud to get at the valve block that the hose was connected to
 removed the hose from the lower valve block and capped it
 removed the hose from the upper fitting and capped it
 removed the upper and lower rubber frame blocks that hold the hose in place
 pulled the old hose out and fished the new hose in place
 reinstalled both rubber frame blocks
 hooked up the upper hose connection
 the lower lave block had the wrong hose fitting, it had a 45* fitting and it needed a 90* fitting

PATTISON AGRICULTURE LIMITED

Box 910
 Balcarres, SK S0G 0C0
 Phone: (306) 334-2492
 Fax: (306) 334-2991
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeseville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



PATTISON

AGRICULTURE



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: [REDACTED]

Deliver To: *** PROFORMA INVOICE ***

[REDACTED]

Bus Phone:
Prv Phone:

[REDACTED]

Bus Phone:
Prv Phone:

Invoice Number:
 Invoice Date: 10/15/2026
 Location: 13
 Work Order Number: [REDACTED]
 Payment Type: Account
 Page: 9 of 13

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
-------------	-------	----------------	--------	-----------

2015 JOHN DEERE 9570R PTO	4414	1RW9570RAFP016811	W117143
---------------------------	------	-------------------	---------

Service Reminders:

doug
 removed the 45 fitting and installed the 90 fitting
 hooked the hose back up
 reinstalled the fan shroud
 reinstalled the rubber hold down and the metal bracket to secure it

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
38H5017	-8mFF_M18mORB90	1.00	54.79	\$54.79	N
R26375	O-RING	1.00	3.01	\$3.01	N
RE582018	Hydraulic Hose	1.00	262.86	\$262.86	N
T77857	-8FF O-ring	1.00	2.53	\$2.53	N

Labor: \$840.00	Parts: \$323.19	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,163.19
-----------------	-----------------	--------------	--------------	-----------------------

JACDIAG1 JD ALL Internal

COMPLAINT:

18 A/C OVERCHARGED, EVACUATE & RECHARGE - B
 * REPLACE P-CLAMP AT FRONT OF ENGINE

CORRECTION:

hooked up the machine
 recovered the old refrigerant
 pulled a vacuum on the system
 charged the system to a spec of 4.5 pounds

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
57M12137	Clamp	1.00	6.40	\$6.40	N

Labor: \$420.00	Parts: \$6.40	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$426.40
-----------------	---------------	--------------	--------------	---------------------

JGEN19- Internal

COMPLAINT:

19 WINDSHIELD WIPER LOOSE, REPAIR - A

CORRECTION:

removed the old windshield wiper arm
 there was tape on the splines of the wiper motor
 removed the tape and installed the new arm with the wiper blade

PATTISON AGRICULTURE LIMITED
 Box 910
 Balcarres, SK S0G 0C0
 Phone: (306) 334-2492
 Fax: (306) 334-2991
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preecaville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

In: [REDACTED] 	Deliver To: *** PROFORMA INVOICE *** 	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">Invoice Number:</td> </tr> <tr> <td>Invoice Date</td> <td>10/15/2026</td> </tr> <tr> <td>Location:</td> <td>13</td> </tr> <tr> <td>Work Order Number:</td> <td>[REDACTED]</td> </tr> <tr> <td>Payment Type:</td> <td>Account</td> </tr> <tr> <td colspan="2">Page: 10 of 13</td> </tr> </table>	Invoice Number:		Invoice Date	10/15/2026	Location:	13	Work Order Number:	[REDACTED]	Payment Type:	Account	Page: 10 of 13	
Invoice Number:														
Invoice Date	10/15/2026													
Location:	13													
Work Order Number:	[REDACTED]													
Payment Type:	Account													
Page: 10 of 13														

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9570R PTO	4414	1RW9570RAFP016811	W117143	

Service Reminders:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE580468	Wiper Arm	1.00	278.07	\$278.07	N
Labor: \$105.00	Parts: \$278.07	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$383.07	

JGEN20- Internal

COMPLAINT:

20 REPLACE DRAW BAR BOLTS - A

CORRECTION:

removed old draw bar bolts with a impact
 cleaned the bolt holes
 installed new bolts and washers
 torque bolts to spec

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
19M7778	M20x220 HH 10.9 BOLT	2.00	31.93	\$63.86	N
24M7242	Washer M21.4x42	2.00	4.11	\$8.22	N
A31870	M20x2.5 DT LockNut	2.00	7.41	\$14.82	N
Labor: \$210.00	Parts: \$86.90	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$296.90	

JENGAIRFILT JD 9570R Internal

COMPLAINT:

23 REPLACE PRIMARY AND SECONDARY ENGINE AIR FILTERS

CORRECTION:

removed housing cover
 removed the old primary and secondary filters
 blew out the housing
 labeled and installed the new filters
 reinstalled the housing cover

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE594852	PRIMARY ENGINE AIR FILTER	2.00	343.84	\$687.68	N
RE594853	SECONDARY ENGINE AIR FILTER	2.00	111.55	\$223.10	N
Labor: \$50.00	Parts: \$910.78	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$960.78	

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 436-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



29 REPLACE TRANSMISSION BREATHER

PATTISON AGRICULTURE LIMITED

Box 910
Balcarres, SK S0G 0C0
Phone: (306) 334-2492
Fax: (306) 334-2991
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2535
North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639

**JOHN DEERE****SERVICE INVOICE**

Deliver To: *** PROFORMA INVOICE ***

Invoice Number:

Invoice Date

10/15/2026

Location:

13

Work Order Number:

Payment Type:

Account

Page:

12 of 13

Bus Phone:

Prv Phone:

Bus Phone:

Prv Phone:

Make/Model:

Meter

Serial Number:

EQ Id:

Fleet No:

2015 JOHN DEERE 9570R PTO

4414

1RW9570RAFP016811

W117143

Service Reminders:

CORRECTION:

removed side panel to get at the breather
before removing breather i cleaned the area to prevent contamination
removed the old breather
cleaned out the socket
installed new breather
reinstalled side panel

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
H216169	BREATHER	1.00	33.71	\$33.71	N
Labor: \$75.00		Parts: \$33.71	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$108.71

JGEN30- Internal**COMPLAINT:**

30 18RW816A - 9R & 9RX SIDE SHIELDS ENHANCEMENT - PEP

CORRECTION:

moved crate out of compound and brought in
printed off instructions
was told kit is not being installed due to cost of kit

Labor: \$0.00 **Parts: \$0.00** **OL&M: \$0.00** **Misc: \$0.00** **Sub-Total: \$0.00**

J01020091 JD 9570R Internal**COMPLAINT:**

31 REPLACE EXHAUST GAS RECIRCULATION VALVE. EGR

CORRECTION:

REMOVED EGR PIPE.
REMOVED EGR VALVE.
CHANGED EGR VALVE & GASKET.
CALIBRATED VALVE.

removed the three clamps at the EGR valve
unplugged the EGR valve
removed the three mounting bolts
removed the old EGR valve

PATTISON AGRICULTURE LIMITED
 Box 910
 Balcarres, SK S0G 0C0
 Phone: (306) 334-2492
 Fax: (306) 334-2991
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To: *** PROFORMA INVOICE ***

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number:
 Invoice Date: 10/15/2026
 Location: 13
 Work Order Number:
 Payment Type: Account
 Page: 13 of 13

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9570R PTO	4414	1RW9570RAFP016811	W117143	

Service Reminders:

installed a new EGR valve and rubber boot
 bolted it down with the three mounting bolts and tightened all the hose clamps
 plugged the EGR valve back in
 went into the cab and calibrated the EGR valve

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
REC368512400	O-Ring	1.00	14.06	\$14.06	N
REC368530900	CLAMP	1.00	151.98	\$151.98	N
REC368683900	Hose Clamp	1.00	58.63	\$58.63	N
REC368722300	Hose	1.00	167.70	\$167.70	N
REC540604900	EGR VALVE KIT	1.00	4,799.98	\$4,799.98	N
REC540604900-CR	CORE for:Valve Kit	-1.00	141.00	-\$141.00	N

Miscellaneous Charges:

SERVICE ACCESSORIES

\$150.00

Labor: \$353.62 Parts: \$5,051.35 OL&M: \$0.00 Misc: \$150.00 Sub-Total: \$5,554.97

Customer PO No:
 Tax Exempt No:
 Advisor: Tara Pankiw

Labor: \$13,122.12
 Parts: \$18,122.84
 OL&M: \$0.00
 Misc: \$154.50
 GST: \$0.00
 PST: \$0.00

Grand Total: \$31,399.46

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by:

Date: