X05-1

SOUTH COUNTRY EQUIPMENT

#8 South Plains Road West
Emerald Park, SK S4L 1C6
Phone: 306-721-5050
www.southcountry.ca

Moose Jaw, SK	306-692-2371
Mossbank, SK	306-354-2411
Assiniboia, SK	306-642-3366
Emerald Park, SK	306-721-5050
Weyburn, SK	306-842-4686
Southey, SK	306-726-2155
Raymore, SK	306-746-2110
Montmartre, SK	306-424-2212

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 4026

[redacted]

Deliver To:

[redacted]

Invoice Number: [redacted]
Invoice Date 11/30/2023
Location: 04
Work Order Number: [redacted]
Payment Type: [redacted]

Page: 1 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 7130	7254	RW7130K030480	W181375	

Service Reminders:

/2WD7130 F Retail

COMPLAINT:

01 GREENLIGHT SERVICE INSPECTION ROW CROP TRACTOR

CAUSE:

CORRECTION:

DUST SEAL ON RH SIDE OF STEERING CYLINDER IS DAMAGED. THE SEAL IS STILL KEEPING DUST OUT, BUT THE LIP IS WARPED IN ONE SPOT. ADVISED CUSTOMER TO MONITOR.

RH REAR TIRE IS LEAKING FLUID AND SHOULD GET REPAIRED.

FRONT TIRES (TIRE SIZE IS 420/85R 28), TREAD AND SIDEWALL HAVE EXCESSIVE WEAR AND THE SIDEWALLS ARE CRACKING.

Labor: $999.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $999.00**

GEN32- Retail

COMPLAINT:

02 DIAGNOSE ACTIVE CODES CAUSING ENGINE TO DERATE

CAUSE:

CORRECTION:

ECU 3513.04, SENSOR SUPPLY VOLTAGE OUT OF RANGE LOW, ACTIVE. FOUND WIRING HARNESS WAS BURNT BY EGR VALVE, NEED TO REPAIR HARNESS.

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	$10.38	$10.38	Y

Labor: $173.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $10.38** **Sub-Total: $183.38**

GEN42- Retail

COMPLAINT:

03 REPLACE ENGINE WIRE HARNESS, BURNT BY THE TURBO

CAUSE:

SOUTH COUNTRY EQUIPMENT

#8 South Plains Road West
Emerald Park, SK S4L 1C6
Phone: 306-721-5050
www.southcountry.ca

Moose Jaw, SK	306-692-2371
Mossbank, SK	306-354-2411
Assiniboia, SK	306-642-3366
Emerald Park, SK	306-721-5050
Weyburn , SK	306-842-4686
Southey, SK	306-726-2155
Raymore, SK	306-746-2110
Montmartre, SK	306-424-2212

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 4026

[redacted]

Deliver To:

[redacted]

Invoice Number: [redacted]
Invoice Date 11/30/2023
Location: 04
Work Order Number:
Payment Type: [redacted]

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 7130	7254	RW7130K030480	W181375	

Service Reminders:

CORRECTION:

REMOVED ALTERNATOR AND INTER COOLER TO GAIN ACCESS TO DAMAGED AREA OF HARNESS, FOUND DAMAGE ON WIRING HARNESS WAS BEYOND REPAIR AND THE EGR TEMPERATURE SENSOR WAS MELTED, NEEDED TO REPLACE THE SENSOR AND WIRING HARNESS.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AL201846	Engine Power WRG Harness	1.00	$1,057.24	$1,057.24	Y
RE522824	TEMPERATUR	1.00	$166.43	$166.43	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
FREIGHT	FREIGHT	1.00	$20.00	$20.00	Y
SERVACCESS	SERVICE ACCESSORIES	83.04	$0.00	$0.00	Y

Labor: $1,384.00 **Parts: $1,223.67** **OL&M: $0.00** **Misc: $20.00** **Sub-Total: $2,627.67**

GEN43- Retail

COMPLAINT:

04 DIAGNOSE DTI CODES, DTI 524082.10, 524078.10, 524080.10.

CAUSE:

CORRECTION:

THE DESCRIPTION ON THE DISPLAY IS A STUCK BUTTON. DISPLAY NEEDS TO BE REPLACED. THE BUTTONS ON TOP OF THE DISPLAY DO NOT WORK.

*** NOT DONE ***

Labor: $0.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $0.00**

GEN44- Retail

COMPLAINT:

05 REPLACE INTAKE MANIFOLD SENSOR, SENSOR HOUSING CRACKED

CAUSE:

CORRECTION:

SOUTH COUNTRY EQUIPMENT

#8 South Plains Road West
Emerald Park, SK S4L 1C6
Phone: 306-721-5050
www.southcountry.ca

Moose Jaw, SK	306-692-2371
Mossbank, SK	306-354-2411
Assiniboia, SK	306-642-3366
Emerald Park, SK	306-721-5050
Weyburn, SK	306-842-4686
Southey, SK	306-726-2155
Raymore, SK	306-746-2110
Montmartre, SK	306-424-2212

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 4026

Deliver To:

[redacted]

Invoice Number: [redacted]
Invoice Date 11/30/2023
Location: 04
Work Order Number: [redacted]
Payment Type: Account

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 7130	7254	RW7130K030480	W181375	

Service Reminders:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE522723	MANIFOLD AI	1.00	$342.04	$342.04	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$5.19	$5.19	Y

Labor: $86.50 **Parts: $342.04** **OL&M: $0.00** **Misc: $5.19** **Sub-Total: $433.73**

GEN45- Retail

COMPLAINT:

06 DIAGNOSE ENGINE TEMPERATURE GAUGE DOES NOT WORK. GAUGE DID NOT MOVE DURING DYNO TEST.

CAUSE:

CORRECTION:

TESTED SUPPLY VOLTAGE AT WIRING HARNESS CONNECTOR FOR COOLANT TEMPERATURE SENSOR. MEASURED 5V. MEASURED VOLTAGE ON SIGNAL WIRE WITH SENSOR CONNECTED AND KEY ON, MEASURED 0V. SPEC IS 4.4V. REMOVED AND REPLACED SENSOR AND RETESTED.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
51M7041	O-RING	1.00	$3.40	$3.40	Y
RE52722	SENSOR	1.00	$67.28	$67.28	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$10.38	$10.38	Y

Labor: $173.00 **Parts: $70.68** **OL&M: $0.00** **Misc: $10.38** **Sub-Total: $254.06**

GEN46- Retail

COMPLAINT:

07 DIAGNOSE CAB SEAT LIFT NOT WORKING, WHEN BUTTON IS PRESSED, CAN HEAR COMPRESSOR ENGAGE BUT SEAT DOES NOT LIFT. WHEN DOWN BUTTON IS PRESSED, CANNOT HEAR ANY AIR BEING RELEASED.

CAUSE:

CORRECTION:

REMOVED SEAT FROM CAB. DISASSEMBLED SEAT BASE AND CHECKED COMPRESSOR, AIR LINES, AND WIRING. TRACED AIR LEAK TO VALVE IN THE SWITCH. REMOVED AND REPLACED THE SWITCH. REASSEMBLED AND REINSTALLED SEAT ASSEMBLY. TESTED OPERATION OF AIR LIFT. SEAT NOW LIFTS PROPERLY AND STAYS UP.

SOUTH COUNTRY EQUIPMENT

#8 South Plains Road West
Emerald Park, SK S4L 1C6
Phone: 306-721-5050
www.southcountry.ca

Moose Jaw, SK	306-692-2371
Mossbank, SK	306-354-2411
Assiniboia, SK	306-642-3366
Emerald Park, SK	306-721-5050
Weyburn , SK	306-842-4686
Southey, SK	306-726-2155
Raymore, SK	306-746-2110
Montmartre, SK	306-424-2212

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 4026

[redacted]

Deliver To:

[redacted]

Invoice Number: [redacted]
Invoice Date 11/30/2023
Location:
Work Order Number:
Payment Type: Account

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 7130	7254	RW7130K030480	W181375	

Service Reminders:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE225257	Switch	1.00	$148.18	$148.18	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$31.14	$31.14	Y

Labor: $519.00 **Parts: $148.18** **OL&M: $0.00** **Misc: $31.14** **Sub-Total: $698.32**

GEN47- Retail

COMPLAINT:

08 DIAGNOSE AND REPAIR REAR WORK LIGHTS DO NOT WORK

CAUSE:

CORRECTION:

REMOVED BULB FROM REAR FENDER WORK LIGHTS AND TESTED BULB, BULB DOES NOT LIGHT WHEN VOLTAGE IS APPLIED. INSTALLED NEW BULB AND TESTED LIGHTS, LIGHTS STILL DO NOT LIGHT UP. TESTED NEW BULBS, BULBS LIGHT UP WHEN VOLTAGE IS APPLIED. CLEANED UP GROUND CONNECTIONS AND RETESTED, FENDER WORK LIGHTS NOW WORK. UPPER REAR WORK LIGHTS NO LONGER WORK. REMOVED AND REPLACED BULB FROM RIGHT HAND UPPER WORK LIGHT AND RETESTED. LIGHT DOES NOT WORK WITH NEW BULB, REINSTALLED OLD BULB. REMOVED ROOF HATCH AND OUTER ROOF PANEL TO GAIN ACCESS TO WIRING HARNESS, WENT THROUGH WIRING HARNESS AND CLEANED CONNECTORS FOR THE WORK LIGHTS, AND TESTED WIRING HARNESS. MEASURED BATTERY VOLTAGE AT WIRING HARNESS CONNECTOR WITH THE LIGHT SWITCH ON. NEED TO REPLACE BALLAST TO GET CURRENT REAR WORK LIGHTS WORKING. REMOVED WORK LIGHTS AND INSTALLED LED WORK LIGHTS. TESTED OPERATION OF NEW LIGHTS, UPPER REAR WORK LIGHTS NOW WORK. REINSTALLED OUTER ROOF PANEL AND ROOF HATCH.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AT130104	BULB, HALOGEN , H3, 55W-12V	2.00	$13.76	$27.52	Y
A-WL20E	ROUND LED WORKLAMP - FLOOD	2.00	$41.16	$82.32	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$10.38	$10.38	Y

Labor: $173.00 **Parts: $109.84** **OL&M: $0.00** **Misc: $10.38** **Sub-Total: $293.22**

GEN48- Retail

COMPLAINT:

09 DIAGNOSE AND REPAIR LH CAB DOOR WILL NOT OPEN OR LATCH PROPERLY. CANNOT OPEN DOOR FROM INSIDE THE CAB SOMETIMES.

CAUSE:

SOUTH COUNTRY EQUIPMENT

#8 South Plains Road West
Emerald Park, SK S4L 1C6
Phone: 306-721-5050
www.southcountry.ca

Moose Jaw, SK	306-692-2371
Mossbank, SK	306-354-2411
Assiniboia, SK	306-642-3366
Emerald Park, SK	306-721-5050
Weyburn, SK	306-842-4686
Southey, SK	306-726-2155
Raymore, SK	306-746-2110
Montmartre, SK	306-424-2212

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 4026

[redacted]

Deliver To:

[redacted]

Invoice Number: [redacted]
Invoice Date 11/30/2023
Location: 04
Work Order Number:
Payment Type: [redacted]

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 7130	7254	RW7130K030480	W181375	

Service Reminders:

CORRECTION:

ADJUSTED STRIKER SO THAT DOOR LATCHES PROPERLY.

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	$10.38	$10.38	Y

Labor: $173.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $10.38** **Sub-Total: $183.38**

/1410097130 Retail

COMPLAINT:

10 REPLACE HEADLIGHT ASSEMBLY, LIGHT BROKEN

CAUSE:

CORRECTION:

*** NOT DONE ***

Labor: $0.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $0.00**

/1401787130 F Retail

COMPLAINT:

11 CHANGE ENGINE AIR FILTERS

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AL150288	AIR FILTER	1.00	$77.09	$77.09	Y
AL172780	AIR FILTER	1.00	$164.17	$164.17	Y

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	$3.11	$3.11	Y

Labor: $51.90 **Parts: $241.26** **OL&M: $0.00** **Misc: $3.11** **Sub-Total: $296.27**

/1015A7130 F Retail

SOUTH COUNTRY EQUIPMENT

#8 South Plains Road West
Emerald Park, SK S4L 1C6
Phone: 306-721-5050
www.southcountry.ca

Moose Jaw, SK	306-692-2371
Mossbank, SK	306-354-2411
Assiniboia, SK	306-642-3366
Emerald Park, SK	306-721-5050
Weyburn , SK	306-842-4686
Southey, SK	306-726-2155
Raymore, SK	306-746-2110
Montmartre, SK	306-424-2212

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 4026

[redacted]

Deliver To:

[redacted]

Invoice Number: [redacted]
Invoice Date 11/30/2023
Location: [redacted]
Work Order Number: [redacted]
Payment Type: Account

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 7130	7254	RW7130K030480	W181375	

Service Reminders:

COMPLAINT:

12 CHANGE ENGINE OIL AND OIL FILTER

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
R502513	Seal - Engine Oil Filter	1.00	$12.11	$12.11	Y
RE504836	Engine Oil Filter	1.00	$35.40	$35.40	Y
TY26674	946ML 15W40 PLUS 50 II	1.00	$9.68	$9.68	Y
TY26679	18.9L 15W40 PLUS 50 II	1.00	$166.52	$166.52	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
EF15	ENVIRO FEE	1.00	$0.15	$0.15	Y
EF300	ENVIRO FEE	1.00	$3.00	$3.00	Y
EF50	ENVIRO FEE	1.00	$0.50	$0.50	Y
OILRECOVER	OIL RECOVERY	1.00	$4.00	$4.00	Y
SERVACCESS	SERVICE ACCESSORIES	1.00	$2.60	$2.60	Y

Labor: $43.25 **Parts: $223.71** **OL&M: $0.00** **Misc: $10.25** **Sub-Total: $277.21**

GEN49- Retail

COMPLAINT:

13 REPLACE CRACKED AIR INTAKE HOSE RUNNING FROM AIR FILTER TO INTAKE ON TURBO

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AL201578	Hose	1.00	$183.80	$183.80	Y
TY22473	HOSE CLAMP #52	1.00	$2.85	$2.85	Y
TY22474	HOSE CLAMP #64	1.00	$2.94	$2.94	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$5.19	$5.19	Y

SOUTH COUNTRY EQUIPMENT

#8 South Plains Road West
Emerald Park, SK S4L 1C6
Phone: 306-721-5050
www.southcountry.ca

Moose Jaw, SK	306-692-2371
Mossbank, SK	306-354-2411
Assiniboia, SK	306-642-3366
Emerald Park, SK	306-721-5050
Weyburn , SK	306-842-4686
Southey, SK	306-726-2155
Raymore, SK	306-746-2110
Montmartre, SK	306-424-2212

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 4026

[redacted]

Deliver To:

[redacted]

Invoice Number: [redacted]
Invoice Date 11/30/2023
Location:
Work Order Number: [redacted]
Payment Type: Account
Page: 7 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 7130	7254	RW7130K030480	W181375	

Service Reminders:

Labor: $86.50 **Parts: $189.59** **OL&M: $0.00** **Misc: $5.19** **Sub-Total: $281.28**

/1700717130 Retail

COMPLAINT:

14 R&R OR REPLACE BATTERY(S). FAILED LOAD TEST, BOLTS ARE CORRODED

CAUSE:

CORRECTION:

*** NOT DONE ***

Labor: $0.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $0.00**

/100201107130 F Retail

COMPLAINT:

15 OIL PAN GASKET, R&R. LEAKING

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
19M8062	SCREW	6.00	$1.80	$10.80	Y
19M8163	BOLT	22.00	$1.64	$36.08	Y
DZ116645	Gasket	1.00	$118.21	$118.21	Y
RE529554	Filler Cap	1.00	$38.90	$38.90	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$41.52	$41.52	Y

Labor: $692.00 **Parts: $203.99** **OL&M: $0.00** **Misc: $41.52** **Sub-Total: $937.51**

/1201117130 Retail

COMPLAINT:

16 REPLACE MFWD AXLE SEALS, RH SIDE

SOUTH COUNTRY EQUIPMENT

#8 South Plains Road West
Emerald Park, SK S4L 1C6
Phone: 306-721-5050
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn , SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 4026

Deliver To:

[redacted]

[redacted]

Invoice Number: [redacted]
Invoice Date 11/30/2023
Location: 04
Work Order Number: [redacted]
Payment Type: Account

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 7130	7254	RW7130K030480	W181375	

Service Reminders:

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
19M5039	SCREW	2.00	$1.93	$3.86	Y
AL159594	SEAL	1.00	$134.43	$134.43	Y
AL81844	TAPERED ROLLER BEARING	2.00	$462.58	$925.16	Y
L113950	O-RING	1.00	$25.34	$25.34	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$72.66	$72.66	Y

Labor: $1,211.00 **Parts: $1,088.79** **OL&M: $0.00** **Misc: $72.66** **Sub-Total: $2,372.45**

/1218187130 Retail

COMPLAINT:

17 REPLACE CAB DOOR SEAL, LH DOOR

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
L176347	WEATHERSTRI	1.00	$182.24	$182.24	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$12.98	$12.98	Y

Labor: $216.25 **Parts: $182.24** **OL&M: $0.00** **Misc: $12.98** **Sub-Total: $411.47**

/1500297130 Retail

COMPLAINT:

18 REPLACE CAB FILTERS & CLEAN PLASTIC GRATE

CAUSE:

SOUTH COUNTRY EQUIPMENT

#8 South Plains Road West
Emerald Park, SK S4L 1C6
Phone: 306-721-5050
www.southcountry.ca

Moose Jaw, SK	306-692-2371
Mossbank, SK	306-354-2411
Assiniboia, SK	306-642-3366
Emerald Park, SK	306-721-5050
Weyburn , SK	306-842-4686
Southey, SK	306-726-2155
Raymore, SK	306-746-2110
Montmartre, SK	306-424-2212

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 4026

[redacted]

Deliver To:

[redacted]

Invoice Number: [redacted]
Invoice Date 11/30/2023
Location: 04
Work Order Number: [redacted]
Payment Type: Account

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 7130	7254	RW7130K030480	W181375	

Service Reminders:

CORRECTION:

FOUND HOUSING FOR THE REAR LH OUTSIDE CABIN FILTER IS BROKEN AT THE HINGE FOR THE HANDLE, WAS STILL ABLE TO CLOSE HOUSING.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AL225552	AIR FILTER	2.00	$89.30	$178.60	Y
L214634	Cab Ricirculation Air Filter	2.00	$42.40	$84.80	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$3.11	$3.11	Y

Labor: $51.90 **Parts: $263.40** **OL&M: $0.00** **Misc: $3.11** **Sub-Total: $318.41**

/100700207130 F Retail

COMPLAINT:

19 TRANSMISSION/HYDRAULIC OIL AND FILTER, R&R

CAUSE:

CORRECTION:

*** NOT DONE ***

Labor: $0.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $0.00**

/1015H7130 F Retail

COMPLAINT:

20 CHANGE MFWD AXLE DIFFERENTIAL AND PLANETARY DRIVE OILS, LOW

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
TY22062	9.46L HYGARD HYD/TRANS OIL	1.00	$84.77	$84.77	Y
TY6354	3.78L HYGARD HYD/TRANS OIL	1.00	$35.42	$35.42	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**

SOUTH COUNTRY EQUIPMENT

#8 South Plains Road West
Emerald Park, SK S4L 1C6
Phone: 306-721-5050
www.southcountry.ca

Moose Jaw, SK	306-692-2371
Mossbank, SK	306-354-2411
Assiniboia, SK	306-642-3366
Emerald Park, SK	306-721-5050
Weyburn , SK	306-842-4686
Southey, SK	306-726-2155
Raymore, SK	306-746-2110
Montmartre, SK	306-424-2212

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 4026

[redacted]

Deliver To:

[redacted]

Invoice Number: [redacted]
Invoice Date 11/30/2023
Location: [redacted]
Work Order Number: [redacted]
Payment Type: Account

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 7130	7254	RW7130K030480	W181375	

Service Reminders:

EF100	ENVIRO FEE	1.00	$1.00	$1.00	Y
EF50	ENVIRO FEE	1.00	$0.50	$0.50	Y
SERVACCESS	SERVICE ACCESSORIES	1.00	$20.76	$20.76	Y

Labor: $346.00 **Parts: $120.19** **OL&M: $0.00** **Misc: $22.26** **Sub-Total: $488.45**

/100501207130 Retail

COMPLAINT:

21 MFWD PINION INPUT SHAFT SEAL REPLACE, FRONT AXLE PINION SHAFT SEAL

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AL159591	SEAL	1.00	$57.93	$57.93	Y
L156850	O-Ring	1.00	$5.39	$5.39	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$19.72	$19.72	Y

Labor: $328.70 **Parts: $63.32** **OL&M: $0.00** **Misc: $19.72** **Sub-Total: $411.74**

/1503267130 Retail

COMPLAINT:

22 REPLACE HOOD SHOCK AND ADJUST LATCH. SHOCK WAS PREVIOUSLY BROKEN AND HELD IN PLACE WITH A WIRE WHICH HAS BROKEN.

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AL174087	GAS OPERATED CYLINDER	2.00	$118.14	$236.28	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$7.79	$7.79	Y

SOUTH COUNTRY EQUIPMENT

#8 South Plains Road West
Emerald Park, SK S4L 1C6
Phone: 306-721-5050
www.southcountry.ca

Moose Jaw, SK	306-692-2371
Mossbank, SK	306-354-2411
Assiniboia, SK	306-642-3366
Emerald Park, SK	306-721-5050
Weyburn , SK	306-842-4686
Southey, SK	306-726-2155
Raymore, SK	306-746-2110
Montmartre, SK	306-424-2212

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 4026

[redacted]

Deliver To:

[redacted]

Bus Phone [redacted]
Prv Phone [redacted]

Invoice Number: [redacted]
Invoice Date 11/30/2023
Location:
Work Order Number: [redacted]
Payment Type: Account

Page: 11 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 7130	7254	RW7130K030480	W181375	

Service Reminders:

Labor: $129.75 **Parts: $236.28** **OL&M: $0.00** **Misc: $7.79** **Sub-Total: $373.82**

/100501207130 F Retail

COMPLAINT:

23 MFWD PINION INPUT SEAL, R&R MFWD DROP BOX OUTPUT SHAFT SEAL LEAKING

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AL229501	Seal	1.00	$73.76	$73.76	Y
L78683	O-RING	1.00	$9.79	$9.79	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$19.72	$19.72	Y

Labor: $328.70 **Parts: $83.55** **OL&M: $0.00** **Misc: $19.72** **Sub-Total: $431.97**

/100600407130 G F Retail

COMPLAINT:

24 INNER TIE ROD, R&R RH SIDE

CAUSE:

CORRECTION:

INNER TIE ROD WAS OK, BALL JOINT ON THE OUTER TIE ROD HAD EXCESSIVE PLAY. REMOVED AND REPLACED OUTER TIE ROD ON RH SIDE.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AL209601	BALL JOINT 28 MM THREADS	1.00	$297.93	$297.93	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$10.38	$10.38	Y

Labor: $173.00 **Parts: $297.93** **OL&M: $0.00** **Misc: $10.38** **Sub-Total: $481.31**

/8005R7130 Retail

COMPLAINT:

SOUTH COUNTRY EQUIPMENT

#8 South Plains Road West
Emerald Park, SK S4L 1C6
Phone: 306-721-5050
www.southcountry.ca

Moose Jaw, SK	306-692-2371
Mossbank, SK	306-354-2411
Assiniboia, SK	306-642-3366
Emerald Park, SK	306-721-5050
Weyburn , SK	306-842-4686
Southey, SK	306-726-2155
Raymore, SK	306-746-2110
Montmartre, SK	306-424-2212

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 4026

[redacted]

Deliver To:

[redacted]

Invoice Number: [redacted]
Invoice Date [redacted]/2023
Location: 04
Work Order Number: [redacted]
Payment Type: Account

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 7130	7254	RW7130K030480	W181375	

Service Reminders:

25 TOE IN ADJUST MFWD

CAUSE:

CORRECTION:

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	$5.19	$5.19	Y

Labor: $86.50 **Parts: $0.00** **OL&M: $0.00** **Misc: $5.19** **Sub-Total: $91.69**

/1413787130 Retail

COMPLAINT:

26 REPLACE CRANKSHAFT DAMPNER

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
19M7938	CAP SCREW	1.00	$1.80	$1.80	Y
19M8292	SCREW	6.00	$3.84	$23.04	Y
AL174123	TORSIONAL D	1.00	$1,286.81	$1,286.81	Y
AL223574	Bearing With Housing	1.00	$165.56	$165.56	Y
L112001	Bushing	2.00	$21.76	$43.52	Y
L220055	Cap Screw	4.00	$7.78	$31.12	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$57.09	$57.09	Y

Labor: $951.50 **Parts: $1,551.85** **OL&M: $0.00** **Misc: $57.09** **Sub-Total: $2,560.44**

/1406677130 Retail

COMPLAINT:

27 REPLACE BELT LINE LIGHT. LH FRONT WORK LIGHT HOUSING BROKEN

SOUTH COUNTRY EQUIPMENT

#8 South Plains Road West
Emerald Park, SK S4L 1C6
Phone: 306-721-5050
www.southcountry.ca

Moose Jaw, SK	306-692-2371
Mossbank, SK	306-354-2411
Assiniboia, SK	306-642-3366
Emerald Park, SK	306-721-5050
Weyburn , SK	306-842-4686
Southey, SK	306-726-2155
Raymore, SK	306-746-2110
Montmartre, SK	306-424-2212

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 4026

[redacted]

Deliver To:

[redacted]

Invoice Number: [redacted]
Invoice Date 11/30/2023
Location: 04
Work Order Number:
Payment Type: [redacted]

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 7130	7254	RW7130K030480	W181375	

Service Reminders:

CAUSE:

CORRECTION:

*** NOT DONE ***

Labor: $0.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $0.00**

GEN50- Retail

COMPLAINT:

28 REPLACE LH LIFT LINK ON THREE POINT HITCH ASSEMBLY. LINKAGE BETWEEN LOWER DRAFT ARM AND TOP ROCKSHAFT ARM ON LH SIDE WAS BENT.

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
34H385	SPRING PIN	1.00	$1.54	$1.54	Y
34M7328	Spring Pin	1.00	$3.51	$3.51	Y
L200756	LIFT LINK	1.00	$307.29	$307.29	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$5.19	$5.19	Y

Labor: $86.50 **Parts: $312.34** **OL&M: $0.00** **Misc: $5.19** **Sub-Total: $404.03**

GEN51- Retail

COMPLAINT:

29 DIAGNOSE SCV#1 NOT WORKING PROPERLY. FLOW ADJUSTMENT KNOB WOULD TURN BUT THERE WAS NO FLOW COMING FROM THE COUPLERS. SCV DOES ENGAGE WITH THE LEVER. TESTED STALL PRESSURE USING ALL 3 SCVS, BUT MEASURED 0 GPM THROUGH SCV 1.

CAUSE:

CORRECTION:

REMOVED FLOW CONTROL VALVE FROM SCV 1 BLOCK, FOUND ROLL PIN INSIDE KNOB WAS BROKEN. REPLACED KNOB AND

SOUTH COUNTRY EQUIPMENT

#8 South Plains Road West
Emerald Park, SK S4L 1C6
Phone: 306-721-5050
www.southcountry.ca

Moose Jaw, SK	306-692-2371
Mossbank, SK	306-354-2411
Assiniboia, SK	306-642-3366
Emerald Park, SK	306-721-5050
Weyburn, SK	306-842-4686
Southey, SK	306-726-2155
Raymore, SK	306-746-2110
Montmartre, SK	306-424-2212

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 4026

[redacted]

Deliver To:

[redacted]

Invoice Number: [redacted]
Invoice Date 11/30/2023
Location: 04
Work Order Number:
Payment Type: [redacted]

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 7130	7254	RW7130K030480	W181375	

Service Reminders:

ROLL PIN. REINSTALLED VALVE. CONNECTED FLOW METER TO SCV 1 COUPLERS. TESTED OPERATION OF SCV 1. FLOW MEASURED 25 GPM, SPEC IS 25.4 GPM.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
34H184	Spring Pin	1.00	$1.21	$1.21	Y
AL177612	Selective Control Valve	1.00	$79.28	$79.28	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$10.38	$10.38	Y

Labor: $173.00 **Parts: $80.49** **OL&M: $0.00** **Misc: $10.38** **Sub-Total: $263.87**

/1405877130 Retail

COMPLAINT:

30 REPLACE SMV SIGN MISSING

CAUSE:

CORRECTION:

*** NOT DONE ***

Labor: $0.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $0.00**

/1203257130 F Retail

COMPLAINT:

31 SUPPLY AFTER MARKET RADIO. TURNS ON BUT THERE IS NO SOUND AND THE VOLUME KNOB IS NOT WORKING PROPERLY

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
SWJHD62	Radio	1.00	$504.06	$504.06	Y

Labor: $0.00 **Parts: $504.06** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $504.06**

/1405867130 Retail

SOUTH COUNTRY EQUIPMENT

#8 South Plains Road West
Emerald Park, SK S4L 1C6
Phone: 306-721-5050
www.southcountry.ca

Moose Jaw, SK	306-692-2371
Mossbank, SK	306-354-2411
Assiniboia, SK	306-642-3366
Emerald Park, SK	306-721-5050
Weyburn , SK	306-842-4686
Southey, SK	306-726-2155
Raymore, SK	306-746-2110
Montmartre, SK	306-424-2212

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 4026

[redacted]

Deliver To:

[redacted]

Invoice Number: [redacted]
Invoice Date 11/30/2023
Location: 04
Work Order Number:
Payment Type: [redacted]

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 7130	7254	RW7130K030480	W181375	

Service Reminders:

COMPLAINT:

32 REPLACE FRONT AND REAR WIPERS

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AL153660	WIPER BLADE	1.00	$39.42	$39.42	Y
AL153661	WIPER BLADE	1.00	$64.36	$64.36	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$3.63	$3.63	Y

Labor: $60.55 **Parts: $103.78** **OL&M: $0.00** **Misc: $3.63** **Sub-Total: $167.96**

GEN52- Retail

COMPLAINT:

33 REPLACE FRONT WASHER FLUID PUMP, REAR WORKS, FRONT DOES NOT.

CAUSE:

CORRECTION:

REPLACED PUMP AND TOPPED UP WASHER FLUID. TESTED OPERATION, CLEANED FRONT NOZZLE.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AL79013	PUMP	1.00	$94.27	$94.27	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$7.79	$7.79	Y

Labor: $129.75 **Parts: $94.27** **OL&M: $0.00** **Misc: $7.79** **Sub-Total: $231.81**

GEN53- Retail

COMPLAINT:

34 REPLACE WIPER BLADE ARM ON REAR WIPER MOTOR, BENT AND IT GETS JAMMED IN ONE PLACE WHEN WIPER IS TURNED ON.

SOUTH COUNTRY EQUIPMENT

#8 South Plains Road West
Emerald Park, SK S4L 1C6
Phone: 306-721-5050
www.southcountry.ca

Moose Jaw, SK	306-692-2371
Mossbank, SK	306-354-2411
Assiniboia, SK	306-642-3366
Emerald Park, SK	306-721-5050
Weyburn , SK	306-842-4686
Southey, SK	306-726-2155
Raymore, SK	306-746-2110
Montmartre, SK	306-424-2212

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 4026

[redacted]

Deliver To:

[redacted]

Invoice Number: [redacted]
Invoice Date 11/30/2023
Location: 04
Work Order Number: [redacted]
Payment Type: Account

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 7130	7254	RW7130K030480	W181375	

Service Reminders:

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AL153662	WIPER ARM	1.00	$244.62	$244.62	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$4.15	$4.15	Y

Labor: $69.20 **Parts: $244.62** **OL&M: $0.00** **Misc: $4.15** **Sub-Total: $317.97**

GEN54- Retail

COMPLAINT:

35 CLEAN SCV COUPLERS AND REPLACE DUST SEALS ON SCV 2 COUPLERS.

CAUSE:

CORRECTION:

FOUND BOTTOM SLEEVE AND CLIP WERE MISSING ON SCV 3, REPLACED MISSING PARTS.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AL177680	COVER GREEN DOORS	1.00	$87.86	$87.86	Y
L158630	Clip	1.00	$5.35	$5.35	Y
L218748	Sleeve	1.00	$16.17	$16.17	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
SERVACCESS	SERVICE ACCESSORIES	1.00	$7.79	$7.79	Y

Labor: $129.75 **Parts: $109.38** **OL&M: $0.00** **Misc: $7.79** **Sub-Total: $246.92**

/1100047130 F Retail

COMPLAINT:

36 GREASE MACHINE COMPLETE

CAUSE:

CORRECTION:

SOUTH COUNTRY EQUIPMENT

#8 South Plains Road West
Emerald Park, SK S4L 1C6
Phone: 306-721-5050
www.southcountry.ca

Moose Jaw, SK	306-692-2371
Mossbank, SK	306-354-2411
Assiniboia, SK	306-642-3366
Emerald Park, SK	306-721-5050
Weyburn , SK	306-842-4686
Southey, SK	306-726-2155
Raymore, SK	306-746-2110
Montmartre, SK	306-424-2212

JOHN DEERE

Invoice To Account No: 4026

Deliver To:

SERVICE INVOICE

[redacted]

Invoice Number: [redacted]
Invoice Date 11/30/2023
Location: 04
Work Order Number: [redacted]
Payment Type: Account

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 7130	7254	RW7130K030480	W181375	

Service Reminders:
*** NOT DONE ***

Labor: $0.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $0.00**

GEN56- Retail

COMPLAINT:

38 REPLACE HOOD CABLE

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AL156954	Rope	1.00	$67.61	$67.61	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
LABORDISC	SERVICE LBR DISCOUNT	1.00	-$86.74	-$86.74	Y

Labor: $86.74 **Parts: $67.61** **OL&M: $0.00** **Misc: -$86.74** **Sub-Total: $67.61**

/GLOPCLEAN7130 F Retail

COMPLAINT:

39 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST

CAUSE:

CORRECTION:

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
GLWASHDISC	GREENLIGHT WASHING DISCOUNT	1.00	-$657.32	-$657.32	Y

Labor: $657.32 **Parts: $0.00** **OL&M: $0.00** **Misc: -$657.32** **Sub-Total: $0.00**

/GLDISC Retail

COMPLAINT:

40 GREENLIGHT INCENTIVE DISCOUNT

SOUTH COUNTRY EQUIPMENT

#8 South Plains Road West
Emerald Park, SK S4L 1C6
Phone: 306-721-5050
www.southcountry.ca

Moose Jaw, SK	306-692-2371
Mossbank, SK	306-354-2411
Assiniboia, SK	306-642-3366
Emerald Park, SK	306-721-5050
Weyburn , SK	306-842-4686
Southey, SK	306-726-2155
Raymore, SK	306-746-2110
Montmartre, SK	306-424-2212

JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 4026

Deliver To:

[redacted]

[redacted]

Invoice Number: [redacted]
Invoice Date 11/30/2023
Location: 04
Work Order Number:
Payment Type: [redacted]

Page: 18 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2016 JOHN DEERE 7130	7254	RW7130K030480	W181375	

Service Reminders:

CAUSE:

CORRECTION:

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
GLPDISCPTS	GL PARTS DISCOUNT PARTS	1.00	-$407.85	-$407.85	Y
GLPDISCSVC	GL PARTS DISCOUNT SERVICE	1.00	-$407.85	-$407.85	Y

Labor: $0.00 **Parts: $0.00** **OL&M: $0.00** **Misc: -$815.70** **Sub-Total: -$815.70**

Customer PO No:
Tax Exempt No: ONFILE
Advisor: STEVE KALLICHUK

GST Registration No: 897357802

Labor:	$9,770.26
Parts:	$8,157.06
OL&M:	$0.00
Misc:	-$1,132.01
GST:	$839.77
PST:	$0.00
Total:	$17,635.08

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.
I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held resposible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by: ..... Date: .....