

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

[Redacted] Bus Phone: Prv Phone:	[Redacted] Bus Phone: Prv Phone:	Invoice Number: [Redacted] Invoice Date: 7/3/2025 Location: 10 Work Order Number: [Redacted] Payment Type: Account Page: 1 of 11
--	--	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	790	1H0X910XJP0825262	105262	

JGLC JD X SERIES ALL Internal

COMPLAINT:

01 X9 SERIES COMBINE VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER


CORRECTION:

VALUEMAX GREEN LIGHT SELF PROPELLED COMBINE CHECKLIST

HEADER SERIAL # _____
 ENGINE HOURS _____ 791 _____
 SEPERATOR HOURS _____ 516 _____

DOES THIS UNIT GET A VALUEMAX STICKER ☒ YES ☐ NO
 HAS THE STICKER BEEN INSTALLED ☒ YES ☐ NO
 THIS UNIT HAS HAD THE CAB CLEANED _____ Is _____ (INITIAL)
 THIS UNIT HAS HAD A FINAL CHECKOVER _____ Is _____ (INITIAL)
 THIS UNIT HAS HAD A COMPLETE GREASE JOB _____ Is _____ (INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMERS INSTRUCTIONS:



Job Total: \$3,860.00

DIAG-1000000171161 Internal

COMPLAINT:

07 Hydraulic Reservoir, Diagnose and Repair 1.

CORRECTION:

Replaced clamp. checked, no leaks. Done

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY22062	HY-GARD J20C 9.46L	1.00	85.28	85.28	\$85.28	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/3/2025 Location: 10 Work Order Number: [REDACTED] Payment Type: Account Page: 2 of 11
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	790	1H0X910XJP0825262	105262	

DIAG-1000000171161 Internal

EF150	ENVIRO FEE	1.00	1.50	1.50	\$1.50	N
-------	------------	------	------	------	--------	---

Labor: \$205.90	Parts: \$85.28	OL&M: \$0.00	Misc: \$1.50	Sub-Total: \$292.68
------------------------	-----------------------	-------------------------	---------------------	----------------------------

EXPERT-1000000163000 Internal

COMPLAINT:

09 ValueMax Cab Clean.

CORRECTION:

START CLEANING THE INSIDE CAB, WASH AND CLEANED THE FLOOR MATS, LEFT HAND CONTROLLERS, FRIDGE, MONITORS, HVAC VENT, AND SEATS.

Labor: \$230.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$230.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

DIAG-1000000213038 Internal

COMPLAINT:

13 Grain Tank Camera, Diagnose and Repair 1.

CORRECTION:

replaced controller. camera work. Done

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
PFA12758	Electronic Control Unit	1.00	5,948.51	5,948.51	\$5,948.51	N

Labor: \$271.96	Parts: \$5,948.51	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$6,220.47
------------------------	--------------------------	-------------------------	---------------------	------------------------------

DIAG-1000000169882 Internal

COMPLAINT:

17 Active Tailings Camera, Diagnose and Repair 1.

CORRECTION:

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/3/2025 Location: 10 Work Order Number: [REDACTED] Payment Type: Account Page: 3 of 11
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	790	1H0X910XJP0825262	105262	

DIAG-1000000169882 Internal

Checked the Tailing and clean grain cameras, I moved them to another combine, both cameras work on it. Checked the electrical wiring, no damage.

I removed the controller from another working combine and installed it, the cameras are working. The controller needs to be replaced.

Labor: \$282.40	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$282.40
------------------------	----------------------	-------------------------	---------------------	----------------------------

EXPERT-1000000230206 Internal

COMPLAINT:

31 Rotor Plastic Dust Shroud, Remove and Replace.

CORRECTION:

COMPLETED THE REPLACEMENT OF THE ROTOR PLASTIC DUST SHROUD RIGHT HAND SIDE.

NOTE: BECAUSE THE FEEDER HOUSING IS LIFTED AND NO WAY TO LOWER IT DOWN DUE TO THE PENDING WORK ON THE LEFT HAND FINAL DRIVE IS OUT AND NO WHEEL, ONLY JACK STAND AND BOTTLE JACK ON THE FLOOR, IT TAKES ME A WHILE TO COMPLETE THIS JOB DUE TO SMALL SPACE WORKING AREA.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE142307	COVER, RIGHT, HOOVER SCOOP	1.00	503.69	503.69	\$503.69	N

Labor: \$100.00	Parts: \$503.69	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$603.69
------------------------	------------------------	-------------------------	---------------------	----------------------------

EXPERT-1000000088467 Internal

COMPLAINT:

34 Update All Controller Software.

CORRECTION:

PATTISON AGRICULTURE LIMITED
610 3rd Avenue West, Box 1670
Shaunavon, SK S0N 2M0
Phone: (306) 297-2639
Fax: (306) 297-3827
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

		Invoice Number:
		Invoice Date: 7/3/2025
		Location: 10
		Work Order Number:
		Payment Type: Account
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	
		Page: 4 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	790	1H0X910XJP0825262	105262	

EXPERT-1000000088467 Internal

1. Update all available controller software to the latest version of Software available.

In order to start the update, i had to diagnose and repair code POD 517931.04.
fuse is out of order, replace fuse- code is active.
removed the controller connectors, some pins have corrosion. Protected against corrosion, the code disappeared.
Start update
ATX-Steering Controller

4/7/2025
DEFHEADER-DEF Header
FED-Front End Domain Controller
HAD-Harvesting Domain Controller
HDE-HAD Domain Extender
MG2-StarFire 7000 Integrated
POD-Powertrain Domain Controller
TLM-Tailings Monitor

OSD-Operator Station Domain Controller

Labor: \$400.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$400.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

EXPERT-1000000241271 Internal

COMPLAINT:
35 X9 Used Combine, Wash and Prepare for Display.

CORRECTION:

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

[Redacted] Bus Phone: Prv Phone:	[Redacted] 43 Bus Phone: Prv Phone:	Invoice Number: [Redacted] Invoice Date: 7/3/2025 Location: 10 Work Order Number: [Redacted] Payment Type: Account Page: 5 of 11
--	---	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	790	1H0X910XJP0825262	105262	

EXPERT-1000000241271 Internal

1. Blow off all chaff off of the combine.
2. Wash out radiator and all coolers.
3. Clean out grain tank and unloading auger.
4. Wash exterior panels and all shields.
5. Vacuum cab and wash floor mat.
6. Clean windows.

This segment was used to install the front wheels. (final drive segment is closed) search and transfer of wheels to the shop.

It took a long time because the wheels were installed on the combine without using a forklift. it was installed manually due to limited space.

Wheels are installed and tightened to the correct torque. Done.

P.S. NEED WASH COMBINE AND CLEAN CAB

Labor: \$2,070.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,070.00
--------------------------	----------------------	-------------------------	---------------------	------------------------------

EXPERT-1000000073841 Internal

COMPLAINT:

37 Feeder House Backshaft Bearing, Remove and Replace.

CORRECTION:

1. Loosen the feeder house drive chain tensioner.
 2. Remove chain from sprocket.
 3. Remove the shifter and the sprocket.
 4. Disconnect speed sensor.
 5. Remove the tone wheel.
 6. Remove bearing housing cap screws, bottom cap screw and nut.
 7. Install the new bearing and secure bearing holder with cap screws.
 8. Install bearing housing cap screws, bottom cap screw and nut. Tighten to specification.
 9. Apply Thread Lock and Sealer (High Strength) to the tone wheel. Install on the shaft and tighten to specification.
 10. Connect speed sensor.
 11. Apply Anti-Seize to the splines on the shaft.
 12. Install the sprocket, shifter, and chain.
 13. Use a pry bar in the holes on the inside plate and move the chain tensioner forward. Tighten the nut to specification.
- Replaced. Done.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

[Redacted] Bus Phone: Prv Phone:	[Redacted] Bus Phone: Prv Phone:	Invoice Number: [Redacted] Invoice Date: 7/3/2025 Location: 10 Work Order Number: [Redacted] Payment Type: Account Page: 6 of 11
--	--	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	790	1H0X910XJP0825262	105262	

EXPERT-1000000073841 Internal

AXE86012	BEARING HO	1.00	623.24	623.24	\$623.24	N
HXE152597	Nut	1.00	233.84	233.84	\$233.84	N

Labor: \$200.00	Parts: \$857.08	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,057.08
------------------------	------------------------	-------------------------	---------------------	------------------------------

EXPERT-1000000139767 Internal

COMPLAINT:

40 Concave Level and Adjust.

CORRECTION:

1. Start engine and press the threshing clearance adjust switch.
 2. Set threshing clearance to 0.
 3. Remove the front separator grate deflector.
 4. Remove cap screws, cap screws and nuts, and the front separator grate.
 5. Move handle to shift the rotor gear case in the neutral position.
 6. Loosen the lower lock nut, lower adjustment nut, and the upper lock nut on the front and rear concave cylinders.
 7. While turning the left-hand rotor clockwise by hand, tighten the upper adjustment nut slowly on the front concave cylinder until the elements "tick" against the rotor. Back off the nut one full turn. Tighten nut finger tight.
 8. While turning the right-hand rotor counterclockwise by hand, tighten the upper adjustment nut slowly on the front concave cylinder until the elements "tick" against the rotor. Back off the nut one full turn. Tighten nut finger tight.
 9. Tighten the lower adjustment nut on the front and rear concave cylinders to specification.
 10. Tighten the upper and lower lock nuts.
 11. Perform the calibration. (See Supporting Documents - User Calibrations - Procedures).
- Done

Labor: \$1,000.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,000.00
--------------------------	----------------------	-------------------------	---------------------	------------------------------

DIAG-1000000090224 Internal

COMPLAINT:

44 Diagnose and Repair Active Trouble Codes 1.

CORRECTION:

1. Diagnose active trouble code. Run combine. checked codes. dont have codes. Done

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/3/2025 Location: 10 Work Order Number: [REDACTED] Payment Type: Account Page: 7 of 11
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	790	1H0X910XJP0825262	105262	

DIAG-1000000090224 Internal

Labor: \$200.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$200.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

DIAG-1000000212618 Internal

COMPLAINT:
 46 Calibrate grain tank cover

CORRECTION:
 Done.

Labor: \$100.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$100.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

DIAG-1000000170753 Internal

COMPLAINT:
 50 Clean Grain Elevator Top Shaft, Sprocket and Bearings, Diagnose and Repair 1.

CORRECTION:
 replaced. Done.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE86009	Bearing With Housing	1.00	272.33	272.33	\$272.33	N
AXE86016	Bearing With Housing, HEX ID	1.00	196.53	196.53	\$196.53	N
Labor: \$300.00		Parts: \$468.86	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$768.86	

DIAG-1000000090221 Internal

COMPLAINT:
 53 Diagnose and Repair Stored Trouble Codes 1. Tailing camera not working

CORRECTION:
 1. Diagnose stored trouble code.

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

[Redacted] Bus Phone: Prv Phone:	[Redacted] Bus Phone: Prv Phone:	Invoice Number: [Redacted] Invoice Date: 7/3/2025 Location: 10 Work Order Number: [Redacted] Payment Type: Account Page: 8 of 11
--	--	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	790	1H0X910XJP0825262	105262	

DIAG-1000000090221 Internal

Labor: \$200.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$200.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

EXPERT-1000000074401 Internal

COMPLAINT:

56 Grain Tank Loading Auger Bearing & Auger, Remove and Replace.

CORRECTION:

1. Open grain tank covers fully.
2. Remove cap screw and washer.
3. Remove carriage bolts and bearing assembly.
4. Install parts in reverse order.

the old auger was replaced with a new one according to the instructions.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE85993	Bearing With Housing, GRAINTANK CRO	1.00	238.55	238.55	\$238.55	N
AXE89023	X9 LOADING AUGER EXT WEAR	1.00	3,996.38	3,996.38	\$3,996.38	N
HXE142368	Washer	1.00	37.48	37.48	\$37.48	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
frt	FREIGHT	1.00	350.00	350.00	\$350.00	N
Labor: \$100.00	Parts: \$4,272.41	OL&M: \$0.00	Misc: \$350.00	Sub-Total: \$4,722.41		

EXPERT-1000000074127 Internal

COMPLAINT:

57 Clean Grain Elevator Mass Flow Sensor Impact Plate, Remove and Replace.

CORRECTION:

1. Disconnect connector.
2. Remove sensor.
3. Install in reverse order, tighten sensor to specification.

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	
		Invoice Date:	7/3/2025
		Location:	10
		Work Order Number:	
		Payment Type:	Account
		Page:	9 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	790	1H0X910XJP0825262	105262	

EXPERT-1000000074127 Internal

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE64829	MASS FLOW	1.00	273.60	273.60	\$273.60	N
Labor: \$200.00		Parts: \$273.60	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$473.60	

DIAG-1000000172270 Internal

COMPLAINT:

61 Front-End Gear Case, Hoses, Fittings, Mounting Hardware, and Drive Shaft Bearing, Diagnose and Repair 2.

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14H809	1/2-13 NUT GR5	1.00	1.82	1.82	\$1.82	N
19H1721	1/2x1-1/2 HH GR5 UNC BOLT	1.00	3.66	3.66	\$3.66	N
24H1360	Washer 5/8x1.469	2.00	2.67	2.67	\$5.34	N
H223849	Quad Ring	1.00	13.50	13.50	\$13.50	N
TY26353	Penetrating Oil 425g	1.00	15.10	15.10	\$15.10	N
Labor: \$600.00		Parts: \$39.42	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$639.42	

JGEN68- Internal

COMPLAINT:

68 Remove hitch and trailer wiring. These will be installed on their new units as they arrive

CORRECTION:

Labor: \$260.78	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$260.78
------------------------	----------------------	-------------------------	---------------------	----------------------------

JGEN72- Internal

COMPLAINT:

72 POWERGARD DEDUCTIBLE

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

[Redacted] Bus Phone: Prv Phone:	[Redacted] Bus Phone: Prv Phone:	Invoice Number: [Redacted] Invoice Date: 7/3/2025 Location: 10 Work Order Number: [Redacted] Payment Type: Account Page: 10 of 11
--	--	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	790	1H0X910XJP0825262	105262	

JGEN72- Internal

CORRECTION:

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
OTHERPG	POWERGARD DEDUCTIBLE	1.00	500.00	500.00	\$500.00	N
Labor: \$0.38		Parts: \$0.00	OL&M: \$0.00	Misc: \$500.00	Sub-Total: \$500.38	

JGEN74- Internal

COMPLAINT:

74 parts returned after segments were already closed

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE85994	BEARING WITH HOUSING, RETHRESHER	-1.00	209.17	209.17	(\$209.17)	N
AXE86003	Bearing With Housing	-1.00	268.95	268.95	(\$268.95)	N
AXE86013	Bearing With Housing	-1.00	251.42	251.42	(\$251.42)	N
AXE87791	Concave	-1.00	281.20	281.20	(\$281.20)	N
HXE142914	CONCAVE WIRE	-1.00	12.80	12.80	(\$12.80)	N

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

 Bus Phone: Prv Phone:	 Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 7/3/2025 Location: 10 Work Order Number: Payment Type: Account Page: 11 of 11
---	---	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	790	1H0X910XJP0825262	105262	

JGEN74- Internal

HXE149469	Bushing	-1.00	86.77	86.77	(\$86.77)	N
-----------	---------	-------	-------	-------	-----------	---

Labor: \$0.00	Parts: (\$1,110.31)	OL&M: \$0.00	Misc: \$0.00	Sub-Total: (\$1,110.31)
----------------------	----------------------------	-------------------------	---------------------	--------------------------------

INVOICE CONTAINS \$125.67 DISCOUNT

Miscellaneous Charges:

SERVICE ACCESSORIES	\$150.00
---------------------	----------

Customer PO No:

Tax Exempt No:

Advisor: Joanne Thronberg

*** DOCUMENT COPY ***

Job Total:	\$22,921.46
Grand Total:	\$22,921.46

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE -- MIN \$35 ON EMERGENCY/UNIT DOWN ORDERS -- 25% RESTOCKING FOR RET

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: Date: