



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	422482
Invoice Date	03/22/2021
Location:	03
Work Order Number:	173376
Payment Type:	Finance
Page:	1 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

/4WD9300 F Retail

COMPLAINT:

01 GREENLIGHT SERVICE INSPECTION 4WD TRACTOR
-10% OFF PARTS FOR GREENLIGHT BOOKING

CAUSE:

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
GLPROMOPTS	GL BOOKING PROMO PARTS	1.00	-\$454.23	-\$454.23	Y
GLPROMOSVC	GL BOOKING PROMO SERVICE	1.00	-\$454.23	-\$454.23	Y

Labor: \$1,199.00	Parts: \$0.00	OL&M: \$0.00	Misc: -\$908.46	Sub-Total: \$290.54
--------------------------	----------------------	-------------------------	------------------------	----------------------------

/4015A9300 F Retail

COMPLAINT:

02 BATTERY(IES), R&R OR REPLACE
-CHARGE AND RETEST BATTERIES (TESTED POORLY DURING CHECKOVER)
-CHANGE OUT BATTERY BOLTS (NOT IN VERY GOOD CONDITION)

CAUSE:

CORRECTION:

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY25876B-CR	CORE for:Wet Charged Battery	-3.00	\$18.00	-\$54.00	Y
TY25879B	Wet Charged Battery,BCI 31,CCA 950	3.00	\$246.24	\$738.72	Y
TY25908	BOLT AND N	3.00	\$1.00	\$3.00	Y

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$6.75	\$6.75	Y

Labor: \$112.50	Parts: \$687.72	OL&M: \$0.00	Misc: \$6.75	Sub-Total: \$806.97
------------------------	------------------------	-------------------------	---------------------	----------------------------

Gen3- Retail

COMPLAINT:



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	422482
Invoice Date	03/22/2021
Location:	03
Work Order Number:	173376
Payment Type:	Finance
Page:	2 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

03- ARE THERE ANY ISSUES WITH THE A-TRON HARNESS'S OPERATION THAT IS CONNECTED @ BATTERY BOX?
-GROUND WIRE RING CONNECTOR LOOSE ON NUT (NEED SMALLER TERMINAL)

CAUSE:

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$4.50	\$4.50	Y
Labor: \$75.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$4.50	Sub-Total: \$79.50	

/1701659300 Retail

COMPLAINT:

04 HEADLINER, REPLACE
-FALLING DOWN

-DO NOT REPAIR

CAUSE:

CORRECTION:

Remove:Mounting hardwareSun visorInside mirrorRadioSpeaker coversHeadlinerAssemble to specifications.

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
----------------------	----------------------	-------------------------	---------------------	--------------------------

/1201799300 F Retail

COMPLAINT:

05 REPLACE CAB AIR FILTERS
-DIRTY

-DO NOT REPAIR CUSTOMER WILL DO

CAUSE:

CORRECTION:



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	422482
Invoice Date	03/22/2021
Location:	03
Work Order Number:	173376
Payment Type:	Finance
Page:	3 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
---------------	---------------	--------------	--------------	-------------------

Gen6- Retail

COMPLAINT:

06- CAB ROOF NOT SITTING DOWN IN THE GROOVE WHERE IT SUPPOSED TO, MAY LEAK
-LOOSEN SCREWS AND PUT WHERE IT BELONGS

-DO NOT REPAIR

CAUSE:

CORRECTION:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
---------------	---------------	--------------	--------------	-------------------

GEN7- Retail

COMPLAINT:

07- REPAIR FLASHER CIRCUIT, NEITHER REAR FACING CAB FLASHER WORKING (MAY JUST BE BULBS)

-DO NOT REPAIR

CAUSE:

CORRECTION:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
---------------	---------------	--------------	--------------	-------------------

GEN8- Retail

COMPLAINT:

08- REPAIR REAR WORK LIGHT CIRCUIT, NEITHER INNER REAR FACING FENDER MOUNTED LIGHTS COMING ON



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	422482
Invoice Date	03/22/2021
Location:	03
Work Order Number:	173376
Payment Type:	Finance
Page:	4 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

CAUSE:

CORRECTION:

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE49904	LAMP	2.00	\$62.90	\$125.80	Y
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$9.00	\$9.00	Y
Labor: \$150.00	Parts: \$125.80	OL&M: \$0.00	Misc: \$9.00	Sub-Total: \$284.80	

/1702229300 F Retail

COMPLAINT:

09 TOP UP WASHER FLUID
-RETEST SQUIRTER'S ONCE IT IS REFILLED
-DO NOT REPAIR

CAUSE:

CORRECTION:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
----------------------	----------------------	-------------------------	---------------------	--------------------------

/1100189300 F Retail

COMPLAINT:

10 REPLACE ENGINE AIR FILTERS
-REPLACE OUTER ENGINE AIR FILTER (DIRTY)
-INNER LOOKS VERY CLEAN YET

-DO NOT REPAIR CUSTOMER WILL DO

CAUSE:

CORRECTION:



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	422482
Invoice Date	03/22/2021
Location:	03
Work Order Number:	173376
Payment Type:	Finance
Page:	5 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
---------------	---------------	--------------	--------------	-------------------

GEN11- Retail

COMPLAINT:

11- OILY DRIP COMING FROM EXHAUST MANIFOLD JOINT, CHECKOUT WHERE IT IS COMING FROM AND REPAIR ISSUE
- POSSIBLE COLD ENG SLOBBER

-DO NOT REPAIR

CAUSE:

CORRECTION:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
---------------	---------------	--------------	--------------	-------------------

/100200129300 F Retail

COMPLAINT:

12 ENGINE VALVE CLEARANCE, CHECK AND ADJUST
-ASK WHEN IT WAS DONE LAST
- PART OF SEG WILL BE DONE WITH INJECTOR CUPS

-DONE WITH SEGMENT 37

CAUSE:

CORRECTION:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
---------------	---------------	--------------	--------------	-------------------

/100200409300 F Retail

COMPLAINT:

13 DAMPER, CRANKSHAFT R+R
-REPLACE CRANKSHAFT DAMPNER (4500 HR SERVICE INTERVAL)



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number: 422482
Invoice Date: 03/22/2021
Location: 03
Work Order Number: 173376
Payment Type: Finance
Page: 6 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

CAUSE:

CORRECTION:

Remove beltRemove damperReplace front engine sealReinstall in reverse order

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
19M7774	SCREW	1.00	\$1.06	\$1.06	Y
R519753	WASHER	1.00	\$56.21	\$56.21	Y
RE523266	TORSIONAL D	1.00	\$1,459.84	\$1,459.84	Y
RE54073	SEAL	1.00	\$137.09	\$137.09	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$45.00	\$45.00	Y

Labor: \$750.00 Parts: \$1,654.20 OL&M: \$0.00 Misc: \$45.00 Sub-Total: \$2,449.20

/1201809300 F Retail

COMPLAINT:

14 REPLACE TIMING GEAR COVER GASKET ONLY
-LEAKING ON LH SIDE NEAR TOP
- WHILE WORKING ON OIL LEAK, NOTICED THAT THE VISCOUS FAN HUB SEAL WAS LEAKING, SHOWED CUSTOMER AND DECIDED TO CHANGE HUB
- WORK FOR HUB WAS DONE WITH THIS SEG

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
PM38628	HF Gskt Maker	1.00	\$31.54	\$31.54	Y
R500214	GASKET	1.00	\$85.68	\$85.68	Y
RE170600	VISCOUS FAN	1.00	\$2,701.28	\$2,701.28	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$63.00	\$63.00	Y

Labor: \$1,050.00 Parts: \$2,818.50 OL&M: \$0.00 Misc: \$63.00 Sub-Total: \$3,931.50

GEN15- Retail



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Souhey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	422482
Invoice Date	03/22/2021
Location:	03
Work Order Number:	173376
Payment Type:	Finance
Page:	7 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

COMPLAINT:

15- REPAIR OIL LEAK @ T-FITTING ON BOTTOM OF HYD RESERVOIR (O-RINGS OR HOSE CLAMP POSSIBLY)

CAUSE:

CORRECTION:

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE254817	HOSE	1.00	\$100.04	\$100.04	Y
TY22465	HOSE CLAMP	2.00	\$2.00	\$4.00	Y
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$18.00	\$18.00	Y

Labor: **\$300.00** Parts: **\$104.04** OL&M: **\$0.00** Misc: **\$18.00** Sub-Total: **\$422.04**

GEN16- Retail

COMPLAINT:

16- REPLACE SHORT FUEL LINE/HOSE AT THE BACK OF THE HEAD, APPEARS TO BE LEAKING AT THE CRIMP (BAD LEAK)

CAUSE:

CORRECTION:

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE504311	Hose	1.00	\$115.70	\$115.70	Y
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$6.75	\$6.75	Y

Labor: **\$112.50** Parts: **\$115.70** OL&M: **\$0.00** Misc: **\$6.75** Sub-Total: **\$234.95**

/100200509300 F Retail

COMPLAINT:

17 ENGINE, FRONT SEAL R+R

-REPLACE ENGINE FRONT SEAL (DAMP BEHIND FRONT DAMNER)

- WOULD SUGGEST REPLACING FRONT DAMPENER AT THIS TIME IF HASN'T BEEN DONE YET



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	422482
Invoice Date	03/22/2021
Location:	03
Work Order Number:	173376
Payment Type:	Finance
Page:	8 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

CAUSE:

CORRECTION:

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE54073	SEAL	1.00	\$137.09	\$137.09	Y
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$9.00	\$9.00	Y
Labor: \$150.00	Parts: \$137.09	OL&M: \$0.00	Misc: \$9.00	Sub-Total: \$296.09	

GEN18- Retail

COMPLAINT:

18- REPLACE LARGE HOSE THAT GOES FROM BOTTOM OF HYD OIL RESERVOIR TO HYD PUMP, LEAKING IN THAT AREA (HOSE IS CRACKED)
-WOULD HAVE TO DRAIN RES TO CHANGE LINE

CAUSE:

CORRECTION:

hat to completely drain the hydraulic system and remove the resevoir to get this chunk of hose out

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
R154049	SUCTION HO	1.00	\$50.20	\$50.20	Y
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$27.00	\$27.00	Y
Labor: \$450.00	Parts: \$50.20	OL&M: \$0.00	Misc: \$27.00	Sub-Total: \$527.20	

GEN19- Retail

COMPLAINT:

19- REPLACE HOSE ON LOWER LH FRONT SIDE OF RESERVOIR (WHILE RESERVOIR IS DRAINED FROM THE ABOVE)
-HOSE IS VERY CRACKED UP AND LIKELY WONT BE LONG UNTIL IT STARTS LEAKING

CAUSE:

CORRECTION:



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number: **422482**
Invoice Date: 03/22/2021
Location: 03
Work Order Number: 173376
Payment Type: Finance
Page: 9 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
R136553	SUCTION HOSE	1.00	\$53.41	\$53.41	Y
TY22470	HOSE CLAMP # 32	1.00	\$2.01	\$2.01	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$6.75	\$6.75	Y

Labor: **\$112.50** Parts: **\$55.42** OL&M: **\$0.00** Misc: **\$6.75** Sub-Total: **\$174.67**

/100501009300 F Retail

COMPLAINT:

20 TRANSMISSION INPUT SEAL, R & R
-LEAKING A BIT

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE158082	SEAL	1.00	\$109.03	\$109.03	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$22.50	\$22.50	Y

Labor: **\$375.00** Parts: **\$109.03** OL&M: **\$0.00** Misc: **\$22.50** Sub-Total: **\$506.53**

GEN21- Retail

COMPLAINT:

21- REPAIR LEAK @ BOTTOM OF TRANSMISSION, HOSE THAT GOES FROM SIDE LITTLE RESERVOIR ON RH SIDE TO TRANSMISSION
-VERY DIRTY WITH OIL (MAYBE HOSE, COULD BE CLAMPS)

CAUSE:

CORRECTION:



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number: **422482**
Invoice Date: 03/22/2021
Location: 03
Work Order Number: 173376
Payment Type: Finance
Page: 10 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$9.00	\$9.00	Y
Labor: \$150.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$9.00	Sub-Total: \$159.00	

GEN22- Retail

COMPLAINT:

22- TRANSMISSION IS CURRENTLY OVERFULL, COMING UP THE FILL TUBE
-CHECK INTO THE ISSUE
- RUN TRACTOR AND RECHECK LEVEL
- ASK CUSTOMER IF HE HAD NOTICED IT GOING UP SLOWLY AND RES GOING DOWN

CAUSE:

CORRECTION:

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$4.50	\$4.50	Y
Labor: \$75.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$4.50	Sub-Total: \$79.50	

/1500369300 G Retail

COMPLAINT:

23 REPLACE COOLANT
-LOOKS TO BE A VERY MUCKY BROWN COLOR

CAUSE:

CORRECTION:

cooling system was very very dirty, flushed a few times to get all the goop out o fit.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
PMCC2610X	Restore	1.00	\$38.62	\$38.62	Y
TY26576	COOL-GARD 9.46 L PREMIX	5.00	\$45.06	\$225.30	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF240	ENVIRO FEE	7.00	\$2.40	\$16.80	Y
SERVACCESS	SERVICE ACCESSORIES	1.00	\$32.67	\$32.67	Y



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Souhey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	422482
Invoice Date	03/22/2021
Location:	03
Work Order Number:	173376
Payment Type:	Finance
Page:	11 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

Labor: \$544.50	Parts: \$263.92	OL&M: \$0.00	Misc: \$49.47	Sub-Total: \$857.89
------------------------	------------------------	-------------------------	----------------------	----------------------------

/1100689300 F Retail

COMPLAINT:

24 CHANGE FUEL FILTERS
-NOT SURE WHEN DONE LAST

-DO NOT REPAIR

CAUSE:

CORRECTION:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
----------------------	----------------------	-------------------------	---------------------	--------------------------

/1200009300 F Retail

COMPLAINT:

25 CHANGE ENGINE OIL AND FILTER
-NOT SURE WHEN DONE LAST
-ENGINE OIL DRAIN VALVE LEAKING (REPAIR)

-DO NOT REPAIR

CAUSE:

CORRECTION:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
----------------------	----------------------	-------------------------	---------------------	--------------------------

/100600509300 F Retail

COMPLAINT:

26 STEERING CYLINDER BUSHINGS, PINS & FOAMS R&R
-REPLACE STEERING BUSHINGS AND POSSIBLY PINS (HAVE A FAIR AMOUNT OF PLAY)



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	422482
Invoice Date	03/22/2021
Location:	03
Work Order Number:	173376
Payment Type:	Finance
Page:	12 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:
CAUSE:

CORRECTION:

Remove steering cylinder hydraulic lines. Remove cylinder pins and cylinder. Remove bushings. Install new bushings. Reassemble in reverse order.

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
H146227	BUSHING	4.00	\$27.99	\$111.96	Y
R112154	PIN FASTEN	4.00	\$214.12	\$856.48	Y
R94418	O-RING	4.00	\$9.51	\$38.04	Y
R94418	O-RING	4.00	\$9.20	\$36.80	Y
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$36.00	\$36.00	Y

Labor: \$600.00 Parts: \$1,043.28 OL&M: \$0.00 Misc: \$36.00 Sub-Total: \$1,679.28

/100600109400 G Retail

COMPLAINT:

27 STEERING CYLINDER, RECONDITION (ONE)
-RESEAL RH STEERING CYLINDER (SHAFT SEAL IS LEAKING QUITE A BIT)

CAUSE:

CORRECTION:

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH136453	PISTON	1.00	\$277.28	\$277.28	Y
AHC11572	Hydraulic Cylin	1.00	\$144.38	\$144.38	Y
AHC22108	Hydraulic Cylinder Kit	1.00	\$99.00	\$99.00	Y
R84824	SEAL	2.00	\$37.96	\$75.92	Y
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$30.60	\$30.60	Y

Labor: \$510.00 Parts: \$596.58 OL&M: \$0.00 Misc: \$30.60 Sub-Total: \$1,137.18

GEN28- Retail

COMPLAINT:



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	422482
Invoice Date	03/22/2021
Location:	03
Work Order Number:	173376
Payment Type:	Finance
Page:	13 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

28- TIGHTEN RH SIDE DASH SCREWS, CLOSEST TO WINDOW (LOOSE)

-DO NOT REPAIR

CAUSE:

CORRECTION:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
---------------	---------------	--------------	--------------	-------------------

GEN29- Retail

COMPLAINT:

29- REPAIR LEAK @ LOWER REAR RH FUEL TANK SMALL FITTING, O-RING ON FITTING OR FITTING LOOSE IN TANK

CAUSE:

CORRECTION:

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$4.05	\$4.05	Y
Labor: \$67.50	Parts: \$0.00	OL&M: \$0.00	Misc: \$4.05	Sub-Total: \$71.55	

/100500609300 F Retail

COMPLAINT:

30 AXLE SEAL REPLACEMENT

-RH FRONT AXLE SEAL LEAKING, REPLACE SEAL

-CHECK AXLE PLAY WITH WHEELS REMOVED, DIDN'T FEEL ANY MOVEMENT WHEN CHECKING OVER TRACTOR

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
------------	-------------	----------	-----------	----------------	-----------



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number: **422482**
Invoice Date: 03/22/2021
Location: 03
Work Order Number: 173376
Payment Type: Finance
Page: 14 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

RE168641	SEAL	1.00	\$171.91	\$171.91	Y
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$51.75	\$51.75	Y

Labor: \$862.50 Parts: \$171.91 OL&M: \$0.00 Misc: \$51.75 Sub-Total: \$1,086.16

/100500609400 G Retail

COMPLAINT:

31 AXLE SEAL REPLACEMENT
-LH REAR AXLE SEAL LEAKING (REPLACE SEAL
-WHILE DUALS ARE REMOVED CHECK AXLE PLAY

CAUSE:

CORRECTION:

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE168641	SEAL	1.00	\$171.91	\$171.91	Y
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	\$51.75	\$51.75	Y

Labor: \$862.50 Parts: \$171.91 OL&M: \$0.00 Misc: \$51.75 Sub-Total: \$1,086.16

GEN32- Retail

COMPLAINT:

32- REPLACE DE-ACCELERATOR SWITCH ON FLOOR (STAYS STUCK DOWN)
-DO NOT REPAIR

CAUSE:

CORRECTION:

Labor: \$0.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$0.00

GEN33- Retail



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	422482
Invoice Date	03/22/2021
Location:	03
Work Order Number:	173376
Payment Type:	Finance
Page:	15 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

COMPLAINT:

33- REPLACE LOWER CENTER SECTION OF STEERING COLUMN PLASTIC (BROKEN)
-REPLACE UPPER CENTER SECTION OF STEERING COLUMN PLASTIC (BROKEN)

-DO NOT REPAIR

CAUSE:

CORRECTION:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
---------------	---------------	--------------	--------------	-------------------

GEN34- Retail

COMPLAINT:

34- REPAIR TELESCOPING SHAFT FOR STEERING COLUMN (FAIR AMOUNT OF FLOP IN IT)

-DO NOT REPAIR

CAUSE:

CORRECTION:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
---------------	---------------	--------------	--------------	-------------------

GEN35- Retail

COMPLAINT:

35- TIGHTEN LOOSE BOLTS ON TOWER CENTER DASH SIDE PANELS (BY THE FLOOR MAT) LOOSE

-DO NOT REPAIR

CAUSE:

CORRECTION:



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Souhey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	422482
Invoice Date	03/22/2021
Location:	03
Work Order Number:	173376
Payment Type:	Finance
Page:	16 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
---------------	---------------	--------------	--------------	-------------------

/100301809300 F Retail

COMPLAINT:

36 UNIT INJECTOR CUPS/SLEEVES, R&R
-REPLACE INJECTOR CUPS

-SEND INJECTORS AWAY TO GET TESTED

CAUSE:

CORRECTION:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
R136507	SCREW	10.00	\$6.17	\$61.70	Y
R136508	SCREW	2.00	\$9.35	\$18.70	Y
R51936	SEALING WASHER	2.00	\$2.64	\$5.28	Y
R521520	GASKET	1.00	\$155.54	\$155.54	Y
RE528634	SLEEVE	6.00	\$119.76	\$718.56	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$89.00	\$89.00	Y

OL&M Charges:

Description	Value
INJECTOR TEST AND REPAIR	\$5,610.82

Labor: \$2,006.00	Parts: \$959.78	OL&M: \$5,610.82	Misc: \$89.00	Sub-Total: \$8,665.60
-------------------	-----------------	------------------	---------------	-----------------------

/1015E9300 F Retail

COMPLAINT:

37 LUBRICATION (GREASE)
-FINAL RUN AND CHECK

CAUSE:

CORRECTION:



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number: **422482**
Invoice Date: 03/22/2021
Location: 03
Work Order Number: 173376
Payment Type: Finance
Page: 17 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

Front differential front pivot pin bushing. Front differential rear pivot pin bushing. Front and rear axles. Upper and lower hinge pins. Front and rear U-joints of: Transmission input shaft PTO input shaft Front axle drive shaft Left and right rear steering cylinder pivot pins. Steering feedback cylinder rear pivot pin. Remote grease fittings: Steering cylinder front pivot pin Steering feedback cylinder front pivot pin Outer bearing support. Left and right lift arms. Center link. Wide swing drawbar

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
TY6341	Grease	1.00	\$5.86	\$5.86	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
GLPROMOSVC	GL BOOKING PROMO SERVICE	1.00	-\$150.00	-\$150.00	Y

Labor: **\$150.00** Parts: **\$5.86** OL&M: **\$0.00** Misc: **-\$150.00** Sub-Total: **\$5.86**

/GLOPCLEAN9300 F Retail

COMPLAINT:

38 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST

CAUSE:

CORRECTION:

___ WASH COMPLETE MACHINE (OPEN & WASH BEHIND ALL SHIELDS) ___ WAX IF REQUIRED ___ REMOVE ANY OTHER DEALER DECALS ___ INSTALL SCE DEALERSHIP DECALS ___ ALL FACTORY SAFETY AND MODEL DECALS IN GOOD CONDITION ___ REMOVE CAB FLOOR MAT AND CLEAN MAT AND FLOOR ___ CLEAN SEAT AND REMOVE STAINS IF NECESSARY ___ VACUUM CAB THOROUGHLY ___ CLEAN INSTRUMENT PANEL, OPERATOR CONTROLS, UPHOLSTERY, AND AIR DELIVERY LOUVERS ___ CLEAN WINDOWS AND MOLDINGS (OPEN WINDOWS TO CLEAN EDGES WHERE APPLICABLE) ___ ELIMINATE ANY CAB ODORS AND INSTALL AIR FRESHENER IF REQUIRED ___ PAINT AREAS THAT ARE BADLY SCRATCHED/DAMAGED - INCLUDING BUCKETS, GRAPPLES, WHEELS, EXHAUST, PLATFORM AUGERS (COMPLETE AUGER), CHOPPER FINS, FEEDERHOUSE DRUMS, BALER PICKUPS

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
GLPROMOSVC	GL BOOKING PROMO SERVICE	1.00	-\$671.22	-\$671.22	Y

Labor: **\$671.22** Parts: **\$0.00** OL&M: **\$0.00** Misc: **-\$671.22** Sub-Total: **\$0.00**

Finance Information

Customer PO No:	Type: AqLine	Auth No: 963661
Tax Exempt No:	Merchant No: 82000505	
Advisor: KELLY SAWIN	Card No: xxxxxxxxxxxx2414	
	Bill Code: 783 - PERFORMAX INSPECTION -	
	Credit Plan: 11395 - TRACTOR	
		180 DAY NPNI-INSPECTION

GST Registration No: 897357802

Labor: \$11,335.72
Parts: \$9,070.94
OL&M: \$5,610.82
Misc: -\$1,185.31
GST: \$1,241.61
PST: \$0.00
Total: \$26,073.78



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK	306-692-2371
Mossbank, SK	306-354-2411
Assiniboia, SK	306-642-3366
Emerald Park, SK	306-721-5050
Weyburn, SK	306-842-4686
Southey, SK	306-726-2155
Raymore, SK	306-746-2110
Montmartre, SK	306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	422482
Invoice Date	03/22/2021
Location:	03
Work Order Number:	173376
Payment Type:	Finance
Page:	18 of 18

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

TERMS AND CONDITIONS

This purchase is subject to the terms of the John Deere Financial Multi-Use Account Agreement. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by:

Date:



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	523254
Invoice Date	04/09/2022
Location:	03
Work Order Number:	196282
Payment Type:	Account
Page:	1 of 3

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

Gen1- Retail

COMPLAINT:

01- REPAIR OIL TRANSFER ISSUE

- DRAINED HYDRO SYSTEM
- REMOVED RES
- REMOVED ALL LINES TO PUMP
- REMOVED PUMP
- REMOVED AXLE LUBE PUMP
- LOOKED INTO DTAC CASE ON THIS PROBLEM
- TRIED TO TEST SEAL FOR LEAKAGE BUT COULDN'T GET THEM TO
- TALKED TO CUSTOMER ABOUT FINDING, REPLACED BOTH SEALS ANYWAYS
- REINSTALLED ALL REMOVED PARTS
- FILLED SYSTEM WITH OIL
- DROVE UNIT AROUND AND FILLED LEVELS AGAIN
- WHEN WAS DRIVING AROUND ACTIVE CODES WOULD COME ON
- LOOKED INTO CODE AND DIA PROBLEM
- REMOVED CONNECTOR FOR SENSOR AND CLEANED
- CODE STILL ACTIVE
- CHECKED SENSOR OPERATION, SEEMED TO BE GOOD
- PROBLEM IS AN ELECTRICAL PROBLEM
- DID MULTIPLE TESTS ON WIRING
- FOUND THAT THE HARNESS WAS SHORTING OUT IN BEHIND THE CONNECTOR
- CUT HARNESS AND REPLACED CONNECTOR AND ELECTRICAL PINS
- DROVE TRACTOR AND TESTED OPERATION
- PROBLEM REPAIRED

CAUSE:

CORRECTION:

Nicks notes: reinstalled resevoir and filled with oil, drained excess oil out of transmission. ran tractor down the road to ensure that there transmission oil level was adequate. had to top up. also noticed that there was a ccu code 18. looked it up and it was the hydraulic oil temperature sensor circuit. checked out sensor and harness continuity and voltage. tried new sensor as per diagnostics and it worked. Then replaced sensor. Plugged it back in and was getting code again. removed loom from over harness and found that there was a section where the insulation was missing off of both wires. replaced connector and stripped wires down so they were no longer bare. reinstalled connector and ran tractor again. problem resolved. tried old sensor back in repaired harness and it threw the code again, so sensor was damaged during the wire touching period of its life

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
03M7191	BOLT	1.00	\$1.36	\$1.36	Y
14M7296	FLANGE NUT	2.00	\$1.74	\$3.48	Y
57M7379	Elec. Connector Housing	1.00	\$11.70	\$11.70	Y



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	523254
Invoice Date	04/09/2022
Location:	03
Work Order Number:	196282
Payment Type:	Account
Page:	2 of 3

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

57M7829	ELEC. CONNE	2.00	\$1.70	\$3.40	Y
F1870R	O-RING	1.00	\$8.18	\$8.18	Y
R128320	SHAFT	1.00	\$284.15	\$284.15	Y
R276248	WASHER	1.00	\$1.95	\$1.95	Y
RE52722	SENSOR	1.00	\$55.88	\$55.88	Y
RE69097	Seal Kit	1.00	\$223.08	\$223.08	Y
RE71352	Seal	1.00	\$53.53	\$53.53	Y
T34448	O-Ring	1.00	\$7.42	\$7.42	Y
TY6354	3.78L HYGARD HYD/TRANS OIL	1.00	\$27.90	\$27.90	Y
U14128	Snap Ring	1.00	\$13.95	\$13.95	Y
U42702	O-RING	1.00	\$5.94	\$5.94	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
EF50	ENVIRO FEE	1.00	\$0.50	\$0.50	Y
FREIGHT	FREIGHT	1.00	\$15.00	\$15.00	Y
SERVACCESS	SERVICE ACCESSORIES	1.00	\$89.00	\$89.00	Y

Labor: \$2,142.00 Parts: \$701.92 OL&M: \$0.00 Misc: \$104.50 Sub-Total: \$2,948.42

/GLOPCLEAN9300 F Retail

COMPLAINT:

02 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST

CAUSE:

CORRECTION:

___ WASH COMPLETE MACHINE(OPEN & WASH BEHIND ALL SHIELDS)___ WAX IF REQUIRED___ REMOVE ANY OTHER DEALER DECALS___ INSTALL SCE DEALERSHIP DECALS___ ALL FACTORY SAFETY AND MODEL DECALS IN GOOD CONDITION___ REMOVE CAB FLOORMAT AND CLEAN MAT AND FLOOR___ CLEAN SEAT AND REMOVE STAINS IF NECESSARY___ VACUUM CAB THOROUGHLY___ CLEAN INSTRUMENT PANEL, OPERATOR CONTROLS, UPHOLSTERY, AND AIR DELIVERY LOUVERS___ CLEAN WINDOWS AND MOLDINGS(OPEN WINDOWS TO CLEAN EDGESWHERE APPLICABLE)___ ELIMINATE ANY CAB ODORS AND INSTALL AIR FRESHENER IF REQUIRED___ PAINT AREAS THAT ARE BADLY SCRATCHED/DAMAGED-INCLUDING BUCKETS, GRAPPLES, WHEELS, EXHAUST, PLATFORM AUGERS(COMPLETE AUGER), CHOPPER FINS, FEEDERHOUSE DRUMS, BALER PICKUPS

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
GLWASHDISC	GREENLIGHT WASHING DISCOUNT	1.00	-\$163.20	-\$163.20	Y

Labor: \$163.20 Parts: \$0.00 OL&M: \$0.00 Misc: -\$163.20 Sub-Total: \$0.00



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	523254
Invoice Date	04/09/2022
Location:	03
Work Order Number:	196282
Payment Type:	Account
Page:	3 of 3

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5289	RW9300H010760	W177683	

Service Reminders:

Customer PO No:
Tax Exempt No:
Advisor: KELLY SAWIN

GST Registration No: 897357802

Labor:	\$2,305.20
Parts:	\$701.92
OL&M:	\$0.00
Misc:	-\$58.70
GST:	\$147.42
PST:	\$0.00
Total:	\$3,095.84

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:

Date:



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	529932
Invoice Date	05/05/2022
Location:	03
Work Order Number:	197859
Payment Type:	Finance
Page:	1 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5400	RW9300H010760	W177683	

Service Reminders:

/SERVICECALL Retail

COMPLAINT:

01 SERVICE CALL

- 1 TRUCK CALL OUT
- TWO TRIPS OUT TO UNIT

CAUSE:

CORRECTION:

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SVCCALL	SERVICE VEHICLE FEE	1.00	\$135.00	\$135.00	Y
Labor: \$159.16	Parts: \$0.00	OL&M: \$0.00	Misc: \$135.00	Sub-Total: \$294.16	

Gen2- Retail

COMPLAINT:

02 - REPAIR A/C

CAUSE:

A/C compressor clutch faulty

CORRECTION:

Replace A/C compressor, vac and recharge system, check operation

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
6315	R134A 12 oz Self Sealing Cans	5.00	\$19.95	\$99.75	Y
R10093	O-RING	2.00	\$2.30	\$4.60	Y
RE576834	Receiver-Dryer	1.00	\$86.22	\$86.22	Y
SE503055	Compressor Rema	1.00	\$749.98	\$749.98	Y
SE503055-CR	CORE for:Compressor Reman	-1.00	\$38.00	-\$38.00	Y
Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	\$18.17	\$18.17	Y



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	529932
Invoice Date	05/05/2022
Location:	03
Work Order Number:	197859
Payment Type:	Finance
Page:	2 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5400	RW9300H010760	W177683	

Service Reminders:

Labor: \$302.75	Parts: \$902.55	OL&M: \$0.00	Misc: \$18.17	Sub-Total: \$1,223.47
------------------------	------------------------	-------------------------	----------------------	------------------------------

Finance Information

Customer PO No:
Tax Exempt No:
Advisor: ADAM DUXBURY

GST Registration No: 897357802

Type:	AgLine	Auth No:	305524
Merchant No:	82000505		
Card No:	xxxxxxxxxxxx2414		
Bill Code:	120	- PARTS & SERVICE -	
Credit Plan:	249	- COMMERCIAL PURCHASE	

Labor:	\$461.91
Parts:	\$902.55
OL&M:	\$0.00
Misc:	\$153.17
GST:	\$75.88
PST:	\$0.00

Total: \$1,593.51

TERMS AND CONDITIONS

This purchase is subject to the terms of the John Deere Financial Multi-Use Account Agreement. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by:

Date:



Box 2098
Highway 2 N.
Assiniboia, SK S0H 0B0
Phone: 306-642-3366
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 8135

Deliver To:

SERVICE INVOICE

Invoice Number:	550900
Invoice Date	07/05/2022
Location:	03
Work Order Number:	200717
Payment Type:	Account
Page:	1 of 1

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2015 JOHN DEERE 9300	5797	RW9300H010760	W177683	

Service Reminders:

Gen2- Retail

COMPLAINT:

02- CHECK A/C

CAUSE:

CORRECTION:

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
6315	R134A 12 oz Self Sealing Cans	2.00	\$19.95	\$39.90	Y
Labor: \$0.00	Parts: \$39.90	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$39.90	

Customer PO No:
Tax Exempt No:
Advisor: KELLY SAWIN

GST Registration No: 897357802

Labor:	\$0.00
Parts:	\$39.90
OL&M:	\$0.00
Misc:	\$0.00
GST:	\$2.00
PST:	\$0.00

Total:	\$41.90
---------------	----------------

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:

Date: