Canada West
Harvest Centre

32 Capital Circle
Corman Park, SK S7R 0H4
Phone: 306-978-2300
Website: www.cawhc.com
Email:ML-Info-cawhc@claas.com

Ship To: IN STORE PICKUP

Branch		
SASKATOON, SK		
Date	Time	Page
07/15/26	13:55:32 (O)	01
Account No	Phone No	Inv No
GBFRI001		W00156
Ship Via	Purchase Order	
Tax ID No		
	Salesperson	
	CM1	

GST 805679776 RT0001

SERVICE PRELIMINARY

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
15986 5300 CLAAS 2022 (X J3201163
5300 QUADRAN

SEGMENT# 1 5 71262 NA 04/02/26 04/09/26 04/30/26
2026 BAILER INSPECTION 18.00
COMPLAINT:
2026 BAILER INSPECTION
1474370 2 9.77 19.54
AGRIGREASE EP 2 TUBE
PARTS 19.54
LABOR 2100.00
11100002 SEGMENT TOTAL==> 2119.54

SEGMENT# 2 5 71262 NA 06/08/26 06/08/26
PICKUP REPAIRS
COMPLAINT:
3 PICKUP FINGERS BROKEN
A FEW PICKUP BANDS BENT
FINGER ROLLER BEARINGS ON SIDES NEED REPLACING
CAUSE:
FINGERS / BANDS ARE BENT AND BROKEN
BEARINGS WORN OUT
CORRECTION:
DISASSEMBLED PICKUP
REPLACED FINGERS
REPLACED BANDS
REPLACED ROLLER BEARINGS
RE-ASSEMBLED PICKUP

2199501	GUIDE ROLLER	5	97.12	485.60
26160621	BEARING FLANGE	10	61.87	618.70
9731010	STRIPPING PLATE	3	78.95	236.85
9732790	DOUBLE TINE	2	26.19	52.38

CONTINUED ON PAGE 02

Thank You For Your Business!

Canada West
Harvest Centre

32 Capital Circle
Corman Park, SK S7R 0H4
Phone: 306-978-2300
Website: www.cawhc.com
Email:ML-Info-cawhc@claas.com

Ship To: IN STORE PICKUP

Branch		
SASKATOON, SK		
Date	Time	Page
07/15/26	13:55:32 (O)	02
Account No	Phone No	Inv No
GBFRI001		W00156
Ship Via	Purchase Order	
Tax ID No		
	Salesperson	
	CM1	

GST 805679776 RT0001

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
15986	5300 CLAAS 2022 (		X J3201163		
	5300 QUADRAN				

			PARTS	1393.53
			LABOR	2100.00
11100002			SEGMENT TOTAL==>	3493.53

SEGMENT# 3 5 71262 NA 06/08/26 06/08/26
PICKUP CASTER WHEEL BEARINGS AND BUSHINGS
COMPLAINT:
PICKUP CASTER WHEEL BEARINGS WORN. REPLACE BEARINGS.
REPLACE PIVOT BUSHINGS AS WELL.
CAUSE:
BEARINGS AND BUSHINGS WORN
CORRECTION:
REMOVED WHEELS
REPLACED BEARINGS
REMOVED PIVOTS
REPLACED BUSHINGS
RE-ASSEMBLED WHEELS

2334730	BUSHING	4	N	116.66	466.64
2358700		4		26.26	105.04
	BEARING GRVD. BALL				
				PARTS	571.68
				LABOR	541.80
11100002				SEGMENT TOTAL==>	1113.48

SEGMENT# 4 5 71262 NA 06/08/26 06/08/26
PICKUP CLUTCH LOOKS LIKE IT GOT HOT
COMPLAINT:
PICKUP CLUTCH LOOKS LIKE IT GOT HOT FROM SLIPPAGE.
DIASSAMBLE CLUTCH AND INSPECT. REPAIR IF NECESSARY.
CAUSE:

CONTINUED ON PAGE 03

Thank You For Your Business!

Canada West
Harvest Centre

32 Capital Circle
Corman Park, SK S7R 0H4
Phone: 306-978-2300
Website: www.cawhc.com
Email:ML-Info-cawhc@claas.com

Ship To: IN STORE PICKUP

Branch		
SASKATOON, SK		
Date	Time	Page
07/15/26	13:55:32 (O)	03
Account No	Phone No	Inv No
GBFRI001		W00156
Ship Via	Purchase Order	
Tax ID No		
	Salesperson	
	CM1	

GST 805679776 RT0001

SERVICE PRELIMINARY

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

15986 5300 CLAAS 2022 (X J3201163
5300 QUADRAN
FRICTION DISCS BURNT
CORRECTION:
REMOVED CLUTCH
DISASSEMBLED CLUTCH
REPLACED DISCS
RE-ASSEMBLED CLUTCH
RE-INSTALLED

2430480	CIRCLIP	1 M	17.43		17.43
8281730	FRICTION PLATE	2 N	94.54		189.08
			PARTS		206.51
			LABOR		174.30
11100002		SEGMENT TOTAL==>			380.81

SEGMENT# 5 5 71262 NA 06/08/26 06/08/26
PICKUP ROLLER CHAIN WORN
COMPLAINT:
PICKUP ROLLER CHAIN WORN. REPLACE CHAIN.
CAUSE:
CHAIN WORN OUT
CORRECTION:
REMOVED CHAIN
INSTALLED NEW CHAIN
SET CHAIN TENSION

29320490	ROLLER CHAIN	1 N	345.17		345.17
			PARTS		345.17
			LABOR		417.90
11100002		SEGMENT TOTAL==>			763.07

SEGMENT# 6 5 71262 NA 06/08/26 06/08/26
CROP PRESS ROLLER

CONTINUED ON PAGE 04

Thank You For Your Business!

Canada West
Harvest Centre

32 Capital Circle
Corman Park, SK S7R 0H4
Phone: 306-978-2300
Website: www.cawhc.com
Email:ML-Info-cawhc@claas.com

Ship To: IN STORE PICKUP

Branch		
SASKATOON, SK		
Date	Time	Page
07/15/26	13:55:32 (O)	04
Account No	Phone No	Inv No
GBFRI001		W00156
Ship Via	Purchase Order	
Tax ID No		
	Salesperson	
	CM1	

GST 805679776 RT0001

SERVICE PRELIMINARY

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
15986 5300 CLAAS 2022 (X J3201163
5300 QUADRAN

COMPLAINT:
REAR CROP PRESS ROLLER BENT. REPLACE ROLLER.
CORRECTION:
REMOVE BOTH ROLLERS
CHANGE BEARINGS
HAD TO SHOT PEEN SHAFTS
THEN PUT ROLLERS BACK IN
FOUND REAR ROLLER TO REQUIRE ANOTHER SHIM
TOOK RIGHT SIDE APART AGAIN AND ADD SHIM
PUT BACK TOGETHER

2341720	SHIM	1	18.37		18.37
6104480		2	44.31		88.62
	BEARING LOCK COLLAR				
8544800	ROLLER	1 N	1600.27		1600.27
			PARTS		1707.26
			LABOR		525.00
11100002		SEGMENT TOTAL==>			2232.26

SEGMENT# 7 5 71262 NA 06/08/26 06/08/26
PTO GUARDS MISSING
COMPLAINT:
MULTIPLE PTO GUARDS MISSING AND DAMAGED. INSTALL ALL
MISSING GUARDS, REPLACE DAMAGED GUARDS.
CAUSE:
MULTIPLE PTO GUARDS MISSING
CORRECTION:
REMOVED SHAFTS
REMOVED BROKEN GUARDS IF STILL THERE
INSTALLED NEW GUARDS
RE-INSTALLED SHAFTS

CONTINUED ON PAGE 05

Thank You For Your Business!

Canada West
Harvest Centre

32 Capital Circle
Corman Park, SK S7R 0H4
Phone: 306-978-2300
Website: www.cawhc.com
Email:ML-Info-cawhc@claas.com

Ship To: IN STORE PICKUP

Branch		
SASKATOON, SK		
Date	Time	Page
07/15/26	13:55:32 (O)	05
Account No	Phone No	Inv No
GBFRI001		W00156
Ship Via	Purchase Order	
Tax ID No		
	Salesperson	
	CM1	

GST 805679776 RT0001

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
15986	5300 CLAAS 2022 (5300 QUADRAN		X J3201163			
13264840	GLIDE RING			2 N 364.67		729.34
13350480	GUARD HALF			1 N 582.59		582.59
1391860	PROTECT.FUNNEL			2 N 76.84		153.68
27197420	GUARD HALF			1 N 560.66		560.66
27204400	GUARD HALF			1 N 1091.79		1091.79
27204720	GUARD HALF			1 N 1005.08		1005.08
				PARTS		4123.14
				LABOR		840.00
11100002 11330002				SEGMENT TOTAL==>		4963.14

SEGMENT# 8 5 71262 NA 06/08/26 06/08/26

CHANGE GEARBOX OILS

COMPLAINT:

CHANGE ALL GEARBOX OILS

CAUSE:

SERVICE DUE

CORRECTION:

DRAINED OIL AND FILLED WITH FRESH OIL IN THESE GEARBOXES:

- MAIN GEAR BOX
- PUMP GEAR BOX
- KNOTTER GEAR BOX
- PICK UP GEAR BOX
- STUFFER GEAR BOX

ENVIRCONTAINER	ENV CONT PER L	20	.10	2.00
ENVOIL	OIL ENVR PER L	20	.05	1.00
1473990		14	8.73	122.22
	AGRISHIFT MT 80W-90 208L			
	Sold per Litre			
1474932		1	125.58	125.58
	AGRISHIFT SYN FE 75W-90 5L			

CONTINUED ON PAGE 06

Thank You For Your Business!

Canada West
Harvest Centre

32 Capital Circle
Corman Park, SK S7R 0H4
Phone: 306-978-2300
Website: www.cawhc.com
Email:ML-Info-cawhc@claas.com

Ship To: IN STORE PICKUP

Branch		
SASKATOON, SK		
Date	Time	Page
07/15/26	13:55:32 (O)	06
Account No	Phone No	Inv No
GBFRI001		W00156
Ship Via	Purchase Order	
Tax ID No		
	Salesperson	
	CM1	

GST 805679776 RT0001

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
15986	5300 CLAAS 2022 (5300 QUADRAN		X J3201163			
1775471	AGRISHIFT SYN F			1 M 426.66		426.66
				PARTS		677.46
				LABOR		945.00
11100002				SEGMENT TOTAL==>		1622.46

SEGMENT# 9 5 71262 NA 06/08/26 06/08/26
AUTO GREASER LOW
COMPLAINT:
AUTO GREASER LOW. FILL AUTO GREASER.
CAUSE:
AUTO GREASER LOW
CORRECTION:
FILLED AUTO GREASER

1460990	4	59.70		238.80
AGRIGREASE EP 2 50KG				
		PARTS		238.80
		LABOR		52.50
11100002		SEGMENT TOTAL==>		291.30

SEGMENT#10 5 71262 NA 06/08/26 06/08/26
CAM FOLLOWER
COMPLAINT:
REPLACE MAIN GEARBOX CAM FOLLOWER BEARING
CAUSE:
CAM FOLLOWER BEARING WORN OUT
CORRECTION:
REMOVE GREASE LINES TO CAM
SPLIT PLATE
REMOVE BEARING
INSTALL NEW BEARING

CONTINUED ON PAGE 07

Thank You For Your Business!

Canada West
Harvest Centre

32 Capital Circle
Corman Park, SK S7R 0H4
Phone: 306-978-2300
Website: www.cawhc.com
Email:ML-Info-cawhc@claas.com

Ship To: IN STORE PICKUP

Branch		
SASKATOON, SK		
Date	Time	Page
07/15/26	13:55:32 (O)	07
Account No	Phone No	Inv No
GBFRI001		W00156
Ship Via	Purchase Order	
Tax ID No		
	Salesperson	
	CM1	

GST 805679776 RT0001

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
15986	5300 CLAAS 2022 (		X J3201163		
	5300 QUADRAN				

INSTALL PLATE
FOUND ROLLER NOT CENTRED
HAD TO REMOVE ASSEMBLY
MOVE SHIMS AROUND
RE-ASSEMBLE CAM ASSEMBLY

FRT	FREIGHT	1	25.00	25.00
2197970	GUIDE ROLLER	1 N	251.51	251.51
4529962	SOCKET HEAD SCR	1 M	10.40	10.40
			PARTS	286.91
			LABOR	718.20
11100002		SEGMENT TOTAL==>		1005.11

SEGMENT#11 5 71262 NA 06/08/26 06/08/26

HYDRAULIC HOSE LEAKING
COMPLAINT:
HYDRAULIC HOSE ON RESERVOIR LEAKING, REPLACE HOSE.
CAUSE:
HYDRAULIC HOSE LEAKING
CORRECTION:
PUT TANK UNDER VACUUM
REMOVED HOSE
INSTALLED NEW HOSE
REMOVED VACUUM
TOPPED UP OIL

6794642	HOSE PIPE	1 M	171.45	171.45
			PARTS	171.45
			LABOR	69.30
11100002		SEGMENT TOTAL==>		240.75

SEGMENT#12 5 71262 NA 06/08/26 06/08/26

CONTINUED ON PAGE 08

Thank You For Your Business!

Canada West
Harvest Centre

32 Capital Circle
Corman Park, SK S7R 0H4
Phone: 306-978-2300
Website: www.cawhc.com
Email:ML-Info-cawhc@claas.com

Ship To: IN STORE PICKUP

Branch		
SASKATOON, SK		
Date	Time	Page
07/15/26	13:55:32 (O)	08
Account No	Phone No	Inv No
GBFRI001		W00156
Ship Via	Purchase Order	
Tax ID No		
	Salesperson	
	CM1	

GST 805679776 RT0001

SERVICE PRELIMINARY

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
15986 5300 CLAAS 2022 (X J3201163
5300 QUADRAN
BLOWER FAN HOSE
COMPLAINT:
HOSE ON BLOWER MOTOR LEAKING. REPLACE HOSE.
CAUSE:
HOSE LEAKING
CORRECTION:
REMOVED HOSE
INSTALLED NEW HOSE

5851560	HOSE PIPE	1	N	99.41	99.41
				PARTS	99.41
				LABOR	88.20
11100002				SEGMENT TOTAL==>	187.61

SEGMENT#13 5 71262 NA 06/08/26 06/08/26
BALE RAMP CLYINDER
COMPLAINT:
BALE RAMP CYLINDER IS BENT. REPLACE CYLINDER.
CAUSE:
CYLINDER BENT
CORRECTION:
REMOVED CYLINDER
INSTALLED NEW CYLINDER

FRT	FREIGHT	2		25.00	50.00
HM5A20000		2		.84	1.68
	WASHER,FLAT M20, DIN125,				
2343180	WASHER	2		.50	1.00
2370330	SPLIT PIN	2	M	.57	1.14
2381150	SHIM	10	N	2.09	20.90
27255380	AXLE	1	N	53.45	53.45
27530990	HYDR. CYLINDER	1	N	1086.16	1086.16

CONTINUED ON PAGE 09

Thank You For Your Business!

Canada West
Harvest Centre

32 Capital Circle
Corman Park, SK S7R 0H4
Phone: 306-978-2300
Website: www.cawhc.com
Email:ML-Info-cawhc@claas.com

Ship To: IN STORE PICKUP

Branch		
SASKATOON, SK		
Date	Time	Page
07/15/26	13:55:32 (O)	09
Account No	Phone No	Inv No
GBFRI001		W00156
Ship Via	Purchase Order	
Tax ID No		
	Salesperson	
	CM1	

GST 805679776 RT0001

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN		WARRANTY DATE	HRS	
15986	5300 CLAAS 2022 (5300 QUADRAN		X J3201163				
340014	1/4" Ball Valve			2 N	63.68		127.36
5007L1004	M.Metric X M NP			2 N	3.05		6.10
5307L1004	F.Metric X M NP			2 N	26.61		53.22
					PARTS		1401.01
					LABOR		262.50
11100002				SEGMENT TOTAL==>			1663.51

SEGMENT#14 5 71262 NA 06/08/26 06/08/26
BALE RAMP BEARINGS *NO STORY*
COMPLAINT:
BALE RAMP ROLLER BEARINGS WORN. REPLACE BEARINGS.

FRT	FREIGHT	1	25.00		25.00
6496940	BEARING	4 N	38.54		154.16
8412770	SHAFT	2 N	318.25		636.50
			PARTS		815.66
			LABOR		157.50
11100002		SEGMENT TOTAL==>			973.16

SEGMENT#15 5 71262 NA 06/08/26 06/08/26
BALER RAM
COMPLAINT:
NEED TO ADJUST RAM KNIFE AND SHEAR BAR
CAUSE:
KNIFE AND SIDE SCRAPERS NEED ADJUSTMENT
CORRECTION:
REMOVE PLATES IN STUFFER AREA
MOVE RAM ABOVE SHEAR BAR
SHIM KNIVES
ADJUST SCRAPERS
PUT STUFFER PLATES BACK IN PLACE

CONTINUED ON PAGE 10

Thank You For Your Business!

Canada West
Harvest Centre

32 Capital Circle
Corman Park, SK S7R 0H4
Phone: 306-978-2300
Website: www.cawhc.com
Email:ML-Info-cawhc@claas.com

Ship To: IN STORE PICKUP

Branch		
SASKATOON, SK		
Date	Time	Page
07/15/26	13:55:32 (O)	10
Account No	Phone No	Inv No
GBFRI001		W00156
Ship Via	Purchase Order	
Tax ID No		
	Salesperson	
	CM1	

GST 805679776 RT0001

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
15986	5300 CLAAS 2022 (5300 QUADRAN		X J3201163		
2365140			4	2.58	10.32
	M10 X 30 STD NECK CH				
8176893	SHIM		4 S	16.14	64.56
				PARTS	74.88
				LABOR	453.60
11100002				SEGMENT TOTAL==>	528.48

SEGMENT#16 5 71262 NA 06/08/26 06/22/26
HYDRAULIC OIL COOLER
COMPLAINT:
BALE REACTION ARM MAKES ALOT OF NOISE WHEN OIL GETS HOT.
COULD TRY TO INSTALL AN OIL COOLER FOR HYDRAULIC SYSTEM.
CAUSE:
HYDRAULIC OIL GETTING TOO WARM DURING REALLY HOT DAYS
CORRECTION:
ORDERED COOLER KIT
IDENTIFY WHERE TO MOUNT COOLER KIT
FABRICATE MOUNTING BRACKETS FOR COOLER
INSTALL COOLER
DRAIN HYDRAULIC SYSTEM
ORDER FITTINGS
MAKE HOSES TO GO TO COOLER
INSTALLED HOSES
BUILT SIMPLE HARNESS TO RUN FAN ON COOLER FROM POWER PLUG
ON REAR OF AXION TRACTOR
DID NOT WORK DUE TO THAT PLUG BEING FUSE LIMITED AT 5 AMPS.
BUILT A HARNESS WITH A RELAY THAT CONNECTS TO BATTERY POWER
TO RUN FAN ON COOLER WITH SIGNAL POWER COMING FROM KEY
SWITCH AT POWER CONNECTOR.
DOES NOT BLOW FUSES AND FUNCTIONS PROPERLY.

CONTINUED ON PAGE 11

Thank You For Your Business!

Canada West
Harvest Centre

32 Capital Circle
Corman Park, SK S7R 0H4
Phone: 306-978-2300
Website: www.cawhc.com
Email:ML-Info-cawhc@claas.com

Ship To: IN STORE PICKUP

Branch		
SASKATOON, SK		
Date	Time	Page
07/15/26	13:55:32 (O)	11
Account No	Phone No	Inv No
GBFRI001		W00156
Ship Via	Purchase Order	
Tax ID No		
	Salesperson	
	CM1	

GST 805679776 RT0001

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
15986	5300 CLAAS 2022 (		X J3201163		
	5300 QUADRAN				
FILL UP HYDRAULIC TANK.					
FRT	FREIGHT	1	25.00		25.00
HOSE ASSEMBLY	HOSE ASSEMBLY	2	12.00		24.00
H84709001	5 PIN WTHR PR C	1 N	37.11		37.11
OPF12810-12-16	1" NPTF MALE FI	2 N	28.19		56.38
OPF21513-12-30		1	34.64		34.64
	#30MM ORING F LT FTG				
OPF21593-12-30		1	63.97		63.97
	#30 MM 90 ORIN F LT FTG				
ROCKMASTER/ 2SN-12		11	12.49		137.39
	3/4" 2 WIRE BRAID HOSE				
SUBLETP	OIL COOLER	1	1783.49		1783.49
007794911	12V 40A 5PIN RE	1 N	29.07		29.07
20891616	16MP-16FP 90 AD	2 N	71.27		142.54
4624520	TENSION BEARING	1 N	79.54		79.54
76-3312PK	14-12GA SOCKET	10 N	3.93		39.30
76-3313PK	14-12GA PIN TER	10 N	3.49		34.90
76-3348PK	1PK 2WAY DTP RE	1 N	20.48		20.48
76-3349PK	2WAY DTP PLUG H	1 N	15.56		15.56
86511459	POWER HARNESS	1 N	84.97		84.97
			PARTS		824.85
			LABOR		3395.70
			SUBLET		1783.49
11100002			SEGMENT TOTAL==>		6004.04

SEGMENT#17 5 71262 NA 04/02/26 04/09/26 04/30/26
BLOWER BEARING
COMPLAINT:
BLOWER BEARING FAILED, REPLACE
CAUSE:

CONTINUED ON PAGE 12

Thank You For Your Business!

Canada West
Harvest Centre

32 Capital Circle
Corman Park, SK S7R 0H4
Phone: 306-978-2300
Website: www.cawhc.com
Email:ML-Info-cawhc@claas.com

Ship To: IN STORE PICKUP

Branch		
SASKATOON, SK		
Date	Time	Page
07/15/26	13:55:32 (O)	12
Account No	Phone No	Inv No
GBFRI001		W00156
Ship Via	Purchase Order	
Tax ID No		
	Salesperson	
	CM1	

GST 805679776 RT0001

SERVICE PRELIMINARY

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
15986 5300 CLAAS 2022 (X J3201163
5300 QUADRAN
BEARING WORN OUT IN LEFT BLOWER
CORRECTION:
REMOVE HYDRAULIC MOTOR
REMOVE BEARING
INSTALL NEW BEARING
RE-INSTALL MOTOR
AFTER FIXING MOTOR, FOUND GREASE LINE WAS RUBBED THROUGH.
REMOVE GREASE LINE, INSTALL NEW LINE AND ZIP TIE IN PLACE.

6654690	9	5.05	45.45
SOLD PER FT			
15FT PER PACKAGE			
		PARTS	45.45
		LABOR	699.30
11100002		SEGMENT TOTAL==>	744.75

SEGMENT#18 5 71262 NA 04/02/26 04/14/26 04/30/26
BAILER SETTINGS AFTER INSPECTION
COMPLAINT:
ADJUSTED BALER KNOTTER SETTINGS AFTER INITIAL INSPECTION
FOUND MULTIPLE SETTINGS OUT OF SPECIFICATION. DURING SETUP,
NEEDLE PENETRATION WAS MEASURED AT 90 MM, WHICH WAS BELOW
SPECIFICATION. ADJUSTED THE LEFT-HAND NEEDLE POSITION TO
ACHIEVE THE CORRECT PENETRATION, THEN RESET NEEDLE HEIGHT
AND RECHECKED ALL KNOTTER SETTINGS. REMOVED BOTH TWINE
TENSION SENSORS, CLEANED INTERNAL COMPONENTS, REASSEMBLED,
AND VERIFIED PROPER OPERATION. PERFORMED A FINAL CHECK OF
ALL ADJUSTMENTS TO ENSURE THE BALER MET FACTORY
SPECIFICATIONS.

		LABOR	2100.00
11100002		SEGMENT TOTAL==>	2100.00

CONTINUED ON PAGE 13

Thank You For Your Business!

Canada West
Harvest Centre

32 Capital Circle
Corman Park, SK S7R 0H4
Phone: 306-978-2300
Website: www.cawhc.com
Email:ML-Info-cawhc@claas.com

Ship To: IN STORE PICKUP

Branch		
SASKATOON, SK		
Date	Time	Page
07/15/26	13:55:32 (O)	13
Account No	Phone No	Inv No
GBFRI001		W00156
Ship Via	Purchase Order	
Tax ID No		
	Salesperson	
	CM1	

GST 805679776 RT0001

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
15986	5300 CLAAS 2022 (		X J3201163		
	5300 QUADRAN				

****** WORK ORDER TOTALS ******	
PARTS	13002.71
LABOR	15640.80
SUBLET	1783.49
INSP DISC PART	650.14-
SHOP SUPPLIES	1000.00
WINTER INSPECT	840.00-
SUB TOTAL==>	29936.86
GST 5%	1496.91
CUSTOMER A/R TOTAL	31433.77

Thank You For Your Business!