



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

WESTLOCK
11140-100 Street
Westlock, AB T7P 2C3
Tel: (780) 349-3720
Fax: (780) 349-3308
Toll Free: 1-855-763-1427

INVOICE

Ship to:

C/S - Jim Holt

*Ref Seal
\$7,549.00*

Invoice to:

DOWN YONDER FARMS
BOX 353
REDWATER AB T0A 2W0

Branch WESTLOCK		
Date 07/20/18	Time 10:01:08 (O)	Page 01
Account No. HOLT0004	Phone No. 7803982273	Reference No. W34283
Ship Via	Purchase Order	
G.S.T. No. 825 724 032 RT0001		
Credit Card No.	Salesperson 321	

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold ---
084743	8230	COMBINE	995	YDG218604	
	8230		686		
SEGMENT# 1 S 02879 NA	07/09/18	07/11/18			
DECLINED - Feeder lateral tilt not working					
87018388		FLANGE BOLT	1	4.14	4.14
				PARTS	4.14
13500019			SEGMENT TOTAL==>		4.14
SEGMENT# 2 S 02879 NA	07/09/18				
DECLINED - Folding auger actuator is hanging up					
SEGMENT# 3 S 02879 NA	07/09/18	07/12/18			
DECLINED - Header Auger is rubbing on LH rear strips					
SEGMENT# 4 S 02879 NA	07/09/18				
DECLINED - Pickup Four wind guard rods are broken					
SEGMENT# 5 S 02879 NA	07/09/18				
DECLINED - Header Auger drive chain needs to be adjusted					
SEGMENT# 6 S 02879 NA	07/09/18	07/09/18			
Feeder chain wear plates are worn			2.50	HRS	
CORRECTION:					
Loosen the feeder chain					
Loosen and removed the retainer bolts and removed the wear plates					
mount and secure the new wear plates with the existing hardware					
Do the necessary adjustment and secure the hardware					
Re-adjust the feeder chain to spec					
47963654		PLATE	2	48.79	97.58
				CONTINUED ON PAGE 02	

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$_____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

WESTLOCK
11140-100 Street
Westlock, AB T7P 2C3
Tel: (780) 349-3720
Fax: (780) 349-3308
Toll Free: 1-855-763-1427

INVOICE

Ship to:

C/S - Jim Holt

Invoice to:

DOWN YONDER FARMS
BOX 353
REDWATER AB T0A 2W0

Branch WESTLOCK		
Date 07/20/18	Time 10:01:08 (O)	Page 02
Account No. HOLT0004	Phone No. 7803982273	Reference No. W34283
Ship Via		Purchase Order
		G.S.T. No. 825 724 032 RT0001
Credit Card No.		Salesperson 321

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
084743	8230 COMBINE	995	YDG218604			Fold - - -
	8230	686				
48001329	PLATE	1		58.31		58.31
48001642	PLATE	1		56.82		56.82
				PARTS		212.71
				LABOR		350.00
13500019				SEGMENT TOTAL==>		562.71

SEGMENT# 7 S 02879 NA 07/09/18
DECLINED - LH feeder chain adjuster bolt is bent

SEGMENT# 8 S 02879 NA 07/09/18 07/09/18

Rock beater blades old style flat

CORRECTION:

loosen and removed the retainer bolts and removed the beater blades

Install and secure the new beater blades secure them with the existing Hardware

87360866	SER KNF-STN TRP	4	155.00	620.00
			PARTS	620.00
			LABOR	280.00
13500019			SEGMENT TOTAL==>	900.00

2.00 HRS

*Rock Beater
update blades*

SEGMENT# 9 S 02879 NA 07/09/18 07/12/18

LH lower retainer bolt is cracked

3.00 HRS

CORRECTION:

Previously removed all the components and removed the front rotor support channel

Do the necessary grinding and welding and painting

Build apiece of metal to reinforce the LH support channel

mount and secure all the components and secure them

ADDITIONAL DESCRIPTION:

CONTINUED ON PAGE 03

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

WESTLOCK
11140-100 Street
Westlock, AB T7P 2C3
Tel: (780) 349-3720
Fax: (780) 349-3308
Toll Free: 1-855-763-1427

INVOICE

Ship to:

C/S - Jim Holt

Invoice to:

DOWN YONDER FARMS
BOX 353
REDWATER AB T0A 2W0

Branch		
WESTLOCK		
Date	Time	Page
07/20/18	10:01:08 (O)	03
Account No.	Phone No.	Reference No.
HOLT0004	7803982273	W34283
Ship Via	Purchase Order	
G.S.T. No.		
825 724 032 RT0001		
Credit Card No.	Salesperson	
	321	

Description of Work and Parts

STK#/FLEET#

084743

8230 COMBINE
8230

HRS
995
686

PIN/EIN
YDG218604

WARRANTY DATE

HRS

Fold - - -

on front rotor support plate.

13500019

LABOR

420.00

SEGMENT TOTAL==>

420.00

SEGMENT#10 S 02879 NA

07/09/18 07/09/18

Impeller Wear bars are worn, one is missing a retainer bolt
CORRECTION:

3.00 HRS

*New Impeller
Wear Bars*

Split the feeder house from combine

loosen and removed the retainer bolts and removed the wear bars

Mount and secure the new wear bars torque the bolts to 65 ,
and after 85 lb ft

48118400

IMPELLER BLD KI

1

418.70

418.70

PARTS

418.70

LABOR

420.00

13500019

SEGMENT TOTAL==>

838.70

SEGMENT#11 S 02879 NA

07/09/18 07/09/18

#8 Cage Vane is bent

1.00 HRS

New Cage Vane

CORRECTION:

loosen and removed the three T- retainer bolts and removed the vane

Install and secure new vane with the existing hardware
torque to 45 lb ft

87106338

BOLT

1

5.46

5.46

87717924

STIFFENER

1

50.75

50.75

PARTS

56.21

LABOR

140.00

13500019

SEGMENT TOTAL==>

196.21

CONTINUED ON PAGE 04

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

WESTLOCK
11140-100 Street
Westlock, AB T7P 2C3
Tel: (780) 349-3720
Fax: (780) 349-3308
Toll Free: 1-855-763-1427

INVOICE

Ship to:

C/S - Jim Holt

Invoice to:

DOWN YONDER FARMS
BOX 353
REDWATER AB T0A 2W0

Branch WESTLOCK		
Date 07/20/18	Time 10:01:08 (O)	Page 04
Account No. HOLT0004	Phone No. 7803982273	Reference No. W34283
Ship Via		Purchase Order
		G.S.T. No. 825 724 032 RT0001
Credit Card No.		Salesperson 321

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - -
084743	8230	COMBINE	995	YDG218604	
	8230		686		
SEGMENT#12 S 02879 NA	07/09/18	07/09/18			
Concave motor bracket is broken				1.00 HRS	
<u>CORRECTION:</u>					
Loosen and removed the hardware					
Removed concave hanger bar and removed the concave motor bracket					
Correction					
Swap the motor to a new bracket					
Mount and secure the new bracket with the existing hanger bar and hardware					
Do all the necessary adjustment					
Set the concave pinch point to zero					
Check for proper operation					
47581464		PIVOT BRACKET	1	266.56	266.56
				PARTS	266.56
				LABOR	140.00
13500019			SEGMENT TOTAL==>		406.56
SEGMENT#13 S 02879 NA	07/09/18	07/09/18			
Front concave hanger bushing has play				.30 HRS	
<u>CORRECTION:</u>					
Replaced the bushing and hardware with a new ones					
83904166		WASHER M10	2	1.60	3.20
86998150		BUSHING	1	12.04	12.04
				PARTS	15.24
				LABOR	42.00
13500019			SEGMENT TOTAL==>		57.24
SEGMENT#14 S 02879 NA	07/09/18	07/09/18			
Rotor drive coupler is making noise				13.00 HRS	
CONTINUED ON PAGE 05					

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

WESTLOCK
11140-100 Street
Westlock, AB T7P 2C3
Tel: (780) 349-3720
Fax: (780) 349-3308
Toll Free: 1-855-763-1427

INVOICE

Ship to:

C/S - Jim Holt

Invoice to:

DOWN YONDER FARMS
BOX 353
REDWATER AB T0A 2W0

Branch WESTLOCK		
Date 07/20/18	Time 10:01:08 (O)	Page 05
Account No. HOLT0004	Phone No. 7803982273	Reference No. W34283
Ship Via		Purchase Order
		G.S.T. No. 825 724 032 RT0001
Credit Card No.		Salesperson 321

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
084743	8230 COMBINE	995 YDG218604		
	8230	686		

CORRECTION:

Removed safety shields on feeder house
Disconnect and removed feeder drive shaft
Disconnect and removed all the electric and hyd connector between combine and feeder house
Split feeder house from combine
removed upper and lower D-plates
Secure the rotor
Removed front rotor support channel
Using the tools removed rotor out of combine
Correction
Follow the instructions
vacuum the rotor and reinstall the cap
Replace the rotor coupler with a new one torque the bolts to 220 240 lb ft
Using the laser tool alignment do the necessary alignment on rotor gear box
Mount and secure a new rotor drive coupler using red lock tite torque to 117 lb ft
as per instructions use foam on the rotor coupler
Re-install rotor coupler into the combine
Reinstall and secure the front rotor support
Follow the instructions do the necessary adjustment to 2mm
Mount and secure upper and lower D- plates
Reinstall the feeder house and secure all the components on the reverse order
Run up the unit and do the rotor calibration and check for proper operation

ADDITIONAL DESCRIPTION:

****CONTACT CUSTOMER ONCE ROTOR IS REMOVED****

CONTINUED ON PAGE 06

Rotor Removal
Install Rotor
New perfect rotor couple

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

WESTLOCK
11140-100 Street
Westlock, AB T7P 2C3
Tel: (780) 349-3720
Fax: (780) 349-3308
Toll Free: 1-855-763-1427

INVOICE

Ship to:

C/S - Jim Holt

Invoice to:

DOWN YONDER FARMS
BOX 353
REDWATER AB T0A 2W0

Branch WESTLOCK		
Date 07/20/18	Time 10:01:08 (O)	Page 06
Account No. HOLT0004	Phone No. 7803982273	Reference No. W34283
Ship Via		Purchase Order
		G.S.T. No. 825 724 032 RT0001
Credit Card No.		Salesperson 321

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - -
084743	8230	COMBINE	995	YDG218604	
	8230		686		
84222993		COUPLING, SPLIN	1	463.32	463.32
86980985		COUPLING	1	142.24	142.24
87324171		BEARING	1	148.96	148.96
				PARTS	754.52
				LABOR	1820.00
13500019			SEGMENT TOTAL==>		2574.52

SEGMENT#15 S 02879 NA	07/09/18	07/09/18			
Self leveling RR centre wear plate is broken			2.00	HRS	
<u>CORRECTION:</u>					
Support the rear shaker shoe					
Loosen and removed the hardware and removed the wear plate					
Replace the rear wear plate with a new one secure the hardware					
84457842		PLATE, WEAR	1	58.71	58.71
				PARTS	58.71
				LABOR	280.00
13500019			SEGMENT TOTAL==>		338.71

SEGMENT#16 S 02879 NA	07/09/18	07/09/18			
Re-thrasher drive belt has a damaged spot			.30	HRS	
<u>CORRECTION:</u>					
Replaced the re-thrasher drive belt with a new one do the necessary adjustment to spec					
87283139		BELT	1	127.44	127.44
				PARTS	127.44
				LABOR	42.00
13500019			SEGMENT TOTAL==>		169.44

SEGMENT#17 S 02879 NA 07/09/18

CONTINUED ON PAGE 07

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$_____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

WESTLOCK
11140-100 Street
Westlock, AB T7P 2C3
Tel: (780) 349-3720
Fax: (780) 349-3308
Toll Free: 1-855-763-1427

INVOICE

Ship to:

C/S - Jim Holt

Invoice to:

DOWN YONDER FARMS
BOX 353
REDWATER AB T0A 2W0

Branch WESTLOCK		
Date 07/20/18	Time 10:01:08 (O)	Page 07
Account No. HOLT0004	Phone No. 7803982273	Reference No. W34283
Ship Via		Purchase Order
		G.S.T. No. 825 724 032 RT0001
Credit Card No.		Salesperson 321

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold
084743	8230	COMBINE	995	YDG218604	
	8230		686		
DECLINED - Rotating knives are worn, need to be flipped over					
SEGMENT#18 S 02879 NA	07/09/18				
DECLINED - x8 stationary knives are broken - x3 knocked down					
SEGMENT#19 S 02879 NA	07/09/18				
DECLINED - Panel above chopper has two holes - SILICONE					
SEGMENT#20 S 02879 NA	07/09/18	07/10/18			
Adjust all chains and belts				1.00 HRS	
<u>CORRECTION:</u>					
Readjust the unloading drive chain.					
conveyor clean elevator drive chain					
Chopper drive belts					
Clean elevator drive chain					
clean elevator drive belt					
bubble up auger drive chain					
pick up header drive chain					
I did lubricated all the drive chains					
13500019				LABOR	140.00
				SEGMENT TOTAL==>	140.00
SEGMENT#21 S 02879 NA	07/09/18	07/13/18			
Main control valve is leaking oil-diagnose				.80 HRS	
<u>CORRECTION:</u>					
using the pressure washer clean up the area					
Run up the unit found the upper solenoid on main control					
valve leak					
continue to replace the seal kit					
run up the unit and check for no leaks					

CONTINUED ON PAGE 08

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

WESTLOCK
11140-100 Street
Westlock, AB T7P 2C3
Tel: (780) 349-3720
Fax: (780) 349-3308
Toll Free: 1-855-763-1427

INVOICE

Ship to:

C/S - Jim Holt

Invoice to:

DOWN YONDER FARMS
BOX 353
REDWATER AB T0A 2W0

Branch WESTLOCK		
Date 07/20/18	Time 10:01:08 (O)	Page 08
Account No. HOLT0004	Phone No. 7803982273	Reference No. W34283
Ship Via		Purchase Order
		G.S.T. No. 825 724 032 RT0001
Credit Card No.		Salesperson 321

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	Fold ---
084743	8230 COMBINE	995	YDG218604			
	8230	686				
86508168	KIT, SEALS	1		30.63		30.63
				PARTS		30.63
				LABOR		112.00
13500019				SEGMENT TOTAL==>		142.63

SEGMENT#22 S 02879 NA 07/09/18
DECLINED - Engine coolant level low

SEGMENT#23 S 02879 NA 07/09/18
DECLINED-Connector above air filter canister is sucking dust
- clean & silicone

SEGMENT#24 S 02879 NA 07/09/18
DECLINED - LH FR wheels have broken bolt

SEGMENT#25 S 02879 NA 07/09/18
DECLINED - Lights
-Rear chaff lights not working
-RH front feeder light not working
-LH front beacon bulb burnt out
-RH front beacon doesn't turn
-4 outer roof lights not working

*Repaired 11/25/18
all working*

SEGMENT#26 S 02879 NA 07/09/18
DECLINED - Change engine oil and filters

Done

SEGMENT#27 S 02879 NA 07/09/18
DECLINED - Change fuel filters

Done

SEGMENT#28 S 02879 NA 07/09/18

CONTINUED ON PAGE 09

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

WESTLOCK
11140-100 Street
Westlock, AB T7P 2C3
Tel: (780) 349-3720
Fax: (780) 349-3308
Toll Free: 1-855-763-1427

INVOICE

Ship to:

C/S - Jim Holt

Invoice to:

DOWN YONDER FARMS
BOX 353
REDWATER AB T0A 2W0

Branch WESTLOCK		
Date 07/20/18	Time 10:01:08 (O)	Page 09
Account No. HOLT0004	Phone No. 7803982273	Reference No. W34283
Ship Via	Purchase Order	
		G.S.T. No. 825 724 032 RT0001
Credit Card No.	Salesperson 321	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - -
084743	8230 COMBINE	995	YDG218604			
	8230	686				
DECLINED - Change hydraulic filters						
SEGMENT#29 S 02879 NA 07/09/18						
DECLINED - Change engine crankcase breather						
SEGMENT#30 S 02879 NA 07/09/18						
DECLINED - Change engine air filters						
SEGMENT#31 S 02879 NA 07/09/18						
lateral tilt doesn't work						

***** WORK ORDER TOTALS *****

PARTS	2564.86
LABOR	4186.00
DISPOSAL FEE	83.72
SHOP SUPPLIES	355.81
SUB TOTAL==>	7190.39
GST 825724032	359.54
VISA	7549.93

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)