



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

WESTLOCK

11140-100 Street
Westlock, AB T7P 2C3
Tel: (780) 349-3720
Fax: (780) 349-3308
Toll Free: 1-855-763-1427

INVOICE

Ship to:

C- DOWN YONDER FARMS

5225.00

Invoice to:

DOWN YONDER FARMS
BOX 353
REDWATER AB T0A 2W0

Branch WESTLOCK		
Date 11/25/19	Time 14:23:33 (Q)	Page 01
Account No. HOLT0004	Phone No. 7803982273	Reference No. W39448
Ship Via		Purchase Order
		G.S.T. No. 825 724 032 RT0001
Credit Card No.		Salesperson 321

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold ---
084743	8230 COMBINE	1322	YDG218604		
	8230	986			
SEGMENT# 1 5 04443 NA	10/31/19	11/01/19	10/31/19		
Header auger is rubbing the strippers				.70	.70
CORRECTION:					
Removed the bolts hitting the strippers. Moved the strippers back and reinstalled the bolts holding the strippers in.					
47677377	KIT	10	122.04		1220.40
			PARTS		1220.40
			LABOR		98.00
13500019			SEGMENT TOTAL==>		1318.40
SEGMENT# 2 S 04443 NA	10/31/19	10/31/19	10/31/19		
x4 Windguard rods broken				.50 HRS	
CORRECTION:					
Removed the four broken wind guards and installed new wind guards.					
308761	CARRIAGE BOLT	1	2.40		2.40
84231228	TINE	4	92.92		371.68
			PARTS		374.08
			LABOR		70.00
13500019			SEGMENT TOTAL==>		444.08
SEGMENT# 3 S 04443 NA	10/31/19		10/31/19		
DECLINED - Header drive shaft shields are damaged					
SEGMENT# 4 S 04443 NA	10/31/19		10/31/19		
DECLINED - x34 Pickup fingers broken					
SEGMENT# 5 S 04443 NA	10/31/19		10/31/19		
DECLINED - Feeder mid floor is worn					

CONTINUED ON PAGE 02

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

WESTLOCK
11140-100 Street
Westlock, AB T7P 2C3
Tel: (780) 349-3720
Fax: (780) 349-3308
Toll Free: 1-855-763-1427

INVOICE

Ship to:
Invoice to:

C- DOWN YONDER FARMS

DOWN YONDER FARMS
BOX 353
REDWATER AB T0A 2W0

Branch WESTLOCK		Page 02
Date 11/25/19	Time 14:23:33 (O)	
Account No. HOLT0004	Phone No. 7803982273	Reference No. W39448
Ship Via		Purchase Order
		G.S.T. No. 825 724 032 RT0001
Credit Card No.		Salesperson 321

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold ---
084743	8230 COMBINE	1322	YDG218604		
	8230	986			

SEGMENT# 6 S 04443 NA 10/31/19 10/31/19 10/31/19
Self leveling RR bearing wearplate is cracked .60 HRS
CORRECTION:
Lifted up the back of the combine. Removed the wear plate.
Installed new wear plate.
84457842 PLATE, WEAR 1 69.89 69.89
PARTS 69.89
LABOR 84.00
13500019 SEGMENT TOTAL==> 153.89

SEGMENT# 7 S 04443 NA 10/31/19 10/31/19 10/31/19
Shorten Cl. Gr. Elevator chain 1.20 HRS
CORRECTION:
Rotated the clean grain elevator chain until the master-links were positioned at the bottom. Then cut off the j-clips and removed them. Loosened off the tension from the chain. Removed the chain link and then installed a half link in. Installed new j-clips and re-tension the chain.
87610182 PIN 2 1.81 3.62
87717729 550hd Offset Lk 1 16.24 16.24
PARTS 19.86
LABOR 168.00
13500019 SEGMENT TOTAL==> 187.86

SEGMENT# 8 S 04443 NA 10/31/19 10/31/19 10/31/19
Return auger bearing RH/LH locking collars broken 6.00 HRS
CORRECTION:
Loosened the belts and pulley bolts. Installed puller and removed the pulleys on each side. Loosened the bolts and

CONTINUED ON PAGE 03

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

WESTLOCK
11140-100 Street
Westlock, AB T7P 2C3
Tel: (780) 349-3720
Fax: (780) 349-3308
Toll Free: 1-855-763-1427

INVOICE

Ship to:
Invoice to:

C- DOWN YONDER FARMS

DOWN YONDER FARMS
BOX 353
REDWATER AB T0A 2W0

Branch WESTLOCK		
Date 11/25/19	Time 14:23:33 (O)	Page 03
Account No. HOLT0004	Phone No. 7803982273	Reference No. W39448
Ship Via		Purchase Order
		G.S.T. No. 825 724 032 RT0001
Credit Card No.		Salesperson 321

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - -
084743	8230 COMBINE	1322 YDG218604			
	8230	986			
locking collars, took the bearing assembly out. Installed new bearings, flanges and locking collars, tightened and reinstalled the pulleys. Centered the pulleys and installed the belts back on.					
47508360	BEARING, B	1	64.21		64.21
47577185	COLLAR	1	12.28		12.28
86620026	FLANGE	2	7.25		14.50
86974037	FLANGE	2	12.60		25.20
86997053	COLLAR	1	21.86		21.86
87605592	BEARING	1	68.69		68.69
			PARTS		206.74
			LABOR		840.00
13500019			SEGMENT TOTAL==>		1046.74

SEGMENT# 9 S 04443 NA 10/31/19 10/31/19 10/31/19
LH curtain between return and clean grain augers damaged .80 HRS
CORRECTION:

Removed the bolts and took the curtains out. Installed new ones on and tightened the bolts.

445395	RIVET	5	2.59		12.95
87552399	SEAL PROTE	1	153.44		153.44
			PARTS		166.39
			LABOR		112.00
13500019			SEGMENT TOTAL==>		278.39

SEGMENT#10 S 04443 NA 10/31/19 10/31/19
DECLINED - Chopper blades are worn

SEGMENT#11 S 04443 NA 10/31/19 10/31/19
DECLINED - x6 Stationary knives broken and x2 knocked down

CONTINUED ON PAGE 04

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

WESTLOCK
11140-100 Street
Westlock, AB T7P 2C3
Tel: (780) 349-3720
Fax: (780) 349-3308
Toll Free: 1-855-763-1427

INVOICE

Ship to:
Invoice to:

C- DOWN YONDER FARMS

DOWN YONDER FARMS
BOX 353
REDWATER AB T0A 2W0

Branch WESTLOCK		
Date 11/25/19	Time 14:23:33 (O)	Page 04
Account No. HOLT0004	Phone No. 7803982273	Reference No. W39448
Ship Via		Purchase Order
		G.S.T. No. 825 724 032 RT0001
Credit Card No.		Salesperson 321

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - -
084743	8230 COMBINE	1322	YDG218604		
	8230	986			

SEGMENT#12 S 04443 NA 10/31/19 10/31/19
DECLINED - Panel above chopper and straw hood has holes

SEGMENT#13 S 04443 NA 10/31/19 10/31/19
DECLINED - Unloading drive chain is worn

SEGMENT#14 S 04443 NA 10/31/19 11/01/19 10/31/19
DEF bundle is leaking coolant 1.00 HRS
CORRECTION:

Topped up the coolant and pressured the coolant system. It was loosing pressure. Tightened all clamps and re-pressured it, left it for a while. It held the pressure. Didn't replace the DEF coolant line, as it didn't leak from there.

ADDITIONAL DESCRIPTION:

SEE RAB FOR INSTRUCTIONS

ANT1	ENVIRO ANTIFRZ	4	.16	.64
B30204C	ANTIFREZ 4L/505	1	11.15	11.15
	PARTS			11.79
	LABOR			84.00
13500019	SEGMENT TOTAL==>			95.79

SEGMENT#15 S 04443 NA 10/31/19 10/31/19
DECLINED - Coolant leak on rad hose

SEGMENT#16 S 04443 NA 10/31/19 10/31/19 10/31/19
Engine fan belts are worn 1.00 HRS

CORRECTION:

Loosened the tensioner and removed the old belts.
Installed new belts and re-tensioned them.

CONTINUED ON PAGE 05

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$_____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

WESTLOCK
11140-100 Street
Westlock, AB T7P 2C3
Tel: (780) 349-3720
Fax: (780) 349-3308
Toll Free: 1-855-763-1427

INVOICE

Ship to:

C- DOWN YONDER FARMS

Invoice to:

DOWN YONDER FARMS
BOX 353
REDWATER AB T0A 2W0

Branch WESTLOCK		
Date 11/25/19	Time 14:23:33 (O)	Page 05
Account No. HOLT0004	Phone No. 7803982273	Reference No. W39448
Ship Via		Purchase Order
		G.S.T. No. 825 724 032 RT0001
Credit Card No.		Salesperson 321

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold ---
084743	8230 COMBINE	1322 YDG218604			
	8230	986			
47490848	SET OF BEL	1	65.71	65.71	
			PARTS	65.71	
			LABOR	140.00	
13500019			SEGMENT TOTAL==>	205.71	
SEGMENT#17 S 04443 NA 10/31/19 10/31/19					
DECLINED - Blow out the rads					
SEGMENT#18 S 04443 NA 10/31/19 10/31/19 10/31/19					
Rotary screen outer driving belt is cracked				.40 HRS	
CORRECTION:					
Removed the old rotary screen drive belt and installed the new rotary screen drive belt.					
9842161	V-BELT	1	101.54	101.54	
			PARTS	101.54	
			LABOR	56.00	
13500019			SEGMENT TOTAL==>	157.54	
SEGMENT#19 S 04443 NA 10/31/19 10/31/19 10/31/19					
x2 LH wheel bolts are broken				3.00 HRS	
CORRECTION:					
Removed both left wheels from machine and then removed the two broken bolts from the hub. All threads were refreshed because they showed some corrosion, cleaned any oil residue. Installed wheels and torqued to spec. Replaced all bolts in both wheels.					
87367550	BOLT	20	24.45	489.00	
			PARTS	489.00	
			LABOR	420.00	
13500019			SEGMENT TOTAL==>	909.00	

CONTINUED ON PAGE 06

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$_____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

WESTLOCK
11140-100 Street
Westlock, AB T7P 2C3
Tel: (780) 349-3720
Fax: (780) 349-3308
Toll Free: 1-855-763-1427

INVOICE

Ship to:

C- DOWN YONDER FARMS

Invoice to:

DOWN YONDER FARMS
BOX 353
REDWATER AB T0A 2W0

Branch WESTLOCK		
Date 11/25/19	Time 14:23:33 (O)	Page 06
Account No. HOLT0004	Phone No. 7803982273	Reference No. W39448
Ship Via		Purchase Order
		G.S.T. No. 825 724 032 RT0001
Credit Card No.		Salesperson 321

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - -
084743	8230 COMBINE	1322 YDG218604			
	8230	986			

SEGMENT#20 S 04443 NA 10/31/19 10/31/19 10/31/19

Lights

1.50 HRS

CORRECTION:

- Replaced the FR RH beacon with new one
- Replaced the burnt bulbs in FR LH and RR beacons
- Installed new bulb in cab roof
- Replaced the bulb in RH FR feeder and grain tank lights

ADDITIONAL DESCRIPTION:

- FR RH beacon doesn't spin
- FR LH and RR beacon bulbs burnt
- Cab roof light doesn't work
- RH FR feeder light doesn't work
- Grain tank light doesn't work

1102258	bulb	1	8.97	8.97
14149590	BULB	1	9.59	9.59
14151095	BULB	2	12.00	24.00
47670938	BEACON	1	164.00	164.00
87107077	BULB	1	31.51	31.51
87329813	BULB	1	17.81	17.81

PARTS 255.88

LABOR 210.00

13500019

SEGMENT TOTAL==>

465.88

SEGMENT#21 S 04443 NA

10/31/19

10/31/19

DECLINED - 1200 Hour Service

- Header drive gearbox oil
- Feeder gearbox oil
- Final drive oils
- Transmission oil

CONTINUED ON PAGE 07

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

WESTLOCK
11140-100 Street
Westlock, AB T7P 2C3
Tel: (780) 349-3720
Fax: (780) 349-3308
Toll Free: 1-855-763-1427

INVOICE

Ship to:

C- DOWN YONDER FARMS

Invoice to:

DOWN YONDER FARMS
BOX 353
REDWATER AB T0A 2W0

Branch WESTLOCK		
Date 11/25/19	Time 14:23:33 (O)	Page 07
Account No. HOLT0004	Phone No. 7803982273	Reference No. W39448
Ship Via		Purchase Order
		G.S.T. No. 825 724 032 RT0001
Credit Card No.		Salesperson 321

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold ---
084743	8230	COMBINE	1322	YDG218604	
	8230		986		

- Cab outer air filter
- Vertical unloading gearbox oil
- Unloading tube gearbox oil (Gearbox on top)
- Hydraulic filters
- Fuel filters
- Tailings gearbox oil
- Rotor gearbox oil
- PTO oil
- Hydraulic oil
- Bubble up gearbox oils
- Engine oil and filters
- Engine air filters
- Engine crankcase breather

SEGMENT#22 S 04261 NA 10/31/19 11/18/19 10/31/19

Wash
wash & detail cab

13500019

LABOR	.01
SEGMENT TOTAL==>	.01

***** WORK ORDER TOTALS *****

PARTS	2981.28
LABOR	2282.01
DISPOSAL FEE	45.64
SHOP SUPPLIES	193.97
DISCOUNT	526.32-
SUB TOTAL==>	4976.58
GST 825724032	248.83

CONTINUED ON PAGE 08

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

WESTLOCK
11140-100 Street
Westlock, AB T7P 2C3
Tel: (780) 349-3720
Fax: (780) 349-3308
Toll Free: 1-855-763-1427

INVOICE

Ship to:

C- DOWN YONDER FARMS

Invoice to:

DOWN YONDER FARMS
BOX 353
REDWATER AB T0A 2W0

Branch WESTLOCK		
Date 11/25/19	Time 14:23:33 (O)	Page 08
Account No. HOLT0004	Phone No. 7803982273	Reference No. W39448
Ship Via		Purchase Order
		G.S.T. No. 825 724 032 RT0001
Credit Card No.		Salesperson 321

Description of Work and Parts

STK#/FLEET#

084743

8230 COMBINE

8230

HRS

1322

986

PIN/EIN

YDG218604

WARRANTY DATE

HRS

Fold ---

VISA

5225.41

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)