PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3689	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4458	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3500416**
Invoice Date	10/30/2025
Location:	08
Work Order Number:	517215
Payment Type:	Account
Page:	1 of 7

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 4730	2112	1N04730XCB0014471	SCHL4730	

Service Reminders:

JGLSPR NOWET JD ALL Retail

COMPLAINT:

01 SPRAYER VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER. WET TESTING SOLUTION SYSTEM NOT INCLUDED. (ALL MODELS PRIOR TO R-SERIES)

***DONT CHANGE ENGINE OIL AND FILTER

CAUSE:

CORRECTION:

SELF PROPELLED SPRAYER VALUEMAX GREEN LIGHT INSPECTION CHECKOVER
****
NOTE: SPRAY TANK MUST BE RINSED AS WELL AS BOOMS WASHED
OFF BEFORE SPRAYER IS BROUGHT INTO SHOP.
IF NOT ADDITIONAL CHARGES WILL APPLY.
****
ENGINE HOURS _2112_____
****
DOES THIS UNIT GET A VALUEMAX STICKER _X_ YES __ NO
HAS THE STICKER BEEN INSTALLED __ YES _X_ NO
CAB HAS BEEN COMPLETELY CLEANED _____(INITIAL)
THIS UNIT HAS HAD A FINAL CHECKOVER ___CK____(INITIAL)
THIS UNIT HAS HAD A COMPLETE GREASE JOB __CK___(INITIAL)
****
THINGS NOTED BUT NOT REPAIRED ON CUSTOMER'S INSTRUCTIONS:

Paid M/C
Thankyou

Job Total: $0.00

J21001090 JD 4730 Retail

COMPLAINT:

02 REPLACE ENGINE FUEL FILTERS

CAUSE:

CORRECTION:

REPLACED PRIMARY AND SECONDARY FUEL FILTERS.
BLED FUEL SYSTEM.
FUNCTION AND LEAK CHECKED

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3500416**
Invoice Date	10/30/2025
Location:	08
Work Order Number:	517215
Payment Type:	Account
Page:	2 of 7

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 4730	2112	1N04730XCB0014471	SCHL4730	

Service Reminders:

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
RE522878	FILTER ELE	1.00	62.29	$62.29	Y
RE541922	FILTER ELE	1.00	62.24	$62.24	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
EF100	ENVIRO FEE	2.00	1.25	$2.50	Y

Labor: $140.00 **Parts: $124.53** **OL&M: $0.00** **Misc: $2.50** **Sub-Total: $267.03**

JHYDFILTER JD 4730 Retail

COMPLAINT:

03 REPLACE HYDRAULIC OIL FILTERS

CAUSE:

CORRECTION:

REPLACE MAIN HYDRULIC FILTER.
REPLACE BOTH HYDRO CHARGE FILTERS.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AN203010	Hydraulic Filter	2.00	108.58	$217.16	Y
AN203010	Hydraulic Filter	1.00	108.57	$108.57	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
EF50	ENVIRO FEE	2.00	0.55	$1.10	Y

Labor: $90.00 **Parts: $325.73** **OL&M: $0.00** **Misc: $1.10** **Sub-Total: $416.83**

JGEN04- Retail

COMPLAINT:

04 DISPLAY DOES NOT WORK CORRECTLY

CAUSE:

CORRECTION:

DISPLAY TOUCH SCREEN WOULD NOT WORK
SENT DISPLAY TO GET
TESTED DISPLAY AND WORKED AS IT SHOULD

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3500416**
Invoice Date	10/30/2025
Location:	08
Work Order Number:	517215
Payment Type:	Account
Page:	3 of 7

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 4730	2112	1N04730XCB0014471	SCHL4730	

Service Reminders:

Labor: $0.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $0.00**

JGEN05- Retail

COMPLAINT:

05 CHECK AIR COMPRESSOR

CAUSE:

CORRECTION:

REPLACED AIR DRYER CARTRIDGE
REPLACED MUFFLER

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AN204967	Air Dryer Cartridge	1.00	418.04	$418.04	Y
AN204970	MUFFLER	1.00	153.25	$153.25	Y

Labor: $52.00 **Parts: $571.29** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $623.29**

JTREADADJ JD 4730 Retail

COMPLAINT:

06 ADJUST AXLE TREAD ADJUST SHIMS. (PER AXLE) X4

CAUSE:

CORRECTION:

ADJUSTED ALL SHIMS FOR TREAD ADJUST TO SPEC

LIFTED SPRAYER AND ADJUSTED SHIMS ON ALL 4 AXELS AND TESTED FUNCTION

Labor: $560.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $560.00**

JWELD3 JD ALL Retail

COMPLAINT:

07 WELD CRACKS ON BOOM BOTH SIDES

CAUSE:

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3500416**
Invoice Date	10/30/2025
Location:	08
Work Order Number:	517215
Payment Type:	Account
Page:	4 of 7

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 4730	2112	1N04730XCB0014471	SCHL4730	

Service Reminders:

CORRECTION:

WELDED CRACKED TUBING ON OUTER BOOMS

CLEANED OFF PAINT FROM ABOUT 10 CRACKS AND WELDED, PAINTED AFTER

Labor: $800.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $800.00**

JELECDIAG1 JD ALL Retail

COMPLAINT:

08 RIGHT HAND TURN SIGNAL NOT WORKING

CAUSE:

CORRECTION:

REMOVED COVER AND REMOVE AND REPLACE BULB AND TEST FUNCTION

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AD2062R	1156 Bulb	1.00	7.27	$7.27	Y

Labor: $50.00 **Parts: $7.27** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $57.27**

JCOOLHEAT JD 4730 Retail

COMPLAINT:

09 INSTALL COOLANT HEATER

CAUSE:

CORRECTION:

DRAIN COOLANT, REMOVE COOLANT PLUG, INSTALL COOLANT HEATER AND MADE SURE IT WAS NOT TOUCHING ENGINE BLOCK, REFILLED WITH COOLANT AND CHECKED FOR LEAKS

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
DZ102076	Coolant Heater	1.00	299.52	$299.52	Y

Labor: $500.00 **Parts: $299.52** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $799.52**

JELECDIAG2 JD ALL Retail

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3500416**
Invoice Date	10/30/2025
Location:	08
Work Order Number:	517215
Payment Type:	Account
Page:	5 of 7

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 4730	2112	1N04730XCB0014471	SCHL4730	

Service Reminders:

COMPLAINT:

10 DIAGNOSE BOOM HEIGHT SENSOR

CAUSE:

CORRECTION:

RH BOOM WOULD LIFT WHILE AUTO BOOM WOULD ENGAGE AND OUTER SENSOR WOULD ALWAYS READ 9, TRIED RECALIBRATING AND SWAPPING SENSORS, CALIBRATION DID NOT HELP BUT SWAPPING SENSORS THE PROBLEM FOLLOWED THE SENSOR, INSTALLED NEW SENSOR AND TESTED FUNCTION. BOOM HEIGHT WORKED AS IT SHOULD.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AN304552	Boomtrac Sensor	1.00	2,946.10	$2,946.10	Y

Labor: $624.00 **Parts: $2,946.10** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $3,570.10**

JSOLUGAUGE JD 4730 Retail

COMPLAINT:

11 REPLACE SOLUTION TANK SIGHT GAUGE

CAUSE:

CORRECTION:

REMOVE MOUNTING CLAMPS.
REPLACE SIGHT GAUGE TUBE.
INSTALL REMOVED HARDWARE.
FUNCTION AND LEAK TEST.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
PMK010-1216	3/4" Clear PVC /ft	6.00	2.51	$15.06	Y

Labor: $140.00 **Parts: $15.06** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $155.06**

J21001007 JD 4730 Retail

COMPLAINT:

12 REPLACE OIL IN PLANETARY WHEEL HUBS.

CAUSE:

PATTISON AGRICULTURE LIMITED
Hwy 5 East, Box 2109
Humboldt, SK S0K 2A0
Phone: (306) 682-2572
Fax: (306) 682-2510
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice Number:	**3500416**
Invoice Date	10/30/2025
Location:	08
Work Order Number:	517215
Payment Type:	Account
Page:	6 of 7

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 4730	2112	1N04730XCB0014471	SCHL4730	

Service Reminders:

CORRECTION:

DRAINED OIL FROM PLANETARY HOUSINGS.
INSTALLED NEW OIL.
LEAK CHECKED.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
TY26372	80W140 Synth 946ml GL5	5.00	43.05	$215.25	Y
Miscellaneous	**Description**	**Quantity**	**Net Price**	**Extended Price**	**Taxed Ind**
EF15	ENVIRO FEE	10.00	0.15	$1.50	Y

Labor: $350.00 **Parts: $215.25** **OL&M: $0.00** **Misc: $1.50** **Sub-Total: $566.75**

JDISC JD ALL Retail

COMPLAINT:

13 GREEN LIGHT INSPECTION DISCOUNTS

CAUSE:

CORRECTION:

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
DISC	Parts Discount	-1.00	450.47	-$450.47	Y

Miscellaneous Charges:

SERVICE ACCESSORIES $150.00

Labor: $0.00 **Parts: $0.00** **OL&M: $0.00** **Misc: -$300.47** **Sub-Total: -$300.47**

Customer PO No:
Tax Exempt No:
Advisor: Sheila Lefebvre

Labor:	$5,406.00
Parts:	$4,601.34
OL&M:	$0.00
Misc:	-$2,491.96
GST:	$375.77
PST:	$0.00
Grand Total:	$7,891.15