Brandt

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
27FEB26	114	114500056

SOLD TO: [redacted]

PAGE 1

SALE TYPE CHARGE

CUSTOMER NO. 14194304

SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN
P-11-86741	[redacted]	114500056	17	13JAN26	

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	844LAH	1DW844LAVKL697363	FMC838	8850	STAN

DESCRIPTION					AMOUNT
REPLACE ENGINE BELT					
1	R531353	V-BELT		102.11	102.11
	* LABOR *				225.00
	SERVICE ACCESSORIES			20.25	20.25
	ENVIRONMENTAL FEE			2.25	2.25
>>---> SEG# 17	PRT	102.11	LAB 225.00	MSC 22.50	349.61
	* GST/HST *			17.48	
CHECK AND REPAIR FOR ACTIVE GREASE SYSTEM CODE					
Grease system coding 005522.07 line A outlet pressure invalid. Spend time reviewing code and gather tooling. Remove lines from grease keg and put keg in manual purge, line B had fair about of air coming out of it. Line A had significant amount of water coming out, keg used to fill auto lube keg has water and grease mixed together. Spend time purging air from system and reinstall lines. Code is cleared and verify machine is greasing normally.					
	** TOTAL LABOR **				576.25
	SERVICE ACCESSORIES			51.86	51.86
	ENVIRONMENTAL FEE			5.76	5.76
>>---> SEG# 18	PRT	.00	LAB 576.25	MSC 57.62	633.87
	* GST/HST *			31.69	
RE & RE BOOM, SWAP OVER GREASE SYSTEM IF REQ'D					
Cleaned and inspected all pins and bores on machine and new					

QST # 1226957240

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL ▶	**CONTINUED**

CUSTOMER COPY

LF-1152C

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
27FEB26	114	114500056

SOLD TO: [redacted]

PAGE 2
SALE TYPE CHARGE
CUSTOMER NO. 14194304
SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN	
P-11-86741	[redacted]	114500056	24	15JAN26		

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	844LAH	1DW844LAVKL697363	FMC838	8850	STAN

DESCRIPTION				AMOUNT
boom. Found lower LH boom cylinder pin and bushings were badly damaged. Pressed out and replaced bushing in boom cylinder. Installed new seals with loctite 680. Installed boom cylinder with new pin. Ordered and installed new seals for new boom and dog bones with loctite 680. Hoisted and mounted boom to front frame using overhead crane. Torqued mounting hardware. Installed Z-bars onto boom and torqued pin retainers. Installed dog bones onto Z-bars and torqued pin retainers. Greased all pins, greased bucket and dog bone bores and wrapped with shrink wrap. Swapped bucket pin grease tubes from old boom to new boom, installed with new banjo fittings. Installed new grease hard lines on dog bones with new banjo fittings. Swapped grease manifold from old boom to new boom. Connected all intact grease hoses, swapped out damaged grease hoses for new ones, and connected. Ran greaser on continuous test, found cracked fitting on boom manifold. Replaced fitting. Ran greaser on continuous test until grease was evident on all pins. No leaks found. Installed boom and bucket sensors. Calibrated boom and bucket position sensors.				
2	AT539835	Link	2,545.96	5,091.92
1	AT481253	Loader B	42,500.00	42,500.00
1	T225134	Bushing CY	360.42	360.42
2	T352831	Seal XY	63.67	127.34
1	M45937	Elbow Fi	24.04	24.04
1	AT481926	Pin	1,371.55	1,371.55
4	T352828	Seal	44.93	179.72
4	T102140	Seal	43.18	172.72
12	T208999	Seal X	77.18	926.16
8	T420108	O-Ring CY	1.21	9.68

QST # 1226957240

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	
TOTAL LABOR	
MISC. CHARGES	
SALES TAX	
PLEASE PAY THIS TOTAL ▶	**CONTINUED**

CUSTOMER COPY

LF-1152C

Brandt

Brandt Tractor Ltd.
9500 190th St.
Surrey, BC
V4N 3S2
(604)882-8888

Service Invoice

JOHN DEERE

INVOICE DATE	BRANCH	INVOICE NO.
27FEB26	114	114500056

SOLD TO: [redacted]

PAGE 3

SALE TYPE CHARGE

CUSTOMER NO. 14194304

SHIP TO

PURCHASE ORDER NO.	PHONE NUMBER	WORK ORDER NO.	SEG.	DATE OPENED	SALESPRN
P-11-86741	[redacted]	114500056	24	15JAN26	

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	844LAH	1DW844LAVKL697363	FMC838	8850	STAN

		DESCRIPTION			AMOUNT
4	T420102	Bolt	CY	47.28	189.12
2	T419972	Fitting	X	62.26	124.52
1	AT499297	Tube	XY	376.74	376.74
1	AT499323	Tube	CY	383.98	383.98
2	T419970	Fitting		20.23	40.46
	* LABOR *				3,600.00
	SERVICE ACCESSORIES			324.00	324.00
	ENVIRONMENTAL FEE			36.00	36.00
>>---> SEG# 24	PRT 51,878.37	LAB 3,600.00	MSC	360.00	55,838.37
	* GST/HST *			2,791.92	
BUILD & REPLACE HYDRAULIC HOSES					
	** TOTAL LABOR **				920.00
	SERVICE ACCESSORIES			82.80	82.80
1	1472143S REPLACE HOSES			4,450.78	4,450.78
	ENVIRONMENTAL FEE			9.20	9.20
>>---> SEG# 26	PRT .00	LAB 920.00	MSC	4,542.78	5,462.78
	* GST/HST *			273.14	
	* TOTAL GST/HST * - GST No. 899544779				3,114.23

QST # 1226957240

PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUM). MINIMUM CHARGE OF $1.50.

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount for repairs thereto.
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair or while field testing.

X _____ SIGNATURE

_____ DATE

DESCRIPTION	AMOUNT
TOTAL PARTS	51,980.48
TOTAL LABOR	5,321.25
MISC. CHARGES	4,982.90
SALES TAX	0.00
PLEASE PAY THIS TOTAL ▶	65,398.86

CUSTOMER COPY

LF-1152C