

**Treeline Heavy Duty Truck and
Trailer Parts**
Box 44
Preeceville, SK S0A3B0, CA
treelineheavyduty@sasktel.net
3065474454



Invoice: 57561

Date: 4/29/2026

Bill To

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
132812	Net 60	6/28/2026			Palaniuk, Cole	122

Item	Description	Quantity	Rate	Amount
Complaint: safety repairs				
Cause: wear and tear				
Labor	Correction: Chassis / Chassis / Repairs for safety. Tighten axle 2 RS lower airbag support crossmember. Put new screws into RS mirror light. Replace steer axle rear upper and lower leaf bushings. Welded nuts onto all of them as threads were too worn and pins would not thread out. Remove fuse box to access master switch PNDB. Replace PNDB and reinstall fuse panel. Fix poor wiring at firewall for trailer wiring circuit. Fix air leak under cab. - Completed: 5/1/2026			\$1,468.88
Parts	CONFIG PNDB WITH CUTOFF BUSHING - A66-03714-018			\$697.37
Parts	Spring Pin, Threaded, 90 DEG - 16-18213-000			\$362.88
Parts	Bushing Spring Pin Thread - 16-18227-000			\$346.76
Parts	Bulk Grade 8 Hardware By Kilogram - Bulk			\$18.91
Parts	Gr. Fit. 1/8 Pipe Str. - 987.18.20			\$6.44
Parts	Freight - Freight			\$50.00

Unit: 122 VIN: 5KJJAED12GLHC4414
License Plate: 152ItY
2016 Western Star Trucks 4900 FA
Chassis: 662,570 Kilometers

Shop Supplies	\$146.89
Pre-Charge Subtotal	\$3,098.13
GST (5% of \$3,048.13)	\$152.40
PST (6% of \$3,048.13)	\$182.88
Total	\$3,433.41
Payments & Credits	\$0.00
Balance Due	\$3,433.41

Any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser understands and agrees that Treeline Heavy Duty makes no warranties of any kind unless expressed in writing. I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that Treeline Heavy Duty is not responsible for loss or damage to vehicles or articles left in the vehicle in case of fire, theft, or any other cause beyond control or for any

5/7/26, 10:56 AM

Invoices

delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto.

Interest at 2% per month (24% per annum) charged on all overdue invoices.

GST# 792276495RT0001

Treeline Heavy Duty Truck and Trailer Parts
 Box 44
 Preeceville, SK S0A3B0, CA
 treelineheavydutytrucks@sasktel.net
 3065474454



Invoice: 54385
Date: 11/30/2025

Bill To

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
132230	Net 60	1/29/2026			Tesla, Glen	122

Item	Description	Quantity	Rate	Amount
Complaint: Safety inspection replace air tank cables supplied replace valve supplied clutch adjust ,clutch brake ABS light diagnose Engine light diagnose Cause: wear and tear (Service Request)				
Labor	Correction: Chassis / Chassis / Repairs for safety. Repaired air leak on fire wall. Secured front fender support. Replaced cracked RS hubcap. Remove oil pan. Clean block and oil pan. Replace oil pan gasket and reinstall pan. Replace oil filter and fill engine with 15w40. Remove and replace bad ABS sensor on axle 3 RS. Replace cracked drum and brake shoes on axle 3 RS. Replace AC belt Replace reflectors on rear of cab. Diagnose ABS faults. Replaced corroded air tank straps. Replaced leaking service air valve. Adjusted clutch and clutch linkage. - Completed: 11/26/2025			\$2,379.41
Parts	Fitting - 121C			\$2.89
Parts	Fitting - 498C			\$4.80
Parts	5/8" Synflex Air Line Per Ft. (#193001) - 148510			\$1.36
Parts	J-bolt - N38J			\$11.88
Parts	UBOLT,SS FENDER MTG - N1238S			\$46.18
Parts	Hub cap, 6 hole, 4 1/2" BC - C5 - 3434024			\$46.44
Parts	Mobile Delvac Syn 75W90 (18.9L) - EO122047			\$7.27
Parts	EHC - 035			\$0.08
Parts	Filter - P7505			\$47.85
Parts	Oil Pan Seal - DDE A4720140022			\$217.10
Parts	Mobil Delvac 15W40 (1000L) Tote - 103107			\$229.05
Parts	Reflective Tape, Silver 150ft - 40641			\$7.56

Item	Description	Quantity	Rate	Amount
Parts	DD16 Belt - K081062HD			\$96.20
Parts	BRAKE DRUM - SSD6722			\$123.04
Parts	Meritor QPlus Shoe - XSS714707QPK			\$72.00
Parts	ABS sensor kit - 577A5342			\$40.06

Complaint: diagnose engine shutting down

diagnose ABS

retorque tires

fix pig tail on oil spinner

Cause: wear and tear

(Inspection)

Labor	Correction:			\$1,128.75
	Chassis / Chassis / Diagnose engine light. Found bad harness to engine crankcase breather spinner.			
	Replaced section of harness. Clear code and confirm engine code did not return. Top up coolant.			
	Had no communication to 2nd axle RS wheel speed sensor. Open up main ABS harness. Fixed large section of wire and ran wheel speed test. Confirmed proper operation. Topped up coolant. - Completed: 11/25/2025			
Parts	Cable, ArcticFlex, 2/14, -85 - 724A2			\$13.60
Parts	AWG 16-14 Heat Shrink Butt Connectors (Blue) - BHT2.5			\$0.80
Parts	Insulated rubber clamp - 848008			\$3.04
Parts	parts - parts			\$50.00
Parts	AWG 22-18 Coated Tin Heat Shrink Butt Connectors (Pink) - BHT1.25			\$1.17

Unit: 122 VIN: 5KJJAED12GLHC4414

License Plate: 152lty

2016 Western Star Trucks 4900 FA

Chassis: 662,570 Kilometers

Shop Supplies	\$350.82
Pre-Charge Subtotal	\$4,881.35
GST	
(5% of \$4,881.35)	\$244.07
PST	
(6% of \$4,881.35)	\$292.88
Total	\$5,418.30
Payments & Credits	\$0.00
Balance Due	\$5,418.30

Any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser understands and agrees that TreeLine Heavy Duty makes no warranties of any kind unless expressed in writing. I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that TreeLine Heavy Duty is not responsible for loss or damage to vehicles or articles left in the vehicle in case of fire, theft, or any other cause beyond control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto.

Interest at 2% per month (24% per annum) charged on all overdue invoices.

GST# 792276495RT0001