

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. 257125	Internal Used Stock No. 257125	Invoice Number:	3351013
		Invoice Date:	4/17/2025
		Location:	10
Bus Phone:	Bus Phone:	Work Order Number:	482917
Prv Phone:	Prv Phone:	Payment Type:	Account
		Page:	1 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9460R PTO		1RW9460RHCP003293	353784M	

JGL4WD JD ALL Internal

COMPLAINT:

01 4WD TRACTOR VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

CORRECTION:

VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKLIST

HOURS: 5485

TRACTOR DYNOED AT: _____

DOES THIS UNIT GET A VALUEMAX STICKER _X_ YES ___ NO

HAS STICKER BEEN INSTALLED _X_ YES ___ NO

CAB HAS BEEN COMPLETELY CLEANED ___ JC___ (INITIAL)

THIS UNIT HAS HAD A FINAL CHECKOVER ___ JC___ (INITIAL)

THIS UNIT HAS HAD A COMPLETE GREASE JOB ___ JC___ (INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMER'S INSTRUCTIONS:

VMC SEASON OF USE 2025

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26859	INSPECTION+ 3 FLUID TEST KIT	1.00	87.56	0.00	\$0.00	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DISI	LAB DISC INTERN	-1.00	625.00	625.00	(\$625.00)	N
Labor: \$2,500.00		Parts: \$0.00	OL&M: \$0.00	Misc: (\$625.00)	Sub-Total: \$1,875.00	

JGEN06- Internal

COMPLAINT:

06 REPLACE OCV TOP BREATHER LINE & P-CLAMP

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
M150681	Clamp	1.00	7.28	7.28	\$7.28	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. 257125	Internal Used Stock No. 257125	Invoice Number: 3351013
		Invoice Date: 4/17/2025
		Location: 10
		Work Order Number: 482917
		Payment Type: Account
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	Page: 2 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9460R PTO		1RW9460RHCP003293	353784M	

JGEN06- Internal

RE555474	Tube	1.00	243.61	243.61	\$243.61	N
----------	------	------	--------	--------	----------	---

Labor: \$150.00	Parts: \$250.89	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$400.89
------------------------	------------------------	-------------------------	---------------------	----------------------------

J01020050 JD 6140D Internal

COMPLAINT:

07 REPLACE VALVE COVER GASKET

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ128752	GASKET	1.00	30.94	30.94	\$30.94	N
R528620	ENGING TURBOCHARGE GASKET	1.00	121.21	121.21	\$121.21	N
R531581	GASKET	2.00	113.17	113.17	\$226.34	N
R531582	GASKET	2.00	114.20	114.20	\$228.40	N
Labor: \$870.00		Parts: \$606.89	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,476.89	

J01020211 JD 9460R Internal

COMPLAINT:

08 REPLACE ACCESSORY DRIVE BELT & TENSIONER PULLEY.

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ10469	Engine Auxiliary Drive Belt Tensioner	1.00	345.28	345.28	\$345.28	N
R536677	V-BELT	1.00	111.97	111.97	\$111.97	N
Labor: \$150.00		Parts: \$457.25	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$607.25	

JGEN09- Internal

COMPLAINT:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. 257125	Internal Used Stock No. 257125	Invoice Number: 3351013
		Invoice Date: 4/17/2025
		Location: 10
		Work Order Number: 482917
		Payment Type: Account
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	
		Page: 3 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9460R PTO		1RW9460RHCP003293	353784M	

JGEN09- Internal

09 VARI COOL SPEED SENSOR HARNESS REPAIR SLEEVING

CORRECTION:

Friday, March 21, 2025 5:54 PM - removed harness from sensor and removed old brittle/broken sleeving and replaced with new sleeving and re installed harness onto sensor.- KB

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY26184	1/4" black split loom /ft	6.00	1.53	1.53	\$9.18	N
Labor: \$200.00		Parts: \$9.18	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$209.18	

JGEN10- Internal

COMPLAINT:

10 REPLACE CAM POSITION SENSOR O RING

CORRECTION:

Labor: \$50.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$50.00
-----------------------	----------------------	-------------------------	---------------------	---------------------------

J01030125 JD 9460R Internal

COMPLAINT:

11 REPLACE CLAMP ON EXPANSION TANK LEAK, HOSE ON BOTTOM OF RAD, TIGHTEN ALL CLAMPS & REPLACE COOLANT RESERVOIR CAP

CORRECTION:

Friday, March 21, 2025 6:17 PM - replaces hose clamp on expansion tank where leak was re tightened all other hose clamps for cooling system, topped up coolant reservoir and replaced cap- KB

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE312969	FILLER CAP, COOLANT PRESSURE-15 PSI	1.00	75.22	75.22	\$75.22	N

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. 257125	Internal Used Stock No. 257125	Invoice Number: 3351013
		Invoice Date: 4/17/2025
		Location: 10
		Work Order Number: 482917
		Payment Type: Account
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	Page: 4 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9460R PTO		1RW9460RHCP003293	353784M	

J01030125 JD 9460R Internal

TY22464	Hose Clamp sz6 11-20mm	3.00	2.60	2.60	\$7.80	N
---------	------------------------	------	------	------	--------	---

Labor: \$1,000.00	Parts: \$83.02	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,083.02
--------------------------	-----------------------	-------------------------	---------------------	------------------------------

J01030070 JD 9460R Internal

COMPLAINT:

12 REPLACE ENGINE VARIABLE SPEED FAN BELT.

CORRECTION:

Friday, March 21, 2025 5:20 PM - removed engine fan and pulled outer sheave for vari cool removed old belt and replaced with new, reinstall outer sheave and torqued bolts to 27ft/lbs then reinstalled fan and torqued bolts to 27 ft/lbs- KB

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
R300399	VarCooling Fan Belt 13.5L	1.00	226.14	226.14	\$226.14	N
Labor: \$390.00	Parts: \$226.14	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$616.14		

JGEN13- Internal

COMPLAINT:

13 REPLACE HOSE CLAMP BY FUEL COOLER

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY22464	Hose Clamp sz6 11-20mm	1.00	2.60	2.60	\$2.60	N
Labor: \$40.00	Parts: \$2.60	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$42.60		

J01001092 JD 9460R Internal

COMPLAINT:

14 BATTERY, REPLACE (ALL)

CORRECTION:

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. 257125	Internal Used Stock No. 257125	Invoice Number: 3351013
		Invoice Date: 4/17/2025
		Location: 10
		Work Order Number: 482917
		Payment Type: Account
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	Page: 5 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9460R PTO		1RW9460RHCP003293	353784M	

J01001092 JD 9460R Internal

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY25879B	BCI31, 950CCA 12V WET CHARGED BATTERY	3.00	322.89	322.89	\$968.67	N
Labor: \$250.00		Parts: \$968.67	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,218.67	

JFUELVENT JD 9460R Internal

COMPLAINT:

15 REPLACE TRANSMISSION BREATHER

CORRECTION:

Friday, March 21, 2025 7:27 PM - remove and replace transmission breather. -KB

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H216169	BREATHER, FUEL TANK	1.00	47.04	47.04	\$47.04	N
Labor: \$25.00		Parts: \$47.04	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$72.04	

JHYDDIAG1 JD ALL Internal

COMPLAINT:

16 PERFORM HYDRAULIC SYSTEM DIAGNOSTICS- "NO PRESSURE BY SCVs" MARCEL

CORRECTION:

RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS: _____

Tuesday, April 1, 2025 4:25 PM - cleaned the suction filters and re assembled the system, filtered hydro back into reservoir, ran unit and took for a drive heated up fluid, re pressure tested pumps 75cc at 1200rpm was 850psi running and 3100 psi stall, 45cc pump at 1200 rpm was 550psi and 3100psi stall, as per logan unit working as should all scvs working and steering working.- KB

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE566118	LEVEL GAUG	1.00	483.68	483.68	\$483.68	N
Labor: \$300.00		Parts: \$483.68	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$783.68	

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. 257125	Internal Used Stock No. 257125	Invoice Number: 3351013
		Invoice Date: 4/17/2025
		Location: 10
		Work Order Number: 482917
		Payment Type: Account
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	Page: 6 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9460R PTO		1RW9460RHCP003293	353784M	

JGEN17- Internal

COMPLAINT:

17 NEED NEW CASE DRAIN COUPLER, 2 HYDRAULIC HOSES LEAKING 2 CLAMPS LEAKING ON LINES

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TA31569	MotorCaseDrain FM -8ORB	1.00	213.62	213.62	\$213.62	N
Labor: \$1,000.00		Parts: \$213.62	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,213.62	

JELECDIAG1 JD ALL Internal

COMPLAINT:

19 PERFORM ELECTRICAL SYSTEM DIAGNOSTICS- MIRROR IN & OUT NOT WORKING

CORRECTION:

RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS: _____

Sunday, March 23, 2025 4:58 PM - PULLED MIRROR OFF LEFT SIDE THE NUT PART OF THE THREADS ON THE EXTENDED MIRRORS IS STRIPED OFF AND THE RIGHT SIDE IS ALMOST STRIPPED OFF. ta

Friday, April 11, 2025 2:58 PM - pulled the mirror brackets off then installed the new mirrors then i adjusted them kr

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE323407	Mirror Kit	1.00	1,538.56	1,538.56	\$1,538.56	N
Labor: \$300.00		Parts: \$1,538.56	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,838.56	

JWIPERBLADE JD 9560R Internal

COMPLAINT:

20 REPLACE WINDSHIELD WIPER BLADES FRONT & REAR

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. 257125	Internal Used Stock No. 257125	Invoice Number: 3351013
		Invoice Date: 4/17/2025
		Location: 10
		Work Order Number: 482917
		Payment Type: Account
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	Page: 7 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9460R PTO		1RW9460RHCP003293	353784M	

JWIPERBLADE JD 9560R Internal

AL153661	Wiper Blade 24"	2.00	73.39	73.39	\$146.78	N
----------	-----------------	------	-------	-------	----------	---

Labor: \$50.00	Parts: \$146.78	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$196.78
-----------------------	------------------------	-------------------------	---------------------	----------------------------

J10030100 JD 9460R Internal

COMPLAINT:

21 REPLACE ENGINE FUEL FILTERS

CORRECTION:

REPLACED PRIMARY AND SECONDARY FUEL FILTERS.

REMOVED AND CLEANED FUEL STRAINER/WATER SEPARATOR.

bled FUEL SYSTEM.

FUNCTION AND LEAK CHECKED.

Sunday, March 23, 2025 4:10 PM - CHANGED 1 FILTER OTHER FILTER IS WRONG. TA

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ112918	FINAL FUEL FILTER	1.00	244.07	244.07	\$244.07	N
DZ130550	PRIMARY FILTER ELEMENT	1.00	240.23	240.23	\$240.23	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	2.00	1.25	1.25	\$2.50	N

Labor: \$80.00	Parts: \$484.30	OL&M: \$0.00	Misc: \$2.50	Sub-Total: \$566.80
-----------------------	------------------------	-------------------------	---------------------	----------------------------

JDBARADAPT JD 9460R Internal

COMPLAINT:

22 DRAW BAR PIN MISSING

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. 257125	Internal Used Stock No. 257125	Invoice Number: 3351013
		Invoice Date: 4/17/2025
		Location: 10
		Work Order Number: 482917
		Payment Type: Account
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	Page: 8 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9460R PTO		1RW9460RHCP003293	353784M	

JDBARADAPT JD 9460R Internal

RE215218	Drawbar Pin	1.00	513.09	513.09	\$513.09	N
----------	-------------	------	--------	--------	----------	---

Labor: \$0.34	Parts: \$513.09	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$513.43
----------------------	------------------------	-------------------------	---------------------	----------------------------

JENGOILCHN JD 9460RT Internal

COMPLAINT:

23 REPLACE ENGINE OIL AND FILTER

CORRECTION:

DRAIN ENGINE OIL AND REMOVE FILTER.

CLEAN AREA.

INSTALL NEW OIL AND FILTER.

RUN UNIT AND LEAK CHECK.

MARK ENGINE HOURS ON NEW FILTER.

ADJUST OIL LEVEL AS REQUIRED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE572785	ENGINE OIL FILTER	1.00	156.67	156.67	\$156.67	N
TY26679	PLUS-50 II 15W-40 CK4/SN 18.9L PAIL	3.00	170.86	170.86	\$512.58	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.25	1.25	\$1.25	N
EF300	ENVIRO FEE	3.00	3.00	3.00	\$9.00	N

Labor: \$100.00	Parts: \$669.25	OL&M: \$0.00	Misc: \$10.25	Sub-Total: \$779.50
------------------------	------------------------	-------------------------	----------------------	----------------------------

JENGAIRFILT JD 9460R Internal

COMPLAINT:

24 REPLACE PRIMARY AND SECONDARY ENGINE AIR FILTERS

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE230985	Secondary EngAir Filter	1.00	176.70	176.70	\$176.70	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. 257125	Internal Used Stock No. 257125	Invoice Number: 3351013
		Invoice Date: 4/17/2025
		Location: 10
		Work Order Number: 482917
		Payment Type: Account
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	Page: 9 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9460R PTO		1RW9460RHCP003293	353784M	

JENGAIRFILT JD 9460R Internal

RE312946	Primary EngAir Filter	1.00	511.67	511.67	\$511.67	N
----------	-----------------------	------	--------	--------	----------	---

Labor: \$50.00 Parts: \$688.37 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$738.37

JHYDOILCHG JD 9460R Internal

COMPLAINT:

25 REPLACE ALL HYDRAULIC FILTERS

CORRECTION:

Friday, March 21, 2025 4:25 PM -

pulled old filters to cut open

check for metal filings found a bit ut not terrible replaced with new filters- KB

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE577612	Hydraulic Oil Filter	3.00	206.11	206.11	\$618.33	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	3.00	1.25	1.25	\$3.75	N
Labor: \$100.00		Parts: \$618.33	OL&M: \$0.00	Misc: \$3.75	Sub-Total: \$722.08	

JCABFILTER JD 9460R Internal

COMPLAINT:

26 REPLACE CAB AIR FILTERS

CORRECTION:

Tuesday, March 18, 2025 7:38 PM - replaced cabin and engine air filters- KB

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE291412	CabRecircFilter	1.00	139.48	139.48	\$139.48	N
TA32591	Cab FreshAir Filter	1.00	125.95	125.95	\$125.95	N
Labor: \$50.00		Parts: \$265.43	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$315.43	

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. 257125	Internal Used Stock No. 257125	Invoice Number: 3351013
		Invoice Date: 4/17/2025
		Location: 10
		Work Order Number: 482917
		Payment Type: Account
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	
		Page: 10 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9460R PTO		1RW9460RHCP003293	353784M	

JHYDDIAG2 JD ALL Internal

COMPLAINT:

27 PERFORM HYDRAULIC SYSTEM DIAGNOSTICS- TRACTOR NOT STEERING PROPERLY

CORRECTION:

RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS: _____

Thursday, March 20, 2025 6:05 PM -

pulled unit in found hydro level low topped up to cold full,
 ran unit and pulled back into shop found reservoir was over full after ran,
 drained 2 pails out of reservoir,
 proceeded to do a filter differential test and had 105 psi inlet and 95 psi outlet differential pressure is 10 psi,
 proceeded to do charge pump pressure test and found 900 rpm - 50 psi wot -120 psi.
 cooler differential inlet- 105 psi outlet- 15 psi,
 flow tested scv and found scv 1-3 was 27 gpm scv 4 was 15 gpm scv 5 was 17 gpm,
 main hydraulic pump pressure test 45cc standby- 525 psi stall- 525 psi 75cc standby- 500 psi stall- 3000 psi.
 front diff lube pressure- 20 psi.
 spent an hour blowing out dirt and stems to be able to perform pressure tests on pumps. -KB, TA

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AR69444	HY-GARD J20C 18.9L PAIL	4.00	158.46	158.46	\$633.84	N
TY22062	HY-GARD J20C 9.46L	1.00	85.28	85.28	\$85.28	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF150	ENVIRO FEE	1.00	1.50	1.50	\$1.50	N

PATTISON AGRICULTURE LIMITED
 610 3rd Avenue West, Box 1670
 Shaunavon, SK S0N 2M0
 Phone: (306) 297-2639
 Fax: (306) 297-3827
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. 257125	Internal Used Stock No. 257125	Invoice Number: 3351013
		Invoice Date: 4/17/2025
		Location: 10
		Work Order Number: 482917
		Payment Type: Account
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	Page: 11 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9460R PTO		1RW9460RHCP003293	353784M	

JHYDDIAG2 JD ALL Internal

EF300	ENVIRO FEE	4.00	3.00	3.00	\$12.00	N
Labor: \$1,400.00	Parts: \$719.12	OL&M: \$0.00	Misc: \$13.50	Sub-Total: \$2,132.62		

INVOICE CONTAINS \$87.56 DISCOUNT

Miscellaneous Charges:

SERVICE ACCESSORIES \$150.00

Customer PO No:

Tax Exempt No:

Advisor: Joe Cadieux

Labor: \$9,055.34

Parts: \$8,992.21

OL&M: \$0.00

Misc: (\$445.00)

Grand Total: \$17,602.55

*** DOCUMENT COPY ***

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE -- MIN \$35 ON EMERGENCY/UNIT DOWN ORDERS -- 25% RESTOCKING FOR RET

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: Date: