



ZIMMERER KUBOTA & EQUIPMENT

www.zimmererkubota.com

SERVING YOU FOR OVER 40 YEARS SINCE 1979



5165 MARK IV PARKWAY
FORT WORTH, TX 76106
(817) 281-6143

2825 N. NOLAN RIVER RD.
CLEBURNE, TX 76033
(817) 645-9106

4701 I-35
DENTON, TX 76207
(940) 382-1564

3472 SOUTH US HWY 287
DECATUR, TX 76234
(940) 627-4744

3218 W. US HWY 82
GAINESVILLE, TX 76240
(940) 668-7861

14851 US HWY 75
VAN ALSTYNE, TX 75495
(903) 712-4035

Invoice #	FTW-129577	PO#	
Date	7/23/2026	Terms	PAID
Time	15:26	Due Date	7/23/2026

RO#	FTW-40693		
RO Date	3/26/2026		
Miles	In	0.0	Out 0.0
Hours	In	1349.0	Out 1351.9
Service Writer	Rachel Lee		
Stock#	(323482) KUBOTA		
Serial#	KBCZ021CTRLB34037		
Yr Make Model	KUBOTA SVL65-2HWC		
Description	SVL65-2HWC		
License			
Fleet#			
In Service Date	3/15/2024		

[Redacted Customer Information]

Service Invoice

Customer

Memo: A4596993 ENGINE [Redacted]

Warranty Service Issue # 2

Com: CUSTOMER STATES THAT THE UNIT BLOWS ALOT OF SMOKE AND RUNNING ROUGH

Cause: CONFIRMED CUSTOMER COMPLAINT. FOUND UNIT EMITTING HEAVY WHITE SMOKE DURING OPERATION. PERFORMED INITIAL INSPECTION OF FUEL AND AIR SYSTEMS NO FAULTS FOUND. CHECKED COOLANT LEVEL AND CONDITION COOLANT LEVEL GOOD. NO COOLANT FOUND IN ENGINE OIL AND NO OIL FOUND IN COOLANT. INSPECTED INTAKE AND EXHAUST SYSTEM AND FOUND OIL RESIDUE PRESENT INSIDE EXHAUST PIPE AND TURBOCHARGER HOSES/TUBES. FOUND OIL LEAKING FROM TURBOCHARGER ACTUATOR AREA INDICATING INTERNAL TURBOCHARGER FAILURE. FOUND THAT A BEARING FAILED INTERNALLY IN TURBO. RAN CYLINDER BALANCE TEST RESULTS WITHIN SPECIFICATION. PERFORMED INJECTOR CUTOUT TEST ON ALL INJECTORS OPERATING WITHIN SPECIFICATION. PERFORMED COMPRESSION TEST ON ALL FOUR CYLINDERS. FACTORY SPECIFICATION IS 315 450 PSI. ALL CYLINDERS MEASURED BETWEEN 295 303 PSI BELOW SPECIFICATION, CYLINDER #1 303 PSI #2 295PSI #3 300 PSI #4 295 CONFIRMING ENGINE IS OUT OF ACCEPTABLE OPERATING RANGE. FAILURE DETERMINED TO BE CAUSED BY INTERNAL TURBOCHARGER FAILURE ALLOWING ENGINE OIL TO ENTER INTAKE AND EXHAUST SYSTEM RESULTING IN OIL CONTAMINATION AND INTERNAL ENGINE DAMAGE. ENGINE REQUIRES REPLACEMENT.

THIS WAS PREAPPROVED ON CLAIM A4557136 PLEASE SEE ATTACHED DOCUMENTATION

Fix: REMOVE AND REPLACE ENGINE AND COMPONENTS, WASH UNIT, TEST UNIT.NO FURTHER ISSUES AT THIS TIME

CASUAL PART # 1J716-17010

NEW ENGINE SERIAL # 8TE6662

Note:

Mech	Type	Description				Total
Labor	STANDARD		28.4900			\$5,982.90
Item	77700-13746-620	Oil w/Coolant Test Kit	1.0000	30.20	0.00%	
Item	V0631-51880-620	ELEMENT,ASSY	1.0000	79.54	0.00%	
Item	1J716-00002-620	V2607-CR-TE4-CTLQBB1 TIER 4	1.0000	17018.72	0.00%	
Item	1K947-43172-620	CARTRIDGE,FILTER	1.0000	43.86	0.00%	
Item	3A111-19130-620	ELEMENT,INNER	1.0000	21.43	0.00%	
Item	59800-26110-620	ELEMENT,OUTER A/C	1.0000	26.46	0.00%	
Item	1J770-05810-620	ELEMENT,KIT	1.0000	81.11	0.00%	
Misc.	FREIGHT - PARTS	ENGINE - 9001678258	1.0000	0	0.00%	
Item	77700-06325-620	50/50 Prediluted Antifreeze Coolant, Gal	3.0000	12.81	0.00%	
Misc.	PICK UP & DELIVERY-SERVICE		1.0000	96.00	0.00%	
Subtotal						\$0.00

Printed:10/15/2026 10:03 AM

Customer Name	Invoice#	RO#	Date
		40693	07/23/2026

Repair Totals									
Warranty	Parts:	17,339.75	Labor:	5,982.90	Misc.:	96.00	PreTax Subtotal:	\$23,418.65	
Internal	Parts:		Labor:		Misc.:		PreTax Subtotal:		
Customer	Parts:		Labor:		Misc.:		PreTax Subtotal:		
							Sales Tax:		
							Total Due from Customer:		
Cash	Check	Check #	CC	CC Type	On Acct.	Mfg Credit	CIT	Deposit	Other
\$0.00	\$0.00		\$0.00		\$0.00	\$0.00	\$0.00	\$0.00	\$0.00

PLEASE REMIT TO: P.O. BOX 10198, FAYETTEVILLE, AR 72703

THANK YOU FOR YOUR BUSINESS. COME BACK SOON.

WARRANTY DISCLAIMER

All parts and accessories are sold and all repairs are provided by the dealership as-is. The dealership hereby disclaims all warranties, express and implied, including any implied warranties of merchantability and fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of any parts or accessories or any repairs performed to the vehicle. The only warranties on parts and accessories or repairs are those which may be offered by the manufacturer or original parts distributor, and only such manufacturer or distributor shall be liable for performance under such warranties. Customer shall not be entitled to recover from the dealership any consequential damages, damages to property, damages for loss of use, loss of time, loss of profit or income, or any other incidental damages. Dealership is not liable for damages resulting from improper installation, misuse, or service performed by any third party.

By authorizing service, customer permits dealership and its employees to operate the vehicle for testing, inspection, or delivery at customer's sole risk. An express mechanic's lien is acknowledged to secure the cost of repairs. Dealership is not responsible for personal articles left in the vehicle, or for loss or damage due to fire, theft, or other casualty, and dealership is hereby released from all such claims. Upon non-payment, purchaser is liable for all collection costs including reasonable attorney's fees. Governed by the laws of the State of Texas.

Summary of Charges	
\$0.00	Taxable
\$0.00	Non-Taxable
\$0.00	Subtotal
\$0.00	Sales Tax
\$0.00	PAY THIS AMOUNT
\$0.00	Amount Tendered
\$0.00	Change Due

Customer Signature	Date
--------------------	------

Exempt Tax Cert #:	
Expiration Date:	

Printed:10/15/2026 10:03 AM