

2021 Bobcat T770

MACHINE INFORMATION



VIN/Serial Number: AT6328591

Rego Number:

Comments:

Service History

Date: 2025-11-11	Reading: hours	Serviced by: Quinton Isaac
Service Items: • Engine Oil • Engine Oil Filter • Hydraulic Oil • Fuel Filter • Coolant • Radiator Notes: Installed new front door glass. New fuel cap Parts: • Engine Oil • Engine Oil Filter • Hydraulic Oil • Fuel Filter • Coolant • Radiator		
Created Date: 2026-03-30		Updated Date: 2026-03-30

Date: 2025-10-13	Reading: hours	Serviced by: Quinton Isaac
------------------	----------------	----------------------------

Service Items: • Engine Oil • Engine Oil Filter • Hydraulic Oil • Fuel Filter • Coolant • Radiator	Parts: • Engine Oil • Engine Oil Filter • Hydraulic Oil • Fuel Filter • Coolant • Radiator
Notes: Reimer enterprise came to diagnose AC system. found system ok but Heater valve was stuck open. I replaced Heater valve few weeks later.	
Created Date: 2026-03-29	
Updated Date: 2026-03-29	

Date: 2025-09-09	Reading: hours	Serviced by: Quinton Isaac
Service Items: • Engine Oil • Engine Oil Filter • Hydraulic Oil • Fuel Filter • Coolant • Radiator	Parts: • Engine Oil • Engine Oil Filter • Hydraulic Oil • Fuel Filter • Coolant • Radiator	
Notes: Replaced Left top tilt cylinder pin and tapered bushing.		
Created Date: 2026-03-30		Updated Date: 2026-03-30

Date: 2025-07-18	Reading: 3770 hours	Serviced by: Quinton Isaac
Service Items: • Engine Oil [Replace] • Engine Oil Filter [Replace] • Hydraulic Oil [Inspect] • Fuel Filter [Replace] • Coolant [Inspect] • Radiator [Clean]	Parts: • Engine Oil • Engine Oil Filter • Hydraulic Oil • Fuel Filter • Coolant • Radiator	

Notes:

Bought from Earthworks Equipment in Saskatoon. Was a local trade in for them. Was thru the shop there before I bought it. All filters and fluids changed. Had some warranty history with the Earthworks shop but owner had done all past maintenance. Note when I test drove it i thought the hydraulics seemed slow but everything else worked well. Found out after I got it home that the hydraulic charge pump was bad. That was the cause of slow hydraulics. Earthworks looked after that pump on warranty.

Created Date: 2026-03-29

Updated Date: 2026-08-26