	CR 9.90 Elevation #6 751983003		CR 9.90 Elevation #6 751983003
Repair	Issue	Repair	Part Number
1	Replace Top Sprockets	1	87665225 (X2), 87665224 (X2)
2	Replace Feeder chain	2	48103500
3	Top Feeder house belt tensioner bushing	3	84057311 (X2)
4	Feeder driver chain	4	
5	Elevator Drive chain	5	
6	Lower feeder house belt tensioner bushings	6	84057311 (X2)
7	Feeder drive chain idler bearing	7	87011880
8	DSP Tensioner bushing	8	84057311 (X2)
9	Adjust transiton veins	9	
10	RH Header drive tensioner bushing bearing	10	6205 bearing (X2)
11	Rh Header drive tensioner bushing	11	84057311 (X2)
12	Bubble up idler sprocket and bearing	12	6205 bearing
13	Bubble up chain	13	
14	Elevator drive belt bushing	14	84057311 (X2)
15	Pre-sieve replace (install from #4)	15	
16	Re align shoe drive gear box	16	
17	Unload idler sprocket and bearing	17	87011880
18	Unload gear box oil	18	
19	Bubble up oil	19	
20	Shoe tensioner bushing	20	84056770
21	Unload belt tensioner bushing	21	84057311 (X2)
22	Main drive tensioner bushing	22	84057311 (X2)
23	Chopper jackshaft drive tensioner bushing	23	420434 (X2)
24	Shoe door flap replace	24	87046174
25	LH return drive belt tensioner bearing	25	6205 bearing (X2)
26	Weld RH fan shield	26	
27	Unload gearbox clean out wing bolts	27	80412049 (X2)
28	LH transmission output seal	28	84045429
29	PSD bearings	29	49436 (X3), 247829
30	Replace inner and outer engine air filter	30	5801439820, 90412128
31	Engine Fan belt idler brg	31	6303 bearing
32	C/G drive chain tensioner idlers	32	84401598
33	Door latch RH side	33	81866169
34	Fuel Tank breather	34	
35	Inside cab filter	35	84217229
36	Outside cab filter	36	360260A2
37	PSD drive roller carage bolts	37	86512420 (X6)
38	Vertical unload auger getting wore	38	
39	Replace sieve light housing	39	86590412
40	2x LH turn latch and striker plate	40	81866169 (X2), 9840986
41	Flip chopper knives	41	
42	Replace inner anti wrap shields	42	84482718 (X3)
43	Rotor gearbox oil	43	
44	Rebuild/Replace diff carrier	44	
45	Reseal transmission	45	84071961, 84045429, 9815655 (X2), 84017986, 84078052
46	Replace RH transmission output shaft bearing	46	28042510
47	Reshim transmission shaft	47	84072116, 84072118 (X3)