	CR 9.90 Elevation (C) 751983003		CR 9.90 Elevation (C) 751983003
Repair	**Issue**	**Reapir**	**Part Number**
1	Top feeder belt bushing	**1**	84057311 (X2)
2	Bottom feeder belt bushing	**2**	84057311 (X2)
3	Feeder drive chain	**3**	
4	DSP tensioner bushing	**4**	84057311 (X2)
5	Header drive tensioner rod/nut	**5**	84589000, 84589006
6	Header drive tensioner bushing	**6**	84057311 (X2)
7	Header drive tensioner pulley bearing	**7**	443898
8	Replace header drive with proper belt (3700 to 3660)	**8**	84589013
9	Main drive tensioner bushing	**9**	84057311 (X2)
10	Unload drive tensioner bushing	**10**	84057311 (X2)
11	Unload drive tensioner bearing	**11**	443898 (X2)
12	Chopper drive tensioner bushing	**12**	84057311 (X2)
13	Chopper drive tensioner bearing	**13**	443898 (X2)
14	Beater drive tensioner bushing	**14**	84057311 (X2)
15	Beater drive tensioner bearing	**15**	86588003
16	Unload drive idler sprocket bearing	**16**	66553
17	Flappy paddle bushings	**17**	89833065 (X2)
18	LH return auger worn at top bearing (top bearing bad)	**18**	325103
19	Clean grain ½ link	**19**	
20	Unload jackshaft bearings	**20**	87338614, 84026027
21	Flip chopper knives (no wind)	**21**	
22	Clean grain drive chain	**22**	
23	Rotor screen drive tensioner pulley	**23**	84072736
24	Water pump	**24**	
25	Fan hub loose	**25**	84356151, 84438926
26	Fan hub belt idler	**26**	727874, 47950448
27	Check wiring on boost sensor (end replaced)	**27**	
28	Clean grain jackshaft sprocket, sprocket key, bearings	**28**	87283679, 87748338, 380530, 51626956, 87605590, 87605592
29	LH wheel bearings, cotter pin	**29**	
30	RH wheel bearing cotter pin	**30**	
31	Top chopper belt	**31**	84188121
32	R&R elevator chain	**32**	47949285