

001-201

**PATTISON AGRICULTURE LIMITED**

Hwy 14 West, Box 599
 Unity, SK S0K 4L0
 Phone: (306) 228-2696
 Fax: (306) 228-2776
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351
 Maple Creek, SK (306) 662-2233
 Kindersley, SK (306) 463-2683
 Kyle, SK (306) 375-2302
 Leader, SK (306) 628-3889
 Unity, SK (306) 228-2696
 North Battleford, SK (306) 445-4468
 Humboldt, SK (306) 682-2572
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639
 Yorkton, SK (306) 783-9459
 Balcarres, SK (306) 334-2492
 Moosomin, SK (306) 435-3301
 Preeceville, SK (306) 547-2007
 Russell, MB (204) 773-2149
 Wynyard, SK (306) 554-2536
 Kamsack, SK (306) 542-2814
 Swan River, MB (204) 734-3466

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No:

Deliver To:

Bus Phone:

Prv Phone:

Bus Phone:

Prv Phone:

Invoice Number: **3501894**

Invoice Date: 10/31/2025

Location: 06

Work Order Number: 515072

Payment Type:

Page: 1 of 15

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE X9 1100

875

1H0X911XAP0825166

175073

CC056

EXPERT-1000000122469

COMPLAINT:

01 X9-Series Combine ValueMax Inspection

CORRECTION:

DOES THIS UNIT GET A VALUE MAX STICKER X YES NOHAS THE STICKER BEEN INSTALLED X YES NOTHIS UNIT HAS HAD THE CAB CLEANED MS THIS UNIT HAS HAD A FINAL CHECK OVER JG KITHIS UNIT HAS HAD A COMPLETE GREASE JOB JG

VMC; SEASON OF USE 2026

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26859	INSPECTION+ 3 FLUID TEST KIT	1.00	85.83	0.00	\$0.00	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
LABDIS	LAB DISC CUST	-1.00	1,187.00	1,187.00	(\$1,187.00)	N
Labor: \$5,150.00		Parts: \$0.00	OL&M: \$0.00	Misc: (\$1,187.00)	Sub-Total: \$3,963.00	

EXPERT-1000000076277

COMPLAINT:

02 Engine Oil and Filter, Change.

CORRECTION:

1. Remove and replace the oil filter.

2. To remove the oil, open the drain valve.

3. To fill the oil, remove the cap.

4. Check the oil level after filling with dipstick.

5. The oil level should be at the "FULL" mark on the dipstick.

OIL AND FILTER CHANGED, RAN AND RE-FILLED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE572785	ENGINE OIL FILTER	1.00	137.80	137.80	\$137.80	N
TY26674	PLUS-50 II 15W-40 CK4/SN BOTTLE 946ml	1.00	9.92	9.92	\$9.92	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preaceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3501894
		Invoice Date:	10/31/2025
		Location:	06
		Work Order Number:	515072
		Payment Type:	
		Page:	2 of 15

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9.1100	875	1H0X911XAP0825166	175073	CC056

EXPERT-1000000076277

TY26679	PLUS-50 II 15W-40 CK4/SN 18.9L PAIL	3.00	170.86	170.86	\$512.58	N
TY27928	Winter Fuel Conditioner 946ml	2.00	34.11	34.11	\$68.22	N
TY6341	SD POLYUREA GREASE	1.00	10.76	10.76	\$10.76	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.25	1.25	\$1.25	N
EF15	ENVIRO FEE	1.00	0.15	0.15	\$0.15	N
EF300	ENVIRO FEE	3.00	3.00	3.00	\$9.00	N

Labor: \$250.00 Parts: \$739.28 OL&M: \$0.00 Misc: \$10.40 Sub-Total: \$999.68

EXPERT-1000000211821

COMPLAINT:

03 Rotary Screen / Vacuum Fan Drive Belt, Remove and Replace.

CORRECTION:

1. Pull lockout pin and rotate handrail up until the handrail locks into place.
2. Open engine access cover.
3. Remove engine access shield.
4. Use a breaker bar to relieve belt tension from the tensioner arm and remove the rotary screen driven belt.
5. Use a breaker bar to relieve tension from the tensioner arm and install the replacement rotary screen driven belt.
6. Install the previously removed shield.

BELT REPLACED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE148727	V-Belt	1.00	181.90	181.90	\$181.90	N

Labor: \$250.00 Parts: \$181.90 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$431.90

EXPERT-1000000076703

COMPLAINT:

05 Replace one row of threshing elements(cracked)

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3501894
		Invoice Date:	10/31/2025
		Location:	06
		Work Order Number:	515072
		Payment Type:	
		Page:	3 of 15

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	875	1H0X911XAP0825166	175073	CC056

EXPERT-1000000076703

CORRECTION:

1. Inspect wear on threshing elements.
2. Remove cap screws and threshing element.
3. If one element needs replaced, replace all in the group. Example: If replacing element 2, replace elements 1 and 3 also.
4. Use Threshing Elements and Separator Tine Location diagram for identifying elements and tines.
5. Tighten the threshing element cap screws to specification

ELEMENTS REPLACED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
KXE10756	THRESHING ELEMENT KIT RH	1.00	1,303.91	1,303.91	\$1,303.91	N

Labor: \$210.00 Parts: \$1,303.91 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$1,513.91

DIAG-1000000230153

COMPLAINT:

06 Adjust feeder house drive chain tension.

CORRECTION:

FEEDER HOUSE CHAIN ADJUSTED
 FLIPPED CHAIN GUARD AROUND

Labor: \$150.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$150.00

EXPERT-1000000088467

COMPLAINT:

07 Update All Controller Software.

CORRECTION:

1. Update all available controller software to the latest version of Software available.

UPDATES INSTALLED

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 14 West, Box 599
 Unity, SK S0K 4L0
 Phone: (306) 228-2696
 Fax: (306) 228-2776
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No:

Deliver To:

Invoice Number: **3501894**

Invoice Date: 10/31/2025

Location: 06

Work Order Number: 515072

Payment Type:

Page: 4 of 15

Bus Phone:

Bus Phone:

Prv Phone:

Prv Phone:

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE X9 1100

875

1H0X911XAP0825166

175073

CC056

EXPERT-1000000088467**Labor: \$400.00****Parts: \$0.00****OL&M: \$0.00****Misc: \$0.00****Sub-Total: \$400.00****DIAG-1000000190991**

COMPLAINT:

09 Repair or replace harness and remove field fix

CORRECTION:

REMOVED OLD HARNESS

REPLACED WITH NEW HARNESS

CHECKED IF THERE ANY CODES

CODE FED 517715.04 WAS DUE TO A CONNECTOR BENT, REPAIRED

Part Number
AXE91897

Description
Wiring Harness

Quantity
1.00

List Price
3,230.41

Net Price
3,230.41

Extended Price
\$3,230.41

Taxed Ind
N

Labor: \$600.00**Parts: \$3,230.41****OL&M: \$0.00****Misc: \$0.00****Sub-Total: \$3,830.41****DIAG-1000000230471**

COMPLAINT:

10 Repair rear and front concaves

CORRECTION:

RH REAR AND FRONT CONCAVES BENT BACK, WELDED AND GRINDED

Labor: \$300.00**Parts: \$0.00****OL&M: \$0.00****Misc: \$0.00****Sub-Total: \$300.00****EXPERT-1000000146885**

COMPLAINT:

11 Active Tailings Concave, Level and Adjust. Level the active tailings concave

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeseville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number:	3501894
Invoice Date:	10/31/2025
Location:	06
Work Order Number:	515072
Payment Type:	
Page:	5 of 15

Make/Model:	Meter:	Serial Number:	Eq ID	Fleet No:
JOHN DEERE X9 1100	875	1H0X911XAP0825166	175073	CC056

EXPERT-1000000146885

- Loosen nuts to remove tension from the tailings and cleaning fan drive belt.
- Remove tailings and cleaning fan drive belt to allow tailings system to turn freely.
- Move adjustment handle downward and install cap screws in existing holes.
- Loosen cap screws and nuts.
- Slowly adjust access door while rotating beater until "ticking" is heard.
- Slowly back off until "ticking" stops and tighten cap screws and nuts.
- Install and adjust tailings system drive belt tensioner until washer is positioned between end of gauge and bottom of step. (See Supporting Document - Tailings and Cleaning Fan Drive Belt—Adjusting).
- Install previously removed shield.

TAILINGS CONCAVES LEVELED/ADJUSTED

Labor: \$200.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$200.00
-----------------	---------------	--------------	--------------	---------------------

EXPERT-1000000139767

COMPLAINT:

12 Repair front and rear concave on left side
Install concaves and level/calibrate

CORRECTION:

- Start engine and press the threshing clearance adjust switch.
- Set threshing clearance to 0.
- Remove the front separator grate deflector.
- Remove cap screws, cap screws and nuts, and the front separator grate.
- Move handle to shift the rotor gear case in the neutral position.
- Loosen the lower lock nut, lower adjustment nut, and the upper lock nut on the front and rear concave cylinders.
- While turning the left-hand rotor clockwise by hand, tighten the upper adjustment nut slowly on the front concave cylinder until the elements "tick" against the rotor. Back off the nut one full turn. Tighten nut finger tight.
- While turning the right-hand rotor counterclockwise by hand, tighten the upper adjustment nut slowly on the front concave cylinder until the elements "tick" against the rotor. Back off the nut one full turn. Tighten nut finger tight.
- Tighten the lower adjustment nut on the front and rear concave cylinders to specification.
- Tighten the upper and lower lock nuts.
- Perform the calibration. (See Supporting Documents - User Calibrations - Procedures).

CONCAVES INSTALLED, LEVELED, CALIBRATED

TEST AT RUN UP

RE-LEVEL, CONCAVES ARE GOOD

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3501894 Invoice Date: 10/31/2025 Location: 06 Work Order Number: 515072 Payment Type: Page: 6 of 15
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	875	1H0X911XAP0825166	175073	CC056

EXPERT-1000000139767

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
11M7030	M5x40 COTTER PIN	4.00	1.04	1.04	\$4.16	N
Labor: \$700.00		Parts: \$4.16	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$704.16	

EXPERT-1000000146159

COMPLAINT:

15 Tailings Elevator Paddle Chain Remove Half Link & Adjust.

CORRECTION:

1. ADJUSTED CHAIN TENSION

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
11M7099	M2x12 COTTER PIN	2.00	0.31	0.31	\$0.62	N
Labor: \$100.00		Parts: \$0.62	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$100.62	

DIAG-1000000230512

COMPLAINT:

16 Left Side Concave, Diagnose and Repair

CORRECTION:

STRAIGHTEN CONCAVE

WELDED UP CRACKS AND GRIND SMOOTH

Labor: \$300.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$300.00
-----------------	---------------	--------------	--------------	---------------------

EXPERT-1000000073663

COMPLAINT:

17 Cabin Air Filter, Remove and Replace.

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 14 West, Box 599

Unity, SK S0K 4L0

Phone: (306) 228-2696

Fax: (306) 228-2776

Http://www.pattisonag.com

GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE**

Invoice To Account No:

Deliver To:

SERVICE INVOICE

		Invoice Number:	3501894
		Invoice Date:	10/31/2025
		Location:	06
		Work Order Number:	515072
		Payment Type:	
Bus Phone:	Bus Phone:	Page:	7 of 15
Prv Phone:	Prv Phone:		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	875	1H0X911XAP0825166	175073	CC056

EXPERT-1000000073663

1. Turn knob and lower access cover.
2. Remove fresh air filter.
3. Remove and replace cabin air filter.
4. Assemble in reverse order.

AIR FILTER REPLACED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TA32591	Cab FreshAir Filter	1.00	121.63	121.63	\$121.63	N

Labor: \$34.00 Parts: \$121.63 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$155.63

EXPERT-10000000272244**COMPLAINT:**

19 Feed Accelerator Gearcase Inner Shaft Seal.

Piece of previous blown belt wrapped around inner seal. Starting to sweat and likely to cause further seal failure.

CORRECTION:

1. Remove all belts from all sheaves on the gearbox.
2. Remove the driven sheave from the feed accelerator gearbox.
3. With the help of another technician, remove the feed accelerator gearbox.
4. Remove the inside sheave with pusher bolts.
5. Remove the inner shaft seal.
6. Install a new inner shaft seal.
7. Install the feed accelerator drive sheave.
8. With the help of another technician, re-install the feed accelerator gearbox.
9. Fill the feed accelerator gearbox with 80W90 gear oil.
10. Install driven sheave on gearbox.
11. Install all removed belts on the gearbox and tension to specification.
12. Ensure everything is properly aligned.
13. Run the machine and check for leaks.
14. Check oil level is still at specification.

CHECKED FOR LEAKS ON RUN UP

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
51M7041	O-RING M14	1.00	3.95	3.95	\$3.95	N
DE31849	SEAL	1.00	14.85	14.85	\$14.85	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Belcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number: **3501894**
Invoice Date: 10/31/2025
Location: 06
Work Order Number: 515072
Payment Type:
Page: 8 of 15

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	875	1H0X911XAP0825166	175073	CC056

EXPERT-1000000272244

P50883	RING	1.00	2.21	2.21	\$2.21	N
TY6296	80W90 946ml GL5	3.00	15.99	15.99	\$47.97	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF15	ENVIRO FEE	3.00	0.15	0.15	\$0.45	N

Labor: \$1,200.00 Parts: \$68.98 OL&M: \$0.00 Misc: \$0.45 Sub-Total: \$1,269.43

EXPERT-1000000073665

COMPLAINT:

20 Cabin Recirculation Filter, Remove and Replace.

CORRECTION:

1. Remove cover.
2. Remove recirculating filter.
3. Remove and replace cabin recirculation filter.
4. Assemble in reverse order.

FILTER REPLACED

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE70605	CAB RECIRC AIR FILTER	1.00	40.66	40.66	\$40.66	N

Labor: \$34.00 Parts: \$40.66 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$74.66

EXPERT-1000000076481

COMPLAINT:

21 Air Filter Elements, Change.

CORRECTION:

1. Remove the air filter elements.
2. Replace with new air filter elements.
3. Check for leaks and for collapse of the aspirator tube.

AIR FILTER REPLACED/ MARKED

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3501894
		Invoice Date:	10/31/2025
		Location:	06
		Work Order Number:	515072
		Payment Type:	
		Page:	9 of 15

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	875	1H0X911XAP0825166	175073	CC056

EXPERT-1000000076481

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE11090	Primary Engine Air Filter	1.00	461.37	461.37	\$461.37	N
HXE11091	Secondary EngAir Filter	1.00	325.55	325.55	\$325.55	N

Labor: \$100.00 Parts: \$786.92 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$886.92

EXPERT-1000000075959

COMPLAINT:

22 Rotor Variable Belt, Remove and Replace.

CORRECTION:

LOOSEN THE HYDRAULIC LINE ON THE ROTOR
 USED BOLTS TO SPLIT PLATE
 LOOSEN THE 4 BOLTS ADJUSTING BOLTS FOR THE ROTOR
 LOOSE THE 2 NUTS ON EYE BOLT
 REMOVED OLD BELT AND INSTALL NEW BELT
 TIGHTEN ALL HARDWARE

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE107859	X9 ROTOR DRIVE BELT	1.00	1,347.29	1,347.29	\$1,347.29	N

Labor: \$400.00 Parts: \$1,347.29 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$1,747.29

EXPERT-1000000147071

COMPLAINT:

23 Clean Grain Elevator Paddle Chain, Remove Half Link & Adjust. REMOVE HALF LINK AND ADJUST CLEAN GRAIN ELEVATOR PADDLE CHAIN

CORRECTION:

ADJUSTED CLEAN GRAIN ELEVATOR PADDLE CHAIN

Labor: \$100.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$100.00

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 14 West, Box 599

Unity, SK S0K 4L0

Phone: (306) 228-2696

Fax: (306) 228-2776

Http://www.pattisonag.com

GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE**

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3501894
		Invoice Date:	10/31/2025
		Location:	06
		Work Order Number:	515072
		Payment Type:	.
		Page:	10 of 15

Make/Model:	Meter:	Serial Number:	Eq ID	Fleet No:
JOHN DEERE X9 1100	875	1H0X911XAP0825166	175073	CC056

EXPERT-1000000229735**COMPLAINT:**

24 Rear Chaffer Element Louver Remove & Replace.

Replace chaffer louver rh rear bent and calibrate sieve and chaffer

CORRECTION:

1. Remove chaffer element and place on a suitable work table. (See Supporting Document - Remove and Install Chaffer Element).
2. Turn the chaffer element over so that the bottom side is up.
3. Remove actuator from chaffer element. (See Supporting Document - Remove and Install Remote Shoe Actuator Motor).
4. Open rear portion of chaffer using the manual adjuster.
5. Remove cap screws and nuts from the manual adjuster.
6. Unscrew manual adjuster counterclockwise and remove.
7. Remove lock nut, bushings, and cap screw.
8. At the rear of chaffer, use a screwdriver to lift end of the leaf spring.
9. Grasp end of the leaf spring with locking pliers and remove. Mark each leaf spring for the reassembly in same location.
10. Remove steel strips from the chaffer in same manner.
11. Mark location of push nuts to be installed in same location as removed. Remove and retain push nuts on ends of louvers.
12. Raise actuator adjuster bar to access louvers.
13. Remove damaged louvers.
14. Remove debris from channels.
15. Install in reverse order of removal following these special instructions:
16. - Guide leaf spring into the channel using locking pliers if necessary.
17. - Tighten cap screw and nuts to specification.
18. - Tighten cap screw and nuts to specification.
19. - Tighten adjuster lock nut to specification.
20. Tighten the actuator cap screw and nuts and actuator lock nut. (See Supporting Document - Remove and Install Remote Shoe Actuator Motor).
21. Install chaffer element. (See Supporting Document - Remove and Install Chaffer Element).
22. Perform calibration.

REMOVE CHAFFER**REPAIRED BENT LOUVERS****INSTALL CHAFFER****CALIBRATED SIEVE AND CHAFFER****CALIBRATION SUCCESSFUL****Labor: \$400.00****Parts: \$0.00****OL&M: \$0.00****Misc: \$0.00****Sub-Total: \$400.00**

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3501894
		Invoice Date:	10/31/2025
		Location:	06
		Work Order Number:	515072
		Payment Type:	
		Page:	11 of 15

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	875	1H0X911XAP0825166	175073	CC056

DIAG-1000000173074

COMPLAINT:

25 Adjust hose routing on back of elevator (pinched)

CORRECTION:

HOSE WAS PINCHED AGAINST THE ELEVATOR
LOOSEN HOSE AND RE ADJUST

Labor: \$100.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$100.00
-----------------	---------------	--------------	--------------	---------------------

EXPERT-1000000154413

COMPLAINT:

26 Static Drag Cable, Install.
Static drag cable ripped off

CORRECTION:

1. Install a static drag cable at the customers request.
DRAG CABLE AND STICKERS INSTALLED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
STATIC	STATIC DRAG CABLE 3/8"	1.00	242.83	242.83	\$242.83	N

Labor: \$100.00	Parts: \$242.83	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$342.83
-----------------	-----------------	--------------	--------------	---------------------

EXPERT-1000000177055

COMPLAINT:

27 Active Tailings System Drive Belt, Remove and Replace.

CORRECTION:

1. Loosen nuts to remove tension from the tailings system elevator and auger belt.
2. Remove the belt and install replacement belt.
3. Tighten nut until the washer is positioned between the end of the gauge and the bottom of the step.
4. Tighten lock nut to specification.

BELT REPLACED

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Belcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:		Invoice Number:	3501894
		Invoice Date:	10/31/2025
		Location:	06
		Work Order Number:	515072
		Payment Type:	
		Page:	12 of 15

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	875	1H0X911XAP0825166	175073	CC056

EXPERT-1000000177055

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE124188	V-Belt	1.00	336.40	336.40	\$336.40	N
Labor: \$140.00		Parts: \$336.40	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$476.40	

EXPERT-1000000176030

COMPLAINT:

28 Replace two bent feed accelerator wings

CORRECTION:

1. Remove round-head bolts and wear strips from the feed accelerator wings.
2. Remove cap screws from the feed accelerator wing.
3. Replace the feed accelerator wings as required.
4. Install the feed accelerator wing and hardware.
5. Tighten the feed accelerator cap screws to specification.
6. Install the feed accelerator wing wear strips and hardware.
7. Tighten the wear strip round-head bolts to specification.

**BOLTS THAT HOLD THE WING WERE RUSTED HARD TO REMOVED
CLEAN BOLT HOLES TORQUED ALL BOLTS TO SPEC**

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
19M7785	M10x25 FLG 10.9 BOLT	6.00	2.43	2.43	\$14.58	N
19M7786	M10x30 FLG 10.9 BOLT	28.00	2.58	2.58	\$72.24	N
H137329	M12 FLANGE LOCK NUT	1.00	3.09	3.09	\$3.09	N
HXE174444	X9 FEED ACCELERATOR/BEATER STRIP ASN 82K	2.00	326.61	326.61	\$653.22	N
HXE177730	X9 FEED ACC/BEATER STRIP ASN 82K	2.00	476.68	476.68	\$953.36	N
L215374	M12 x 35 CARRIAGE BOLT 10.9	1.00	4.99	4.99	\$4.99	N
Labor: \$300.00		Parts: \$1,701.48	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,001.48	

DIAG-1000000230650

COMPLAINT:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number: **3501894**
Invoice Date: 10/31/2025
Location: 06
Work Order Number: 515072
Payment Type:
Page: 13 of 15

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	875	1H0X911XAP0825166	175073	CC056

DIAG-1000000230650

29 Clean debris and build up from tailboard cover

CORRECTION:
REMOVE COVER

BLOW OUT SPREADER TOP
INSTALL TAILBOARD, CANVAS

Labor: \$100.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$100.00
-----------------	---------------	--------------	--------------	---------------------

EXPERT-1000000075441

COMPLAINT:

30 Replace one row of threshing elements

CORRECTION:

1. Inspect wear on threshing elements.
2. Remove cap screws and threshing element.
3. If one element needs replaced, replace all in the group. Example: If replacing element 2, replace elements 1 and 3 also.
4. Use Threshing Elements and Separator Tine Location diagram for identifying elements and tines.
5. Tighten the threshing element cap screws to specification.

THRESHING ELEMENTS REPLACED
TORQUED TO 60LBS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
KXE10755	Threshing Element kit LH	1.00	1,278.82	1,278.82	\$1,278.82	N
Labor: \$210.00	Parts: \$1,278.82	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,488.82		

JWASH JD X9

COMPLAINT:

31 WASH USED X9 COMBINE. READY FOR DISPLAY.

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number: **3501894**
Invoice Date: 10/31/2025
Location: 06
Work Order Number: 515072
Payment Type:
Page: 14 of 15

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	875	1H0X911XAP0825166	175073	CC056

JWASH JD X9

INCLUDES THE FOLLOWING:

- BLOW OFF ALL CHAFF.
- WASHING OUT RADIATOR AND ALL COOLERS.
- CLEAN OUT GRAIN TANK AND UNLOADING AUGER.
- WASH EXTERIOR PANELS AND ALL SHIELDS.
- VACUUM CAB AND WASH FLOOR MAT
- CLEAN WINDOWS

Labor: \$2,070.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,070.00
-------------------	---------------	--------------	--------------	-----------------------

JELECDIAG6 JD ALL

COMPLAINT:

32 DIAGNOSE FED 517715.04

CORRECTION:

CHECKED CABLES, SEEMED GOOD, CHECKED POWER CONNECTION AND CLEANED, NO CHANGE
CHANGED SENSOR
CHECKED VOLTAGE AND OHMS THROUGH THREE CONNECTIONS, FOUND A BENT PIN THAT CORRELATED TO THE
SENSOR.
REPAIRED PIN AND CODES IS GONE

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 14 West, Box 599

Unity, SK S0K 4L0

Phone: (306) 228-2696

Fax: (306) 228-2776

Http://www.pattisonag.com

GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Presceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE**

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3501894
		Invoice Date:	10/31/2025
		Location:	06
		Work Order Number:	515072
		Payment Type:	
		Page:	15 of 15

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	875	1H0X911XAP0825166	175073	CC056

JELECDIAG6 JD ALL

RE584414

PRESSURE SENSOR

1.00 183.13 183.13 \$183.13 N

Labor: \$232.00	Parts: \$183.13	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$415.13
------------------------	------------------------	-------------------------	---------------------	----------------------------

INVOICE CONTAINS \$85.83 DISCOUNT

Miscellaneous Charges:

SERVICE ACCESSORIES

\$150.00

Customer PO No:

Tax Exempt No:

Advisor:

Labor:	\$14,130.00
Parts:	\$11,568.42
OL&M:	\$0.00
Misc:	(\$1,026.15)
Grand Total:	\$24,672.27

*** DOCUMENT COPY ***

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE -- MIN \$35 ON EMERGENCY/UNIT DOWN ORDERS -- 25% RESTOCKING FOR RET

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by: Date: