

001-202

**PATTISON AGRICULTURE LIMITED**

Hwy 83 Bypass
Swan River, MB R0L 1Z0
Phone: (204) 734-3466
Fax: (204) 734-5677
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number:	3160141
Invoice Date:	5/9/2024
Location:	19
Work Order Number:	437370
Payment Type:	
Page:	1 of 6

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	347	1H0X911XPPB825200	175052	

JGLC JD X SERIES ALL**COMPLAINT:**

01 X9 SERIES COMBINE VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER


CORRECTION:

VALUEMAX GREEN LIGHT SELF PROPELLED COMBINE CHECKLIST

HEADER SERIAL # _____ N/A _____
ENGINE HOURS _____ 347 _____
SEPERATOR HOURS _____

DOES THIS UNIT GET A VALUEMAX STICKER X YES NO
HAS THE STICKER BEEN INSTALLED X YES NO
THIS UNIT HAS HAD THE CAB CLEANED _____ (INITIAL)
THIS UNIT HAS HAD A FINAL CHECKOVER _____ (INITIAL)
THIS UNIT HAS HAD A COMPLETE GREASE JOB OD _____ (INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMERS INSTRUCTIONS:

**Job Total: \$4,748.18****JWASH JD X9****COMPLAINT:**

02 WASH USED X9 COMBINE. READY FOR DISPLAY.

CORRECTION:

INCLUDES THE FOLLOWING:

- BLOW OFF ALL CHAFF.
- WASHING OUT RADIATOR AND ALL COOLERS.
- CLEAN OUT GRAIN TANK AND UNLOADING AUGER.
- WASH EXTERIOR PANELS AND ALL SHIELDS.
- VACUUM CAB AND WASH FLOOR MAT
- CLEAN WINDOWS

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 83 Bypass
 Swan River, MB R0L 1Z0
 Phone: (204) 734-3466
 Fax: (204) 734-5677
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3160141 Invoice Date: 5/9/2024 Location: 19 Work Order Number: 437370 Payment Type: Page: 2 of 6
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	347	1H0X911XPPB825200	175052	

JWASH JD X9

Labor: \$2,070.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,070.00
--------------------------	----------------------	-------------------------	---------------------	------------------------------

JCABFILTER JD X9 11

COMPLAINT:
 11 REPLACE CAB AIR FILTERS

CORRECTION:
 REMOVED CAB AIR FILTERS
 CLEANED FILTER HOUSING
 INSTALLED NEW AIR FILTERS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE70605	Cab Recirc Air Filter	1.00	36.26	36.26	\$36.26	N
RE284091	Cab Air Filter	1.00	119.47	119.47	\$119.47	N
Labor: \$50.00	Parts: \$155.73	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$205.73		

J06001690 JD S790

COMPLAINT:
 12 WATER EXTINGUISHER, RECHARGE

CORRECTION:
 RECHARGED WATER FIRE EXTINGUISHER

Labor: \$25.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$25.00
-----------------------	----------------------	-------------------------	---------------------	---------------------------

JADJCHAFSIEV JD X911

COMPLAINT:
 13 FACTORY CALIBRATION OF SIEVE AND CHAFFER

CORRECTION:

PATTISON AGRICULTURE LIMITED

Hwy 83 Bypass
 Swan River, MB R0L 1Z0
 Phone: (204) 734-3466
 Fax: (204) 734-5677
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 763-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:		Bus Phone: Prv Phone:		Invoice Number:	3160141
				Invoice Date:	5/9/2024
				Location:	19
				Work Order Number:	437370
				Payment Type:	
				Page:	3 of 6

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	347	1H0X911XPPB825200	175052	

JADJCHAFSIEV JD X911

PERFORM FACTORY CALIBRATION AS PER SERVICE ADVISOR

Labor: \$195.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$195.00
-----------------	---------------	--------------	--------------	---------------------

JGEN02-**COMPLAINT:**

14 REPLACE BOTTOM STAIRCASE & ADJUST THE FOLDING LADDER

(DAMAGED)

CORRECTION:
 REMOVED AND REPLACED BOTTOM STAIRCASE
 ADJUSTED FOLDING LADDER

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE154049	Plate	1.00	153.81	153.81	\$153.81	N
HXE154052	Plate	1.00	155.47	155.47	\$155.47	N
Labor: \$146.25		Parts: \$309.28	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$455.53	

J06001001 JD S790**COMPLAINT:**

15 TOP UP ALL FLUIDS.

CORRECTION:

TOPPED UP COOLANT AND CHOPPER GEARCASE

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26575	COOL-GARDII 3.78L 50/50 PREMIX	1.00	25.91	25.91	\$25.91	N
TY6354	HY-GARD J20C JUG 3.78L	1.00	35.60	35.60	\$35.60	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF25	ENVIRO FEE	1.00	0.25	0.25	\$0.25	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 83 Bypass
Swan River, MB R0L 1Z0
Phone: (204) 734-3466
Fax: (204) 734-5677
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351
Maple Creek, SK (306) 662-2233
Kindersley, SK (306) 463-2683
Kyle, SK (306) 375-2302
Leader, SK (306) 628-3889
Unity, SK (306) 228-2696
North Battleford, SK (306) 445-4468
Humboldt, SK (306) 682-2572
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639

Yorkton, SK (306) 783-9459
Balcarres, SK (306) 334-2492
Moosomin, SK (306) 435-3301
Preeceville, SK (306) 547-2007
Russell, MB (204) 773-2149
Wynyard, SK (306) 554-2536
Kamsack, SK (306) 542-2814
Swan River, MB (204) 734-3466

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Bus Phone: Prv Phone:		Invoice Number: 3160141 Invoice Date: 5/9/2024 Location: 19 Work Order Number: 437370 Payment Type: Page: 4 of 6	
--------------------------	--	--	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	347	1H0X911XPPB825200	175052	

J06001001 JD S790

EF60 ENVIRO FEE 1.00 0.60 0.60 \$0.60 N

Labor: \$50.00 Parts: \$61.51 OL&M: \$0.00 Misc: \$0.85 Sub-Total: \$112.36

JGEN01-**COMPLAINT:**

16 REPLACE DAMAGED TRANSMISSION HOSE HOLDERS

CORRECTION:

FULLY RAISED FEEDER HOUSING AND ENGAGED SAFETY STOPS

BLOCKED FRONT DRIVE TIRES

REMOVED TRANSMISSION SHIELDS

REPLACED DAMAGED TRANSMISSION HOSE HOLDERS/ CLAMPS, SCREWS, NUTS AND TIE BANDS

REINSTALLED TRANSMISSION SHIELDS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7298	M8-1.25 FLG NUT	2.00	1.52	1.52	\$3.04	N
19M9843	M8x90 FLG 10.9 BOLT	1.00	6.47	6.47	\$6.47	N
H224073	TIE BAND	8.00	3.24	3.24	\$25.92	N
HXE127195	Clamp	4.00	22.22	22.22	\$88.88	N
Labor: \$48.75		Parts: \$124.31	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$173.06	

J06180300 JD S680**COMPLAINT:**

17 REPLACE FEEDERHOUSE STONE TRAP DOOR AND HOUSING.

CORRECTION:

REPLACED FEEDERHOUSE STONE TRAP DOOR AND SEALS

TOUCHED UP PAINT

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE37564	Door	1.00	922.64	922.64	\$922.64	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 83 Bypass
Swan River, MB R0L 1Z0
Phone: (204) 734-3466
Fax: (204) 734-5677
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3160141 Invoice Date: 5/9/2024 Location: 19 Work Order Number: 437370 Payment Type: Page: 5 of 6
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	347	1H0X911XPPB825200	175052	

J06180300 JD S680

HXE161580 Seal	2.00	25.30	25.30	\$50.60	N
----------------	------	-------	-------	---------	---

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
FRT	FREIGHT	1.00	35.00	35.00	\$35.00	N

Labor: \$390.00	Parts: \$973.24	OL&M: \$0.00	Misc: \$35.00	Sub-Total: \$1,398.24
------------------------	------------------------	-------------------------	----------------------	------------------------------

J06180268 JD X9 1100

COMPLAINT:

21 INSTALL CONCAVES, LEVEL AND CALIBRATE.

CORRECTION:

INSTALLED CONCAVES (ENSURE THAT THE CONCAVES ARE TIGHT TO ONE ANOTHER AND THERE IS ADEQUATE BULKHEAD CLEARANCE)
 LEVELED CONCAVES AS PER SERVICE ADVISOR.
 PERFORMED CONCAVE CALIBRATION.

Labor: \$780.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$780.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

JGEN08-

COMPLAINT:

23 REPLACE PRIMARY ENGINE AIR FILTER

CORRECTION:

CLEANED AREA.
 REPLACED PRIMARY ENGINE AIR FILTER

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE11090	Primary Engine Air Filter	1.00	427.55	427.55	\$427.55	N

Labor: \$30.00	Parts: \$427.55	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$457.55
-----------------------	------------------------	-------------------------	---------------------	----------------------------

J10030100 JD X9 1100

COMPLAINT:

CONTINUED ON NEXT PAGE->



PATTISON AGRICULTURE LIMITED
Hwy 83 Bypass
Swan River, MB R0L 1Z0
Phone: (204) 734-3466
Fax: (204) 734-5677
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

Bus Phone:	Bus Phone:	Invoice Number:	3160141
Prv Phone:	Prv Phone:	Invoice Date:	5/9/2024
		Location:	19
		Work Order Number:	437370
		Payment Type:	
		Page:	6 of 6

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	347	1H0X911XPPB825200	175052	

J10030100 JD X9 1100

25 REPLACE ENGINE FUEL FILTERS.

CORRECTION:

REPLACED PRIMARY AND SECONDARY FUEL FILTERS.

REMOVED AND CLEANED FUEL STRAINER.

bled FUEL SYSTEM.

FUNCTION AND LEAK CHECKED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ124761	Primary Fuel Filter 13.6L	1.00	151.17	151.17	\$151.17	N
DZ124786	Secondary Fuel Filter 13.6L	1.00	145.22	145.22	\$145.22	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	2.00	1.00	1.00	\$2.00	N

Labor: \$80.00 Parts: \$296.39 OL&M: \$0.00 Misc: \$2.00 Sub-Total: \$378.39

ATTENTION: Part(s) values for this invoice have changed. Original Invoice Parts Sale Value = \$1210.86
INVOICE CONTAINS \$22.21 DISCOUNT

Miscellaneous Charges:

SERVICE ACCESSORIES

\$150.00

Customer PO No:

Tax Exempt No:

Advisor: Taylor Blaylock

Job Total: \$9,850.86

Grand Total: \$9,850.86

*** DOCUMENT COPY ***

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE -- MIN \$35 ON EMERGENCY/UNIT DOWN ORDERS -- 25% RESTOCKING FOR RET

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: Date:

001-202



PATTISON AGRICULTURE LIMITED
 Hwy 83 Bypass
 Swan River, MB R0L 1Z0
 Phone: (204) 734-3466
 Fax: (204) 734-5677
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Deliver To: Bus Phone: Prv Phone:		Invoice Number: 3317621 Invoice Date: 1/14/2025 Location: 19 Work Order Number: 472221 Payment Type: Page: 1 of 13		
Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	597	1H0X911XPPB825200	175052	

JGLC JD X SERIES ALL**COMPLAINT:**

01 X9 SERIES COMBINE VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER


CORRECTION:

VALUEMAX GREEN LIGHT SELF PROPELLED COMBINE CHECKLIST

 HEADER SERIAL # _____ N/A _____
 ENGINE HOURS _____ 596.5 _____
 SEPARATOR HOURS _____ 434.9 _____

DOES THIS UNIT GET A VALUEMAX STICKER ☒ YES ☐ NO
 HAS THE STICKER BEEN INSTALLED ☒ YES ☐ NO
 THIS UNIT HAS HAD THE CAB CLEANED _____ DB _____ (INITIAL)
 THIS UNIT HAS HAD A FINAL CHECKOVER _____ TF _____ (INITIAL)
 THIS UNIT HAS HAD A COMPLETE GREASE JOB _____ YES _____ (INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMERS INSTRUCTIONS:

**Job Total: \$3,860.00****JWASH JD X9****COMPLAINT:**

02 WASH USED X9 COMBINE. READY FOR DISPLAY.

CORRECTION:

INCLUDES THE FOLLOWING:

- BLOW OFF ALL CHAFF.
- WASHING OUT RADIATOR AND ALL COOLERS.
- CLEAN OUT GRAIN TANK AND UNLOADING AUGER.
- WASH EXTERIOR PANELS AND ALL SHIELDS.
- VACUUM CAB AND WASH FLOOR MAT
- CLEAN WINDOWS

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 83 Bypass
 Swan River, MB R0L 1Z0
 Phone: (204) 734-3466
 Fax: (204) 734-5677
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3317621
		Invoice Date:	1/14/2025
		Location:	19
		Work Order Number:	472221
		Payment Type:	
		Page:	3 of 13

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	597	1H0X911XPPB825200	175052	

J06001009 JD X9 1100

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY6354	HY-GARD J20C JUG 3.78L	1.00	35.64	35.64	\$35.64	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF60	ENVIRO FEE	1.00	0.60	0.60	\$0.60	N
Labor: \$30.00		Parts: \$35.64	OL&M: \$0.00	Misc: \$0.60	Sub-Total: \$66.24	

JFUELVENT JD S790

COMPLAINT:

05 CLEAN OR REPLACE FUEL TANK VENT.

CORRECTION:

REMOVED AND REPLACED FUEL TANK VENT

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H216169	DEF Tank Breather	1.00	45.60	45.60	\$45.60	N
Labor: \$25.00		Parts: \$45.60	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$70.60	

J10030113 JD S790

COMPLAINT:

06 REPLACE DEF TANK VENT FILTER.

CORRECTION:

REMOVED AND REPLACED DEF TANK VENT FILTER

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H216169	DEF Tank Breather	1.00	45.60	45.60	\$45.60	N
Labor: \$30.00		Parts: \$45.60	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$75.60	

JENGAIRFILT JD X9 11

COMPLAINT:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 83 Bypass
 Swan River, MB R0L 1Z0
 Phone: (204) 734-3466
 Fax: (204) 734-5677
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3317621 Invoice Date: 1/14/2025 Location: 19 Work Order Number: 472221 Payment Type: Page: 5 of 13
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	597	1H0X911XPPB825200	175052	

JGEN09- |
 EF15 ENVIRO FEE 1.00 0.15 0.15 \$0.15 N

Labor: \$50.00	Parts: \$15.99	OL&M: \$0.00	Misc: \$0.15	Sub-Total: \$66.14
-----------------------	-----------------------	-------------------------	---------------------	---------------------------

JHYDDIAG2 JD ALL**COMPLAINT:**

10 DIAGNOSE HYDRAULIC OIL LEAKING FROM ENGINE FAN FITTING

CORRECTION:

REMOVED UPPER PROTECTIVE COVER FROM THE ENGINE COMPARTMENT
 REMOVED RADIATOR SUPPORT BEAM
 REMOVED UPPER PART OF THE PROTECTIVE FIBERGLASS CASING FROM THE ENGINE COOLING FAN
 RAN ENGINE ON DIFFERENT SPEEDS FOR MAKING PRESSURE IN THE ENGINE FAN HYDRAULIC LINE
 DURING DIAGNOSTICS FOUND THE BANJO BOLT WAS NOT PROPERLY TIGHTENED
 REMOVED BANJO BOLT AND O-RINGS
 CHECKED FOR DAMAGE AND FOUND NONE
 REINSTALLED BANJO BOLT AND TIGHTENED TO SPECIFICATION
 CLEANED AREA AROUND THE ENGINE FAN
 REINSTALLED PREVIOUSLY LISTED PARTS IN REVERSE ORDER
 RAN UNIT AND CHECK ENGINE FAN OPERATION
 FOUND UNIT OPERATES AS SHOULD WITH NO LEAKS



Labor: \$600.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$600.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

JGEN08-**COMPLAINT:**

11 TIGHTEN CLAMPS ON ALL COOLANT HOSES

CORRECTION:

TIGHTENED ALL ENGINE COOLANT SYSTEM CLAMPS TO SPECIFICATIONS

Labor: \$100.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$100.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 83 Bypass
 Swan River, MB R0L 1Z0
 Phone: (204) 734-3466
 Fax: (204) 734-5677
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3317621
		Invoice Date:	1/14/2025
		Location:	19
		Work Order Number:	472221
		Payment Type:	
		Page:	6 of 13

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	597	1H0X911XPPB825200	175052	

J06030050 JD S790**COMPLAINT:**

12 REBUILD ROTARY SCREEN JACKSHAFT ASSEMBLY.

CORRECTION:

SHIFTED ROTARY SCREEN BELT TO THE NON-WORKING POSITION
 LOOSENED VACUUM FAN DRIVE BELT
 DISMANTLED OUTER PULLEY OF THE ROTARY SCREEN JACKSHAFT
 DISMANTLED INNER PULLEY OF THE ROTARY SCREEN JACKSHAFT WITH BUSHING AND SPACER
 LOOSENED BOLTS SECURING INNER AND OUTER BEARINGS TO THE SHAFT
 REMOVED BOLTS SECURING INNER BEARING CAGE TO THE FRAME
 REMOVED INNER BEARING WITH SPECIAL TOOL
 REMOVED BOLTS SECURING OUTER BEARING CAGE TO THE FRAME
 REMOVED JACKSHAFT FROM THE UNIT
 INSTALLATION OF NEW PARTS FOR THE ROTARY SCREEN JACKSHAFT ASSEMBLY WAS CARRIED OUT IN THE
 REVERSE ORDER OF DISASSEMBLY
 PERFORMED REQUIRED ADJUSTMENTS AND TIGHTENED/TORQUED BOLTS TO SPEC AS PER SERVICE ADVISOR

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
49M4100	SHAFT KEY	1.00	5.84	5.84	\$5.84	N
49M5606	Shaft Key	1.00	3.59	3.59	\$3.59	N
AXE70716	Bearing w/Housing	2.00	139.77	139.77	\$279.54	N
HXE166406	SHAFT	1.00	501.15	501.15	\$501.15	N
Labor: \$850.00		Parts: \$790.12	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,640.12	

JGEN07-**COMPLAINT:**

13 ADJUST ENGINE DOOR AND REPLACE MISSING LADDER PIN

CORRECTION:

LOOSENED ENGINE DOOR LOCK FASTENING
 CLOSED ENGINE DOOR AND ADJUSTED DOOR LOCK POSITION
 TIGHTENED ENGINE DOOR LOCK FASTENING BOLTS TO SPECIFICATION
 CHECKED ENGINE DOOR FUNCTION AND FOUND TO OPERATE AS SHOULD
 INSTALLED MISSING LADDER PIN
 REPAIR COMPLETE

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 83 Bypass
 Swan River, MB R0L 1Z0
 Phone: (204) 734-3466
 Fax: (204) 734-5677
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3317621 Invoice Date: 1/14/2025 Location: 19 Work Order Number: 472221 Payment Type: Page: 7 of 13
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	597	1H0X911XPPB825200	175052	

JGEN07-

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AL200495	Quick Lock Pin	1.00	53.45	53.45	\$53.45	N
Labor: \$200.00		Parts: \$53.45	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$253.45	

JGEN06-

COMPLAINT:

14 REPLACE DAMAGED SEPARATOR DOOR SEAL

CORRECTION:

REMOVED DAMAGED SEPARATOR DOOR SEAL
 CLEANED DEBRIS FROM AREA WHERE NEW SEAL IS TO BE INSTALLED
 INSTALLED NEW SEAL ON SEPARATOR DOOR

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE141829	Seal	1.00	61.01	61.01	\$61.01	N
Labor: \$100.00		Parts: \$61.01	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$161.01	

JGEN05-

COMPLAINT:

15 REPLACE VACUUM FAN SEAL

CORRECTION:

REMOVED DAMAGED VACUUM FAN SEAL
 CLEANED SEATING AREA FOR NEW SEAL TO BE INSTALLED
 INSTALLED NEW SEAL
 CHECKED OPERATION AND FOUND TO OPERATE AS SHOULD

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE38720	Vacuum Fan WEATHERSTR	1.00	88.86	88.86	\$88.86	N
Labor: \$100.00		Parts: \$88.86	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$188.86	

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 83 Bypass
 Swan River, MB R0L 1Z0
 Phone: (204) 734-3466
 Fax: (204) 734-5677
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3317621
		Invoice Date:	1/14/2025
		Location:	19
		Work Order Number:	472221
		Payment Type:	
		Page:	8 of 13

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	597	1H0X911XPPB825200	175052	

JGEN04-**COMPLAINT:**

16 TIGHTEN HOSE CLAMPS BETWEEN MEG AND HYDRAULIC EXPANSION TANK

CORRECTION:

CLEANED AND TIGHTENED HOSE CLAMPS BETWEEN MEG AND HYDRAULIC EXPANSION TANK TO SPEC

Labor: \$100.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$100.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

J06001555 JD X9 1100**COMPLAINT:**

17 TIGHTEN BELTS AND CHAINS NOT INCLUDED IN VMI INSPECTION.

CORRECTION:

**TECHNICIANS ADD STORY FOR CORRECTION OF WHICH BELTS AND CHAINS WILL BE ADJUSTED

- TAILING ELEVATOR CONVEYOR CHAIN TIGHTEN TO SPECIFICATION.
- TAILING ELEVATOR DRIVE BELT TIGHTEN TO SPECIFICATION.
- CLEANING SHOE CONVEYOR CHAIN TIGHTEN TO SPECIFICATION.
- CLEANING SHOE ELEVATOR DRIVE BELT TIGHTEN TO SPECIFICATION.

Labor: \$300.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$300.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

J06180268 JD X9 1100**COMPLAINT:**

18 INSTALL CONCAVES, LEVEL AND CALIBRATE.

CORRECTION:

INSTALLED CONCAVES (ENSURE THAT THE CONCAVES ARE TIGHT TO ONE ANOTHER AND THERE IS ADEQUATE BULKHEAD CLEARANCE)
 LEVELED CONCAVES AS PER SERVICE ADVISOR.
 PERFORMED CONCAVE CALIBRATION.

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 83 Bypass
 Swan River, MB R0L 1Z0
 Phone: (204) 734-3466
 Fax: (204) 734-5677
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:		Invoice Number: 3317621 Invoice Date: 1/14/2025 Location: 19 Work Order Number: 472221 Payment Type: Page: 9 of 13	
--------------------------	--	--	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	597	1H0X911XPPB825200	175052	

J06180268 JD X9 1100

Labor: \$800.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$800.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

JGEN03- Internal**COMPLAINT:**

19 REPLACE DAMAGED FEEDERHOUSE SEAL

CORRECTION:

DISMANTLED FEEDER HOUSE TOP SHEET WITH DAMAGED SEAL ASSEMBLY
 REMOVED DAMAGED SEAL FROM THE TOP FEEDER HOUSE SHEET
 CLEANED DEBRIS FROM ALL CONNECTION AREAS BETWEEN SEAL AND SHEET
 INSTALLED NEW SEAL ON THE TOP FEEDER HOUSE SHEET
 TIGHTENED BOLTS SECURING SEAL TO SPECIFICATION
 INSTALLED TOP FEEDER HOUSE SHEET ON THE FEEDER HOUSE
 TIGHTENED HARDWARE SECURING SHEET TO SPECIFICATION

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7396	M8-1.25 FLG NYLOCK NUT	22.00	1.76	1.76	\$38.72	N
HXE174701	Seal	1.00	70.26	70.26	\$70.26	N

Labor: \$300.00	Parts: \$108.98	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$408.98
------------------------	------------------------	-------------------------	---------------------	----------------------------

JGEN02-**COMPLAINT:**

20 REPLACE 1 DAMAGED CONVEYOR CHAIN SLAT

CORRECTION:

REMOVED DAMAGED CONVEYOR CHAIN SLAT
 INSTALLED NEW CHAIN SLAT WITH NEW HARDWARE

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7517	M10-1.5 NYLOCK NUT	4.00	2.38	2.38	\$9.52	N
19M7402	M10x25 HH 10.9 BOLT	4.00	2.30	2.30	\$9.20	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 83 Bypass
Swan River, MB R0L 1Z0
Phone: (204) 734-3466
Fax: (204) 734-5677
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Deliver To:

Invoice Number: 3317621 Invoice Date: 1/14/2025 Location: 19 Work Order Number: 472221 Payment Type: Page: 10 of 13	
Bus Phone: Prv Phone:	Bus Phone: Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	597	1H0X911XPPB825200	175052	

JGEN02-

HXE113327	X9 FEEDER CHAIN SLAT	1.00	67.52	67.52	\$67.52	N
-----------	----------------------	------	-------	-------	---------	---

Labor: \$100.00	Parts: \$86.24	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$186.24
------------------------	-----------------------	-------------------------	---------------------	----------------------------

J06001040 JD X9 1100

COMPLAINT:

21 REMOVE HALF LINK AND ADJUST FEEDERHOUSE CONVEYOR CHAIN TENSION.

CORRECTION:

LOOSENED FEEDER HOUSE CONVEYOR CHAIN
 REMOVED HALF LINKS FROM EACH BRANCH OF CHAIN
 CONNECTED ALL BRANCHES, APPLIED LOCTITE TO ALL BOLTS AND TIGHTENED TO SPECIFICATIONS
 TIGHTENED FEEDER HOUSE CONVEYOR CHAIN TO SPECIFICATIONS
 CHECKED FEEDER HOUSE CONVEYOR CHAIN FUNCTION AND CHAIN TENSION
 FOUND TO OPERATE AS SHOULD

Labor: \$300.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$300.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

JGEN01-

COMPLAINT:

22 REPLACE FEEDERHOUSE DRIVE CHAIN GUIDES

CORRECTION:

LOOSENED RIGHT SIDE FEEDER HOUSE CHAIN
 DISMANTLED CHAIN GUIDES SUPPORT PLATES
 REPLACED PLASTIC CHAIN GUIDES
 INSTALLED CHAIN GUIDES SUPPORT PLATES ON THE FEEDER HOUSE AND TIGHTENED TO SPECIFICATION
 INSTALLED FEEDER HOUSE DRIVE CHAIN AND TIGHTENED TO SPECIFICATION
 CHECKED OPERATION OF THE FEEDER HOUSE DRIVE CHAIN
 FOUND TO OPERATE AS SHOULD

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE159287	Guide	1.00	77.18	77.18	\$77.18	N

PATTISON AGRICULTURE LIMITED

Hwy 83 Bypass
 Swan River, MB R0L 1Z0
 Phone: (204) 734-3466
 Fax: (204) 734-5677
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3317621 Invoice Date: 1/14/2025 Location: 19 Work Order Number: 472221 Payment Type: t Page: 11 of 13
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	597	1H0X911XPPB825200	175052	

JGEN01-

HXE160082	GUIDE	1.00	102.66	102.66	\$102.66	N
-----------	-------	------	--------	--------	----------	---

Labor: \$250.00	Parts: \$179.84	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$429.84
------------------------	------------------------	-------------------------	---------------------	----------------------------

JSOFTWARE JD X9 1100**COMPLAINT:**

23 UPDATE ALL CONTROLLER SOFTWARE

CORRECTION:

UPDATED SOFTWARE ON ____ COREOS-Gen4 OS, DISPLAY, FED AND MG-2 ____ CONTROLLERS.
 HAD TO PERFORM THE FOLLOWING CALIBRATIONS.

Labor: \$400.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$400.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

JELECDIAG3 JD ALL**COMPLAINT:**

24 DIAGNOSE CODES POD 158.01 AND POD 517594.16

CORRECTION:

REMOVED TRANSMISSION RETURN FILTER AND CHECKED FOR ANY DAMAGE OR RESTRICTION
 FOUND NO ISSUES
 REINSTALLED FILTER AND TIGHTENED TO SPECIFICATION
 FOUND DTC NO LONGER APPEARED

Labor: \$120.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$120.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

JELECDIAG1 JD ALL**COMPLAINT:**

25 DIAGNOSE CODE CAB 523597.05

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 83 Bypass
Swan River, MB R0L 1Z0
Phone: (204) 734-3466
Fax: (204) 734-5677
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Deliver To:

Bus Phone: Prv Phone:		Bus Phone: Prv Phone:		Invoice Number: 3317621
				Invoice Date: 1/14/2025
				Location: 19
				Work Order Number: 472221
				Payment Type:
				Page: 12 of 13

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	597	1H0X911XPPB825200	175052	

JELECDIAG1 JD ALL

KEYED SWITCH ON AND ALL DTCs DELETED AND UPDATED
FOUND WHEN BEACONS TURNED ON THE TROUBLE CODE FOR RIGHT BEACON BECOMES ACTIVE
FOLLOWED STEPS AS PER SERVICE ADVISOR DIAGNOSTICS PROCEDURES
DISMANTLED FRONT PART OF CABIN ROOF AND DISCONNECTED CONNECTOR XE82 AND CHECKED FOR DAMAGE OR
OXIDIZED CONTACTS
FOUND IMPROPERLY INSTALLED CONNECTOR XE82.
REINSTALLED CONNECTOR XE82 PROPERLY AND APPEAR OF THE DTC CAB 523597.05 CHECKED.
FOUND CODE NO LONGER APPEARS
REINSTALLED FRONT PART OF THE CABIN ROOF BACK AND BOLTS
SECURING ROOF TIGHTENED TO SPECIFICATION
APPEARING OF THIS DTC CHECKED AGAIN AND NO PROBLEMS FOUND

Labor: \$300.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$300.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

JELECDIAG2 JD ALL

COMPLAINT:
26 DIAGNOSE CODES ATX 158.04, 168.04 AND AIC 168.04

CORRECTION:
RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS:

ATX AND PODC CONTROLLERS CHECKED FOR DAMAGE AND DIRTY OR LOOSEN CONTACTS. PROBLEMS NOT FOUND.
FUSE F101 CHECKED FOR DAMAGE AND NO PROBLEMS FOUND.
WITH ENGINE RUNNING, CONNECTOR XA26 ON THE ATX CONTROLLER DISCONNECTED AND VOLTAGE BETWEEN M1
TERMINAL AND COMBINE GROUND CHECKED. IT WAS 12.9V.
KEY SWITCH TURN OFF AND CONNECTORS XA26 AND XA68-3 DISCONNECTED FROM THE ATX AND PODC
CONTROLLERS.
RESISTANCE BETWEEN TERMINAL M1 OF XA26 CONNECTOR AND CONTACT 7 OF XA68-3 CONNECTOR CHECKED AND
RESISTANCE 154 Ohm.
FOUND THAT CONTACT 7 OF XA68-3 CONNECTOR WAS LOOSEN. CAVITY OF THIS CONTACT WAS SQUEEZED AND
INSTALLED IN THE CONNECTOR.
DTCs WERE DELETED AND UPDATED .
ATX 158.04, ATX 168.04 AND AIC 168.04 CODES NO APPEAR.

Labor: \$400.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$400.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

CONTINUED ON NEXT PAGE->

**PATTISON AGRICULTURE LIMITED**

Hwy 83 Bypass
Swan River, MB R0L 1Z0
Phone: (204) 734-3466
Fax: (204) 734-5677
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number: **3317621**
Invoice Date: 1/14/2025
Location: 19
Work Order Number: 472221
Payment Type:
Page: 13 of 13

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	597	1H0X911XPPB825200	175052	

JDISC JD ALL**COMPLAINT:**

28 GREEN LIGHT INSPECTION DISCOUNTS

****2025 VALUEMAX CERTIFIED****

ONE YEAR PARTS AND LABOR WARRANTY ON REPAIRS COMPLETED, STARTING AUGUST 1ST 2025

CORRECTION:

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
---------------	---------------	--------------	--------------	-------------------

Miscellaneous Charges:

SERVICE ACCESSORIES

\$150.00

Customer PO No:**Tax Exempt No:****Advisor:** Taylor Blaylock**Job Total:** \$14,311.86**Grand Total:** \$14,311.86***** DOCUMENT COPY *****

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE -- MIN \$35 ON EMERGENCY/UNIT DOWN ORDERS -- 25% RESTOCKING FOR RET

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: Date:

001 - 202



PATTISON AGRICULTURE LIMITED
Hwy 83 Bypass
Swan River, MB R0L 1Z0
Phone: (204) 734-3466
Fax: (204) 734-5677
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3511417 Invoice Date: 11/26/2025 Location: 19 Work Order Number: 516547 Payment Type: Page: 1 of 9
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	749	1H0X911XPPB825200	175052	

EXPERT-1000000143717

COMPLAINT:


01 X9-Series Combine ValueMax Inspection Job

CORRECTION:

VALUEMAX GREEN LIGHT SELF PROPELLED COMBINE CHECKLIST

 HEADER SERIAL # _____ N/A _____
 ENGINE HOURS 748.6
 SEPARATOR HOURS 510.4

DOES THIS UNIT GET A VALUEMAX STICKER X YES NO
 HAS THE STICKER BEEN INSTALLED X YES NO
 THIS UNIT HAS HAD THE CAB CLEANED _____ RG _____ (INITIAL)
 THIS UNIT HAS HAD A FINAL CHECKOVER _____ DT _____ (INITIAL)
 THIS UNIT HAS HAD A COMPLETE GREASE JOB _____ OS _____ (INITIAL)



Job Total: \$3,963.00

JELECDIAG3 JD ALL

COMPLAINT:

03 DIAGNOSE CHOPPER SHROUD HAD 517805.04 & 517804.04 AND WINDROW PIVOT HAD 517586.04 TROUBLE CODES

CORRECTION:

PATTISON AGRICULTURE LIMITED

Hwy 83 Bypass
 Swan River, MB R0L 1Z0
 Phone: (204) 734-3466
 Fax: (204) 734-5677
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number:	3511417
Invoice Date:	11/26/2025
Location:	19
Work Order Number:	516547
Payment Type:	
Page:	2 of 9

Bus Phone:
 Prv Phone:

Bus Phone:
 Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	749	1H0X911XPPB825200	175052	

JELECDIAG3 JD ALL

LOOKED UP CODES HAD 517805.04 & 517804.04 AND WINDROW PIVOT HAD 517586.04 TROUBLE CODES
 FOUND LOW BATTERY POWER CAUSED CODE HAD 517804.04 AND HAD 517805.04 TO APPEAR
 CHARGED BATTERIES AND FOUND THE TWO DTCs NO LONGER APPEARED
 DURING HAD 517586.04 DIAGNOSTICS FOUND WIRES AND CONNECTORS IN GOOD CONDITION
 FOUND NO DAMAGE OR BLOCKS OF THE WINDROW ACTUATOR OR PIVOT
 DTAC SOLUTION 221743 RECOMMENDED TO REPLACE WINDROW ACTUATOR
 INSTALLED NEW ACTUATOR AND CABLE
 CHECKED WINDROW/SPREADER CHOPPER FUNCTION
 FOUND CODE HAD 517586.04 NO LONGER APPEARED AND THE WINDROW/SPREADER SYSTEM WORKS AS SHOULD

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE105709	Actuator	1.00	2,154.65	2,154.65	\$2,154.65	N
AXE105831	Wiring Harness	1.00	333.52	333.52	\$333.52	N

Labor: \$1,050.00	Parts: \$2,488.17	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$3,538.17
--------------------------	--------------------------	-------------------------	---------------------	------------------------------

EXPERT-1000000213917**COMPLAINT:**

04 Feeder House Lower Drive Chain Guide, Remove, flip & reinstall

CORRECTION:

LOOSENEED AND REMOVED FEEDER HOUSE DRIVE CHAIN
 REMOVED LOWER FEEDER HOUSE DRIVE CHAIN GUIDE, FLIPPED AND REINSTALLED
 REINSTALLED FEEDER HOUSE DRIVE CHAIN AND TIGHTENED

Labor: \$105.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$105.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

DIAG-1000000168106**COMPLAINT:**

05 Multi-Coupler Hydraulic Hoses, Diagnose and Repair 1

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 83 Bypass
 Swan River, MB R0L 1Z0
 Phone: (204) 734-3466
 Fax: (204) 734-5677
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

		Invoice Number:	3511417
		Invoice Date:	11/26/2025
		Location:	19
		Work Order Number:	516547
		Payment Type:	
		Page:	3 of 9

Bus Phone:
 Prv Phone:

Bus Phone:
 Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	749	1H0X911XPPB825200	175052	

DIAG-1000000168106

DISCONNECTED LH MULTI COUPLER HYDRAULIC HOSES
 INSPECTED FITTING O-RINGS AND FOUND O-RINGS IN SPEC
 DISCONNECTED MULTI COUPLER ELECTRICAL WIRINGS AND CONNECTORS
 REMOVED MULTI COUPLER FROM FEEDER HOUSE
 REMOVED MULTI COUPLER SUPPORT BRACKET
 REMOVED TECHNOLOGICAL HOLES PLUGS AND REPLACED PLUG O-RINGS
 REINSTALLED TECHNOLOGICAL HOLES PLUGS AND TIGHTENED TO SPECIFICATIONS
 REASSEMBLED THE MULTI COUPLER ASSEMBLY IN REVERSE ORDER OF DISASSEMBLY
 CHECKED MULTI COUPLER FUNCTIONS AND FOUND TO OPERATE AS SHOULD
 REPAIR COMPLETE

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
R26375	O-RING	1.00	2.95	2.95	\$2.95	N
R26448	O-RING	2.00	2.57	2.57	\$5.14	N
R30903	O-RING	1.00	2.12	2.12	\$2.12	N
Labor: \$315.00		Parts: \$10.21	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$325.21	

EXPERT-1000000139767

COMPLAINT:
 06 Concave Level and Adjust

CORRECTION:
 CONCAVE ZERO LEVELING AND CLEARANCE CALIBRATIONS PERFORMED AS PER SERVICE ADVISOR
 RECOMMENDATIONS ON BOTH SIDES OF THE COMBINE.
 OPERATIONS OF THE CONCAVE LEVELING SYSTEM CHECKED AND NO PROBLEMS DETECTED.

Labor: \$525.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$525.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

EXPERT-1000000135714

COMPLAINT:
 07 Perform Factory Calibration of Sieve and Chaffer FACTORY CALIBRATION OF SIEVE AND CHAFFER

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 83 Bypass
Swan River, MB R0L 1Z0
Phone: (204) 734-3466
Fax: (204) 734-5677
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3511417 Invoice Date: 11/26/2025 Location: 19 Work Order Number: 516547 Payment Type: Page: 4 of 9
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	749	1H0X911XPPB825200	175052	

EXPERT-1000000135714

SIEVE AND CHAFFER CALIBRATIONS PERFORMED AS PER SERVICE ADVISOR RECOMMENDED.

Labor: \$210.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$210.00
-----------------	---------------	--------------	--------------	---------------------

EXPERT-1000000291867

COMPLAINT:

08 Clean Grain Elevator Paddle Chain, Adjust

CORRECTION:

Removed nuts, shield and washers.
 Loosened nuts on the bearing mount plate.
 Loosened nuts on the adjusting screw.
 Turned the adjusting nut to change the chain tension:
 - Turning the nut counterclockwise tightens the chain.
 - Turning the nut clockwise loosens the chain.
 Ensured the chain was adjusted properly by checking the lower end can move side-to-side on the sprocket but cannot be pulled away from it.
 If the chain loosens up to 6 mm (1/4 in) from the sprocket, readjust the chain.
 Tightened all nuts.
 Reinstalled washers, shield and nuts.

Labor: \$52.50	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$52.50
----------------	---------------	--------------	--------------	--------------------

EXPERT-1000000076286

COMPLAINT:

09 Engine Coolant, Add

CORRECTION:

Topped up engine coolant to spec

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26575	COOL-GARDII 3.78L 50/50 PREMIX	1.00	26.38	26.38	\$26.38	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 83 Bypass
 Swan River, MB R0L 1Z0
 Phone: (204) 734-3466
 Fax: (204) 734-5677
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3511417
		Invoice Date:	11/26/2025
		Location:	19
		Work Order Number:	516547
		Payment Type:	
		Page:	5 of 9

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	749	1H0X911XPPB825200	175052	

EXPERT-1000000076286

EF25	ENVIRO FEE	1.00	0.25	0.25	\$0.25	N
------	------------	------	------	------	--------	---

Labor: \$52.50	Parts: \$26.38	OL&M: \$0.00	Misc: \$0.25	Sub-Total: \$79.13
-----------------------	-----------------------	-------------------------	---------------------	---------------------------

EXPERT-1000000213518**COMPLAINT:**

10 Cab Ladder Step Links, Remove and Replace

CORRECTION:

REMOVED DAMAGED BOTTOM STEP
 STRAIGHTENED BENT BRACKETS
 INSTALLED RUBBER BRACKETS ON THE LADDER AND TIGHTENED TO SPECIFICATIONS
 INSTALLED BOTTOM STEP AND TIGHTENED TO SPECIFICATIONS
 PAINTED OUTER SIDES OF THE BENT BRACKETS
 CHECKED CAB LADDER FUNCTION AND FOUND TO OPERATE AS SHOULD
 REPAIR COMPLETE

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
03M7195	M10x45 CB 8.8 SN	10.00	2.91	2.91	\$29.10	N
14M7296	M10-1.5 FLG NUT	6.00	2.16	2.16	\$12.96	N
HXE180483	STRAP	2.00	22.74	22.74	\$45.48	N
HXE181173	Hanger	2.00	109.56	109.56	\$219.12	N
HXE185452	STRAP	2.00	39.45	39.45	\$78.90	N
Labor: \$210.00		Parts: \$385.56	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$595.56	

EXPERT-1000000074148**COMPLAINT:**

11 Fuel Filters, Remove and Replace

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 83 Bypass
 Swan River, MB R0L 1Z0
 Phone: (204) 734-3466
 Fax: (204) 734-5677
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

		Invoice Number:	3511417
		Invoice Date:	11/26/2025
		Location:	19
		Work Order Number:	516547
		Payment Type:	
Bus Phone:	Bus Phone:	Page:	6 of 9
Prv Phone:	Prv Phone:		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	749	1H0X911XPPB825200	175052	

EXPERT-1000000074148

Closed fuel precleaner valve
 Removed and replaced secondary fuel filter
 Removed and replaced primary fuel filter
 Disconnected water sensor (if equipped).
 Removed fuel from the filters and discarded.
 Lubricated the replacement primary and secondary fuel filter seals with a thin film of oil or fuel.
 Aligned filter slots on the primary and secondary fuel filters with housing tabs.
 Installed and tightened primary and secondary fuel filters until it is hand-tight.
 Tightened primary fuel filter by an additional 1/2 turn.
 Tightened secondary fuel filter by one additional full turn.
 Opened valve on the fuel precleaner.
 Primed fuel system, turned the key switch to the ON position for 60 seconds.
 Started engine and ran 3—5 minutes at low idle.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ124761	Primary Fuel Filter 13.6L	1.00	155.99	155.99	\$155.99	N
DZ124786	Secondary Fuel Filter 13.6L	1.00	149.84	149.84	\$149.84	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	2.00	1.25	1.25	\$2.50	N
Labor: \$80.00		Parts: \$305.83	OL&M: \$0.00	Misc: \$2.50	Sub-Total: \$388.33	

EXPERT-1000000076481**COMPLAINT:**

12 Air Filter Elements, Change

CORRECTION:

Removed and replaced air filter elements.
 Checked for leaks and for collapse of the aspirator tube.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE11090	Primary Engine Air Filter	1.00	461.37	461.37	\$461.37	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 83 Bypass
 Swan River, MB R0L 1Z0
 Phone: (204) 734-3466
 Fax: (204) 734-5677
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 763-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number:	3511417
Invoice Date:	11/26/2025
Location:	19
Work Order Number:	516547
Payment Type:	
Page:	7 of 9

Bus Phone:
 Prv Phone:

Bus Phone:
 Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	749	1H0X911XPPB825200	175052	

EXPERT-1000000076481

HXE11091	Secondary EngAir Filter	1.00	325.55	325.55	\$325.55	N
----------	-------------------------	------	--------	--------	----------	---

Labor: \$50.00	Parts: \$786.92	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$836.92
-----------------------	------------------------	-------------------------	---------------------	----------------------------

EXPERT-1000000076277**COMPLAINT:**

13 Engine Oil and Filter, Change

CORRECTION:

DRAINED ENGINE OIL
 REMOVED ENGINE OIL FILTER
 CLEANED ENGINE OIL FILTER HOUSING
 INSTALLED NEW ENGINE OIL FILTER AND MARKED
 FILLED WITH NEW ENGINE OIL TO SPEC
 RAN UNIT AND RECHECKED OIL LEVEL
 FOUND OIL IN SPEC

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE572785	ENGINE OIL FILTER	1.00	137.80	137.80	\$137.80	N
TY26674	PLUS-50 II 15W-40 CK4/SN BOTTLE 946ml	1.00	9.92	9.92	\$9.92	N
TY26675	PLUS-50 II 15W-40 CK4/SN JUG 9.46L	6.00	89.73	89.73	\$538.38	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	1.00	1.25	1.25	\$1.25	N
EF15	ENVIRO FEE	1.00	0.15	0.15	\$0.15	N
EF150	ENVIRO FEE	6.00	1.50	1.50	\$9.00	N

Labor: \$125.00	Parts: \$686.10	OL&M: \$0.00	Misc: \$10.40	Sub-Total: \$821.50
------------------------	------------------------	-------------------------	----------------------	----------------------------

EXPERT-1000000073663**COMPLAINT:**

14 Cabin Air Filter, Remove and Replace

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 83 Bypass
 Swan River, MB R0L 1Z0
 Phone: (204) 734-3466
 Fax: (204) 734-5677
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number: **3511417**
 Invoice Date: 11/26/2025
 Location: 19
 Work Order Number: 516547
 Payment Type: i
 Page: 8 of 9

Bus Phone:
 Prv Phone:

Bus Phone:
 Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	749	1H0X911XPPB825200	175052	

EXPERT-1000000073663

REMOVED CAB FRESH AIR FILTER
 CLEANED FILTER HOUSING
 MARKED AND INSTALLED NEW CAB FRESH FILTER

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TA32591	Cab FreshAir Filter	1.00	121.63	121.63	\$121.63	N
Labor: \$17.00		Parts: \$121.63	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$138.63	

EXPERT-1000000073665

COMPLAINT:
 15 Cabin Recirculation Filter, Remove and Replace

CORRECTION:
 Removed cover.
 Removed recirculating filter.
 Removed and replaced cabin recirculation filter.
 Assembled in reverse order.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE70605	Cab Recirc Air Filter	1.00	40.66	40.66	\$40.66	N
Labor: \$17.00		Parts: \$40.66	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$57.66	

JDISC JD ALL

COMPLAINT:
 16 GREEN LIGHT INSPECTION DISCOUNTS

****2026 VALUEMAX CERTIFIED****

ONE YEAR PARTS AND LABOR WARRANTY ON REPAIRS COMPLETED, STARTING AUGUST 1ST 2026

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 83 Bypass
Swan River, MB R0L 1Z0
Phone: (204) 734-3466
Fax: (204) 734-5677
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:

Invoice Number:	3511417
Invoice Date:	11/26/2025
Location:	19
Work Order Number:	516547
Payment Type:	
Page:	9 of 9

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	749	1H0X911XPPB825200	175052	

JDISC JD ALL

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
---------------	---------------	--------------	--------------	-------------------

Miscellaneous Charges:
SERVICE ACCESSORIES

\$150.00

Customer PO No:
Tax Exempt No:
Advisor: Tammy Forsachuk

Job Total: \$11,786.61
Grand Total: \$11,786.61

*** DOCUMENT COPY ***

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE -- MIN \$35 ON EMERGENCY/UNIT DOWN ORDERS -- 25% RESTOCKING FOR RET

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: Date: