

003-245



JOHN DEERE

SERVICE INVOICE

PATTISON AGRICULTURE LIMITED
 Hwy 38 South, Box 1057
 Kelvington, SK S0A 1W0
 Phone: (306) 327-4355
 Fax: (306) 327-4314
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3425549 Invoice Date: 7/30/2025 Location: 09 Work Order Number: 483962 Payment Type: Page: 1 of 18
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9520RX PTO	3519	1RW9520RVJP805521	W0805521	

JGL4WD JD ALL**COMPLAINT:**

01 4WD TRACTOR VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER


CORRECTION:

VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKLIST

 HOURS: 3519
 TRACTOR DYNOED AT:

 DOES THIS UNIT GET A VALUEMAX STICKER __ YES __X__ NO
 HAS STICKER BEEN INSTALLED __ YES __X__ NO
 CAB HAS BEEN COMPLETELY CLEANED __JOE__(INITIAL)
 THIS UNIT HAS HAD A FINAL CHECKOVER __AK__(INITIAL)
 THIS UNIT HAS HAD A COMPLETE GREASE JOB __AK__(INITIAL)
THINGS NOTED BUT NOT REPAIRED ON CUSTOMER'S INSTRUCTIONS:

- REAR DAMPENER PUSHED IN.
- FAN SHROUD HAS CRACK.
- TOP UP WINDSHIELD FLUID.
- SIDE MIRROR BROKEN.
- MISSING OPERATORS MANUAL.
- TRACKS HAS SOME DAMAGE.



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY6341	SD POLYUREA GREASE	1.00	11.14	11.14	\$11.14	N
Labor: \$2,500.00		Parts: \$11.14	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,511.14	

JWASH10 USED 4WD**COMPLAINT:**

02 WASH USED 4WD TRACTOR. READY FOR DISPLAY.

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 38 South, Box 1057
 Kelvington, SK S0A 1W0
 Phone: (306) 327-4355
 Fax: (306) 327-4314
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Bus Phone: Prv Phone:		Invoice Number: 3425549 Invoice Date: 7/30/2025 Location: 09 Work Order Number: 483962 Payment Type: Page: 2 of 18			

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9520RX PTO	3519	1RW9520RVJP805521	W0805521	

JWASH10 USED 4WD

INCLUDES THE FOLLOWING:

- WASH COMPLETE EXTERIOR.
- WASHING OUT RADIATOR AND ALL COOLERS.
- VACUUM CAB AND WASH FLOOR MAT.
- WASH ALL CAB INTERIOR SURFACES
- CLEAN WINDOWS


Labor: \$920.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$920.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

JGEN03-

COMPLAINT:

03 RETURN EMISSIONS TO FACTORY

CORRECTION:



CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 38 South, Box 1057
Kelvington, SK S0A 1W0
Phone: (306) 327-4355
Fax: (306) 327-4314
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE****SERVICE INVOICE**

Deliver To:		Invoice Number: 3425549 Invoice Date: 7/30/2025 Location: 09 Work Order Number: 483962 Payment Type: Page: 3 of 18
Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	
Make/Model: JOHN DEERE 9520RX PTO	Meter: 3519	Serial Number: 1RW9520RVJP805521
	Eq ID: W0805521	Fleet No:

JGEN03-

REMOVED TOP SHIELD TO GET ACCESS TO THE EMISSION.
 DISCONNECTED COOLANT, DEF LINES FROM DEF NOZZLE.
 REMOVED HARNESS AND DEF NOZZLE.
 REMOVED SHIELDS AROUND DOS FILTER AND DPF.
 REMOVED SHIELDS AROUND SCR CANISTER.
 REMOVED ALL TEMPERATURE SENSORS AND PRESSURE SENSORS.
 REMOVED DEF PIPE AND HOSE CLAMPS.
 REMOVED DOC RIPE AND INSTALLED FILTER.
 REINSTALLED EVERYTHING BACK.
 PLUGGED TEMPERATURE MODULE BACK.
 REMOVED BLOCKING PLATE FROM EGR COOLER.
 REASSEMBLED EGR COOLER BACK.
 STARTED UNIT AND ATTEMPTED TO WARM UP TO THE OPERATING TEMPERATURE.
 ECU 002629.03 CODE POPULATES ON THE SCREEN.
 LIFTED HOOD AND CHECKED SENSOR.
 CLEANED CONTACTS AND PLUGGED BACK IN PLACE.
 INSTALLED NEW ECU SOFTWARE.
 CHECKED IF UNIT STILL HAS DEF AND CHECKED QUALITY.
 CHECKED DEF PUMP IF IT WAS WORKING.
 REMOVED LINE FROM THE NOZZLE.
 ATTEMPTED TO FLUSH LINES, NO SUCCESS.
 REMOVED IN LINE AND DEF PUMP FILTERS AND REPLACED THEM WITH A NEW ONES.
 CHECKED PUMP, PUMP WAS WORKING BUT NO DEF COMING OF THE LINE.
 CHECKED AL LINES FOR ANY LEAKAGE OR DAMAGE.
 FOUND SUCTION LINE WAS BROKEN BY THE CLAMP.
 REMOVED LINE AND REPLACED WITH A NEW ONE.
 PURGE SYSTEM AND RAN DEF PUMP TEST.
 REINSTALLED LINE TO THE NOZZLE.
 RAN DEF DOSING UNIT TEST, IT FAILED DUE INJECTION DELAY.
 REMOVED LINES ON DEF INJECTOR AND DISCONNECTED HARNESS.
 REMOVED NOZZLE, GASKET AND REPLACED WITH A EW ONE.
 CLEANED THREADS AND INSTALLED NEW NOZZLE BOLTS.
 RAN UNIT AND TRIED TO DO SERVICE BURN.
 IT WAS RUNNING FOR 15 MIN AND POPULATED ANOTHER CODE ECU 4766.17.
 REMOVED SHIELDS TO GET ACCESS TO THE ALL TEMPERATURE SENSORS.
 DISCONNECTED TEMPERATURE MODULE AND REPLACED WITH A NEW ONE.
 REASSEMBLED EVERYTHING BACK.
 RAN UNIT AND INITIATED PARK BURN, FAILED.
 CHECKED CODES, ECU 4766.18 WAS ACTIVE NOW.
 CHECKED SENSOR AND WIRES NO VISUAL DAMAGE.
 CLEANED SENSORS AND REINSTALLED EVERYTHING BACK.



CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 38 South, Box 1057
Kelvington, SK S0A 1W0
Phone: (306) 327-4355
Fax: (306) 327-4314
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

		Invoice Number:	3425549
		Invoice Date:	7/30/2025
		Location:	09
		Work Order Number:	483962
		Payment Type:	
Bus Phone: Prv Phone:		Page: 4 of 18	
Make/Model:	Meter:	Serial Number:	Eq ID:
JOHN DEERE 9520RX PTO	3519	1RW9520RVJP805521	W0805521
		Fleet No:	

SERVICES PERFORMED AND REMOVED EVERYTHING FROM.
 CHECKED FOR LOOSE CLAMPS OR ANY DAMAGE IN PIPES, EVERYTHING LOOKS GOOD.
 TIGHTENED ALL CLAMPS AROUND.
 DRAINED TANK AND FUEL WAS CLEAN, 200 L OF FRESH FUEL WAS ADDED INTO THE SYSTEM.
 REMOVED AND REPLACED EXHAUST GASKET WITH A NEW ONE.
 RAN UNIT FOR 5 MIN AND HAD ACTIVE ECU CODES 189.31, 159.31, 3719.00, 3719.14, 4766.18.
 CHECKED MODULE CONNECTOR FOR ANY BROKEN WIRES OR PUSHED PINS.
 CHECKED EGR VALVE FOR OPEN CYCLE AND PLUGS FOR ANY DAMAGE, CLEANED CONNECTOR.
 DISCONNECTED FUEL INJECTOR LINE AND REMOVED INJECTOR.
 CHECKED FOR ANY DAMAGE ON THE INJECTOR.
 REASSEMBLED EVERYTHING IN BACK ORDER.
 CHECKED FUEL SUPPLY LINE FOR ANY BLOCKAGE.
 CHECKED FUEL PUMP FOR WORKING CONDITIONS.
 CHECKED ALL THE CONNECTORS AROUND FUEL INJECTOR PUMP, NO VISUAL DAMAGE.
 REMOVED DOS AND DPF SENSOR AND CHECKED READING WITH AMBIENT TEMPERATURE, ALL WERE IN SPEC.
 ERASED ECU EMISSIONS CODE AND STARTED SERVICE REGENERATION.
 AFTER SERVICE REGEN IT HAD CODE ECU 3719.14 AND DERATED CODES.
 ATTEMPTED TO DO PARC REGENERATION - FAILED.
 DROVE UNIT TO THE GAS STATION AND ADD FUEL.
 STARTED SERVICE REGENERATION AND RECORDING ALL THE PARAMETERS DURING REGENERATION.
 CONTACTED DTAC FOR FURTHER STEPS.
 NOTIFIED CUSTOMER ABOUT THAT HE NEED NEW FILTERS.
 REMOVED SHIELDS AND DOS WITH DPF FILTER.
 ATTEMPTED TO INSTALL NEW FILTERS- FAILED DUE TO WRONG FILTERS.
 NOTIFIED CUSTOMER ABOUT ISSUE.
 REMOVED OLD FILTERS AND RETURNED TO THE CUSTOMER WITH THE REST OF THE PARTS.
 INSTALLED DOC FILTER THAT CUSTOMER PROVIDED.
 INSTALLED MOUNTS FOR THE DPF FILTER IN RIGHT PLACE.
 INSTALLED DPF FILTER BACK ON UNIT.
 INSTALLED DEF INJECTION PIPE.
 INSTALLED SHIELDS THAT GOES AROUND EMISSION FILTERS
 INSTALLED DEG INJECTORS COOLING LINES AND PUMP SUPPLY LINE.
 INSTALLED ALL THE SENSORS BACK IN PLACE AND APPLIED NEVER SIZED TO THEM.
 INSTALLED THE REST SHIELDS AROUND SCR CANISTER.
 INSTALLED MISSING SEALS AND GROMMETS THAT WERE MISSING.
 PRIMED DEF SYSTEM AND CLEARED CODES.
 ADD DEF INTO TANK.
 RAN UNIT AND CHECKED FUNCTION.
 DID SERVICE REGENERATION WITH PARK BURN AND IT PASSED.
 REINSTALLED THE REST OF SHIELD AROUND EMISSION STACK OF FILTERS.
 VERIFY REPAIRS.

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 38 South, Box 1057
Kelvington, SK S0A 1W0
Phone: (306) 327-4355
Fax: (306) 327-4314
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number:	3425549
Invoice Date:	7/30/2025
Location:	09
Work Order Number:	483962
Payment Type:	
Page:	5 of 18

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9520RX PTO	3519	1RW9520RVJP805521	W0805521	

JGEN03-

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ114640	FILTER KIT	1.00	233.07	233.07	\$233.07	N
DZ124403	DEF Inline Supply Filter	1.00	154.04	154.04	\$154.04	N
R529640	GASKET	2.00	65.18	65.18	\$130.36	N
R537624	BOLT	3.00	3.39	3.39	\$10.17	N
R537860	GASKET	2.00	81.31	81.31	\$162.62	N
R545605	Sealing Ring	1.00	20.80	20.80	\$20.80	N
R552352	Grommet	2.00	14.71	14.71	\$29.42	N
R554432	Grommet	1.00	49.98	49.98	\$49.98	N
RE555626	DEF Dosing Injector	1.00	1,097.36	1,097.36	\$1,097.36	N
RE555626-CR	CORE for:DEF Dosing Injector	-1.00	146.00	146.00	(\$146.00)	N
RE572158	DEF Line	1.00	534.13	534.13	\$534.13	N
RE572248	Gasket	1.00	25.74	25.74	\$25.74	N
RE575421	Temperature Sensor	1.00	905.70	905.70	\$905.70	N
SWDEF025	DIESEL EXHAUST FLUID	2.00	22.99	22.99	\$45.98	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	2.00	1.25	1.25	\$2.50	N
FRT	FREIGHT	1.00	35.00	35.00	\$35.00	N

Labor: \$9,600.00	Parts: \$3,253.37	OL&M: \$0.00	Misc: \$37.50	Sub-Total: \$12,890.87
--------------------------	--------------------------	-------------------------	----------------------	-------------------------------

JGEN04-

COMPLAINT:
04 REMOVE BLADE BRACKET AND HOSES

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 38 South, Box 1057
 Kelvington, SK S0A 1W0
 Phone: (306) 327-4355
 Fax: (306) 327-4314
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Bus Phone: Prv Phone:		Invoice Number: 3425549	
		Invoice Date: 7/30/2025	
		Location: 09	
		Work Order Number: 483962	
		Payment Type:	
Page: 6 of 18			

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9520RX PTO	3519	1RW9520RVJP805521	W0805521	

JGEN04-

UNHOOKED UNIT FROM VERTICAL TILLAGE
 WASHED BACK END AS HOSES WERE FROZEN IN FRAME
 REMOVED ELBOWS FROM HOSES TO PULL THROUGH FRAME
 REMOVED HOSES
 REMOVED CROSS MEMBERS WITH LITTLE FORKLIFT
 REMOVED MID MOUNTS
 REMOVED T MOUNT
 REMOVED SIDE FRAMES WITH CRANE
 REMOVED TOW CABLE AS HAD NO FACTORY MOUNT. WAS MOUNTED ON BLADE SIDE FRAME

GROUND AND REMOVED PAINT OFF SIDE FRAMES
 INSTALLED CABLE WITH NEW PIN
 WENT TO INSTALL MOUNT PLATE AND 1 HOLE DIDNT LINE UP ON CUSTOMER SUPPLIED PLATE
 REMOVED PLATE DRILLED OUT WHOLE
 REINSTALLED PLATE AND TORQUED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
11M7056	M8x50 COTTER PIN	1.00	1.98	1.98	\$1.98	N
14M7277	M20-2.5 NUT	4.00	5.38	5.38	\$21.52	N
14M7589	M16-2.0 FLG STOVER LOCK NUT	1.00	5.69	5.69	\$5.69	N
19M7824	M16x60 FLG 10.9 BOLT	1.00	10.14	10.14	\$10.14	N
19M8224	M20x60 HH 10.9 BOLT	4.00	11.64	11.64	\$46.56	N
24M7242	Washer M21.4x42	8.00	4.17	4.17	\$33.36	N
TY25624	Ag Green Spray Paint	1.00	23.03	23.03	\$23.03	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF25	ENVIRO FEE	1.00	0.25	0.25	\$0.25	N
Labor: \$1,600.00		Parts: \$142.28	OL&M: \$0.00	Misc: \$0.25	Sub-Total: \$1,742.53	

J01020011 JD 9520RX**COMPLAINT:**

05 VALVE CLEARANCE, ENGINE - ADJUST W/HEAD BOLT UPDATE.

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 38 South, Box 1057
Kelvington, SK S0A 1W0
Phone: (306) 327-4355
Fax: (306) 327-4314
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639

**JOHN DEERE****SERVICE INVOICE**

Deliver To:		Invoice Number: 3425549	
		Invoice Date: 7/30/2025	
		Location: 09	
		Work Order Number: 483962	
		Payment Type:	
		Page: 7 of 18	
Bus Phone:	Bus Phone:		
Prv Phone:	Prv Phone:		
Make/Model:	Meter:	Serial Number:	Eq ID: Fleet No:
JOHN DEERE 9520RX PTO	3519	1RW9520RVJP805521	W0805521

J01020011 JD 9520RX

MOVED HOOD INTO SERVICE POSITION AND DISCONNECTED HOOD HARNESS.
REMOVED INTAKE PIPE BETWEEN TURBOCHARGERS.
REMOVED FUEL INJECTION NOZZLE.
REMOVED EXHAUST PIPE BETWEEN TURBOCHARGERS.
REMOVED SIDE SHIELD.
REMOVED HARNESS AND THE REST OF HARDWARE TO GET ACCESS TO THE VALVE COVER.
REMOVED VALVE COVER.
ADJUSTED VALVE LASH TO THE SPEC.
REASSEMBLED IN REVERSE ORDER.
INSTALLED NEW VALVE COVER GASKETS, INTAKE AND EXHAUST GASKETS AND SEAL TO THE TURBOCHARGER LINE.
RAN UNIT.
VERIFY REPAIRS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ114164	O-Ring	1.00	32.93	32.93	\$32.93	N
DZ128752	GASKET	1.00	30.94	30.94	\$30.94	N
R528620	Turbo Flange Ring	2.00	121.21	121.21	\$242.42	N
R531581	Front Rocker Cover Gasket	1.00	91.85	91.85	\$91.85	N
R531582	Rear Rocker Cover Gasket	1.00	92.68	92.68	\$92.68	N
RE541291	Turbo Gasket -hot	1.00	33.59	33.59	\$33.59	N
Labor: \$2,200.00		Parts: \$524.41	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,724.41	

JSOFTWARE JD 9R 540

COMPLAINT:
06 UPDATE ALL CONTROLLER SOFTWARE

CORRECTION:
UPDATED SOFTWARE ON 2 CONTROLLERS.
REMOVED MTG MODULE AND REPLACED WITH A NEW ONE.
NEW MTG S/N PCMA4RB146891

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
BPF12617	R MODEM UPDATE KIT	1.00	450.00	450.00	\$450.00	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 38 South, Box 1057
Kelvington, SK S0A 1W0
Phone: (306) 327-4355
Fax: (306) 327-4314
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Deliver To:

Invoice Number:	3425549
Invoice Date:	7/30/2025
Location:	09
Work Order Number:	483962
Payment Type:	it
Page:	8 of 18

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9520RX PTO	3519	1RW9520RVJP805521	W0805521	

JSOFTWARE JD 9R 540

PFA12696	Antenna	1.00	49.93	49.93	\$49.93	N
----------	---------	------	-------	-------	---------	---

Labor: \$100.00	Parts: \$499.93	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$599.93
-----------------	-----------------	--------------	--------------	---------------------

JELECDIAG1 JD ALL

COMPLAINT:

07 PTO TEMP SENSOR

CORRECTION:

REMOVED SHIELDS AROUND PTO.
REMOVED AND REPLACED SENSOR WITH A NEW ONE.
CHECKED FUNCTION WITH PTO ENGAGED, NO CODES.
REINSTALLED SHIELDS BACK.
VERIFY REPAIRS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ123024	SENSOR	1.00	77.57	77.57	\$77.57	N

Labor: \$60.00	Parts: \$77.57	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$137.57
----------------	----------------	--------------	--------------	---------------------

JGEN08-

COMPLAINT:

08 OCV FILTER HOSE

CORRECTION:

INSTALLED MISSING DRAIN HOSE WITH CLAMP
VERIFY REPAIRS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
R541994	Hose	1.00	204.97	204.97	\$204.97	N
TY22467	CLAMP	1.00	2.54	2.54	\$2.54	N

Labor: \$50.00	Parts: \$207.51	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$257.51
----------------	-----------------	--------------	--------------	---------------------

PATTISON AGRICULTURE LIMITED

Hwy 38 South, Box 1057
Kelvington, SK S0A 1W0
Phone: (306) 327-4355
Fax: (306) 327-4314
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351
Maple Creek, SK (306) 662-2233
Kindersley, SK (306) 463-2683
Kyle, SK (306) 375-2302
Leader, SK (306) 628-3889
Unity, SK (306) 228-2696
North Battleford, SK (306) 445-4468
Humboldt, SK (306) 682-2572
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639

Yorkton, SK (306) 783-9459
Balcarres, SK (306) 334-2492
Moosomin, SK (306) 435-3301
Preeceville, SK (306) 547-2007
Russell, MB (204) 773-2149
Wynyard, SK (306) 554-2536
Kamsack, SK (306) 542-2814
Swan River, MB (204) 734-3466

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number: **3425549**
Invoice Date: 7/30/2025
Location: 09
Work Order Number: 483962
Payment Type:
Page: 9 of 18

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9520RX PTO	3519	1RW9520RVJP805521	W0805521	

JENGAIRFIL JD 9520RX

COMPLAINT:

09 REPLACE PRIMARY AND SECONDARY ENGINE AIR FILTERS

CORRECTION:

UNFASTEN AIR FILTER HOUSING CLIPS.

CHECKED COVER SEAL AND HOUSING FOR DAMAGE.

REMOVED AND REPLACE BOTH ENGINE AIR FILTERS.

ASSEMBLED IN THE REVERSE ORDER.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE594852	PRIMARY ENGINE AIR FILTER	2.00	367.88	367.88	\$735.76	N
RE594853	SECONDARY ENGINE AIR FILTER	2.00	113.67	113.67	\$227.34	N
Labor: \$50.00		Parts: \$963.10	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,013.10	

J01001200 JD 9520RX

COMPLAINT:

10 ENGINE AUXILIARY DRIVE BELT, REPLACE

CORRECTION:

REMOVED AND REPLACED WITH A NEW ONE AUXILIARY BELT.
RAN UNIT AND CHECKED FUNCTION.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
R536677	V-BELT	1.00	111.97	111.97	\$111.97	N
Labor: \$150.00		Parts: \$111.97	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$261.97	

JGEN11-

COMPLAINT:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 38 South, Box 1057
Kelvington, SK S0A 1W0
Phone: (306) 327-4355
Fax: (306) 327-4314
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number: **3425549**
Invoice Date: 7/30/2025
Location: 09
Work Order Number: 483962
Payment Type:
Page: 10 of 18

Make/Model: Meter: Serial Number: Eq ID: Fleet No:

JOHN DEERE 9520RX PTO 3519 1RW9520RVJP805521 W0805521

JGEN11-

11 REPAIR FAN DRIVE

CORRECTION:

REMOVED OUTSIDE SHEAVE OF FAN DRIVE.

REMOVED FAN.

REMOVED FAN BELT AND REPLACED WITH A NEW ONE.

DISCONNECTED FAN SPEED SENSOR.

REMOVED FAN DRIVEN SHEAVES.

DISASSEMBLED AND CHECKED INSIDE, OUTSIDE SHEAVE WAS WORN AND INSIDE SHEAVE SHAFT HAD GROVES.

INSTALLED NEW DRIVEN SHEAVES.

REINSTALLED EVERYTHING IN REVERSE ORDER.

TORQUED ALL HARDWARE TO THE SPEC.

RAN UNIT AND CHECKED FUNCTION.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
R300399	VarCooling Fan Belt 13.5L	1.00	226.14	226.14	\$226.14	N
RE590285	13.5L FAN DRIVEN ASSEMBLY	1.00	2,420.25	2,420.25	\$2,420.25	N
Labor: \$422.66		Parts: \$2,646.39	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$3,069.05	

J01001092 JD 9520RX**COMPLAINT:**

12 BATTERY CABLE

CORRECTION:

OPENED SIDE DOOR AND DISCONNECTED BATTERY CABLE.

REMOVED POSITIVE CABLE FROM THE TRACTOR AND REPLACED WITH A NEW ONE.

TIGHTENED ALL HARDWARE.

RAN UNIT AND CHECKED FUNCTION.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE575300	Battery Cable	1.00	992.95	992.95	\$992.95	N
Labor: \$250.00		Parts: \$992.95	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,242.95	

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 38 South, Box 1057
Kelvington, SK S0A 1W0
Phone: (306) 327-4355
Fax: (306) 327-4314
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3425549
		Invoice Date:	7/30/2025
		Location:	09
		Work Order Number:	483962
		Payment Type:	
		Page:	11 of 18

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9520RX PTO	3519	1RW9520RVJP805521	W0805521	

J01060011 JD 9520RX

COMPLAINT:

13 REPLACE STEERING CYLINDER PINS AND BUSHINGS. (BOTH SIDES)

CORRECTION:

REMOVED STEERING CYLINDER HYDRAULIC LINES.
REMOVED STEERING PINS AND CYLINDER.
REMOVED BUSHINGS FROM CYLINDER.
INSTALLED NEW BUSHINGS.
INSTALLED NEW PINS WITH NEW O-RINGS AND SEALS.
INSTALLED NEW GREASE ZERKS.
REASSEMBLED ALL COMPONENTS AND GREASED PINS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
JD7760	Zerk-2NPT 65deg	4.00	1.95	1.95	\$7.80	N
R247733	BUSHING	4.00	107.67	107.67	\$430.68	N
R247735	Seal	8.00	21.50	21.41	\$171.28	N
R568624	PIN	2.00	307.26	307.26	\$614.52	N
R568626	PIN	2.00	289.69	289.69	\$579.38	N
R93633	O-RING	8.00	8.76	8.76	\$70.08	N
Labor: \$1,300.00		Parts: \$1,873.74	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$3,173.74	

JGEN14-

COMPLAINT:

14 SCV #5 BARRELS

CORRECTION:

REMOVED AND REPLACED SCV'S PLASTIC COVERS.
CLEANED DIRT AROUND.
REMOVED INSIDE SEALS AND REPLACED WITH A NEW ONES.
REMOVED AND REPLACED SCV'S COUPLERS WITH ANEW ONES.
REINSTALLED DUST COVERS AND CHECKED FUNCTION.
VERIFY REPAIRS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 38 South, Box 1057
Kelvington, SK S0A 1W0
Phone: (306) 327-4355
Fax: (306) 327-4314
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3425549
		Invoice Date:	7/30/2025
		Location:	09
		Work Order Number:	483962
		Payment Type:	
		Page:	12 of 18

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9520RX PTO	3519	1RW9520RVJP805521	W0805521	

JGEN14-

RE186600	1/2" SCV Socket Seal Kit	1.00	42.65	42.65	\$42.65	N
RE577560	-8 1/2 FEM SCV BREAKAWAY CPLR	2.00	255.58	255.58	\$511.16	N

Labor: \$150.00	Parts: \$553.81	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$703.81
-----------------	-----------------	--------------	--------------	---------------------

JENGOILCHN JD 9520RX

COMPLAINT:

15 REPLACE ENGINE OIL AND FILTER

CORRECTION:

DRAINED ENGINE OIL AND REMOVE FILTER.
CLEANED AREA.
INSTALLED NEW OIL AND FILTER.
RUN UNIT AND LEAK CHECK.
MARKED ENGINE HOURS ON NEW FILTER.
ADJUSTED OIL LEVEL AS REQUIRED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE572785	ENGINE OIL FILTER	1.00	156.67	156.67	\$156.67	N
TY26675	PLUS-50 II 15W-40 CK4/SN JUG 9.46L	1.00	89.73	89.73	\$89.73	N
TY26679	PLUS-50 II 15W-40 CK4/SN 18.9L PAIL	2.00	170.86	170.86	\$341.72	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.25	1.25	\$1.25	N
EF150	ENVIRO FEE	1.00	1.50	1.50	\$1.50	N
EF300	ENVIRO FEE	2.00	3.00	3.00	\$6.00	N

Labor: \$100.00	Parts: \$588.12	OL&M: \$0.00	Misc: \$8.75	Sub-Total: \$696.87
-----------------	-----------------	--------------	--------------	---------------------

J10030100 JD 9520RX

COMPLAINT:

16 REPLACE ENGINE FUEL FILTERS

PATTISON AGRICULTURE LIMITED

Hwy 38 South, Box 1057
 Kelvington, SK S0A 1W0
 Phone: (306) 327-4355
 Fax: (306) 327-4314
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
 Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
 Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
 Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
 Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
 Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
 North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
 Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639



JOHN DEERE

SERVICE INVOICE

Deliver To:

Invoice Number: 3425549 Invoice Date: 7/30/2025 Location: 09 Work Order Number: 483962 Payment Type: Page: 13 of 18	
Bus Phone: Prv Phone:	Bus Phone: Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9520RX PTO	3519	1RW9520RVJP805521	W0805521	

J10030100 JD 9520RX**CORRECTION:**

REPLACED PRIMARY AND SECONDARY FUEL FILTERS.
 REMOVED AND CLEANED FUEL STRAINER/WATER SEPARATOR.
 BLED FUEL SYSTEM.
 FUNCTION AND LEAK CHECKED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ112918	FINAL FUEL FILTER	1.00	244.07	244.07	\$244.07	N
DZ130550	FILTER ELE	1.00	240.23	240.23	\$240.23	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	2.00	1.25	1.25	\$2.50	N

Labor: \$80.00 Parts: \$484.30 OL&M: \$0.00 Misc: \$2.50 Sub-Total: \$566.80

JHYDFILTER JD 9520RX**COMPLAINT:**

17 REPLACE HYDRAULIC OIL FILTERS (ALL FILTERS)

CORRECTION:

REMOVED AND REPLACED 4 HYDRAULIC FILTERS WITH A NEW ONES.
 REMOVED AND REPLACED FILTER OIL FILTERS SEAL RINGS WITH A NEW ONES.
 TOP UP WITH HYDRAULIC OIL.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AR69444	HY-GARD J20C 18.9L PAIL	1.00	158.46	158.46	\$158.46	N
R564922	Oil Filter Seal Ring	4.00	16.30	16.30	\$65.20	N
R567277	RING	1.00	18.41	18.41	\$18.41	N
RE577250	HYDRAULIC OIL FILTER	1.00	161.70	161.70	\$161.70	N
RE577612	Hydraulic Oil Filter	4.00	206.11	206.11	\$824.44	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	5.00	1.25	1.25	\$6.25	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 38 South, Box 1057
 Kelvington, SK S0A 1W0
 Phone: (306) 327-4355
 Fax: (306) 327-4314
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3425549 Invoice Date: 7/30/2025 Location: 09 Work Order Number: 483962 Payment Type: Page: 14 of 18
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9520RX PTO	3519	1RW9520RVJP805521	W0805521	

JHYDFILTER JD 9520RX

EF300	ENVIRO FEE	1.00	3.00	3.00	\$3.00	N
-------	------------	------	------	------	--------	---

Labor: \$100.00	Parts: \$1,228.21	OL&M: \$0.00	Misc: \$9.25	Sub-Total: \$1,337.46
------------------------	--------------------------	-------------------------	---------------------	------------------------------

JCABFILTER JD 9520RX**COMPLAINT:**

18 REPLACE CAB AIR FILTERS

CORRECTION:

REMOVED AND REPLACE CAB RECIRCULATION FILTER WITH A NEW ONE.

REMOVED AND REPLACE FRESH AIR FILTER WITH A NEW ONE.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE291412	CabRecircFilter	1.00	139.48	139.48	\$139.48	N
TA32591	Cab FreshAir Filter	1.00	125.95	125.95	\$125.95	N
Labor: \$50.00		Parts: \$265.43	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$315.43	

J0112020 JD 9520RX**COMPLAINT:**

19 ADJUST TRACK ALIGNMENT. ALL FOUR.

CORRECTION:

ADJUSTED ALL FOUR TRACK ALIGNMENTS AS PER SERVICE ADVISOR.

TWO FRONT TRACKS MAX ON ADJUSTERS AND WASN'T ABLE TO CENTER TRUCKS.

ADJUSTING BOLTS TORQUED TO 221 FT-LBS.

LOCKING PLATES TORQUED TO 95 FT-LBS.

VERIFY REPAIRS.

Labor: \$800.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$800.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

J01001701 JD 9520RX**COMPLAINT:**

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 38 South, Box 1057
Kelvington, SK S0A 1W0
Phone: (306) 327-4355
Fax: (306) 327-4314
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE**

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone: Bus Phone: Prv Phone:		Invoice Number: 3425549 Invoice Date: 7/30/2025 Location: 09 Work Order Number: 483962 Payment Type: Page: 15 of 18
---	--	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9520RX PTO	3519	1RW9520RVJP805521	W0805521	

J01001701 JD 9520RX

20 REPLACE OIL IN ALL TRACK MID ROLLERS AND IDLERS. (32 TOTAL)

CORRECTION:

REPLACED OIL IN ALL TRACK IDLERS AND ROLLERS. (32 TOTAL)
REMOVED COVERS TO DRAIN OILS.
CLEANED UP SEALING SURFACES OF COVER AND HUB.
REPLACED O-RINGS IF REQUIRED.
REINSTALLED COVERS AND TORQUES HARDWARE.
REFILLED WITH OIL.
DROVE TRACTORS AND RECHECKED OIL LEVELS.
CHECKED FOR LEAKS.
DISPOSED OF USED OIL.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AR69444	HY-GARD J20C 18.9L PAIL	1.00	158.46	158.46	\$158.46	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF300	ENVIRO FEE	1.00	3.00	3.00	\$3.00	N
Labor: \$1,900.00		Parts: \$158.46	OL&M: \$0.00	Misc: \$3.00	Sub-Total: \$2,061.46	

J01130010 JD 9520RX

COMPLAINT:

21 REPLACE GUDGEON SPINDLE BUSHINGS/BEARINGS.

CORRECTION:

PATTISON AGRICULTURE LIMITED

Hwy 38 South, Box 1057
Kelvington, SK S0A 1W0
Phone: (306) 327-4355
Fax: (306) 327-4314
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

		Invoice Number:	3425549
		Invoice Date:	7/30/2025
		Location:	09
		Work Order Number:	483962
		Payment Type:	t
		Page:	16 of 18

Bus Phone:

Bus Phone:

Prv Phone:

Prv Phone:

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE 9520RX PTO

3519

1RW9520RVJP805521

W0805521

J01130010 JD 9520R>

DISCONNECTED HYDRAULIC HOSES AND CAPPED THEM.
DISCONNECTED ALL ELECTRICAL CONNECTIONS AT THE HINGE AREA.
REMOVED FUEL LINES AND CAPPED THEM
REMOVED TRANSMISSION OUTPUT SHAFT.
REMOVED PTO SHAFTS AND SHIELDS.
INSTALLED STANDS ON FRONT AND REAR OF TRACTOR.
REMOVED PLATE ON BACK AXLE AND REMOVED DRIVE SHAFT BETWEEN SPINDLE DRIVE SHAFT AND REAR AXLE.
REMOVED YOKES ON BOTH SIDES OF SPINDLE SHAFT AND THEN REMOVED SHAFT.
ATTEMPTED TO REMOVE SPINDLE RETAINING NUT BY HANDS, NO SUCCESS.
REMOVED SPINDLE RETAINER CAP AND THRUST WASHERS BY TORCHING IT.
SPLIT TRACTOR.
WELDED SUPPORTS FOR REMOVING SPINDLE OF THE UNIT.
REMOVED SPINDLE BOLTS AND USED JACKS TO REMOVE SPINDLE.
DURING DISASSEMBLING NOTICED THAT GUDGEON WAS BROKEN AT TWIST STOPPER.
DISCONNECTED ALL HYDRAULIC HOSES BETWEEN GUDGEON AND TRANSMISSION.
REMOVED PTO OF THE UNIT.
REMOVED STEP.
CAPPED STEERING CYLINDER LINES.
REMOVED STEERING PINS AND MOVED CYLINDERS OF THE WAY.
SECURE GUDGEON WITH STRAPS AND CRANE.
REMOVED TOP GUDGEON PIN WITH HYDRAULIC JACK BY PUSHING IT OUT.
ATTEMPTED TO REMOVE BOTTOM PIN BY APPLYING PENETRATING OIL AND LEFT IT SOP FOR 30 MIN, NO SUCCESS.
PREHEAT FRAME AROUND PIN AND TRIED TO GET IT LOOSE, NO SUCCESS.
TORCHED SPACERS AND THEN TORCHED BOTTOM PIN.
REMOVED GUDGEON OF THE UNIT.
INSTALLED NEW GUDGEON WITH NEW PINS.
INSTALLED NEW SPINDLE AND TORQUED BOLTS TO THE SPEC.
INSTALLED NEW SPINDLE SEALS AND SPINDLE REAR BEARING.
ROLLED TRACTOR BACK TOGETHER.
INSTALLED DRIVE SHAFT WITH NEW SEALS AND DUST CAPS.
TORQUED DRIVE SHAFT BOLTS BETWEEN SPINDLE SHAFT AND BACK AXLE TO THE SPEC.
INSTALLED GREASE ZERK TO THE SPINDLE SHAFT.
INSTALLED FRONT SPINDLE NUT WITH SEAL AND FRONT SPINDLE BEARING.
TORQUED SPINDLE NUT TO THE SPEC AND STEER TRACTOR FROM SIDE TO SIDE.
RE-TORQUED NUT TO THE SPEC.
INSTALLED GREASE ZERKS INTO GUDGEON AND GREASED IT.
REASSEMBLED ALL HYDRAULIC LINES AND HARNESS BACK IN PLACE.
CHECKED GUDGEON PLAY ON PINS AND SHIMMED TO THE SPEC.
REINSTALLED TRANSMISSION OUTPUT SHAFT.
REINSTALLED PTO BACK ON UNIT AND ADJUSTED DRIVE SHAFT.
REINSTALLED ALL PTO HYDRAULIC LINES AND HARNESS BACK IN PLACE.

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 38 South, Box 1057
Kelvington, SK S0A 1W0
Phone: (306) 327-4355
Fax: (306) 327-4314
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355
Shaunavon, SK (306) 297-2639

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number: **3425549**
Invoice Date: 7/30/2025
Location: 09
Work Order Number: 483962
Payment Type: .
Page: 17 of 18

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9520RX PTO	3519	1RW9520RVJP805521	W0805521	

REASSEMBLED THE REST OF THE PARTS IN REVERSE ORDER.
TORQUED ALL HARDWARE TO THE SPEC.
RAN UNIT AND CHECKED FUNCTION.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
15H558	-2NPT HEXSOC PLUG 1/8	2.00	3.42	3.42	\$6.84	N
19M9136	M20x110 HH 10.9 BOLT	10.00	19.53	19.53	\$195.30	N
BRE10559	Gudgeon Kit	1.00	14,490.46	14,490.46	\$14,490.46	N
JD7759	Zerk-2NPT Str8	2.00	1.65	1.65	\$3.30	N
JD7760	Zerk-2NPT 65deg	1.00	1.90	1.90	\$1.90	N
R248388	Spindle	1.00	9,564.24	9,564.24	\$9,564.24	N
R551044	Thrust Washer	1.00	417.04	417.04	\$417.04	N
R562284	CAP	1.00	614.81	614.81	\$614.81	N
R86105	V-RING SEAL	1.00	99.48	99.48	\$99.48	N
R93633	O-RING	1.00	8.13	8.13	\$8.13	N
R98309	CAP SCREW	2.00	20.81	20.81	\$41.62	N
RE586670	Ball Bearing	1.00	106.98	106.98	\$106.98	N
RE587092	SEAL	2.00	47.29	47.29	\$94.58	N
RE587658	BALL BEARI	1.00	137.33	137.33	\$137.33	N
TY6341	SD POLYUREA GREASE	1.00	10.76	10.76	\$10.76	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 38 South, Box 1057
Kelvington, SK S0A 1W0
Phone: (306) 327-4355
Fax: (306) 327-4314
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Deliver To:

Invoice Number:	3425549
Invoice Date:	7/30/2025
Location:	09
Work Order Number:	483962
Payment Type:	
Page:	18 of 18

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9520RX PTO	3519	1RW9520RVJP805521	W0805521	

J01130010 JD 9520RX

YZ502232	O-Ring	3.00	17.46	17.46	\$52.38	N
----------	--------	------	-------	-------	---------	---

Labor: \$11,200.00	Parts: \$25,845.15	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$37,045.15
---------------------------	---------------------------	-------------------------	---------------------	-------------------------------

INVOICE CONTAINS \$0.72 DISCOUNT

Miscellaneous Charges:
SERVICE ACCESSORIES

\$150.00

Customer PO No:
Tax Exempt No:
Advisor: Vivian Bollman

Labor:	\$33,582.66
Parts:	\$40,427.84
OL&M:	\$0.00
Misc:	\$211.25
Grand Total:	\$74,221.75

*** DOCUMENT COPY ***

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE -- MIN \$35 ON EMERGENCY/UNIT DOWN ORDERS -- 25% RESTOCKING FOR RET

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: Date: