

Experian AutoCheck Report

Report run: 10/12/2026 18:11:35 EDT

2021 Ford E-150 Lariat / XL / XLT

Crew Cab 4D (2.7L V6 DI Gasoline)


VIN:	1FTEW1CP1MKE40435
Class:	Pickup - Fullsize
Country of Assembly:	United States
Vehicle Age:	5 year(s)
Estimated In Service:	10/14/2021
Last Reported Odometer:	11 (02/25/2022)

One Owner

AutoCheck

Vehicle Usage

Lease



Vehicle History at a Glance

State Title Brand

CLEAN

Auction Brand / Issues

NO ISSUE

Accident / Damage

No Accidents or Damage Reported

Open Recall Check

2 OPEN RECALL(S)

Insurance Loss / Transfer

NO ISSUE

Odometer Check

Last reported odometer: 11 (02/25/2022)

Certified Pre-Owned

NO CPO INFO AVAILABLE

Service / Repair

1 Service Record(s) Reported

Additional History

Lien Reported

1 Year AutoCheck

BUYBACK


Protection

This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

Learn More

Your Vehicle Checks Out There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.



Airbag Deployed



Structural Damage



Overturned



No Damage



Open Recall Check



Information Reported: AutoCheck found 2 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date - 09/30/2024

Recall Type - Safety

NHTSA / OEM Recall No. - 24V635 / 24S55

Campaign Description - Safety Recall: ENGINE VALVE INSPECTION TEST
Status: Remedy Not Available

Recall Date - 07/08/2025

Recall Type - Safety

NHTSA / OEM Recall No. - 25V455 / 25S75

Campaign Description - Safety Recall: LOW PRESSURE FUEL PUMP - SOFTWARE UPDATE
Status: Remedy Not Available

[More information](#) including remedy or risk factors. Locate your nearest authorized [Ford Dealer](#) to schedule repair.



Recommended Maintenance

OEM Recommended Maintenance Schedule

Based on your vehicle's last reported mileage, these are the most recent and upcoming recommended maintenance intervals from your vehicle's manufacturer.

OEM Recommended Services

Please contact your local dealer or visit the OEM's website for details.



Odometer Check



Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported



Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2021 Ford F-150 Lariat / XL / XLT (1FTEW1CP1MKE40435) Report Run Date: 10/12/2026 18:11:35 EDT

2021

Vehicle Prep and Other Pre-Titling Events

Location: TX

Preparation Date: 10/2021

Event Date	Location	Odometer	Data Source	Details
10/14/2021	TX	11	Service Record	Vehicle Inspected Promotional Service Performed

2022

Owner 1

Location: TX

Owned From: 01/2022

Usage: Lease

Event Date	Location	Odometer	Data Source	Details
01/26/2022	BAYTOWN, TX		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
02/25/2022	BAYTOWN, TX	11	Motor Vehicle Dept.	Title(Title #:10525344607250001) (Leased Vehicle)(Lien Reported)
03/11/2024	BAYTOWN, TX		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
09/30/2024			Manufacturer	Manufacturer Recall NHTSA Recall 24V635 / Mfr. Recall 24S55 Safety Recall: ENGINE VALVE INSPECTION TEST LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Not Available
03/01/2025	BAYTOWN, TX		Motor Vehicle Dept.	Registration Event/Renewal
07/08/2025			Manufacturer	Manufacturer Recall NHTSA Recall 25V455 / Mfr. Recall 25S75 Safety Recall: LOW PRESSURE FUEL PUMP - SOFTWARE UPDATE LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Not Available
11/11/2025	BAYTOWN, TX		Motor Vehicle Dept.	Title(Title #:28695345969012445) (Lien Reported)
03/01/2026	BAYTOWN, TX		Motor Vehicle Dept.	Registration Event/Renewal

Unreported Event Dates

The following events have been reported to AutoCheck without a specified date.

Event Date	Location	Odometer	Data Source	Details
Unreported			Independent Source	Vehicle Manufactured and Shipped to Dealer

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (1FTEW1CP1MKE40435) qualifies for **AutoCheck Buyback Protection**. If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbpterms or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.