# Work Order History Report

| Asset | W/O No | Description | Finished | Done Reading | |
|---|---|---|---|---|---|
| **P0206** | | **Komatsu PC1250-8 excavator** | | | |
| | 53305 | - Replace batteries<br>- Starting problem<br>- Clean cab | 13/03/2025 | | Hours |
| | 49442 | Final disposal works | 20/10/2024 | | Hours |
| | 14840 | Machine Disposal Repairs: oil leaks<br>Reseal LH and RH control valve banks.<br>Re-seal lower control valve<br>Replace various O'rings on pipes and hoses (cooler hose, swivel valve fitting, pilot pressure control hose, pilot hose to front of control valve, hydraulic pump fittings).<br>Repair bent platform<br>Remove access ladder<br>Wash machine after repair | 5/09/2024 | 14471 | Hours |
| | 2789 | Demob and sorting out around work shop area | 20/05/2023 | | Hours |
| | 857 | Inspect bent ladder and remove. Fit safety chain and check rear ladder operation. | 18/05/2023 | 14383 | Hours |
| | 3955 | Removed counter weight | 16/05/2023 | | Hours |
| | 2321 | Carried out repairs to machine prepping for transport | 16/05/2023 | | Hours |
| | 753 | Remove counter weight bolts & demob | 1/05/2023 | 14382 | Hours |
| | 1041 | Prep demob | 28/04/2023 | | Hours |
| | 841 | Demob. Collect dipper arm stand from across creek. Remove arm and loop hoses. Remove catwalk beacon and handrails, intake and exhaust stack | 27/04/2023 | 14382 | Hours |
| | 927 | Check oil leak, repair grease line. | 22/04/2023 | | Hours |
| | 918 | Remove cracked steel pipe from pump room. Braze and refit. | 20/04/2023 | | Hours |
| | 715 | Lip up new lip shroud between pos 4 & 5 | 15/04/2023 | 14382 | Hours |
| | 700 | Tighten stick to bucket retainer | 10/04/2023 | 14382 | Hours |
| | 815 | Inspect oil leak. Remove and make new hose. Fit and inspect for leaks. | 3/04/2023 | 14382 | Hours |

| Asset | W/O No | Description | Finished | Done Reading | |
|---|---|---|---|---|---|
| | 667 | Carried out repairs to machine fitted new alternator then tested, all ok. | 1/04/2023 | 14350 | Hours |
| | 653 | Carried out repairs to machine wont start found alternator u/s parts on order | 30/03/2023 | 14343 | Hours |
| | 649 | Carried out repairs to machine, replaced air con belt and checked aircon gas, tested machine, all ok. | 29/03/2023 | 14343 | Hours |
| | 2343 | Pulled staircase off as operator left it down | 15/03/2023 | | Hours |
| | 900 | Horn fault | 14/03/2023 | 14333 | Hours |
| | 880 | 250hr service, check over machine and inspect all oil levels | 9/03/2023 | 14320 | Hours |
| | 997 | Teeth change out | 8/03/2023 | | Hours |
| | 995 | Weld up oil hard line that broke | 7/03/2023 | | Hours |
| | 1253 | Welded retainers back in as middle tooth dropped out | 24/02/2023 | | Hours |
| | 476 | Tilt bucket main pivot pin walked out damaged GPS cable bucket return to workshop. | 18/02/2023 | 1 | Hours |
| | 469 | Manual grease machine, give service truck run down on system for greasing. | 17/02/2023 | 1 | Hours |
| | 544 | Change orings at compressor fittings as they were leaking. evac and gas - test | 15/02/2023 | 1 | Hours |
| | 1224 | Diagnosed hydraulic leak in pump room. Replaced seal and filter. Carried out regassing air conditioner system as machine has ac line from compressor leaking. Parts have been ordered but cant get as road closed | 7/02/2023 | | Hours |
| | 2815 | B2 lip protectors and pins | 30/08/2022 | | Hours |
| | 2816 | B2 install lip problems and fix pins on bucket | 29/08/2022 | | Hours |
| | 2817 | Repairs to bucket | 26/08/2022 | | Hours |
| | 2975 | Repairs to lip | 24/08/2022 | | Hours |
| | 2976 | Replace heel blocks | 23/08/2022 | | Hours |
| | 2978 | Bucket repairs | 22/08/2022 | | Hours |
| | 2979 | Repair cracks and replace wear plates | 19/08/2022 | | Hours |
| | 2980 | Replace wear plates | 18/08/2022 | | Hours |