Work Order History Report

Asset	W/O No	Description	Finished	Done Reading
P0237		**Komatsu PC1250-8 excavator**		
	58348	Replace bucket tooth GET and keeper.	16/03/2026	Hours
	57067	INTRODUCTION TO SITE - USO	12/02/2026	Hours
	60806	Operator and Diesel Pressure Hot Wash x 8hrs to clean Excavator on site at USO	6/11/2025	Hours
	58078	October R & M Monthly WO USO: Inspect & grease Fluid check Top up coolant	24/10/2025	Hours
	57911	Excavator - 1000hr service 10967hrs	11/10/2025	Hours

Asset	W/O No	Description	Finished	Done Reading	
	57416	- Replace starter motor 01/09 10808hrs - Replace broken E stop on rear of machine 02/09, 10810hrs - Tighten up radiator hose 03/09 10835hrs - Fire suppression repair - replace bottle head and re-charge. 08/09 - LH boom cylinder return blown hose, remove and replace, replace o rings, fill hyd tank with 100L, run up and test 17/09 - Replace o rings on bucket cylinder, replace o rings around control valve 27/09 - Carry out prestart , check fluid and grease 30/09	30/09/2025		Hours
	55179	Excavator - 250hr service 10194 hrs	4/09/2025		Hours
	56974	Excavator - 250hr service 10680hrs - Repair coolant leak	22/08/2025		Hours
	56707	Grease stick to bucket and check fluids 12/08 Repair broken wire for auto greaser pressure switch	22/08/2025		Hours
	56031	- AC not working- remove plug and clean contact, test ok. 08.07 10470hrs - Repair oil leak on swing pump 10.07 10489hrs - AC not working, low on gas, repair leak and vac clean, charge with R134A 1.2kg 14.07.2025 - A/c overhaul, leaking A/C compressor from front seal, cracked split hi and low side hose off the compressor from fatiged hose, replace compressor, remove cooler pack guard, replace hi side hose and fit guard, replace low side hose, disassemble cab and replace TX valve, pressure test system, vac down and charge with R134A and test. 19.07 10526hrs - Change out RHS cylinder boom pin and bush, RHS pin squealing from failed injector, replaced pin and bush. - Grease system faulting, C/O V96 grease valve 23/07	20/07/2025		Hours
	55909	Excavator - 500hr service and defects from to do list 10483hrs - Install handrails	11/07/2025	10483	Hours
	55329	USO June R&M - Wash down digger	28/06/2025		Hours

Asset	W/O No	Description	Finished	Done Reading
		- Fix hyd leaks - Site paperwork - Replace LH boom bearing/ pin. Replace egr cooler lines - Replace boom arch hose - Repair grease leaks, fit new grease injectors - Prep for weekend work, digger down due to alternator locking up and burning belt, Replace alternator. - Change out faulty coolant level sensor - 250 hour service - Clean shed, organise parts, obtain engine oil sample, grease - Fabricate handrails for counterweight - Grease boom pins - Replace boom arch hoses - Wash down digger		
	55566	Carry out 12month fire suppression and fire extinguisher service on Komatsu PC1250 p1237 - Replace fire panel and hosing through out system	12/06/2025	Hours
	54678	Air con not working, check fuses & circuit breakers Gas ac Fit radio Shim up boom pivot pins, shim up stick to boom pin, fit UHF Top up coolant Repair hyd oil leak under cab R&R leaking boom hose Repair boom arch leaks	31/05/2025	Hours
	52477	Pre hire repairs as per HME inspection, w/o 52332 Install fire suppression system.	27/03/2025	Hours

Asset	W/O No	Description	Finished	Done Reading	
		Straighten belly guards Repair cooler pack guard Clean cab Check, tag and bag fire extinguisher Fit first aid kit Check and fill greaser Check and repair greaser lines, leak on boom Fit safety stickers as required Remove Maas stickers Fit hi vis tape as required Clean cooler pack, reverse fan to help clean Reseal blocks on bottom of control valves Replace leaking hose at front of slew motor Reseal hydraulic block near main suction Reseal adjustment screw on LHS pump Replace 3x leaking test fittings Replace hose at cooler pack Replace rear carrier roller on LHS Replace front carrier roller on RHS Replace start isolator Replace E stop at isolator Replace air valve on air tank Ulan spec, fuel system, exhaust lagging, segregation of hoses Paperwork and fulcrum photos			
	52332	HME Inspection - Excavator Quote #: 311 *Finish 10,014hrs	10/02/2025	10015	Hours
	18509	Checked over hand rails took photos of damage Organise parts to fix defect Opened engine cover and inspected leaks	9/08/2024	10004	Hours

Asset	W/O No	Description	Finished	Done Reading
		Inspected hydraulic control valve for leaks		
		Repair coolant leak on turbo coolant feed hose		
		Inspect oil leaks in hydraulic pump area		
		Dropped belly plates under machine		
		Check over leaks On counter weight side of engine		
		Tested and made sure heater is now working		
		Repair air operated grease pump		
		Remove turbo feed coolant line		
		Re seal with new hose and clamps		
		Remove rocker cover and inspect		
		Assemble rocker cover, fit new engine breather		
		Check all hose clamps up top of engine with 1/4 ratchet		
		Remove all clamps from hydraulic suction lines		
		Remove all U bolts		
		Remove mounting bolts for suction pipes on pumps		
		Cut hoses of pipes		
		Clean up all large clamps with wire wheel		
		Clean up pipe work		
		Install new Onrings		
		Install all new suctions hoses on pipe work		
		to pumps		
		Install main suction pipe		
		Install 3x suction pipes		
		Re-fit suction pipe with new hoses and saddle clamps		
		Bolt up u clamps that mount suction pipe		
		Remove small suction steel pipe with half clamps		
		Installed new joiner O rings		
		Cleaned up and installed new mount o ring		
		Install all suction hose clamps		
		Tension all hose clamps		
		Re seal 3 fittings		

Asset	W/O No	Description	Finished	Done Reading	
		Drill holes for bolt holes Cut off old hand rail Weld hand rail onto new box piece of box section Cap off ends and weld out Cut off old latch Weld on new latch Prep for paint Paint hand rail piece Install new hand rail Drill holes to suit u bolts Test operate digger Clean off belly plates and install them Re seal hydraulic block that was sweating oil Fit new seatbelt to machine Install pin seals in stick and h link Fill greaser Shim bucket evenly Install all locking plates Clean up around bucket Re seal hydraulic valve under cabin Install belly plate under cabin Tighten new work light and adjust			
	17957	Prep bucket in Dubbo, send to site. Replace lip. Repair cracks. Fit wear pack as required. Linebore hitch pin bores	30/07/2024		Hours
	18508	Excavator - 2000hr service Check valve lash and check over valve springs	24/07/2024	10004	Hours
	18152	Drop belly plates and turn on heater tapes Replace 5x blown light globes. Fix wiring running over cabin for roof lights Hours: 9905 15/06/24	10/07/2024		Hours

Asset	W/O No	Description	Finished	Done Reading	
	12580	Excavator - 500hr service	26/04/2024	9711	Hours
	14875	Hours 8635 Remove all belly guards, clean. Remove track frame guards Remove and reseal stick cylinder Took off front guards, tightened up coolant hose clamps. Reseal lift cylinders, drain hydraulic oil, change out suction hoses, remove control valve. Removed pilot hydraulic lines, replace. Fit steel piping to valve block 1, replace all o-rings, reseal steel filter screen on valve block one, reseal control valve one and reinstall, remove lines to control valve 2, remove valve 2 and start to reseal. Replace leaking hydraulic hoses Pulled off engine guards, pulled off the taper covers, reseal covers Strip clean and reseal control valve 2, sort parts out.	18/04/2024		Hours
	14020	Bucket adapter cracked about to fall off, replace with new adapter Travel down to pit Remove bucket teeth and replace with new bucket teeth Check for leaks Look over machine	28/03/2024	9668	Hours
	8750	Supply replacement tracker	15/03/2024	9482	Hours
	10044	FAULT - Seatbelt is locked up and needs replacing, part number 22B-57-11911. Also needs 2 replaceable wear pads for bottom of bucket and a weld on block as were one of the wear pads goes it's broken the mount off. REPAIRS - Load all equipment and parts to do the job. Travel to site. Sign in and paperwork.. Move machine in to position to do works. Clean machine and bucket to do the job. Remove old adapters. Gouging, grind out cracks Weld up cracks. Hours: 9362 - Hours 9454 09/03/2024 @Wade Earthmoving	9/03/2024		Hours
	9684	Excavator - 250hr service	24/02/2024	9380	Hours

Asset	W/O No	Description	Finished	Done Reading	
	5898	Prehire repairs, paperwork, wash Check over Fill out prehire paperwork Wash machine Diagnose A/C not working. Replace A/C compressor.	14/10/2023	8654	Hours
	14874	Hours 8635 Off-hire Check over Strip machine for transport, demob machine, organise paperwork to demob machine, collect all parts up to send with machine.	19/03/2023		Hours
	14880	Hours 8557 Replace hoses - clean out travel motor cavity, remove old hoses, fit new hoses, test, top up oil, put covers back on.	21/12/2022		Hours
	14882	Hours 8513 Replace grease controller, reprogram run cycle make sure working Horn not working - R&R Diaphragm in horn	5/12/2022		Hours
	14881	Hours 8513 Replace bucket pins and bushes	5/12/2022		Hours
	14885	Hours 8492 Bucket Repairs Wash buckets, remove bucket, machine creeps difficult to remove, found pins and bushes u/s. Spoke to Scott, organising to repair ata later date. Organise hot works permit, boiler maker did repairs, fit bucket.	22/11/2022		Hours

Asset	W/O No	Description	Finished	Done Reading
		Turn shin guards Remove shin guards, turn, one wouldnt go on adapter welds too high. Shin guard had been gauged out to fit. Grind down weld, fit shin guards.		
	14883	Hours 8492 Replace all Orings blocks and hoses off pumps Replace pilot hoses to pumps. Replace spike hoses from pumps and control valves	22/11/2022	Hours
	14887	Hours 8356 Counter weight bolts are loose Tighten counter weight bolts to spec, fill up grease pod. Check system.	17/10/2022	Hours
	14886	Hours - 8356 500 Hours Service	17/10/2022	Hours
	14925	Hours 8298 CPB Monthly inspection	4/10/2022	Hours
	14924	Hours 8298 Hydraulic oil leaks, replace multiple O-rings around control valve hoses, reseal valve spools on control valve, wash machine, replace o-rings on hoses to slew joint.	4/10/2022	Hours
	14927	Hours 8285 Replace bucket teeth.	28/09/2022	Hours
	14926	Hours 8285 Replace track rollers. Lift up machine, chock machine, loosen off tracks, undo roller bolts, remove rollers, do same to other side, one roller had broken bolt, blow out with oxy, clean up with die grinder remove bolt, clean thread with tap,fit new rollers torque to spec. Tighten tracks.	28/09/2022	Hours
	14928	8270 Hours 250 Hours Service	23/09/2022	Hours
	14929	Hours 8200 Blown dipper cylinder hose. Organise new hose, organise EWP to get hose off. Remove old hose, fit new hose, top up hyd tank. Test for leaks	8/09/2022	Hours
	14930	Hours 8183 Grease pump reseal, wash grease pump and tank. Remove grease pump, strip clean, assemble with new parts and seals. Fit pump. Fill grease pot. Test pump.	6/09/2022	Hours
	14931	Hours 8166 Blown machine hose, remove blown hose and one beside it that was leaking from crimp. Get hoses made, fit new hoses. Fill up hyd tank. Test for leaks. Clean machine.	1/09/2022	Hours
	14932	Hours 8137 Replace belt tensioner and water pump. Remove belly guards, found belt tensioner failed.R&R	29/08/2022	Hours

Asset	W/O No	Description	Finished	Done Reading
	14945	Prestart defect Ladders/Hand Rails/Steps/Walkways Failed - Gate lock missing, auto greaser stops randomly. Replaced missing pin and spring for gate latch. Adjust auto greaser settings.	8/08/2022	Hours
	14948	Hours 7993 1000 Hour Service UHF losing power - replaced power to plug Grease line to main boom lift ram broken - repaired grease lines to bottoms of boom lift cylinders	17/07/2022	Hours
	14961	Pre start defects Leaking hydraulic fluid - replaced 12 leaking hydraulic hoses and several O rings on valves and fitting.s	24/06/2022	Hours
	15037	Load out off site Clean up demob area	6/12/2019	Hours
	15039	Hours 5723 250 Hour service	14/04/2018	Hours
	15040	Hours 5213 Extract fault code E11-CA323-cyl 5 injector wiring fault No miss fire or rough running conditions	21/01/2018	Hours
	15041	Hours 4150 Sample engine oil and check over	13/01/2018	Hours
	15042	Hours 5069 R&R radiator cap, top up coolant	3/01/2018	Hours
	15044	Hours 5019 R/R x4 wear plates Fit x3 missing shin guard pins	16/12/2017	Hours

Asset	W/O No	Description	Finished	Done Reading
	15046	Hours 4999 Replace busted fitting on RH boom cylinder grease line Refit 1 tooth	13/12/2017	Hours
	15047	Hours 4992 Retime auto greaser. Check all levels after service.	12/12/2017	Hours
	15048	Hours 1000hr service	10/12/2017	Hours
	15049	Hours 4990	7/12/2017	Hours
	15050	Hours 4990 Drain and replace both final drives and slew motor oils	5/12/2017	Hours
	15051	4987 Hours R&R split grease hose on boom	4/12/2017	Hours
	15053	Hours 4858 Remove belly plates Drain coolant Remove broken exhaust section Remove EGR cooler and components Swap all hoses/brackets onto new cooler Refit cooler with new gaskets & seals Modify repaired exhaust pipe as the rotation of the flange was incorrect Fit exhaust & fill coolant Check for leaks Test run for 30 mins	15/11/2017	Hours
	15057	Hours 4534 Remove tappet covers, adjust valve lash in correct order to manufacturers spec, fit new seals to tappet covers and refit test Refit ancillary items, air cleaner stacks and bonnets. Test run to temp and assess performance.	17/09/2017	Hours

Asset	W/O No	Description	Finished	Done Reading
	15060	Hours 4495 Service and check over	1/09/2017	Hours
	15061	Hours 4318 Remove bucket grease line. Make up replacement.	30/07/2017	Hours
	15062	Hours 4298 Replace air tank Replace bucket grease nipples Tighten up suction hose on pump Tighten up main feed for grease	22/07/2017	Hours
	15063	Hours 4045 Service Dropped oil and refilled Changed filters and checked over	8/07/2017	Hours
	15064	Hours 4189 Shut down inspections and grease	7/07/2017	Hours
	15065	Leak in guts of digger Repair slow leak from rotary connection	27/06/2017	Hours
	15066	Hours 4140 Check over & grease bucket Found fire extinguisher mount half off, replaced bolts.	25/06/2017	Hours
	15067	Hours 4045 Service and inspections	10/06/2017	Hours
	15068	Hours 3980 Change quick fill set for grease Grease bucket	31/05/2017	Hours
	15069	Hours 3962 Replace 2x retainer teeth	30/05/2017	Hours
	15070	Hours 3959 Blown hyd lines Had new hose made, fitted. Refill hyd oil	29/05/2017	Hours
	15071	Hours 3864 Fit replacement bucket cyl line LH side Replace broken grease injector & plumb up General check of oils etc Shut down checks	13/05/2017	Hours
	15072	Hours 3874 Blown hose off bucket cylinder Removed line	11/05/2017	Hours

Asset	W/O No	Description	Finished	Done Reading
		Took into town and got made		
	15073	Hours 3852 Grease whole digger	6/05/2017	Hours
	15074	HOurs 3834 Check over machine and knock in teeth retainer	4/05/2017	Hours
	15075	Hours 3815 Clean out filters and grease bucket Tighten up loose bolt on pin cap.	3/05/2017	Hours
	15076	Hours 3815 Top up hyd oil & run up Fix up missing grease fitting on stick cylinder	2/05/2017	Hours
	15083	Hours 3809 Demob	22/02/2017	Hours
	15084	Hours 3808 Travel to machine Take photos of unit & details as per request of Rob Kinsella Send via e-mail	16/02/2017	Hours
	15085	Hours 3762 Pick up GET from workshop, load & change Dispose of parts.	10/01/2017	Hours

Asset	W/O No	Description	Finished	Done Reading
	15087	Hours 3746 Fit new tooth retainer Replaced failed auto greaser line	9/01/2017	Hours
	15089	Hours 3702 Check retainers on bucket teeth General inspection	15/12/2016	Hours
	15088	Hours 3693 Replace missing tooth retainer	15/12/2016	Hours
	15090	Fill auto greaser	8/12/2016	Hours
	15092	Hours 3642 Travel to machine Fill auto greaser	30/11/2016	Hours
	15091	Hours 3642 Travel to machine General inspection	30/11/2016	Hours
	15095	Hours 3613 Pump and load oils Travel to machine Perform 500hr service Remove GET and assist with bucket repair General checkover of machine Dispose of oil filters and oil at workshop Refit GET and move machine for fuel truck access.	26/11/2016	Hours
	15097	Hours 3602 Load parts Travel to machine	24/11/2016	Hours

Asset	W/O No	Description	Finished	Done Reading
		Replace failed GET retainer springs and wear plates Grease, inspect bucket Cracks appearing around teeth to floor Organise boilmaker to perform repairs		
	15098	Hours 3579 Load parts at workshop Travel to machine Grease machine and change out bucket teeth between truck loading	22/11/2016	Hours
	15296	Hours 3505 Load parts Travel to machine Fit new check plate Remove lower check plate Clean out clay and fit new pins	11/11/2016	Hours
	15297	Hours 3446 Travel to machine Grease machine & refit check plate that was dislodged Return to workshop and unload	7/11/2016	Hours
	15298	Hours 3379 Organise service truck Fill auto greaser	25/10/2016	Hours
	15299	Hours 3312 Fill auto greaser Top up oil Drain water trap	17/10/2016	Hours
	15300	Hours 3306 Perform early 500 hr service Remove failed pilot hose and take to Gympie to have new one made Return to site, fit hose, test machine Dispose of waste oil and filters	15/10/2016	Hours
	15301	Hours 3247 Diagnose leaking hyd hose on pump Replace O-ring Order filter kit and slew bank deals Order engine oil & grease	10/10/2016	Hours
	15302	Hours 3242 Tighten loose bucket pin caps Diagnose leaking slew bank Reseal grease line on auto lub	8/10/2016	Hours
	15303	Hours 3221 Grease bucket and general inspection	6/10/2016	Hours

Asset	W/O No	Description	Finished	Done Reading
	15304	Hours 3208 Pick up platform ladder & hose from w/shop JHA & return to machine in cut 4 Fit new hose, top up hyd oil and test Monitor first operation of machine.	4/10/2016	Hours
	15306	Diagnose and pick up new e-stops and flashing light from town Return to site and fit Perform site pass out, move to lay down area	30/09/2016	Hours
	15307	Hours 3205 Fit counter weight, handrails, walkways, ladders, boom Connect hoses under boom	28/09/2016	Hours
	15308	Hours 3205 Escort in JHA & unload/position	27/09/2016	Hours
	15309	Replace batteries and move	25/06/2014	Hours
	15310	Travel to quarry, fit new foam to radiator core Lift new core into place & slide in Fit new bottom radiator hose Fit top guard & hoses Fit all belly plates. Fill radiator up. Took 110 ltrs Fit all guards, clean up area. Travel back to w/shop/	24/02/2014	Hours
	15312	Drain coolant from radiator (not mcuh left) Remove bottom hose, had to remove guards from top. Remove 3 top radiator hoses so guards could be removed. Went to remove 1st core it was stuck had to gently pry out. Clean up area & stack parts in safe spot. Bring U/S core back to w/shop Waiting for Maas to find out what they want done with it.	14/02/2014	Hours
	15311	Leaking radiator core to be removed - remove overhead bolts & bracket. Remove hoses (seized to header tank) Remove guarding Remove core Grown into insulating foam Stack parts in safe place Transport U/S core to EOS Workshop	14/02/2014	Hours
	15315	Escort float onto site, block off loading area. Load excavator, help to tie on. Escort off site.	21/11/2013	Hours
	15316	Filled out paperwork, set up 1250 & set up crane. Demob.	20/11/2013	Hours

Asset	W/O No	Description	Finished	Done Reading
	15341	Hours 2998 Perform 1000 hour service Cleaned up oils and old filters Shimmed buck to stick, push pin out and fit shim. Reassembled pins, test ok.	30/09/2013	Hours
	15342	Hours 2769 Carry out 250hr service Replace leaking radiator cap Inspect radiator, replace leaking radiator cap	19/08/2013	Hours
	15343	Check bucket to stick clearance and sort out shims to fit at service.	25/06/2013	Hours
	15344	Hours 2436 Check leaking grease fitting broken (no sign of impact). Pick up new fitting from Pirtek and fit to machine	24/06/2013	Hours
	15346	Time cycle is correct, repair oil leaks, reseal fitting on air compressor. Tighten oil filters - found filter sensor U/S	19/06/2013	Hours
	15347	Hours 2369 Test for low hydraulic power, operate mode switches and test. Rocker switch dirty.	14/06/2013	Hours
	15348	Hours 2365 Remove leaking quickfill fittings hyd sealant leaking, clean, dry & reassemble with teflon tape.	21/05/2013	Hours
	15349	Hours 2365 R&R leaking coolant sight glass hoses ans clean and re-clamp	15/05/2013	Hours
	15350	Hours 2365 Adjust left track, travel track and readjust	8/05/2013	Hours

Asset	W/O No	Description	Finished	Done Reading
		Check roller oil.		
	15352	Hours 2365 Set up machine. release left track adjuster and block up track frame. Replace no 8 roller and torque to 1300 ft 16 Reset machine on ground.	7/05/2013	Hours
	15353	Hours 2364 Clean out track rollovers and mounting bolts.	19/04/2013	Hours
	15355	Hours 2271 Carry out 250hr service as per service sheet	21/03/2013	Hours
	15359	Hours 2198 Trace fuel leak to fuel filters Remove filters and sediment bowls, check seals & refit. Test, OK. Ajust bucket tilt, grease injector. Tighten loose grease hoses.	6/03/2013	Hours
	15360	Hours 2198 Check and adjust grease injector for bucket pin.	25/02/2013	Hours
	15363	Hours 2189 Poor greasing to tilt pin Clean and fit spare large grease injector.	22/02/2013	Hours
	15364	Remove broken grease fitting form H link. Fit new adaptor.	13/02/2013	Hours
	15366	Replace hyd filters.	21/01/2013	Hours
	15367	Hours 2054 Change hydraulic filters.	18/01/2013	Hours
	15368	Replace broken bolts in under carriage	16/01/2013	Hours

Asset	W/O No	Description	Finished	Done Reading
	15370	Hours 2025 Carry out 2000 hr service	13/01/2013	Hours
	15558	Hours 1814 Check auto greaser Adjust injector for bucket pin	29/11/2012	Hours
	15559	Hours 1767 250 Hour service	21/11/2012	Hours
	15561	Hours 1647 Check and repair grease lines for bucket pins	2/11/2012	Hours
	15562	Hours 1596 Inspect loose bucket pins	22/10/2012	Hours
	15563	Hours 1488 Carry out 250hr service	5/10/2012	Hours
	15564	Test new solenoid valve adjust timer and regulator pressure for correct operation. Test. OK	3/10/2012	Hours
	15565	Hours 1472 Auto lube solenoid U/S	2/10/2012	Hours
	15572	Hours 1422 Pick up new water pump R&R covers, drain coolant.	24/09/2012	Hours

Asset	W/O No	Description	Finished	Done Reading
		Replace leaking water pump, fill with coolant. Test OK.		
	15573	Hours 1372 Check and top up coolant Trace leak to water pump order parts.	17/09/2012	Hours
	15575	Hours 1295 Check fault light, blow out air filter.	7/09/2012	Hours
	15576	Hours 1250 250 hr service Scratch on RH bucket cyl rod.	2/09/2012	Hours
	15577	Fit new travel alarm and test operation, show operator how to reverse fan direction.	24/07/2012	Hours
	15578	Inspect oil leak and change over o-ring on hydraulic filter.	21/07/2012	Hours
	15579	Hours 961 1000 hr service	19/07/2012	Hours
	15580	Fault code & buzzer came up Operator cleared. Code buzzer stayed on fault, was hard to find because of that. Found to be slew brake half on.	12/06/2012	Hours
	15581	Running warm, show operator how to reverse fan. Clean buckets and around container.	24/04/2012	Hours
	15582	Hours 548 Replace 3 worn teeth with second hand teeth	18/04/2012	Hours
	15583	Hours 500 Carry out 500hr service and inspections.	14/04/2012	Hours
	15586	Hours 305 Rotate bucket teeth, carry out bucket inspection	14/03/2012	Hours
	15588	Dogbone to bucket pin retaining plate missing bolts broken. Replace bolts and plate, travel to town, get plate & bolts & filters as they had gone missing from container. Carry out service and checks as per workshop maintenance schedule.	18/02/2012	Hours
	15587	Hours 178 Carry out initial 100hr service. Change oil filters & check levels.	18/02/2012	Hours

Asset	W/O No	Description	Finished	Done Reading
		Remove top radiator cover, locate and tighten loose coolant clamp.		
	15589	Adjust A/C and Alt belts	10/02/2012	Hours
	15590	Hours 112 R&R and clean loose retainer bolts in bucket pin	9/02/2012	Hours
	15591	Hours 11 Assemble machine	12/01/2012	Hours
	15601	Hours 8 Cover up exhaust and intake	24/12/2011	Hours
	15602	Hours 3 Unlaod Stall boom and parts. Unpack hand rails. Look over parts required. Sort out console for fitting site, required shut downs and fitting quick fills and jump starts.	17/11/2011	Hours