Work Order History Report

Asset	W/O No	Description	Finished	Done Reading	
P0282		**Cat 773F Dump Truck**			
	193331	Disposal. wash Fill hydraulic oil. Replace batteries	10/06/2026		Hours
	59359	HME Inspection - Rigid Dump Truck Quote #:	28/11/2025		Hours
	58045	October Monthly R & M WO: - trans oil temp fault, not coming out of first gear, damaged wiring from shift control 02/10 Check all E stops for issues/no start, found front contact to be sticking pull apart clean and free up 16623hrs Wiper not working, diagnose and release	10/10/2025		Hours
	57657	September R & M Monthly WO: - wiper squirter blocked/ unblocked jet 18/09 - Hyd oil leak/ blown o ring on hoist control valve, replace o ring and fill with oil 18/09	18/09/2025		Hours
	56929	INTRODUCTION TO SITE - USO	17/09/2025		Hours
	57334	Rigid Dump Truck - 500hr Service and to do list repairs 16540hrs - carry out service - repair broken wire on rev light - oil leak from trans filter housing, change o ring, - check and adjust all tyre pressures - replace A/C fan motor 15/09	10/09/2025	16540	Hours
	56708	August R&M Monthly: Steering wheel not adjusting found broken cable. Remove P1206 to fit P282. - Seat compressor failed and body up alarm not working 16484hrs 29/08 - Remove air valve and replace with new one, order, didn't fix look into further, found compressor U/S order parts - Strip seat down and replace seat compressor, run new wire for body up alarm - Replace tyre - split.	29/08/2025	16484	Hours
	56326	Rigid Dump Truck - 250hr Service 16282hrs - 16349 hrs	4/08/2025	16349	Hours
	56044	July USO R&M - remove rock guard 11.7 - Trans fault cleaned check plugs, found dog bone retainer bolt broken	17/07/2025		Hours

Asset	W/O No	Description	Finished	Done Reading
		- Adjust mirrors - Trans fault, cleaned and checked plugs, found broken bolt for dog bone, pin walked out - repair - Plug seat belt wiring back in		
	55253	June R&M USO - C/O leaking trans pipe, clean bay - Change out faulty trans temp sensor - Commission truck, lights, mirrors, feets - Fit trans cooker hose, top up fluids - Gas up front suspension strut, fit mirrors, greased machine, check all fluids, send to work - Remove and repair trans oil filter pipe - Remove trans pipe and repair- order pipe and re-fit. - Replace halogen lights to LED - Replace hoist/ trans lever unit - Start removing leaking pipe - Top up coolant, fit nut to rear suspension strut bottom pin retaining bolt - Top up trans oil - oil leak 16188hrs	27/06/2025	Hours
	52701	USO spec works. Replace floor liners. Inspect defect (To-Do's) as per task list, action as required. USO OIL CHARGE OUT Repair damaged front RH bumper Replace missing bolts in engine covers Check/tag and bag fire extinguishers Repair access light Fill washer bottle Grease machine, replace nipples on bulkhead Replace emergency stop, starter isolator, fire suppression, 3 points of contact stickers on front Remove Maas stickers Fit thinksafe, QR stickers Remove old client stickers Fill fuel Repair exhaust tip Top up diff oil Repair crack in LH suspension cylinder bottom brace Remove broken bolts in side rock deflector Fit hungry boards Repair reverse lights USO spec On hire fulcrum photos Maas paperwork	17/03/2025	Hours

Asset	W/O No	Description	Finished	Done Reading	
	12504	4x 24.00R35 Used Tyres missed on work order 7086	18/03/2024		Hours
	9890	De-Mobilisation Remove handrails, secure access steps.	8/03/2024		Hours
	8798	Rigid Dump Truck - 2000hr Service Repair oil leaks at brake filters. Pump up rear struts.	18/01/2024	16018	Hours
	8646	Tub Inspection & Material Ordering	11/01/2024	15977	Hours
	8402	Repair park brake fault. System integrity tested - fault with operator - not fully latching seat belt.	2/01/2024	15887	Hours
	8380	Major AC system repair. Compressor failure. Replace ac compressor. Flush/clean a/c system. Vac and gas system after repairs.	1/01/2024	15886	Hours
	8188	Temporary repair step support. Order replacement.	18/12/2023	15830	Hours
	8183	Mechanical checkover. Replace broken rear view mirror	17/12/2023	15820	Hours
	7888	Investigate park brake fault. cleaned seat belt switch as found to be faulty. Tested operation ok.	9/12/2023	15753	Hours
	7512	Mechanical pre start checks. Fit wheel nut indicators	3/12/2023	15721	Hours
	7191	Minor R&M Monday 13/11/23 to Sunday 19/11/23	19/11/2023		Hours
	7086	Remove and replace Pos 3,4,5 & 6 tyres Jack and and support machine. Remove and replace all rear tyres as required.	12/11/2023	15721	Hours
	6802	Minor R&M Monday 06.11.23 to Sunday 12.11.23 Fit new steering wheel bush kit Park brake would not release. Found operator not locking seatbelt in correctly to release park brake	12/11/2023		Hours
	6535	Minor R&M Monday 23-10-23 to Sunday 29-10-23 LH steering cylinder leaking. With some difficulty, removed cylinder, and with further difficulty, stripped cylinder. Used special spanner to get piston nut off rod. Manufactured flogging spanner to enable disassembly of steering cylinder. Replaced all seals, and reassembled cylinder. refitted to truck as required, and plumbed. Tested operation- all OK. - Tried removing cylinder from truck in lay down yard, to swap out with cylinder from this truck, as it was quite a struggle to get the cylinder apart for a reseal. Couldn't release ball joint from it's mount, so reassembled and focussed on disassembly of original cylinder.	29/10/2023		Hours
	6221	Minor R&M Monday 16-10-23 to Sunday 22-10-23 Changed out park brake solenoid.	22/10/2023		Hours

Asset	W/O No	Description	Finished	Done Reading	
		Checked over after fire suppression repairs done. Reset control panel. That part was all OK, but found a wire out of a remote shutdown switch at bottom of stairs. Repaired and tested- all OK. Continued to look for electrical issue. Found rubbed through wire in engine bay. Stripped and repaired wiring as required. Then found Deutsch plug for seat belt warning to be U/S. Removed and replaced plug. Checked- all OK. Electrical fault still present- low current to solenoid. Traced all wiring, looking for fault. Park-brake still not releasing. Checked over for issue. Found one wire broken in loom. Repaired wire, but unable to check operation as of 18/10. Fire suppression tube broke on contact- very brittle. New parts being sourced by Pirtek. Pirtek (Luke) attended site to replace 'burn tube, and convert system to local fluid type, by changing cylinder head, and nozzles. Still wouldn't start after repairs done.			
	5604	Rigid Dump Truck - 500hr Service Top up steer & hydraulic oils Repair blown light bulbs Secure reverse light & tidy wiring Repair seatbelt warning light Replace grease line	10/10/2023	15644	Hours
	5723	Minor R&M Monday 25-09-23 to Sunday 01-10-23 Checked and cleaned out air cleaners pre-shift Repair oil leak from hydraulic filter housing Torque converter temp sensor fault. Removed sensor from truck in lay down yard, and fitted to P282 to get it going. Went Ok for a while, then did the same thing again. Checked over wiring- found broken wire pertaining to the fault. Repaired- all OK.	1/10/2023		Hours
	5583	Minor R&M Monday 18-09-23 to Sunday 24-09-23 Repair aerial Steering column strut failure. Removed strut from P0302 to get truck going. Have ordered new struct for P0302	24/09/2023		Hours
	5382	Minor R&M: Set road speed limit to 40kph Rectifiy hydraulic oil leak between hyd filters in chassis Further oil leaks around hydraulic filters in chassis Finish off hydraulic leaks. Fix wiring issue at front battery isolator.	17/09/2023	15474	Hours
	5087	Minor R&M Monday 15422 hours carry out brake test carry out park test Check accumulator pressures	5/09/2023	15422	Hours
	4723	Pre hire work	23/08/2023		Hours
	4452	Minor R&M - put 773 together	11/08/2023	15421	Hours
	2555	Off hire repairs Reseal fittings on chassis side of fuel tank Reseal brake filter Replace reverse camera Welding repairs: - repair cracks in chassis behind strut - repair handrails	7/08/2023	15421	Hours

Asset	W/O No	Description	Finished	Done Reading	
		- repair ladders, steps, walkways - repair hungry boards - weld wear plates into tub - weld up under fire suppression support, repair mount - repair front corner damage, weld new piece in Rewire lights after damage repair to front end Replace starter motor gasket Replace dog bone bearings Replace LH lift cylinder end bearings Replace RH lift cylinder top bearing Replace air cleaner inlet hose Replace batteries, clean out battery box Replace strut bearings Stamp rims Carry out brake tests - passed Refit e-stop in cab Replace RH steer cylinder rod end ball stud Service Fire Suppression system			
	3908	Reseal accumulator charge cable and all hoses. Remove fire suppression and engine cover to be welded.	2/07/2023		Hours
	3906	Remove lift cylinder, bearing collapsed.	1/07/2023		Hours
	9722	Damage to front bumper, repaired mud flap.	22/06/2023		Hours
	3947	Removed eyebrow from machine	13/05/2023		Hours
	2304	Carried out repairs to machine seat, fitted new seat base	13/05/2023		Hours
	1891	Demobe - Get franna and boom lift to remove all cat walks and put in tub	6/05/2023		Hours
	761	Remobe w/shop	30/04/2023	15417	Hours
	1081	Finish off welding out beaver tail. Clean up around work area.	19/04/2023		Hours
	1080	Beaver tail repairs. Cut and prep new biz. Install and weld out biz strips installed	18/04/2023		Hours
	1079	Beaver tail repairs. Remove oil biz. Prep and clean ready for new biz	17/04/2023		Hours
	693	Condition report	9/04/2023	15417	Hours
	822	Fit spacers to RHS lift cylinder pin	7/04/2023	15417	Hours
	681	Carried out repairs to machine finished replacing body lift cyl pin and bearings. Removed dog bone, then replaced both bearing and then replaced a worn out tie rod end .	6/04/2023	15417	Hours
	674	Carried out repairs to machine fitting new parts and carrying out demob jobs. Fit new parts to machine, replaced tub lift ram bearings and pins.	4/04/2023	15417	Hours

Asset	W/O No	Description	Finished	Done Reading	
	15654	Hours 153415 Trace electrical fault for ac found low pressure switch faulty.	22/03/2023		Hours
	15656	Hrs - 15322 Broken bolt - remove broken bolt and add new guard mount.	20/03/2023		Hours
	605	Carried out inspection and testing on this machine. Heated up front bumper and straightened	18/03/2023	15322	Hours
	1223	Diagnosed faulty reverse buzzer	7/02/2023		Hours
	1213	Carried out running checks/movement checks/ defects list	6/02/2023		Hours
	15659	Hours 15258 250 hr service	1/02/2023		Hours
	15661	Prestart defect - Reverse Camera - camera lense cracked.	29/01/2023		Hours
	15660	Pre start defect - lights including head, stop, tail, indicator Lights including head, stop, tail, indicators, work Flood - reverse light stay on randomly, even when not in reverse gear	29/01/2023		Hours
	15655	Hours - 15322 250 hr service	27/01/2023		Hours
	15657	Hours 15322 Replace LH step rubbers	17/01/2023		Hours
	15658	Hours - 15258 Steer oil & hydraulic oil - add	9/01/2023		Hours
	15663	Empty bin coming down too hard at the end. Carried out inspection on bun - no fault found at time of test Check all engine fluid levels and leaks - diesel leaking - all OK at time of test All 3 fire extinguishers are out of date. - Tags missing new ones are required.	11/12/2022		Hours
	15662	Hours - 14050 1000 hr service	11/12/2022		Hours
	15665	Work to be completed at service interval HMU leaking - replaced Windscreen wipers not working - re-wired as required Right hand front light out - replaced bulb as required Check all e-stop functions - ok at time of test Test & tag fire supp/extinguishers - checked all ok as required Control for tub to lower sometimes will not lower, or very slow to lower - repair carried out - concern rectified No front step (reported 29.09.2022) - replaced as required	29/11/2022		Hours
	15664	Hours 14702 250 hr Service	1/11/2022		Hours
	15666	Pre-start defects	19/09/2022		Hours

Asset	W/O No	Description	Finished	Done Reading
		~~Entry step broken - replaced~~ Right front bumper corner damaged - noted sent back to work		
	15668	R&R POS 1 Tyre	18/09/2022	Hours
	15669	Hrs 14474 Repair reverse camera & repair beacon short in beacon replaced	11/09/2022	Hours
	15667	Pre-start defect - rotating beacon Replaced during service	11/09/2022	Hours
	15670	Hours 14474 500 hr service	9/09/2022	Hours
	15671	Transmission shift fault Check tub height control sensor and all solenoids.	7/09/2022	Hours
	15672	Replace rear strut bolt	5/09/2022	Hours
	15674	Fitted and replace wiper blades	31/08/2022	Hours
	15673	Hours 14401 Replace u/s wiper blades	31/08/2022	Hours
	15676	Hours 14356 R&R lower strut bolts broken Fit new bolts and washers	27/08/2022	Hours
	15675	Hours 14561 Repair step Repaired grease lines and greased	27/08/2022	Hours
	15677	Hours 14337 Knock strut pin back in and replace retaining bolt.	22/08/2022	Hours
	15678	Hrs 14327 Strut retainer bolt broken	21/08/2022	Hours
	15679	Hrs 13979 Trans bypass light coming on Found break in wire, repaired.	15/08/2022	Hours
	15681	Hours 14224 Retarder fault	12/08/2022	Hours
	15682	Check split inside wall steer tyre	4/08/2022	Hours
	15685	Hours 14099 1000 hr service	1/08/2022	Hours
	15684	Hours 14101 Hungry board repairs	1/08/2022	Hours

Asset	W/O No	Description	Finished	Done Reading
	15683	Hours 16099 1000 hr service	1/08/2022	Hours
	15686	Replace brake cooler hose Line up A-Frame pin	31/07/2022	Hours
	15687	Hours 13904 Re-gassed front struts	13/07/2022	Hours
	15689	Hours 13924 Refitted/repair rear strut pins	8/07/2022	Hours
	15688	Rear strut pins Remove broken bolts Pull pin out of strut Clean up bore & fit new pin and bolts Regas strut	8/07/2022	Hours
	15690	Hours 13810 Upgrade lights for N/S and fix light harness	1/07/2022	Hours
	15691	Hours 13813 Drained gas from front RH shock Topped up oil in shock then re-gased	23/06/2022	Hours
	15692	Hrs 13753 Removed trans temp sensor Replaced with P0290 sensore	14/06/2022	Hours
	15693	Hrs 13745 Greased Blew out filters Topped up hydraulic oil	9/06/2022	Hours
	15694	Hours 13655 Adjust rear strut heights Morning pre start checks	22/05/2022	Hours
	15696	Remove eyebrows walkway and steps and put in tub for transport Fit new stickers	21/03/2022	Hours
	15695	Stripped stairs, cat walk and eye brows off Fitted plant stickers and washed machine.	21/03/2022	Hours
	15697	Fitted RH suspension strut, removed LH plant ID sticker. Check fluid levels, adjusted grease lines. Fix oil leaks LHS machine	11/03/2022	Hours
	15699	Released RH steer cylinder and fitted it. Re-sealed suspension strut.	10/03/2022	Hours
	15698	Resealed reat strut, cleaned mounting, ready to install.	10/03/2022	Hours

Asset	W/O No	Description	Finished	Done Reading
	15700	Assist mechanic	9/03/2022	Hours
	15709	Install A frame bearing and A frame. Install fuel tank, replaces trans suction hose. Install wiring loom for transmission and tension drive shaft. Install guard over drive shaft.	7/03/2022	Hours
	15708	Hours 13469 Clean and re-assemble hyd tank	7/03/2022	Hours
	15707	New seals in drive arms Put in sensor guards Cleanup up around dog bones	7/03/2022	Hours
	15705	Put hoses back together around transmission, bolted in drive shaft, resealed all hoses. Rescaled hyd tank bung. Replaced leaking test fitting LHR brake cooling pipe Find broken clamp RHS brake cooling pipe.	7/03/2022	Hours
	15703	Repair cracks in manifold	7/03/2022	Hours
	15710	R&R dogbone bearings. Remove LHR strut cover Start removing circe.	5/03/2022	Hours
	15716	Remove steering	4/03/2022	Hours
	15715	Assist pulling fuel tank off	4/03/2022	Hours
	15714	Removed RHS rear strut from frame, remove A-Frame bearing and clean for assembly. Clean and remove steering crank. Remove bushes Remove fuel tank for A-frame line boring	4/03/2022	Hours
	15713	Hours 13469 Remove steer cylinders Remove vs ball studs and drag links Disassemble steer cylinders Both rods re drained Disassemble RHR strut to get bearing eye machined.	4/03/2022	Hours
	15712	Weld up oil tank	4/03/2022	Hours
	15711	Hrs 13469 Remove steer cylinders. Remove all U/S ball studs from cylinders and drag links. Disassemble both steer cylinders to reseal. Both rods need to be-chromed, disassemble spare cylinder to get rod shortened. Disassemble RHR strut to get bearing eye matched	4/03/2022	Hours
	15717	Hrs 13469 1000 hr service	3/03/2022	Hours

Asset	W/O No	Description	Finished	Done Reading
		Assist with A frame bearing remova		
	15718	Hours 13469 Check over and do defect list, order parts.	2/03/2022	Hours
	15719	Pop all ball studs, start to remove A-frame and replace bearings.	3/02/2022	Hours
	15720	Demob	20/01/2022	Hours
	15721	Hours 13408 Repair seat belt Fit new e-stop	12/12/2021	Hours
	15722	Hours 13393 Clamp up brake lines	14/11/2021	Hours
	15723	Hours 13374 Repair wheel chart holders	3/11/2021	Hours
	15724	Hours 13284 250hr service	21/10/2021	Hours
	15725	Hours 13191 Mobilise	30/09/2021	Hours
	15726	Hours 12796 Oil leak on brake hyd fitters Tighten loose fittind. Leak slowed down Will need reseal Complete FFP check over and paperwork	12/07/2021	Hours
	15729	Hours 12793 Fit new hyd hose from pump to hose valve Filled hyd tanks Tip load off top of spill way Replace UHF hand piece	11/07/2021	Hours
	15727	Hours 12793 Fit new hyd hose from pump to hose valve Filled hyd tank Tip load off top pf spill way Replace UHF hand piece	11/07/2021	Hours
	15730	Hours 12793 Remove blown pump to hoist hose at top of spill way	10/07/2021	Hours
	15731	Hours 12618 500 hr service	16/06/2021	Hours
	15732	Hours 12584 FFP checks and repairs	11/06/2021	Hours

Asset	W/O No	Description	Finished	Done Reading
	15734	Hours 12466 Remove brake filter hose	29/05/2021	Hours
	15733	Hours 124666 Fitted blown hose from accumulator to filters Repaired front step	29/05/2021	Hours
	15735	Hours 1239 Repair E-stop wires	17/05/2021	Hours
	15736	Hours 12371 Repair step Replace 1x rubber and straighten brackets	16/05/2021	Hours
	15737	Hours 123632 Weld up engine head and fire suppression mounts Make up brackets	11/05/2021	Hours
	15738	Hours 12334 Carry out diagnostic checks and change all machines to 40km p/h	10/05/2021	Hours
	15739	Hours 12294 Complete 250hr service Adjust and tighten mirrors Blow out AC filters	1/05/2021	Hours
	15740	Hours 12268 Hyd leak Remove brake hyd fitters Replaced O-ring on fittins. Fitted housing missing Topped up hyd oil.	28/04/2021	Hours
	15741	Hours 12227 Reseal brake filter fitting o-ring	19/04/2021	Hours
	15742	Hours 12207 Grease	17/04/2021	Hours
	15743	Hours 12185 Refit front LH outer mudguard Blew out A/C filters Adjust RH mirrors.	15/04/2021	Hours
	15744	Hours 12134 Reseal brake filter fittings.	6/04/2021	Hours
	15745	Hours 12105 Grease & check over machine system	31/03/2021	Hours
	15746	Hours 12069 Fit RH lower strut bolt	24/03/2021	Hours

Asset	W/O No	Description	Finished	Done Reading
		Fit steps		
	15747	Broken step on front Remove and fit new one	8/03/2021	Hours
	15748	Grease plant	25/02/2021	Hours
	15749	Hours 12003 Mobilise after fire supression set off	21/02/2021	Hours
	15750	Rock remover	18/02/2021	Hours
	15751	Hours 12001 - MObilise and grease truck	11/02/2021	Hours
	15752	Assemble & fit LH main mirror to transport position Complete actions on FFP and sign off HV inspection.	9/02/2021	Hours
	15753	Hours 12001 NPM FFP & HV Inspectionns Wrap & segregate steer cylinder hoses and grease lines Replace missing safety stickers Check & mark critical mounting points per FFP Replace front bumper lights with LED's Refit top engine covers Remove rock ejector off spare truck and fit to P3/4 Move out shed and fit P3 & P6 tyres	5/02/2021	Hours
	15755	NPM FFP Inspections	4/02/2021	Hours
	15756	Hours 12000 North Parkes FFP Sleeve hosing Fit stickers Secure hosing Fit fire extinguishers Check front strut mounting bolts	28/01/2021	Hours
	15758	Painted and prep hand rails.	27/01/2021	Hours
	15757	Hours 12000 North parkes FFP Bolt hand rails on Turn steps around Sleeve hyd hoses with croc sleeve	27/01/2021	Hours
	15759	NPM FFP & HV Clear inspection	22/01/2021	Hours
	15760	Hours 12000 Remove handrails for paint	14/01/2021	Hours

Asset	W/O No	Description	Finished	Done Reading
	15761	Hours 12000 Test fire suppression and remove bottle for testing.	6/01/2021	Hours
	15762	Insulate 4 fuel lines - take to wash bay	21/12/2020	Hours
	15763	Install new fuel cooler Start connecting fuel lines	18/12/2020	Hours
	15765	Cover fuel lines in burst protection	15/12/2020	Hours
	15764	Insulate fuel lines Remove broken fuel cooler	15/12/2020	Hours
	15766	Start insulating fuel lines Change front left brake pads Change both cab filters	14/12/2020	Hours
	15767	Chnage inner LH tie rod end Grease Change final drive oil	12/12/2020	Hours
	15768	Change air cleaners Replace air cleaner lids Install A-frame retainer Pop both front ball joints Replace ball joint Check fluids Pump up back tyres Turn machine around	11/12/2020	Hours
	15769	Install guards Hose clamps Top up steer oil/hyd Take tub off stands Start truck	10/12/2020	Hours
	15770	Connect hoses up for transmission Connect wiring Install guards Start installing P clamps Install dog bone Install all pin retainers Fit new window washer stalk	9/12/2020	Hours
	15772	Hours 11999 Fit new A frame returning nut & refit A frame in machine	8/12/2020	Hours
	15771	Fit clearance light Reseal fittings in steer cylinders Connect hoses up to transmission Install shock pins	8/12/2020	Hours

Asset	W/O No	Description	Finished	Done Reading
		Clean out window washer holes Diagnose faulty washer stalk		
	15775	Hours 11999 Fit new A-Frame bearing & retainer nut Tabs broken off nut where lock sits Order new nut	7/12/2020	Hours
	15773	Change batteries Clean out battery box Remount fire suppression module Change x2 engine oil filters Change torque converter filter Install torque converter Fill tube & fill oil	7/12/2020	Hours
	15776	Change fuel filters Clean torque converter screen Change 2x brake filters	5/12/2020	Hours
	15778	Fit new isolator Fill engine oil	2/12/2020	Hours
	15777	Hours 11999 Replace leaking hydraulic suction hoses Replace leaking O-ring on pilot filter housing Fit new POS 5 valve extension and prtector Start 1000hr service	2/12/2020	Hours
	15780	Assist Shane with A-Frame & drive franna	1/12/2020	Hours
	15779	Hours 11999 Jack up rear axle and remove lower strut pins Fit come alongs to rear axle & pull axle backwards & remove A frame bearing	1/12/2020	Hours
	15781	Hours 11999 Continue with A-Frame removal Finish removing all hoses Connect franna & remove pin Tried to lift out but will not lift up Checked and found bearing has to come out rearward Pump tyres back up and remove stands Jack up machine until rear axle hanging from struts and off the ground Place stands under tub Tried to remove bearking, but axle will not go back far enough as it was hitting on struts.	30/11/2020	Hours
	15782	Hours 11999 Continue with rear A Frame bearing.	27/11/2020	Hours
	15783	Pre hire repairs - clean up bay	26/11/2020	Hours

Asset	W/O No	Description	Finished	Done Reading
	15784	Hours 11999 Finish ordering parts for 773's Clean up work area Bring machine into work area & set up for A frame removal Start to removal A Frame	25/11/2020	Hours
	15785	Jump start Check over	24/11/2020	Hours
	15786	Gas up struts	23/09/2020	Hours
	15787	Hours 11691 Find hyd leak. Remove and replace hyd hose.	22/01/2018	Hours
	15789	Hours 11542 Remove and replace access steps	13/12/2017	Hours
	15788	Hours 11542 Remove and replace access steps	13/12/2017	Hours
	15790	Hours 11381 Fit walkway, eyebroes, mirrors, hook up wiring.	8/10/2017	Hours
	15791	HOurs 11381 Fit and adjust mirrors, pump up front struts, fit strut guards	29/09/2017	Hours
	15792	Fit walkways and check over	14/09/2017	Hours
	15793	Strip for transport	24/10/2016	Hours
	15794	Hours 11251 Carry out engine service Check over machine Grease	27/09/2016	Hours
	15795	Hours 11242 Replace hose	23/09/2016	Hours
	15796	Diagnose and repair speed sensor fault	12/09/2016	Hours
	15797	Hose and top up oil Grease	25/08/2016	Hours
	15798	Replace mirror window rock ejector check over	18/08/2016	Hours
	15799	Carry out 1000hr service. Replace rock ejector	10/08/2016	Hours
	15800	Replace POS 2 brake pads	9/08/2016	Hours
	15801	Hours 10999 Carry out service, grease and check over	5/08/2016	Hours

Asset	W/O No	Description	Finished	Done Reading
	15920	Hours 10869 - repair coolant leak, top up trans oil.	15/07/2016	Hours
	15921	10689 Hours - help with POS4 tyre	14/07/2016	Hours
	15922	10689 Hours - replace u/h LH armrest	14/06/2016	Hours
	15923	Repair tub	1/06/2016	Hours
	15924	Check over for new contract, resecure fire suppression control box.	17/05/2016	Hours
	15925	10551 Hours Change engine oil and filters, fuel filters and outer air filters. Repair lights check over.	5/05/2016	Hours
	15926	Repairs to hungry boards	7/04/2016	Hours
	15927	Hours 10328 Fit on to lift cylinder, couldn't get pin to go through bearing cleaned up holes fit mudflap.	17/03/2016	Hours
	15928	Carry out pin in lift cylinder. Remove bearing. Remove exhaust manifold and drill out broken stud. Fit manifold.	10/03/2016	Hours
	15929	Replace mirror and mirror bracket	22/02/2016	Hours
	15930	Hours 10143 Replace missing step. Replace u/s alt belts.	11/02/2016	Hours
	15931	Hours 10143 Check over and start	10/02/2016	Hours
	15932	Hours 10016 Carry out 1000hr service as manufacturers recommendations	7/01/2016	Hours
	15933	Replace fan hub bolt.	5/01/2016	Hours
	15934	Hours 9961 Remove POS 1 wheel, replace brake pads Replace left handed steer ram, ball joint.	22/12/2015	Hours
	15935	Hours 9701 Check A/C	1/12/2015	Hours
	15936	Hours 9547 Completed 500hr service as manufacturer recommends	12/11/2015	Hours
	15937	Hours 9346 Check fault codes, test drive	22/10/2015	Hours
	15939	Hours 9044 Carry out 1000hr service as per manufacturers recommendations. Change engine oil, filters. Fuel filters, inner and outer air cleaners, change trans oil, filter, check screens, replace pilot filters, replace steer filters. Check front hub bungs diff and final drive bungs.	24/09/2015	Hours
	15944	Hours 8966	20/09/2015	Hours

Asset	W/O No	Description	Finished	Done Reading
		Fit and tension POS3,5,6 wheels and pump up to 90psi.		
	15945	Unloaded tyre & bucket from truck. Changed out POS 4 tyre with new & inflated.	18/09/2015	Hours
	15946	Replace POS 4 wheel	16/09/2015	Hours
	15953	Hours 8922 Replace body up switch	14/09/2015	Hours
	15954	Replace front step, repair lights, repair tub up sensor	10/09/2015	Hours
	15955	Hours 8847 Replace bent pos 5/6 wheel	8/09/2015	Hours
	15956	Hours 8842 Check faulty tub up sensor	7/09/2015	Hours
	15957	Hours 8827 Inspected reverse fault. Checked all wiring and reconnected	3/09/2015	Hours
	15959	Hours 8564 - Carry out 500hr service as per manufacturer recommendations	12/08/2015	Hours
	15958	Hours 8564 Change out POS 4 wheel end	12/08/2015	Hours
	15960	Hours 8487 Replace pos5 wheel & tension Replace LH mudflaps	5/08/2015	Hours
	15962	Hours 8451 Cut out RH lift cyl pin, replace pin and bearing, pump up POS 5 tyre.	3/08/2015	Hours
	15961	Repair hyd leak at tank. Replace final drive oils and cab filters	3/08/2015	Hours
	15963	Inflated POS 5 tyre, checked over truck	27/07/2015	Hours
	15964	Hours 8429 - Change out POS 3 tyre and tension	24/07/2015	Hours
	15965	Hours 8369 Change out POS 6 tyre and tension	21/07/2015	Hours
	15966	Hours 8358 Change out POS 5 tyres.	15/07/2015	Hours
	15968	Hours 8088 Fitted hungry boards	4/07/2015	Hours
	15967	Hours 8270 Check over and grease	3/07/2015	Hours
	15970	Hours 8088 Fit clamps to rear strut socks, tyre report and pressures. Finish off pre hire report. Topped up washer fluid, clean out cab, re	1/06/2015	Hours

Asset	W/O No	Description	Finished	Done Reading
		-fit seat cover, replace fittings on intake, refit engine covers.		
	15969	Hours 8088 Completed remainder of valve set. Carried out pre-hire with Dustin.	1/06/2015	Hours
	15973	Hours 8088 Complete valve set Repair front steps. Assisted in started motor fitment.	29/05/2015	Hours
	15972	Hours 8088 - Topped up hydraulic oil, removed rocker covers, removed injectors and replaces seals. Refitted all rocker covers, fit rear strut socks, started pre-hire report.	29/05/2015	Hours
	15971	Hours 8088 Purle rear struts with oil, gas front and rear struts to spec height.	29/05/2015	Hours
	15974	Hours 8088 - carried out check over, re-tag extinguishers. installed UHF	28/05/2015	Hours
	15975	Fill rear struts with oil to spec.	7/01/2015	Hours
	15976	Remove bearings and replace in struts, fit struts.	10/12/2014	Hours
	15977	Hours 8084 - replace trans hose	5/12/2014	Hours
	15978	Hours 8084 Straighten and fit wheel chock bracket.	4/12/2014	Hours
	15979	Hours 8084 Get broken bolts out of wheel chock bracket, replace clamp on intake pipe, replace headlight. Remove rear struts.	26/11/2014	Hours
	15980	Check over machine	16/10/2014	Hours
	15981	Hours 8028 - replace air cleaners	30/09/2014	Hours
	15982	Change trans/torque converter oil & filter & check screen. Check diff bung. Replace front hub oils. Replace hyd filters. Replace steer oil & filters. Replace inner and outer cab filters. Replaced trans & diff breathers.	26/09/2014	Hours
	15983	Start 2000hr service. Change engine oil, filters, fuel filter. Blow out air filters.	21/09/2014	Hours
	15984	Hours 7842 - Bleed fuel system and start	13/08/2014	Hours
	15985	Turn RH step upside down and fit chain across handrail.	7/08/2014	Hours
	15986	Hours 7725 Fit fuse to flashing light wiring.	21/07/2014	Hours
	15987	Hours 7654 - fit flashing light to machine	7/07/2014	Hours
	15989	Fab flashing light brackets.	4/07/2014	Hours
	15990	500hr Service - Change engine oil and filters/fuel filters/air cleaners, clean cab filters, check over.	23/06/2014	Hours

Asset	W/O No	Description	Finished	Done Reading
	15991	Hours - 7543 Replace broken steps, bent brackets and step rubbers.	12/06/2014	Hours
	15992	No start - bleed fuel system and start.	27/05/2014	Hours
	15993	Hours 7409 Oil and gas rear struts	15/05/2014	Hours
	15994	Hours 7409 Re-seal RHR strut.	14/05/2014	Hours
	15995	Check strut, suspect oil bleed leaking, loosen and retighten. Clean and re-inspect.	12/05/2014	Hours
	15996	Order seal kit for RHR strut after receiving call on the way home that it was leaking	2/05/2014	Hours
	15997	Oil & gas front & rear struts as required. Check lights. Replace e-stop. Top up oils. Check over ready for work.	28/04/2014	Hours
	15998	SSwap tyres between P282 & P302 & P281	27/03/2014	Hours
	15999	Hrs 7347 Charge front struts - take height to 170mm attempt to get hand rails out.	26/03/2014	Hours
	16000	Hours 7346 Check over, carry out defect list. Fit wheel chocks. Tag fire suppression. Tighten fire suppression bolts.	20/03/2014	Hours
	16002	Hours 7346 Replace 2x rubber strap on steps and replace steel tag, fire extinguisher and fire suppression. Clean out LH inner front headlight as it was dull. Check over machine.	19/03/2014	Hours
	16006	Hours 7346 Carry out defect list of repairs to be done	18/03/2014	Hours
	16007	Hours 7345 Fit new bar and squarker	15/03/2014	Hours
	16008	Fabricate hungry boards	17/02/2014	Hours
	16010	Hours 7250 Change speed sensors, fit mirror, check over machine.	6/02/2014	Hours
	16009	Hours 7242 - Seat fault broken, earth wire and remote start fault. Broken switch at LH step.	6/02/2014	Hours
	16011	Hours 7108 Check out engine fault light, Remote shutdown switch & bracket missing - on order.	29/01/2014	Hours
	16012	Fit mirrors	27/01/2014	Hours
	16013	Change mirrors	26/01/2014	Hours
	16014	Hours 7083 - Finish off 1000 hr service and clean up area.	20/01/2014	Hours

Asset	W/O No	Description	Finished	Done Reading
	16015	Hours 7083 Carry out 1000 hr service.	19/01/2014	Hours
	16016	Shutdown fault - e-stop got hit with dirt	3/01/2014	Hours
	16017	Hours 6905 Diagnose hoist fault coming down slow.	1/01/2014	Hours
	16020	Hours 6880 Replace batteries	30/12/2013	Hours
	16019	Hours 6878 Check start problem, connect ET no codes - primed up fuel and machine started.	30/12/2013	Hours
	16018	Hours 6880 Replace batteries	30/12/2013	Hours
	16021	Hours 6838 Get hyd oil from workshop and fill.	22/12/2013	Hours
	16022	Hours 6803 Reseal leaking fittings on tranny filters. Check for leak, OK. Top up A/C gas & check operation. OK.	17/12/2013	Hours
	16023	Hours 6803 - Fit walkway/stairs/mudflaps and eyebrows	9/12/2013	Hours
	16024	Strip down for transport.	10/10/2013	Hours
	16025	Change out all drive belts	12/09/2013	Hours
	16052	Hours 6689 Jump start truck. R&R batteries	28/08/2013	Hours
	16054	Hours 6687 Checked all front steering/suspension for noise. Topped up strut gas.	26/08/2013	Hours
	16056	Hours 6516 Carry out 250hr service	20/07/2013	Hours
	16057	Hours 6393 Repaired POS1 tyre. Put repaired tyre on POS3 and POS 3 onto POS1.	30/06/2013	Hours
	16058	Hours 6380 Removed bent rock ejector and replaced with ejector.	29/06/2013	Hours
	16059	Hours 6381 Jump started truck. Checked alternator charging. Checked driveline uni joint for vibration.	27/06/2013	Hours
	16060	Blown main hyd hose. Remove hose, Remove hose from P122 and fit to P262 Start machine lower> And more machine off wall out of walk area.	26/06/2013	Hours
	16061	Hours 6335 250 hr service.	20/06/2013	Hours

Asset	W/O No	Description	Finished	Done Reading
	16062	Hours 6238 Inspect tub up hydraulics. Checked all wiring, intermittant tub fault.	2/06/2013	Hours
	16063	Hours 6100 Starting issues, diagnose fuel issue.	15/05/2013	Hours
	16064	Hours 6065 Bleed up fuel system	29/04/2013	Hours
	16065	Hours 6064 6000hr service.	28/04/2013	Hours
	16066	Reset snub positon	27/04/2013	Hours
	16067	Hours 5878 Reset snub position on tub.	20/03/2013	Hours
	16068	Hours 5849 Replaced e-stop	14/03/2013	Hours
	16069	Hours 5817 Top steer and hyd oil check over	9/03/2013	Hours
	16070	Hours 5782 Truck no start, end up being burnt out start isolator. Changed out isolator, all OK.	27/02/2013	Hours
	16071	Hours 5782 Carry out 250hr service	25/02/2013	Hours
	16073	Hours 5513 Fit bracket & assemble grease blocks to bracket with fittings & nipples. Connected hoses & secured.	10/12/2012	Hours
	16072	Fit up steering grease lines.	10/12/2012	Hours
	16221	Hours 5490 Carry out 500hr service and inspection Checked a/c system. OK. Tub slow to drop. Will need re-callibrating. Drained containers & sorted filters. Took grease pump to truck and greased. Cleaned grease & oil off truck.	5/12/2012	Hours
	16223	Hours 5481 Chock missing. Service Due 5500 hours	3/12/2012	Hours
	16224	Hours 5361 Found missing coolant as water pump intake hose leaking coolant. Tighten clamps and topped up with coolant, pre-start inspection done.	8/11/2012	Hours
	16225	Hours 5336 Check over and grease	29/10/2012	Hours

Asset	W/O No	Description	Finished	Done Reading
	16226	Hours 5293 Fit up wheel choc bracket	22/10/2012	Hours
	16227	Hours 5285 Change out damaged step rubber	21/10/2012	Hours
	16228	Hours 527 Finish off 250hr service, fit up window pins to 2 windows.	18/10/2012	Hours
	16229	Hours 5272 250 Hour Service	17/10/2012	Hours
	16231	Hours 5254 Complaint that transmission not changing gears properly, went to workshop and checked board for trans service overdue, took filters back, changed filters and checked screen in torque converter. OK. Service truck too busy to top up oil, sourced trans oil from workshop and filled up. Test OK. Hoist valve good.	14/10/2012	Hours
	16230	Hours 5254 MIA tub wont go down, checked operation of dump body OK.	14/10/2012	Hours
	16234	Hours 5237 Inspections and fire extinguishers.	11/10/2012	Hours
	16235	Slow hoist operation. Checked pressures and times and adjusted. Reflashed ECM and calibrated.	23/09/2012	Hours
	16236	Hours 5143 1000hr service Fitted boots to struts. Checked faults in pre-start book Checked horn. Checked seat belt. Fitted march 09.	21/09/2012	Hours
	16237	Hours 5144 1000 hour service	20/09/2012	Hours
	16238	Adjusted rear camera, new fuel filters, cleared codes & check fuel pressure, drain sediment from tank.	19/08/2012	Hours
	16239	Hours 4789 - 250 hour service	13/07/2012	Hours
	16240	Stamp rims.	3/06/2012	Hours
	16241	Fit all stickers	1/06/2012	Hours
	16242	Top up hyd/steering oil tank levels, check all fluids and all work carried out was completed, make brackets to lower two front steps under/to required height.	31/05/2012	Hours
	16245	Fit all stickers, apply radiator caps	30/05/2012	Hours
	16244	Fit up product link and sink into truck, fit up POS ID signage.	30/05/2012	Hours
	16248	Fit all mudflaps, floor mat, stickers, wheel chock holder, place dash back into place, apply 2x turbo covers, mirrors.	29/05/2012	Hours

Asset	W/O No	Description	Finished	Done Reading
	16247	Pump up struts and tie back any loose wiring.	29/05/2012	Hours
	16250	Unload truck, dry assemble deflector guards	28/05/2012	Hours
	16249	Dry assemble guards, mud guards etc	28/05/2012	Hours
	16251	Fit up reverse camera, make up camera harness, oxy out tags in rear of tub. Crane in gear in tub for transport.	15/05/2012	Hours
	16254	Assemble 773	24/04/2012	Hours
	16255	Hours 4569 Torque up rear outer wheel nuts. Prepare hand rails for painting. Strip down rear strut for repairs.	23/04/2012	Hours
	16256	Hours 4569 Remove seizel rh rear strut and strip down	21/04/2012	Hours