Work Order History Report

Asset	W/O No	Description	Finished	Done Reading	
P0283		**Cat 773F Dump Truck**			
	60001	January/February R&M Replace rear tyre Lance rear suspension pins Replace both rear struts (Removed struts from machine in Dubbo - sent to site) Replace seat belt. Replace rear tyre - supplied from Dubbo. Shim body pads. Replace blown hose. 6 MONTHLY FIRE SUPPRESSION TEST/INSPECTION.	12/02/2026		Hours
	58762	November R&M - Hand rail repairs - Hyd leak, fill with hyd oil - Replaced leaking hose, swapped filter housing - Pump up both rear struts, tighten both front rack deflectors - Set vehicle speed limit - Shift fault, electrical issues, water ingress in plugs - Codes on dash, checked all trans plugs cleaned, - Resecured harness	30/01/2026		Hours
	59415	December R&M Electrical faults RH rear strut, lower pin seized. Book CJM for lance removal. Brake fault, charge brake accumulator. Replace speed sensor. Replace blown hose	17/12/2025		Hours
	56169	Rigid Dump Truck - 500hr Service 15262hrs - 15617 hrs Repair radio. Weld repairs to guard. Repair horn. Adjust strut ride height. Repair RH headlight wiring.	17/11/2025	15617	Hours
	56746	Rigid Dump Truck - 250hr Service. Lake Cowal	7/11/2025		Hours

58154	October R&M - Replace camera - Top up oil	28/10/2025	Hours

Asset	W/O No	Description	Finished	Done Reading
	57294	September R&M - Guage on dash not working correctly, Tested sensor, ordered parts - Replace T/Q oil temp sensor - Repair A/C electrical - Customer had concern of truck no starting, Isolator was found to be off, Turned start isolator on and started machine all ok - inspect hyd leak , removed hose to repair - fit hyd hose - repair hyd leak	25/09/2025	Hours
	56799	August Monthly R&M - 5 yearly suppression and fire extinguisher service - No start primed fuel. Removed springs from fuel valve and lengthened - tested all good - Repair hyd leak on hoist filter housing - high t/q alarm, drained oil. Inspected sensor, faulty, sensor ordered. 31/08	31/08/2025	Hours
	56289	July - Monthly R&M - Grease machine - Replace oring in hydraulic cap. Show operator around truck for prestart - No start. Chase fuel issue. Over ride primer pump and got going. Suspect transfer pump - Move steps and mirror - Fit radio	30/07/2025	Hours
	54973	Fit tyres. Prep for Lake Cowal (CMC. FFP). - Remove rhs steer cylinder & reseal - Replace Y link and bushes, clean cab, R+R safety stickers, straighten exhaust tip - R+R maas stickers R+R safety stickers, R+R hi-vis tape - FULCRUM photos, Maas & Lake Cowal paperwork - Hi-vis stickers . Wash clean cab, clean windows, paperwork, FULCRUM, full fuel - Replace Y link bushes and pin. Order parts. Fit new plant numbers. Remove old stickers. - Fit steer cylinder. Fit new window on cab. Paint front of tub. Fit maas stickers. Grease. Replace quick fill. - Repair alloy window frame	10/07/2025	Hours
	52700	Inspect for defects - report to Nathan (Bedford Weir) Fab and fit hungry boards to Tray. Workshop clean up, install steer cylinder Fire suppression - test Remove rhs steer cyl Check wiring TFO tracker - stopped reporting Replace missing wheel chock	7/07/2025	Hours

Asset	W/O No	Description	Finished	Done Reading	
		Replace missing A/C test port covers Replace brake pressure switch behind the Hyd tank Straighten up bent exhaust tip Replace circuit breaker door on front of truck Replace centre steer pivot pin/bearings Replace damaged wheel chock Repair cab door frame, fit glass Clean cab Check, tag and bag fire extinguisher Fill washer bottle Replace front brake switch on dash Fit safety stickers as required Remove Maas stickers Fit thinksafe, QR stickers if required Replace Plant ID sticker Remove old client stickers Replace quick fill receiver Replace o'rings on lines to transmission, starting to leak Replace broken diff breather Top up steer oil Reseal RH steer cylinder USO spec Fulcrum on hire photos Maas paperwork			
	50411	Rectify AC fault and replace batteries Investigate AC fault. Find compressor leaking. De-gas and replace compressor. Hose blew as re-gassing. Supply & fit new hose from compressor to condenser. Gas up and test system - all appears okay at time of test.	11/01/2025		Hours
	49556	14926 FFP repairs (Pre-Hire) Check machine over, remove and link, clean components, order parts, inspect and link pin/bush condition Remove steering link, clean up, order parts Replace drag link spindle pin and bushes, replace grease line fittings, grease machine, replace brake pressure sensor and test Replace transmission lines, O-rings and one broken half clamp Wash truck Fill up fuel - on hire Park machine for float hire access, on hire photos, fuel machine	3/11/2024	15953	Hours

Asset	W/O No	Description	Finished	Done Reading	
	11279	Inspection	25/04/2024	14924	Hours
	12496	2x 24.00R35 used Tyres missed on work order 7085	18/03/2024		Hours
	9893	De- Mobilisation Hours - 15953	4/03/2024		Hours
	9046	Diagnose Hydraulic leak. Cracked fittings between hydraulic filters.	25/01/2024	14920	Hours
	8648	Tub Inspection & Material Ordering Check over machine fixing minor defects during down time Replace Oring on final drive. Repair RHS step light not working due to wiring fault. Replace reverse alarm.	11/01/2024	14879	Hours
	8327	Rigid Dump Truck - 250hr Service	8/01/2024	14750	Hours
	8008	Replace blown o ring on hydraulic hose. replaced all o rings that required changing.	11/12/2023	14653	Hours
	7956	Investigate AC system blowing hot air. Connect gauges and check pressures and went through system. Replaced compressor and dryer. Charge with gas and test system. Charge system with AC gas and check operation.	10/12/2023	14642	Hours
	7530	Check over machine as required. One Light required - ordered. Check operation of steering column actuator. All ok.	3/12/2023	14603	Hours
	7230	Remove and replace Pos4 tyre valve, and topped up pressure as necessary. Valve had been hit by rocks, and snapped. Replaced suction hose, o-ring and clamps as per previously diagnosed. Topped up with oil, and carried out running checks- all OK. Suction hose o-ring blown. Hose too stiff to remove. Cut out and replace hose, o-ring, and clamps. Made parts list, and ordered as required.	19/11/2023	14601	Hours
	7173	Diagnosed alternator as faulty. Removed and replaced alternator as required. Removed Pos 4 valve stem cover, and valve stem due to =damage. New one to be sourced.	16/11/2023	14601	Hours
	7085	Travel to Cloncurry from Rocklands site and collect 2 x new front tyres Replace front two steer tyres	15/11/2023	14601	Hours
	5821	Rigid Dump Truck - 500hr Service	20/10/2023	14595	Hours
	5585	Set road speed to 40kph Rewire and repair aerial	21/09/2023	14464	Hours
	4786	Pre hire repairs	26/08/2023	14374	Hours

Asset	W/O No	Description	Finished	Done Reading	
	2556	Additional Parts - missed inv Off hire repairs LH hoist top bearing line bored, reseal head POS 4 strut reseal, rod end line bored, replaced bearings Replace both L&R tie rod end ball studs Replace both outer ball studs of steer cylinders Replace brake cooling hose Fit new asset ID numbers Stamped rims for tyre register Fit number plates Weld up fire suppression mount plate Washed	14/07/2023	14370	Hours
	3889	Strip hydraulic tank, replace sight glass seals. Repair broken return screen pipe - broken off. Clean and put back together. Fit cooling hoses.	1/07/2023		Hours
	3888	Fit bearing to A frame torque nut and fit new lock bolt and keeper. Join A frame back to truck. Fit new genuine pin	30/06/2023		Hours
	3887	Remove hoses and harnesses. Remove pin, found nut "loose" on A frame bearing pre-load. Split A frame. Removed bearing and inspected	28/06/2023		Hours
	3886	Move truck, jack up, start A frame job. Remove dog bone and top strut pins	27/06/2023		Hours
	3885	Assemble LHS hoist cylinder after repairs, fit to machine. Fit bearing RHS Hoist cylinder barrel end. Fit back on body	26/06/2023		Hours
	4105	Reseal hydraulic tank, fit back together, fill up hydraulics.	21/06/2023		Hours
	4103	Weld up broken return in hydraulic tank.	20/06/2023		Hours
	4102	Oil leaks from hoist valve. Drain Hydraulic oil for hydraulic reseal.	19/06/2023		Hours
	16263	Hours 14363 Chassis cracks - Move truck and fire supression hoses for boily to weld crack under cab. Jump start and charge batteries from my truck to start.	27/03/2023		Hours
	16264	Hours 14363 Check over/fit 2 ways.	20/03/2023		Hours
	16268	Off hire paperwork	16/01/2023		Hours

Asset	W/O No	Description	Finished	Done Reading
	16322	Take out 2 way	22/12/2022	Hours
	16269	Horn failed, very quiet. Still works Cab windows failed, needs new seal on door glass. Step rubber torn, move step up to the other holes.	8/12/2022	Hours
	16278	Hours 14228 Replace door seals, remove doors, remove old door seals fit new door seals.	5/12/2022	Hours
	16272	Service brake test failed, accumulator needs attention, fitter aware - Resealed Tyres- condition/wheel nuts (visual inspection). Failed - chunks out of tyre tread from rock, all wheels.Safe to operate. Suspension condition (visual inspection) failed - noise from front right side when traversing rougher surfaces.	5/12/2022	Hours
	16279	Hours 14227 250 hr service	22/11/2022	Hours
	16291	Hours 14234 CPB monthly inspection	4/10/2022	Hours
	16286	Hours 14118 Work out new system for wheel chokes mount. Rope not approved. Fit new strap - fit strap to chocks and check fire extinguisher. Put straps over all trucks. Strap wheel chokes, P1137, P1136,P291.	4/10/2022	Hours
	16319	Pre start defects Warning light on - warning only on start up. Goes away after brake accumulators build pressure. Wiper blades need replacing. Replaced wiper blades.	18/08/2022	Hours
	16300	Hours 13985 1000 hr service	18/08/2022	Hours
	16323	Reseal pipes hoses to brake accumulators. Charge brake accumulators.	13/08/2022	Hours
	16324	Hours 13977 Carry out 250hr service and checks	12/08/2022	Hours
	16325	Hours 13971	11/08/2022	Hours

Asset	W/O No	Description	Finished	Done Reading
		Fit venturi to hyd tank Replace brake tank sensor Remove tooling		
	16326	Hours 13954 Brake oil temp code coming up Check sensor Check harness Check plugs Sensor US.	9/08/2022	Hours
	16328	Hours 13909 CPB monthly check	6/07/2022	Hours
	16313	Brake oil pressure temp high alarm on when starting truck. Replaced brake temp sensor.	28/06/2022	Hours
	16329	Hours 13829 Locate truck 2 way not working, replace and fir new ariel plug on solder on, wires torn out.	15/06/2022	Hours
	16331	Hours 13761 Complete 250hr service	21/04/2022	Hours
	16330	Hours 13761 Complete 250 hour service.	21/04/2022	Hours
	16314	13754 Hours - 250 hour service	21/04/2022	Hours
	16332	Hours 13698 Complete CPB monthly	6/04/2022	Hours
	16317	Fire extinguisher failed plastic tag. fire suppression due. Checked fire suppression tag. Currently in date.	30/03/2022	Hours
	16334	Hours 13614 Fit UHF radio Solder new power cord in	24/01/2022	Hours
	16335	Install TFO tracker Remove NPM tracker Replace front lights Repair wiring	16/10/2021	Hours
	16357	Hours 12892 GAS AC	28/08/2021	Hours

Asset	W/O No	Description	Finished	Done Reading
	16336	Hours 13229 Truck not starting Checked e-stops Found faulty isolator Replaced isolator - started truck	22/07/2021	Hours
	16337	Hours 13302 Complete FFP inspection Repaired front e-stop	13/07/2021	Hours
	16338	Hours 13106 FFP checks and repairs	11/06/2021	Hours
	16340	Hours 13085 R&R step assembly	9/06/2021	Hours
	16341	Hours 13054 Fit POS 6 tyre Fit new seat compressor	3/06/2021	Hours
	16342	Hours 13054 Fit POS 5 tyre	2/06/2021	Hours
	16345	Hours 13054 Fit new duo seals RHR final	1/06/2021	Hours
	16344	Hours 13054 Set track up for RH seal change. Remove RH rubber and rims. Remove cover plate and carrier. Remove ring gear. Remove hub. Remove seals, inspected bearings. Fitted new duo seals. Fitted hub. Performed bearing adjustment. Fitted ring gear, carrier, Cover plate. Tyres to be filled later.	1/06/2021	Hours
	16346	Hours 13042 Steering fault, cleaned steer sensor & solenoid. Replaced leaking heating star hose from pump. Top up oil. Test drove OK. Repaired front step rubbers.	28/05/2021	Hours
	16348	Hours 13023 Complete 1000hr service Trans filters, hydraulic filters, remove hyd brake filter housings. Remove all fitting. Cleaned - replaced O rings. Fitted housing with new filters. Topped up hyd oil	25/05/2021	Hours
	16347	Hours 13026 1000 hour service	25/05/2021	Hours
	16351	Hours 1298 Assist with removal of tyres	14/05/2021	Hours
	16352	Hours 12992 Complete part of 1000hr service as required.	13/05/2021	Hours
	16353	Hours 12981 Pump up POS 5 tyres, check all others.	12/05/2021	Hours

Asset	W/O No	Description	Finished	Done Reading
	16354	HOurs 12967 Carry out diagnostic checks and change all machines to 40km p/h	10/05/2021	Hours
	16355	Hours 129667 Weld and repair mounts and supports under fire supression.	9/05/2021	Hours
	16356	Hours 12948 Repair a/c compressor wiring.	4/05/2021	Hours
	16358	Hours 12880 Clean trans electrical plugs	27/04/2021	Hours
	16359	Hours 12849 Check strut pressures.	19/04/2021	Hours
	16360	Hours 12790 Grease	17/04/2021	Hours
	16361	Hours 12749 Fit fuel cap. Adjust mirrors	5/04/2021	Hours
	16362	Hours 12724 - Grease	1/04/2021	Hours
	16364	Hours 12720 250 hr service. FFP paperwork. Grease	30/03/2021	Hours
	16365	Refit fire supression valve	17/02/2021	Hours
	16370	Hours 12655 Retarder fault. Find fault. Swap out solenoid valve	3/02/2021	Hours
	16372	Hours 12655 Gas rear struts Reseal tranny suction and broke filter lines Fill steer oil	2/02/2021	Hours
	16375	Sleeve hoses Fit reflective tape Fit safety stickers	22/01/2021	Hours
	16376	Remove clamps for steering	21/01/2021	Hours
	16377	FFP for NPM	20/01/2021	Hours

Asset	W/O No	Description	Finished	Done Reading
	16379	Hours 12663 Install handrails and mirrors	12/01/2021	Hours
	16378	Fit handrails. Weld on new extinguisher brackets. Fit safety decals.	12/01/2021	Hours
	16380	Hours 12663 Hydraulic sleeving Fit terminal covers where needed Tidy battery lock Fit safety stickers North Parkes FFP, sleeve hosing with burst protection	11/01/2021	Hours
	16382	Fit hydraulic sleeving Refit clamps on hoses	9/01/2021	Hours
	16383	Hours 12663 North Parkes FFP Fitted boots to electrical terminals	8/01/2021	Hours
	16385	Hours 12663 Test fire suppression and remove bottle for testing	6/01/2021	Hours
	16387	Remove hand rails/take to paint bay	5/01/2021	Hours
	16390	Cover missed fuel lines in burst protection	17/12/2020	Hours
	16391	Removed damaged fuel line Insulate fuel lines Prime up fuel	16/12/2020	Hours
	16393	Cover fuel lines in burst protection	15/12/2020	Hours
	16396	Paint touch up Hand rails	11/12/2020	Hours
	16398	Front bumper Hand rails Repair bumper - Agriweld	9/12/2020	Hours
	16475	Install rear liner in tub back	8/12/2020	Hours
	16401	Mud guard Fire supression repairs Air leak	8/12/2020	Hours

Asset	W/O No	Description	Finished	Done Reading
	16476	Bulb repair Tub reline	7/12/2020	Hours
	16477	Install new arm rest Fill hydraulic oil Install new isolator stickers Grease	4/12/2020	Hours
	16479	Replace o-rings in filter housing behind cab. Fit new seat base. Assemble seat.	28/11/2020	Hours
	16482	Replace inner ball joint - was very tight Clean filter housing behind cab to reseal Pull lid off RH ball joint and put grease seal in	27/11/2020	Hours
	16480	Hours 12662 Fit new hydraulic suction hose	27/11/2020	Hours
	16485	Replace steps. Remove seat and disassemble. Replace hoses. Replace fuel tank mount. Replace steer sensor. Diagnose steer fault.	26/11/2020	Hours
	16484	Replace x1 ball joint	26/11/2020	Hours
	16483	Hours 12662 Reseal starter Fit new exhaust pipe Fit hydraulic hose to lift block	26/11/2020	Hours
	16486	Hours 12662 Jump start machine Check over and do up defect list	24/11/2020	Hours
	16487	HOurs 12661 Start truck and check over	15/03/2020	Hours
	16488	HOurs 12655 Cleaned around hoist valve. Remove main hoses from pump clamps, and fitted new o-rings. Fitted hose and checked for leaks. OK.	3/12/2019	Hours
	16489	Hours 10514	19/10/2019	Hours

Asset	W/O No	Description	Finished	Done Reading
		250 hour service and greased		
	16490	HOurs 12422 Grease and general check over	29/09/2019	Hours
	16491	Hours 11105 Find oil leak, R&R O-Ring on filter housing	9/01/2018	Hours
	16493	Remove hyrdaulic pressure switch, renew O-ring, refit pressure switch.	17/10/2017	Hours
	16494	Pump up front struts	29/09/2017	Hours
	16495	Hours 11035 Fit fire extinguisher bracket	8/09/2017	Hours
	16496	Hours 11035 Replace faulty kill switch @ front bumper	7/09/2017	Hours
	16497	Hours 11033 Refit HMU and cover	10/08/2017	Hours
	16498	Hours 11033 Secure LH outer steer cylinder tie rod. Start fitting new HMU Remove steer pin LHS Fit new steer pin LHS	9/08/2017	Hours
	16499	Hours 11033 Fit new transmission suction hose Fill transmission oil	4/08/2017	Hours
	16501	Hours 11033 Remove transmission suction hose Change brake filters Check torque converter screen	3/08/2017	Hours
	16500	Changed brake coolant filters Resealed housing Resealed sensor on housing Tagged fire extinguisher Removed hose from cooler to torque converter and fitted new one Changed hyd filters Fitted wheel chocks	3/08/2017	Hours
	16506	Hours 11033 Complete and check over and organise parts	2/08/2017	Hours
	16505	Hours 11033 1000 hour service	2/08/2017	Hours
	16504	HOurs 11033 Change engine oil	2/08/2017	Hours

Asset	W/O No	Description	Finished	Done Reading
		Change engine oil filters Change fuel filters Check tranny screen Drain tranny Change tranny filter Remove HMU		
	16502	Fitted air cleaners Fitted cab filter Top up window washer	2/08/2017	Hours
	16507	HOurs 10979 Check fleet for first day back	9/01/2017	Hours
	16508	Hours 10934 Fit new flashing light	8/12/2016	Hours
	16510	Hours 10861 Load new tyres at workshop Escort tyre handler into haul circuit Close haul circuit Assist with removal/replacement of POS1 & 2 tyres	25/11/2016	Hours
	16509	Hours 10861 Jack and chocked Stripped and fitted 2x new 24.00R35 goodyear tyres to POS1&2. Inflated	25/11/2016	Hours
	16511	Hours 10861 Reported to have blown tyre Returned to site after loading jacks and blocking Travel to haul circuit, jacked and blocked machine in order to fit heavy edmo jack past blown tyre Organise replacement tyres with Scott Organise for steve childs to come to site to strip and fit Organise the above with Paul.	23/11/2016	Hours
	16512	Hours 10741 Pump oils and load filters Travel to machine Perform 250hr service Dispose of oils & filters	6/11/2016	Hours

Asset	W/O No	Description	Finished	Done Reading
	16515	Hours 10529 Unload tub Fit walkways, stairs, tub wings, mudguards etc	20/09/2016	Hours
	16516	Hours 10529 Unload P0283 then load P0192	16/09/2016	Hours
	16518	Hours 10527 Removed rest of sidewalk Put HMU guard on, fitted electrical cover on steer pump.	14/09/2016	Hours
	16517	Fuelled up machine, cleaned out cab, fit arm rest pad, removed platform and handrails for float, removed mirror, lowered struts (suspension) for float, filled out pre-hire paperwork for machine.	14/09/2016	Hours
	16522	Hours 10527 Dug dirt out from underneath and between wheel etc, painted side rails and wheel chock holders, washed machine, pulled side steps and platform off machine.	13/09/2016	Hours
	16521	Weld repairs.	13/09/2016	Hours
	16520	Washed machine and knocked off mud and cleaned cab, weld up handrails, checked over machine for cracks, painted handrails, removed eyebrows for float and steps, installed reflective tape.	13/09/2016	Hours
	16519	Welding repairs	13/09/2016	Hours
	16524	Weld repairs	12/09/2016	Hours
	16523	Removed RH lift cylinder pin - got welder to lance out, remove bush from ram, installed new bush and spaces, fit cylinder back to tub installed pin, install/fit handrails, repaired CD played, installed rubber over batteries.	12/09/2016	Hours
	16525	Installed emergency steer pump. Test solenoid on prelube. Test pre-lube pump. Find why pre-lube didnt work. Clean workshop.	9/09/2016	Hours
	16527	Hours 10528 Check over, replace button on front e-stop.	8/09/2016	Hours
	16526	Weld repairs Installed UHF E-stops repaired. Brake test. Clean work space. Removed emergency steering pump. Removed steer pump off 775E for parts. Changed out cab filters.	8/09/2016	Hours

Asset	W/O No	Description	Finished	Done Reading
	16530	Hours 10528 Tried to press out tub pin. Fit seal kit to HMU	7/09/2016	Hours
	16529	Pre hire inspection. Remove steer column strut and re-assemble. Clean work area. Tried to remove top pin on lift cylinder (seized, fordy to lance). Tyre report. Checked for defects.	7/09/2016	Hours
	16528	Hours 10527 Tried to get lift cylinder pin out. Realigned hand rails.	7/09/2016	Hours
	16534	Hours 10527 Filled window washer fluid, wheel chocks fitted. Bend wheel chock brackets back. Straightened exhaust. Straightened guard. Pulled steering apart.	6/09/2016	Hours
	16532	Remove/replaced tie rod end and steer cylinder ball joints, tensioned, tested, re tensioned. Removed HMU and ordered seal kit. Started removal of top pin on RHS lift cylinder. Assisted Kev with front step.	6/09/2016	Hours
	16531	Straighten POS 2 step and guard	6/09/2016	Hours
	16576	Hungry boards	30/06/2016	Hours
	16535	Hours 10494 Change engine oil and filters, fuel filters and outer air filters. Check machine over.	16/06/2016	Hours
	16538	Hours 10486 Pressure test steering	14/06/2016	Hours
	16540	Hours 10486 Continue check/clean connections to transmission carry out clutch fill calibration	2/06/2016	Hours
	16541	Hours 10486 Check/clean wiring/ connections to transmission	1/06/2016	Hours
	16542	Check wiring for transmission fault.	31/05/2016	Hours
	16544	Hours 10476 Replace broken fuel tank e-stop, replace faulty starter isolator, diagnose us secondary steer motor and organise parts.	30/05/2016	Hours
	16545	Hours 10423 Change out broken mirror with P0301.	18/05/2016	Hours
	16546	Hours 10200 Replace faulty fuel tank sender, replace faulty low steering pressure sensor, replace faulty trans output speed sensor #1. Refit covers. Test drive.	7/04/2016	Hours

Asset	W/O No	Description	Finished	Done Reading
	16547	Hours 10173 Diagnose no power to low steer pump pressure sensor fault. Bridge out sensor dump load to test. All good. Order parts.	4/04/2016	Hours
	16548	Hours 10010 Carry out 1000hr service - Change engine oil and filter - Change fuel filters - Change air cleaners - Change transmission oil and filter - Check screens - Change brake filters - Change front hub oils - Change diff and final drive oils - Replace cab filters	4/03/2016	Hours
	16549	Hours 9855 Replace broken step rubbers, remove trans/hoist control assembley, remove broken transmission handpieces and replace, wire in re-fit trans hoist assy.	11/02/2016	Hours
	16550	Hours 9855 Check over and start	10/02/2016	Hours
	16551	Hours 9848 Fit large mirror	21/01/2016	Hours
	16552	Hours 9835 Removed POS 3 wheel, clean off mud, found leak out of valve on POS 4 replace valve and stem, pump up all good to fit POS 3.	19/01/2016	Hours
	16553	Hours 9835 Pump up POS 4 tyre, very slow to pump up. Couldn't find leak.	18/01/2016	Hours
	16554	Hours 9743 Reseal right hand rear strut	6/01/2016	Hours
	16555	Hours 9712 Check out steer pump pressure found switch to be faulty. Tighten up rear wheel nuts, repair fuel gauge.	5/01/2016	Hours
	16556	Replace brake cooling hose	23/12/2015	Hours
	16557	Hours 9714 Diagnose oil leak Top up hydraulic oil and send back to go line. Organise parts.	18/12/2015	Hours
	16558	Hours 9503 Change engine oil and fuel filters and outer air filters.	2/12/2015	Hours
	16559	Hours 9410 Replace transmission hose	24/11/2015	Hours
	16560	Hours 9137 Replace brake cooling hose, top up hydraulic oil	27/10/2015	Hours

Asset	W/O No	Description	Finished	Done Reading
	16561	Hours 9104 Check take P3, P4, P5 and P6 tyres to 90 PSI. Replace fan belts.	21/10/2015	Hours
	16562	Hours 9089 Cut and remove broken section of LH hungry board	20/10/2015	Hours
	16563	Hours 9004 Carry out engine service as manufacture recommends	9/10/2015	Hours
	16564	Struggle to dump Tested pressure only 2070psi Adjusted to 2750psi	10/09/2015	Hours
	16565	Hours 8632 Fit new lift cylinder bearing and pin, grease, bearing.	9/09/2015	Hours
	16566	Hours 8632 Cut out LH lift cylinder pin. Clean up cylinder. Grease machine, straighten front bumper.	7/09/2015	Hours
	16567	Remove rock from between tyres. Fit new rock ejector.	31/08/2015	Hours
	16568	Hours 8377 Change out POS 5 and 6 wheel Slow to pump up POS 5 wheel	18/08/2015	Hours
	16569	Finish 2000hr service Change front hub oil, check diff king and final drive kings, replace brake filter.	7/08/2015	Hours
	16570	Replace POS 4 and POS 5 wheel and tension.	5/08/2015	Hours
	16571	Hours 8073 Start 2000hr service as per manufacturers recommendations. Change engine oil, filter and fuel filters. Replace inner and outer air cleaners Replace trans filter and oil Replace brake filters.	23/07/2015	Hours
	16572	Adjusted mirrirs. Washed down fuel tank with water cart as it was covered in mud as mudflap damaged.	16/07/2015	Hours
	16573	Hours 8002 Finished off POS 4 fitment. Removed and replaced POS 4 tyre	15/07/2015	Hours
	16574	Hours 7982 Replaced transmission hose. Removed and replaced O-rings on brake filter housings. Greased and check over. Checked wheel nut tension. Adjusted tub down sensor.	10/07/2015	Hours
	16575	Hours 7905 Check over and grease	3/07/2015	Hours

Asset	W/O No	Description	Finished	Done Reading
	16577	Weld Repairs	22/06/2015	Hours
	16579	Hours 7807 Diagnose and repair fire suppression leak. Found valve in tank, all O-rings were u/s. Replace all and re-gassed all. Paper work completed.	12/06/2015	Hours
	16578	Hours 7884 Cut off step. Repaired fire suppression system. Resealed main shuttle valve head. Completed site paperwork.	12/06/2015	Hours
	16580	Hours 7883 Diagnose fire supression leak	11/06/2015	Hours
	16581	Hours 7883 Regassed/refilled fire supression. Fitted new front step. Topped up fuel. Refit POS 6 rim and tyre. Pre hire report.	10/06/2015	Hours
	16582	Hours 7883 Complete remainder of valve set. Complete site paperwork Adjusted strut heights.	9/06/2015	Hours
	16584	Hours 7883 Removed intake tubes removed all intake tubes, removed all rocker covers. Resealed injectors torque all wheels to 1500ft/lbs. Removed all steps and brackets from truck. Completed checkover and ordered parts.	5/06/2015	Hours
	16583	Hours 7883 REpaired bent steps. Completed valve set. Repaired mudflap. Tightened & replaced. Orings on brake filters	5/06/2015	Hours
	16585	Hours 7883 Removed all steps and guards from tub	4/06/2015	Hours
	16586	Fit new RH front bumper	18/02/2015	Hours
	16587	Remove POS 6 wheel, load onto trailer, take to marathons tyres.	11/12/2014	Hours
	16588	Hours 7878 Straighten mudguard LHS Remove RH bumpers	5/12/2014	Hours
	16589	Hours 7878 LHF brake pads.	3/12/2014	Hours
	16590	Hours 7878 Check over machine.	16/10/2014	Hours
	16591	Hours 7797 Repalce muffler	19/09/2014	Hours
	16592	Hours 7794 Check no start, remove hose from filter and back blow into tank, check F/W separator for sediment. OK. Bleed and start	12/09/2014	Hours

Asset	W/O No	Description	Finished	Done Reading
	16593	Hours 7770 Check why fire supression system activated, faulty muffler, bypass system and restart truck.	9/09/2014	Hours
	16594	Swap UHF handset	8/09/2014	Hours
	16595	Turn RH step upside down and fit chain across handrail	7/08/2014	Hours
	16596	Hours 7565 Fit fuse to flashing light wiring.	21/07/2014	Hours
	16601	Hours 7509 Escort tyre fitters to machine, stay with them while tyre was changed, tyre truck broke down so job took longer.	9/07/2014	Hours
	16603	Check which tyre was leaking, found loose wheel nuts on POS 6, tightened wheel nuts	8/07/2014	Hours
	16604	Hours 7504 Fit flashing light to machine	7/07/2014	Hours
	16605	Fab flashing light bracket	4/07/2014	Hours
	16606	Hours 7504 Change engine oil and filters, change fuel filters and bleed fuel system, check over machine.	3/07/2014	Hours
	16608	Hours 7392 Replace broken steps, bent brackets and step rubbers	12/06/2014	Hours
	16611	Oil and gas front and rear struts as required Check lights, Replace e-stop Top up oils. Check over ready for work	28/04/2014	Hours
	16612	Travel to gate 17 and continue assembly of machine	17/04/2014	Hours
	16607	Hours 7412 Replace RH lower mirror	17/04/2014	Hours
	16613	swap tyres from each truck P283 and P293 as per Scotts instructions.	26/03/2014	Hours
	16614	Hours 7193 Carry out check over list defects.Repair fault in LH inner high beam, adjust steering column. Tag fire supression.	20/03/2014	Hours
	16615	Remove walkways/eyebrows/stairs.	17/03/2014	Hours
	16617	Reseal starter motor	6/02/2014	Hours
	16618	6963 Hours Finish off 1000hr service, replace trans filter and oils, replace hydraulic filters and check plugs, blow cab filters out.	30/01/2014	Hours
	16619	Hours 6885 Chase up parts for service and start 1000 hr service.	23/01/2014	Hours

Asset	W/O No	Description	Finished	Done Reading
	16621	Fab hungry boards	22/01/2014	Hours
	16620	Hours 6883 Check and Charge AC	22/01/2014	Hours
	16623	Hours 6874 Fit missing rock ejector, check out retarded coming on then switch off.	21/01/2014	Hours
	16622	Check and gas AC	21/01/2014	Hours
	16624	R&R pos 4 tyre	8/01/2014	Hours
	16625	Hours 6731 Fit new batteries	3/01/2014	Hours
	16626	Jump start machine.	2/01/2014	Hours
	16627	Hours 6673 Fit up rock ejector. Refit rear right rock guard	29/12/2013	Hours
	16628	Hours 6661 Remove bent rock ejector	28/12/2013	Hours
	16629	Hours 6602 Defect list, reflective tape, unit numbers, segegrate wiring.	11/12/2013	Hours
	16630	Hours 6602 Diagnose and repair wiring to front light. Grease line segregation at rear of harness	10/12/2013	Hours
	16631	Pump up struts	9/12/2013	Hours
	16632	Fit walkway/stairs/mudflaps and yellow eyebrows	8/12/2013	Hours
	16633	Hours 6601 Fit new lower bearing and fit RH rear strut	20/11/2013	Hours
	16634	Hours 6601 Remove RH rear strut for machining repairs	15/11/2013	Hours
	16635	Hours 6601 Check over, segregate wiring/hosing/fire supression lines, replace fuel filter to all metal type. Remove unused monitor coaxial cables, fit site required decals, replace blown globe in RH lower work light.	13/11/2013	Hours
	16637	Hours 6476 Check over and change air filters	8/09/2013	Hours
	16638	Change out transmission filters	5/09/2013	Hours
	16639	Hours 6385 Carry out 250 hr service	1/09/2013	Hours

Asset	W/O No	Description	Finished	Done Reading
	16640	Hours 6302 250 hour service	15/08/2013	Hours
	16641	Hours 6270 250 hour service	6/08/2013	Hours
	16642	Hours 6128 Inspected oil leak from pump. Ordered parts for reseal	7/07/2013	Hours
	16643	Hours 6104 Removed rock from POS6 and POS5 tyres. Replace broken rock ejector	5/07/2013	Hours
	16644	Hours 6034 Topped up steer oil and coolant	26/06/2013	Hours
	16646	250 hour service Change out bent rock ejector Calibrate trans	23/06/2013	Hours
	16647	Hours 6005 Change out step rubber & bent wheel choc brackets	20/06/2013	Hours
	16649	Hours 5890 Replaced bent rock ejector	7/06/2013	Hours
	16650	HOurs 5913 Inspect harsh shifting from 4th gear Completed calibration on no 4 clutch pack	3/06/2013	Hours
	16652	Hours 5824 Fit up new batteries	15/05/2013	Hours
	16654	Hours 5824 250 hour service	14/05/2013	Hours
	16655	Hours 5796 Inspect 2 way operation, replace due to faulty operation	13/05/2013	Hours
	16658	Carry out 500 hr service	1/04/2013	Hours
	16659	Hours 5576 Change torn LH step rubbers	31/03/2013	Hours
	16667	Hours 5437 Steer oil top up and check over	9/03/2013	Hours
	16668	5418 hours Repair hydraulic oil leak on filter housing	6/03/2013	Hours
	16669	Hours 5306 Repair damaged steer pressure sensor wiring	10/02/2013	Hours

Asset	W/O No	Description	Finished	Done Reading
	16670	Hours 5253 250 Hours service as per service sheet	30/01/2013	Hours
	16671	Hours 5246 Inspection. 1 wheel chock missing. Tyre inspection	21/01/2013	Hours
	16672	Hours 5226 Replace tensioner spring and re-assemble fan belts. Check a/c vent temp. Came down to 1 loc at 60% humidity	14/01/2013	Hours
	16673	Hours 5173 Fit up grease lines to steering	10/12/2012	Hours
	16674	Hours 5143 Fix fire extinguisher brackets and recertify ext's. Make and fit grease hoses. Make and fit last 2 grease hoses and service.	4/12/2012	Hours
	16675	Hours 5143 Needs grease lines finished. Ext falling off.	3/12/2012	Hours
	16676	Assess grease system as to how plate for grease block should be mounted. Went to water truck	28/11/2012	Hours
	16677	Fit up remote grease system	25/11/2012	Hours
	16678	Hours 5011 Pre start inspection. OK	8/11/2012	Hours
	16679	Hours 5011 Finish off 1000 hour service. Top up fluids after start up, carry out running checks. Plan and start assembling grease system to steering system. Carry out wiggle checks and start making up grease hoses for steering.	2/11/2012	Hours
	16681	Hours 5011 Load parts to do service and missing fire ext brackets on RH step. Started service outside of w/shop. Changed engine air filters, cab air filters and had truck put in workshop. Changed primary air filters. Took oil samples & changed engine oil. Change torque converter oil & cleaned screen. Drain trans fluid and changed screen. Filled with fluid. Moved truck. Changed trans filter.	1/11/2012	Hours
	16680	Hours 5011 Organise and get truck to workshop and started 1000hr service	1/11/2012	Hours
	16685	Hours 5011 Replace broken brake pipe clamps on rear brakes. Cleaned out nuts and fitted additional bolt clamps. Tyre report. Note 1000 hour service due. Done at 4831 hours on 04/10/2012 Extinguisher missing. Remove broken fire extinguisher bracket clamp and return to workshop. Pick up parts.	31/10/2012	Hours
	16691	Hours 4900 Retarder sticking	24/10/2012	Hours
	16694	Set up hoist snub with ET	16/10/2012	Hours
	16695	Hours 4831 Change out LH step rubber that was damaged.	5/10/2012	Hours

Asset	W/O No	Description	Finished	Done Reading
	16699	Hours 4831 Carry out 250hr service - only oil/filters change to bring back into service line.	4/10/2012	Hours
	16698	Hours 4831 250 hour service replaced and bled primary and secondary fuel filters. replaced ac filter, filled washer bottle. Fitted grease nipple to top of RH rear strut and greased machine. Took engine oil sample, carried out all running checks and inspections, restamped fire extinguisher.	4/10/2012	Hours
	16700	Hours 4830 Checked over as is due for service.	3/10/2012	Hours
	16701	Inspect for oil leak - was trans fitting.	2/10/2012	Hours
	16703	Hours 4683 Chop to length two roll pins and fit to window latches	31/08/2012	Hours
	16704	HOurs 4557 Change out broken seat with P293	3/08/2012	Hours
	16705	Hours 4540 Change out LH outer mirror that ABI group broke	31/07/2012	Hours
	16708	Hours 4506 Abi damage change out 2 test port fittings and half dozen P clamps due to rocking flicking up and damaging fittings.	25/07/2012	Hours
	16711	Finish off 250hr service	13/07/2012	Hours
	16746	Info tag fitted of low fuel pressure, hook up etc & test & check operation, test OK	7/07/2012	Hours
	16748	Hours 4391 Sync in hour meter to product link	3/07/2012	Hours
	16750	Fit all stickers	1/06/2012	Hours
	16751	Top up hyd steering oil tank levels, check all fluids and all work carried out was completed, make brackets to lower two front steps under/to required height.	31/05/2012	Hours
	16753	Fit all stickers, PR radiator caps	30/05/2012	Hours
	16752	fit up product link and sink into truck, fit up POS ID signage	30/05/2012	Hours
	16757	Pump up struts and tie back any loose wiring	29/05/2012	Hours
	16755	Fit all mudflaps, floor matt, stickers, wheel chock holder, place dash back into place, apply 2x turbo covers, mirrors.	29/05/2012	Hours
	16759	Unload truck, dry assemble deflector guards	28/05/2012	Hours
	16758	Dry assemble guards, mud guards etc	28/05/2012	Hours
	16760	Weld in isolation panel in front grill and paint and fit up	22/05/2012	Hours

Asset	W/O No	Description	Finished	Done Reading
	16761	Travel to pinkanbar load up truck and also let down front struts	16/05/2012	Hours
	16763	Fit up reverse camera, make up camera harness, oxy out tags in rear of tub, crane in gear in tub for passport	15/05/2012	Hours
	16765	Assemble 773	27/04/2012	Hours
	16767	Assemble 773	25/04/2012	Hours
	16766	Hours 4275 Fit up new painted hand rails. Paint foot steps up.	25/04/2012	Hours
	16768	Hours 4275 Torque up rear outer wheel nuts. Prepare for painting. Strip down struts for repairs.	24/04/2012	Hours
	16770	Hours 4275 Remove seizal LH rear strut and strip down Fit up guards etc, level check, fit up tyres fit up fire cans. Create list. Remove parts in body and set out	21/04/2012	Hours