# Work Order History Report

| Asset | W/O No | Description | Finished | Done Reading | |
|---|---|---|---|---|---|
| **P0291** | | **Cat 773 Dump Truck** | | | |
| | 60375 | February R&M<br>Load truck - Demob | 6/02/2026 | | Hours |
| | 60002 | January R&M<br>Remove and replace both rear struts<br>Brake temp fault.<br>- 6-month Fire Suppression service | 6/02/2026 | | Hours |
| | 58804 | Rigid Dump Truck - 250hr Service<br>14377 hrs - 14382 hrs<br>Inspection & engine oil sample only<br>Wheel chock missing - fitted second hand one<br>Eng oil top up<br>Secured horn<br>Replaced broken grease nipples | 30/01/2026 | 14382 | Hours |
| | 59364 | Rigid Dump Truck - 500hr Service and to do list<br>14401hrs<br>LH strut leaking oil. Plan replacement 03/11<br>Hose leaking @ crimp 03.11 | 18/01/2026 | 14401 | Hours |
| | 59416 | December R&M<br>Rock deflector repair.<br>Pre lube pump repair.<br>Replace valve in front strut and pump up.<br>Repair reverse camera.<br>Inspect second steer solenoid. | 11/12/2025 | | Hours |

| | | | |
|---|---|---|---|
| 58763 | November R&M<br>Oil leak trans/ hyd<br>Seal RH door<br>Fit new RHS mirror<br>Replace transmission cap<br>Refit hydraulic filter housing<br>Replace batteries | 30/11/2025 | Hours |

| Asset | W/O No | Description | Finished | Done Reading | |
|---|---|---|---|---|---|
| | 58155 | October R&M<br>- wheel chock holder<br>- Electrical faults, repair wires | 21/10/2025 | | Hours |
| | 57295 | September R&M<br>- Steering fault-found harness rubbing, repaired and resecured 22/09<br>- Cab panel loose/missing bolt 22/09 | 22/09/2025 | | Hours |
| | 54974 | Fit Tyres.<br>Prep for Lake Cowal (CMC FFP)<br>Pre hire repairs | 19/09/2025 | | Hours |
| | 56745 | Rigid Dump Truck - 2000hr Service<br>14106hrs | 19/09/2025 | 14106 | Hours |
| | 56800 | August Monthly R&M<br>Assemble and fit fire suppression<br>system to Cat 773F ID P291<br>-Replace fire panel due to missing<br>-Replace control head, siphon tube and<br>burst disc due to missing<br>-Wire in new fire panel and test | 18/09/2025 | | Hours |
| | 56457 | July Monthly Work Order R&M<br>Grease machine | 23/07/2025 | | Hours |
| | 52702 | Inspect for Damage report to Nathan (Bedford Weir). 13856 02-07-25<br>Fab and fit hungry boards to Tray.<br>Replaced passenger seat belt<br>Fuel relief ordered<br>Access step fit new rubbers<br>Fuel tank breather hose<br>Reverse alarm not load enough (replace ordered NAPA)<br>Fit service sticker, done at 13769hr<br>Clean cab<br>Check, tag and bag fire extinguisher<br>Fit first aid kit | 7/03/2025 | 13852 | Hours |

| Asset | W/O No | Description | Finished | Done Reading | |
|---|---|---|---|---|---|
| | | Fill and test window washers<br>Secure radio correctly<br>Grease machine<br>Secure grease lines around steer links and cylinders<br>Remove Maas stickers<br>Fit thinksafe stickers<br>Fit hi vis tape as required<br>Remove old client stickers<br>Secure hoses rubbing around T/C area<br>Repair oil leak around hydraulic pump<br>Repair cracks around RH strut mount, top<br>Repair cracks around LH strut, bottom brace<br>Remove broken bolts in rock deflectors<br>Shim tub pads<br>Fit and tension wheels<br>USO spec<br>Paperwork, fulcrum photos | | | |
| | 50739 | Step Repairs and Change out seat buckle | 29/11/2024 | | Hours |
| | 49559 | 13601hrs<br>FFP repairs (Pre-Hire)<br>Wash truck<br>Park machine for float access, on hire phots, fuel machine | 3/11/2024 | 13601 | Hours |
| | 18337 | Replace Batteries<br>First set of batteries not correct<br>Remove & replace with correct batteries<br>Test - all appears okay | 1/07/2024 | | Hours |
| | 11287 | Inspection | 25/04/2024 | 13601 | Hours |
| | 9897 | DE-MOBILISATION<br>HOURS: 13600 | 23/02/2024 | | Hours |
| | 8328 | Rigid Dump Truck - 500hr Service<br>Repaired seat belt | 14/01/2024 | 13555 | Hours |
| | 8647 | Tub Inspection & Material Ordering. | 11/01/2024 | 13536 | Hours |
| | 8274 | Repaired seatbelt<br>Check hub oil levels | 19/12/2023 | 13431 | Hours |
| | 8133 | Recover machine from being bogged. | 14/12/2023 | 13392 | Hours |
| | 7936 | Investigate AC system fault. Found compressor has failed. Remove and replace compressor. Regas system. requires | 9/12/2023 | 13349 | Hours |

| Asset | W/O No | Description | Finished | Done Reading | |
|---|---|---|---|---|---|
| | | further attention to be completed.<br>AC system fault. Revac system recharge with gas. test system and send back to work. | | | |
| | 7532 | Machine not starting. Primed fuel system and re-started machine. Carry out check over as required. | 3/12/2023 | 13312 | Hours |
| | 7134 | Checked and tested steering found to be ok.<br>Blew out cabin and engine air filters as required, pre-shift. | 26/11/2023 | 13298 | Hours |
| | 6339 | Rigid Dump Truck - 250hr Service | 30/10/2023 | 13223 | Hours |
| | 5796 | Grease, check over machine and check electrical fault | 1/10/2023 | 13069 | Hours |
| | 2961 | Pre hire repairs.<br>Transmission hose replaced.<br>Air intake elbow replaced.<br>Serviced fire suppression.<br>Repair engine covers.<br>Repair cracks in chassis.<br>Clean up electrical wiring under cab.<br>Secure grease hoses to steering.<br>Replace wiper blades.<br>Replace asset numbers.<br>Check per site requirements.<br>Rear struts line bored & resealed.<br>Replace hydraulic hoses as required<br>Rim testing.<br>Replace A-frame bearing<br>Replace dog bone bearingsRepair and add support to P1 and P2 strut towers (cracked)<br>Replace steering ball studs x 4<br>Replace steering link pivot pin and bush.<br>Replace LH hoist cylinder bearings<br>Replace RH hoist cylinder bearings<br>Repair oil leaks<br>Assembly of machine walkways<br>Adjust road speed, and adjust strut heights<br>Clean up window frame. | 28/08/2023 | 13051 | Hours |
| | 16871 | Hours 13033<br>Fuel gauge not working - tested fuel sender not reading | 3/04/2023 | | Hours |
| | 16866 | Hours 13049<br>Off hire paperwork. No key & not clean. | 6/03/2023 | | Hours |
| | 16868 | Hours 13049<br>Step torn - replace step rubbers<br>Replace exhaust elbow - remove and replace | 20/02/2023 | | Hours |

| Asset | W/O No | Description | Finished | Done Reading | |
|---|---|---|---|---|---|
| | | Jump start and move - charge batteries and move | | | |
| | 16880 | Hours 12944<br>Jump start, fit new batteries, replace cheak valve in priming pump. More investigation needed. Check all fuel pressures, swapped fuel relief with another truck. Checked fuel lines, changed out fuel transfer pump | 8/02/2023 | | Hours |
| | 237 | Fit fuel transfer pump & fuel sender, inspect oil leak | 24/01/2023 | 13050 | Hours |
| | 16883 | Orange flashing light not working - replace | 16/01/2023 | | Hours |
| | 16879 | Hours 12944<br>AC not cold - A1 sparky repaired | 16/01/2023 | | Hours |
| | 16877 | Hours 13033<br>1000 Hour service | 16/01/2023 | | Hours |
| | 16874 | Hours 13033<br>Reseal accumulator valve | 16/01/2023 | | Hours |
| | 16864 | Hours 13049<br>Check over/fit 2 ways | 9/01/2023 | | Hours |
| | 16903 | Take out 2 way | 22/12/2022 | | Hours |
| | 16876 | Hours 13033<br>Accumulator hose - replace hose | 22/12/2022 | | Hours |
| | 16884 | Hours 12776<br>Flat tyre POS 5 - locate machine, limp to workshop, jack up truck, found valve stem torn off, remove outer tyre, get valve stem, remove extension. Pump up tyre reseat on o-ring, fit outer tyre. Remove jack. | 17/10/2022 | | Hours |
| | 16888 | Hours 12756<br>250 hr service | 10/10/2022 | | Hours |
| | 16898 | Reverse camera dust over lense, diagnose camera issue. Replace camera. | 4/10/2022 | | Hours |
| | 16889 | Hours 12743<br>CPB monthly inspection | 4/10/2022 | | Hours |
| | 16890 | Hours 12691<br>Platform cracked from fire suppression bottle. Cut gusset for platform, weld up cracks in platform, weld in gusset, paint. | 19/09/2022 | | Hours |
| | 16905 | Hours 12546<br>Complaint of hoist slow, check system went for load, run out in float, hoist coming down with in spec time.<br>Fire suppression checking floor.<br>Remove handrail gate to operate till repair. | 15/08/2022 | | Hours |
| | 16906 | Hours 12543<br>Charge brake accumulators | 13/08/2022 | | Hours |
| | 16907 | Hours 12518<br>Seat wont go up<br>Lift up seat and found air lines punctured | 9/08/2022 | | Hours |

| Asset | W/O No | Description | Finished | Done Reading |
|---|---|---|---|---|
| | | Replace seat air lines | | |
| | 16909 | Hours 12518<br>Locate truck, hard to start<br>Primed up<br>Check over fuel system<br>More investigation needed. | 8/08/2022 | Hours |
| | 16910 | Hours 12504<br>Locate truck<br>Fire extinguisher<br>CPB request | 4/08/2022 | Hours |
| | 16911 | Hours 12495<br>Take tyre fitter to truck | 2/08/2022 | Hours |
| | 16912 | Hours 12484<br>Complete 500 hour service | 26/07/2022 | Hours |
| | 16899 | Hours 12473<br>500 Hour service | 26/07/2022 | Hours |
| | 16914 | Hours 12484<br>Remove old batteries and found holder broken<br>Removed rods - cut and made new rods using M/O threaded rod<br>Fitted new batteries<br>Tap out worn threads on cover plate<br>Fitted cover plates, new bolts. Check charge | 25/07/2022 | Hours |
| | 16915 | Hours 12469<br>Locate track and jump started<br>Tracker charge 27v<br>Batteries failed | 19/07/2022 | Hours |
| | 16916 | Hours 12453<br>CPB monthly check | 6/07/2022 | Hours |
| | 16917 | Hours 12420<br>Locate truck<br>Wireless not working - found blown fuse<br>Got power to radio<br>Radio U/S<br>Wire new radio | 22/06/2022 | Hours |
| | 16918 | Hours 12390<br>Locate plant<br>Jump start truck<br>Prime charge batteries from my truck<br>Accumulator pressure fault up<br>Locate wiring, clean plug, fault inactive | 15/06/2022 | Hours |
| | 16919 | Hours 12387 | 1/06/2022 | Hours |

| Asset | W/O No | Description | Finished | Done Reading |
|---|---|---|---|---|
| | | Locate machine<br>Charge truck through jumper leads<br>Prime fuel system<br>Jump start truck<br>Fault codes arising behind truck safe to operate to move truck | | |
| | 16902 | Revere camera cloudy and unable to be used. Cleaned reverse camera glass. | 21/05/2022 | Hours |
| | 16900 | FM radio not working - replaced | 5/05/2022 | Hours |
| | 16920 | Hours 1238<br>Complete CPB monthly | 22/04/2022 | Hours |
| | 16901 | Left hand seat bracket broken, base of seat replaced. Note used CAT740 part number 218-0861 | 7/04/2022 | Hours |
| | 16922 | Truck not starting<br>Locate truck<br>Bleed fuel<br>Jump start truck<br>Remove battery cover<br>Checked battery clamps - OK<br>Check charge rate - 27.5v - OK<br>Fit covers | 6/04/2022 | Hours |
| | 16924 | Hours 12378<br>Attempt to order seat pan - discontinued<br>Part check and measured seat pan in P0233 - same part<br>Order seat pan | 30/03/2022 | Hours |
| | 16923 | Hours 12372<br>C/O seat pan | 30/03/2022 | Hours |
| | 16925 | Hours 12369<br>Locate machine<br>Jump start<br>Check charge rate - 27V | 16/03/2022 | Hours |
| | 16926 | Hours 12322<br>Locate truck and jump start | 18/01/2022 | Hours |
| | 16927 | Git LH mirror and pump up rear struts | 21/12/2021 | Hours |
| | 16928 | Install TFO tracker<br>Remove NPM tracker<br>Replace front lights<br>Diagnose rear camera<br>Repair wiring for front lights | 16/10/2021 | Hours |
| | 16929 | Hours 11975<br>Complete FFP inspection<br>Replaced RH head light bulb | 14/07/2021 | Hours |

| Asset | W/O No | Description | Finished | Done Reading |
|---|---|---|---|---|
| | 16930 | Hours 11974<br>Using CHT ET & sis<br>Inspected plugs for trans speed sensor<br>Moved sensor forward and pin to plugs to isolate fault | 10/07/2021 | Hours |
| | 16932 | Hours 11974<br>Trans speed sensor 1 fault<br>Swap sensors with P1136<br>Still faulting<br>Further investigation required | 9/07/2021 | Hours |
| | 16933 | HOurs 11866<br>Check leak POS 4<br>Duo starting R/R E-stop & repair findex mount | 12/06/2021 | Hours |
| | 16935 | Hours 11866<br>FFP instructions and repairs | 9/06/2021 | Hours |
| | 16937 | Hours 11779<br>Assist 250 hour service | 29/05/2021 | Hours |
| | 16936 | Hours 11779<br>250 hour service<br>Fit new step rubbers<br>Reseal brake line block at POS3/4<br>Check tyre pressures<br>Swap out seat compressor | 29/05/2021 | Hours |
| | 16939 | Hours 11650<br>Fit new steering sensor | 13/05/2021 | Hours |
| | 16938 | Hours 10845<br>Test starter motors | 13/05/2021 | Hours |
| | 16940 | Carry out diagnostic checks and change all machines to 40km p/h | 10/05/2021 | Hours |
| | 16971 | Hours 11588<br>Fire suppression mounts cracking. Grind out weld crack around and below fire sus tank | 1/05/2021 | Hours |
| | 16972 | Hours 11553<br>Clean steer sensor | 28/04/2021 | Hours |
| | 16973 | Blow out a/c cab filters | 26/04/2021 | Hours |
| | 16974 | Hours 11541<br>500 hr service | 22/04/2021 | Hours |
| | 16975 | Hours 11541<br>Check seat compressor<br>Drain engine oil<br>Check over | 21/04/2021 | Hours |

| Asset | W/O No | Description | Finished | Done Reading |
|---|---|---|---|---|
| | 16976 | Hours 11498<br>Grease | 17/04/2021 | Hours |
| | 16977 | Hours 11454<br>Repair step. Quarterly | 13/04/2021 | Hours |
| | 16978 | Hours 11423<br>Fit new fuel sender | 6/04/2021 | Hours |
| | 16979 | Hours 11372<br>Grease | 1/04/2021 | Hours |
| | 16980 | Hours 11394<br>Grease & check over machine and tyres | 31/03/2021 | Hours |
| | 16981 | Hours 11222<br>Fit hose from brake filters to accumulators | 2/03/2021 | Hours |
| | 16982 | Hours 11217<br>Grease & check over<br>Diagnose leak | 18/02/2021 | Hours |
| | 16983 | Hours 11206<br>Grease and check over machine | 10/02/2021 | Hours |
| | 16985 | Hours 11206<br>Grease, tyre valve | 9/02/2021 | Hours |
| | 16987 | Clear NP FFP & HV defects | 3/02/2021 | Hours |
| | 16988 | Hours 11205<br>North Parkes FFP<br>Safety stickers, repair seat, replace E-stop<br>Secure hosing, check all critical fasteners<br>Clean out battery box | 2/02/2021 | Hours |
| | 16990 | Hours 11205<br>North Parkes FFP<br>Fit safety stickers<br>Fit reflective tape<br>Fit x2 9kg fire extinguishers and tag<br>Sleeve hosing with croc sleeve | 1/02/2021 | Hours |
| | 16992 | Handrails | 29/01/2021 | Hours |
| | 16993 | Prep for painting<br>Put prime coat on | 28/01/2021 | Hours |

| Asset | W/O No | Description | Finished | Done Reading |
|---|---|---|---|---|
| | 16994 | Hours 11205<br>Continue to install decals<br>Burst protection, remove handrail for paint<br>Paint tow points | 27/01/2021 | Hours |
| | 16997 | Hours 11204<br>Test fire suppression and remove bottle for testing | 12/01/2021 | Hours |
| | 16996 | Hours 11205<br>Install decals, burst protection, remove handrail for paint, paint tow points | 12/01/2021 | Hours |
| | 16995 | Hours 11204<br>Sheath hydraulic hoses around engine | 12/01/2021 | Hours |
| | 16998 | cover fuel lines in burst protection and repair front grill bolts | 16/12/2020 | Hours |
| | 17001 | Start insulating fuel lines | 15/12/2020 | Hours |
| | 17000 | Cover fuel lines in burst protection | 15/12/2020 | Hours |
| | 17002 | Front bumps<br>Mud guards<br>Air line repairs | 11/12/2020 | Hours |
| | 17003 | Repair crack in rear of tub | 8/12/2020 | Hours |
| | 17004 | Remove liners from tub and repair cracks | 7/12/2020 | Hours |
| | 17005 | Hours 11202<br>Fit new stickers<br>Move out of workshop<br>Assist jack | 4/12/2020 | Hours |
| | 17009 | Repair and change fire suppression. | 3/12/2020 | Hours |
| | 17007 | Grease<br>Check tyre pressures<br>Remove broken P sticker<br>Remove isolator stickers<br>Weld on fire extinguisher bracket<br>Replace transmission cooler hose<br>Wash & tag extinguishers | 3/12/2020 | Hours |
| | 17006 | Hours 11202<br>Replace RH lift cylinder bearing<br>Replace stickers<br>Assist Jack with replacing hose - check levels | 3/12/2020 | Hours |
| | 17010 | HOurs 11202<br>Assemble brake filter housing and fit<br>Replace outer steer cylinder pins | 2/12/2020 | Hours |

| Asset | W/O No | Description | Finished | Done Reading |
|---|---|---|---|---|
| | | Start to remove RH side top lift cylinder pin | | |
| | 17012 | Hours 11205<br>Complete 250 hr service<br>Change rear diff dog bone bushes<br>Remove brake filter housing ass<br>Reseal break filter ass | 1/12/2020 | Hours |
| | 17014 | HOurs 11205<br>Complete 250hr service | 30/11/2020 | Hours |
| | 17015 | Hours 11055<br>Carry out 1000 hr service | 29/09/2020 | Hours |
| | 17016 | Hours 10928<br>Diagnose speed saber fault | 4/09/2020 | Hours |
| | 17017 | Hours 10733<br>Carry out service<br>Replace control lights<br>Replace multifunction switch<br>Replace wiper relay<br>Replace steer pressure switch<br>Replace brake pressure switch | 7/07/2020 | Hours |
| | 17019 | Hours 10711<br>Diagnose electrical fault with rear lights | 24/06/2020 | Hours |
| | 17020 | Hours 10557<br>carry out 500 hr service | 25/05/2020 | Hours |
| | 17021 | carry out 1000hr service<br>Change all oils and filters | 31/03/2020 | Hours |
| | 17022 | Replace POS 1 and 2 brake pads | 21/02/2020 | Hours |
| | 17023 | Hours 9359<br>Fit and adjust mirrors, pump up front struts and fit strut guards | 29/09/2017 | Hours |
| | 17025 | Drop struts and check over | 14/09/2017 | Hours |
| | 17026 | Hours 9121<br>Check out fuel draining back. Check test alarm and disconnect | 23/09/2016 | Hours |
| | 17027 | Hrs 8979<br>Carry out 1000hr service as manufacturer recommendations and check over | 26/08/2016 | Hours |
| | 17029 | Hours 8526<br>Check over and grease | 21/06/2016 | Hours |
| | 17028 | Hours 8752<br>Carry out service | 21/06/2016 | Hours |

| Asset | W/O No | Description | Finished | Done Reading |
|---|---|---|---|---|
| | 17030 | Wash | 14/05/2016 | Hours |
| | 17031 | Hours 8520<br>Adjust fuel tank and bolt bracket<br>Assist fordy with hungry board, operate digger. Clean.<br>Weld repairs | 13/05/2016 | Hours |
| | 17069 | Hours 8520<br>Fit new trans oil shaft sheal & fit covers<br>Check over machine<br>Stall tests on machine | 12/05/2016 | Hours |
| | 17068 | Weld repairs | 12/05/2016 | Hours |
| | 17067 | Hours 8520<br>Greased machine<br>Fit evac valve<br>Fit other steering rod end<br>Final check over machine | 12/05/2016 | Hours |
| | 17033 | Hours 8520<br>Remove fuel tank bracket fit guards | 12/05/2016 | Hours |
| | 17073 | Hours 8518<br>Carried out 500hr service<br>Changed engine oil and filters, fuel filters, air cleaners, cab cleaners, check oil level & condition.<br>Start greasing machine. | 11/05/2016 | Hours |
| | 17072 | Hours 8520<br>Assisted Josh in defect list and checkover | 11/05/2016 | Hours |
| | 17071 | Hours 8518<br>Carried out 500hr service<br>Write up list on machine<br>Removed steering inner tie rod joints that had excessive movement<br>Refit<br>Fit new A/C belt & checked all bearings, ok<br>Started removing covers and driveshafy on torque converter output shaft | 11/05/2016 | Hours |
| | 17070 | Hours 8518<br>Reseal hydraulic filter fittings & change filters<br>Fit up new steering joints in cylinders<br>Check wheel nut tensions<br>Fix cab seal leak | 11/05/2016 | Hours |
| | 17144 | Hours 8518<br>Start check over on machine<br>Jack up struts and check bearings in lift cylinder bottom bearing | 10/05/2016 | Hours |

| Asset | W/O No | Description | Finished | Done Reading |
|---|---|---|---|---|
| | 17147 | Check over for defects | 24/07/2015 | Hours |
| | 17148 | Hours 8103<br>Travel to Narrabri, Carry out 1000 hr service as per manufacturers recommendations. Change engine oil and filters, change fuel filters, change inner and outter air cleaners. Replace cab filters, replace front hub oil, check final drive and diff bungs. Pack up and travel to nundle. | 11/06/2015 | Hours |
| | 17150 | Hours 7849<br>Wash machine | 16/05/2015 | Hours |
| | 17149 | Pump up front struts | 20/04/2015 | Hours |
| | 17151 | Washed machine<br>Completed pre hire paperwork<br>Fitted safety stickers<br>Topped up oils | 16/04/2015 | Hours |
| | 17152 | Organised parts and pressure washer to do repairs and wash machine | 15/04/2015 | Hours |
| | 17154 | Fit hungry boards | 11/04/2015 | Hours |
| | 17153 | Complete pre hire site paperwork/checks | 11/04/2015 | Hours |
| | 17156 | Hours 7849<br>Replace tie end rods<br>Replaced bent rock ejector<br>Fitted up hungry boards | 10/04/2015 | Hours |
| | 17155 | Replace required tie rod ends, fit hungry boards | 10/04/2015 | Hours |
| | 17157 | Replace top lift cyl pin LH cyl | 11/12/2014 | Hours |
| | 17158 | Hours 7849<br>Reseal starter motor, replace 3 bulbs in headlights, straighten bumper with porta power | 4/12/2014 | Hours |
| | 17159 | Hours 7849<br>Swap LH pad with used pad to even up pads | 3/12/2014 | Hours |
| | 17160 | Hours 7894<br>Drop struts | 6/11/2014 | Hours |
| | 17161 | Hours 7849<br>Check over machine and make up job lists | 14/10/2014 | Hours |
| | 17162 | Hours 7804<br>Check for coolant leaks, check transmission downshift fault | 12/09/2014 | Hours |
| | 17163 | Hours 7796<br>Remove guards and remove header tank for filler neck replacement/repair, clean silastic off component reseal and refit repaired tank, top up coolant and test. OK. Refit guards | 11/09/2014 | Hours |

| Asset | W/O No | Description | Finished | Done Reading |
|---|---|---|---|---|
| | 17164 | Hours 7795<br>Top up engine oil | 7/09/2014 | Hours |
| | 17165 | Hours 7720<br>Put bar and pipe on P6 wheel nuts | 12/08/2014 | Hours |
| | 17166 | Hours 7682<br>Tighten wheel nuts after two loads | 7/08/2014 | Hours |
| | 17168 | Hours 7681<br>Repair steps both sides | 6/08/2014 | Hours |
| | 17167 | Hours 7681<br>Help tyre fitter | 6/08/2014 | Hours |
| | 17169 | Hours 7618<br>Fit fuse to flashing light wiring | 21/07/2014 | Hours |
| | 17170 | Travel to fill 3, check tyre after report was made that it was going to blow out | 11/07/2014 | Hours |
| | 17171 | Hours 7555<br>Fit flashing light to machine | 7/07/2014 | Hours |
| | 17172 | Fab flashing light brackets | 4/07/2014 | Hours |
| | 17173 | Hours 7507<br>500hr service<br>Change engine oil and filters/fuel fitlers/air filters/clean cab filters | 26/06/2014 | Hours |
| | 17174 | Hours 7448<br>Replace front right hand bumper, had to modify bolt holes to make fit, replace step rubbers | 12/06/2014 | Hours |
| | 17176 | Fit mirrors and gas struts | 29/05/2014 | Hours |
| | 17175 | Hours 7395<br>Fit steps/mirrors, pump up starts | 29/05/2014 | Hours |
| | 17179 | Hours 7395<br>Fit new bearing to lift cylinder, clean up bosses and pin, fit lift cylinder and pins, fill out site paperwork, check over machine, fit wheel chocks, | 20/05/2014 | Hours |
| | 17178 | Hours 7351<br>Replaced damaged brake filter housing<br>Replace leaking O-rings & tighten fittings on filter head.<br>Remove mudflap and straighten POS 1 mudguard and refit mudflap | 20/05/2014 | Hours |
| | 17177 | Hours 7395<br>Repair exhaust, fit hoist cylinder. | 20/05/2014 | Hours |
| | 17182 | Hours 7395<br>Remove hungry boards/check over, stamp rims, help millsy | 19/05/2014 | Hours |
| | 17181 | Hours 7395 | 19/05/2014 | Hours |

| Asset | W/O No | Description | Finished | Done Reading |
|---|---|---|---|---|
| | | Remove LH lift cyl pin, heated up and pressed pin out due to being seized up, remove bearing from cylinder. | | |
| | 17180 | Hours 7395<br>Remove hungry boards | 19/05/2014 | Hours |
| | 17183 | Dis-assemble ready from transport | 16/05/2014 | Hours |
| | 17184 | Hours 7351<br>Change out torque converter fill tube, repair oil leak on brake circuit. | 12/05/2014 | Hours |
| | 17186 | Hours 7330<br>Drop belly guards, get radiator welded up, fill with coolant and fit belly guards | 9/05/2014 | Hours |
| | 17185 | Repair radiator | 9/05/2014 | Hours |
| | 17188 | Hours 7328<br>Change out front tyres, check out coolant leak, fit step rubbers, change out fan belts. | 8/05/2014 | Hours |
| | 17187 | Hours 7330<br>Find coolant leak, crack around drain valve on bottom tank, drain coolant | 8/05/2014 | Hours |
| | 17190 | Check out reports of retarder not working correctly, could not fault | 29/04/2014 | Hours |
| | 17191 | Hours 7149<br>Remove fan shrouds, remove fan and hub assembly.<br>Dissassemble, fit new bearings, remove broken bolt from shaft. Assemble fan hub assembly, Fit new belts, fit fan and fan shrouds. | 23/04/2014 | Hours |
| | 17192 | R&R POS 3 tyre. Side wall split leaking. | 20/04/2014 | Hours |
| | 17193 | Hours 7023<br>Carry out 1000hr service, change engine oil and filter/air cleaners/cab filters/fuel filters/steer oil and filters/brake filters/trans oil and filter, check trans screen, check diff and final drive bungs, change front hub oils, change POS 5 tyre. | 9/04/2014 | Hours |
| | 17194 | Fit body up alarm | 8/04/2014 | Hours |
| | 17195 | Hours 6957<br>Change out POS 6 tyre and tension | 31/03/2014 | Hours |
| | 17196 | Hours 6894<br>Fit new lower strut & refit strut to machine<br>Gas up rear struts | 21/03/2014 | Hours |
| | 17197 | Assemble strut | 17/03/2014 | Hours |
| | 17198 | Adjust all strut heights. | 25/02/2014 | Hours |
| | 17199 | Hours 8884<br>Regas front strut, run out of gas, organise more gas | 24/02/2014 | Hours |
| | 17200 | Hours 6876<br>Check strut heights, OK. | 23/02/2014 | Hours |

| Asset | W/O No | Description | Finished | Done Reading |
|---|---|---|---|---|
| | | Check for hyd fault.<br>Wouldn't play up.<br>Send back to work. | | |
| | 17201 | Hours 6842<br>Straighten steps, replace rubbers, pump up rear struts | 18/02/2014 | Hours |
| | 17203 | Assist with fitting hungry boards | 13/02/2014 | Hours |
| | 17202 | Fit hungry boards | 13/02/2014 | Hours |
| | 17205 | Hours 6804<br>Repair leaking fitting on RH steer cylinder | 11/02/2014 | Hours |
| | 17204 | Fab hungry boards | 11/02/2014 | Hours |
| | 17206 | Fab hungry boards | 10/02/2014 | Hours |
| | 17207 | Check over for 3 monthly inspection | 28/01/2014 | Hours |
| | 17208 | Fab hungry boards | 23/01/2014 | Hours |
| | 17215 | Hours 6648<br>Remove broken bolt from fan hub, clean up all parts. Order parts<br>Fit new seal, park bearings & re-assemble &refit hub.<br>Kit bolts & guards & fan | 21/01/2014 | Hours |
| | 17217 | Remove fan hub, bearing U/S | 20/01/2014 | Hours |
| | 17216 | Hours 6648<br>Remove fan hub | 20/01/2014 | Hours |
| | 17218 | Fab hungry boards | 17/01/2014 | Hours |
| | 17219 | Fab hungry boards | 16/01/2014 | Hours |
| | 17221 | Fab hungry boards | 15/01/2014 | Hours |
| | 17220 | Hours 6590<br>Reseal LH rear strut and recharge per spec<br>Service engine<br>Check front brakes for wear | 15/01/2014 | Hours |
| | 17222 | Hours 6503<br>R&R rear strut | 5/01/2014 | Hours |
| | 17223 | Hours 6440<br>Replace bent loader rubbers | 29/12/2013 | Hours |
| | 17225 | Hours 6331<br>Clean out window seal and fit rubber | 4/12/2013 | Hours |

| Asset | W/O No | Description | Finished | Done Reading |
|---|---|---|---|---|
| | 17224 | Hours 6331<br>Replace smashed RHS quarter glass | 4/12/2013 | Hours |
| | 17227 | Hours 6299<br>Straighten and replace step rubbers, repair fuel sender fault. | 24/11/2013 | Hours |
| | 17228 | Hours 6164<br>Check over machine, carry out pre-hire inspection and order required parts | 8/11/2013 | Hours |
| | 17229 | Hours 6156<br>Pump up rear struts | 1/11/2013 | Hours |
| | 17230 | Hours 6156<br>Conduct all field wiring, check power to lights | 31/10/2013 | Hours |
| | 17231 | Hours 6156<br>Gas up struts | 30/10/2013 | Hours |
| | 17235 | Hours 6156<br>Repair wiring and deutsch plugs, remove camera cables, bolt up stairs, blow out rear engine radiators due to excess dirt and seeds. | 29/10/2013 | Hours |
| | 17232 | Hours 6156<br>Fit rock guards, walkways, steps and mudflaps<br>Segregated hyd & electrics. Fit required decals and reflective tapes. Oil up front shocks and charge with nitrogen. | 29/10/2013 | Hours |
| | 17236 | Fit new fuel/water separator filters and check lights. | 28/10/2013 | Hours |
| | 17237 | Hours 6156<br>Check over defect list and start doing repairs | 27/10/2013 | Hours |
| | 17238 | Strip down for transport | 11/10/2013 | Hours |
| | 17239 | Hours 6041<br>Change out all drive belts | 10/09/2013 | Hours |
| | 17240 | Hours 5792<br>Checked tyre pressure & adjusted. Repaired oil leak at transmission filter housing. | 1/08/2013 | Hours |
| | 17241 | Hours 5640<br>Assemble radiator & accessories. Repair wiring to main harness plug as it had corrosion in the terminals. Replaced all terminal pins. | 2/07/2013 | Hours |
| | 17242 | Hours 5640<br>Fit up radiator and accessories. | 1/07/2013 | Hours |
| | 17243 | Travel to mackay and picked up radiator for P0291 as instructed by Greg Patterson | 28/06/2013 | Hours |
| | 17244 | Hours 5640<br>Continue removal of radiator and take into town. | 18/06/2013 | Hours |
| | 17245 | Hours 5640<br>Try and block up radiator covers that were leaking. No good. Start removing radiator. | 17/06/2013 | Hours |

| Asset | W/O No | Description | Finished | Done Reading |
|---|---|---|---|---|
| | 17246 | Hours 5640<br>Remove and strip radiator assembly | 15/06/2013 | Hours |
| | 17247 | Finish off 500 hour service | 23/05/2013 | Hours |
| | 17248 | Hours 5448<br>Jump start truck and load test, remove and replace | 12/05/2013 | Hours |
| | 17249 | Hours 5455<br>Jump start truck and check over batteries | 11/05/2013 | Hours |
| | 17250 | Hours 5282<br>Carry out 250hr service as per sheet | 24/03/2013 | Hours |
| | 17252 | Hours 5236<br>Inspected fuel tank<br>Cracked mount bracket | 17/03/2013 | Hours |
| | 17253 | Hours 5188<br>Diagnose fuel gauge fault | 9/03/2013 | Hours |
| | 17254 | Replaced front step rubber | 14/02/2013 | Hours |
| | 17255 | Hours 5001<br>Carry out 1000 hr service as per service sheet, incl hyd oil too | 29/01/2013 | Hours |
| | 17256 | Hours 4871<br>Rebuild leaking engine oil filter housing with new gaskets O rings | 16/12/2012 | Hours |
| | 17257 | Hours 4792<br>Trans solenoid #2 fault, tested and diagnosed wiring fault.<br>Removed all connectors and checked connections., Found had connection fitted new terminal and reassembled. Tested OK. | 5/12/2012 | Hours |
| | 17258 | Hours 4791<br>Purge last 2 grease hoses | 3/12/2012 | Hours |
| | 17260 | Hours 4791<br>Complete service as per sheet | 30/11/2012 | Hours |
| | 17259 | Hours 4791<br>Set up & start making grease hoses. 250 hour service and inspections,<br>Make up last 2 grease hoses and fit. Bled grease lines. | 30/11/2012 | Hours |
| | 17261 | Hours 4791<br>Fit bracket for grease system to steering, check valve manifold bracket.<br>Assembled grease manifolds & assembled to mounted bracket.<br>Fittings aimed hose connection into pipes.<br>Removed & modified bracket.<br>Re-assembled, OK.<br>Made hoses for 8 or 10 joints and eventually removed seized grease nipples.<br>Fitted 90 fittings into steering joints & reconnected grease hoses. Checked if due for service. | 28/11/2012 | Hours |

| Asset | W/O No | Description | Finished | Done Reading |
|---|---|---|---|---|
| | 17262 | Hours 4662<br>Loss of coolant no evident leak, chock missing. | 8/11/2012 | Hours |
| | 17263 | Hours 4595<br>Tyre report | 22/10/2012 | Hours |
| | 17264 | Hours 4532<br>Check if tub not lowering at normal speed as OK. Gears changing normally | 14/10/2012 | Hours |
| | 17265 | Recert ext and tighten clamp on bracket. Grease truck | 9/10/2012 | Hours |
| | 17266 | Drive back to Emerald and pick up new trans ECM and flash and set up trans test run all OK | 3/10/2012 | Hours |
| | 17268 | Hours 4508<br>Call up for ECM code on - carried out tests and found that ECM was faulty. | 2/10/2012 | Hours |
| | 17269 | Hours 4508<br>Drive to Emerald to get trans ECM flash in software and reset trans. | 1/10/2012 | Hours |
| | 17276 | Hours 4508<br>Trans speed sensor code - hook et up and clear & test run come back on and go through trouble shooting. | 30/09/2012 | Hours |
| | 17277 | Hours 4502<br>Replace engine speed sensor and started engine. No good.<br>Trans fault light still on.<br>Pulled ECU out of other machine and connected. Trans fault light went out, swapped back and trans fault light on again.<br>ECU faulty. | 28/09/2012 | Hours |
| | 17282 | Changed out speed sensor #2 on transmission | 20/09/2012 | Hours |
| | 17283 | Replaced speed sensors for transmission output speed | 17/09/2012 | Hours |
| | 17284 | Hours 4428<br>250 hr service | 7/09/2012 | Hours |
| | 17285 | Hours 4366<br>Get operator, take for a drive to get trans hot, calibrate transmission with ET. | 22/08/2012 | Hours |
| | 17288 | 250 Hours service | 21/08/2012 | Hours |
| | 17289 | Fitted new steering sensor, fuel filters, cleared codes, 250 hr service, updated ECMs. | 19/08/2012 | Hours |
| | 17290 | Hours 4220<br>Charge up fire suppression as was low. | 30/07/2012 | Hours |
| | 17292 | Weld in isolation front grill and paint<br>Fab up e-stop bracket for fuel tank<br>Fab up e-stop bracket for in cab<br>Fab up POS ID rear sign fit rear wheels | 23/05/2012 | Hours |
| | 17294 | Fit up product link and sink into truck. Stamp rear inner wheels, fit up rear rock ejector. | 20/05/2012 | Hours |