264 – 2012 Mack CXU613 Tandem Axle, SN: 1M1AW02Y8CM021388

- 12/4/24 Cab air bags & shocks replaced
- 6/14/24 All-Fuel Injectors replaced
- 8/23/22 Crank sensors replaced
- 8/23/22 Turbo replaced
- 4/26/22 HVAC controller replaced, A/C system rebuilt, Compressor replaced.
- 6/9/20 5th Wheel plate replaced
- 11/7/19 Steering axle bearings & King pins replaced.
- 8/24/18 Front Shocks replaced
- 12/1/16 Winter front kit installed
- Standard maintenance