

UNITED DIESEL SERVICE

PO BOX 26803

Salt Lake City, UT 84126

ar@uniteddieselservice.net

(801) 972-2378

Invoice:

8347

Date:

8/28/2025**Bill To**

CATE MACHINERY

2055 Pioneer Road

Salt Lake City, UT 84104

Remit Payment To

Billing

PO BOX 26803

Salt Lake City, UT 84126

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
2272	Net 30	9/27/2025	AUSTIN LINDSEY		

Item	Description	Quantity	Rate	Amount
Inspection				
Labor	REPAIR CHECKS AND VERIFICATION: FINAL REPAIRS CHECK TO VERIFY REQUESTED JOB ITEMS HAVE BEEN PROPERLY REPAIRED AND TO ADVISE CUSTOMER OF ANY OTHER POSSIBLE NEEDED REPAIR ITEMS	1.00000	\$85.00	\$85.00

Complaint: Diag and replace the turbo actuator**Cause:** Customer request

Labor	Correction: Chassis / Chassis / Recommend replacing turbo and vgt	4.00000	\$125.00	\$500.00
Parts	Dirty Core for VGT ACTUATOR	-1.00000	\$280.00	-\$280.00
Parts	ACTUATOR	1.00000	\$2,448.46	\$2,448.46
Parts	Inherent Core for ACTUATOR	1.00000	\$218.75	\$218.75
Parts	Dirty Core for ACTUATOR	-1.00000	\$218.75	-\$218.75

Complaint: REPLACE TURBO AND VGT ACTUADOR**Cause:** Customer request

(Inspection)

Labor	Correction: Chassis / Chassis / Paulo ---- Drained coolant , removed turbo Max--- installed new turbo with new hardware and gaskets Filled coolant with what came out pressurized system found pin hole on hose going to Vgt Trimmed hose back and repressurized system no more leaks good	5.00000	\$125.00	\$625.00
Parts	Dirty Core for TURBO	-1.00000	\$650.00	-\$650.00
Parts	OIL DRAIN GASKET	1.00000	\$6.16	\$6.16

Parts	TURBO CHARGER	1.00000	\$6,267.76	\$6,267.76
Parts	Inherent Core for TURBO CHARGER	1.00000	\$781.25	\$781.25
Parts	Dirty Core for TURBO CHARGER	-1.00000	\$781.25	-\$781.25
Parts	FREIGHT	1.00000	\$280.00	\$280.00
Parts	DOUBLE ENDED STUD	4.00000	\$16.49	\$65.96
Parts	NUT	4.00000	\$6.72	\$26.88
Parts	TURBOCHARGER GASKET	1.00000	\$19.70	\$19.70
Parts	OIL DRAIN GASKET	1.00000	\$8.56	\$8.56
Parts	EXHAUST GASKET	1.00000	\$9.56	\$9.56
Parts	SEALING WASHER	2.00000	\$7.20	\$14.40
Parts	SEALING WASHER	5.00000	\$6.78	\$33.90
Parts	GREEN COOLANT 50/50	1.00000	\$21.74	\$21.74

Unit: VIN: 490773UAADF69

2019 DOOSAN HP450

Chassis: 0 Miles

Shop Supplies	\$500.00
Pre-Charge Subtotal	\$9,983.08
Salt Lake City (1% of \$0.00)	\$0.00
Salt Lake Co Tr (1.05% of \$0.00)	\$0.00
Salt Lake County (1.35% of \$0.00)	\$0.00
Utah (4.85% of \$0.00)	\$0.00
Total	\$9,983.08
Payments & Credits	\$0.00
Balance Due	\$9,983.08

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice. All credit card transactions are subject to a 3.75% fee.

IMPORTANT NOTICE – VEHICLE STORAGE & MECHANIC'S LIEN POLICY

Storage fees will begin to accrue after **30 days** of a vehicle being left on United Diesel Service property **without prior notice or an agreement** with shop management. Storage will be charged at a rate of **\$25 per day**, starting on the 31st day. Vehicles left without communication or written approval may be considered **abandoned**. In such cases, a **notice of abandonment** will be issued, and management will make reasonable efforts to contact the customer. If there is no response, the vehicle may be subject to a **mechanic's lien** in accordance with **Utah Code § 38-2-1** and may be sold to recover unpaid charges. The vehicle owner will be responsible for all **lien-related fees**

and any **outstanding storage charges**. By authorizing service or signing this invoice, the customer acknowledges and agrees to these terms.

Customer Signature:_____

Printed Name:_____ **Date:**_____

CATE MACHINERY

2055 Pioneer Road
Salt Lake City, UT 84104
alindsey@cateequipment.com

UNITED DIESEL SERVICE

1905 Pioneer Road
Salt Lake City, UT 84104
ar@uniteddieselservice.net

REPAIR CHECKS AND VERIFICATION

Completed Date: 8/27/2025

Unit: VIN: 490773UAADF69

Year/Make/Model: 2019 DOOSAN HP450

Chassis Miles: 0 Miles (8/15/2025)

Engine Hours: No recorded.

Service Order: 2272

Chassis: 490773UAADF69 2019 DOOSAN HP450

Procedure	Result
1. oil level full?	Completed
2. all job lines are completed and notes make sense?	Completed
3. Coolant is full?	Completed
4. Is the truck clean, steering wheel, seat, door, hood, bumper, steps and fairings?	Satisfactory (ok)
5. What is the overall condition of the vehicle? Brakes, belts, hoses, leaks, tires, etc.	Satisfactory (ok)

Technician: RAFAEL MEZACASA

Digital Signature: RAFAEL MEZACASA

Date: 8/27/2025