

Basic start date	Sort Field	Description	System status	Order	Notification	Priority	Main Work Center	Functional Location	Planning Plant	Order Type	Maintenance Plan	Selected Line	Total actual costs	Total planned costs	WBS element	Revision	Room
05/27/2026	TRD414	24W Stat Insp F	TECO CNF	MACN 50157826	10289461	3	MN73	3111-01-04-51-DZT414	2110	WA02	30104792		774.00	794.50			
05/13/2026	TRD414	light on right sid	TECO CNF	EXCP 10094620	10320220	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			1,964.05	1,706.05			
05/08/2026	TRD414	Grease fault	TECO CNF	EXCP 10093945	10318282	1	MN73	3111-01-04-51-DZT414-S	2110	WA01			258.00	0.00			
05/04/2026	TRD414	*RTW*REPLACI	TECO CNF	PRT 10086434	10297353	3	MN73	3111-01-04-51-DZT414-ik2110		WA01			38,594.34	38,594.36			
05/03/2026	TRD414	14D Svce PM Si	TECO CNF	GMP5 50154780	10284214	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980		7,526.90	8,815.63			
05/03/2026	TRD414	Investigate elec	TECO CNF	PRT 10084968	10295374	2	MN73	3111-01-04-51-DZT414-E	2110	WA01			1,958.22	1,958.22			
05/03/2026	TRD414	REPLACE HOSI	TECO CNF	PRT 10086435	10297358	3	MN73	3111-01-04-51-DZT414-H	2110	WA01			319.44	1,038.73			
05/03/2026	TRD414	48W Insp Tow F	TECO CNF	PRT 10159551	10292310	3	MN73	3111-01-04-51-DZT414	2110	WA02	30147389		258.00	258.00			
05/03/2026	TRD414	HD*Drain Replen	TECO CNF	PRT 10084497	10294207	3	MN73	3111-01-04-51-DZT414-E	2110	WA01			129.00	614.20			
05/03/2026	TRD414	28D Tech Insp	TECO CNF	PRT 10154782	10284216	3	MN73	3111-01-04-51-DZT414-V	2110	WA02	30107980		0.00	0.00			
05/02/2026	TRD414	REPLACE BOG	TECO CNF	GMP5 10093118	10316450	2	MN73	3111-01-04-51-DZT414-D	2110	WA01			4,663.65	6,283.95			
04/28/2026	TRD414	Ladder fault	TECO CNF	EXCP 10092567	10314991	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			258.00	0.00			
04/27/2026	TRD414	Replace breathe	TECO CNF	EXCP 10092464	10314653	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			3,204.36	2,688.36			
04/27/2026	TRD414	Fan Return Filte	TECO CNF	EXCP 10092298	10314550	1	MN73	3111-01-04-51-DZT414-H	2110	WA01			468.75	210.74			
04/14/2026	TRD414	Grease Fault	TECO EXCP GMP	10090572	10310095	1	MN73	3111-01-04-51-DZT414-S	2110	WA01			810.44	810.44			
04/13/2026	TRD414	14D Svce PM Si	TECO CNF	GMP5 50152011	10279434	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980		2,243.67	1,856.66			
03/31/2026	TRD414	28D Tech Insp	TECO CNF	PRT 10149386	10274974	3	MN73	3111-01-04-51-DZT414-V	2110	WA02	30107980		0.00	0.00			
03/30/2026	TRD414	14D Svce PM Si	TECO CNF	GMP5 50149385	10274973	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980		7,002.99	6,627.91			
03/30/2026	TRD414	Grease Pump m	TECO CNF	EXCP 10088636	10304931	2	MN73	3111-01-04-51-DZT414-E	2110	WA01			2,314.88	1,411.88			
03/30/2026	TRD414	Replace missing	TECO CNF	GMP5 10083638	10289882	2	MN73	3111-01-04-51-DZT414-E	2110	WA01			516.00	258.00			
03/30/2026	TRD414	Replace TCO sp	TECO CNF	PRT 10083637	10289881	2	MN73	3111-01-04-51-DZT414-E	2110	WA01			416.16	674.16			
03/30/2026	TRD414	7/C Output Seal	TECO CNF	EXCP 10088633	10304960	1	MN73	3111-01-04-51-DZT414-D	2110	WA01			323.46	194.48			
03/29/2026	TRD414	Push arm crack	TECO CNF	EXCP 10088572	10304746	1	MN73	3111-01-04-51-DZT414-S	2110	WA01			898.93	124.93			
03/22/2026	TRD414	14D Svce PM Si	TECO CNF	PRT 10146588	10270597	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980		1,366.89	1,753.91			
03/12/2026	TRD414	SHIFT FAULT	TECO CNF	EXCP 10086301	10289851	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			1,465.08	368.58			
03/12/2026	TRD414	Front left cylind	TECO CNF	EXCP 10086282	10298884	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			258.00	0.00			
03/08/2026	TRD414	FIX E-STOP FA	TECO CNF	NMAT 10085659	10297355	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			129.00	0.00			
03/07/2026	TRD414	BROKEN RAIL	TECO CNF	EXCP 10085649	10297348	2	MN73	3111-01-04-51-DZT414-S	2110	WA01			387.00	0.00			
03/05/2026	TRD414	14D Svce PM Si	TECO CNF	GMP5 50143669	10265655	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980		10,781.29	10,395.81			
03/05/2026	TRD414	48W CMon Test	TECO CNF	PRT 10144506	10267188	3	MN73	3111-01-04-51-DZT414-S	2110	WA02	30095488		258.00	258.00			
03/05/2026	TRD414	28D Tech Insp	TECO CNF	PRT 10143668	10265654	3	MN73	3111-01-04-51-DZT414-V	2110	WA02	30107980		0.00	0.00			
03/01/2026	TRD414	14D Svce PM Si	TECO CNF	PRT 10140763	10261026	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980		2,339.45	1,823.56			
03/01/2026	TRD414	Breathesafe not	TECO CNF	EXCP 10084777	10295135	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			129.00	0.00			
02/23/2026	TRD414	Replace Missing	TECO CNF	EXCP 10084001	10292967	1	MN73	3111-01-04-51-DZT414-S	2110	WA01			305.85	47.85			
02/22/2026	TRD414	Replac AM/FM	TECO CNF	EXCP 10083823	10292641	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			358.13	229.12			
02/15/2026	TRD414	LHS front inner	TECO CNF	EXCP 10082921	10290027	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			387.00	0.00			
02/15/2026	TRD414	48W Sfty Insp	CTECO CNF	PRT 10136755	10254366	3	MN73	3111-01-04-51-DZT414	2110	WA02	30091955		387.00	387.00			
02/15/2026	TRD414	Ladder not dock	TECO CNF	PRT 10079876	10263050	3	MN73	3111-01-04-51-DZT414-D	2110	WA01			258.00	1,548.00			
02/15/2026	TRD414	28D Tech Insp	TECO CNF	PRT 10138003	10256434	3	MN73	3111-01-04-51-DZT414-V	2110	WA02	30107980		0.00	0.00			
02/14/2026	TRD414	14D Svce PM Si	TECO CNF	GMP5 50138002	10256433	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980		5,912.45	7,589.38			
02/13/2026	TRD414	Hot A/C	TECO CNF	EXCP 10082775	10289618	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			2,255.21	1,223.21			
02/13/2026	TRD414	Replac green b	TECO CNF	EXCP 10082826	10289692	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			481.78	288.28			
02/13/2026	TRD414	Ladder breaker	TECO CNF	EXCP 10082828	10289690	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			399.04	141.04			
02/13/2026	TRD414	AM/FM antenna	TECO CNF	EXCP 10082827	10289691	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			241.35	47.85			
02/10/2026	TRD414	PO Pirtek - Repl	TECO CNF	EXCP 10082359	10288582	1	MN73	3111-01-04-51-DZT414-S	2110	WA01			502.04	244.04			
02/03/2026	TRD414	CM - Inv Engine	TECO CNF	EXCP 10081362	10286218	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			950.29	692.29			
02/02/2026	TRD414	*PO*Coolant ho	TECO PCNF	EXCJ 10079878	10281724	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			784.03	655.03			
01/28/2026	TRD414	CM - Engine Fu	TECO CNF	EXCP 10080558	10283916	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			129.00	0.00			
01/24/2026	TRD414	lift cylinder cap	TECO CNF	GMP5 10080172	10282644	2	MN73	3111-01-04-51-DZT414-ik2110		WA01			3,516.92	2,226.92			
01/23/2026	TRD414	*PO*Replace fai	TECO CNF	EXCP 10079738	10281540	1	MN73	3111-01-04-51-DZT414-H	2110	WA01			1,838.23	1,580.23			
01/22/2026	TRD414	Remove and refi	TECO CNF	GMP5 10079929	10282014	1	MN73	3111-01-04-51-DZT414-D	2110	WA01			1,135.51	232.51			
01/22/2026	TRD414	14D Svce PM Si	TECO CNF	GMP5 50136337	10253659	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980		387.93	1,161.00			
01/21/2026	TRD414	Leaking grease	TECO CNF	EXCP 10079879	10281722	1	MN73	3111-01-04-51-DZT414-S	2110	WA01			1,366.06	868.54			
01/21/2026	TRD414	E-stop on ripper	TECO CNF	EXCP 10079737	10281549	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			516.49	0.48			
01/21/2026	TRD414	Transmission hc	TECO CNF	EXCP 10079740	10281542	1	MN73	3111-01-04-51-DZT414-D	2110	WA01			277.53	19.53			
01/21/2026	TRD414	12W Insp Fuel	TECO CNF	PRT 10135273	10251727	3	MN73	3111-01-04-51-DZT414	2110	WA02	30110107		258.00	193.50			
01/21/2026	TRD414	Low pressure fu	TECO CNF	EXCP 10079739	10281546	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			129.00	122.71			
01/21/2026	TRD414	Grease supply li	TECO CNF	PRT 10079880	10281721	1	MN73	3111-01-04-51-DZT414-S	2110	WA01			129.00	0.00			
01/21/2026	TRD414	24W Fire Sfty A	TECO CNF	PRT 10135272	10251726	3	MN73	3111-01-04-51-DZT414	2110	WA02	30110107		129.00	387.00			
01/21/2026	TRD414	28D Tech Insp	TECO CNF	PRT 10136335	10253657	3	MN73	3111-01-04-51-DZT414-V	2110	WA02	30107980		0.00	0.00			
01/20/2026	TRD414	14D Svce PM Si	TECO CNF	GMP5 50136333	10253655	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980		10,344.22	8,408.95			
01/20/2026	TRD414	Chassis Crack	TECO CNF	EXCP 10079707	10281281	1	MN73	3111-01-04-51-DZT414-S	2110	WA01			9,712.84	3,262.84			
01/20/2026	TRD414	Push arm knuck	TECO CNF	EXCP 10079708	10281275	1	MN73	3111-01-04-51-DZT414-S	2110	WA01			903.00	0.00			
01/16/2026	TRD414	RH Track lockin	TECO CNF	EXCP 10079150	10279873	2	MN73	3111-01-04-51-DZT414-D	2110	WA01			409.81	22.81			
01/07/2026	TRD414	Breathe-safe ala	TECO CNF	EXCP 10078022	10276924	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			258.00	0.00			
12/31/2025	TRD414	35D Svce PM Si	TECO PRC	SETC 50135259	10251713	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980		0.00	1,161.00			
12/30/2025	TRD414	Snapped left bla	TECO CNF	GMP5 10077152	10274323	2	MN73	3111-01-04-51-DZT414-H	2110	WA01			9,638.00	0.00			
12/23/2025	TRD414	14D Svce PM Si	TECO CNF	PRT 10136336	10253658	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980		2,984.41	1,823.40			
12/22/2025	TRD414	Ripper Boot mis	TECO CNF	EXCP 10076430	10272059	1	MN7										

Basic start date	Sort Field	Description	System status	Order	Notification	Priority	Main Work Center	Functional Location	Planning Plant	Order Type	Maintenance Plan	Selected Line	Total actual costs	Total planned costs	WBS element	Revision	Room
12/14/2025	TRD414	28D Tech Insp	TTECO CNF	PRT	150136334	10253656	3	MN73	3111-01-04-51-DZT414-V	2110	WA02	30107980	0.00	0.00			
12/10/2025	TRD414	E-stop fault	TECO CNF	EXCP	10074992	10267961	1	MN73	3111-01-04-51-DZT414-E	2110	WA01		258.00	0.00			
12/05/2025	TRD414	Breathe Safe fal	TECO CNF	EXCP	10074341	10266221	1	MN73	3111-01-04-51-DZT414-E	2110	WA01		387.00	0.00			
12/04/2025	TRD414	Rh track pitch e	TECO CNF	EXCP	10074108	10265770	1	MN73	3111-01-04-51-DZT414-D	2110	WA01		23,708.92	203.72			
12/04/2025	TRD414	*PO*machine n	TECO CNF	GMP5	10073523	10263932	2	MN73	3111-01-04-51-DZT414-E	2110	WA01		4,241.46	1,016.46			
12/04/2025	TRD414	LH blade push a	TECO CNF	EXCP	10074107	10265777	1	MN73	3111-01-04-51-DZT414-IA	2110	WA01		917.71	143.71			
12/02/2025	TRD414	RHS grease line	TECO CNF	EXCP	10073944	10264979	1	MN73	3111-01-04-51-DZT414-D	2110	WA01		306.30	177.30			
11/30/2025	TRD414	14D Svce PM Si	TECO CNF	GMP5	50136331	10253653	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980	3,006.81	3,006.82			
11/27/2025	TRD414	Wipe switch	TECO CNF	EXCP	10073307	10263343	1	MN73	3111-01-04-51-DZT414-E	2110	WA01		1,197.36	681.34			
11/27/2025	TRD414	*PO*Grease hos	TECO CNF	EXCP	10073306	10263342	1	MN73	3111-01-04-51-DZT414-S	2110	WA01		1,068.95	294.95			
11/27/2025	TRD414	Replace faulty v	TECO CNF	GMP5	10073354	10263338	2	MN73	3111-01-04-51-DZT414-E	2110	WA01		920.11	560.44			
11/27/2025	TRD414	LHS door wiper	TECO CNF	NMAT	10073348	10263365	1	MN73	3111-01-04-51-DZT414-S	2110	WA01		258.00	0.00			
11/26/2025	TRD414	Ladder Fault	TECO CNF	EXCP	10073134	10262948	1	MN73	3111-01-04-51-DZT414-E	2110	WA01		516.00	0.00			
11/26/2025	TRD414	70D Tech Insp	TTECO NMAT	PRC	50135155	10251532	3	MN73	3111-01-04-51-DZT414-V	2110	WA02	30107980	0.00	0.00			
11/26/2025	TRD414	35D Svce PM Si	TECO PRC	SETC	50135156	10251533	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980	0.00	5,031.00			
11/15/2025	TRD414	X-SAMPLE TRA	TECO CNF	EXCP	10071992	10259550	2	MN73	3111-01-04-51-DZT414-D	2110	WA01		1,843.56	1,327.58			
11/13/2025	TRD414	14D Svce PM Si	TECO CNF	GMP5	50136195	10253487	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980	12,236.43	10,301.65			
11/13/2025	TRD414	*RTW* Replace	TECO CNF	GMP5	10067829	10246941	2	MN73	3111-01-04-51-DZT414-D	2110	WA01		1,111.37	1,111.38			
11/13/2025	TRD414	Install Momenta	TECO CNF	PRT	10065330	10239980	2	MN73	3111-01-04-51-DZT414	2110	WA01		935.63	935.63			
11/13/2025	TRD414	SMPL-C - Coola	TECO CNF	PRT	10070795	10255503	3	MN73	3111-01-04-51-DZT414-D	2110	WA01		293.75	293.75			
11/13/2025	TRD414	28D Tech Insp	TTECO CNF	PRT	150136194	10253486	3	MN73	3111-01-04-51-DZT414-V	2110	WA02	30107980	0.00	0.00			
11/12/2025	TRD414	Ladder fault	TECO CNF	GMP5	10071712	10258609	1	MN73	3111-01-04-51-DZT414	2110	WA01		304.92	46.92			
11/08/2025	TRD414	Breath Safe	TECO CNF	EXCP	10071113	10257256	1	MN73	3111-01-04-51-DZT414-S	2110	WA01		1,507.02	668.55			
11/02/2025	TRD414	TRD414 replace	TECO CNF	EXCP	10070365	10255192	1	MN73	3111-01-04-51-DZT414-D	2110	WA01		139.96	139.95			
11/01/2025	TRD414	**PO** Low cool	TECO PCNF	EXCF	10070031	10254159	1	MN73	3111-01-04-51-DZT414-E	2110	WA01		5,067.91	3,066.27			
10/31/2025	TRD414	REPLACE RH D	TECO CNF	EXCP	10070246	10254618	2	MN73	3111-01-04-51-DZT414-S	2110	WA01		1,002.46	486.45			
10/31/2025	TRD414	RH turbo drain	TECO CNF	PRT	10070274	10254714	1	MN73	3111-01-04-51-DZT414-E	2110	WA01		260.14	2.14			
10/26/2025	TRD414	Coolant Leak	TECO CNF	EXCP	10069580	10252808	1	MN73	3111-01-04-51-DZT414-E	2110	WA01		774.00	0.00			
10/23/2025	TRD414	Blown Coolant	TECO CNF	EXCP	10069308	10251996	1	MN73	3111-01-04-51-DZT414-E	2110	WA01		769.65	253.64			
10/22/2025	TRD414	CM - Resample	TECO CNF	EXCP	10069045	10251492	1	MN73	3111-01-04-51-DZT414	2110	WA01		329.50	71.50			
10/22/2025	TRD414	TRD414 Prograi	TECO CNF	EXCP	10069095	10251558	1	SN28	3111-01-04-51-DZT414-E	2110	WA01		0.00	0.00			
10/20/2025	TRD414	*PO* Repl missi	TECO PCNF	EXCF	10067607	10248182	1	MN73	3111-01-04-51-DZT414	2110	WA01		13,094.54	9,252.86			
10/20/2025	TRD414	Re-Mob Works	TECO CNF	EXCP	10068791	10250803	2	MN73	3111-01-04-51-DZT414	2110	WA01		2,733.21	2,346.21			
10/13/2025	TRD414	Access ladder b	TECO CNF	EXCP	10067775	10248444	1	MN73	3111-01-04-51-DZT414-S	2110	WA01		2,028.15	645.02			
10/12/2025	TRD414	*PO*ReplaceMis	TECO CNF	EXCP	10067715	10248265	1	MN73	3111-01-04-51-DZT414-E	2110	WA01		6,034.86	5,196.54			
10/12/2025	TRD414	Replace turbo tin	TECO CNF	EXCP	10067618	10248187	1	MN73	3111-01-04-51-DZT414	2110	WA01		3,374.33	2,664.83			
10/01/2025	TRD414	*PO*Liner Repla	TECO CNF	GMP5	10064563	10239608	2	MN73	3111-01-04-51-DZT414	2110	WA01		72,928.57	73,702.41			
09/23/2025	TRD414	16000H Repl Nc	TECO CNF	PRC	50093382	10181881	1	MN73	3111-01-04-51-DZT414-E	2110	WA02	30107965	0.00	0.00			
09/20/2025	TRD414	Remove LHS tra	TECO CNF	EXCP	10064691	10239965	1	MN73	3111-01-04-51-DZT414	2110	WA01		387.00	0.00			
09/19/2025	TRD414	TRD414 - Re ins	TECO CNF	EXCP	10064953	10240688	1	SN28	3111-01-04-51-DZT414-E	2110	WA01		5,837.23	5,837.24			
07/29/2025	TRD414	24W Fire Sfty A	TECO CNF	NMAT	50099974	10192699	3	MN73	3111-01-04-51-DZT414	2110	WA02	30110107	258.00	0.00			N/A
07/29/2025	TRD414	12W Insp Fuel F	TECO CNF	NMAT	50099975	10192700	3	MN73	3111-01-04-51-DZT414	2110	WA02	30110107	258.00	0.00			N/A
07/13/2025	TRD414	35D Svce PM Si	TECO CNF	MACN	50096769	10187480	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980	2,580.00	2,424.10			UP
07/09/2025	TRD414	16000H Insp Ch	TECO CNF	NMAT	50064461	10135629	3	MN73	3111-01-04-51-DZT414-S	2110	WA02	30107954	516.00	0.00			
07/09/2025	TRD414	Repair Broken I	TECO CNF	NMAT	10022932	10121882	2	MN73	3111-01-04-51-DZT414-S	2110	WA01		258.00	0.00			
07/09/2025	TRD414	Replace Implem	TECO CNF	MACN	10022935	10121880	3	MN73	3111-01-04-51-DZT414-H	2110	WA01		258.00	262.17			
07/09/2025	TRD414	Replace Wrong	TECO CNF	MACN	10023068	10122368	2	MN73	3111-01-04-51-DZT414-H	2110	WA01		258.00	632.77			
07/09/2025	TRD414	Replace Fan Ho	TECO CNF	MACN	10026019	10128658	2	MN73	3111-01-04-51-DZT414	2110	WA01		258.00	632.77			
07/09/2025	TRD414	Window Sprayer	TECO CNF	NMAT	10031161	10145667	3	MN73	3111-01-04-51-DZT414-S	2110	WA01		258.00	0.00			
07/09/2025	TRD414	4000H Calb Tra	TECO CNF	MACN	50063238	10133972	3	MN73	3111-01-04-51-DZT414-D	2110	WA02	30107953	258.00	46.08			UP
07/09/2025	TRD414	Reseal Priority	TECO CNF	MACN	10023067	10122370	3	MN73	3111-01-04-51-DZT414-H	2110	WA01		129.00	10.13			
07/09/2025	TRD414	Blade and acces	TECO CNF	NMAT	10023413	10123223	2	MN73	3111-01-04-51-DZT414-IA	2110	WA01		129.00	0.00			
07/09/2025	TRD414	Replace LH doo	TECO CNF	MACN	10026911	10135372	2	MN73	3111-01-04-51-DZT414-S	2110	WA01		129.00	3,135.68			
07/09/2025	TRD414	Replace wiper a	TECO CNF	NMAT	10040126	10166679	3	MN73	3111-01-04-51-DZT414-E	2110	WA01		129.00	0.00			
07/04/2025	TRD414	*B HSTY* Remo	TECO CNF	EXCP	10055149	10214687	2	MN73	3111-01-04-51-DZT414-D	2110	WA01		1,181.66	990.08			
07/02/2025	TRD414	16000H Repl En	TECO GMP5	MAC	50064466	10135634	3	MN73	3111-01-04-51-DZT414-E	2110	WA02	30107954	-10,745.55	-418,852.93			UP
07/01/2025	TRD414	Decommission	TTECO CNF	NMAT	10053943	10211341	2	SN28	3111-01-04-51-DZT414-E	2110	WA01		0.00	0.00			
06/16/2025	TRD414	Replace Springs	TECO CNF	EXCP	10052908	10208234	1	MN73	3111-01-04-51-DZT414-D	2110	WA01		678.28	0.00			
06/12/2025	TRD414	24W Stat Insp	F TTECO PRC	SETC	50090995	10177872	3	MN73	3111-01-04-51-DZT414	2110	WA02	30104792	0.00	793.82			
06/08/2025	TRD414	35D Svce PM Si	TECO PRC	SETC	50088843	10175108	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980	0.00	0.00			
05/28/2025	TRD414	Investigate PTX	TECO CNF	NMAT	10031599	10147542	3	SN28	3111-01-04-51-DZT414-E	2110	WA01		0.00	0.00			
05/20/2025	TRD414	Replace All rippi	TECO CNF	GMP5	10032570	10145453	2	MN73	3111-01-04-51-DZT414-H	2110	WA01		6,200.52	-11,161.00			Z
05/12/2025	TRD414	16000H Repl Pu	TECO MACM	PRC	50064459	10135627	3	MN73	3111-01-04-51-DZT414-E	2110	WA02	30107954	0.00	387.00			UP
05/05/2025	TRD414	16000H Repl Hc	TECO MACM	PRC	50064463	10135631	3	MN73	3111-01-04-51-DZT414-E	2110	WA02	30107954	0.00	10,579.51			UP
05/05/2025	TRD414	16000H Repl Hc	TECO MACM	PRC	50064464	10135632	3	MN73	3111-01-04-51-DZT414-E	2110	WA02	30107954	0.00	6,722.99			UP
05/05/2025	TRD414	16000H Repl In	TECO MSPT	PRC	50064465	10135633	3	MN73	3111-01-04-51-DZT414-E	2110	WA02	30107954	0.00	16,924.68			UP
05/04/2025	TRD414	8000H OviH A/C	TECO MSPT	PRC	50049244	10112768	3	MN73	3111-01-04-51-DZT414-S	2110	WA02	30107952	0.00	17,923.07			UP
05/04/2025	TRD414	16000H Repl Hc	TECO MACM	PRC	50064460	10135628	3	MN73	3111-01-04-51-DZT414-E	2110	WA02	30107954	0.00	1,975.24			UP
05/04/2025	TRD414	16000H Repl Ac	TECO MACM	PRC													

Basic start date	Sort Field	Description	System status	Order	Notification	Priority	Main Work Center	Functional Location	Planning Plant	Order Type	Maintenance Plan	Selected Line	Total actual costs	Total planned costs	WBS element	Revision	Room
03/24/2025	TRD414	Missing Segmer	TECO CNF	EXCP 10042658	10180858	1	MN73	3111-01-04-51-DZT414	2110	WA01			421.50	292.50			
03/23/2025	TRD414	35D Svce PM Si	TECO CNF	GMP5 50074146	10151689	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980		1,304.35	1,305.26			UP
03/22/2025	TRD414	Engine oil and fi	TECO CNF	EXCP 10042553	10180457	1	MN73	3111-01-04-51-DZT414	2110	WA01			1,245.04	400.91			
03/18/2025	TRD414	Ladder Fault	TECO CNF	EXCP 10041900	10179232	1	MN73	3111-01-04-51-DZT414	2110	WA01			1,300.68	526.68			
03/05/2025	TRD414	CM – Investigate	TECO CNF	EXCP 10040244	10172619	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			3,191.00	218.26			
02/27/2025	TRD414	damage speed	TECO CNF	EXCP 10039469	10170578	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			533.78	275.78			
02/26/2025	TRD414	FAILED ROLLEIT	TECO CNF	EXCP 10039348	10170238	1	MN73	3111-01-04-51-DZT414-D	2110	WA01			5,347.57	4,057.57			
02/23/2025	TRD414	TRD414 No GP	TECO CNF	EXCP 10038903	10169085	2	SN28	3111-01-04-51-DZT414-E	2110	WA01			0.00	0.00			
02/21/2025	TRD414	48W Sfty Insp	CTECO CNF	PRT I 50057296	10125021	3	MN73	3111-01-04-51-DZT414	2110	WA02	30091955		774.00	387.00			
02/21/2025	TRD414	24W Fire Sfty	ATECO CNF	PRT I 50065366	10137188	3	MN73	3111-01-04-51-DZT414	2110	WA02	30110107		387.00	387.00			
02/21/2025	TRD414	12W Insp Fuel	FTECO CNF	PRT I 50065367	10137189	3	MN73	3111-01-04-51-DZT414	2110	WA02	30110107		387.00	193.50			
02/20/2025	TRD414	35D Svce PM Si	TECO PCNF	GMP 50067389	10140818	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980		10,264.49	7,803.51			UP
02/14/2025	TRD414	Pos 3 Hot Roller	TECO CNF	EXCP 10037786	10166478	1	MN73	3111-01-04-51-DZT414	2110	WA01			4,125.68	3,103.97			
02/01/2025	TRD414	Operator called	TECO CNF	EXCP 10036448	10162576	1	MN73	3111-01-04-51-DZT414-D	2110	WA01			16,610.37	-7,491.21			
01/27/2025	TRD414	*RTW*STEERIN	TECO CNF	EXCP 10035811	10160808	1	MN73	3111-01-04-51-DZT414-D	2110	WA01			12,119.11	106.26			
01/27/2025	TRD414	FAILED SEAT	TECO CNF	EXCP 10035831	10160841	1	MN73	3111-01-04-51-DZT414-S	2110	WA01			4,259.85	4,001.85			
01/16/2025	TRD414	35D Svce PM Si	TECO PCNF	GMP 50061521	10132255	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980		2,627.52	3,275.64			UP
12/30/2024	TRD414	INVESTIGATE	TECO CNF	EXCP 10032780	10151831	1	MN73	3111-01-04-51-DZT414-H	2110	WA01			3,213.78	504.79			
12/17/2024	TRD414	GREASE FAULT	TECO CNF	EXCP 10031691	10148133	1	MN73	3111-01-04-51-DZT414-S	2110	WA01			516.00	0.00			
12/17/2024	TRD414	BREATHESAFE	TECO CNF	EXCP 10031692	10148134	1	MN73	3111-01-04-51-DZT414-S	2110	WA01			516.00	0.00			
12/16/2024	TRD414	Replace Pos 3	FTECO CNF	EXCP 10031545	10147755	1	MN73	3111-01-04-51-DZT414-D	2110	WA01			4,128.86	2,838.84			
12/15/2024	TRD414	48W Stat Insp	FTECO CNF	PRT I 50052968	10118427	3	MN73	3111-01-04-51-DZT414	2110	WA02	30104792		2,061.67	2,061.67			UP
12/15/2024	TRD414	Replace Seat B	TECO CNF	PRT I 10022931	10121878	2	MN73	3111-01-04-51-DZT414-S	2110	WA01			1,269.36	495.37			
12/15/2024	TRD414	Inspect Gear Se	TECO CNF	PRT I 10021608	10117568	2	MN73	3111-01-04-51-DZT414-D	2110	WA01			387.00	1,419.00			
12/14/2024	TRD414	35D Svce PM Si	TECO PCNF	GMP 50050039	10114098	3	MN73	3111-01-04-51-DZT414	2110	WA02	30107980		4,992.09	8,217.10			UB
12/12/2024	TRD414	*PO*Excessive	TECO CNF	EXCP 10031257	10146759	1	MN73	3111-01-04-51-DZT414-D	2110	WA01			81,855.63	73,186.78			
12/11/2024	TRD414	Ladder Fault	TECO CNF	EXCP 10031075	10146383	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			550.87	34.87			
12/10/2024	TRD414	R/H track pitch	TECO CNF	EXCP 10031056	10146123	1	MN73	3111-01-04-51-DZT414-D	2110	WA01			22,132.68	1,683.32			
12/10/2024	TRD414	L/H rear idler	haTECO CNF	EXCP 10031057	10146124	1	MN73	3111-01-04-51-DZT414-D	2110	WA01			14,379.37	9,339.84			
12/10/2024	TRD414	Filler cap fallen	TECO CNF	EXCP 10031015	10146079	1	MN73	3111-01-04-51-DZT414	2110	WA01			234.66	105.66			
12/05/2024	TRD414	Replace Blower	TECO CNF	PRT I 10030314	10144370	1	MN73	3111-01-04-51-DZT414-S	2110	WA01			1,316.04	284.04			
12/05/2024	TRD414	Replace E stop	TECO CNF	PRT I 10030323	10144392	1	MN73	3111-01-04-51-DZT414	2110	WA01			583.12	67.12			
11/26/2024	TRD414	Ladder fault	TECO CNF	EXCP 10029313	10141376	1	MN73	3111-01-04-51-DZT414-S	2110	WA01			516.00	0.00			
11/25/2024	TRD414	Work lights u/s	TECO CNF	EXCP 10029151	10140999	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			2,469.36	2,544.42			
11/11/2024	TRD414	torque convertor	TECO CNF	EXCP 10027510	10136643	2	MN73	3111-01-04-51-DZT414-D	2110	WA01			5,556.60	2,915.72			
11/09/2024	TRD414	*RTW*Steering	TECO CNF	PRT I 10027202	10135974	1	MN73	3111-01-04-51-DZT414	2110	WA01			8,276.75	3,251.12			
11/09/2024	TRD414	Overheating issi	TECO CNF	EXCP 10027203	10135975	1	MN73	3111-01-04-51-DZT414	2110	WA01			1,004.01	230.02			
11/04/2024	TRD414	Engine over hea	TECO CNF	PRT I 10026510	10129546	1	MN73	3111-01-04-51-DZT414	2110	WA01			387.00	0.00			
11/04/2024	TRD414	MACHINE OVER	TECO CNF	EXCP 10026533	10129590	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			0.00	0.00			
11/01/2024	TRD414	EngineTrans O	TECO CNF	PRT I 10026374	10129304	1	MN73	3111-01-04-51-DZT414	2110	WA01			387.00	0.00			
10/15/2024	TRD414	steering fault	TECO CNF	EXCP 10023985	10125663	1	MN73	3111-01-04-51-DZT414-D	2110	WA01			516.00	0.00			
10/08/2024	TRD414	Wrong fan hose	TECO CNF	EXCP 10023056	10122365	2	MN73	3111-01-04-51-DZT414-H	2110	WA01			0.00	0.00			
10/08/2024	TRD414	Wrong fan hose	TECO CNF	EXCP 10023057	10122367	2	MN73	3111-01-04-51-DZT414-H	2110	WA01			0.00	0.00			
10/07/2024	TRD414	Wrong Fan Hos	TECO CNF	EXCP 10022884	10121879	2	MN73	3111-01-04-51-DZT414-H	2110	WA01			258.00	0.00			
10/07/2024	TRD414	Worn fast fill	hoseTECO CNF	EXCP 10022888	10121922	2	MN73	3111-01-04-51-DZT414-H	2110	WA01			258.00	0.00			
10/06/2024	TRD414	AIR FILTER RE	TECO CNF	PRT I 10022828	10121651	1	MN73	3111-01-04-51-DZT414-E	2110	WA01			760.22	244.22			
09/09/2024	TRD414	Grease Fault	TECO CNF	EXCP 10019295	10111337	2	MN73	3111-01-04-51-DZT414-S	2110	WA01			2,122.74	1,606.75			
													574,736.04	42,564.38			