KEEP ON TRUCKIN'
MECHANICAL SERVICES LTD.
780 205 0775

INVOICE

Keep On Truckin Mechanical Services Ltd

PO Box 12459 RPO 10
Lloydminster, Ab
T9V 3C6
keepontruckin@live.ca

Date	Invoice #
11/06/26	21749

Invoice To

BEAMISH FARMS LTD
BOX 2127
LLOYD, SASK
S9V 1R6

P.O. No.	Terms	UNIT #
	Net 45	

Item	Description	Qty	Rate	Amount
	1986 INTERNATIONAL SERIAL#2HSFBJXR3GCA15586 PLATE#185KNA SK ODO:50787KMS 7558 HRS CVIP / SPEEDOMETER / AIR LEAK / DASH LIGHTS Performed SK safety inspection R&R unevenly worn #3 rh brake shoes due to failed and broken anchor spring, replaced leaking wheel seal, R&R worn drum R&R #1 rh and #2 lh/rh clevis pins/bushings, unbolted #2 lh brake pot and moved up in mount holes to correct push rod angle R&R worn 5th wheel saddle pins/bushings, adjusted 5th wheel Repaired poor cab light ground and replaced bulb Checked for no rh mirror heat, found power wire off switch and mirror heat power wire disconnected, connected and verified proper operation Repaired wires at vehicle speed sensor for speedometer Repaired reverse light wire in frame mid way down chassis, repaired reverse light wire at light. Repaired/cleaned poor connection for hood marker light inside housing. Repaired poor ground for roof light. Plugged in several unplugged gauge lights R&R leaking transmission output oil seal, R&R worn driveshaft steady bearing. Removed interaxle and tightened loose front diff output and rear diff input yolk nuts Troubleshot air leak under hood, valve for shutters leaking air but shutters removed, removed air supply from valve no longer being used Replaced missing frame/crossmember bolt Wiper knob cracked so loose on switch, knob obsolete so placed clamp on knob to tighten on switch Sent for test drive, speedometer now works and transmission leak fixed			

FOR YOUR CONVENIENCE WE ACCEPT MASTERCARD, VISA
(2.5% charge for Mastercard/Visa) INTERAC and e-transfer
keepontruckin@live.ca
***Please retorque wheels between 100-150kms**
All invoices over 30 days are subject to 2.5% interest charge

Subtotal	
Payments/Credits	
GST	
Balance Due	

GST/HST No. 811750454

KEEP ON TRUCKIN'
MECHANICAL SERVICES LTD.
780 205 0775

INVOICE

Keep On Truckin Mechanical Services Ltd

PO Box 12459 RPO 10
Lloydminster, Ab
T9V 3C6
keepontruckin@live.ca

Date	Invoice #
11/06/26	21749

Invoice To

BEAMISH FARMS LTD
BOX 2127
LLOYD, SASK
S9V 1R6

P.O. No.	Terms	UNIT #
	Net 45	

Item	Description	Qty	Rate	Amount
	Greased unit, checked levels and stickered			
	PARTS			
SASK DECAL	SASK DECAL	1	20.00	20.00
Parts	HK4515Q-34 BAGGED HARDWARE KIT	1	16.06	16.06
Parts	SSD6799 BRAKE DRUM	1	418.31	418.31
Parts	K2262 REAR SEAL	1	44.79	44.79
Parts	XSS714515QK BRAKE SHOES	1	68.88	68.88
Parts	0202-6-6G PIPE COUPLING FNPTX FNPT	1	2.66	2.66
RK069731 PIN &...	RK069731 BRACKET PIN & BUSHING KIT	1	149.44	149.44
1/2 X 1-1/2 CAPS...	1/2 X 1-1/2 NC ZINC GRADE 8 HEX HEAD CAPSCREW	3	0.50	1.50
1/2 FLAT WASH...	1/2 FLAT WASHER	6	0.18	1.08
STOVER LOCKN...	1/2 STOVER LOCKNUT	3	0.27	0.81
50/50 COOLANT ...	ACT GREEN UNIVERSAL A/F 50/50	11.34	2.97	33.68
3929131 WHEEL ...	WHEEL SEAL DRIVE OIL SEAL GRIT GUARD 2106	1	78.44	78.44
CLEVIS PIN 5/8"...	CLEVIS PIN 5/8"	2	1.60	3.20
BUSHING CLEV...	5/8 CLEVIS BUSHING	3	4.63	13.89
5/8 X 1 3/4 CAPS...	5/8 X 1 3/4 NC ZINC GRADE 8 HEX HEAD CAPSCREW	2	1.35	2.70
5/8 STOVER	5/8" STOVER LOCKNUT	2	0.49	0.98
5/8 FLAT WASH...	5/8 FLAT WASHER	4	0.29	1.16
CLEVIS PIN 1/2"...	CLEVIS PIN 1/2"	2	1.31	2.62
BUSHING CLEV...	CLEVIS BUSHING	2	3.63	7.26
CENTER BEARI...	CENTER BEARING ASSEMBLY	1	149.81	149.81
LABOUR	LABOUR	19.72	155.00	3,056.60
SHOP SUPPLIES...	SHOP SUPPLIES (L)	1	150.00	150.00
	GST on sales		5.00%	211.19

FOR YOUR CONVENIENCE WE ACCEPT MASTERCARD, VISA
(2.5% charge for Mastercard/Visa) INTERAC and e-transfer
keepontruckin@live.ca
***Please retorque wheels between 100-150kms**
All invoices over 30 days are subject to 2.5% interest charge

Subtotal	**$4,223.87**
Payments/Credits	**$0.00**
GST	**$211.19**
Balance Due	**$4,435.06**

GST/HST No. 811750454