Schmidt's Auto
260 Pembina Ave East, Box 190
Winkler, MB. R6W 4A5
Phone: 204-325-5206 Fax: 204-325-6820
QUALITY AUTOMOTIVE SERVICE YOU CAN TRUST!

INVOICE
40602
Org. Est. # 053125
GST # R 820967180

INVOICE

Printed Date: 03/25/2022 **Work Completed: 03/25/2022**

[redacted]

2012 Ford - Pickup F350 Super Duty - 6.2L, V8 (379CI) VIN(6)
Lic # : CHX660 Odometer In : 125040

VIN # : 1FT7W3B67 **CEA09138**

Part Description / *Number*	Qty	Sale	Ext
LONG BLOCK - F350 Super Duty,Gas/Ethanol *BC3Z 6006 ERM*	1.00	6,642.35	6,642.35
Lift Support *3B897006*	2.00	27.14	54.28
Tailored Resistor Ignition Wire Set *6937K*	1.00	197.15	197.15
Exhaust Manifold *674-988*	1.00	125.25	125.25
Engine Block Heater *3100002*	1.00	79.28	79.28
Automatic Transmission Front Pump Seal *710852*	1.00	32.96	32.96
PCV Valve *V449*	1.00	15.74	15.74
Exhaust Manifold *674-987*	1.00	125.79	125.79
Ignition Coil - OE Manufacturer *IC742*	3.00	135.31	405.93
Ignition Coil *C823*	3.00	92.48	277.44
Air Filter *49883*	1.00	29.46	29.46
Capacitor Assy *AL1Z18801A*	2.00	17.64	35.28
Turn signal/Wiper switch *CBS2141*	1.00	76.41	76.41
Flat Wiper Blade *C22UB*	2.00	19.74	39.48
LONG LIFE ANTI-FREEZE *LLAF*	4.00	5.99	23.96
Shop Supplies			21.50

Labor Description	Hours	Ext
Diagnose engine noise Removed left valve cover and found all intake valves bent Timing chain has jumped, possible tensioner broken Would recommend engine replacement due to it consuming alot of oil	1.00	92.00
ENGINE ASSEMBLY (COMPLETE) - Remove & Replace - F250 Super Duty,F350 Super Duty,Gas/Ethanol w/Air Cond - [Includes: R&I Engine Assembly. Transfer Fuel and Electrical Assemblies and Engine Mounts. DOES NOT include transfer of Manifolds, Valve Cover(s), Tim	18.10	1,665.20
Replaced wiper switch, wipers would come on while driving Replaced wipers	1.25	115.00
Replaced 6 ignition coils, damaged after removal		
Replaced front pump seal on transmission		
Replaced hood shocks		
Replaced exhaust manifold - right side was cracked		
Install new block heater		

[Recommendations]
Next oil change occurs at 129,040 Kilometers - Conv. Motor Oil

Taxes	
GST	502.72
PST	703.81

Email Address:***schmidtsautoshop@gmail.com***

Copyright (c) 2022 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

Schmidt's Auto
260 Pembina Ave East, Box 190
Winkler, MB. R6W 4A5
Phone: 204-325-5206 Fax: 204-325-6820
QUALITY AUTOMOTIVE SERVICE YOU CAN TRUST!

INVOICE
40602
Org. Est. # 053125
GST # R 820967180

INVOICE

Printed Date: 03/25/2022 **Work Completed: 03/25/2022**

[redacted]

2012 Ford - Pickup F350 Super Duty - 6.2L, V8 (379CI) VIN(6)
Lic # : CHX660 Odometer In : 125040

VIN # : 1FT7W3B67 **CEA09138**

Part Description / *Number*	Qty	Sale	Ext	Labor Description	Hours	Ext

Org. Estimate 11,260.99 Revisions 0.00 Current Estimate 11,260.99

Labor:	**1,872.20**
Parts:	**8,182.26**
SubTotal:	**10,054.46**
Tax:	**1,206.53**
Total:	**11,260.99**
Bal Due:	**$11,260.99**

[Payments -]

Vehicle Received: 3/25/2022

Customer Number : 2491

Schmidt's Auto is not responsible for loss or damage to vehicles or articles left in vehicle in case of fire , theft, or any other cause beyond our control. Wheel Nuts are torqued to factory specifications & must be rechecked after 75 KMS. I hereby authorize my indebtness in the amount showing and agree to pay the balance owing hereon. 2% monthly late fee charged on accounts over 30 days.

Signature _____ Date_____

Email Address:***schmidtsautoshop@gmail.com***

Service Advisor : SCHMIDT, HENRY JR, Tech : MARTINS, JIMMY

Copyright (c) 2022 Mitchell Repair Information Company, LLC invhrs 5.12.21kr