

A01-285



Ramsey Truck and Auto Repair Inc
883-A Doris Drive
Evansdale, IA 50707

3192390764

ramseyrepair@outlook.com

Invoice

Date	Invoice #
10/11/2024	10026

P.O. No.

Terms
Due on receipt

Bill To
Vieth Construction Corp 6419 Nordic Drive Cedar Falls, IA 50613

FT-035

Unit#	Mileage	Make	Model	VIN#	License Plate#	Year
	101500	Ram	2500	3CGUR5HL1KG682170	JHS 084	2019

Quantity	Description	Rate	Amount
1	ABS Sensor	74.00	74.00T
1	Alignment Light Truck	99.95	99.95T
0.5	Labor	110.00	55.00T
	Replaced LR speed sensor. Aligned.		
	Sales Tax	7.00%	16.03
Late fee computed at 1.5% monthly to invoices over 30 days. Annual rate of 18%.			
Thank you for your business.		Total	\$244.98

A01-285



Ramsey Truck and Auto Repair Inc
883-A Doris Drive
Evansdale, IA 50707

3192390764

ramseyrepair@outlook.com

Invoice

Date	Invoice #
10/7/2024	10007

P.O. No.

Terms
Due on receipt

Bill To
Vieth Construction Corp 6419 Nordic Drive Cedar Falls, IA 50613

Unit#	Mileage	Make	Model	VIN#	License Plate#	Year
	100851	Ram	2500		JHS 084	2019

Quantity	Description	Rate	Amount
1	Wheel Seal	38.48	38.48T
1	Cabin Air Filter	29.36	29.36T
1	Oil Filter	7.40	7.40T
1	Fuel Filter	101.05	101.05T
1	Fuel Filter	81.97	81.97T
1	Air Filter	60.04	60.04T
1.5	Labor	110.00	165.00T
	Serviced.		
	Replaced LR wheel seal.		
	Sales Tax	7.00%	33.83
FT-0355 Late fee computed at 1.5% monthly to invoices over 30 days. Annual rate of 18%.			
Thank you for your business.		Total	\$517.13

AD1-285



Ramsey Truck and Auto Repair Inc
883-A Doris Drive
Evansdale, IA 50707

3192390764

ramseyrepair@outlook.com

Invoice

Date	Invoice #
9/24/2025	11286

P.O. No.

Terms
Due on receipt

Bill To
Vieth Construction Corp 6419 Nordic Drive Cedar Falls, IA 50613

Unit#	Mileage	Make	Model	VIN#	License Plate#	Year
	133493	Ram	2500 HD	FF-035	JHS 084	2020

Quantity	Description	Rate	Amount
1	Wheel Seal	40.83	40.83T
1	Brake Pads	100.74	100.74T
1	Air Filter	66.53	66.53T
1	Oil Filter	7.75	7.75T
1	Fuel Filter	102.68	102.68T
1	Fuel Filter	91.08	91.08T
3.5	Oil 15w-40	20.22	70.77T
4	Labor	120.00	480.00T
	Serviced and changed air filter. Replaced left rear wheel seal. Replaced rear brakes. Sales Tax	7.00%	67.23
	Late fee computed at 1.5% monthly to invoices over 30 days. Annual rate of 18%.		
Thank you for your business.		Total	\$1,027.61

A01-285

Ramsey Truck and Auto Repair Inc
883-A Doris Drive
Evansdale, IA 50707

3192390764 ramseyrepair@outlook.com

Invoice

Date	Invoice #
3/23/2026	11915

Bill To
Vieth Construction Corp 6419 Nordic Drive Cedar Falls, IA 50613

P.O. No.

Terms
Due on receipt

FT-035

Unit#	Mileage	Make	Model	VIN#	License Plate#	Year
	138068	Ram	2500		JHS 084	2019

Quantity	Description	Rate	Amount
1	Cabin Air Filter	28.01	28.01T
1	Oil Filter	11.92	11.92T
1	Air Filter	57.09	57.09T
1	Crankcase filter	147.27	147.27T
1	Fuel Filter	49.51	49.51T
1	DEF	21.46	21.46T
3.5	Oil 10W-30 Diesel	26.88	94.08T
1	Computer Hook-Up Fee	40.00	40.00T
2.5	Labor	120.00	300.00T
1.5	Labor	120.00	180.00T
	Serviced. Replaced crank case filter. Added DEF fluid. Cleared codes. Test drove until limit light turned off. Sales Tax	7.00%	65.05
	Late fee computed at 1.5% monthly to invoices over 30 days. Annual rate of 18%.		

Thank you for your business.	Total	\$994.39
------------------------------	--------------	----------