

MID COUNTRY MACHINERY, LLC.

4718 Sergeant Road

Waterloo, IA 50701

319-234-8710

www.midcountry.com

A01-48

Ship To:	SAME AS BELOW
Invoice To:	Vieth Construction Corp
	6419 Nordic Dr Cedar Falls IA 50613

Branch WATERLOO		
Date 02/21/24	Time 16:01:52 (O)	Page 01
Account No. VIETH001	Phone No. 3192771006	Invoice No. W15994
Ship Via	Purchase Order	
		Salesperson 144

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
W000501	BOMAG BW142-PDB-2	2674	1365105111002	
	BW142PDB-2			

SEGMENT# 1 C 166 NA 02/09/24 02/14/24

FUEL AND HYDRAULIC LEAK

CORRECTION:

2/14/24 TB

FOUND FUEL LEAK. RAN NEW FUEL RETURN LINES. IDENTIFIED
HYDRAULIC LEAK AND LOOKED UP PARTS AND LOOK AT THE BACK UP
ALARM WIRING.

2/15/24 TB

PULLED INSIDE FOLLOWED WIRING FOR BACK UP ALARM AND
REPLACED WIRES AND RELAY, RE-WIRED BACKUP ALARM, POWER
WASHED THE MACHINE AND LOOKED UP BACK UP ALARM SWITCH GOT
PART NUMBERS TO ORDER PARTS.

2/19/24 TB CP

CHANGED HYDRAULIC FILTER AND O-RING, RAN NEW WIRING TO MAKE
THE NEW SWITCH WORK. INSTALLED SEAT BELT.

2/20/24 TB CP

FINISHED WIRING. THE SWITCH WASN'T WORKING BECAUSE THE
PROXIMITY WAS TOO FAR AWAY. PUT COVERS BACK ON AND OPERATED
FOR 30 MINUTES TO MAKE SURE IT WASN'T LEAKING.

DONE

ADDITIONAL DESCRIPTION:

LOAD TEST BATTERY, CLEAN, INSPECK AND TIGHTEN TERMINALS.

HAS FUEL LEAK.

HAS HYDRAULIC LEAK.

NEEDS BACK-UP ALARM CORRECTED.

NEEDS SEAT BELT KIT INSTALLED (PROVIDED BY VIETH).

IFRT

05750879

06220882

INBND FREIGHT

Pulse generator

ORING

1	30.67	30.67
1	370.36	370.36
1	3.60	3.60

CONTINUED ON PAGE 02