

a02-205

PATTISON AGRICULTURE LIMITED

Hwy 14 West, Box 599
 Unity, SK S0K 4L0
 Phone: (306) 228-2696
 Fax: (306) 228-2776
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



PATTISON
 AGRICULTURE



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3412742
		Invoice Date:	7/12/2025
		Location:	06
		Work Order Number:	480420
		Payment Type:	
		Page:	1 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	735	1H0X911XHP0825204	175071	CC061

JGLC JD X SERIES ALL**COMPLAINT:**

01 X9 SERIES COMBINE VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

CORRECTION:

VALUEMAX GREEN LIGHT SELF PROPELLED COMBINE CHECKLIST

HEADER SERIAL # _____ NA

ENGINE HOURS _____ 735

SEPERATOR HOURS _____ 499

DOES THIS UNIT GET A VALUEMAX STICKER ☒ YES ☐ NOHAS THE STICKER BEEN INSTALLED ☒ YES ☐ NO

THIS UNIT HAS HAD THE CAB CLEANED _____ MS

THIS UNIT HAS HAD A FINAL CHECKOVER _____ FN

THIS UNIT HAS HAD A COMPLETE GREASE JOB _____ FN

THINGS NOTED BUT NOT REPAIRED ON CUSTOMERS INSTRUCTIONS:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26859	INSPECTION+ 3 FLUID TEST KIT	1.00	87.56	87.56	\$87.56	N
TY6341	SD POLYUREA GREASE	2.00	11.14	11.14	\$22.28	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
LABDIS	LAB DISC CUST	-1.00	1,290.00	1,290.00	(\$1,290.00)	N

Labor: \$5,150.00 Parts: \$109.84 OL&M: \$0.00 Misc: (\$1,290.00) Sub-Total: \$3,969.84

JSOFTWARE JD X9 1100**COMPLAINT:**

02 UPDATE ALL CONTROLLER SOFTWARE

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 654-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3412742
		Invoice Date:	7/12/2025
		Location:	06
		Work Order Number:	480420
		Payment Type:	
		Page:	2 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	735	1H0X911XHP0825204	175071	CC061

JSOFTWARE JD X9 1100

UPDATED SOFTWARE ON THE FOLLOWING CONTROLLERS.

UPDATED:
FED
HAD
DEF HEADER
(SENT REMOTELY)
COREOS
DISPLAY

Labor: \$400.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$400.00
-----------------	---------------	--------------	--------------	---------------------

JENGOILCHNG JD X9 11

COMPLAINT:

03 REPLACE ENGINE OIL AND FILTER

CORRECTION:

DRAIN OIL
REMOVE OIL FILTER
ADD OIL
RUN & ADJUST LEVEL



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE572785	ENGINE OIL FILTER	1.00	151.85	151.85	\$151.85	N
TY26679	PLUS-50 II 15W-40 CK4/SN 18.9L PAIL	3.00	170.86	170.86	\$512.58	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.25	1.25	\$1.25	N
EF300	ENVIRO FEE	3.00	3.00	3.00	\$9.00	N

Labor: \$250.00	Parts: \$664.43	OL&M: \$0.00	Misc: \$10.25	Sub-Total: \$924.68
-----------------	-----------------	--------------	---------------	---------------------

JENGAIRFILT JD X9 11

COMPLAINT:

04 REPLACE PRIMARY AND SECONDARY ENGINE AIR FILTERS

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3412742
		Invoice Date:	7/12/2025
		Location:	06
		Work Order Number:	480420
		Payment Type:	
		Page:	3 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	735	1H0X911XHP0825204	175071	CC061

JENGAIRFILT JD X9 11

CORRECTION:
REMOVE AIR FILTERS
CLEAN OUT HOUSING
INSTALL NEW AIR FILTERS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE11090	Primary Engine Air Filter	1.00	463.00	463.00	\$463.00	N
HXE11091	Secondary EngAir Filter	1.00	326.70	326.70	\$326.70	N
Labor: \$100.00		Parts: \$789.70	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$889.70	

JTOPCOOLANT JD ALL

COMPLAINT:
05 TOP UP COOLANT.
- CLEAN OUT FUEL SEDIMENT BOWL

CORRECTION:
TOP UP COOLANT
REMOVE SEDIMENT BOWLS
CLEAN SEDIMENT BOWLS
RE-INSTALL SEDIMENT BOWLS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26576	COOL-GARD II 50/50 PRE-MIX JUG 9 46L	1.00	63.33	63.33	\$63.33	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF150	ENVIRO FEE	1.00	1.50	1.50	\$1.50	N
Labor: \$25.00		Parts: \$63.33	OL&M: \$0.00	Misc: \$1.50	Sub-Total: \$89.83	

JCABFILTER JD X9 11

COMPLAINT:
06 REPLACE CAB AIR FILTERS

PATTISON AGRICULTURE LIMITED

Hwy 14 West, Box 599
 Unity, SK S0K 4L0
 Phone: (306) 228-2696
 Fax: (306) 228-2776
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3412742
		Invoice Date:	7/12/2025
		Location:	06
		Work Order Number:	480420
		Payment Type:	
		Page:	4 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	735	1H0X911XHP0825204	175071	CC061

JCABFILTER JD X9 11

CORRECTION:
 REMOVE CAB FILTERS
 CLEAN OUT HOUSING
 INSTALL NEW CAB FILTERS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE70605	CAB RECIRC AIR FILTER	1.00	39.23	39.23	\$39.23	N
TA32591	Cab FreshAir Filter	1.00	125.95	125.95	\$125.95	N
Labor: \$100.00		Parts: \$165.18	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$265.18	

JHYDDIAG1 JD ALL**COMPLAINT:**

08 DIAGNOSE OIL LEAK AT MULTI-COUPLER, COMING FROM BACK OF COUPLER OR BOTTOM OF SOLENOIDS

- REPLACE BROKE SHEAR BOLT IN MULTI-COUPLER HANDLE
- REPLACE ALL 3 SPARE SHEAR BOLTS, MISSING
- REPLACE MISSING HARDWARE IN SHIELD ABOVE TRANSMISSION

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

		Invoice Number:	3412742
		Invoice Date:	7/12/2025
		Location:	06
		Work Order Number:	480420
		Payment Type:	
Bus Phone:	Bus Phone:		
Prv Phone:	Prv Phone:	Page:	5 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	735	1H0X911XHP0825204	175071	CC061

JHYDDIAG1 JD ALL

REMOVED BROKEN BOLT & REPLACED BROKE SHEAR BOLT IN MULTI-COUPLER HANDLE
INSTALL 3 SPARE SHEAR BOLTS
CLEAN MULTI-COUPLER AREA
REMOVE SOLENOIDS
TIGHTEN VALVES
RE-INSTALL SOLENOIDS
RUN & CHECK FOR LEAKS
CLEAN AREA
REMOVE ENTIRE MULTI-COUPLER
REMOVE BRACKET AT THE BACK
CLEAN AREA
REMOVE PLUG
REPLACE O-RING
RE-INSTALL PLUG
RE-INSTALL BRACKET
RE-INSTALL MULTI-COUPLER
CLEAN AREA

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7264	M4-0.75 NYLOCK NUT	4.00	0.54	0.54	\$2.16	N
14M7298	M8-1.25 FLG NUT	1.00	1.55	1.55	\$1.55	N
19M7866	M8x20 FLG 10.9 BOLT	1.00	1.86	1.86	\$1.86	N
19M9326	M4x30 HEXSOC 12.9 BOLT	4.00	2.22	2.22	\$8.88	N

Labor: \$476.00 Parts: \$14.45 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$490.45

J06171003 JD X9 1100

COMPLAINT:

09 REPLACE FEEDERHOUSE DRIVE CHAIN LOWER GUIDE MOUNTING BRACKETS AND HOSE SHIELD, WORN FROM CHAIN

- ADJUST FEEDERHOUSE DRIVE CHAIN.

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeseville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3412742 Invoice Date: 7/12/2025 Location: 06 Work Order Number: 480420 Payment Type: Page: 6 of 21
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	735	1H0X911XHP0825204	175071	CC061

J06171003 JD X9 1100
 REMOVE LOWER GUIDE CHAIN
 MOVE PLASTIC WEAR STRIP FROM OLD GUIDE TO NEW GUIDE
 INSTALL NEWS GUIDE
 REPLACE CHAIN
 TENSION CHAIN
 RUN & CHECK

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7298	M8-1.25 FLG NUT	2.00	1.60	1.60	\$3.20	N
AXE101426	Bracket	1.00	542.54	542.54	\$542.54	N
AXE90399	X9 FEEDER CHAIN DRIVE 80H BSN 83000	1.00	1,183.16	1,183.16	\$1,183.16	N
AXE99762	Bracket	1.00	838.86	838.86	\$838.86	N
H218025	M8x20 CB CARBIDE	5.00	7.07	7.07	\$35.35	N
HXE173727	Bracket	1.00	163.76	163.76	\$163.76	N
Labor: \$150.00		Parts: \$2,766.87	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,916.87	

J06001040 JD X9 1100
 COMPLAINT:
 10 REMOVE HALF LINK AND ADJUST FEEDERHOUSE CONVEYOR CHAIN TENSION.

CORRECTION:
 -LOOSEN FEEDERHOUSE CHAIN
 -REMOVE HALF LINK AND RECONNECT FEEDER CHAIN
 -TIGHTEN BACK UP FEEDERHOUSE CHAIN

Labor: \$300.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$300.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

J06171151 JD S790
 COMPLAINT:
 11 FEEDERHOUSE CONVEYOR CHAIN SLAT, REPLACE (ONE)

CORRECTION:

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3412742
		Invoice Date:	7/12/2025
		Location:	06
		Work Order Number:	480420
		Payment Type:	
		Page:	7 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	735	1H0X911XHP0825204	175071	CC061

J06171151 JD S790

- LOOSEN FEEDERHOUSE CHAIN
- REMOVE BENT CHAIN SLANT
- INSTALL NEW CHAIN SLANT AND TIGHTEN
- TIGHTEN BACK UP FEEDERHOUSE CHAIN

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE113327	X9 FEEDER CHAIN SLAT	1.00	67.52	67.52	\$67.52	N
Labor: \$100.00		Parts: \$67.52	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$167.52	

J06171332 JD X9 1100

COMPLAINT:

12 REPLACE MISSING SEAL FOR LEFT SIDE STONE TRAP DOOR

CORRECTION:

-INSTALL NEW RUBBER ON STONE TRAP DOOR

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE161580	SEAL	1.00	19.11	19.11	\$19.11	N
Labor: \$120.00		Parts: \$19.11	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$139.11	

EXPERT-1000000176030

COMPLAINT:

13 REPLACE 4 BENT FEED ACCELERATOR WINGS

- CLEAN OUT FEED ACCELERATOR

- INSTALL A PIECE OF RUBBER ON FEED ACCELERATOR GEARCASE SHIFT CABLE (RUBBING ON HYDRAULIC LINE)

CORRECTION:

-REMOVE BOLTS AND FEEDING TEETH TO REMOVE BENT FEED ACCELERATOR WINGS

-INSTALL NEW FEED WINGS

-TIGHTEN ALL HARDWARE ON FEED ACCELERATOR WINGS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE174444	X9 FEED ACCELERATOR/BEATER STRIP ASN 82K	3.00	425.88	425.88	\$1,277.65	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 14 West, Box 599
 Unity, SK S0K 4L0
 Phone: (306) 228-2696
 Fax: (306) 228-2776
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3412742
		Invoice Date:	7/12/2025
		Location:	06
		Work Order Number:	480420
		Payment Type:	
		Page:	8 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	735	1H0X911XHP0825204	175071	CC061

EXPERT-1000000176030

HXE177730	X9 FEED ACC/BEATER STRIP ASN 82K	2.00	583.14	583.14	\$1,166.28	N
-----------	----------------------------------	------	--------	--------	------------	---

Labor: \$600.00	Parts: \$2,443.93	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$3,043.93
------------------------	--------------------------	-------------------------	---------------------	------------------------------

J06180268 JD X9 1100

COMPLAINT:

14 INSTALL CONCAVES, LEVEL AND CALIBRATE.

- REPLACE MISSING HARDWARE FOR LEFT SIDE COVERS
- REPLACE MISSING HARDWARE FOR RIGHT SIDE COVERS

CORRECTION:

CLEAN OUT THRESHING ELEMENTS
 SEARCH FOR CONCAVES IN THE SHED
 REPAIR 10 CONCAVES
 INSTALL FRONT LIPS ON BOTH SIDES FRONT CONCAVES
 INSTALL CONCAVES
 INSTALL Z-PLATES
 REMOVE 1 CONCAVE FOR MISSED REPAIR
 REPAIR 1 CONCAVE
 RE-INSTALL CONCAVES
 LEVEL CONCAVES
 CALIBRATE CONCAVES
 RUN & CHECK
 RE-LEVEL CONCAVES
 RE-CALIBRATE CONCAVES
 RUN & CHECK



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
03M7676	M8x30 CB 10.9 SN	14.00	1.01	1.01	\$14.14	N
11M7030	M5x40 COTTER PIN	4.00	1.06	1.06	\$4.24	N
14M7298	M8-1.25 FLG NUT	6.00	1.60	1.60	\$9.60	N
19M7789	M12x30 FLG 10.9 BOLT	4.00	2.63	2.63	\$10.52	N
AXE87791	FRONT LIP - LH	1.00	306.48	306.48	\$306.48	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 14 West, Box 599
 Unity, SK S0K 4L0
 Phone: (306) 228-2696
 Fax: (306) 228-2776
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preaceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



PATTISON

AGRICULTURE



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3412742
		Invoice Date:	7/12/2025
		Location:	06
		Work Order Number:	480420
		Payment Type:	
		Page:	9 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	735	1H0X911XHP0825204	175071	CC061

J06180268 JD X9 1100

AXE87792

FRONT LIP - RH

1.00

325.06

325.06

\$325.06

N

Labor: \$1,600.00**Parts: \$670.04****OL&M: \$0.00****Misc: \$0.00****Sub-Total: \$2,270.04****J06175204 JD X9 1100****COMPLAINT:**

15 ADJUST TAILINGS ELEVATOR PADDLE CHAIN

- CLEAN ACTIVE TAILINGS CAMERA LENS

CORRECTION:

LOOSEN BOLTS ON BEARING

ADJUST TAILINGS ELEVATOR PADDLE CHAIN TO SPEC

TIGHTEN BOLTS ON BEARING

CLEAN CAMERA LENS

RUN & CHECK

Labor: \$100.00**Parts: \$0.00****OL&M: \$0.00****Misc: \$0.00****Sub-Total: \$100.00****JWELD2 JD ALL****COMPLAINT:**

16 CLEAN OUT DEBRIS FROM BEHIND TAILINGS ELEVATOR LOWER DOOR LATCH

- RE WELD LATCH ON TO ELEVATOR HOUSING (SPOT WELDS SEPARATING FROM HOUSING)

CORRECTION:

CLEAN OUT DEBRIS FROM BACK OF LATCH

STRAIGHTEN LATCH

GRIND PAINT OFF FOR WELDING

WELD LATCH

CLEAN AREA

PRIME AND PAINT

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 14 West, Box 599
 Unity, SK S0K 4L0
 Phone: (306) 228-2696
 Fax: (306) 228-2776
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No:

Deliver To:

Bus Phone:

Prv Phone:

Bus Phone:

Prv Phone:

Invoice Number: **3412742**

Invoice Date: 7/12/2025

Location: 06

Work Order Number: 480420

Payment Type:

Page: 10 of 21

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE X9 1100

735

1H0X911XHP0825204

175071

CC061

JWELD2 JD ALL

Labor: \$200.00

Parts: \$0.00

OL&M: \$0.00

Misc: \$0.00

Sub-Total: \$200.00

JGEN17-**COMPLAINT:**

17 TIGHTEN ALL HYDRAULIC CLAMPS IN ENGINE BAY
 - AUXILIARY TANK HOSE LEAKING

CORRECTION:

TIGHTENED ALL HYDRAULIC CLAMPS IN ENGINE BAY
 TIGHTENED CLAMPS ON AUXILIARY TANK HOSES

Labor: \$150.00

Parts: \$0.00

OL&M: \$0.00

Misc: \$0.00

Sub-Total: \$150.00

EXPERT-1000000075123**COMPLAINT:**

18 Straw Chopper Drive Belt, Remove and Replace

CORRECTION:

- LOOSEN BELT TENSIONER
 - REMOVE OLD BELT
 - INSTALL NEW BELT
 - RE TIGHTEN BELT TENSIONER

Part Number
 HXE124215

Description
 EXTRA FINE CUT CHOPPER DRV BELT

Quantity
 1 00

List Price
 920.77

Net Price
 920.77

Extended Price
 \$920.77

Taxed Ind
 N

Labor: \$350.00

Parts: \$920.77

OL&M: \$0.00

Misc: \$0.00

Sub-Total: \$1,270.77

EXPERT-1000000102331**COMPLAINT:**

19 Flip Straw Chopper Hammers (Straight Blades Only)

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 14 West, Box 599
 Unity, SK S0K 4L0
 Phone: (306) 228-2696
 Fax: (306) 228-2776
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No:

Deliver To:

Bus Phone:

Prv Phone:

Bus Phone:

Prv Phone:

Invoice Number: **3412742**

Invoice Date: 7/12/2025

Location: 06

Work Order Number: 480420

Payment Type:

Page: 11 of 21

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE X9 1100

735

1H0X911XHP0825204

175071

CC061

EXPERT-1000000102331**CORRECTION:**

- REMOVE BOLTS TO FLIP STRAW CHOPPER KNIVES
(A HANDFUL OF BOLTS WERE RUSTED AND HARD TO REMOVE)
- FLIP KNIVES AND RE TIGHTEN BOLTS

Labor: \$150.00**Parts: \$0.00****OL&M: \$0.00****Misc: \$0.00****Sub-Total: \$150.00****EXPERT-1000000089986****COMPLAINT:**

20 REPLACE RIGHT SIDE FRONT SIEVE PITMAN DRIVE ARM, RUBBER CRACKED

- CALIBRATE SIEVE AND CHAFFER ELEMENT

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 14 West, Box 599
 Unity, SK S0K 4L0
 Phone: (306) 228-2696
 Fax: (306) 228-2776
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3412742
		Invoice Date:	7/12/2025
		Location:	06
		Work Order Number:	480420
		Payment Type:	
		Page:	12 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	735	1H0X911XHP0825204	175071	CC061

EXPERT-1000000089986

- REMOVE HARNESS AND HARNESS HOLDERS ON FRAME
- REMOVE SIDE SHIELDS ON THE REAR TAILBOARD CHAFFER
- DISCONNECT CONNECTIONS TO REAR TAILBOARD SENSOR
- REMOVE BOLTS HOLDING REAR TAILBOARD CHAFFER AND REMOVE IT
- REMOVE 2 FINS ON SIDE OF FRAME TO REMOVE CHAFFER
- REMOVE CHAFFER ELEMENT
- REMOVE SIEVE ELEMENT
- REMOVE 2 PITMAN ARMS TO BE ABLE TO REMOVE SIEVE AND CHAFFER FRAME
- LOOSEN ALL 4 CORNERS OF FRAME CONNECTED TO PITMAN ARMS TO ALLOW EASIER INSTALLATION
- PULL OUT 4 BOLTS HOLDING FRAME IN
- REMOVE BELT
- PULL FRAME OUT
- REMOVE BOLTS FROM WORN PITMAN ARM AND INSTALL NEW PITMAN ARM WITH RED LOCK TIGHT
- CONNECT COME ALONG TO CENTER THE PITMAN ARMS
- REINSTALL FRAME
- INSTALL SIEVE ELEMENT AND BOLT DOWN AND CONNECT CONNECTORS
- START TO TIGHTEN ALL PITMAN ARMS
- 1 BOLT ON PITMAN ARM BECAME STRIPPED AND COULD NOT BE REMOVED
- GRIND NUT OFF AND BEAT OUT WORN BOLT
- PUT IN NEW BOLT AND RE TIGHTEN THAT PITMAN ARM
- CONTINUE TO GO AROUND MACHINE AND RE TIGHTEN ALL BOLTS AND PITMAN ARMS
- INSTALL CHAFFER ELEMENT BOLT UP AND RE CONNECT CONNECTORS
- CALIBRATED SIEVE AND CHAFFER
- FIX FEW BENT ELEMENTS
- RE INSTALL REAR TAILBOARD CHAFFER
- RE INSTALL SIDE SHIELDS ON REAR TAILBOARD CHAFFER
- WALK AROUND FOR FINAL INSPECTION



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
03M7358	M16x140 CB 10.9 SN	1.00	23.63	23.63	\$23.63	N
14M7291	M16-2 FLG NUT	1.00	5.36	5.36	\$5.36	N
AXE85936	ARM	1.00	443.49	443.49	\$443.49	N

Labor: \$700.00	Parts: \$472.48	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,172.48
------------------------	------------------------	-------------------------	---------------------	------------------------------

J06001201 JD X9 1100

COMPLAINT:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 14 West, Box 599
 Unity, SK S0K 4L0
 Phone: (306) 228-2696
 Fax: (306) 228-2776
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3412742
		Invoice Date:	7/12/2025
		Location:	06
		Work Order Number:	480420
		Payment Type:	
		Page:	13 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	735	1H0X911XHP0825204	175071	CC061

J06001201 JD X9 1100

21 ADJUST CLEAN GRAIN ELEVATOR PADDLE CHAIN AND REMOVE HALF LINK.

CORRECTION:

LOOSEN TENSION ON BELT
 LOOSEN BOLTS ON BEARING
 REMOVE 1/2 LINK FROM CHAIN
 ADJUST CLEAN GRAIN ELEVATOR PADDLE CHAIN TO SPEC
 TIGHTEN BOLTS ON BEARING
 RE-TENSION BELT
 CLEAN CAMERA LENS
 RUN & CHECK

Labor: \$100.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$100.00

EXPERT-1000000016358**COMPLAINT:**

22 TOP & MIDDLE SEPARATOR GRATES MISSING FINGERS ON RIGHT SIDE FRONT ROW

CORRECTION:

REMOVE GRATES
 INSTALL NEW GRATES

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE132083	SEPARATOR GRATE	1.00	629.89	629.89	\$629.89	N
HXE132084	SEPARATOR	1.00	750.57	750.57	\$750.57	N

Labor: \$182.00 Parts: \$1,380.46 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$1,562.46

J06180111 JD X9 1100**COMPLAINT:**

23 REPLACE RIGHT ROTOR, 1ST & 4TH ROW OF THRESHING ELEMENTS (CRACKED) (MATCHED SET OF 3) CONCAVES REMOVED

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3412742 Invoice Date: 7/12/2025 Location: 06 Work Order Number: 480420 Payment Type: Page: 14 of 21
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	735	1H0X911XHP0825204	175071	CC061

J06180111 JD X9 1100

REMOVE BROKEN ELEMENTS

INSTALL NEW ELEMENTS & TORQUE TO SPEC

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
KXE10756	THRESHING ELEMENT KIT RH	2.00	1,266.26	1,266.26	\$2,532.52	N
Labor: \$240.00		Parts: \$2,532.52	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,772.52	

JGEN24-

COMPLAINT:

24 REPLACE FEED ACCELERATOR GEARCASE SHIFT FORK SEAL, LEAKING

CORRECTION:

REMOVE CABLE FROM GEARCASE SELECTOR

REMOVE SEAL

INSTALL NEW SEAL

RE-INSTALL CABLE TO SELECTOR

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AT12820	SEAL	1.00	21.28	21.28	\$21.28	N
Labor: \$600.00		Parts: \$21.28	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$621.28	

JGEN25-

COMPLAINT:

25 DIAGNOSE FOLDING HOPPER DOES NOT CLOSE ALL OF THE TIME, BINDING

- REPLACE RIGHT SIDE HOPPER PLASTIC SHIELD

CORRECTION:

PATTISON AGRICULTURE LIMITED

Hwy 14 West, Box 599
 Unity, SK S0K 4L0
 Phone: (306) 228-2696
 Fax: (306) 228-2776
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3412742
		Invoice Date:	7/12/2025
		Location:	06
		Work Order Number:	480420
		Payment Type:	
		Page:	15 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	735	1H0X911XHP0825204	175071	CC061

JGEN25-

-ADJUSTED PINS TO ALLOW HOPPER TO FOLD

OPEN HOPPER, OPENED FINE
 TRY TO CLOSE, WOULD NOT CLOSE
 PUT IN SERVICE MODE AND DROP DOWN AUGER
 TRY OPEN AND CLOSE IN SERVICE MODE STILL WOULD NOT WORK
 SHUT OFF AND GO INSPECT INSIDE HOPPER
 FOUND REAR EXTENSION ARMS FLIPPED AND OVER CENTERED, ADJUSTED TO PROPER POSITION
 INSPECT ALL RODS AND PLASTIC CLAMPS FOR BINDING
 FOUND 1 BINDING WITH BRACKET BENT
 LOOSEN OFF AND STRAIGHTEN
 TIGHTEN AND CHECK FOR BINDING
 CHECK SPECS FOR ADJUSTMENTS ON TURNBUCKLES
 MEASURE AND WAS IN SPEC ACCORDING TO SA - 64MM
 GO CHECK ON A KNOWN GOOD COMBINE AND MEASURE 71MM, ALSO FOUND A DTAC WHERE THEY SET TO 71MM
 ADJUSTED TO 71MM AND TESTED AND IT WORKED
 DISABLED SERVICE MODE

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE81922	Link	1.00	86.36	86.36	\$86.36	N
HXE166125	RH Grain Door Hinge Cover	1.00	315.94	315.94	\$315.94	N

Labor: \$1,200.00 Parts: \$402.30 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$1,602.30

JGEN26-**COMPLAINT:**

26 RE ATTACH FOLDING UNLOADING AUGER ACTUATOR MOUNT BACK ON TO AUGER TUBE & REMOUNT ACTUATOR.
 TEST FUNCTION
 - INSPECT FOLDING AUGER COG & DRIVER FOR DAMAGE AFTER AUGER IS FOLDING BACK IN.

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 14 West, Box 599
 Unity, SK S0K 4L0
 Phone: (306) 228-2696
 Fax: (306) 228-2776
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Presceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No:

Deliver To:

Bus Phone:	
Prv Phone:	

Bus Phone:	
Prv Phone:	

Invoice Number:	3412742
Invoice Date:	7/12/2025
Location:	06
Work Order Number:	480420
Payment Type:	
Page	16 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	735	1H0X911XHP0825204	175071	CC061

JGEN26-

REMOVE STRAPS HOLDING BRACKET TO UNLOADING TUBE
 REMOVE TAPE COVERING HOLES
 MARK POSITION OF AUGER
 REMOVE BRACKET HOLDING AUGER FLIGHT IN PLACE
 REMOVE AUGER FLIGHT
 DRILL OUT HOLES IN BRACKET
 DRILL OUT HOLES IN AUGER TUBE
 FIT BOLTS TO TUBE
 INSTALL BRACKET TO TUBE
 TIGHTEN BRACKET TO TUBE
 RE-INSTALL AUGER FLIGHT
 OPEN SIDE PANEL TO LINE UP SPLINES
 MADE SURE ORIGINAL MARKS ON AUGER FLIGHT LINES UP
 RE-INSTALL BRACKET HOLDING AUGER FLIGHT IN PLACE
 INSTALL ACTUATOR
 TEST FOLDING REPEATEDLY

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7298	M8-1.25 FLG NUT	8.00	1.60	1.60	\$12.80	N
H218025	M8x20 CB CARBIDE	8.00	7.07	7.07	\$56.56	N
M84309	5/16 PUSH NUT	8.00	2.85	2.85	\$22.80	N

Labor: \$690.00	Parts: \$92.16	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$782.16
-----------------	----------------	--------------	--------------	---------------------

JGEN27-**COMPLAINT:**

27 INSTALL RIGHT SIDE WINDOW WIPER NOZZLE PROPERLY, SPRAYING AWAY FROM WINDSHIELD

CORRECTION:

-REMOVE WIPER NOZZLE
 -RE INSTALL CORRECTLY
 -TEST IT

Labor: \$50.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$50.00
----------------	---------------	--------------	--------------	--------------------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3412742 Invoice Date: 7/12/2025 Location: 06 Work Order Number: 480420 Payment Type: Page: 17 of 21
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	735	1H0X911XHP0825204	175071	CC061

J06171005 JD S790

COMPLAINT:

- 28 REPLACE LEFT SIDE FEEDERHOUSE SHIELD, MISSING INSPECTION DOOR.
- REPLACE MISSING HARDWARE IN FEEDERHOUSE TOP SHIELD
- INSTALL RIGHT SIDE MOUNTING BRACKET & HARDWARE, MISSING

CORRECTION:

- REPLACED MISSING HARDWARE
- INSTALL MISSING BRACKET AND BOLTS
- INSTALL NEW FEEDERHOUSE SHIELD

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7396	M8-1.25 FLG NYLOCK NUT	1.00	1.76	1.76	\$1.76	N
19M7865	M8x16 FLG 10.9 BOLT	2.00	1.70	1.70	\$3.40	N
19M7866	M8x20 FLG 10.9 BOLT	3.00	1.86	1.86	\$5.58	N
AH204634	Latch	1.00	152.32	152.32	\$152.32	N
H154071	Rivnut M8 hex	1.00	2.40	2.40	\$2.40	N
HXE152961	Bracket	1.00	80.40	80.40	\$80.40	N
HXE160739	GEARSHIFT	1.00	50.91	50.91	\$50.91	N
HXE169589	SUPPORT	1.00	201.73	201.73	\$201.73	N
Labor: \$150.00		Parts: \$498.50	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$648.50	

JDRAGCHAIN JD X9 11

COMPLAINT:

- 29 INSTALL STATIC DRAG CABLE.

CORRECTION:

- DRILL HOLE
- INSTALL NEW STATIC DRAG CABLE

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7296	M10-1.5 FLG NUT	1.00	2.17	2.17	\$2.17	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3412742
		Invoice Date:	7/12/2025
		Location:	06
		Work Order Number:	480420
		Payment Type:	
		Page:	18 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	735	1H0X911XHP0825204	175071	CC061

JDRAGCHAIN JD X9 11

19M7866	M8x20 FLG 10.9 BOLT	1.00	1.86	1.86	\$1.86	N
STATIC	STATIC DRAG CABLE 3/8"	1.00	249.89	249.89	\$249.89	N
X9STATIC	X9 STATIC BRACKET	1.00	54.21	53.52	\$53.52	N

Labor: \$100.00 Parts: \$307.44 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$407.44

JWASH JD X9

COMPLAINT:

30 WASH USED X9 COMBINE. READY FOR DISPLAY.

CORRECTION:

INCLUDES THE FOLLOWING:

- BLOW OFF ALL CHAFF.
- WASHING OUT RADIATOR AND ALL COOLERS.
- CLEAN OUT GRAIN TANK AND UNLOADING AUGER.
- WASH EXTERIOR PANELS AND ALL SHIELDS.
- VACUUM CAB AND WASH FLOOR MAT
- CLEAN WINDOWS



Labor: \$2,070.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$2,070.00

JGEN31-

COMPLAINT:

31 PAINT FEEDERHOUSE DRUM

- MAKE SURE NO LOOSE PLASTIC ON SEAT
- MAKE SURE GLOBE CONNECTOR PLUG IS DONE UP

CORRECTION:

- REMOVE FEEDERHOUSE CHAIN
- CLEAN UP DRUM
- PAINT FEEDERHOUSE DRUM
- PUT BACK ON FEEDERHOUSE CHAIN

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 14 West, Box 599
 Unity, SK S0K 4L0
 Phone: (306) 228-2696
 Fax: (306) 228-2776
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
 Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
 Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
 Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
 Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
 Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
 North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
 Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3412742
		Invoice Date:	7/12/2025
		Location:	06
		Work Order Number:	480420
		Payment Type:	
		Page:	19 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	735	1H0X911XHP0825204	175071	CC061

JGEN31-

TY25638 MED GLOSS BLACK SPRAY PAINT 1.00 20.79 20.79 \$20.79 N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF25	ENVIRO FEE	1.00	0.25	0.25	\$0.25	N

Labor: \$300.00 Parts: \$20.79 OL&M: \$0.00 Misc: \$0.25 Sub-Total: \$321.04

JGEN32-

COMPLAINT:

32 REPLACE BROKEN GREASE NIPPLE ON STEERING

CORRECTION:

REMOVE BROKEN OFF NIPPLE
 INSTALL NEW NIPPLE
 GREASE ARM

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
JD7842	Zerk 1/4"-28 Str8	1.00	0.75	0.75	\$0.75	N

Labor: \$70.00 Parts: \$0.75 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$70.75

JGEN33-

COMPLAINT:

33 REMOVE REAR HITCH .(X HENNINGS. SN 830550) (INSTALL REAR HITCH IS ON 497448)

CORRECTION:

Labor: \$550.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$550.00

JGEN34-

COMPLAINT:

34 REPLACE KEY SWITCH

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 14 West, Box 599
 Unity, SK S0K 4L0
 Phone: (306) 228-2696
 Fax: (306) 228-2776
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No:

Deliver To:

		Invoice Number:	3412742
		Invoice Date:	7/12/2025
		Location:	06
		Work Order Number:	480420
		Payment Type:	
Bus Phone:	Bus Phone:	Page:	20 of 21
Prv Phone:	Prv Phone:		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	735	1H0X911XHP0825204	175071	CC061

JGEN34-

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
R30903	O-Ring	1.00	2.19	2.19	\$2.19	N
RE594150	ROTARY SWI	1.00	266.13	266.13	\$266.13	N
Labor: \$100.00		Parts: \$268.32	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$368.32	

J06001009 JD X9 1100**COMPLAINT:**

35 TWO SPEED CHOPPER GEARCASE OIL, REPLACE (PARTS ONLY)

CORRECTION:

Remove drain plug.

Allow oil to drain.

Install the drain plug and torque to specification. 30 N·m (22 lb·ft)

Refill with Hy-Gard until visible in the sight glass.

Shift lever to opposite speed.

Run the separator for one minute.

Let the machine sit for five minutes.

Re-check oil level.

Torque the fill plug to specification. 30 N·m (22 lb·ft)

Shift lever back to original speed.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY22062	HY-GARD J20C 9.46L	1.00	85.28	85.28	\$85.28	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF150	ENVIRO FEE	1.00	1.50	1.50	\$1.50	N
Labor: \$0.00		Parts: \$85.28	OL&M: \$0.00	Misc: \$1.50	Sub-Total: \$86.78	

JPWRGRD JD ALL**COMPLAINT:**

36 POWERGARD DEDUCTIBLE CUSTOMER PORTION

- RE: CHOPPER GEARCASE - POWERTRAIN DEDUCTIBLE \$1000.00

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED

Hwy 14 West, Box 599
 Unity, SK S0K 4L0
 Phone: (306) 228-2696
 Fax: (306) 228-2776
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351 Yorkton, SK (306) 783-9459
 Maple Creek, SK (306) 662-2233 Balcarres, SK (306) 334-2492
 Kindersley, SK (306) 463-2683 Moosomin, SK (306) 435-3301
 Kyle, SK (306) 375-2302 Preeceville, SK (306) 547-2007
 Leader, SK (306) 628-3889 Russell, MB (204) 773-2149
 Unity, SK (306) 228-2696 Wynyard, SK (306) 554-2536
 North Battleford, SK (306) 445-4468 Kamsack, SK (306) 542-2814
 Humboldt, SK (306) 682-2572 Swan River, MB (204) 734-3466
 Kelvington, SK (306) 327-4355
 Shaunavon, SK (306) 297-2639

**JOHN DEERE****SERVICE INVOICE**

Invoice To Account No:

Deliver To:

Bus Phone:

Prv Phone:

Bus Phone:

Prv Phone:

Invoice Number: **3412742**
 Invoice Date: 7/12/2025
 Location: 06
 Work Order Number: 480420
 Payment Type:
 Page: 21 of 21

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE X9 1100

735

1H0X911XHP0825204

175071

CC061

JPWRGRD JD ALL
CORRECTION:

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
OTHERPG	POWERGARD DEDUCTIBLE	1.00	1,000.00	1,000.00	\$1,000.00	N
Labor: \$0.00		Parts: \$0.00	OL&M: \$0.00	Misc: \$1,000.00	Sub-Total: \$1,000.00	

INVOICE CONTAINS \$0.69 DISCOUNT

Miscellaneous Charges:
 SERVICE ACCESSORIES

\$150.00

Customer PO No:
 Tax Exempt No:
 Advisor:

Labor: \$17,423.00
 Parts: \$14,777.45
 OL&M: \$0.00
 Misc: (\$126.50)
Grand Total: \$32,073.95

*** DOCUMENT COPY ***

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE – MIN \$35 ON EMERGENCY/UNIT DOWN ORDERS -- 25% RESTOCKING FOR RET

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by:

Date: