a02-222

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No.

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3337264**
Invoice Date:	3/17/2025
Location:	06
Work Order Number:	479195
Payment Type:	
Page:	1 of 14

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	582	1H0X910XLP0825266	176114	

JGLC JD X SERIES ALL
COMPLAINT:
01 X9 SERIES COMBINE VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

VMC; SEASON OF USE 2025

CORRECTION:
VALUEMAX GREEN LIGHT SELF PROPELLED COMBINE CHECKLIST
****
HEADER SERIAL # _____NA
ENGINE HOURS _____582.3_____
SEPARATOR HOURS _____384.5_____
****
DOES THIS UNIT GET A VALUEMAX STICKER _X_ YES __ NO
HAS THE STICKER BEEN INSTALLED _X_ YES __ NO
THIS UNIT HAS HAD THE CAB CLEANED _____MS___
THIS UNIT HAS HAD A FINAL CHECKOVER _____AG_
THIS UNIT HAS HAD A COMPLETE GREASE JOB ____TT_
****
THINGS NOTED BUT NOT REPAIRED ON CUSTOMERS INSTRUCTIONS:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26859	INSPECTION+ 3 FLUID TEST KIT	1.00	87.56	84.87	$84.87	N
TY6341	SD POLYUREA GREASE	2.00	10.87	10.80	$21.60	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
LABDIS	LAB DISC CUST	-1.00	1,290.00	1,290.00	($1,290.00)	N

Labor: $5,150.00 **Parts: $106.47** **OL&M: $0.00** **Misc: ($1,290.00)** **Sub-Total: $3,966.47**

JENGOILCHNG JD X9 10
COMPLAINT:
02 REPLACE ENGINE OIL AND FILTER

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3337264**
Invoice Date:	3/17/2025
Location:	06
Work Order Number:	479195
Payment Type:	
Page:	2 of 14

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	582	1H0X910XLP0825266	176114	

JENGOILCHNG JD X9 10
DRAINED ENGINE OIL
REPLACED FILTER
CLEANED UP
RAN FOR LEAKS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE572785	ENGINE OIL FILTER	1.00	151.85	151.85	$151.85	N
TY26679	PLUS-50 II 15W-40 CK4/SN 18.9L PAIL	3.00	170.86	170.86	$512.58	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.25	1.25	$1.25	N
EF300	ENVIRO FEE	3.00	3.00	3.00	$9.00	N

Labor: $250.00 **Parts: $664.43** **OL&M: $0.00** **Misc: $10.25** **Sub-Total: $924.68**



J10030100 JD X9 1000
COMPLAINT:
03 REPLACE ENGINE FUEL FILTERS.
- REPLACE ENGINE FUEL STRAINER, HAS HOLE IN IT

CORRECTION:
REPLACED PRIMARY AND SECONDARY FUEL FILTERS
MARKED HOURS ON FILTER
REPLACED PRE-FILTER ELEMENT. HAD HOLE IN IT
PUT PRE FILTER BOWL BACK WITH NEW FILTER
CHARGED FUEL SYSTEM. AWAITING RUN-UP TO CHECK FOR LEAKS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ124761	Primary Fuel Filter 13.6L	1.00	163.69	163.69	$163.69	N
DZ124786	Secondary Fuel Filter 13.6L	1.00	157.26	157.26	$157.26	N
R502778	Fuel Pre-filter Screen	1.00	48.83	48.83	$48.83	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	2.00	1.25	1.25	$2.50	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3337264**
Invoice Date:	3/17/2025
Location:	06
Work Order Number:	479195
Payment Type:	
Page:	3 of 14

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	582	1H0X910XLP0825266	176114	

J10030100 JD X9 1000

EF50	ENVIRO FEE	1.00	0.55	0.55	$0.55	N

Labor: $160.00 **Parts: $369.78** **OL&M: $0.00** **Misc: $3.05** **Sub-Total: $532.83**

JENGAIRFILT JD X9 10
COMPLAINT:
04 REPLACE PRIMARY AND SECONDARY ENGINE AIR FILTERS

CORRECTION:
REMOVED OLD FILTER
INSTALLED NEW FILTERS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE11090	Primary Engine Air Filter	1.00	463.00	463.00	$463.00	N
HXE11091	Secondary EngAir Filter	1.00	326.70	326.70	$326.70	N

Labor: $100.00 **Parts: $789.70** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $889.70**

JCABFILTER JD X9 10
COMPLAINT:
05 REPLACE CAB AIR FILTERS

CORRECTION:
REMOVE CAB AIR FILTERS
CLEANED FILTER HOUSING
INSTALLED NEW AIR FILTERS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE70605	CAB RECIRC AIR FILTER	1.00	39.23	39.23	$39.23	N
RE284091	Cab Air Filter	1.00	122.07	122.07	$122.07	N

Labor: $100.00 **Parts: $161.30** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $261.30**

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No	Deliver To:	
		Invoice Number: **3337264**
		Invoice Date: 3/17/2025
		Location: 06
		Work Order Number: 479195
		Payment Type:
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	Page: 4 of 14

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	582	1H0X910XLP0825266	176114	

EXPERT-1000000204231
COMPLAINT:
06 Two Speed Chopper Gearcase Oil, Replace

CORRECTION:
Remove drain plug.
Allow oil to drain.
Install the drain plug and torque to specification.
Refill with Hy-Gard until visible in the sight glass.
Shift lever to opposite speed.
Run the separator for one minute.
Let the machine sit for five minutes.
Re-check oil level.
Torque the fill plug to specification.
Shift lever back to original speed.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY22062	HY-GARD J20C 9.46L	1.00	85.28	85.28	$85.28	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF150	ENVIRO FEE	1.00	1.50	1.50	$1.50	N

Labor: $80.00 **Parts: $85.28** **OL&M: $0.00** **Misc: $1.50** **Sub-Total: $166.78**

JGEN07-
COMPLAINT:
07 - TOP UP ENGINE COOLANT
- REPLACE MISSING HARDWARE FOR SHIELD ABOVE TRANSMISSION (L/H SIDE)

CORRECTION:
COOLANT TOPPED UP

TRANSMISSION SHIELD WAS BENT OUT OF SHAPE
BENT SHIELD BACK TO ACCEPTABLE SHAPE FOR BOLTS TO FASTEN

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7299	M12-1.75 FLG NUT	1.00	2.92	2.92	$2.92	N
19M7790	M12x35 FLG 10.9 BOLT	1.00	3.83	3.83	$3.83	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number:	**3337264**
Invoice Date:	3/17/2025
Location:	06
Work Order Number:	479195
Payment Type:	
Page:	5 of 14

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	582	1H0X910XLP0825266	176114	

JGEN07-

LVU30700	SPACER	1.00	32.93	32.93	$32.93	N
TY26576	COOL-GARD II 50/50 PRE-MIX JUG 9.46L	1.00	63.76	63.33	$63.33	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF150	ENVIRO FEE	1.00	1.50	1.50	$1.50	N

Labor: $120.00 **Parts: $103.01** **OL&M: $0.00** **Misc: $1.50** **Sub-Total: $224.51**

JSOFTWARE JD X9 1000
COMPLAINT:
08 UPDATE ALL CONTROLLER SOFTWARE

CORRECTION:
UPDATED SOFTWARE ON THE FOLLOWING CONTROLLERS.

FED
HAD
MG2
DISPLAY GEN 4

Labor: $400.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $400.00**

JHYDDIAG4 JD ALL
COMPLAINT:
09 REPLACE TOP LEFT MULTI-COUPLER (STUCK)
- REPLACE ALL 3 MULTI COUPLER SPARE SHEAR BOLTS
- REPLACE MULTI COUPLER SHEAR BOLT IN HANDLE

CORRECTION:
REMOVED AND REPLACED TOP LEFT COUPLER
INSTALLED NEW BOLT IN MULTICOUPLER
INSTALLED SPARE BOLTS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7264	M4-0.75 NYLOCK NUT	4.00	0.54	0.54	$2.16	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3337264**
Invoice Date:	3/17/2025
Location:	06
Work Order Number:	479195
Payment Type:	
Page:	6 of 14

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	582	1H0X910XLP0825266	176114	

JHYDDIAG4 JD ALL

19M9326	M4x30 HEXSOC 12.9 BOLT	4.00	2.22	2.22	$8.88	N
AXE73035	X9 MC Coupler 1/2" FM	1.00	475.11	475.11	$475.11	N

Labor: $100.00 **Parts: $486.15** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $586.15**

EXPERT-1000000074062
COMPLAINT:
10 REPLACE FEEDERHOUSE HEADER LOCKING PIN CABLE (KINKED, WILL NOT RETRACT)

CORRECTION:
REMOVED AND REPLACED CABLE
ADJUSTED CABLE

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH212083	Push Pull Cable	1.00	526.59	526.59	$526.59	N

Labor: $250.00 **Parts: $526.59** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $776.59**

J06171003 JD X9 1000
COMPLAINT:
11 ADJUST FEEDERHOUSE DRIVE CHAIN.

CORRECTION:
LOOSENED OFF DRIVE CHAIN TENSIONER.
REMOVED MASTER LINK AND SPLIT CHAIN.
CUT OUT A FULL LINK AND INSTALLED AN OFFSET LINK.
REATTACHED CHAIN AND TENSION TO SPEC.
RAN FEEDERHOUSE AND RECHECKED TENSION.

Labor: $100.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $100.00**

J06001040 JD X9 1000
COMPLAINT:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3337264**
Invoice Date:	3/17/2025
Location:	06
Work Order Number:	479195
Payment Type:	
Page:	7 of 14

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	582	1H0X910XLP0825266	176114	

J06001040 JD X9 1000
12 REMOVE HALF LINK AND ADJUST FEEDERHOUSE CONVEYOR CHAIN TENSION.

CORRECTION:
TOOK CHAIN APART
REMOVED HALF LINK
INSTALLED CHAIN BACK TOGETHER

Labor: $300.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $300.00**

EXPERT-1000000128779
COMPLAINT:
13 REPLACE FEEDERHOUSE REVERSING MOTOR OUTPUT SHAFT SEAL, LEAKING
- REFERENCE DTAC 225887 (REPLACE VALVES AS WELL)



CORRECTION:
Fully lower header and reel to ground and continue depressing the switch for 5 to 10 seconds to relieve hydraulic system pressure.
Stop engine.
To allow removing the pump without draining the reservoir, connect D15032NU Vacuum Pump to reservoir. If vacuum pump is not available, drain reservoir.
Remove the left-hand side shields.
Disconnect the hydraulic lines.
To prevent contamination cap all openings and fittings.
Remove socket head cap screws and hydraulic motor from the support arm and coupler.
To prevent contamination cap all openings and fittings.
Remove cap screws from the hydraulic motor.
Repair or replace seals, seal ring, and O-rings as necessary.
Install parts in reverse order.
Install the reverser hydraulic motor.
Repair or replace as necessary.
Install parts in reverse order using the following special instruction:
- Install the hydraulic motor using the socket head cap screws. Tighten socket head cap screws to specification.
INSTALLED VALVES AS PER DTAC
RAN FOR 5 MINUTES AND CHECKED FOR LEAKS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AA46577	REEL DRIVE MOTOR SEAL KIT	1.00	415.27	415.27	$415.27	N

CONTINUED ON NEXT PAGE->>

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Invoice Number:	**3337264**
Invoice Date:	3/17/2025
Location:	06
Work Order Number:	479195
Payment Type:	
Page:	8 of 14

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	582	1H0X910XLP0825266	176114	

EXPERT-1000000128779

TCA23801	SOLENOID H		2.00	544.77	544.77	$1,089.54	N
Miscellaneous	**Description**		**Quantity**	**List Price**	**Net Price**	**Extended Price**	**Taxed Ind**
FRT	FREIGHT		1.00	35.00	35.00	$35.00	N

Labor: $650.00 **Parts: $1,504.81** **OL&M: $0.00** **Misc: $35.00** **Sub-Total: $2,189.81**

JHYDDIAG1 JD ALL
COMPLAINT:
14 RESEAL TRANSMISSION LUBRICATION PUMP HYDRAULIC MOTOR, LEAKING ON FRONT OF TRANSMISSION

CORRECTION:
REMOVED SHIELD
REMOVED PUMP
RESEALED PUMP
INSTALLED PUMP
TESTED FOR LEAKS GOOD

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE75096	Seal Kit	1.00	211.07	211.07	$211.07	N

Labor: $422.00 **Parts: $211.07** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $633.07**

J06171060 JD X9 1000
COMPLAINT:
15 CLEAN OUT FEED ACCELERATOR, BAD VIBRATION

CORRECTION:
REMOVE ONE SET OF WINGS.
CLEAN DEBRIS OUT FROM CENTER OF ASSEMBLY.
torq the bolts on the wing .

Labor: $200.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $200.00**

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number:	**3337264**
Invoice Date:	3/17/2025
Location:	06
Work Order Number:	479195
Payment Type:	
Page:	9 of 14

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	582	1H0X910XLP0825266	176114	

JGEN16-
COMPLAINT:
16 REPLACE FRONT LEFT GULL WING DOOR LOCKING PLATE AND CLIP, MISSING

CORRECTION:
REPLACED METAL BRACKET AND HAIR PIN

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H173257	Clevis	1.00	31.96	31.96	$31.96	N
J16931	R-Clip	1.00	0.29	0.29	$0.29	N

Labor: $30.00 **Parts: $32.25** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $62.25**

JADJUSTBELT JD S790
COMPLAINT:
17 REMOVE SHIM FROM UNLOADING AUGER DRIVE BELT TENSIONER PULLEY AND ADD SHIM TO IDLER PULLEY, BELT RIDING ON EDGE

CORRECTION:
REMOVED PULLEY
REMOVED SHIM
INSTALLED PULLEY

Labor: $100.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $100.00**

J06180268 JD X9 1000
COMPLAINT:
18 INSTALL CONCAVES, LEVEL AND CALIBRATE.
- REPAIR LEFT AND RIGHT REAR CONCAVES

CORRECTION:
INSTALLED CONCAVES (ENSURE THAT THE CONCAVES ARE TIGHT TO ONE ANOTHER AND THERE IS ADEQUATE BULKHEAD CLEARANCE)
LEVELED CONCAVES AS PER SERVICE ADVISOR.
PERFORMED CONCAVE CALIBRATION.

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3337264**
Invoice Date:	3/17/2025
Location:	06
Work Order Number:	479195
Payment Type:	
Page:	10 of 14

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	582	1H0X910XLP0825266	176114	

J06180268 JD X9 1000

Labor: $800.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $800.00**

J06180070 JD X9 1000
COMPLAINT:
19 ROTOR VARIABLE BELT, REMOVE AND REPLACE

CORRECTION:
Remove the unloading auger drive belt.
Remove the feeder house fixed or variable speed drive belt.
Loosen rotor variable drive belt.
Remove the rotor drive belt and install replacement belt.
Adjust the rotor drive belt.
Install the previously removed feeder house fixed or variable speed drive belt.
Install the previously removed unloading auger drive belt.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE107859	X9 ROTOR DRIVE BELT	1.00	1,644.79	1,644.79	$1,644.79	N

Labor: $400.00 **Parts: $1,644.79** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $2,044.79**

EXPERT-1000000177235
COMPLAINT:
20 REPLACE CHOPPER GEARCASE ROTARY UNION, LEAKING

CORRECTION:
REMOVED AND REPLACED UNION

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH218190	Hyd Rotary Union	1.00	764.21	764.21	$764.21	N

Labor: $80.00 **Parts: $764.21** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $844.21**

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number:	**3337264**
Invoice Date:	3/17/2025
Location:	06
Work Order Number:	479195
Payment Type:	
Page:	11 of 14

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	582	1H0X910XLP0825266	176114	

EXPERT-1000000075693
COMPLAINT:
21 REPLACE CHOPPER RIGHT SIDE BEARING (HOT ON RUN UP)

CORRECTION:
REMOVED PULLEY
REMOVED BEARING
REPLACED BEARING
TORQUED TO SPEC
REINSTATED PULLEY
TENSIONED BELT

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
03M7209	M16x60 CB 8.8 SN	4.00	8.35	8.35	$33.40	N
14M7291	M16-2 FLG NUT	4.00	5.20	5.20	$20.80	N
AXE74879	Ball Bearing	1.00	454.71	454.71	$454.71	N

Labor: $1,150.00 **Parts: $508.91** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $1,658.91**

J06001201 JD X9 1000
COMPLAINT:
22 ADJUST CLEAN GRAIN ELEVATOR PADDLE CHAIN AND REMOVE HALF LINK

CORRECTION:
CHAIN ADJUSTED

Labor: $100.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $100.00**

JGEN23-
COMPLAINT:
23 ADJUST ENGINE DECK ACCESS COVER LATCH, NOT SITTING CORRECTLY

CORRECTION:
REMOVED CLIPS BOLT TO ADJUST IT TO CLIP AND LEVEL

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3337264**
Invoice Date:	3/17/2025
Location:	06
Work Order Number:	479195
Payment Type:	
Page:	12 of 14

Make/Model	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	582	1H0X910XLP0825266	176114	

JGEN23-

Labor: $100.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $100.00**

JGEN24-
COMPLAINT:
24 REPLACE FEED ACCELERATOR GEARCASE SHIFT FORK SEAL IN BACK COVER, LEAKING

CORRECTION:
REMOVED OLD SEAL
INSTALLED NEW SEAL

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AT12820	SEAL	1.00	29.37	29.37	$29.37	N

Labor: $450.00 **Parts: $29.37** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $479.37**

JGEN25-
COMPLAINT:
25 REPLACE TOP LEFT GRAIN TANK PLASTIC COVER

CORRECTION:
REMOVED AND REPLACED PLASTIC SHIELD

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H240320	LH Grain Tank Hingle Cover	1.00	283.19	283.19	$283.19	N

Labor: $50.00 **Parts: $283.19** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $333.19**

JELECDIAG1 JD ALL
COMPLAINT:
26 DIAGNOSE CLEANING FAN SPEED SET POINT NOT REACHED (STOPS AT 1340 RMP, WILL NOT GO TO 1430 RPM)

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Bus Phone:
Prv Phone:

Deliver To:

Bus Phone:
Prv Phone:

Invoice Number:	**3337264**
Invoice Date:	3/17/2025
Location:	06
Work Order Number:	479195
Payment Type:	
Page:	13 of 14

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	582	1H0X910XLP0825266	176114	

JELECDIAG1 JD ALL
CHECKED BELT SIZE - GOOD
CHECKED SHIM GAP - GOOD
RAN COMBINE AND CLEANING FAN GETS UP TO SPEED

Labor: $300.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $300.00**

JADJCHAFSIEV JD X910
COMPLAINT:
27 FACTORY CALIBRATION OF SIEVE AND CHAFFER

CORRECTION:
PERFORM FACTORY CALIBRATION AS PER SERVICE ADVISOR

Labor: $200.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $200.00**



JWASH JD X9
COMPLAINT:
28 WASH USED X9 COMBINE. READY FOR DISPLAY.

CORRECTION:
INCLUDES THE FOLLOWING:
-BLOW OFF ALL CHAFF.
-WASHING OUT RADIATOR AND ALL COOLERS.
-CLEAN OUT GRAIN TANK AND UNLOADING AUGER.
-WASH EXTERIOR PANELS AND ALL SHIELDS.
-VACUUM CAB AND WASH FLOOR MAT
-CLEAN WINDOWS

Labor: $2,070.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $2,070.00**

JGEN30-
COMPLAINT:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 14 West, Box 599
Unity, SK S0K 4L0
Phone: (306) 228-2696
Fax: (306) 228-2776
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		

PATTISON AGRICULTURE

JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number:	**3337264**
Invoice Date:	3/17/2025
Location:	06
Work Order Number:	479195
Payment Type:	
Page:	14 of 14

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1000	582	1H0X910XLP0825266	176114	

JGEN30-
30 PAINT FEEDERHOUSE DRUM
- MAKE SURE NO LOOSE PLASTIC ON SEAT
- MAKE SURE GLOBE CONNECTOR PLUG IS DONE UP

CORRECTION:

Labor: $300.00 **Parts: $0.00** **OL&M: $0.00** **Misc: $0.00** **Sub-Total: $300.00**

INVOICE CONTAINS $3.26 DISCOUNT

Miscellaneous Charges:
SERVICE ACCESSORIES $150.00

Customer PO No:
Tax Exempt No:
Advisor:

*** DOCUMENT COPY ***

Labor:	$14,512.00
Parts:	$8,271.31
OL&M:	$0.00
Misc:	($1,088.70)
Grand Total:	$21,694.61

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE -- MIN $35 ON EMERGENCY/UNIT DOWN ORDERS -- 25% RESTOCKING FOR RET

TERMS AND CONDITIONS
I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: ..... Date: .....