

002-55

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeseville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3337451
		Invoice Date:	3/18/2025
		Location:	01
		Work Order Number:	474838
		Payment Type:	
		Page:	1 of 22

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

JGLSPR JD ALL

COMPLAINT:

01 SPRAYER VALUEMAX GREEN LIGHT SERVICE INSPECTION CHECKOVER

CORRECTION:

SELF PROPELLED SPRAYER VALUEMAX GREEN LIGHT INSPECTION CHECKOVER

NOTE: SPRAY TANK MUST BE RINSED AS WELL AS BOOMS WASHED
 OFF BEFORE SPRAYER IS BROUGHT INTO SHOP.
 IF NOT ADDITIONAL CHARGES WILL APPLY.

ENGINE HOURS 1088

DOES THIS UNIT GET A VALUEMAX STICKER ☒ YES ☐ NO

HAS THE STICKER BEEN INSTALLED ☒ YES ☐ NO

CAB HAS BEEN COMPLETELY CLEANED ☐ AV (INITIAL)

THIS UNIT HAS HAD A FINAL CHECKOVER ☐ BT (INITIAL)

THIS UNIT HAS HAD A COMPLETE GREASE JOB ☐ MS (INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMER'S INSTRUCTIONS:



Job Total: \$1,950.00

J21001008 JD 616R

COMPLAINT:

04 REPLACE AIR DRYER CARTRIDGE FILTER

CORRECTION:

Friday, February 7, 2025 1:47 PM -

REMOVED AND REPLACED AIR DRYER FILTER.

INSTALLED NEW O-RING.

MARKED ENGINE HOURS AND DATE ON NEW FILTER INSTALLED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

		Invoice Number: 3337451
		Invoice Date: 3/18/2025
		Location: 01
		Work Order Number: 474838
		Payment Type:
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	
		Page: 2 of 22

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

J21001008 JD 616R

BA5374	DESSICANT AIR DRYER	1.00	87.54	82.10	\$82.10	N
--------	---------------------	------	-------	-------	---------	---

Labor: \$35.00	Parts: \$82.10	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$117.10
----------------	----------------	--------------	--------------	---------------------

JCABFILTER JD 616R

COMPLAINT:

05 REPLACE CAB AIR FILTERS

CORRECTION:

Friday, February 7, 2025 2:06 PM -

REMOVED CABIN AIR FILTERS.

CLEANED HOUSINGS.

MARKED ENGINE HOURS AND DATE ON NEW FILTERS BEING INSTALLED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE333567	CabFreshFilter Carbon	1.00	690.56	690.56	\$690.56	N
RE595871	Cab Recirc Filter Carbon	1.00	318.23	318.23	\$318.23	N
Labor: \$50.00		Parts: \$1,008.79	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,058.79	

EXPERT-1000000098672

COMPLAINT:

06 AutoTrac Strainer, Clean

CORRECTION:

Remove hose fitting from port P on the AutoTrac valve.

Remove strainer fitting.

Clean contaminants from the strainer.

Install the strainer fitting in port P of the AutoTrac valve, Tighten to specification.

Install the hose fitting to the strainer fitting, Tighten to specification.

Verify proper hydraulic oil level in the reservoir. Add oil as necessary.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
51M7045	O-RING M22	1.00	6.18	6.18	\$6.18	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 436-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3337451 Invoice Date: 3/18/2025 Location: 01 Work Order Number: 474838 Payment Type: Page: 3 of 22
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

EXPERT-1000000098672

77857	-8FF O-ring	1.00	3.30	3.30	\$3.30	N
-------	-------------	------	------	------	--------	---

Labor: \$36.00	Parts: \$9.48	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$45.48
-----------------------	----------------------	-------------------------	---------------------	---------------------------

J21001007 JD 616R

COMPLAINT:

07 REPLACE OIL IN PLANETARY WHEEL HUBS.

CORRECTION:

DRAINED OIL FROM PLANETARY HOUSINGS.

INSTALLED NEW OIL.

LEAK CHECKED.

TOPPED UP AFTER RUNNING.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26372	SYN GL-5 80W-140 BOTTLE 946ml	14.00	47.83	47.83	\$669.62	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF15	ENVIRO FEE	14.00	0.15	0.15	\$2.10	N
Labor: \$175.00		Parts: \$669.62	OL&M: \$0.00	Misc: \$2.10	Sub-Total: \$846.72	

JHYDOLCHG JD R4045

COMPLAINT:

08 REPLACE HYDRAULIC OIL AND FILTERS.

INSTALL A NEW FILLER CAP ON TANK.

CORRECTION:

DRAIN HYDRAULIC RESERVOIR.

INSTALL NEW OIL.

CHECK AND ADJUST LEVEL AS REQUIRED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AKK23814	CommandDrive Hydro Pump Filter	1.00	315.21	315.21	\$315.21	N
AT318160	HYDRAULIC OIL FILTER	1.00	209.99	209.99	\$209.99	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3337451 Invoice Date: 3/18/2025 Location: 01 Work Order Number: 474838 Payment Type: Page: 4 of 22
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

JHYDOILCHG JD R4045

KK77228	High Pressure Hyd Filter	1.00	176.92	176.92	\$176.92	N
TY26797	10W30 18.9L Torq-Gard CJ4/SM	5.00	144.33	144.33	\$721.65	N
TY27956	TORQ-GARD II 10W30 CK4 18.9L	1.00	144.50	144.50	\$144.50	N
Miscellaneous						
EF100	ENVIRO FEE	3.00	1.25	1.25	\$3.75	N
EF300	ENVIRO FEE	6.00	3.00	3.00	\$18.00	N

Labor: \$210.00	Parts: \$1,668.27	OL&M: \$0.00	Misc: \$21.75	Sub-Total: \$1,800.02
------------------------	--------------------------	-------------------------	----------------------	------------------------------

J21001090 JD 616R

COMPLAINT:

09 REPLACE ENGINE FUEL FILTERS

CORRECTION:

Tuesday, February 11, 2025 3:44 PM -
 UNPLUGGED ELECTRICAL CONNECTOR.
 REMOVED FUEL FILTERS.
 CLEANED AND INSTALLED NEW FILTERS.
 ENGINE HOURS AND DATE MARKED ON NEW FILTERS INSTALLED.
 PRIMED FUEL SYSTEM AND CHECKED FOR LEAKS.
 STARTED AND RAN SPRAYER.

FUEL ADDED TO RUN.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ112918	FINAL FUEL FILTER	1.00	236.54	236.54	\$236.54	N
DZ130550	Primary Fuel Filter	1.00	232.82	232.82	\$232.82	N
Miscellaneous						
BULKFUEL	BULK FUEL CHARGE	100.00	1.79	1.79	\$179.00	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Belcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2636
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number: **3337451**
 Invoice Date: 3/18/2025
 Location: 01
 Work Order Number: 474838
 Payment Type:
 Page: 5 of 22

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

J21001090 JD 616R

EF100	ENVIRO FEE	2.00	1.25	1.25	\$2.50	N
-------	------------	------	------	------	--------	---

Labor: \$70.00	Parts: \$469.36	OL&M: \$0.00	Misc: \$181.50	Sub-Total: \$720.86
----------------	-----------------	--------------	----------------	---------------------

JENGOILCHNG JD 616R

COMPLAINT:

10 REPLACE ENGINE OIL AND FILTER

CORRECTION:

Tuesday, February 11, 2025 1:54 PM -

REMOVED COVER.

REMOVED PRIMARY ENGINE AIR FILTER AND CLEANED HOUSING.

REMOVED SECONDARY AND REPLACED WITH NEW.

INSTALLED PRIMARY ENGINE AIR FILTER.

MARKED ENGINE HOURS AND DATE ON NEW FILTERS INSTALLED.

REINSTALLED HOUSING COVER.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE509672	Engine Oil Filter	1.00	49.00	49.00	\$49.00	N
TY26674	PLUS-50 II 15W-40 CK4/SN BOTTLE 946ml	1.00	9.92	9.92	\$9.92	N
TY26675	PLUS-50 II 15W-40 CK4/SN JUG 9.46L	1.00	89.73	89.73	\$89.73	N
TY26679	PLUS-50 II 15W-40 CK4/SN 18.9L PAIL	1.00	170.86	170.86	\$170.86	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF15	ENVIRO FEE	1.00	0.15	0.15	\$0.15	N
EF150	ENVIRO FEE	1.00	1.50	1.50	\$1.50	N
EF300	ENVIRO FEE	1.00	3.00	3.00	\$3.00	N
EF50	ENVIRO FEE	1.00	0.55	0.55	\$0.55	N

Labor: \$100.00	Parts: \$319.51	OL&M: \$0.00	Misc: \$5.20	Sub-Total: \$424.71
-----------------	-----------------	--------------	--------------	---------------------

JENGAIRFILT JD 616R

COMPLAINT:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

		Invoice Number:	3337451
		Invoice Date:	3/18/2025
		Location:	01
		Work Order Number:	474838
		Payment Type:	
Bus Phone:	Bus Phone:		
Prv Phone:	Prv Phone:		
		Page	6 of 22

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

JENGAIRFILT JD 616R

11 REPLACE PRIMARY AND SECONDARY ENGINE AIR FILTERS

CORRECTION:

REMOVED AND REPLACED PRIMARY AND SECONDARY ENGINE AIR FILTERS.
 CLEANED HOUSING.
 INSTALLED NEW FILTERS WITH ENGINE HOURS MARKED ON FILTERS INSTALLED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AKK37892	PRIMARY ENGINE AIR FILTER	1.00	530.26	530.26	\$530.26	N
AKK37893	Secondary EngAir Filter	1.00	309.17	309.17	\$309.17	N
Labor: \$50.00		Parts: \$839.43	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$889.43	

J21150201 JD R4044

COMPLAINT:

12 REPLACE BOTH FENCE ROW NOZZLES. ONE IS MISSING AND ONE IS BROKEN.

CORRECTION:

Tuesday, February 11, 2025 1:30 PM -
 REMOVED AND REPLACED BROKEN LH FENCE ROW NOZZLE.
 REMOVED RH FENCE ROW NOZZLE AND BRACKET.
 BRACKET WAS QUITE BENT.
 DISASSEMBLED AND STRAIGHTENED BRACKET.
 REINSTALLED BRACKET WITH NEW FENCE ROW NOZZLE.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AKK17746	NozzleQD bulkhead_1/2" PTC	2.00	73.63	73.63	\$147.26	N
PS90420	NozzleCap Black	2.00	1.40	1.40	\$2.80	N
SPPOC-06	OC-06 OFF CENTRE BRASS TIP	2.00	15.26	15.26	\$30.52	N
Labor: \$100.00		Parts: \$180.58	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$280.58	

JRINSEGAUGE JD R4060

COMPLAINT:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3337451
		Invoice Date:	3/18/2025
		Location:	01
		Work Order Number:	474838
		Payment Type:	
		Page:	7 of 22

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

JRINSEGAUGE JD R4060

13 REPLACE RINSE TANK SIGHT GAUGE

CORRECTION:

REMOVE MOUNTING CLAMPS.
 REPLACE SIGHT GAUGE TUBE.
 INSTALL REMOVED HARDWARE.
 FUNCTION AND LEAK TEST.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
PMK010-1216	3/4" Clear PVC /ft	5.00	3.54	3.54	\$17.70	N
Labor: \$140.00		Parts: \$17.70	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$157.70	

J21001051 JD 616R

COMPLAINT:

14 REMOVE AND CLEAN ALL SOLUTION STRAINERS.
 ALSO CLEAN ALL SPRAY TIP STRAINERS.

CORRECTION:

Tuesday, February 11, 2025 11:46 AM -
 CLEANED AND REMOVED ALL NOZZLE TIPS.
 CLEANED STRAINERS ON ALL NOZZLES.
 INNER BOOM NOZZLES WERE CAKED AND SEIZED ON NEEDED TO WORK FREE IN ORDER TO GET OFF OF BOOM.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
PSLDXQ2003	LDX-Blue Nozzle	4.00	13.40	13.40	\$53.60	N
PSLDXQ2004	LDX-Red Nozzle	4.00	13.40	13.40	\$53.60	N
PSLDXQ2005	LDX-Brown Nozzle	5.00	13.40	13.40	\$67.00	N
PSLDXQ2006	LDX-Grey Nozzle	5.00	13.40	13.40	\$67.00	N
Labor: \$500.00		Parts: \$241.20	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$741.20	

JSOLUGAUGE JD R4045

COMPLAINT:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3337451
		Invoice Date:	3/18/2025
		Location:	01
		Work Order Number:	474838
		Payment Type:	
		Page:	8 of 22

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

JSOLUGAUGE JD R4045

15 REPLACE SOLUTION TANK SIGHT GAUGE

CORRECTION:

REMOVE MOUNTING CLAMPS.
 REPLACE SIGHT GAUGE TUBE.
 INSTALL REMOVED HARDWARE.
 FUNCTION AND LEAK TEST.


Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
PMK010-1216	3/4" Clear PVC /ft	6.00	3.54	3.54	\$21.24	N
Labor: \$140.00		Parts: \$21.24	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$161.24	

J21130212 JD R4044

COMPLAINT:

16 LH BREAKAWAY BOOM, REPAIR AS IT IS CRACKED.

CORRECTION:



PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3337451
		Invoice Date:	3/18/2025
		Location:	01
		Work Order Number:	474838
		Payment Type:	
		Page:	9 of 22

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

J21130212 JD R4044

REMOVED LH BREAKAWAY AND BROUGHT INSIDE.
 FOUND 3 FISSURES IN BREAKAWAY BOOM.
 REMOVED PLUMBING AND BRACKETS.
 IT WAS DECIDED NOT TO USE CARBON FIBER REPAIR KITS AND INSTEAD TO EPOXY AS CRACKING WAS NOT SIGNIFICANT ENOUGH.
 USED EPOXY AND COVERED AREAS (X4).
 AFTER THIS WAS DONE SANDED EPOXY DOWN.
 WHEN REINSTALLING BRACKET FOUND THAT RIVETS WOULD NOT HOLD IN HOLES IN ONE OF THE BRACKETS.
 REMOVED BRACKET AND WILL MOVE OVER.
 COVERED HOLES WITH EPOXY AND WILL HAVE TO MOVE BRACKET OVER ONCE EPOXY IS DRY.

Monday, March 3, 2025 10:42 AM -
 BEGAN TO BUFF OFF EPOXY FROM SIDE OF BOOM WHERE REPAIRS WERE MADE.

Monday, March 3, 2025 2:33 PM -
 EPOXY WAS ALLOWED TO DRY OVER WEEKEND.
 FINISHED BUFFING OFF AND SMOOTH OFF AREAS WHERE REPAIRS WERE MADE.
 WIPED OFF AND CLEANED MATERIAL BEFORE APPLYING PAINT.
 APPLIED PAINT TO AREAS WHERE REPAIRS WERE MADE.
 AFTER PAINT IS DRY WILL DRILL OUT AND INSTALL BRACKETS THAT WERE REMOVED IN ORDER TO ALLOW FOR REPAIRS TO BE MADE PROPERLY.

Tuesday, March 4, 2025 5:05 PM -
 INSTALLED LH BREAKAWAY BOOM AND INSTALLED ALL ELECTRICAL AND PLUMBING AND SECURED.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AKK10887	Rivet SST	8.00	4.63	4.63	\$37.04	N
AKK18564	3/16x.925 Rivet SS	5.00	4.35	4.35	\$21.75	N
PSLDXQ2003	LDX-Blue Nozzle	2.00	13.82	13.82	\$27.64	N
T77613	-6FF O-ring	5.00	3.35	3.35	\$16.75	N
T77857	-8FF O-ring	-5.00	3.41	3.41	(\$17.05)	N
LOCTITE398466	Hysol 9460 200ml Epoxy	1.00	134.95	134.95	\$134.95	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Mooseomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number: **3337451**
 Invoice Date: **3/18/2025**
 Location: **01**
 Work Order Number: **474838**
 Payment Type:
 Page: **10 of 22**

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

J21130212 JD R4044						
325.PF609-N	Epoxy Mixing Nozzle 6/pk	1.00	3.95	3.95	\$3.95	N
Labor: \$1,599.75	Parts: \$225.03	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,824.78		

JGEN20- Internal

COMPLAINT:

17 BOOM ADJUSTMENTS.
 ADJUST BOTH BREAKAWAY BOOM SECTIONS, ALIGNMENT AND TENSION.
 ADJUST BOOM SUSPENSION ON BOTH SIDES.
 ADJUST ALL ROPES, T3 LINK, T6 AND T7 ROPES.
 ADJUST OUTER BOOM SECTIONS.

CORRECTION:

Tuesday, March 4, 2025 5:05 PM -
 COMPLETED BOOM ADJUSTMENTS.
 CALIBRATED AUTO FOLD/UNFOLD.

Labor: \$900.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$900.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

J21130213 JD R4060

COMPLAINT:

18 RH BREAKAWAY BOOM, REPLACE AS IT IS DAMAGED ON THE MOUNTING BRACKET.
 ALSO REPLACE BREAKAWAY ROPE ON RIGHT HAND SIDE AS IT IS BROKEN.

CORRECTION:

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

		Invoice Number:	3337451
		Invoice Date:	3/18/2025
		Location:	01
		Work Order Number:	474838
		Payment Type:	
Bus Phone:	Bus Phone:		
Prv Phone:	Prv Phone:		
		Page	11 of 22

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

J21130213 JD R4060

UNFOLDED SPRAYER.

REMOVED PLUMBING.

UNPLUGGED ELECTRICAL AND WRAPPED UP ALONG OUTER BOOM.

REMOVED RH BREAKAWAY AND BROUGHT INSIDE.

FOUND FISSURE IN RH BOOM.

REMOVED PLUMBING AND BRACKETS.

IT WAS DECIDED NOT TO USE CARBON FIBER REPAIR KITS AND INSTEAD TO EPOXY AS CRACKING WAS NOT SIGNIFICANT ENOUGH.

USED EPOXY AND COVERED AREA X1

Tuesday, March 4, 2025 5:06 PM -

COMPLETED REPAIRS ON RH BREAKAWAY BOOM.

REINSTALLED PLUMBING.

REINSTALLED BREAKAWAY ONTO RH BOOM.

PLUGGED IN AND REINSTALLED PLUMBING.

INSTALLED AND SECURED ELECTRICAL.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AKK10887	Rivet SST	5.00	4.63	4.63	\$23.15	N
AKK18564	3/16x.925 Rivet SS	5.00	4.35	4.35	\$21.75	N
AKK22689	Rope, Breakaway Stop	1.00	280.85	280.85	\$280.85	N
RE258807	7" Ziptie w/ Slide Tree	1.00	2.69	2.69	\$2.69	N
T77613	-6FF O-ring	5.00	3.35	3.35	\$16.75	N
T77857	-8FF O-ring	5.00	3.41	3.41	(\$17.05)	N

Labor: \$900.45	Parts: \$328.14	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,228.59
------------------------	------------------------	-------------------------	---------------------	------------------------------

JGEN18-

COMPLAINT:

19 OUTSIDE BREAKAWAY LIFT CYLINDER IS LEAKING . REMOVE AND RESEAL.

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Belcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2672	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

		Invoice Number:	3337451
		Invoice Date:	3/18/2025
		Location:	01
		Work Order Number:	474838
		Payment Type:	
		Page:	12 of 22
Bus Phone:	Bus Phone:		
Prv Phone:	Prv Phone:		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

JGEN18-

Monday, February 24, 2025 4:37 PM -
 UNFOLDED MACHINE.
 INSPECTED CYLINDER NO VISIBLE LEAKS.
 FITTING IS WHERE THE LEAK IS COMING FROM.
 LOOSENED FITTINGS AND REMOVED O-RINGS AND INSTALLED NEW.
 CLEANED OFF ALL OIL RESIDUE.


Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
T77613	-6FF O-ring	3.00	3.35	3.35	\$10.05	N
T77857	-8FF O-ring	2.00	3.41	3.41	\$6.82	N

Labor: \$260.00	Parts: \$16.87	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$276.87
-----------------	----------------	--------------	--------------	---------------------

J21130015 JD 616R

COMPLAINT:
 20 MAIN BOOM TILT PIVOT PIN & BUSHINGS (RH), REPLACE

CORRECTION:
 SUPPORT BOOM.
 REMOVE TILT PINS.
 MOVE BOOM AWAY.
 REPLACE BUSHINGS.
 MOVE BACK INTO PLACE.
 INSTALL PINS.



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
KK70822	Cotter Pin	1.00	7.77	7.77	\$7.77	N
KK76713	Pin	1.00	120.41	120.41	\$120.41	N
KK76757	Bushing	2.00	35.05	35.05	\$70.10	N
N409842	Bushing	2.00	27.67	27.67	\$55.34	N
83-6043-1	15" LoPro Head Zipties 100pk EA	1.00	1.00	1.00	\$1.00	N

Labor: \$400.00	Parts: \$254.62	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$654.62
-----------------	-----------------	--------------	--------------	---------------------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3337451 Invoice Date: 3/18/2025 Location: 01 Work Order Number: 474838 Payment Type: Page: 13 of 22
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

J21130014 JD 616R

COMPLAINT:

21 MAIN BOOM TILT PIVOT PIN & BUSHINGS (LH), REPLACE

CORRECTION:

SUPPORT BOOM.

REMOVE TILT PINS.

MOVE BOOM AWAY.

REPLACE BUSHINGS.

MOVE BACK INTO PLACE.

INSTALL PINS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
KK70822	Cotter Pin	1.00	7.77	7.77	\$7.77	N
KK76713	Pin	1.00	120.41	120.41	\$120.41	N
KK76757	Bushing	2.00	35.05	35.05	\$70.10	N
N409842	Bushing	2.00	27.67	27.67	\$55.34	N
83-6043-1	15" LoPro Head Zipties 100pk EA	1.00	1.00	1.00	\$1.00	N
Labor: \$400.00		Parts: \$254.62	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$654.62	

JGEN15-

COMPLAINT:

22 RETORQUE CENTERFRAME BOOM HARDWARE.

CORRECTION:

Thursday, February 20, 2025 3:26 PM -

TORQUED ALL CENTER FRAME BOOM HARDWARE.

Labor: \$200.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$200.00
------------------------	----------------------	-------------------------	---------------------	----------------------------

J21070085 JD R4060

COMPLAINT:

23 RIGHT HAND SIDE INNER BOOM CYLINDER, REMOVE & RESEAL AS IT IS LEAKING.

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2636
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone:
Prv Phone:

Bus Phone:
Prv Phone:

Invoice Number: **3337451**
 Invoice Date: **3/18/2025**
 Location: **01**
 Work Order Number: **474838**
 Payment Type:
 Page: **14 of 22**

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

J21070085 JD R4060

CORRECTION:

Tuesday, February 18, 2025 2:55 PM -
 LOOSENED REMOVED HYDRAULIC LINES.
 REMOVED HARDWARE HOLDING PIN.
 BEGAN TO REMOVE OUTER PIN.
 USED PENETRATING FLUID TO REMOVE SEIZED PIN.
 REMOVED PIN.
 DRAINED HYDRAULIC FLUID FROM CYLINDER.
 REMOVED RETAINING RING.
 INSTALLED FILLER RING.
 REMOVED ROD.
 HEATED AND REMOVED NUT.
 REMOVED AND REPLACED SEALS ON PISTON AND ROD.
 CLEANED AND INSTALLED NEW SEALS.
 REINSTALLED PISTON AND ROD WITH NEW SEALS.
 INSTALLED NUT AND TORQUED TO 258 FT/LBS AND ADDITIONAL TORQUE TURN OF 30 DEGREES AS PER MANUAL.
 WHILE INSTALLING ONTO UNIT PULLED ROD END BACK TOO FAR AND HOOKED ON EDGE OF ROD AND TORE SEALS ON INNER.
 REMOVED CYLINDER ROD.
 REMOVED NUT, PISTON AND ROD END.
 REMOVED DAMAGED SEALS (HAD TO ORDER WILL BE HERE 2/19/2025)

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AHC16970	HydCyl Piston Seal Kit	1.00	163.28	163.28	\$163.28	N
AHC16974	HyCyl Bore SealKit	1.00	131.10	127.06	\$127.06	N
AHC16988	HydCyl Rod SealKit	1.00	54.28	54.28	\$54.28	N
H212793	HydCyl FillerRing .236	1.00	40.13	40.13	\$40.13	N
Labor: \$436.00		Parts: \$384.75	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$820.75	

JENGDIAG1 JD ALL .

COMPLAINT:

24 DIAGNOSE AND REPAIR OIL LEAK AT OIL SUPPLY LINE TO THE ON BOARD AIR COMPRESSOR.

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3337451
		Invoice Date:	3/18/2025
		Location:	01
		Work Order Number:	474838
		Payment Type:	
		Page:	15 of 22

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

JENGDIAG1 JD ALL

RECORD DIAGNOSTIC TESTS, PROCEDURES AND RESULTS: _____

Friday, February 7, 2025 4:59 PM -
 REMOVED FLOOR MAT AND ACCESS PANELS.
 COULD NOT REACH FITTING FROM FLOOR.
 REMOVED RH PANELING TO ACCESS TOP OF TRANSMISSION.
 BROKEN FITTING FREE.
 CLEANED OFF AND REMOVED HOSE.
 REMOVED O-RING AND REINSTALLED LINE.
 REINSTALLED RH ACCESS PANEL.
 INSTALLED ACCESS PANELS AND FLOOR MAT.
 RAN AND CHECKED FOR LEAKS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
T77857	-8FF O-ring	1.00	3.30	3.30	\$3.30	N
Labor: \$300.00		Parts: \$3.30	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$303.30	

JWHLTOEADJ JD 616R

COMPLAINT:
 25 ADJUST FRONT WHEEL TOE.
 TIGHTEN FIXED SIDE OF BALL JOINT ON LEFT HAND STEERING CYLINDER.

CORRECTION:

Labor: \$250.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$250.00
-----------------	---------------	--------------	--------------	---------------------

JTREADADJ1 JD 616R

COMPLAINT:
 26 ADJUST AXLE TREAD ADJUST SHIMS. FRONT AND REAR

CORRECTION:

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3337451
		Invoice Date:	3/18/2025
		Location:	01
		Work Order Number:	474838
		Payment Type:	
		Page:	16 of 22

Make/Model	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

JTREADADJ1 JD 616R

RAISED WHEEL FROM GROUND.
 ADJUSTED TREAD ADJUST WIDTH ON WHEEL STATION TO 70 INCHES.
 REMOVED ADJUSTING SCREWS AND FIXED WEDGE SCREWS ONE AT A TIME AND COATED WITH NEVER SEIZE.
 RE-INSTALLED FIXED WEDGE BOLTS BUT LEFT LOOSE, TO ALLOW WEDGE TO SHIFT TO CORRECT POSITION.
 RE-INSTALLED ADJUSTING SCREWS AND TORQUED TO 105 LB-FT.
 TORQUED FIXED WEDGE SCREWS TO 184 LB-FT.
 BACKED OFF ADJUSTING SCREWS 1/6TH OF A TURN.
 TORQUED JAM NUTS TO 350 LB-FT.

REPEATED FOR ALL FOUR WHEEL STATIONS.
 CHECKED OPERATION OF TREAD ADJUST.
 CALIBRATED SENSORS IF NECESSARY.

Labor: \$500.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$500.00
-----------------	---------------	--------------	--------------	---------------------

J21130350 JD 616R

COMPLAINT:
 27 UNDERFRAME MIRROR, REPLACE MIRROR ON RIGHT HAND SIDE

CORRECTION:
 Tuesday, February 11, 2025 5:17 PM -
 REMOVED UNDERSIDE MIRROR AND ELECTRICAL CONNECTOR.
 UNBOXED NEW MIRROR.
 NEW MIRROR IS NOT RIGHT STYLE AND HAS NO ELECTRICAL CONNECTOR.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AKK34593	MIRROR ASSY	1.00	493.55	493.55	\$493.55	N
Labor: \$80.00	Parts: \$493.55	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$573.55		

JGEN09-

COMPLAINT:
 28 DIAGNOSE AND REPAIR OIL WEEP FROM THE FRONT RIGHT WHEEL MOTOR. POSSIBLY LEAKING FROM THE SPEED CONTROL VALVE HOUSING MOUNT TO THE MOTOR.

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3337451
		Invoice Date:	3/18/2025
		Location:	01
		Work Order Number:	474838
		Payment Type:	
		Page:	17 of 22

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

JGEN09-CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
T240987	O-Ring	1.00	58.21	58.21	\$58.21	N
T325019	Gasket	1.00	213.94	213.94	\$213.94	N
T358546	O-Ring	1.00	41.32	41.32	\$41.32	N
T381225	O-Ring	3.00	33.06	33.06	\$99.18	N
Labor: \$800.00		Parts: \$412.65	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,212.65	

JGEN08-COMPLAINT:

29 DIAGNOSE AND REPAIR OIL WEEP FROM THE FRONT LEFT WHEEL MOTOR, POSSIBLY LEAKING FROM THE SPEED CONTROL VALVE HOUSING MOUNT TO THE MOTOR.

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
T240987	O-Ring	1.00	58.21	58.21	\$58.21	N
T325019	Gasket	1.00	213.94	213.94	\$213.94	N
T347010	O-Ring	1.00	19.81	19.81	\$19.81	N
T381225	O-Ring	3.00	33.06	33.06	\$99.18	N
Labor: \$800.00		Parts: \$391.14	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,191.14	

JHYDDIAG2 JD ALL

COMPLAINT:

30 REPLACE BOTH FRONT HYDRO DRIVE HOSES AS THEY ARE DAMAGED WHERE THEY GO THROUGH THE SWIVEL CLAMPS.

CORRECTION:

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

		Invoice Number:	3337451
		Invoice Date:	3/18/2025
		Location:	01
		Work Order Number:	474838
		Payment Type:	
Bus Phone:	Bus Phone:		
Prv Phone:	Prv Phone:	Page:	18 of 22

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

JHYDDIAG2 JD ALL

Martino

11 feb 2025

- 1) Start by removing moon clamps on hydraulic wheel motor and remove hose end.(Left hand side)
 - 2) Remove first hold down clamp and start to fit new hose with new o-ring first o-ring was supplied wrong.
 - 3) Remove clamps one by one and remove old hose systematically and re route new hose.
 - 4) Remove swivel ball clamps from old hose and fit to new hose and fit other end of hose to bulk head manifold with new o-ring.
 - 5) Once all clamps has been fitted tighten clamps to specification.
 - 6) Re torque moon clamps to specification.
- Right hand side.
- 1) Start by removing moon clamps on hydraulic wheel motor and remove hose end.(Left hand side)
 - 2) Remove first hold down clamp and start to fit new hose with new o-ring first o-ring was supplied wrong.
 - 3) Remove clamps one by one and remove old hose systematically and re route new hose.
 - 4) Remove swivel ball clamps from old hose and fit to new hose and fit other end of hose to bulk head manifold with new o-ring.
 - 5) Once all clamps has been fitted tighten clamps to specification.
 - 6) Re torque moon clamps to specification.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7832	M5-0.8 NUT blk	12.00	8.91	8.91	\$106.92	N
AKK30404	Hydro Hose -Front FWD Propel	2.00	1,108.44	1,108.44	\$2,216.88	N
KK81128	M5x20 HexSoc 10.9 blk	12.00	1.59	1.59	\$19.08	N
T59014	-12_6xFlg O-ring	2.00	8.40	8.40	\$16.80	N
T78313	-16_6xFlg O-ring	2.00	8.03	8.03	\$16.06	N
T78393	-20_6xFlg O-ring	1.00	10.67	10.67	\$10.67	N

Labor: \$1,200.00 Parts: \$2,386.41 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$3,586.41

JGEN06-

COMPLAINT:

31 REPLACE BOTH COOLING SYSTEM PRESSURE CAPS.
 TOP UP COOLANT LEVEL.

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE312969	Coolant Cap-Black15psi	2.00	72.92	72.92	\$145.84	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Belcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

		Invoice Number:	3337451
		Invoice Date:	3/18/2025
		Location:	01
		Work Order Number:	474838
		Payment Type:	
Bus Phone:	Bus Phone:		
Prv Phone:	Prv Phone:	Page:	19 of 22

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

JGEN06-

TY26576	COOL-GARD II 50/50 PRE-MIX JUG 9.46L	1.00	63.76	63.33	\$63.33	N
---------	--------------------------------------	------	-------	-------	---------	---

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF150	ENVIRO FEE	1.00	1.50	1.50	\$1.50	N

Labor: \$60.00	Parts: \$209.17	OL&M: \$0.00	Misc: \$1.50	Sub-Total: \$270.67
----------------	-----------------	--------------	--------------	---------------------

JGEN05-

COMPLAINT:

32 PERFORM A PARKED REGEN AS THE SOOT LOAD IS SHOWING 86%.

CORRECTION:

Wednesday, February 26, 2026 2:49 PM -
 TOOK SPRAYER OUT OF SHOP.
 ADDED 100 LITERS OF DIESEL.
 INITIATED PARKED REGENERATION ON SPRAYER.
 ALLOWED TO COMPLETE.
 COOLED DOWN AND BROUGHT INTO SHOP.

Labor: \$130.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$130.00
-----------------	---------------	--------------	--------------	---------------------

JGEN04-

COMPLAINT:

33 BOTH AIR CLEANER DUMP VALVES ARE MISSING. INSTALL 2 NEW ONES.

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AKK37895	AirFilterHousing Dust Valve	2.00	154.88	154.88	\$309.76	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
FRT	FREIGHT	1.00	35.00	35.00	\$35.00	N

Labor: \$80.00	Parts: \$309.76	OL&M: \$0.00	Misc: \$35.00	Sub-Total: \$424.76
----------------	-----------------	--------------	---------------	---------------------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: 3337451 Invoice Date: 3/18/2025 Location: 01 Work Order Number: 474838 Payment Type: Page: 20 of 22
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

JGEN34-

COMPLAINT:

34 DEF LEVEL FLASHING LOW. ADD A JUG.
 ADDED BY BT 3/4/2025

CORRECTION:

Tuesday, March 4, 2025 3:51 PM -
 ADDED DEF FLUID TO TANK AS WARNING WAS ON SCREEN ON START UP.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SWDEF025	DIESEL EXHAUST FLUID	1.00	22.99	22.99	\$22.99	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.25	1.25	\$1.25	N
Labor: \$25.00	Parts: \$22.99	OL&M: \$0.00	Misc: \$1.25	Sub-Total: \$49.24		

JGEN35-

COMPLAINT:

36 L.H. INNER TO OUTER BOOM BUSHING IS BROKEN.

CORRECTION:

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3337451
		Invoice Date:	3/18/2025
		Location:	01
		Work Order Number:	474838
		Payment Type:	
		Page:	21 of 22

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

JGEN35-

Tuesday, March 11, 2025 4:33 PM -

STARTED SPRAYER.

LIFTED BOOMS FROM CRADLE.

USED BOOM MAINTENANCE AND SWUNG INNER BOOMS OUTWARD OUT AND AWAY FROM CRADLES.

LOWERED LH BOOM TO WORKING HEIGHT.

RELIEVED PRESSURE IN OUTER BOOM CYLINDER.

REMOVED FASTENERS AND LOWER PIN.

REMOVED BUSHING ON LH OUTER SIDE.

REPLACED WORN BUSHING.

INSPECTED OTHER BUSHINGS DID NOT NEED TO REPLACE AT THIS TIME.

INSTALLED NEW BUSHING.

INSTALLED PIN AND PLASTIC PULLEY FOR ROPE.

INSTALLED FASTENERS AFTER ALIGNING PIN.

CORRECTED AND MOVED HARNESS AWAY FROM ROPE.

REPLACED O-RING ON CYLINDER.

TIGHTENED HYDRAULIC LINES.

STARTED SPRAYER AND MOVED BOOMS TO HOME POSITION.

RAN SPRAYER OUTSIDE

UNFOLDED BOOM AND CHECKED.

AFTER DOING SO RH BREAKAWAY SECTION AT END WAS MISSING CRADLE.

UPLOADED BHC SOFTWARE TO SEE IF IT WOULD CORRECT IT.

COMPLETED CALIBRATION.

AFTER DOING SO RH BOOM WOULD HIT CRADLE WHILE FOLDING.

UNFOLDED AND FOLDED SPRAYER SEVERAL MORE TIMES TO CHECK THAT BOOM WOULD LAND IN CRADLE.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
KK33266	Bushing	1.00	18.30	18.30	\$18.30	N
T77613	-6FF O-ring	1.00	3.35	3.35	\$3.35	N

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
 2777 North Service Road West
 Swift Current, SK S9H 5M1
 Phone: (306) 773-9351
 Fax: (306) 773-2045
 Http://www.pattisonag.com
 GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Belcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No:

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number:	3337451
		Invoice Date:	3/18/2025
		Location:	01
		Work Order Number:	474838
		Payment Type:	
		Page:	22 of 22

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 616R 132' CB 1600GL 800/55/R4	1088	1N0616RXLN0238167	166025	CS002

JGEN35-							
T77857	-8FF O-ring	-1.00	3.41	3.41	(\$3.41)	N	

Labor: \$599.40	Parts: \$18.24	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$617.64
-----------------	----------------	--------------	--------------	---------------------

INVOICE CONTAINS \$12.60 DISCOUNT

Miscellaneous Charges:
 SERVICE ACCESSORIES

\$150.00

Customer PO No:
 Tax Exempt No:
 Advisor:

Job Total: \$25,013.42
 Grand Total: \$25,013.42

*** DOCUMENT COPY ***

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE – MIN \$35 ON EMERGENCY/UNIT DOWN ORDERS – 25% RESTOCKING FOR RET

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: _____ Date: _____