

Experian AutoCheck Report

Report run: 10/06/2026 14:04:23 EDT

2021 GMC Sierra 2500HD

Crew Cab 4D (6.6L V8 DI Gasoline)


VIN:	1GT18LE79MF205730
Class:	Pickup - Fullsize
Country of Assembly:	United States
Vehicle Age:	5 year(s)
Estimated In Service:	09/02/2021
Last Reported Odometer:	120,196 (07/29/2026)

One Owner

AutoCheck

Vehicle Usage

Lease



Vehicle History at a Glance

State Title Brand CLEAN	Auction Brand / Issues NO ISSUE	Accident / Damage No Accidents or Damage Reported NO ISSUE
Open Recall Check 1 OPEN RECALL(S)	Insurance Loss / Transfer NO ISSUE	Odometer Check Last reported odometer: 120,196 (07/29/2026) NO ISSUE
Certified Pre-Owned NO CPO INFO AVAILABLE	Service / Repair 1 Service Record(s) Reported NO ISSUE	Additional History NO ISSUES REPORTED



This vehicle is eligible for Buyback Protection




Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

Learn More



Accident & Damage

Your Vehicle Checks Out There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.



Open Recall Check



Information Reported: AutoCheck found 1 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date - 02/21/2024

Recall Type - Safety

NHTSA / OEM Recall No. - 24V060 / N232426400

Campaign Description - Safety: TAILGATE MAY OPEN UNEXPECTEDLY
Status: Remedy Available

[More information](#) including remedy or risk factors. Locate your nearest authorized [GMC Dealer](#) to schedule repair.



Recommended Maintenance

OEM Recommended Maintenance Schedule

Based on your vehicle's last reported mileage, these are the most recent and upcoming recommended maintenance intervals from your vehicle's manufacturer.

OEM Recommended Services



120000 Mile Service

- Change engine oil and filter
- Check accelerator pedal
- Check automatic transmission shift lock control function



127500 Mile Service

Not Yet Due

- Change engine oil and filter
- Check accelerator pedal
- Check automatic transmission shift lock control function



135000 Mile Service

Not Yet Due

- Change engine oil and filter
- Change transfer case fluid
- Check accelerator pedal



Odometer Check



Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported



Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2021 GMC Sierra 2500HD (1GT18LE79MF205730) Report Run Date: 10/06/2026 14:04:23 EDT

2021

Owner 1

Location: TXOwned From: 09/2021Usage: Lease				
Event Date	Location	Odometer	Data Source	Details
09/02/2021	HOUSTON, TX		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
09/11/2021	HOUSTON, TX	10	Motor Vehicle Dept.	Title(Title #:14620144440250006) (Leased Vehicle)
08/23/2022	HOUSTON, TX	25,444	Independent Emission Source	Passed Emission Inspection Passed Safety Inspection
09/12/2022	HOUSTON, TX		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
08/28/2023	HOUSTON, TX	50,975	Independent Emission Source	Passed Emission Inspection Passed Safety Inspection
09/07/2023	HOUSTON, TX		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
09/07/2023	HOUSTON, TX		Motor Vehicle Dept.	Registration Event/Renewal
02/21/2024			Manufacturer	Manufacturer Recall NHTSA Recall 24V060 / Mfr. Recall N232426400 Safety: TAILGATE MAY OPEN UNEXPECTEDLY LOCATE YOUR NEAREST AUTHORIZED GMC DEALER TO SCHEDULE REPAIR. Status: Remedy Available
07/18/2024		71,152	GP1 Chevrolet of Spring 281.469.5222	Vehicle Serviced or Inspected
08/19/2025	HOUSTON, TX	93,860	Independent Emission Source	Passed Emission Inspection Passed Safety Inspection
09/01/2025	HOUSTON, TX		Motor Vehicle Dept.	Registration Event/Renewal
07/29/2026	HOUSTON, TX	120,196	Independent Emission Source	Passed Emission Inspection Passed Safety Inspection
09/01/2026	HOUSTON, TX		Motor Vehicle Dept.	Registration Event/Renewal

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (1GT18LE79MF205730) qualifies for [AutoCheck Buyback Protection](#). If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbpterms or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.