BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***3088045***
Document Date:	4/01/2024
Repair Order No.:	870056
RO Creation Date:	18/12/2023
Rego No.:	XQ78CL
Make/Model:	2017 KENWORTH K200
Vehicle ID No.:	6F5000000HA459565
Fleet No:	
Odometer:	280968
Engine Hours:	
Delivery Date:	17/11/2017
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XQ78CL
Page:	1 of 2

k038 Replace waterpump.

Drained the cooling system, disassembled and removed and replaced the water pump, reassembled all and refilled the cooling system. ***$380.00***

Part Number	Part Description	Quantity	Total Cost
5719759	"CORE	1.00	1,194.00
3678724	SEAL O RING	1.00	22.77
3684384	"SEAL	1.00	50.11
	Parts Totals:	***3.00***	***$1,266.88***

k032 Replaced anyfailed RHS tanks strap rubbers

Removed the failed RH and LH fueltank straps and removed and replaced the strap rubbers, refitted the tank straps and secured all. ***$304.00***

Part Number	Part Description	Quantity	Total Cost
K89-1004-1260	LINING-TANK STRAP	6.00	235.50
K231-496P0L	FUEL TANK STRAP SQUARE	1.00	316.62
2922	REFLEX REFLECTOR AMBER	1.00	5.94
	Parts Totals:	***8.00***	***$558.06***

K046 Mount supplied driving lights to the lower bull bar mounting position. (Lights are in cab LHS)

Mounted and wired up the supplied driving lights on the bull bar as requested. ***$449.20***

Part Number	Part Description	Quantity	Total Cost
LT13/30	LOOM TUBE SOLIT	1.00	26.88
LT10/30	LUME TUBE SPLIT	1.00	20.88
PR12V200	RELAY POWER N/O 12V 200A RESISTOR	1.00	43.88
WIRING, CONDUIT, ETC	Wiring, Conduit, Terminals and Ties	1.00	45.00
	Parts Totals:	***4.00***	***$136.64***

K038-1 Horton needsrekit

Disassembled and removed the Hortonfan hub, disassembled and cleaned the Horton fan hub, reassembled and kitted and reassembled the Horton fan hub, refittedthe Horton fan hub, reassembled all and ran up and checked operation. ***$855.02***

Part Number	Part Description	Quantity	Total Cost
F35008SD	HT/S SUPER DUTY OEM KIT	1.00	769.63
BBC4	BRAKE CLEANER	2.00	9.98

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***3088045***
Document Date:	4/01/2024
Repair Order No.:	870056
RO Creation Date:	18/12/2023
Rego No.:	XQ78CL
Make/Model:	2017 KENWORTH K200
Vehicle ID No.:	6F5000000HA459565
Fleet No:	
Odometer:	280968
Engine Hours:	
Delivery Date:	17/11/2017
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XQ78CL
Page:	2 of 2

1896741	HEX. BOLT METRIC M12X50		2.00	9.70
K233-490-55	STUD-FAN HUB		2.00	37.80
		Parts Totals:	***7.00***	***$827.11***

Advisor: Allan Mungai

PART S	$2,788.69
LABOUR	$1,988.22
MISC. CONSUMABLES	$59.71
ENVIRONMENTAL LEVY	$10.00
SUBLET	$0.00
OTHER CHARGES	$0.00
TOTAL GST CHARGED	$484.66
TOTAL Incl. GST	$5,331.28

Workshop Trading Hours: Mon-Fri 6:30am to 9:15pm, Sat 8am to 12pm
*** Refrigerant trading authority number: AU13435 ***

Customer's Signature

Bank Account Details for Direct Payments:
Bank: CBA Branch: Kyogle
BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd