# Experian AutoCheck Report

Report run: 11/09/2026 13:05:48 EST

## 2017 Ford F-150 Lariat / XL / XLT

Extended Cab 4D (5.0L V8 SMPI Flex Fuel)

| | |
|---|---|
| **VIN:** | 1FTFX1EF4HFB50243 |
| **Class:** | Pickup - Fullsize |
| **Country of Assembly:** | United States |
| **Vehicle Age:** | 9 year(s) |
| **Estimated In Service:** | 02/16/2017 |
| **Last Reported Odometer:** | 192,000 (04/01/2025) |

One Owner AutoCheck

**Vehicle Usage**
Personal

83 — 72 — 91

## AutoCheck Score

Similar vehicles usually range between **83 and 91**

## Vehicle History at a Glance

**State Title Brand**
CLEAN

**Auction Brand / Issues**
NO ISSUE

**Accident / Damage**
MODERATE

**Open Recall Check**
3 OPEN RECALL(S)

**Insurance Loss / Transfer**
NO ISSUE

**Odometer Check**
Last reported odometer:
**192,000 (04/01/2025)**
NO ISSUE

**Certified Pre-Owned**
NO CPO INFO AVAILABLE

**Service / Repair**
6 Service Record(s) Reported
NO ISSUE

**Additional History**
NO ISSUES REPORTED


1 Year AutoCheck BUYBACK Protection

### This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. Terms & Conditions

Learn More

## Accident & Damage



Airbag Deployed

Overturned

Structural Damage

Moderate

| Damage Date | Damage Type | Severity |
|---|---|---|
| 08/29/2023 | Collision | Moderate |

Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.

## Open Recall Check

### Information Reported: AutoCheck found 3 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

**Recall Date** - 12/17/2018

**Recall Type** - Safety

**NHTSA / OEM Recall No.** - 18V894 / 18S45

**Campaign Description** - Safety Recall: ENGINE BLOCK HEATER WIRE ASSEMBLY - WATER INTRUSION OR CORROSION
Status: Remedy Unknown

**Recall Date** - 12/20/2018

**Recall Type** - Safety

**NHTSA / OEM Recall No.** - 18V894 / 18S45

**Campaign Description** - Safety Recall: ENGINE BLOCK HEATER WIRE ASSEMBLY - WATER INTRUSION OR CORROSION
Status: Remedy Available

**Recall Date** - 04/20/2026

**Recall Type** - Safety

**NHTSA / OEM Recall No.** - 26V237 / 26S28

**Campaign Description** - Safety Recall: POWERTRAIN CONTROL MODULE PCM REPROGRAMMING
Status: Remedy Not Available

More information including remedy or risk factors. Locate your nearest authorized Ford Dealer to schedule repair.

## Service History

### Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.

#### Regular Oil Changes

- 1 oil services reported
- Last oil service reported 08/05/2017

#### Fluids Maintained

Information not available.

#### OEM Recommended Services

**190000 Mile Service**

- Adjust Tire Pressure
- Balance Tires

### Brakes Maintained

- 2 brake pad replacements
- Brake last maintained on 10/23/2023

### Tires Maintained

Information not available.

### A/C & Climate Control

Information not available.

### Other Services

- Cabin air filter replaced on 10/23/2023
- Battery replaced on 10/23/2023

- Ford Factory Multi-Point Inspection

### 195000 Mile Service Not Yet Due

- Adjust Tire Pressure
- Balance Tires
- Ford Factory Multi-Point Inspection

## Odometer Check

### Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

**State Title Odometer Check**

No issues reported

**Auction Odometer Check**

No issues reported

**Odometer Calculation Check**

No issues reported

## Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.
**Vehicle:** 2017 Ford F-150 Lariat / XL / XLT (1FTFX1EF4HFB50243) **Report Run Date:** 11/09/2026 13:05:48 EST

2017

### Vehicle Prep and Other Pre-Titling Events

Preparation Date: 02/2017

| Event Date | Location | Odometer | Data Source | Details |
|---|---|---|---|---|
| 02/16/2017 | | | Independent Source | Vehicle Manufactured and Shipped to Dealer |

2017

### Owner 1

Location: IL | Owned From: 06/2017 | Usage: Personal

| Event Date | Location | Odometer | Data Source | Details |
|---|---|---|---|---|
| 06/13/2017 | SAINT LOUIS, MO | 10 | Motor Vehicle Dept. | Title(Title #:THP48997) |
| 06/30/2017 | HOMER GLEN, IL | | Motor Vehicle Dept. | Registration Event/Renewal |
| 07/03/2017 | HOMER GLEN, IL | 20 | Motor Vehicle Dept. | Title(Title #:171846938860) |
| 08/05/2017 | NILES, IL | 8,140 | Independent Repair Center | Lube, Oil And/Or Filter Changed |
| 06/13/2018 | HOMER GLEN, IL | | Motor Vehicle Dept. | Registration Event/Renewal |
| 09/06/2018 | | | Manufacturer | Manufacturer Service Bulletin<br>Mfr. Recall 18N03<br>Warranty Extension - Single Repair: DOOR LATCH FREEZING CONCERNS<br>LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR.<br>Status: Remedy Unknown |

| Event Date | Location | Odometer | Data Source | Details |
|---|---|---|---|---|
| 09/26/2018 | | | Manufacturer | Manufacturer Service Bulletin<br>Mfr. Recall 18N03<br>Warranty Extension - Single Repair: DOOR LATCH FREEZING CONCERNS<br>LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR.<br>Status: Remedy Unknown |
| 12/17/2018 | | | Manufacturer | Manufacturer Recall<br>NHTSA Recall 18V894 / Mfr. Recall 18S45<br>Safety Recall: ENGINE BLOCK HEATER WIRE ASSEMBLY - WATER INTRUSION OR CORROSION<br>LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR.<br>Status: Remedy Unknown |
| 12/20/2018 | | | Manufacturer | Manufacturer Recall<br>NHTSA Recall 18V894 / Mfr. Recall 18S45<br>Safety Recall: ENGINE BLOCK HEATER WIRE ASSEMBLY - WATER INTRUSION OR CORROSION<br>LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR.<br>Status: Remedy Available |
| 05/15/2019 | HOMER GLEN, IL | | Motor Vehicle Dept. | Registration Event/Renewal |
| 05/23/2020 | HOMER GLEN, IL | | Motor Vehicle Dept. | Registration Event/Renewal |
| 06/19/2020 | BERWYN, IL | 84,111 | Independent Repair Center | Tires or Wheels Service Performed |
| 05/07/2021 | BERWYN, IL | 99,094 | Independent Repair Center | Tires or Wheels Service Performed |
| 06/11/2021 | LINCOLNSHIRE, IL | 101,000 | Independent Emission Source | Passed Emission Inspection |
| 06/17/2021 | HOMER GLEN, IL | | Motor Vehicle Dept. | Registration Event/Renewal |
| 06/30/2021 | | | Manufacturer | Manufacturer Service Bulletin<br>Mfr. Recall 20M04<br>Customer Satisfaction Program - Multi Repair: POWER DOOR LOCK ACTUATOR FAILURE<br>LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR.<br>Status: Remedy Unknown |
| 06/23/2022 | HOMER GLEN, IL | | Motor Vehicle Dept. | Registration Event/Renewal |
| 04/28/2023 | ROSELLE, IL | 148,942 | Friendly Ford Inc<br>630.924.8686 | Battery Serviced or Replaced<br>Multiple Point Vehicle Inspection<br>Brakes Serviced<br>Tires or Wheels Service Performed |
| 08/29/2023 | IL | | State Agency | Vehicle Overturned<br>Right Rear Impact with Another Vehicle(Case #:03-23-16007)<br>Moderate Damage Reported |
| 10/19/2023 | SCHAUMBURG, IL | 157,000 | Independent Emission Source | Failed Emission Inspection |
| 10/23/2023 | ROSELLE, IL | 157,311 | Friendly Ford Inc<br>630.924.8686 | Fuel System Serviced<br>Air Filter Changed<br>Battery Serviced or Replaced<br>Multiple Point Vehicle Inspection<br>Engine Serviced<br>Brakes Serviced<br>Starting or Charging System Service Performed<br>Tires or Wheels Service Performed |
| 10/23/2023 | IL | | Service Record | Vehicle Inspected<br>Electrical System Serviced |
| 10/30/2023 | SCHAUMBURG, IL | | Independent Emission Source | Passed Emission Inspection |
| 03/29/2024 | HOMER GLEN, IL | | Motor Vehicle Dept. | Registration Event/Renewal |
| 06/05/2024 | HOMER GLEN, IL | | Motor Vehicle Dept. | Registration Event/Renewal |
| 04/01/2025 | SCHAUMBURG, IL | 192,000 | Independent Emission Source | Passed Emission Inspection |
| 05/20/2025 | HOMER GLEN, IL | | Motor Vehicle Dept. | Registration Event/Renewal |

| Event Date | Location | Odometer | Data Source | Details |
|---|---|---|---|---|
| 04/20/2026 | | | Manufacturer | Manufacturer Recall<br>NHTSA Recall 26V237 / Mfr. Recall 26S28<br>Safety Recall: POWERTRAIN CONTROL MODULE PCM REPROGRAMMING<br>LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR.<br>Status: Remedy Not Available |

**AutoCheck Terms and Conditions**

This report, and any reliance upon it, is subject to **AutoCheck Terms and Conditions**. If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

**Buyback Protection Terms and Conditions**

This vehicle (1FTFX1EF4HFB50243) qualifies for **AutoCheck Buyback Protection.** If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbpterms or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

**About AutoCheck**

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

**Patent Notice**

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.