

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [REDACTED]	Internal Used Stock No. [REDACTED]	Invoice Number: [REDACTED]
		Invoice Date: 7/7/2025
		Location: [REDACTED]
		Work Order Number: [REDACTED]
		Payment Type: [REDACTED]
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	Page: 1 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

EXPERT-1000000122469 Internal

COMPLAINT:

X9 SERIES COMBINE VALUEMAX INSPECTION

CORRECTION:

VALUEMAX GREEN LIGHT SELF PROPELLED COMBINE CHECKLIST

HEADER SERIAL # _____

ENGINE HOURS 731 _____

SEPARATOR HOURS 521 _____

DOES THIS UNIT GET A VALUEMAX STICKER ☒ YES ☐ NO

HAS THE STICKER BEEN INSTALLED ☒ YES ☐ NO

THIS UNIT HAS HAD THE CAB CLEANED _____ GL _____ (INITIAL)

THIS UNIT HAS HAD A FINAL CHECKOVER _____ MM & PS _____ (INITIAL)

THIS UNIT HAS HAD A COMPLETE GREASE JOB _____ MM _____ (INITIAL)

THINGS NOTED BUT NOT REPAIRED ON CUSTOMERS INSTRUCTIONS:

SEE QUOTE

WARRANTY DATES ON REPAIRS COMPLETED:

START DATE: AUGUST 1, 2025

END DATE: AUGUST 1, 2026

Job Total: \$3,860.00

JSOFTWARE JD X9 1100 Internal

COMPLAINT:

UPDATE ALL CONTROLLER SOFTWARE (RECOMMENDED)

CORRECTION:

UPDATED ALL REQUIRED SOFTWARE ON ALL CONTROLLERS

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [REDACTED]	Internal Used Stock No. [REDACTED]	Invoice Number: [REDACTED]
		Invoice Date: 7/7/2025
		Location: [REDACTED]
Bus Phone:	Bus Phone:	Work Order Number: [REDACTED]
Prv Phone:	Prv Phone:	Payment Type: [REDACTED]
		Page: 2 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

JSOFTWARE JD X9 1100 Internal

Labor: \$400.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$400.00
-----------------	---------------	--------------	--------------	---------------------

EXPERT-1000000073963 Internal

COMPLAINT:

FEEDER HOUSE CONVEYOR DRIVE CHAIN, REMOVE AND REPLACE

CORRECTION:

LOOSENED NUT AND MOVE THE SPROCKET REARWARD.

LOOSENED CAP SCREWS AND REMOVED SPACERS FROM BETWEEN THE PLATES.

REMOVED AND REPLACED CHAIN.

ALIGNED THE PREVIOUSLY REMOVED SPACERS AND CAP SCREWS IN THE SLOTS ON THE PLATES.

USED A PRY BAR IN THE HOLES ON THE INSIDE PLATE TO MOVE THE SPROCKET FORWARD AND TIGHTENED NUT TO SPECIFICATION.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE90399	X9 FEEDER CHAIN DRIVE 80H BSN 83000	1.00	1,183.16	1,183.16	\$1,183.16	N
Labor: \$100.00	Parts: \$1,183.16	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,283.16		

JGEN04- Internal

COMPLAINT:

FEEDER HOUSE VALVE BLOCK , LEAKING MAY NEED O-RINGS OR TIGHTENING (RECOMMENDED)

CORRECTION:

CLEANED AREA

REMOVED HYD LINES

REMOVED OLD O-RINGS

LUBED AND INSTALLED NEW O-RINGS

RECONNECTED HYD LINES

TEST RAN

REPAIR VERIFIED

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kevington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [REDACTED] Bus Phone: Prv Phone:	Internal Used Stock No. [REDACTED] Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 7/7/2025 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 3 of 21
--	--	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

JGEN04- Internal

Labor: \$80.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$80.00
----------------	---------------	--------------	--------------	--------------------

JGEN05- Internal

COMPLAINT:

2 COUPLERS LEAKING ON MULTI-COUPLER , REPLACE (RECOMMENDED)

CORRECTION:

LEAKING MULTI-COUPPLERS WERE NOT MARKED
CLEANED MULTI-COUPLER FACE AND LOOKED FOR WEEPING OIL
REMOVED TWO LEAKING MULTI COUPLERS
INSTALLED NEW MULTI COUPLERS
CLEANED AREA OF HYDRAULIC OIL
REPAIR VERIFIED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE73035	X9 MC Coupler 1/2" FM	2.00	490.20	490.20	\$980.40	N
Labor: \$180.00	Parts: \$980.40	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,160.40		

JGEN06- Internal

COMPLAINT:

REPLACE MULTI-COUPLER DUST COVER BROKEN (RECOMMENDED)

CORRECTION:

REMOVED OLD MULTI-COUPLER DUST SHIELD HINGES
INSTALLED NEW MULTI-COUPLER DUST SHIELD HINGES

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE77006	HINGE	1.00	287.87	287.87	\$287.87	N
Labor: \$60.00	Parts: \$287.87	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$347.87		

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preecaville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [REDACTED]	Internal Used Stock No. [REDACTED]	Invoice Number: [REDACTED]
Bus Phone:	Bus Phone:	Invoice Date: 7/7/2025
Prv Phone:	Prv Phone:	Location: [REDACTED]
		Work Order Number: [REDACTED]
		Payment Type: [REDACTED]
		Page: 4 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

JGEN07- Internal

COMPLAINT:

CLEAN LOCKING PINS ON FEEDER HOUSE (RECOMMENDED)

- HARD TO LATCH

CORRECTION:

SCRAPED OUT ALL DIRT AND DEBRIS FROM LOCKING PINS
SPRAYED PENETRATING OIL ON LOCKINGS PINS
OPENED AND CLOSED MULTI COUPLER HANDLE
PINS SLID IN AND OUT EASIER
REPAIR VERIFIED

Labor: \$50.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$50.00
----------------	---------------	--------------	--------------	--------------------

JGEN08- Internal

COMPLAINT:

FEEDER HOUSE DRIVEN BELT TENSIONER , REPLACE TENSIONER BOLT AND NUT (RECOMMENDED)

CORRECTION:

REMOVED TENSIONER NUTS AND UNIDID PIN AT BOTTOM SECURED WITH COTTER PIN.
PULLED OFF SPRING AND PLASTIC BASE AND TENSIONER GAUGE.
REMOVED IDLER PULLEY TO REMOVE PIN FROM TENSIONER.
REINSTALLED NEW TENSIONER ROD.
REINSTALLED PIN AND COTTER PIN INTO PLACE AND IDLER PULLEY
PUT SPRING AND PLASTIC BASE ONTO ROD AND TENSION BELT.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7276	M16-2.0 NUT	2.00	3.46	3.46	\$6.92	N
AXE88288	Rod	1.00	198.89	198.89	\$198.89	N
Labor: \$150.00	Parts: \$205.81	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$355.81		

JGEN09- Internal

COMPLAINT:

STRAIGHTEN PRE-CLEANER DIVIDERS (RECOMMENDED)

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. XXXXXXXXXX Bus Phone: Prv Phone:	Internal Used Stock No. XXXXXXXXXX Bus Phone: Prv Phone:	Invoice Number: XXXXXXXXXX Invoice Date: 7/7/2025 Location: XXXXXXXXXX Work Order Number: XXXXXXXXXX Payment Type: XXXXXXXXXX Page: 5 of 21
--	--	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

JGEN09- Internal

CORRECTION:

REMOVED BENT PRE CLEANER FIN FROM PRE-CLEANER
STRAIGHTENED OUT FIN WITH HAMMER
REINSTALLED PRE CLEANER FIN ONTO PRE-CLEANER
REPAIR VERIFIED

Labor: \$100.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$100.00
-----------------	---------------	--------------	--------------	---------------------

EXPERT-1000000146238 Internal

COMPLAINT:

ACTIVE TAILINGS SYSTEM SLIP CLUTCH, REMOVE AND REPLACE (RECOMMENDED)

- TAILINGS SLIP CLUTCH LOOSE AND WOBBLER

CORRECTION:

LOOSENEED HARDWARE AND REMOVED TAILINGS AUGER DRIVE BELT.
LOOSENEED AND REMOVED CLEAN GRAIN ELEVATOR DRIVE BELT.
REMOVED LOCK NUT, SLIP CLUTCH ASSEMBLY, AND SHAFT KEY FROM SHAFT.
INSTALLED A NEW SHAFT KEY, INSTALL SLIP CLUTCH ASSEMBLY, AND RETAIN WITH NUT AND TIGHTEN TO SPECIFICATION.
INSTALLED THE TAILINGS AUGER AND CLEAN GRAIN ELEVATOR DRIVE BELTS AND ADJUST TO SPECIFICATION.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE92005	SLIP CLUTCH - CLEANING SHOE RETRESHER	1.00	2,795.22	2,795.22	\$2,795.22	N
Labor: \$300.00		Parts: \$2,795.22	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$3,095.22	

JGEN12- Internal

COMPLAINT:

REPLACE O-RINGS ON CHOPPER GEARCASE LUBE LINE LEAKING (RECOMMENDED)

CORRECTION:

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kinderley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [REDACTED]	Internal Used Stock No. [REDACTED]	Invoice Number: [REDACTED]
		Invoice Date: 7/7/2025
		Location: [REDACTED]
Bus Phone:	Bus Phone:	Work Order Number: [REDACTED]
Prv Phone:	Prv Phone:	Payment Type: [REDACTED]
		Page: 6 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

JGEN12- Internal

REMOVED SHIELD FOR CHOPPER GEARCASE
REMOVED LUBE LINE ON CHOPPER GEARCASE
REPLACED O-RINGS ON LUBE LINE AND FITTING FOR LUBE LINE
RECONNECTED LUBE LINE TO CHOPPER GEAR CASE
REINSTALLED SHIELD
REPAIR VERIFIED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
R26375	8ORB O-Ring	1.00	4.25	4.25	\$4.25	N
T77814	-4FF O-ring	1.00	3.09	3.09	\$3.09	N
Labor: \$70.00		Parts: \$7.34	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$77.34	

JADJCHAFSIEV JD X911 Internal

COMPLAINT:
FACTORY CALIBRATION OF SIEVE AND CHAFFER (RECOMMENDED)

CORRECTION:
OPENED AND CLOSED CHAFFER ALL THE WAY
OPENED 5MM AND USED 5MM GAUGE TOOL TO CHECK
PERFORMED CALIBRATION OF CHAFFER
OPENED AND CLOSED SIEVE ALL THE WAY
OPENED SIEVE 5MM AND USED 5MM GAUGE TOOL TO CHECK
PERFORMED CALIBRATION OF SIEVE
REPAIR VERIFIED

Labor: \$200.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$200.00
-----------------	---------------	--------------	--------------	---------------------

JGEN14- Internal

COMPLAINT:
TAIL BOARD GEARCASE LEAKING, LEFT HAND ,RE-SEAL (RECOMMENDED)

CORRECTION:

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [REDACTED]	Internal Used Stock No. [REDACTED]	Invoice Number: [REDACTED]
Bus Phone:	Bus Phone:	Invoice Date: 7/7/2025
Prv Phone:	Prv Phone:	Location:
		Work Order Number:
		Payment Type:
		Page: 7 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

JGEN14- Internal

REMOVED NUT RETAINING TONE WHEEL TO HEX SHAFT
REMOVED TONE WHEEL
USED SEAL PULLER AND REMOVED LEFT HAND SEAL
LUBED NEW SEAL AND INSTALLED INTO BORE
REINSTALLED TONE WHEEL
PUT BLUE LOCTITE ON THREADS AND INSTALLED NUT
TIGHTENED NUT
REPAIR VERIFIED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DE32519	SEAL	1.00	30.20	30.20	\$30.20	N
Labor: \$600.00		Parts: \$30.20	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$630.20	

EXPERT-1000000019910 Internal

COMPLAINT:
BATTERY BOX DEBRIS, CLEAN (RECOMMENDED)

CORRECTION:
USED AIR GUN AND BLEW OUT ALL DIRT AND DEBRIS
REINSTALLED BATTERY BOX COVER
REPAIR VERIFIED

Labor: \$45.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$45.00
----------------	---------------	--------------	--------------	--------------------

EXPERT-1000000074298 Internal

COMPLAINT:
CLEAN GRAIN ELEVATOR CHAIN SPROCKET, REMOVE AND REPLACE (RECOMMENDED)

- BOTTOM SPROCKET KEY LOOSE, REPLACE

CORRECTION:

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [REDACTED]	Internal Used Stock No. [REDACTED]	Invoice Number: [REDACTED]
		Invoice Date: 7/7/2025
		Location: [REDACTED]
Bus Phone:	Bus Phone:	Work Order Number: [REDACTED]
Prv Phone:	Prv Phone:	Payment Type: [REDACTED]
		Page: 8 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

EXPERT-1000000074298 Internal

OPENED THE CLEAN-OUT DOOR. REMOVE THE NUT AND PIN FROM THE PADDLE CHAIN CONNECTING LINK.
REMOVED CAP SCREWS AND BEARING COVER.
ADJUSTED AUGER TO ITS LOWEST POSITION BY LOOSENING NUTS AND ADJUSTING NUT.
REMOVED CAP SCREW AND CAP SCREW AND WASHER.
REMOVED NUTS AND PLATE.
REMOVED CHAIN SPROCKET AND SHAFT KEY, SPACER, AND WASHER.
INSTALLED THE NEW CHAIN SPROCKET, NEW SHAFT KEY, SPACER, AND WASHER.
INSTALLED PLATE, NUTS, CAP SCREW AND WASHER, AND CAP SCREW.
LOOSELY INSTALLED NUTS.
INSTALLED BEARING COVER USING CAP SCREWS.
INSTALLED PIN AND NUT ONTO THE PADDLE CHAIN CONNECTING LINK.
TURNED NUT TO ADJUST CHAIN TENSION.
TURNING NUT COUNTERCLOCKWISE TIGHTENS CHAIN, AND TURNING NUT CLOCKWISE LOOSENS CHAIN.
AFTER CHAIN IS ADJUSTED, TIGHTENED NUTS TO SPEC

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
49M6480	Shaft Key M8x7x50 2/pkg	1.00	5.26	5.26	\$5.26	N
Labor: \$560.00		Parts: \$5.26	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$565.26	

EXPERT-1000000075643 Internal

COMPLAINT:
RIGHT-HAND CONCAVE, REPAIR AND WELD IF NEEDED(RECOMMENDED)

CORRECTION:
USED VISE GRIP AND HAMMER TO SLIDE OUT WIRES IN CONCAVE
USED TWO FLAT PLATES AND BOLTS TO STRAIGHTEN OUT CONCAVE PLATES
WELDED CRACKS ON PLATE
GROUND DOWN BEADS
RE-FED WIRES THROUGH CONCAVE

Labor: \$300.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$300.00
-----------------	---------------	--------------	--------------	---------------------

EXPERT-1000000179735 Internal

COMPLAINT:

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyla, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [REDACTED]	Internal Used Stock No. [REDACTED]	Invoice Number: [REDACTED]
		Invoice Date: 7/7/2025
		Location: [REDACTED]
Bus Phone:	Bus Phone:	Work Order Number: [REDACTED]
Prv Phone:	Prv Phone:	Payment Type: [REDACTED]
		Page: 9 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

EXPERT-1000000179735 Internal
RIGHT-HAND THRESHING ELEMENT, REMOVE AND REPLACE (RECOMMENDED)

- ELEMENT CRACKED

CORRECTION:

REMOVED THRESHING ELEMENT 4,5,6
HAVE TO REPLACE IN SECTIONS TO KEEP ROTOR BALANCED
INSTALLED NEW THRESHING ELEMENTS ONTO SECTION 4,5,6
SLID CONCAVES ONTO CRADLE
HAND TIGHTENED BOLTS
PRIED CONCAVES UP TO Z-BAR AND INSTALLED CARRIAGE BOLTS
INSTALLED CONCAVE COVER BRACKETS TO CONCAVES
TIGHTENED ALL BOLTS
LEFT SEPARATOR GRATE OFF FOR CONCAVE LEVELING

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
KXE10756	THRESHING ELEMENT RH	1.00	1,306.50	1,306.50	\$1,306.50	N
Labor: \$810.00		Parts: \$1,306.50	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,116.50	

EXPERT-1000000074738 Internal
COMPLAINT:
VACUUM FAN DRIVE BELT, REMOVE AND REPLACE (RECOMMENDED)

CORRECTION:

RAISED THE REAR GULL WING DOOR ON THE RIGHT-HAND SIDE OF THE MACHINE.
REMOVED BOLT OF FAN BRUSH TO SLIDE BELT UNDERNEATH
ROUTED BELT AROUND VACUUM FAN
ROUTED BELT THROUGH PULLEYS
LOOSENED OFF BOLT ON TOP IDLER GUARD
SLID BELT THROUGH
TIGHTENED UP IDLER PULLEY GUARD
TENSIONED BELT
REPAIR VERIFIED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [REDACTED]	Internal Used Stock No. [REDACTED]	Invoice Number: [REDACTED]
		Invoice Date: 7/7/2025
		Location: [REDACTED]
		Work Order Number: [REDACTED]
		Payment Type: [REDACTED]
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	Page: 10 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

EXPERT-1000000074738 Internal
HXE168680 Rotary Screen V-Belt X9 1.00 95.10 95.10 \$95.10 N

Labor: \$120.00 Parts: \$95.10 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$215.10

JBLOWCOLERPK1 JD ALL Internal
COMPLAINT:
WASH/BLOW OUT COOLING PACKAGE ALL MACHINES (RECOMMENDED)

CORRECTION:
WASHED OUT RADIATOR.
WASHED OUT ALL COOLERS.

Labor: \$150.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$150.00

JGEN23- Internal
COMPLAINT:
RE-TIGHTEN HOSE CLAMPS ON MAIN ENGINE GEARCASE, MAIN HYDRAULIC PUMP STACK AND HYDRAULIC RESERVOIR

CORRECTION:
TIGHTENED UP ALL HOSE CLAMPS ON MAIN ENGINE GEARCASE, MAIN HYDRAULIC PUMP STACK, AND HYDRAULIC RESERVOIR

Labor: \$200.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$200.00

JGEN24- Internal
COMPLAINT:
WIRING HARNESS FOR PITCH SENSOR ON FAN NEEDS TO BE RE-SECURED (RECOMMENDED)

CORRECTION:
ROUTED PITCH SENSOR HARNESS FOR FAN CORRECTLY
ALL ZIP-TIES AND CHRISTMAS TREE RETAINERS ARE IN PLACE

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK	(306) 773-9351	Yorkton, SK	(306) 783-9459
Maple Creek, SK	(306) 662-2233	Balcarres, SK	(306) 334-2492
Kindersley, SK	(306) 463-2683	Moosomin, SK	(306) 435-3301
Kyle, SK	(306) 375-2302	Preeceville, SK	(306) 547-2007
Leader, SK	(306) 628-3889	Russell, MB	(204) 773-2149
Unity, SK	(306) 228-2696	Wynyard, SK	(306) 554-2536
North Battleford, SK	(306) 445-4468	Kamsack, SK	(306) 542-2814
Humboldt, SK	(306) 682-2572	Swan River, MB	(204) 734-3466
Kelvington, SK	(306) 327-4355		
Shaunavon, SK	(306) 297-2639		



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [REDACTED]	Internal Used Stock No. [REDACTED]	Invoice Number: [REDACTED]
		Invoice Date: 7/7/2025
		Location: [REDACTED]
		Work Order Number: [REDACTED]
		Payment Type: [REDACTED]
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	Page: 11 of 21

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE X9 1100

734

1H0X911XKN0820301

107646A

JGEN24- Internal

Labor: \$70.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$70.00
----------------	---------------	--------------	--------------	--------------------

JGEN25- Internal

COMPLAINT:

ADJUST STEP IN HOPPER, RUBBING ON ROCKSHAFT (RECOMMENDED)

CORRECTION:

LOOSENED OFF BOLTS ON HOPPER STEP
ADJUSTED STEP TO NOT HIT ROCKSHAFT
TIGHTENED BOLTS
REPAIR VERIFIED

Labor: \$70.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$70.00
----------------	---------------	--------------	--------------	--------------------

EXPERT-1000000077752 Internal

COMPLAINT:

FIRE EXTINGUISHER, CHARGE (RECOMMENDED)

CORRECTION:

FILLED WATER FIRE EXTINGUISHER WITH WATER
CHARGED EXTINGUISHER
RE-SECURED FIRE EXTINGUISHER ONTO BRACKET

Labor: \$50.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$50.00
----------------	---------------	--------------	--------------	--------------------

EXPERT-1000000076484 Internal

COMPLAINT:

FUEL PRECLEANER FILTER, CLEAN (RECOMMENDED)

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. XXXXXXXXXX Bus Phone: Prv Phone:	Internal Used Stock No. XXXXXXXXXX Bus Phone: Prv Phone:	Invoice Number: XXXXXXXXXX Invoice Date: 7/7/2025 Location: XXXXXXXXXX Work Order Number: XXXXXXXXXX Payment Type: XXXXXXXXXX Page: 12 of 21
--	--	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

EXPERT-1000000076484 Internal



CLOSED THE VALVE ON THE FUEL PRE-CLEANER.
 REMOVED THE FUEL PRE-CLEANER FILTER AND CLEANED THE SCREEN.
 INSTALLED THE SCREEN AND FUEL PRE-CLEANER FILTER.
 OPENED THE VALVE FOR THE PRE-CLEANER

Labor: \$25.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$25.00
----------------	---------------	--------------	--------------	--------------------

JENGAIRFILT JD X9 11 Internal

COMPLAINT:
 REPLACE PRIMARY AND SECONDARY ENGINE AIR FILTERS (RECOMMENDED)

CORRECTION:
 REMOVED OLD FILTERS
 CLEANED FILTER HOUSING
 MARKED DATE AND HOURS ON PRIMARY AND SECONDARY ENGINE AIR FILTERS
 INSTALLED NEW FILTERS
 REINSTALLED COVER FOR HOUSING
 REPAIR VERIFIED



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE11090	Primary Engine Air Filter	1.00	477.72	477.72	\$477.72	N
HXE11091	Secondary EngAir Filter	1.00	337.08	337.08	\$337.08	N
Labor: \$50.00		Parts: \$814.80	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$864.80	

JENGOILCHNG JD X9 11 Internal

COMPLAINT:
 REPLACE ENGINE OIL AND FILTER (RECOMMENDED)

CORRECTION:

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No: [REDACTED]	Internal Used Stock No: [REDACTED]	Invoice Number: [REDACTED]
		Invoice Date: 7/7/2025
		Location: [REDACTED]
Bus Phone:	Bus Phone:	Work Order Number: [REDACTED]
Prv Phone:	Prv Phone:	Payment Type: [REDACTED]
		Page: 13 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

JENGOILCHNG JD X9 11 Internal
DRAINED ENGINE OIL INTO PALES
REMOVED OIL FILTER
LUBED O-RING AND INSTALLED NEW FILTER
MARKED HOURS AND DATE ON FILTER
FILLED WITH 57L OF PLUS-50II ENGINE OIL
REPAIR VERIFIED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
RE572785	ENGINE OIL FILTER	1.00	156.67	156.67	\$156.67	N
TY26656B	15/40 II BULK OIL	57.00	8.26	8.26	\$470.82	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.25	1.25	\$1.25	N
EF15	ENVIRO FEE	57.00	0.15	0.15	\$8.55	N
Labor: \$125.00		Parts: \$627.49	OL&M: \$0.00	Misc: \$9.80	Sub-Total: \$762.29	

J10030100 JD X9 1100 Internal
COMPLAINT:
REPLACE ENGINE FUEL FILTERS (RECOMMENDED)

CORRECTION:
REMOVED PRIMARY AND SECONDARY FUEL FILTERS
REMOVED FUEL WATER SEPARATOR FROM FUEL FILTER
CLEANED WATER SEPARATOR
LUBED AND INSTALLED NEW O-RINGS ONTO FILTERS
INSTALLED FUEL FILTERS TO COMBINE
TURNED KEY OVER AND LET FUEL CYCLE
STARTED MACHINE AND CHECKED FOR LEAKS
REPAIR VERIFIED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ124761	Primary Fuel Filter 13.6L	1.00	168.89	168.89	\$168.89	N
DZ124786	Secondary Fuel Filter 13.6L	1.00	162.25	162.25	\$162.25	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Praceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [REDACTED]	Internal Used Stock No. [REDACTED]	Invoice Number: [REDACTED]
Bus Phone:	Bus Phone:	Invoice Date: 7/7/2025
Prv Phone:	Prv Phone:	Location:
		Work Order Number:
		Payment Type:
		Page: 14 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

J10030100 JD X9 1100 Internal
EF100 ENVIRO FEE 2.00 1.25 1.25 \$2.50 N

Labor: \$80.00 Parts: \$331.14 OL&M: \$0.00 Misc: \$2.50 Sub-Total: \$413.64

EXPERT-1000000074132 Internal

COMPLAINT:

FUEL TANK BREATHER, REMOVE AND REPLACE (RECOMMENDED)

CORRECTION:

REMOVED BREATHER CAP

INSTALLED NEW BREATHER CAP

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H216169	DEF Tank Breather	1.00	47.04	47.04	\$47.04	N
Labor: \$17.00		Parts: \$47.04	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$64.04	

EXPERT-1000000076344 Internal

COMPLAINT:

HYDRAULIC LUBE FILTER, REMOVE AND REPLACE (RECOMMENDED)

CORRECTION:

REMOVED FILTER

REMOVED O-RING

INSTALLED NEW O-RING

INSTALLED NEW FILTER

MARKED HOURS ON FILTER

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
R567277	RING	1.00	18.41	18.41	\$18.41	N
RE577250	Hydraulic Oil Filter	1.00	161.70	161.70	\$161.70	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [REDACTED]	Internal Used Stock No. [REDACTED]	Invoice Number: [REDACTED]
Bus Phone:	Bus Phone:	Invoice Date: 7/7/2025
Prv Phone:	Prv Phone:	Location: [REDACTED]
		Work Order Number: [REDACTED]
		Payment Type: [REDACTED]
		Page: 15 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

EXPERT-1000000076344 Internal
EF100 ENVIRO FEE 1.00 1.25 1.25 \$1.25 N

Labor: \$75.00 Parts: \$180.11 OL&M: \$0.00 Misc: \$1.25 Sub-Total: \$256.36

EXPERT-1000000076101 Internal

COMPLAINT:

HYDROSTATIC CHARGE FILTER, REPLACE (RECOMMENDED)

- OMHXE162878 SN(815001-820000)
- OMDXE11330 SN(820001-825000)
- OMDXE11749 SN(825001-)

CORRECTION:

REMOVED THE HYDROSTATIC CHARGE FILTER AND DISCARD.
COATED THE SEAL ON THE REPLACEMENT HYDROSTATIC CHARGE FILTER WITH OIL.
INSTALL THE HYDROSTATIC CHARGE FILTER AND TIGHTENED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
R564922	RING	1.00	16.30	16.30	\$16.30	N
RE577612	Hydraulic Oil Filter	1.00	206.11	206.11	\$206.11	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.25	1.25	\$1.25	N

Labor: \$25.00 Parts: \$222.41 OL&M: \$0.00 Misc: \$1.25 Sub-Total: \$248.66

EXPERT-1000000076103 Internal

COMPLAINT:

AUXILIARY HYDRAULIC RETURN FILTER, REPLACE (RECOMMENDED)

- OMHXE162878 SN(815001-820000)
- OMDXE11330 SN(820001-825000)
- OMDXE11749 SN(825001-)

CORRECTION:

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No: XXXXXXXXXX Bus Phone: Prv Phone:	Internal Used Stock No: XXXXXXXXXX Bus Phone: Prv Phone:	Invoice Number: XXXXXXXXXX Invoice Date: 7/7/2025 Location: XXXXXXXXXX Work Order Number: XXXXXXXXXX Payment Type: XXXXXXXXXX Page: 16 of 21
--	--	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

EXPERT-1000000076103 Internal
 REMOVED FILTER BOWLS FROM FILTER HOUSING
 CLEANED AND COATED THREADS WITH SILVER ANTI SEIZE
 INSTALLED NEW FILTERS INTO BOWLS
 REINSTALLED FILTER BOWLS TO FILTER HOUSING
 REPAIR VERIFIED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE73797	Hydraulic Filter	1.00	172.15	172.15	\$172.15	N
AXE73798	Hydraulic Filter	1.00	211.92	211.92	\$211.92	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	2.00	1.25	1.25	\$2.50	N

Labor: \$25.00 Parts: \$384.07 OL&M: \$0.00 Misc: \$2.50 Sub-Total: \$411.57

EXPERT-1000000076100 Internal
 COMPLAINT:
 MAIN ENGINE GEAR CASE BREATHER, REPLACE (RECOMMENDED)

- OMHXE162878 SN(815001-820000)
- OMDXE11330 SN(820001-825000)
- OMDXE11749 SN(825001-)

CORRECTION:
 REMOVE AND REPLACE THE MAIN ENGINE GEAR CASE BREATHER

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE82230	BREATHER	1.00	144.22	144.22	\$144.22	N

Labor: \$25.00 Parts: \$144.22 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$169.22

J06001001 JD S790 Internal
 COMPLAINT:
 TOP UP ALL FLUIDS - RECOMMENDED
 - MAIN ENGINE GEARCASE OVERFILLED, COOLANT LOW

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [REDACTED]	Internal Used Stock No. [REDACTED]	Invoice Number: [REDACTED]
		Invoice Date: 7/7/2025
		Location: [REDACTED]
		Work Order Number: [REDACTED]
		Payment Type: [REDACTED]
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	Page: 17 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

J06001001 JD S790 Internal

CORRECTION:

DRAINED MAIN ENGINE GEARCASE OIL

RECHECKED LEVEL

OIL LEVEL GOOD

TOPPED UP COOLANT

Labor: \$50.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$50.00
-----------------------	----------------------	-------------------------	---------------------	---------------------------

JCABFILTER JD X9 11 Internal

COMPLAINT:

REPLACE CAB AIR FILTERS - RECOMMENDED

CORRECTION:

REMOVED OLD CAB FILTERS

CLEANED HOUSING

MARKED NEW FILTERS WITH HOURS AND DATE

INSTALLED NEW FILTERS

REPAIR VERIFIED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE70605	Cab Recirc Air Filter	1.00	40.49	40.49	\$40.49	N
TA32591	Cab FreshAir Filter	1.00	125.95	125.95	\$125.95	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
FRT	FREIGHT	1.00	35.00	35.00	\$35.00	N

Labor: \$50.00	Parts: \$166.44	OL&M: \$0.00	Misc: \$35.00	Sub-Total: \$251.44
-----------------------	------------------------	-------------------------	----------------------	----------------------------

EXPERT-1000000291865 Internal

COMPLAINT:

TAILINGS ELEVATOR PADDLE CHAIN, ADJUST

CORRECTION:

CONTINUED ON NEXT PAGE->

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



PATTISON
AGRICULTURE



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [REDACTED]	Internal Used Stock No. [REDACTED]	Invoice Number: [REDACTED]
Bus Phone:	Bus Phone:	Invoice Date: 7/7/2025
Prv Phone:	Prv Phone:	Location: [REDACTED]
		Work Order Number: [REDACTED]
		Payment Type: [REDACTED]
		Page: 18 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

EXPERT-1000000291865 Internal

REMOVED NUTS, SHIELD, AND WASHERS.
LOOSENEED NUTS ON THE BEARING MOUNT PLATE.
LOOSENEED NUTS ON THE ADJUSTING SCREW.
TURNED THE ADJUSTING NUT TO CHANGE THE CHAIN TENSION:
- TURNING THE NUT COUNTERCLOCKWISE TIGHTENS THE CHAIN.
- TURNING THE NUT CLOCKWISE LOOSENS THE CHAIN.
ENSURED THE CHAIN IS ADJUSTED PROPERLY BY CHECKING THAT THE LOWER END CAN MOVE SIDE-TO-SIDE ON THE SPROCKET BUT CANNOT BE PULLED AWAY FROM IT. IF THE CHAIN LOOSENS UP TO 6 MM (1/4 IN) FROM THE SPROCKET, READJUST THE CHAIN.
TIGHTENED ALL NUTS.
REINSTALLED WASHERS, SHIELD, AND NUTS.

Labor: \$50.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$50.00
----------------	---------------	--------------	--------------	--------------------

EXPERT-1000000291867 Internal

COMPLAINT:
CLEAN GRAIN ELEVATOR REMOVE A LINK AND ADJUST - CRITICAL

CORRECTION:
REMOVED NUTS, SHIELD, AND WASHERS.
LOOSENEED NUTS ON THE BEARING MOUNT PLATE.
LOOSENEED NUTS ON THE ADJUSTING SCREW.
TURNED THE ADJUSTING NUT TO CHANGE THE CHAIN TENSION:
- TURNING THE NUT COUNTERCLOCKWISE TIGHTENS THE CHAIN.
- TURNING THE NUT CLOCKWISE LOOSENS THE CHAIN.
ENSURED THE CHAIN IS ADJUSTED PROPERLY BY CHECKING THAT THE LOWER END CAN MOVE SIDE-TO-SIDE ON THE SPROCKET BUT CANNOT BE PULLED AWAY FROM IT. IF THE CHAIN LOOSENS UP TO 6 MM (1/4 IN) FROM THE SPROCKET, READJUST THE CHAIN.
TIGHTENED ALL NUTS.
REINSTALLED WASHERS, SHIELD, AND NUTS.

Labor: \$50.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$50.00
----------------	---------------	--------------	--------------	--------------------

EXPERT-1000000139767 Internal

COMPLAINT:

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [REDACTED]	Internal Used Stock No. [REDACTED]	Invoice Number: [REDACTED]
		Invoice Date: 7/7/2025
		Location: [REDACTED]
Bus Phone:	Bus Phone:	Work Order Number: [REDACTED]
Prv Phone:	Prv Phone:	Payment Type: [REDACTED]
		Page: 19 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

EXPERT-1000000139767 Internal
CONCAVE LEVEL AND ADJUST

CORRECTION:

STARTED COMBINE CLOSED CONCAVES ALL THE WAY
REMOVED SEPARATOR GRATE ON BOTH SIDES
LOOSENED OFF JAM NUTS ON BOTH SIDES
SPUN ROTOR WHILE TIGHTENING NUT FOR LEVELING TILL A TICK SOUND WAS MADE
BACKED OFF NUT UNTIL TICK SOUND WENT AWAY
TIGHTENED JAM NUTS BACK UP
REPEATED PROCESS FOR OTHER SIDE
PERFORMED THRESHING AND CONCAVE LEVELING CALIBRATION
SPUN ROTORS AFTER CALIBRATIONS TO ENSURE NO TICK NOISE WAS BEING MADE
NO NOISE MADE
REINSTALLED SEPARATOR GRATES ON BOTH SIDES
REPAIR VERIFIED

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
03M7199	M12x35.CB 8:8 SN	2.00	2.61	2.61	\$5.22	N
Labor: \$500.00		Parts: \$5.22	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$505.22	

JGEN41- Internal

COMPLAINT:

REPLACE STRAW CHOPPER TENSIONER ROD (THREADS PILED UP)

CORRECTION:

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balfarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Preeceville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. [REDACTED]	Internal Used Stock No. [REDACTED]	Invoice Number: [REDACTED]
		Invoice Date: 7/7/2025
		Location: [REDACTED]
		Work Order Number: [REDACTED]
		Payment Type: [REDACTED]
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	Page: 20 of 21

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

JGEN41- Internal
LOOSENE TENSION
REMOVED HARDWARE, SPRING AND GAUGE
REMOVED COTTER PIN AND WASHER
TRIED REMOVE FASTENER PIN BUT IT WAS INSTALLED INCORRECTLY FACING TO THE PULLEY
REMOVED SEPARATOR AIR DUCT
REMOVED CHOPPER BELT FROM TENSION IDLERS
TRIED TO PIVOT ARM UP AND TRIED TO REMOVED FASTENER PIN AGAIN BUT IT DIDN'T WORK
CUT TENSIONER IN HALF FOR EASY REMOVAL
REMOVED TENSION ARM WITH DOUBLE IDLERS
REMOVED BOTTOM IDLER AND REMOVE FASTENER PIN AND DISCONNECT TENSIONER ROD FROM ARM
REINSTALLED IDLER AND TIGHT TO SPEC
REINSTALLED TENSION ARM WITH TWO IDLERS ONTO UNIT AND TIGHT TO SPEC
INSTALLED NEW TENSIONER ROD AND CONNECT TO THE TENSION ARM, SECURE WITH WASHER AND COTTER PIN
REINSTALLED PIVOT GUIDE, TENSION GAUGE, SPRING AND TENSIONER HARDWARE
REINSTALLED CHOPPER BELT
TIGHTENED COPPER BELT AS REQUIRE
REINSTALLED SEPARATOR AIR DUCT
RUN AND CHECK UNIT

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
14M7276	M16-2.0 NUT	2.00	3.34	3.34	\$6.68	N

PATTISON AGRICULTURE LIMITED
Hwy 8 South
Kamsack, SK S0A 1S0
Phone: (306) 542-2814
Fax: (306) 542-2178
Http://www.pattisonag.com
GST Number 818708372

Swift Current, SK (306) 773-9351	Yorkton, SK (306) 783-9459
Maple Creek, SK (306) 662-2233	Balcarres, SK (306) 334-2492
Kindersley, SK (306) 463-2683	Moosomin, SK (306) 435-3301
Kyle, SK (306) 375-2302	Prescaville, SK (306) 547-2007
Leader, SK (306) 628-3889	Russell, MB (204) 773-2149
Unity, SK (306) 228-2696	Wynyard, SK (306) 554-2536
North Battleford, SK (306) 445-4468	Kamsack, SK (306) 542-2814
Humboldt, SK (306) 682-2572	Swan River, MB (204) 734-3466
Kelvington, SK (306) 327-4355	
Shaunavon, SK (306) 297-2639	



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No: XXXXXXXXXX Bus Phone: Prv Phone:	Internal Used Stock No: XXXXXXXXXX Bus Phone: Prv Phone:	Invoice Number: XXXXXXXXXX Invoice Date: 7/7/2025 Location: XXXXXXXXXX Work Order Number: XXXXXXXXXX Payment Type: XXXXXXXXXX Page: 21 of 21
--	--	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE X9 1100	734	1H0X911XKN0820301	107646A	

JGEN41- Internal						
AXE88250	Rod	1.00	226.87	226.87	\$226.87	N

Labor: \$310.78	Parts: \$233.55	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$544.33
------------------------	------------------------	-------------------------	---------------------	----------------------------

Miscellaneous Charges:
SERVICE ACCESSORIES \$150.00

Customer PO No:
Tax Exempt No:
Advisor: Rocky Anaka

Job Total: \$20,238.43
Grand Total: \$20,238.43

*** DOCUMENT COPY ***

ALL QUOTES ISSUED ARE VALID FOR 7 DAY FROM ISSUE -- MIN \$35 ON EMERGENCY/UNIT DOWN ORDERS -- 25% RESTOCKING FOR RET

TERMS AND CONDITIONS

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any such unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control

Received by: Date: