Car Service Salisbury

1 Stanbel Road
Salisbury Plains SA 5108
ABN 30 008 264 319
Tel: 8250 0583 Fax: 8281 6568
Email: accounts@carservicesalisbury.com
Website: www.carservicesalisbury.com
Au 38172

Tax Invoice

Inv. No.	34071	Date	17/07/25	Order No.	-	Sales ID	-

Client Details

Hispec Transport

Vehicle Details

Rego: 436 ET5 **Odo:** 127176
Make/Model: GMC SIERRA 2500 HD
Year: 2018
VIN: 1GT12EY2JF261465
Next service: Premium Service
Due: 17/01/26 **Kms:** 137176

Account	12138	Home	-	Work	-	Mobile	0412 979 093

Work done

Premium Service & 65 Point Repco Authorised Service Inspection. Including: Change Engine Oil & Oil Filter & Check Air Filter, Check Battery & All Other Levels & Top Up As Required, Check Tyres & Lights Etc, Visual Check Of Hoses, Belts, Exhaust, Suspension, Shockers & Under Car Components. Check Wheel Bearings For Play. Remove Road Wheels & Inspect Brakes For Wear / Leaks, Inspect Brake Fluid.
Checked Vehicle For Power Steer Leak, Found Power Steer Hose Fallen Off, Refitted Hose With 2 New Clamps & Topped Up Fluid Level, Bled Systemof Air , Degreased Oil From Vehicle & Road Tested - Ok.

Inspection report: https://tinyurl.com/ythy66h4

Services, Parts & Labour

Mechanical

Qty	Description	Unit Price	Total (Ex)	Tax		Total (Inc)
1	Premium Service	$436.36	$436.36	$43.64	GST	$480.00
1	Air Filter	$127.27	$127.27	$12.73	GST	$140.00
10	Dhd 15w-40	$12.46	$124.55	$12.45	GST	$137.00
1	Oil Filter	$53.64	$53.64	$5.36	GST	$59.00
2	Adblue 10l	$6.37	$12.73	$1.27	GST	$14.00
1	Waste Management Fee	$18.18	$18.18	$1.82	GST	$20.00
1	Workshop Supplies	$18.18	$18.18	$1.82	GST	$20.00
	Total Premium Service		**$790.91**	**$79.09**		**$870.00**
1	Check Power Steering Leak	$290.91	$290.91	$29.09	GST	$320.00
2	Penrite Premium Fully Synthetic Transmission Fluid L V	$17.27	$34.55	$3.45	GST	$38.00
2	Degreaser	$4.54	$9.09	$0.91	GST	$10.00
2	Hose Clamp	$3.63	$7.27	$0.73	GST	$8.00
	Total Check Power Steering Leak		**$341.82**	**$34.18**		**$376.00**
			$1,132.73	**$113.27**		**$1,246.00**

Vehicle report

(future) Diff Oil Condition & Leaks: Rear Right Axle Seal Leaking.
(future) Exhaust System: Exhaust Leaks Present, Will Require Exhaust Specialist
(urgent) Tread Depth Lf (mm): Worn On Inner Edge
(urgent) Tread Depth Rf (mm): Worn On Inner Edge
(urgent) Wheel / Rim Condition: Rear Right Wheel Missing 1x Lug Nut. Requires Replacement
(future) Dash Warnings & Instruments: Tyre Pressure System Warning On Dash, Aftermarket Wheels Fitted To Vehicle

Financial Summary

Total (Ex. Tax)	$1,132.73	Terms	Cash on delivery
Tax Total	$113.27	Paid	$0.00
Total (Inc. Tax)	**$1,246.00**	**Balance**	**$1,246.00**

We Are Proud Of All Our Repairs, If You Are, Please Tell Others, If You Are Not Please Tell Us First.
We Would Like To Thank You For Your Business And Assure You Of Our Personal Attention At All Times.

Bsb - 105-012
Account - 120 441 740
Abn -