BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***3184114***
Document Date:	22/04/2024
Repair Order No.:	882899
RO Creation Date:	9/04/2024
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	676597
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	1 of 6

QC INSTALL SAFETY EQUIPMENT. Completed Quick Check.

INSTALL SAFETY EQUIPMENT. Completed Quick Check.

kwbsl KW B - Service Labour;

Check Ultra-Shift Latest Software inTECU	***$760.00***
Carryout Ultra-Shift Grease Procedure	
Reset Ultra-Shift Grease Interval	
Reset Ultra-Shift Grade Sensor Calibration	
Sample Engine Oil Sample	
Change Engine Oil	
Change Engine Oil Filter	
Change Fuel Filters	
Change SCR Air Filter & Carry out airside flush as per QSOL E5	
Clean Combo Sensor (Cummins EGR Engines Only)	
Check Exhaust System & Report	
Check Gearbox Oil Level	
Check Auxiliary Transmission Oil Level	
Check Forward Rear Axle Oil Level	
Check Rear Rear Axle Oil Level	
Check Power Steering Oil Level	
Check Air Cleaner Element	
Check Engine Oil Level after Starting	
Check Radiator Coolant Level	
Check & Record Coolant Antifreeze Concentration	
Check Battery Electrolyte Level & Tighten Terminals	
Check Front Wheel Bearings Play & Adjust	
Check Steer Hub Oil for Contamination & Top Up	
Check Bell Housing Bolts	
Check Clutch Fluid Level (DOT 4 ONLY)	
Check Free Play in Steering & All Components	
Lube All Grease Points, Replace Any Nipples Not Taking Grease	
Fill Auto Greaser	
Check Clutch Linkage Bolts	
Check Driveline for Movement & Report	
Check Tension Cab & Sleeper Mount Bolts	

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***3184114***
Document Date:	22/04/2024
Repair Order No.:	882899
RO Creation Date:	9/04/2024
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	676597
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	2 of 6

Check Tension U-Bolts
Check Tension Rear Suspension Bolts
Check Tension Steering Draglink Pinch Bolts
Check Tension Engine Mount Bolts - Front & Rear
Check Tension Radiator Mount Bolts - incl. Upper Stabilizer
Alignment. Centralize Steering Wheel
Top Up Windscreen Washer Bottle & Test Washers
Drain Air Tanks
Check Condition of All Air & Electrical Lines & eliminate Rubbing
Report Any Oil Leaks
Check Tension Radiator Hoses With Torque Wrench
Check Tension C.A.C Hoses with Torque Wrench
Lube Door Locks, Latches & Wedge Blocks with Silicon
Check Operation of All Lights, Gauges, Wipers & Horns
Check & Adjust Clutch
Check & Adjust Brakes
Check & Adjust Belts
Check Interior Appointments
Check Retract Seatbelts For Operation & Fraying.
Clean Down Vehicle
Fit service sticker
****

Brake lining condition
LHF 1st 6mm RHF 1st 6mm
LHF 2nd mm RHF 2nd mm
LHFD 6mm RHFD 6mm
LHMD mm RHMD mm
LHRD 10mm RHRD 7mm
Road test.

Part Number	Part Description	Quantity	Total Cost
1324.05	PREMIUM BLUE 8600 5L OIL	1.00	48.01
1324.20	PREMIUM BLUE 8600 20L OIL	2.00	341.32
MK13555	FILTER KIT - E5/X15	1.00	128.95
K37-1004	FILTER-FUEL/WATER PACCAR	1.00	33.57
AS2474	AIR/OIL SEPARATOR	1.00	17.14
TRPCAF0001	TRP KW CAB AIR FILTER	1.00	25.78
G	GREASE	1.00	15.00
		1.00	1.00
	Parts Totals:	***8.00***	***$609.77***

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***3184114***
Document Date:	22/04/2024
Repair Order No.:	882899
RO Creation Date:	9/04/2024
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	676597
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	3 of 6

K039 Customer reports the water in fuel warning is on

Complaint: ***$190.00***
Water in fuel fault.
Cause:
Faulty WIF sensor.
Drained fuel from fuel/water separator. Checked fuel tanks, no signs of water in fuel tanks. Replaced fuel /water separator filter (due on service) Checked wiring, all ok. Checked sensor, found to be faulty. Replaced sensor and cleared all faults.

Part Number	Part Description	Quantity	Total Cost
RK5561702	KIT-SENSOR	1.00	113.07
	Parts Totals:	***1.00***	***$113.07***

K046 Mirror markerlights not working

Complaint: ***$57.00***
Marker lights out.
Cause:
Blown bulb.
Correction:
Checked lights, found L/H mirror marker light to be inop. Removed mirror and lamp lense and replaced blown bulb. Refitted lense and mirror.

Part Number	Part Description	Quantity	Total Cost
W125	GLOBE,WEDGE BASE 12V5W	1.00	1.36
	Parts Totals:	***1.00***	***$1.36***

K039-1 Bottom radiator mount damaged. Remove and send to Kools.

Complaint: ***$1,520.01***
Bottom radiator mount damaged
Cause:
Broken radiator bottom stud.
Correction:
Removed the grill from front of the truck.
Removed intake piping from the CAC.
Removed coolant draw down pipe from radiator.
Removed the bottom coolant pipe from radiator.
Lifted radiator out with the forklift and put in radiator stand.
Removed CAC from radiator and all shrouding. Sent to Kools.

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***3184114***
Document Date:	22/04/2024
Repair Order No.:	882899
RO Creation Date:	9/04/2024
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	676597
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	4 of 6

Refit all componets to radiator.
Replace CAC and radiator bushes.
Replace hoses.
Install radiator and secure to spec.
Refit all components
Fill coolant and pressure test, all good.
Sublet Kools Radiator Services ***$2,768.75***
PO W538280
Invoice 00041132
Externally clean Kenworth K200 radiator, check bolt tension on top tank, remove bottom tank and cross brace, supply new bottom tank, cross brace, gasket, components, pressure test and paint.

Part Number	Part Description	Quantity	Total Cost
K066-177	BUSH-ANTI VIBRATION	2.00	113.18
80-100T	HOSE 1" (PER FOOT)	1.00	14.91
G000215A	MOUNT	2.00	127.46
D1030-2650A-1	HOSE-SILICONE 2-1/2"	1.00	42.03
40016	CLAMP-HOSE SIZE 21-38MM	4.00	14.92
B9228-0275B	CLAMP	2.00	28.18
K363-390	WASHER-RADIATOR MTG	2.00	25.64
ELC40-20M	PACGEN ELC40 PREMIX 20L	1.00	121.80
	Parts Totals:	***15.00***	***$488.12***

K002 Secure loosemudguard poles. ***$95.00***

Complaint:
LHR & RHR mudguard poles loose
Cause:
Loose fasteners
Correction:
Secure poles as required.

K031-2 Exhaust stackstay arm Insecure ***$57.00***

Complaint:
Exhaust stack stay arm Insecure
Cause:

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***3184114***
Document Date:	22/04/2024
Repair Order No.:	882899
RO Creation Date:	9/04/2024
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	676597
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	5 of 6

Stay nuts loose
Correction:
Tightened loose nuts on exhaust stay bracket as required.

K024 LH steer shock absorber loose

Complaint: ***$95.00***
LH steer shock absorber loose
Cause:
Loose nut.
Correction:
Freed off and tightened loose top LH steer shock absorber nut.

Part Number	Part Description	Quantity	Total Cost
C71-1006	SHOCK ABSORBER REAR SUSP'N	1.00	475.41
	Parts Totals:	***1.00***	***$475.41***

K017 Rectify SCRinline gasket leaking

Complaint: ***$190.00***
SCR inline gasket leaking
Cause:
Gasket perished
Correction:
Removed exhaust pipe at SCR and replaced gasket. Refitted exhaust pipe.

Part Number	Part Description	Quantity	Total Cost

BROWN AND HURLEY
The BIG TRUCK People

TRUCK SALES, TRAILER SALES, PARTS & SERVICE

A.B.N. 66 010 732 966

2632 Ipswich Road, Darra QLD 4076
Phone: (07) 3363 8000 Fax: (07) 3363 8080
bris.admin@brownandhurley.com.au
www.brownandhurley.com.au

SERVICE TAX INVOICE

Invoice To:

Deliver To:

Document No.:	***3184114***
Document Date:	22/04/2024
Repair Order No.:	882899
RO Creation Date:	9/04/2024
Rego No.:	XB98IO
Make/Model:	2013 KENWORTH K200 6X4 PM
Vehicle ID No.:	6F5000000DA450180
Fleet No:	
Odometer:	676597
Engine Hours:	
Delivery Date:	04/10/2013
Invoice To:	12116
Customer ABN:	21 625 785 275
P/Order No.:	XB98IO
Page:	6 of 6

2866337CUM	GASKET 5"		1.00	40.82
		Parts Totals:	***1.00***	***$40.82***

Service Reminders Advisor: Christopher Collins
0447015911 Use Premium blue oil.

Workshop Trading Hours: Mon-Fri 6:30am to 9:15pm, Sat 8am to 12pm
*** Refrigerant trading authority number: AU13435 ***

PART S	$1,728.55
LABOUR	$2,964.01
MISC. CONSUMABLES	$30.00
ENVIRONMENTAL LEVY	$30.00
SUBLET	$2,768.75
OTHER CHARGES	$0.00
TOTAL GST CHARGED	$752.13
TOTAL Incl. GST	$8,273.44

Customer's Signature

Bank Account Details for Direct Payments:
Bank: CBA Branch: Kyogle
BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd