EquipmentName	Workshop	Description	CompletionComments	DateDone	DistanceDone	Workstate	Division	Rego	Supplier	EquipmentType
1065	Wodonga - Workshop	VehService\AS A Service		01/09/2026	616097	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Tablet Won't Turn On	tablet turned on and started charging	01/09/2026	616097	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	heater + aircon not working	inspected seemed to work	01/09/2026	616097	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	clutch ajustment	All Ready Completed	22/08/2026	612729	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Oil Leak On Rear Diff	All Ready Completed	22/08/2026	612729	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Driver Camera Been Tampered With	Adjusted guardian driver facing camera due to be facing down to dash, adjusted into correct position and tightened up into place.	22/08/2026	612729	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Sensor In Seat May Have Been Unhooked	Reconnected seat belt alarm.	22/08/2026	612729	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	change reversing sound in truck	Sound can not be changed in truck.	22/08/2026	612729	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Check suspension mounting point's, [very noisy & cluncky]	All Ready Completed	22/08/2026	612729	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Indicator Stalk Loose	Previsly repaired	22/08/2026	612729	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	VehService\CS C Service		23/07/2026	600012	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Check clutch NO free play		23/07/2026	600012	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Insp\ANN INSP To Complete R/W within 12 months		23/07/2026	600012	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	DrivLine\DIFF OIL Replace Diff oils		23/07/2026	600012	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	fuel gauge not working		14/07/2026	598594	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
			-truck driven with no faults or warnings on dash.							
			-fuel and oil gauge working as intended.							
			-heater fan working correctly, had previous faults.							
			-service reminder or truck shut off light comes on ((yellow spanner symbol)) engine light didn't display once.							
			-truck scanned for faults and codes, multiple codes present, all cleared.							
1065	Wodonga - Workshop	oil pressure gauge not working	-light stalk replaced, had slight play in old stalk, new stalk has play aswell.	14/07/2026	598594	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	fuel gauge dash light not working		14/07/2026	598594	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	grease nipple broken of thrust bearing	done by sammy and aaron	14/07/2026	601211	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	check engine light coming on everyday	inspected by sammy	14/07/2026	601211	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	steering column wont adjust	inspected by sammy	14/07/2026	601211	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Adjust clutch	completed by AR AM	13/07/2026	598081	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
			NO INFO PROVIDED YET							
			CUSTOMER REPORTS TRUCK STOPPED WHILST DRIVING, NOW WON'T CRANK AT ALL, CUSTOMER BELIEVES POSSIBLE							
			ALTERNATOR FAULT							
			.							
			* Sourced parts, loaded breakdown van & travelled to truck located near Wangaratta							
			* Attempted to connect laptop but found unable to							
			* Driver mentioned speedo, coolant temp, adblue & boost not showing any readings							
			* Suspect ECM has lost power							
			* Removed battery cover & checked main power fuse - All ok							
			* Pulled dash panel out & checked engine fuse							
			* Found fuse to be blown							
			* Removed & replaced fuse							
			* Started truck							
			* Found fault no longer present							
1065	Wodonga - Workshop	Body\BREAKDOWN	* Loaded tools & travelled back to TCTC workshop	07/07/2026	597098	Completed	LHB	XW64CD	TWIN CITY TRUCK CENT	P/MOVER
			Labour- Mobile- Breakdown							
			Travelled to Nudgee							
			Found ECM Ignition fuse blowing							
			Located and repaired shorted wiring in engine harness							
1065	Wodonga - Workshop	Elect\ELECT P&W	Checked operation	04/07/2026	597098	Completed	LHB	XW64CD	WARREGO TRANSPORT	P/MOVER
			Vehicle came in after hours with trailer lights not working							
			When vehicle came in checked out indicators and brake lights working tail lights and side markers							
			not working and found no power coming from truck. Check plugs to trailers and tidyed up wiring in							
		Elect\ELECT P&W BREAKDOWN	plugs. Found blown fuses for L/H and R/H trailer tail light feed. Replace both fuses and supply							
1065	Wodonga - Workshop	WW134561	driver with spares. Driver took vehicle for test drive and still working when returned. Checked ok.	24/06/2026	591619	Completed	LHB	XW64CD	MARULAN TRUCK & BU	P/MOVER
1065	Wodonga - Workshop	Elect\ELECT P&W	EUROCOIL 7CORE	19/06/2026	586830	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	C Service & Repairs (TCTC P/O: WW0871		19/06/2026	586830	Completed	LHB	XW64CD	TWIN CITY TRUCK CENT	P/MOVER
		A Service								
		Serviced @ 578,513 Klms								
1065	Wodonga - Workshop			26/05/2026	582484	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Need's Steer Tyre's 1-2		17/05/2026	573986	Completed	LHB	XW64CD	BORDER BANDAG PTY L	P/MOVER
		Check For Boost Leak/s & Repair								
1065	Wodonga - Workshop	WW133689		07/05/2026	586830	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	A Service	completed by SMc	29/04/2026	567393	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	R/H Steer Tyre Valve Leak	Steer tyres replaced and leaking valve stem repaired.	29/04/2026	567393	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	New Wipers Please	Removed old wiper blades, fitted new wiper blades.	29/04/2026	567393	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Coolant Leak Causing Derating & Eng Cut Out	Pressure Tested Cooling System, cold test found no leaks, drove truck and got warm, hot test carried out no leaks, sent truck back to work.	29/04/2026	567393	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
			CALL OUT							
			FOUND NO START							
1065	Wodonga - Workshop	Engine\BREAKDOWN	STARTER LOCK OUT RELAY FAILED	14/04/2026	562407	Completed	LHB	XW64CD	WARREGO TRANSPORT	P/MOVER
1065	Wodonga - Workshop	Replace Turn Table Dog Bones		27/03/2026	551330	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	A Service		26/03/2026	551330	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Body\AIR LEAK		06/03/2026	540213	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Bad Air Leak loosing air		06/03/2026	540212	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	No range on the UHF radio.		06/03/2026	540212	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Bad air leak between Diff and gearbox.		06/03/2026	540212	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Bunk cooler not working.		06/03/2026	540212	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Main Bunk curtain is missing.		06/03/2026	540212	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Loading Guage Light is NOT working, hard to see at night.		06/03/2026	540212	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
			completed at 538,069							
1065	Wodonga - Workshop	VehService\BS B Service	SMc CB	06/03/2026	540212	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	All drive hub seals blown.	inspected ok	05/03/2026	540212	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
			inspected ok							
1065	Wodonga - Workshop	Top and feet bushes n/s	SMc CB	05/03/2026	540212	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
			inspected ok							
1065	Wodonga - Workshop	Power dividor movment and seal blown	SMc CB	05/03/2026	540212	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
		Power divider has excessive movement	inspected ok							
1065	Wodonga - Workshop	Rear engine mounts cracked	SMc CB	05/03/2026	540212	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Bunk Cooler Not Working.		05/03/2026	540212	Unlocked	LHB	XW64CD	Wodonga Workshop	P/MOVER
			inspected ok							
1065	Wodonga - Workshop	Bad oil leak front diff.	SMC CB	05/03/2026	540212	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
		Power dividor movment and seal blown	Inspected ok							
1065	Wodonga - Workshop	Slip joint slight movement	SMC CB	05/03/2026	540212	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	move asset to tctc to get repairs		19/02/2026	531070	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER

			Travel to Manildra yard Started vehicle and confirmed air leak present Inspected vehicle and found air tank drain bung cable to be stuck between 2 hoses holding the drain open Rerouted cable								
1065	Wodonga - Workshop	Susp\AIR LEAK BREAKDOWN	Returned to workshop	10/02/2026	525852	Completed	LHB	XW64CD	NOWRA TRUCK & TRAC	P/MOVER	
1065	Wodonga - Workshop	Body\PANELS remove party hat for bulk NEEDS NEW DRIVE CENTRE CAP FITTED (AXLE BOLTS NEED TURNING)		09/02/2026	524150	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop			06/02/2026	524150	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	engine light on		06/02/2026	524150	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	NEEDS NEW STEERING WHEEL COVER		06/02/2026	524150	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	UHF Radio & Cigarette Lighter Not Working		06/02/2026	524150	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Insp\ANN INSP		06/02/2026	524150	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
			Travel to breakdown at the BP on Eastlink 11/12/25 as requested, Inspected truck had derated, Scanned and checked codes, no active codes only stored codes, Cleared all codes and truck was right to go,								
1065	Wodonga - Workshop	Elect\RERATE TRUCK DERATED	Travel back to workshop with in spec	02/02/2026	535126	Completed	LHB	XW64CD	ELITE DIESEL REPAIRS	P/MOVER	
1065	Wodonga - Workshop	Feet bushes	S.Mc	20/01/2026	522523	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Rear diff seal	tightened diff bolts monitor repalced rhr seal and bearings	20/01/2026	522523	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	All drive hub seals blown	S.Mc	20/01/2026	522523	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	NEEDS NEW HYDRAULIC FLUID (URGENT)	DW	20/01/2026	522523	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	NEEDS NEW WIPER DRIVER SIDE	S.Mc checked ok	20/01/2026	522523	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	COOLANT TEMP GAUGE NOT WORKING.	S.Mc	20/01/2026	522523	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	DrivLine\DIFF OIL	S.Mc replaced RHR hub seal Bearings,shoes adjusted all drive wheel bearings replaced shoes on lhr	20/01/2026	522523	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Rear hub seal	S.Mc	20/01/2026	522523	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Front right t rod bush n/s	S.Mc completed	20/01/2026	522523	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Prevent\TRANS OIL	S.Mc	20/01/2026	522523	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	VehService\AS A Service		20/01/2026	522523	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
			Traveled onsite to Greenfreight Wodonga. Checked tracking unit and found no GPS signal. Plug in new gps antenna and unit started tracking. Removed old antenna and ran new gps antenna. Secured cables and tested.								
1065	Wodonga - Workshop	DrCabElect\GPS	Returned to Arkon ALTERNATOR FAILURE DIAGNOSE AND FIND FAULT - R&R ALTERNATOR-	19/01/2026	525852	Completed	LHB	XW64CD	ARKON AUTO ELECTRIC	P/MOVER	
1065	Wodonga - Workshop	Engine\ALT A Service	SHOULD BE A WARRANTY CLAIM HERE AS ALTERNATOR WAS ONLY REPLACED JUNE 2025 - WORKSHOP HAVE BEEN NOTIFIED	09/01/2026	530853	Completed	LHB	XW64CD	CALLAWAY DIESEL	P/MOVER	
1065	Wodonga - Workshop	Serviced @ 811,094 Klms		13/12/2025	508446	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Replace Wiper Blades		13/12/2025	508446	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Tyres\TP11+12		07/12/2025	494235	Completed	LHB	XW64CD	BORDER BANDAG PTY L	P/MOVER	
1065	Wodonga - Workshop	Tyres\TP9+10		07/12/2025	494235	Completed	LHB	XW64CD	BORDER BANDAG PTY L	P/MOVER	
1065	Wodonga - Workshop	Tyres\TP5+6		07/12/2025	494235	Completed	LHB	XW64CD	BORDER BANDAG PTY L	P/MOVER	
1065	Wodonga - Workshop	Tyres\TP7+8		07/12/2025	494235	Completed	LHB	XW64CD	BORDER BANDAG PTY L	P/MOVER	
1065	Wodonga - Workshop	Check Truck Road Speed Settings Driver Saying Truck Only Doing 97 Klm/hr	Plugged computer into truck, check tyre size & road speed setting	22/11/2025	562407	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	A Service Serviced @ 497,150 Klms A Service	Mitchell Newley 1hr	22/11/2025	494235	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Serviced @ 488,092 Klms		01/11/2025	488373	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	A SERVICE		01/11/2025	488373	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	SPEEDO		01/11/2025	488373	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Front torque rod bushs need to be replaced		01/11/2025	488373	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	WIPPER BLADES		01/11/2025	488373	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Tyres\TP1+2 B Service (Daimler Albury P/O: Serviced @ 476,000 Klms		21/10/2025	485205	Completed	LHB	XW64CD	BORDER BANDAG PTY L	P/MOVER	
1065	Wodonga - Workshop	WW097232 Tyres\PRES CHECK 1-12		11/10/2025	476580	Completed	LHB	XW64CD	DAIMLER TRUCKS ALBU	P/MOVER	
1065	Wodonga - Workshop		FULL PRESSURE CHECK ON PM	09/10/2025	476580	Completed	LHB	XW64CD	BORDER BANDAG PTY L	P/MOVER	
1065	Wodonga - Workshop	COOLANT LEAK	DIAGNOSED AND REPLACED SIGHT GLASS WITH PLUG. REPLACED RADIATOR CAP.	16/09/2025	466634	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Check Correct Tyre Size Is In ECM.	Connected computer checked tyre size, the tyre size in ECM was 515 Revs Per Klm, checked tyre Rev Per Klm 305/70R22.5 should be 513 Revs Per Klm, chang	13/09/2025	462279	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	VehService\AS A Service		13/09/2025	462247	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	TIGHTEN GUARDIAN CAMERA		04/09/2025	456688	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Drop off to TCTC		04/08/2025	438338	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	VehService\AS A Service		19/07/2025	429218	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Check and adjust clutch		19/07/2025	429218	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Replace broken trailer light plug	Replaced broken plug and tested to confirm repair	05/07/2025	422350	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	VehService\CS		30/06/2025	414129	Completed	LHB	XW64CD	PACCAR PARTS FLEET SE	P/MOVER	
			* Checked electrical routing * Check wiring harness, looms, connections, lighting & components * Confirmed alternator output below specification requirements * Removed components to access alternator * Removed/replaced alternator * Aligned & tensioned all components								
1065	Wodonga - Workshop	Replace Alternator. (TCTC P/O: WW095199)	* Check & confirm charging to specification * Check belts & pulleys * Belt failure evident - cracked * Removed/replaced belts * Aligned & tensioned to specification	21/06/2025	414218	Completed	LHB	XW64CD	TWIN CITY TRUCK CENT	P/MOVER	
1065	Wodonga - Workshop	Replace Belts. (TCTC P/O: WW095199)		21/06/2025	414218	Completed	LHB	XW64CD	TWIN CITY TRUCK CENT	P/MOVER	
			* Check electrical routing * Check wiring looms, switches, contacts & components * Check & load test batteries * Batteries below specification * Removed/replaced batteries * Adjusted, aligned & installed terminals * Re check electrical routings								
1065	Wodonga - Workshop	Replace Batteries. (TCTC P/O: WW095199)	* Test, confirm & quality check repair	21/06/2025	414218	Completed	LHB	XW64CD	TWIN CITY TRUCK CENT	P/MOVER	

		CANBERRA TRUCK REPAIRS-BREAKDOWN. ROAD SIDE SERVICE AT GOULBURN TRUCK PARK GOVENORS HILL, TO GREENFREIGHTS K220, XW64CD. CUSTOMER COMPLAINED OF BLOWN COOLANT HOSE. ON ARRIVAL, FOUND COOLANT LEVEL DOWN 2 LITRES AND NO BLOWN HOSES.CHECKED OVER FOLLOWED TRUCK A FEW KILOMETRES, ALL GOOD.									
1065	Wodonga - Workshop	RETURN TO WORKSHOP		06/06/2025	562407	Completed	LHB	XW64CD	PACCAR PARTS FLEET SE	P/MOVER
1065	Wodonga - Workshop	VehService\AS A Service		17/05/2025	393999	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
		Change ECM Settings From 104 Klms To 100 Klms.								
1065	Wodonga - Workshop	(Cummins Wodonga P/O: WW093936)		03/05/2025	384949	Completed	LHB	XW64CD	CUMMINS SOUTH PACII	P/MOVER
1065	Wodonga - Workshop	rear drive axle temps constantly activating warning notifications in the dash and are s		01/05/2025	383583	Completed	LHB	XW64CD	PACCAR PARTS FLEET SE	P/MOVER
		TWIN CITY TRUCK CENTRE-	.							
		WARNING LIGHT.	* Inspect to diagnose							
		CUSTOMER SAID SPANNER ORANGE WARNING LIGHT KEEPS COMING UP ON	* Removed/replaced water & fuel separator connection							
1065	Wodonga - Workshop	DASH.. DIAGNOSE AND REPORT	* Cleared codes, road tested & confirmed repair	27/04/2025	383583	Completed	LHB	XW64CD	PACCAR PARTS FLEET SE	P/MOVER
1065	Wodonga - Workshop	Brakes\BOOSTER		23/04/2025	381760	Completed	LHB	XW64CD	MECHANIKA MOTORS P	P/MOVER
1065	Wodonga - Workshop	Tyres\TP1+2		23/04/2025	380656	Completed	LHB	XW64CD	BEAUREPAIRES	P/MOVER
1065	Wodonga - Workshop	Tyres\TP01		15/04/2025	376335	Completed	LHB	XW64CD	BEAUREPAIRES	P/MOVER
1065	Wodonga - Workshop	Truck Shut Down Lost All Electric's. (Gilbert & Roach Huntingwood P/O: WW092405		04/04/2025	365283	Completed	LHB	XW64CD	PACCAR PARTS FLEET SE	P/MOVER
		VehService\AS								
1065	Wodonga - Workshop	TCTC PO #WW093130	FITTED SEAT COVER CORRECTLY.	28/03/2025	367845	Completed	LHB	XW64CD	PACCAR PARTS FLEET SE	P/MOVER
1065	Wodonga - Workshop	TCTC- REPLACED LH STEER HUB SEAL. REPLACED DRUM AND LININGS.		28/03/2025	367845	Completed	LHB	XW64CD	PACCAR PARTS FLEET SE	P/MOVER
		TWIN CITY TRUCK CENTRE-								
		ENSURE ENGINE BRAKE COMING ON AT 103KM/HR ON CRUISE & PEDAL .								
		* Connected laptop & checked all parameters								
1065	Wodonga - Workshop	* Test operations - All ok, operating as required		12/02/2025	586830	Completed	LHB	XW64CD	PACCAR PARTS FLEET SE	P/MOVER
		VehService\BS								
1065	Wodonga - Workshop			25/01/2025	352077	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
		WINDSCREEN P/SIDE NEEDS REPLACEMENT.								
1065	Wodonga - Workshop	Completed under work order #WO187802		24/01/2025	253250	Completed	LHB	XW64CD	AUTOTEK AUSTRALIA	P/MOVER
1065	Wodonga - Workshop	VehService\AS	KR 2 HOURS LABOUR.	10/01/2025	343346	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
1065	Wodonga - Workshop	Noise In Drive Line. (TCTC P/O: WW090913)		12/12/2024	334587	Completed	LHB	XW64CD	TWIN CITY TRUCK CENT	P/MOVER
		LAB T - BREAKDOWN - AH								
		BREAKDOWN LOCATION: MARULAN SOUTHBOUND NSW 2579								
		BREAKDOWN DETAILS: VEHICLE IS NON START								
		Travelled to breakdown location.								
		Upon arrival, the vehicle started immediately without issue.								
		Conducted a thorough inspection of the batteries, alternator, and starter								
		motor wiring. All components were found to be in good condition.								
1065	Wodonga - Workshop	Completed the necessary checks, packed up, and returned to base.		05/12/2024	332488	Completed	LHB	XW64CD	MECHANIKA MOTORS P	P/MOVER
1065	Wodonga - Workshop	Replace Damaged Suzie Leads. (G&S Diesel's P/O: WW090387)		26/11/2024	494003	Completed	LHB	XW64CD	G & S DIESEL SERVICE	P/MOVER
1065	Wodonga - Workshop	Check Tyre Pressures On Positions 1,2,3,4,5,6,7,8,9,10. (Wodonga Tyre & Auto P/O: W		19/11/2024	322706	Completed	LHB	XW64CD	BEAUREPAIRES	P/MOVER
1065	Wodonga - Workshop	Truck Has No Trailer Lights. (G&S Diesel's P/O:WW090166)		16/11/2024	494003	Completed	LHB	XW64CD	G & S DIESEL SERVICE	P/MOVER
1065	Wodonga - Workshop	Tyres\TP5+6		29/10/2024	312819	Completed	LHB	XW64CD	BEAUREPAIRES	P/MOVER
1065	Wodonga - Workshop	Tyres\TP7+8		29/10/2024	312819	Completed	LHB	XW64CD	BEAUREPAIRES	P/MOVER
1065	Wodonga - Workshop	Tyres\TP9+10		29/10/2024	312819	Completed	LHB	XW64CD	BEAUREPAIRES	P/MOVER
1065	Wodonga - Workshop	Tyres\TP3+4		29/10/2024	312819	Completed	LHB	XW64CD	BEAUREPAIRES	P/MOVER
1065	Wodonga - Workshop	Tint Windows. (All About Window Tinting P/O: WW089363)		12/10/2024	304511	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
		Elect\DRV LIGHT								
		*Wire driving light switch to relays								
		Remove dash an interior panels. Run 3mm twin from center of dash out to								
		driving light relays mounted in the battery box. Install driving light switch.								
		Locate high beam signal and wire to switch. Test driving lights and secure								
1065	Wodonga - Workshop	with cable ties.		11/09/2024	286427	Completed	LHB	XW64CD	ARKON AUTO ELECTRIC/	P/MOVER
		Elect\TRL LIGHTS								
		BREAKDOWN								
		BREAKDOWN REPAIR								
		.								
		The following breakdown repair for Greenfreight Distribution Pty Ltd, to a Kenworth								
		K220, vin#6F5000000NA480302,								
		registration#XW64CD & fleet number#1065 included:								
		.								
		* Customer contacted dealership breakdown technician with information regarding								
		breakdown								
		* Customer advised that trailer lights not working								
		* Technician travelled to customer depot, Wodonga								
		* Inspected trailer lights & confirmed no failure - repair completed on trailer								
		* Jacked cab over for access								
		* Checked fuses to MUX module - located 3 blown fuses to trailer								
		* Suspected when driver connected wrong trailer plug that this would have caused								
		fuse issue								
		* Removed/replaced fuses								
		* Installed trailer plug, tested & confirmed all lights working								
1065	Wodonga - Workshop	* Return truck to service		10/09/2024	285061	Completed	LHB	XW64CD	PACCAR PARTS FLEET SE	P/MOVER
		VehService\AS (TCTC P/O: WW088595)								
1065	Wodonga - Workshop	Serviced @ 284,957 Klms		07/09/2024	284957	Completed	LHB	XW64CD	TWIN CITY TRUCK CENT	P/MOVER
		B Service (TCTC P/O: WW088595)								
1065	Wodonga - Workshop	Serviced @ 284957 Klms		07/09/2024	284957	Completed	LHB	XW64CD	TWIN CITY TRUCK CENT	P/MOVER
			*Fit new driving lights							
			Source driving light switch and patch lead for can switches.							
			Locate driving light wiring behind lh head light. Extend wiring to behind the grill.							
			Remove grill. Cut length of right angle for light to mount on. Fit behind the grill							
			and mount lights. Terminate wiring into the spot lights and cable tie securely.							
			Remove cover to gain access to junction box where driving light wiring is.							
			Wire in 2 relays for spot lights connected to the high beam signal coming from the ecu.							
			Send truck to get spot lights turn on in the ecu. Remove badge and fit led backing. Wire into the drl circuit.							
1065	Wodonga - Workshop	Fit Driving Lights Behind Grill (Arkon Auto Electrical P/O: WW088328)		29/08/2024	274316	Completed	LHB	XW64CD	ARKON AUTO ELECTRIC/	P/MOVER
1065	Wodonga - Workshop	SERVICE DUE.		19/07/2024	254025	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
			RUBY 2 HOURS LABOUR							
1065	Wodonga - Workshop	A Service	ADJUSTED CLUTCH	19/07/2024	254025	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER
		Replace Drivers Side Windscreen (Albury Auto Screen P/O: WW087338)								
1065	Wodonga - Workshop			13/07/2024	253250	Completed	LHB	XW64CD	AUTOTEK AUSTRALIA	P/MOVER
		Torn Suzie Hoses (G&S Diesel's P/O: WW087258)								
1065	Wodonga - Workshop			10/07/2024	238672	Completed	LHB	XW64CD	G & S DIESEL SERVICE	P/MOVER

1065	Wodonga - Workshop	Insp\ANN INSP		19/06/2024	242640	Completed	LHB	XW64CD	TWIN CITY TRUCK CENT	P/MOVER	
1065	Wodonga - Workshop	Prevent\TRANS OIL		19/06/2024	242640	Completed	LHB	XW64CD	TWIN CITY TRUCK CENT	P/MOVER	
1065	Wodonga - Workshop	DrivLine\DIFF OIL C Service		19/06/2024	242640	Completed	LHB	XW64CD	TWIN CITY TRUCK CENT	P/MOVER	
1065	Wodonga - Workshop	Serviced @ 242,640 Klms		19/06/2024	242640	Completed	LHB	XW64CD	TWIN CITY TRUCK CENT	P/MOVER	
1065	Wodonga - Workshop	Prevent\STEER W/B		19/06/2024	242640	Completed	LHB	XW64CD	TWIN CITY TRUCK CENT	P/MOVER	
1065	Wodonga - Workshop	Tyres\TP1+2		09/05/2024	209257	Completed	LHB	XW64CD	BEAUREPAIRES	P/MOVER	
1065	Wodonga - Workshop	Record Check Results As Attached To This Job		16/04/2024	1	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	UHF external speaker doesn't work		16/04/2024	1	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	After treat light on	FLUSHED DOSER PUMP. FLOW TESTED. FAILED. TCTC REPLACED DOSER PUMP UNDER WARRANTY.	16/04/2024	1	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	C Service As Per Attached Checklist		16/04/2024	1	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Replaced Doser Nozzle	BLED SYSTEM. CLEARED CODES.	10/04/2024	203586	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	truck derated at Euroa	Graham Thompson motors attended	09/04/2024	206742	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	BIG DIFF LEAK FROM FRONT DIFF. OIL IS ALL OVER EVERYTHING.	checked for power @ DC to DC charger, no power. Tilted cabin checked fuse @ alternator - found blown, looked for then rang around for fuse picked fuses up and replaced fuse, started and checked for power on both sides of fuse. Lowered cabin, checked for power @ DC to DC charger all good. Ran truck to charge battery .	23/03/2024		Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	bunk cooler N/W	Tidied up suzi leads so they were not getting dragged over deck plate and caught on tanks.	16/03/2024	190794	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Record Check Results As Attached To This Job		10/02/2024	178203	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	BIG DIFF LEAK FROM FRONT DIFF. OIL IS ALL OVER EVERYTHING.		10/02/2024	178203	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	A Service As Per Attached Checklist		10/02/2024	178203	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	A Service As Per Attached Checklist		10/02/2024	178203	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	No LH Indicators To Trailers	REPLACED TRAILER PLUG. REPAIRED WIRING. REPLACED FUSE IN ECM COMPARTMENT.	12/01/2024	160600	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Record Check Results As Attached To This Job		06/12/2023	140577	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	B Service As Per Attached Checklist		06/12/2023	140577	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	10		27/11/2023		Completed	LHB	XW64CD	Albury Workshop	P/MOVER	
1065	Wodonga - Workshop	RADIATOR CORE LEAKING (WARRENTY) CARRY OUT ENGINE SERVICE (CUMMINS)		07/10/2023	92138	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	WOD WORKSHOP TO COMPLETE REMAINING		07/10/2023	92138	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Record Check Results As Attached To This Job		29/09/2023	92208	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	FIT FIRST AID KIT. ORDERED.		29/09/2023	92208	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	A Service As Per Attached Checklist		29/09/2023	92208	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	*PM 1065 *Tablet not charging MT data tablet not charging. Found usb cable behind console had separated. Re plugged in and tested charging. Had to perform unit reset as it was not working correctly via the app.									
1065	Wodonga - Workshop	All working and tested & charging.		03/09/2023		Completed	LHB	XW64CD	Albury Workshop	P/MOVER	
1065	Wodonga - Workshop	Record Check Results As Attached To This Job		11/07/2023	1	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	A Service As Per Attached Checklist		11/07/2023	1	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Record Check Results As Attached To This Job C Service As Per Attached Checklist ***COMPLIMENTARY NO CUSTOMER LABOUR CHARGE KENWORTH TRUCK 1st SERVICE POLICY ***	* Removed/replaced engine filter & oil, specification used in parts section below. * Check all engine operation & components * Removed/replaced transmission oil filter * Check all hydraulic lines fitting & level lubricant levels to specification * Removed/replaced power steering filter & gasket * Removed/replaced differential oil, specification used in parts section below. * Removed/replaced fuel filter * Check cooling system & pressure test * Check all belts, idler pulleys, fan, shrouds & adjust to specification * Check all electrical routing, wiring looms, switches, sensors & components * Check all wheel equipment & steering components * Check all braking & adjust to specification * Check clutching & adjust to specification * Check all suspension components * Check all internal cabin operation, components & adjust to specification * Check all external cabin components & adjust to specification * Check windscreen washers, wipers, refill & test operation * Lubricate, adjust relevant components as required * Re torque all fitting & fixtures * Wash vehicle complete	07/05/2023	17381	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	***CUSTOMER RESPONSIBLE FOR ALL PARTS REQUIRED FOR 1st SERVICE***	* Road test, confirm & quality check	07/05/2023	17381	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	DROP OFF TCTC. Coolant from front left hand side of engine. TCTC called out to Wodonga to investigate.		23/04/2023	7437	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Truck is still currently under Warranty. Yellow Button Leaking Air. TCTC to Investigate Saturday 22/04/2023		19/04/2023	238672	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Truck is under Warranty		19/04/2023	238672	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Drop 1065 off to TCTC and picking Shaun up.		16/04/2023		Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	Truck pre delivery	COULDN'T CONNECT FOR DOWNLOAD. COULDN'T WEIGH AS WEIGHBRIDGE NOT WORKING. IAP NOT WORKING. TOOK BACK TO TCTC AS INTAKE SNORKEL	07/04/2023	1700	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	
1065	Wodonga - Workshop	FIT FIRST AID KIT. ORDERED.		07/04/2023	1700	Completed	LHB	XW64CD	Wodonga Workshop	P/MOVER	