EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
MVU026	Wodonga - Workshop	Body\BREAKDOWN	Body\BREAKDOWN		TOW - MCKOY STREET WODONGA - WODONGA DEPOT	01/07/2026	481213	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	GREALY MOTORS PTY LTD	UTE
					ENGINE U/S. REPLACE ENGINE WITH DONK FROM WRECKED MYRTLEFORD FALCON. REMOVE USABLE SPARES FROM DONOR VEHICLE.											
MVU026	Wodonga - Workshop	Engine\ENG REBLD	DIAGNOSE AND REPAIR ENGINE.		T.PEACHEY 2% HOURS	19/01/2026	475590	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	VehService\8S	VehService\8S	VehService\8S		19/01/2026	475606	Service	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP	Insp\ANN INSP		19/01/2026	475606	PreventativeMaintenance	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Susp\SUSPENSION	Replace Right Hand & Left Hand Upper & Lower Control Arms			31/01/2025	473622	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
			GREALY MOTORS & TOWING													
MVU026	Wodonga - Workshop	Susp\BREAKDOWN	Tow Vehicle From Cause-Way to Greenfreight Yard. (Grealy Towing P/O: WW091829			31/01/2025	473622	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Elect\ELECT P&W	GPS 4G upgrade			05/06/2024	469852	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	DrCabRep\WINDSCREEN	WINDSCREEN SCRATCHED FROM WIPER ARM.			26/03/2024		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Body\DAMAGE	BONNET RELEASE CABLE NOT SECURE			26/03/2024		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
					REMOVE FRONT GRILLE, COVERS, THERMO FANS, PULL BACK RADIATOR AND REMOVE OLD CONDENSOR AND REPLACE											
MVU026	Wodonga - Workshop	Engine\COOL LEAKS	THERMOSTAT HOUSING BOTTOM PIPE GASKET LEAKING		WITH NEW ONE, REMOVE AND REPLACE ORIFICE TUBE, FIT NEW ORINGS .VACUUM DOWN SYSTEM AND RECHARGE											
MVU026	Wodonga - Workshop	Engine\BREAKDOWN	BREAKDOWN REPAIRS		SYSTEM,TEST OPERATION OK.	26/03/2024		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Albury Workshop	UTE
MVU026	Wodonga - Workshop	Cooling\COOL LEAKS	over heated			08/02/2024	470241	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Albury Workshop	UTE
MVU026	Wodonga - Workshop	Engine\ELECT P&W	NOT STARTING. COIL PACKS AND BATTERY ORDERED.		found tensioner & belt to have failed & pin hole in header tank	31/01/2024	470241	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Albury - Workshop	DrCabRep\DOOR LOCK	LH DOOR MISSING INTERNAL GRAB HANDLE WITH SCREW STICKING OUT.			08/12/2023		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	BORDER DYNO SERVICE	UTE
MVU026	Albury - Workshop	DrCabElect\ELECT P&W	BOTH LH &RH WINDOWS WON'T GO DOWN- BOTH SWITCHES BROKEN.			28/10/2023	470241	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Albury Workshop	UTE
MVU026	Wodonga - Workshop	Engine\ELECT P&W	REPLACED COIL PACKS.			28/10/2023	470241	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Albury Workshop	UTE
MVU026	Wodonga - Workshop	DrCabRep\WINDSCREEN	WINDSCREEN SCRATCHED FROM WIPER ARM.			17/03/2023	463848	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Body\DAMAGE	BONNET RELEASE CABLE NOT SECURE			15/03/2023		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Eneine\COOL LEAKS	THERMOSTAT HOUSING BOTTOM PIPE GASKET LEAKING			15/03/2023		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
			Check & Test Battery Replace If Needed (Marshall Batteries)													
MVU026	Wodonga - Workshop	Elect\BATTERY	Purchase Order Number: WW077221		REPLACED.	15/03/2023	463848	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
			Check & Test Coil Packs (Bursons)													
MVU026	Wodonga - Workshop	Engine\ENG TUNE	Purchase Order Number: WW077230			15/03/2023	463848	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Engine\ELECT P&W	NOT STARTING.		DIAGNOSED FAILED COIL PACKS AND BATTERY.	15/03/2023	463848	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
			Oil Pan Damaged issue with gear selection after collecting a rock.													
			Sent to Shanes Transmissions for diagnosis and repairs.													
MVU026	Wodonga - Workshop	DrivLine\DAMAGE	PO# WW075387			28/11/2022	470241	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
			Uni Joints for replacement tailshaft													
			Supplied by Repco													
MVU026	Wodonga - Workshop	DrivLine\TAIL SHAFT	PO# WW075398			28/11/2022	470241	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	VehService	Log Book Service 457600km			18/11/2022	457600	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Albury Workshop	UTE
			CHECK BOTHS DOORS LOCKING & BOTHS													
			WINDOWS N/W													
			CHECK DOOR LOCKING- REMOVE LHS DOOR TRIM- DIAGNOSE FAULTY ACTUATOR. REMOVE													
			SUPPLY AND FIT NEW ONE REASSEMBLE DOOR TRIM													
			RECHECK AND LOCATE FAULTY REMOTE- SUPPLY AND RECODE NEW REMOTE													
			CHECK ELEC WINDOWS- DIANGOSE FAULTY MASTER SWITCH FAULTY AND LHS SWITCH FAULTY													
			REMOVE AND REPLACE													
			REPLACE MASTER SW PLUG AS REQUIRED													
MVU026	Wodonga - Workshop	DrCabRep\DOOR LOCK	CHECK ALL OK			29/10/2022		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Albury Workshop	UTE
MVU026	Wodonga - Workshop	Brakes	Replace front brake pads			07/08/2022		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Elect\WORK LIGHT	REPLACED WORKLIGHTS. REPAIRED WIRING. REPAIRED WIPERS AND WASHERS.			08/06/2022	450122	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Steering\WHEEL BRGS	Replace LH wheel bearing and thermo fans, replaced diff oil			12/04/2022		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	DrivLine\DIFF OIL	Diff Oil Chanee			12/04/2022		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
			Replace drivers seat belt													
			Supplied by Repco Wodonga													
MVU026	Wodonga - Workshop	DrCabRep\SEAT	PO# WW069313		Replaced drivers side seatbelt.	23/12/2021	445811	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
					baxters Poww069144.											
MVU026	Wodonga - Workshop	Elect\ELECT P&W	breakdown light not working.		REPLACED LIGHT. WIRE SWITCH.	14/12/2021		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
			Service as per attached Checklist													
			Parts supplied by Repco Wodonga													
MVU026	Wodonga - Workshop	VehService\AS	PO# WW068003			26/10/2021	445111	Service	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Insp\RWC COMP	CHECK OVER UTE AND WRITE LIST OF REPAIRS REQUIRED			26/10/2021	445111	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Body\HOUSEKEEP	REPLACED BONNET STRUTS			26/10/2021	445111	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Body\HOUSEKEEP	REPLACED TOOLBOX STRUTS AND CLEANED OUT TOOLBOX. CLEANED OUT BACK OF UTE			26/10/2021	445111	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	DrCabRep\WINDSCREEN	WINDSCREEN SCRATCHED FROM WIPER ARM.			26/10/2021	445111	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	DrCabRep\DOOR LOCK	LH DOOR MISSING INTERNAL GRAB HANDLE WITH SCREW STICKING OUT.			26/10/2021	445111	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	DrCabElect\ELECT P&W	BOTH LH &RH WINDOWS WON'T GO DOWN- BOTH SWITCHES BROKEN.			26/10/2021	445111	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Body\DAMAGE	BONNET RELEASE CABLE NOT SECURE			26/10/2021	445111	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Engine\COOL LEAKS	THERMOSTAT HOUSING BOTTOM PIPE GASKET LEAKING			26/10/2021	445111	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
			Jump start and bring into workshop.													
			Test charge rate 14.4 Volts all OK.													
			Run vehicle to charge battery.													
MVU026	Wodonga - Workshop	Engine\BATTERY	Turn off, test battery 12.7V, load tested battery all OK.			09/09/2021	355247	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
					Found batteries flat due to failed alternator.											
					Removed and replaced alternator.											
					Work lights inoperative, broken wiring - Repaired.											
					Jump pack not working, both batteries dead flat.											
					Removed and replaced.											
MVU026	Wodonga - Workshop	Elect\ALT	replace alternator		Repaired jumper leads anderson plug and put battery on charge.	01/09/2021	444685	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	DrCabRep\SEAT	PICK UP FROM UNIVERESAL UPOLSTERY			08/07/2021		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Albury Workshop	UTE
MVU026	Wodonga - Workshop	Tyres\ALIGNMENT	Passenger Thrust Alignment			23/06/2021	442226	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Tyres\CLEANSKIN	Supply and fit 4 tyres			23/06/2021	442210	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Eneine\BATTERY	Suzuky Battery			27/03/2021		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Engine\CONSUMABLE	Supply Fuse			27/03/2021		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Elect\BATTERY	check current draw. Locate battery to be fault. Charge and test			27/03/2021	438267	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Elect\BATTERY	pick up parts. Fit battery and fuse for dual battery			27/03/2021	438267	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Elect\ALT2 DR	test and diagnose faulty alternator. Travel to Baxters and return for parts. Remove and replace alternator as required			18/03/2021	437915	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Elect\ALT	Reolace Alternator			18/03/2021		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Elect\ALT2 DR	check alternator and clean contracts			16/03/2021	437855	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Cooling\COOL LEAKS	Replace coolant hoses that split		Blacklocks PO WW062572	10/03/2021	437843	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Body\HOUSEKEEP	check over and make a repair list - includes replacing power steering oil and wash around pump			02/03/2021	437349	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Steering\PUMP	replace leaking power steer pump			02/03/2021		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Elect\ELECT P&W	reoair iumoer leads in on call ute			01/01/2021		Reoair	Comoleted	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Workshop\CLEAN	clean and inspect ready for on call			30/12/2020		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Workshop\MOVE ASSET	picked up call out ute from Deano's signs			17/12/2020		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Workshop\MOVE ASSET	drop off at Deano signs for shockers			17/12/2020		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	DrCabElect\GPS	fit tracking unit			15/12/2020	435255	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	DrivLine\GEARBOX	service auto box			11/12/2020		Reoair	Comoleted	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	DrivLine\DRV LN SER	assist refill transmission. Test drive and inspect driveline, has shudder between 85-105 kph			11/12/2020		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	DrCabRep\SEAT	driver seat bent (losing back issues)			08/12/2020		Fault	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Susp\HOUSEKEEP	front suspension knocks and wonders			08/12/2020		Fault	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Susp\HOUSEKEEP	rear spring sagged (too much weight in tray)			08/12/2020		Fault	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Elect\HEAD LIGHT	headlights unsafe - needs new ones			08/12/2020		Fault	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Steering\PWR STEER	steering wheel falling apart			08/12/2020		Fault	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	DrCabRep\WINDSCREEN	windscreen damage from wipers			08/12/2020		Fault	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
			auto gearbox issues selecting gear													
MVU026	Wodonga - Workshop	DrivLine\GEARBOX	ute insufficient to do job required, need 4x4 to do logging call outs!			08/12/2020		Fault	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Workshop\TRAINING	set up as call out ute			08/12/2020		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Brakes\BRAKE ADJ	carried out brake bleed on vehicle			28/10/2020		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
					repco Poww059016											
MVU026	Wodonga - Workshop	Brakes\EBS Kit	change ABS controller		completed	27/10/2020	433131	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Workshop\MOVE ASSET	droff off 1018's oower steerine box to ABS. 854's radiator to Natrad and oick up Peter from Cummins after droooeine off 981			21/10/2020		Reoair	Comoleted	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
					morey warnock POww057716											
					repco Poww058681											
					put engine in ute											
					finish off-test drive											
MVU026	Wodonga - Workshop	Engine\ENG REBLD	rebuild engine		check over/repair/clean tail lightds/ door trim etc	08/10/2020	432606	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Engine\ENG REBLD	put engine in ute, finish everything off, test drive, check over repairs/ clean tail lights/ door trim etc			08/10/2020	432606	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Engine\ENG REBLD	clean all parts up, clean parts and start reinstalliung, reinstalling parts			08/10/2020	432606	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
			chack timming													
MVU026	Wodonga - Workshop	Engine\ENG TUNE	remove head			20/08/2020		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Myrtleford - Workshop	VehService\8S	service due	VehService\8S	completed: see attahced	20/11/2018	408868	Service	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Wodonga - Workshop	Elect\HEAD LIGHT	replace L/H globe			15/09/2018	405389	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Wodonga Workshop	UTE
MVU026	Albury - Workshop	Elect\HEAD LIGHT	REPLACE HEAD LIGHT GLOBE			22/08/2018		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Albury Workshop	UTE
MVU026	Albury - Workshop	Elect\HEAD LIGHT	REPLACE HEAD LIGHT GLOBE			20/07/2018		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Albury Workshop	UTE
MVU026	Myrtleford - Workshop	VehService\AS	Job Added From Invoice			26/06/2018	0	Service	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Myrtleford Workshop	UTE
MVU026	Myrtleford - Workshop	VehService\AS	Job Added From Invoice			05/03/2018	386000	Service	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Myrtleford Workshop	UTE
MVU026	Myrtleford - Workshop	Engine\EXHAUST	Replace leaking exhaused .		Lavington Tyre & Exhaust .	09/01/2018		Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Myrtleford Workshop	UTE
MVU026	Myrtleford - Workshop	DrCabRep\SEAT	Job Added From Invoice			01/11/2017	0	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Myrtleford Workshop	UTE
MVU026	Albury - Workshop	Elect\HEAD LIGHT	REPLACED BLOWN HEADLIGHT GLOBES			20/07/2017	366045	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Albury Workshop	UTE
MVU026	Myrtleford - Workshop	Tyres\TP01	Job Added From Invoice			12/04/2017	0	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Myrtleford Workshop	UTE
MVU026	Myrtleford - Workshop	VehService	Job Added From Invoice			24/10/2016	0	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Myrtleford Workshop	UTE
MVU026	Myrtleford - Workshop	Body\WINDSCREEN	Job Added From Invoice			08/07/2016	0	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Myrtleford Workshop	UTE
MVU026	Myrtleford - Workshop	Tyres\TP01	Job Added From Invoice			15/01/2016	0	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Myrtleford Workshop	UTE
MVU026	Myrtleford - Workshop	Tyres\TP01	Job Added From Invoice			15/01/2016	0	Repair	Completed	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Myrtleford Workshop	UTE
MVU026	Myrtleford - Workshop	Elect\DOOR LOCK	Job Added From Invoice			04/12/2015	0	Reoair	Comoleted	FL Green Distribution	UTES	Wodonga	WDW	WTZ605	Myrtleford Workshop	UTE