EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	WorkAge	WorkState	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
1071	Albury - Workshop	Insp|ANT INSP	TELEMATICS SOLUTIONS - CHECK GUARDIAN SYSTEM IS WORKING AND PROVIDE TICKET TO ACCESS DATA.			17/10/2025 5:53:23		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	TELEMATICS	MVNEWR
1071	Albury - Workshop	Cooling|RADIATOR	Re-fit Radiator.			09/06/2025 5:53:23		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Albury Workshop	MVNEWR
1071	Albury - Workshop	Chassis|OPTIV WHEE	Removed Load cell's from Turn Table.		completed by JS TP	01/08/2025 5:53:23		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Albury Workshop	MVNEWR
1071	Albury - Workshop	Tyres|Callout	Tyres|Callout Chassis|BOOSTER Travelled 0km ways to recover 2 x boosters and 6 booster pegs. + return to depot.		CALL OUT TO INFLATED ROLLED OVER TRUCK	29/07/2025 5:53:23		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	BORDER BANDAGS PTY LTD - 4	MVNEWR
1071	Albury - Workshop	Chassis|BOOSTER	Travelled 318km			18/07/2025 5:53:23		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Tyres|TYRES	Tyres|TYRES Mobile Tyre & Towing After Accident @ Woodalgia.		STEER WAS RUN FLAT - DRIVER DROVE ON IT WITH CRACKED RIM	17/07/2025 5:53:23		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	BORDER BANDAGS PTY LTD	MVNEWR
1071	Albury - Workshop	Chassis|DRAWBAR	Removed Pin & Washer, Off Side of Drawbar with Impact Bolt Needing Travel Truck & Trailer from Accident Site to Workshop Depot			15/07/2025 5:53:23		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Albury Workshop	MVNEWR
1071	Albury - Workshop	Elec|SELECT PREW	power in stereo cuts out and lights dim when using power windows			15/07/2025 5:53:23		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Elec|ALT/ST DR	volts on tablet ranging from 9 to 12 depending on what lights running		Inspected alternator. Found charging at 13.7 volts. Tested charge at batteries - Charging 13 volts at batteries. Checked isolator and found 13.1 volts. 0.7 voltage drop between alternator and batteries. Notified James Krause of still right to use but will need attention	13/07/2025 5:53:23		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Susp|WORN* GAUGE	No accurate code (up to 10 Sec out)		Attempt to calibrate scales as Channel 2 was 10 Ton out. Recalibrated all channels, Channel 1 would not update correctly. Notified James Krause. Advised will need off the road for further repairs.	15/07/2025 5:53:23		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Tyres|TYR-HI	Tyres|TYR-HI|DRIVE			15/07/2025 5:53:23		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	BORDER BANDAGS PTY LTD - 4	MVNEWR
1071	Albury - Workshop	Tyres|TYR-LT STEER	Tyres|TYR-LT STEER			15/07/2025 5:53:23		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	BORDER BANDAGS PTY LTD - 4	MVNEWR
1071	Albury - Workshop	Tyres|TYR-HI	Tyres|TYR-HI|DRIVE			15/07/2025 5:53:23		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	BORDER BANDAGS PTY LTD - 4	MVNEWR
1071	Albury - Workshop	Wa-fs|sup|MOVE ASSIST	Hook up TI22/324			15/07/2025 5:53:23		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Albury Workshop	MVNEWR
1071	Albury - Workshop	Engine|VALV CODE	AFTER TRUST & CHECK ENGINE LIGHTS ON INTERMITTENT.			15/07/2025 5:53:23		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Engine|VALV CODE	CHECK ENGINE LIGHT ON ALL THE TIME			09/07/2025 5:53:23		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 L Service, Jack up steer axle check bearings and king pins.													
1071	Albury - Workshop	Vehicle|Veh Svc	Replace cabin filter.	Vehicle|Veh Svc		09/07/2025 5:53:23		Preventative Maintenance	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Engine|VALV CODE	AD BLU LIGHT COMING ON AND OFF REGULARY			09/07/2025 5:53:23		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Drv|ABRAKE|INSTGAUGE	check engine & after load light is on dash.			09/07/2025 5:53:23		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 L Service			09/07/2025 5:53:23		Service	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Engine|VALV CODE	Check engine and afterload light randomly on	Vehicle|Veh Svc		09/07/2025 5:53:23		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Elec|ALTO DR	Alternator not charging		-dit issue checked over, all working but all terminals need to be cleaned and terminal painted for protection. -further testing required on all auxiliary cable. for voltage drop	07/07/2025 5:27:186		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 Service [TCTC PORT095236]	Vehicle|Veh Svc		01/07/2025 5:27:01		Service	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	PACCAR PARTS FLEET SERVICES - 6	MVNEWR
					* Customer contacted dealership breakdown technician with information regarding breakdown * Customer advised of CTI system not working * Technician travelled to breakdown location, Bowtells Rest Area, NSW * Inspect & located screen in dash not working * Driver had attempted turning off/on several times but no change * Pulled dash panel/down & unplugged from power - left sit idle for a period then plugged back in * Turned it back on & performed its normal start up procedure - working fine now * Installed dash & returned truck to service										
1071	Albury - Workshop	Elec|INDICATORS	CTI Stopped Working, Screen Went Blank.													
1071	Albury - Workshop	CTI|CTI Elect	(TCTC #'s): TR95316	Vehicle|CTI		01/06/2025 5:17:57		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	TWIN CITY TRUCK CENTRE - CSD	MVNEWR
1071	Albury - Workshop	Elec|INDICATORS	Blinker Failing, Tripping Breaker Elec|INDICATORS [PORT095215]	Insp|LANN INSP		24/06/2025 5:18:19		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
			*Callout *RH indicator blowing circuit breaker Travel to Greenfreight Wodonga. RH indicator blowing circuit breaker. Disconnect 9-trailer still blows circuit breaker. Disconnect A-trailer doesn't Tail lights work, but not indicators. Disconnected trailer plug and tested truck Jay greens tow bill out. RH needs to be trailer plug and reassemble. Once truck around the yard doesn't fault. Sent truck down away. Truck driver got to Lovington WP and started again. Travel out there and check truck. Not faulting. Check 'A' trailer is today. Could not try check 'both' trailer at the same time.													
1071	Albury - Workshop	Elec|INDICATORS		Vehicle|CTI		24/06/2025 5:18:19		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 3 Service	Vehicle|Veh Svc		24/06/2025 5:18:19		Service	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	PACCAR PARTS FLEET SERVICES - 6	MVNEWR
1071	Albury - Workshop	Insp|ANN INSP	Insp|ANN INSP	Insp|ANN INSP		24/06/2025 5:18:19		Preventative Maintenance	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	PACCAR PARTS FLEET SERVICES - 6	MVNEWR
1071	Albury - Workshop	Chassis|SCRUBS	no bluetooth cable.		Not required as discussed with James Krause	06/06/2025 5:56:11		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Driv|ref CLUTCH	1 CLUTCH ADJUSTMENT			06/06/2025 5:56:11		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 Service	Vehicle|Veh Svc		06/06/2025 5:56:11		Service	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Drl.Cab|Ind|INSTGAUGE	check engine light on		In active faults at time of service	06/06/2025 5:56:11		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Driv|ref CEL LEAK	RHF hub seal leaking			06/06/2025 5:56:11		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Engine	TOP UP OIL		Completed during service	06/06/2025 5:56:11		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 Service	Vehicle|Veh Svc		30/05/2025 5:53:09		Service	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Driv|ref DRV SIR SER	ADJUST DPF WHEN EMPTY			30/05/2025 5:53:09		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
					-high idle PTO issue checked over, allowing along chass and behind dash cluster checked. -PTO switch and master switch box next to drivers seat tested, couldnt fault -master switch box swapped over + vehicle test driven, couldnt fault -hazard light switch for truck faults. cant will need to be reclaced										
1071	Albury - Workshop	Engine|VALV CODE	has major throttle fault - clicking on high idle @ random Accelerator Free Revving/High idling On It's Own without Being Able To Control.			29/05/2025 5:53:55		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Elec|SELECT PREW	Twin City Attended And Attempted To Fix. Engine Management Problem Started Again. Engine Manufacturer BREAKDOWN AFTER HOURS CALLOUT			29/05/2025 5:53:55		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
			The following breakdown repair for Greenfreight logging, to a 7609 Kenworth Truck Chassis# 1FUDDDDD0PLA76815, Registration#WPY99g & fleet number#8371 included:													
			* Customer contacted dealership breakdown technician with information regarding breakdown * Customer advised of truck engine/aftertreatment light on & RPM keeps changing from 600-1000rpm intermittently by itself * Technician called driver direct for more information * Technician sourced additional parts * Technician travelled to breakdown location, Tumbarumba, NSW * Connected diagnostic tooling - no active fault codes evident * Multiple inactive codes present & most of them related to charging * Start truck & monitored voltage/gauge - no failure evident, unable to find any faults & truck running normal * Checked battery voltage & confirmed @ 12.7v * Check battery charging & confirmed @ 13.2v * Use data monitor logger & check ECM power supply - no failure evident * Follow wiring diagnostic & check from alternator to starter motor, to earth studs & to battery's * Retention earth connections as precautionary measure * Removed battery terminals, cleaned & replaced including isolator * Start truck & check over once again - no failure evident * Cleaned inactive codes & returned truck to service													
1071	Albury - Workshop	Engine|BREAKDOWN	* Technician returned home			28/05/2025 5:53:55		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	PACCAR PARTS FLEET SERVICES - 6	MVNEWR
1071	Albury - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 Service	Vehicle|Veh Svc		21/05/2025 5:53:55		Service	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Tyres|Front - R	Tyres|Front - R			21/05/2025 5:53:55		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	BEAUMONTARES - 6	MVNEWR
1071	Albury - Workshop	Body|SUNVISOR	Rear light bar bent (Needs to be Replaced)		Completed during rear axle exchange	21/05/2025 5:53:55		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Drivaxle|AXLE REPLC	Drivaxle|AXLE REPLC bullwage rear axle housing			14/05/2025 4:59:79		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Drivaxle|WHEEL BRGS	L/H Rear drive hub came off pinkmeuver.		Gathered back in to site .notarized another airmenveyer. I drove down 1068 & Chevve followed in work utm to Lonewood. where we met Ross in 1071. disconnected 1071 from trailers T505/506 & connected 1068 to trailers T505/506. helped Ross back up trianales and move stuff from one truck to the other. i drove 1071 down the road	05/05/2025 4:59:79		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Drivaxle|BREAKDOWN	Tow Truck From Longwood To Wodonga Workshop. (AAA Towing RTO: T0960216)			05/05/2025 5:53:23		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Chassis	PTO cover leaking bolts tight			05/05/2025 5:53:23		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Steering|WHEEL SEAL	Both LH drive hub seals leaking Vehicle|Veh Svc 8 L Service, Jack up steer axle check bearings and king pins.		INSPECTED WHEEL BEARINGS.	05/05/2025 4:59:00		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Vehicle|Veh Svc	Replace cabin filter.	Vehicle|Veh Svc		05/05/2025 4:59:000		Preventative Maintenance	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Tyres|TYR-LO	Tyres|TYR-LO			28/04/2025 4:57:13		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	BEAUMONTARES	MVNEWR
1071	Albury - Workshop	Tyres|TYR-HI	Tyres|TYR-HI			28/04/2025 4:57:13		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	BEAUMONTARES	MVNEWR
1071	Albury - Workshop	Drivaxle|CLUTCH	Needs clutch free play adjust			21/04/2025 5:48:233		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Engine|VALV CODE	Check engine light on - EGR CONTROL.			21/04/2025 5:48:233		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Engine|EXHAUST	Crushed exhaust pipe behind muffler - TCTC Warranty			16/04/2025 5:48:027		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Elec|DASH LIGHT	HEADLIGHT HIGH LIGHTS WON'T TURNOFF - NEED TO REMOVE FUSE- FUSE IS IN CLIP HOLDER.		Duplicate job	16/04/2025 4:58:027		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Steering|WHEEL SEAL	WHEEL SEAL ON STEER IS WEEPING.		Removed remote breather and cleaned out. Removed remote breather hose and found fitting cracked. Fitting in gearbox for remote hose snapped off while removing hose. Parts required from WAPD to repair and drivers side taxibus removed to gain access to extract broken fitting and repair	16/04/2025 4:58:027		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Elec|TRL LIGHTS	Cab guard lights wont turn off - had to remove fuse - fuse in Uncup holder		Replaced male	16/04/2025 4:58:027		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 Service	Vehicle|Veh Svc		16/04/2025 4:58:027		Service	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
					Plugged monitor to mdvr. Formatted and assigned harddrive. Gave results. Started recording											
1071	Albury - Workshop	Drl.Cab|Ind|GPS	Drl.Cab|Ind|GPS			16/04/2025 4:57:183		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	ARKON AUTO ELECTRICAL - 4	MVNEWR
1071	Albury - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 Service	Vehicle|Veh Svc		08/04/2025 4:72065		Service	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Elec|ALT	ALTERNATOR STOPPED CHARGING.		BREAKDOWN. Called in for alternator out chrainne. Was only replaced by TCTC D200 yesterday as a breakdown out at Koetong. Came in and inspected. Found alternator is workes but will cause a reading incorrects. Reslaved and reapired broken terminals for volt sauge and set up concrete as alternator was replaced with a different one	03/04/2025 4:70082		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Tyres|TYR-HI	Tyres|TYR-HI			01/04/2025 4:70993		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	BEAUMONTARES - 6	MVNEWR
1071	Albury - Workshop	Tyres|TYR-HI	Tyres|TYR-HI			01/04/2025 4:70993		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	BEAUMONTARES - 6	MVNEWR
1071	Albury - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 Service	Vehicle|Veh Svc		28/03/2025 4:69666		Service	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Engine|VALV CODE	check engine light on		Couldn't fault during service	28/03/2025 4:69666		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Engine|AZBLUE	aftertreat light coming on intermittently		Couldn't fault during service	28/03/2025 4:69666		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Drivaxle|OIL LEAK	Leaking gearbox breather		Replaced exhaust elbow, adjust freely in bana diff R.S. 2 X HOURS LABOUR.	28/03/2025 4:69666		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 Service	Vehicle|Veh Svc		21/03/2025 4:68913		Service	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Body|EXHAUST	replaced exhust flex after the muffler and new clamps			21/03/2025 4:67013		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Albury Workshop	MVNEWR
1071	Albury - Workshop	Tyres|TYR-LO	Tyres|TYR-LO			21/03/2025 4:62352		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	BEAUMONTARES - 6	MVNEWR
1071	Albury - Workshop	Elec|START MOTR	Starter motor almost dead - TCTC Warranty		Checked over and attempted to start as truck was stuck on wash bay. TCTC was called out to replace starter under warranty	21/03/2025 4:64106		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Wodonga - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 Service	Vehicle|Veh Svc	Exhaust pipe cracked at connection that joins tow muffler warranty reclaimed by lighten yoke nut on rear of gearbox	12/03/2025 4:62250		Preventative Maintenance	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Elec|BATTERY	Truck hard to start. Been reported for 2 months			11/03/2025 4:52753		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Susp|SHOCK ABS	SHOCK ABSORBER LEAKING SHOCK NUMBERS.		Previously completed	11/03/2025 4:52751		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 Service Vehicle|Veh Svc 8 Service	Vehicle|Veh Svc		11/03/2025 4:52751		Service	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Vehicle|Veh Svc	PTO created for call: 8978120 not sent to customer	Vehicle|Veh Svc		04/03/2025 4:48:092		Service	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	PACCAR PARTS FLEET SERVICES - 6	MVNEWR
1071	Albury - Workshop	Wa-fs|sup|MOVE ASSIST	HOOKED UP TI21/316.			25/02/2025 4:65573		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Albury Workshop	MVNEWR
1071	Albury - Workshop	Chassis|AIR LEAK	AIR LEAK FROM LH TANK OR DRYER*		Swap air dryer with spare~	19/02/2025 4:65569		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Engine|START MOTR	Starter needs looking at or replacing.		Starter motor is ok	19/02/2025 4:65569		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 Service	Vehicle|Veh Svc	4100186 5. MUCAR8	19/02/2025 4:65569		Service	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Brake|BRE RELINE	REJOINED ALL DRIVES. REPLACED DRUMS.			19/02/2025 4:65569		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Wodonga - Workshop	Body|WINDSCREEN	Cracked drivers side windscreen.			12/02/2025 4:65859		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	AUSTRALIA GLASS	MVNEWR
1071	Wodonga - Workshop	Brake|BRE RELINE	FULL RELINE REQUIRED.			07/02/2025 4:55275		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Wodonga - Workshop	Engine|FAULT CODE	Check engine light on.		No active coastal alarm tested with computer no check engine light on	07/02/2025 4:55275		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Wodonga - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 Service	Vehicle|Veh Svc	69kg Pins need to measured with a dial findicator at the beginning of the service measure for vertical movement and record figure. Measured alternator output at 15 volts	07/02/2025 4:55275		Service	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Wodonga - Workshop	Elec|ALT	Check alternator, volts low and high beam is flickering.		Batteries were load tested and measured 12.5 volts	07/02/2025 4:55275		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Wodonga - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 L Service	Vehicle|Veh Svc	R1 no paperwork done at the same time as the 8 month 8 service was completed	07/02/2025 4:55275		Preventative Maintenance	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Wodonga - Workshop	Engine|ALT	Hard to start.		Tested charging system and batteries all checked with load tester Checked hot pipe not leaking	07/02/2025 4:55275		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Wodonga - Workshop	Engine|HOT PIPE	Rust leaking air at loader no air leaks (Done another hot pipe)			01/02/2025 4:55275		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 Service	Vehicle|Veh Svc	4100186x	31/01/2025 4:58207		Service	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Wodonga - Workshop	Engine|ALT	starting motor on way out. very slowly turns engine over			21/01/2025 4:52211		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Wodonga - Workshop	Brake|LINE LEAK	left hand steer OS leak			14/01/2025 4:52211		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Wodonga - Workshop	Steering|OIL LEAK	OIL LEAK	Vehicle|Veh Svc		14/01/2025 4:52211		Service	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Albury - Workshop	Tyres|TYR-LT	Tyres|TYR-LT			17/01/2025 4:22859		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	BEAUMONTARES - 6	MVNEWR
1071	Albury - Workshop	Tyres|TYR-HI	Tyres|TYR-HI			07/01/2025 4:21755		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	BEAUMONTARES - 6	MVNEWR
1071	Albury - Workshop	Tyres|TYR-LO	Tyres|TYR-LO			07/01/2025 4:21755		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	BEAUMONTARES - 6	MVNEWR
1071	Albury - Workshop	Steering|OIL LEAK	HUB SEAL LEFT STEER.			06/01/2025 4:21439		Repair	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
					Replace th stem hub cap and gasket Replace steer hub cap											
1071	Wodonga - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 L Service	Vehicle|Veh Svc	Replace fuses on trailer control box as were worse and some blown	06/01/2025 4:21439		Preventative Maintenance	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Wodonga - Workshop	Engine|START MOTR	Check Starter Motor, Seems HE & mis when Starting.		Seems to start fine every time I start it	06/01/2025 4:21439		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Wodonga - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 Service	Vehicle|Veh Svc	/	06/01/2025 4:21439		Service	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Wodonga - Workshop	Vehicle|Veh Svc	Vehicle|Veh Svc 8 Service	Vehicle|Veh Svc	/	16/12/2024 4:54269		Service	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Wodonga - Workshop	Brakes	BRAKE ISSUES.		CHECKED BRAKES & BOOSTERS. DIAGNOSED AND REPLACED TRACTOR PROTECTION VALVE.	11/12/2024 4:50942		Fault	Completed	Greenfreight Logging NSW	KW0151250	Albury	ATK	KW7616	Wodonga Workshop	MVNEWR
1071	Wodonga - Workshop

1071	Wodonga - Workshop	VehServ/all/LIS	VehServ/all/LIS	VehServ/all/LIS		08/07/2024 269801	Service	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	VehServ/all/BS	VehServ/all/BS	VehServ/all/BS	269801ds	08/07/2024 269801	Service	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Albury - Workshop	Tyres	Tyres	Tyres		03/07/2024 268163	Repair	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	BEAUREPAIRES - 6	P/MOVER
1071	Wodonga - Workshop	Elec/ElMK LIGHT	BRAKE LIGHTS STUCK ON.		Previously Repaired and Completed	03/07/2024 268267	Fault	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	VehServ/all/LIS	VehServ/all/LIS	VehServ/all/LIS		03/07/2024 268267	Service	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	VehServ/all/TRANS OIL	Transmission Oil Change	VehServ/all/TRANS OIL		20/06/2024 255160	PreventativeMaintenance	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	Division/DIFF OIL	Diff Oil Change	Division/DIFF OIL		20/06/2024 255160	PreventativeMaintenance	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	VehServ/all/LIS	VehServ/all/LIS	VehServ/all/LIS		20/06/2024 255163	Service	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	VehServ/all/Svc	B 1 Service	VehServ/all/Svc	255159 ks A kit Gal Subliner coated/doubles plate Cracked wellbore behind outer wheel	20/06/2024 255163	PreventativeMaintenance	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	DrCabBed/LOCALES	NO SCALES ON THIS TRAILERS. ONLY SHOWING BAY 1.		Front LH Guard realigned. Led Service	20/06/2024 255160	Fault	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Body/ENGS/DOORS	FRONT LEFT WHEEL ARCH NEEDS TO BE STRAIGHTENED.			06/06/2024 266050	Fault	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER	
1071	Wodonga - Workshop	VehServ/all/LIS	VehServ/all/LIS	VehServ/all/LIS		06/06/2024 266050	Service	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	DrCabBed/LOCALES	CAN'T LOAD TRAILERS. KEEP BLOWING FUSES. NO SCALES ON TRAILERS.		Scales just needed to be relocated	06/06/2024 266050	Fault	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	DrCabBed/LOCALES	SCALES NOT WORKING.		Scales just needed to be relocated	06/06/2024 266050	Fault	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	Elec/ITRL LIGHTS	CLEARANCE LIGHTS ON TRAILERS NOT WORKING.		Repaired Wiring Short \ Park light Circuit Last Service	06/06/2024 266050	Fault	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Albury - Workshop	Tyres/ITP/4x4	Tyres/ITP/4x4			26/05/2024 232060	Repair	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	BEAUREPAIRES - 6	P/MOVER
1071	Albury - Workshop	Tyres/ITP/4x4	Tyres/ITP/4x4			26/05/2024 232060	Repair	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	BEAUREPAIRES - 6	P/MOVER
1071	Wodonga - Workshop	Insp/LANN INSP	Annual Inspection	Insp/LANN INSP		23/05/2024 255050	PreventativeMaintenance	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	VehServ/all/BS	B Service	VehServ/all/BS		23/05/2024 255050	Service	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	DrCabBed/LOCALES	NO SCALES ON TRAILERS (CH 2 & CH3)		DIAGNOSED BROKEN WIRES AT PLUG. REPLACED PLUG. NEED TRAILERS EMPTY TO FIND FURTHER FAULTS.	23/05/2024 255050	Fault	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/04/2024 218137	Repair	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	Division/CEL LEAK	Passenger Side Rear Axle Leaking Oil			27/04/2024 218137	Repair	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	Division/CEL LEAK	PASSENGER SIDE REAR AXLE LEAKING OIL			27/04/2024 218137	Repair	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	VehServ/all/BS	Service As Per Attached Checklist	VehServ/all/BS		27/04/2024 218137	Service	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/04/2024 205092	Repair	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.		Scales just needed to be relocated	12/04/2024 205092	Repair	Completed	GreenFreight Logging NSW	6565151255	Albury	ATK	9967600	Wodonga Workshop	P/MOVER
1071	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.	

1071	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.			04/10/2023 61266	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Veh\service\JAS	Service As Per Attached Checklist	Veh\service\JAS		04/10/2023 61266	Service	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/09/2023 57258	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.			27/09/2023 57258	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.			27/09/2023 57258	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Dir\Cabins\F\JAP	TMA DATA NOT WORKING & LOG BOOK NOT WORKING RIGHT.			27/09/2023 57258	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Dir\Cabins\F\JAP	GET TMA DATA WORKING AGAIN.			27/09/2023 57258	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Elec\TAIL\WORK LIGHT	Work lights not working on cab rack.		Hagleys repaired	27/09/2023 57258	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Veh\service\JAS	Service As Per Attached Checklist	Veh\service\JAS		27/09/2023 57258	Service	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	CTS\T1 Drive	Replaced Pressure Regulator Valve		checked afterwards for air leaks - OK	26/09/2023	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Engine\Fuel\Lube	Fuel pump - not pumping up not going down.		checked operation of system - OK	26/09/2023	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/09/2023 53796	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Dir\Cab\Reg\HOUSEKEEP	FIT FIRST AID KIT.			21/09/2023 53796	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Dir\Cabins\F\RADIO	UHF WIRED TO HAVIA. Service As Per Attached Checklist			21/09/2023 53796	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Veh\service\JAS	TCTC FOR 538 LIST	Veh\service\JAS		21/09/2023 53796	Service	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/09/2023 68782	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Dir\Cab\Reg\HOUSEKEEP	FIT FIRST AID KIT.			15/09/2023 68782	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.			15/09/2023 68782	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Dir\Cabins\F\RADIO	UHF WIRED TO HAVIA.			15/09/2023 68782	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Dir\Cabins\F\JAP	TMA DATA NOT WORKING & LOG BOOK NOT WORKING RIGHT.			15/09/2023 68782	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Elec\TAIL\WORK LIGHT	WORK LIGHTS ON CAB RACK NOT WORKING.			15/09/2023 68782	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Dir\Cabins\F\JAP	GET TMA DATA WORKING AGAIN.			15/09/2023 68782	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Elec\TAIL\WORK LIGHT	WORK LIGHTS ON CAB RACK NOT WORKING.			15/09/2023 68782	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Body\MUDGUARDS	MISSING R/H/R MUDFLAP.			15/09/2023 68782	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Veh\service\JAS	Carry out A Service as per job card for TRSR X15	Veh\service\JAS		15/09/2023 68782	Service	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.			15/09/2023 68782	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			08/09/2023 61701	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	Dir\Cabins\F\RADIO	UHF WIRED TO HAVIA.			08/09/2023 61701	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	Dir\Cabins\F\JAP	TMA DATA NOT WORKING & LOG BOOK NOT WORKING RIGHT.			08/09/2023 61701	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	Elec\TAIL\WORK LIGHT	WORK LIGHTS ON CAB RACK NOT WORKING.			08/09/2023 61701	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	Dir\Cabins\F\JAP	GET TMA DATA WORKING AGAIN.			08/09/2023 61701	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	Veh\service\JAS	Carry out A Service as per job card for TRSR X15	Veh\service\JAS		08/09/2023 61701	Service	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	Dir\Cab\Reg\HOUSEKEEP	FIT FIRST AID KIT.			08/09/2023 61701	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.			08/09/2023 61701	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			01/09/2023 36171	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	CTS\T1 Elec	RESET C.T.I. SETTINGS 30 PSI TO 40KM & 50 PSI TO 90KM.		CAN'T BE DONE.	01/09/2023 36171	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	CTS\T1 Elec	RESET C.T.I. TO 90 KM/H ON 50PSI. 90KM ON 50PSI PLEASE.			01/09/2023 36171	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Engine\BOOST HOSE	TRUCK DOWN ON POWER. 15% ON TURBO BOOST.			01/09/2023 36171	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Engine\START P&W	TURN OFF AUTO SHUT OFF PLEASE.			01/09/2023 36171	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Dir\Cab\Reg\DOOR LOCK	STICK 58/100 DOOR RUBBERS BOTH SIDES.			01/09/2023 36171	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	CTS\T1 Elec	RESET CTI SETTING 30PSI TO 90KM & 50PSI TO 99KM			01/09/2023 36171	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Dir\Cabins\F\RADIO	UHF WIRED TO HAVIA.			01/09/2023 36171	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Brake\EBS FAULTS	TRAILER ABS LIGHT STAYS ON.			01/09/2023 36171	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Brake\EBS FAULTS	TRAILER ABS LIGHT IS ON ALL THE TIME.			01/09/2023 36171	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Engine\ADBLUE	AFTER TREAT LIGHT IS STAYING ON.			01/09/2023 36171	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Dir\Cabins\F\JAP	TMA DATA NOT WORKING & LOG BOOK NOT WORKING RIGHT.			01/09/2023 36171	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Dir\Cab\Reg\HOUSEKEEP	TRUCK IS LOCKED. KEYS IN THE BOX.			01/09/2023 36171	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Elec\SELECT P&W	SCALES ON BACK BAY NOT WORKING.			01/09/2023 36171	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Elec\TAIL\WORK LIGHT	WORK LIGHTS ON CAB RACK NOT WORKING.			01/09/2023 36171	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Engine	TRUCK DOWN ON POWER.			01/09/2023 36171	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Dir\Cabins\F\JAP	GET TMA DATA WORKING AGAIN.			01/09/2023 36171	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Veh\service\JAS	Carry out A Service as per job card for TRSR X15	Veh\service\JAS	REPLACED WD COUPLING.	01/09/2023 36171	Service	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/08/2023 27573	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Veh\service\JAS	Carry out A Service as per job card for TRSR X15	Veh\service\JAS		19/08/2023 27573	Service	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		REPLACED BOOST HOSE.	28/07/2023 18103	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	Engine	TRUCK DOWN ON POWER, TURBO BOOST 15%.		COMPLETED ECM ADJUSTMENT.	28/07/2023 18103	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	Engine	TURN OFF AUTO SHUT OFF.			28/07/2023 18103	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	Dir\Cab\Reg\DOOR LOCK	STICK 58/100 DOOR SEALS.			28/07/2023 18103	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	CTS\T1 Elec	RESET C.T.I. SETTINGS 30 PSI TO 40KM & 50 PSI TO 90KM.			28/07/2023 18103	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	Dir\Cab\Reg\HOUSEKEEP	TRUCK IS LOCKED. KEYS IN THE CUT CAB.		ALREADY FITTED.	28/07/2023 18103	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	Engine\START P&W	TURN OFF AUTO SHUT OFF.			28/07/2023 18103	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	CTS\T1 Elec	RESET C.T.I. TO 90 KM/H ON 50PSI. 90KM ON 50PSI PLEASE.			28/07/2023 18103	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	Dir\Cab\Reg\DOOR LOCK	STICK 58/100 DOOR RUBBERS BOTH SIDES.			28/07/2023 18103	Fault	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
			Carry out A Service as per job card for TRSR X15 (TCTC)															
1071	Albury - Workshop	Veh\service\JAS	Auxiliary Valve Number 22 Wire	Veh\service\JAS		19/07/2023 18103	Service	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			31/07/2023 9679	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Body\MUDGUARDS	SUPPLY AND FIT MUDFLAPS AS REQUESTED.			31/07/2023 9679	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Wodonga - Workshop	Dir\Cabins\	SUPPLIED & INSTALLED AIR BLOWER BEHIND DRIVERS SEAT		For ordering via service inspection for Greenfreight logging, as a new element in Truck Checklists No.21, and registered	31/07/2023 9679	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
					8936.76830 included:													
					* Removed/replaced engine filter & oil, specification used in parts section below.													
					* Check all engine operation & components													
					* Removed/replaced transmission oil filter													
					* Check all hydraulic lines fitting & level lubricant levels to specification													
					* Removed/replaced power steering filter & gasket													
					* Removed/replaced differential oil, specification used in parts section below.													
					* Removed/replaced fuel filter													
					* Check cooling system & pressure test													
					* Check all belts, idler pulleys, fan, shrouds & adjust to specification													
					* Check all electrical routing, wiring looms, switches, sensors & components													
					* Check all wheel equipment & steering components													
					* Check all braking & adjust to specification													
					* Check clutching & adjust to specification													
					* Check all suspension components													
					* Check all internal cabin operation , components & adjust to specification													
					* Check all external cabin components & adjust to specification													
					* Check windscreen washers, wipers, refill & test operation													
					* Lubricate, adjust relevant components as required													
			Service As Per Attached Checklist (First Service) (TCTC)		* Re torque all fitting & fixtures													
1071	Wodonga - Workshop	Veh\service\JAS	***COMPLIMENTARY NO CUSTOMER LABOUR CHARGE KENWORTH TRUCK 1.U SERVICE POLICY***		* Wash vehicle complete													
1071	Wodonga - Workshop	Veh\service\JAS	***CUSTOMER RESPONSIBLE FOR ALL PARTS REQUIRED FOR 1.U SERVICE***	Veh\service\JAS	* Road test, confirm & audits check	31/07/2023 9679	Service	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Wodonga Workshop	P/MOVER			
1071	Albury - Workshop	Tyres\TPS+6	Tyre Position 6 = 6			08/07/2023	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Albury Workshop	P/MOVER			
1071	Albury - Workshop	Tyres\TPS+5	Tyre Position 5 = 5			08/07/2023	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Albury Workshop	P/MOVER			
1071	Albury - Workshop	Tyres\TPS+7	Tyre Position 7 = 7			08/07/2023	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Albury Workshop	P/MOVER			
1071	Albury - Workshop	Tyres\TPS+10	Tyre Position 9 = 10			08/07/2023	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	Albury Workshop	P/MOVER			
1071	MyShed'ed - Workshop	Dir\Cabins\F\SCALES	recalibration scales			01/07/2023 0488	Repair	Completed	GreenFreight Logging NSW	6905151255	Albury	ATE	9967600	MyShed'ed Workshop	P/MOVER			