LOAD23 COMPLETE HISTORY NOV26

Code\SubCode	Description	Completed By	Completed	DistanceDone	HourDone	Completion Comment	Manager Comment	State	WO#	Supplier	PoSuppliers	Missed
DrCabElect \RADIO	playing up with CD player i... more		21 Mar 2024				Completed - Not Required	Completed		Wodonga Workshop		
DrCabElect \RADIO	cd radio loosing signal U... more		21 Mar 2024				Completed - Not Required	Completed		Wodonga Workshop		
DriCabRep \ELECT P&W	work light behind cab not w... more		21 Mar 2024				Completed - Not Required	Completed		Wodonga Workshop		
Body \HOUSEKEEP	RHS need fixing better		21 Mar 2024				Completed - Not Required	Completed		Wodonga Workshop		
VehService \AS	A Service almost due 700km		21 Mar 2024				Completed - Not Required	Completed		Wodonga Workshop		17 missed ►
Hydraulics \HOSES	Travel to site. Got asked ... more		26 Aug 2023					Completed		Albury Workshop	RAPID HYDRAULICS & PNEUMATICS -4	
Hydraulics \RAM	Hoses on loader Travel to ... more		24 Aug 2023					Completed		Albury Workshop	RAPID HYDRAULICS & PNEUMATICS -4	
DriCabRep \WINDOW REG	TCTC supply parts		17 Apr 2023	943300				Completed		Albury Workshop	PACCAR PARTS FLEET SERVICES - 4	
Hydraulics \BREAKDOWN	Callout at 9:30 27/06/22 fr... more		27 June 2022					Completed		Albury Workshop	RAPID HYDRAULICS & PNEUMATICS -4	
DriCabRep \ELECT P&W	work light behind cab not w... more		11 May 2021					Completed		Wodonga Workshop		
Body \HOUSEKEEP	LHS step needs replacing		11 May 2021					Completed		Wodonga Workshop		
Body \HOUSEKEEP	RHS need fixing better		11 May 2021			step on RHS & LHS bent, wai... more		Completed		Wodonga Workshop		
VehService \AS	A Service almost due 700km		11 May 2021					Completed		Wodonga Workshop		2 missed ►
Body \ELECT P&W	brake lights not working		11 May 2021			brake lights inop, inspecte... more	brake lights inop, inspecte... more	Completed		Wodonga Workshop		
Brakes \BRAKE ADJ	Brake Adjustment.		1 Apr 2021	943300		Brake Adjustment in Service.	Brake Adjustment in Service.	Completed		Wodonga Workshop		
Cooling \RADIATOR	Turn on Heater Taps		1 Apr 2021	943300		Heater taps turned on.	Heater taps turned on.	Completed		Wodonga Workshop		
VehService \BS	B Sevice over due		3 Dec 2020	23020				Completed		Albury Workshop		
Air Con \AIR CON	aircon not working	Kevin Drum	11 Nov 2020					Completed		Albury Workshop		
VehService \BS	B Service overdue due hrs... more		3 Nov 2020	22838				Completed		Albury Workshop		
Engine \COMPRESSOR	organised compressor and mo... more		3 Nov 2020	22838				Completed		Albury Workshop		
Body \LIGHTS	left hand side work light b... more		30 Oct 2020					Completed		Albury Workshop		
VehService \AS	A Service Due	Kevin Drum	9 Sept 2020	910118				Completed		Albury Workshop		3 missed ►
Engine \COMPRESSOR	air dryer letting out air e... more		18 Aug 2020	900041				Completed		Albury Workshop		
Engine \ENG TUNE	truck has a miss		18 Aug 2020	900041				Completed		Albury Workshop		
DrivLine \CLUTCH	clutch adjustment		18 Aug 2020	900041				Completed		Albury Workshop		
Susp \HCV	right height spring all ove... more	Kevin Drum	18 Aug 2020	899919		repaired bent HCV bracket ... more	repaired bent HCV bracket ... more	Completed		Albury Workshop		
Cooling \COOL LEAKS	check for coolant leak - none		10 Aug 2020	898230				Completed		Albury Workshop		
Cooling \CONSUMABLE	took 8 lts coolant		10 Aug 2020	898230				Completed		Albury Workshop		
Cooling \COOL LEAKS	possible heater core leaking		10 Aug 2020	898230				Completed		Albury Workshop		
DriCabRep \WINDOW REG	side & window seal needs fi... more		5 Aug 2020			RR's pre Jan 20 (system cl... more	Completed	Completed		Wodonga Workshop		
DriCabRep \DAMAGE	roof lining needs fixing		5 Aug 2020				Completed	Completed		Wodonga Workshop		
DriCabRep \DAMAGE	loader needs floor mats		5 Aug 2020				Completed	Completed		Wodonga Workshop		
Elect \ELECT P&W	leg switch sticking		5 Aug 2020				Completed	Completed		Wodonga Workshop		
DriCabRep \WINDSCREEN	loader need new front window		5 Aug 2020				Completed	Completed		Wodonga Workshop		

Code\SubCode	Description	Completed By	Completed	DistanceDone	HourDone	Completion Comment	Manager Comment	State	WO#	Supplier	PoSuppliers	Missed
DriCabRep \SEAT	truck needs new seat		5 Aug 2020				Completed	Completed		Wodonga Workshop		
DrCabElect \RADIO	cd player in truck has now ... more		5 Aug 2020				Completed	Completed		Wodonga Workshop		
Elect \DRV LIGHT	needs new driving lights		5 Aug 2020				Completed	Completed		Wodonga Workshop		
Body \DAMAGE	roof needs looking at leaki... more		5 Aug 2020				Completed	Completed		Wodonga Workshop		
Body \HOUSEKEEP	very slippery when wet		5 Aug 2020				Completed	Completed		Wodonga Workshop		
Body \HOUSEKEEP	tow chain needs moving out ... more		5 Aug 2020				Completed	Completed		Wodonga Workshop		
Body \HOUSEKEEP	rack need makig up for hyd ... more		5 Aug 2020				Completed	Completed		Wodonga Workshop		
DrCabElect \RADIO	truck need new CD player		5 Aug 2020				Completed	Completed		Wodonga Workshop		
Body \MIRRORS	RHS mirror needs replacing		5 Aug 2020				Completed	Completed		Wodonga Workshop		
Body \HOUSEKEEP	tow chain needs moving no g... more		5 Aug 2020				Completed	Completed		Wodonga Workshop		
Body \OH&S	LHS step needs looking at		5 Aug 2020				Completed	Completed		Wodonga Workshop		
VehService \AS	A Service overdue		2 Aug 2020	895056		Carry Out A Service	Carry Out A Service	Completed		Albury Workshop		174 missed ►
DrCabElect \RADIO	cd radio loosing signal U... more		2 Aug 2020	895056				Completed		Albury Workshop		
Elect \INDICATORS	replace and rewire bonnet i... more		2 Aug 2020	895056				Completed		Albury Workshop		
Cooling \RADIATOR	flush radiator		2 Aug 2020	895056				Completed		Albury Workshop		
Susp \SUSPENSION	require front top diff stab... more		2 Aug 2020	895056				Completed		Albury Workshop		
Brakes	Record Check Results As Att... more		2 Aug 2020	895056				Completed		Albury Workshop		
Tyres \FITMENT	Job Added From Invoice		17 July 2020	937334	0			Completed		Albury Workshop		
Elect \BATTERY	had jump start at Shelly	Kevin Drum	8 July 2020	888589				Completed		Albury Workshop		
VehService \BS	B Service		28 June 2020	22027				Completed		Albury Workshop		
Chassis \EXHAUST	replace exhaust		28 June 2020	22027				Completed		Albury Workshop		
Engine \OIL LEAK	oil leaks		28 June 2020	22027				Completed		Albury Workshop		
Engine \ELECT P&W	wiring engine bay		28 June 2020	22027				Completed		Albury Workshop		
DriCabRep \WIPERS	replaced wiper blades	Kevin Drum	1 June 2020	879436				Completed		Albury Workshop		
VehService \AS	A Service Due (875,000km)		8 May 2020	873900				Completed		Albury Workshop		
Elect \DRV LIGHT	driving light shorting out ... more	Kevin Drum	8 May 2020	873900				Completed		Albury Workshop		
Elect \DRV LIGHT	driving light flickering on... more	Kevin Drum	1 May 2020	871682				Completed		Albury Workshop		
DrCabElect \INST/GAUGE	some globes in dash need re... more		1 May 2020	871682				Completed		Albury Workshop		
DrivLine \AIR LEAK	air leak under back diff		1 May 2020	871682				Completed		Albury Workshop		
VehService \AS	A Service almost due		26 Apr 2020				Completed	Completed		Albury Workshop		1 missed ►
DrCabElect \RADIO	UHF hand piece needs replac... more		26 Apr 2020				Completed	Completed		Albury Workshop		
Elect \DRV LIGHT	driving light need looking at		26 Apr 2020				Completed	Completed		Albury Workshop		
Susp \SUSPENSION	check suspension slipping o... more		26 Apr 2020				Completed	Completed		Albury Workshop		
Elect \DRV LIGHT	driving light shorting out		8 Apr 2020	865876				Completed		Albury Workshop		
DrCabElect \RADIO	playing up with CD player i... more		8 Apr 2020	865876				Completed		Albury Workshop		
DrCabElect \SEAT	air leak under seat	Kevin Drum	3 Apr 2020	864007				Completed		Albury Workshop		
DrCabElect \WINDSCREEN	L/H windscreen wiper not wo... more	Kevin Drum	4 Mar 2020	855855				Completed		Albury Workshop	PACCAR PARTS FLEET SERVICES - 4	
DrivLine \SUSPENSION	check suspension all over t... more		12 Feb 2020	849492				Completed		Albury Workshop		
VehService \AS	A Service almost due		12 Feb 2020	849492				Completed		Albury Workshop		1 missed ►

Code\SubCode	Description	Completed By	Completed	DistanceDone	HourDone	Completion Comment	Manager Comment	State	WO#	Supplier	PoSuppliers	Missed
Body \ELECT P&W	raise PO for red/amber ligh... more		24 Jan 2020					Completed		Wodonga Workshop	PACCAR PARTS FLEET SERVICES - 4	
Elect \HEAD LIGHT	RHS headlight out		20 Dec 2019	840283				Completed		Albury Workshop		
VehService \AS	A Service Due		20 Dec 2019	840283				Completed		Albury Workshop		5 missed ►
Air Con \AIR CON	aircon fan needs looking at... more		12 Dec 2019	838385				Completed		Albury Workshop		
Elect \TRL LIGHTS	side lights not working LHS	Kevin Drum	29 Oct 2019	826430				Completed		Albury Workshop		
Engine \FUEL TANK	fuel leak around pump		6 Sept 2019	814364				Completed		Albury Workshop		
Body \OH&S	LHS step needs looking at		6 Sept 2019	814364				Completed		Albury Workshop		
VehService \AS	A Service almost due (815,0...		6 Sept 2019	814364				Completed		Albury Workshop		146 missed ►
Body \HOUSEKEEP	needs new wheel brace old o... more		2 Sept 2019	812650				Completed		Albury Workshop		
Body \HOUSEKEEP	tow chain needs moving no g... more		2 Sept 2019	812650				Completed		Albury Workshop		
Brakes \BOOSTER	Replaced broken LHF brake b... more		24 July 2019	802789				Completed		Rosewood Workshop		
VehService \AS	A Service Due 800000km		18 July 2019	80677				Completed		Albury Workshop		
Body \MIRRORS	mirror needs replacing R/H ... more		18 July 2019	80677				Completed		Albury Workshop		
DriCabRep \WIPERS	washer not working		18 July 2019	80677				Completed		Albury Workshop		
Elect \WORK LIGHT	lights behind cab had to cu... more		18 July 2019	801660				Completed		Albury Workshop		
DrCabElect \RADIO	truck need new CD player		15 July 2019	800853				Completed		Albury Workshop		
Elect \DRV LIGHT	truck need driving lights ... more		15 July 2019	800853				Completed		Albury Workshop		
Elect \DRV LIGHT	truck needs better driving ... more		11 July 2019	799844				Completed		Albury Workshop		
Body \MIRRORS	RHS mirror needs replacing		11 July 2019	799844				Completed		Albury Workshop		
VehService \AS	A Service		11 July 2019	799844				Completed		Albury Workshop		
DrivLine \AIR LEAK	diff lock leaking air		25 June 2019	799308				Completed		Albury Workshop		
VehService \AS	A Service almost due		25 June 2019	799308				Completed		Albury Workshop		1 missed ►
Body \HOUSEKEEP	rack need makig up for hyd ... more		25 June 2019	799308				Completed		Albury Workshop		
Body \DAMAGE	roof needs looking at leaki... more		27 May 2019	789980				Completed		Albury Workshop		
Elect \TAIL LIGHT	reverse lights sometimes no... more		27 May 2019	789980				Completed		Albury Workshop		
Body \HOUSEKEEP	very slippery when wet		27 May 2019	789980				Completed		Albury Workshop		
VehService \AS	A Service Due 790000		25 May 2019	789728				Completed		Albury Workshop		1 missed ►
Elect \WORK LIGHT	running light stay on		25 May 2019	789728				Completed		Albury Workshop		
Elect \DRV LIGHT	needs new driving lights		25 May 2019	789728				Completed		Albury Workshop		
VehService \BS	B Service 500 off		11 Apr 2019	780094				Completed		Albury Workshop		81 missed ►
DrCabElect \RADIO	CD radio bad service		11 Apr 2019	780094				Completed		Albury Workshop		
DrCabElect \RADIO	UHF has no range		24 Mar 2019	775259				Completed		Albury Workshop		
DrCabElect \INST/GAUGE	CD radio has same problem ... more		24 Mar 2019	775259				Completed		Albury Workshop		
DrCabElect \RADIO	cd player in truck has now ... more		19 Mar 2019	773950				Completed		Albury Workshop		
DriCabRep \SEAT	truck needs new seat		19 Mar 2019	773950				Completed		Albury Workshop		
DriCabRep \SEAT	truck needs new seat		15 Mar 2019	772830				Completed		Albury Workshop		
Elect \DRV LIGHT	need new driving lights		15 Mar 2019	772830				Completed		Albury Workshop		
DriCabRep \WINDOW REG	side & window seal needs fi... more		21 Feb 2019	767168				Completed		Albury Workshop		
DriCabRep \DAMAGE	roof lining needs fixing		21 Feb 2019	767168				Completed		Albury Workshop		
DriCabRep \DAMAGE	loader needs floor mats		21 Feb 2019	767168				Completed		Albury Workshop		
Elect \ELECT P&W	leg switch sticking		21 Feb 2019	767168				Completed		Albury Workshop		
Engine \OIL LEAK	oil leaking under the loader		21 Feb 2019	767168				Completed		Albury Workshop		
Workshop \MOVE ASSET	pick up LOAD23 from Nixons ... more		11 Jan 2019					Completed		Myrtleford Workshop	MITCHS MOBILE MECHANICS P/L -4	
Workshop \MOVE ASSET	tow truck and loader to Nix... more		28 Aug 2018					Completed		Myrtleford Workshop	SHEPPARTON MOTOR PANEL- 4	

Code\SubCode	Description	Completed By	Completed	DistanceDone	HourDone	Completion Comment	Manager Comment	State	WO#	Supplier	PoSuppliers	Missed
Body \DAMAGE	Salvage truck at accident s... more		1 June 2016					Completed		Myrtleford Workshop	SHEPPARTON MOTOR PANEL- 4	
Body \DAMAGE	Clean truck		1 June 2016					Completed		Myrtleford Workshop		
Engine \HOUSEKEEP	Inspect engine & turbo big ... more		1 June 2016					Completed		Myrtleford Workshop		
Body \MOUNTS	bottom L step needs sliding... more		29 Jan 2016			completed	completed	Completed		Myrtleford Workshop		
Chassis \MUDGUARDS	Left front flap falling off		29 Jan 2016			remove un-needed mudflap an... more	completed	Completed		Myrtleford Workshop		
Susp \HOUSEKEEP	replace RHF drive rebound r... more		29 Jan 2016			completed	completed	Completed		Myrtleford Workshop		
Tyres \TP08	Job Added From Invoice		24 Jan 2016	568114	0			Completed		Albury Workshop		
Tyres \TP08	Job Added From Invoice		24 Jan 2016	0	0			Completed		Albury Workshop		
Tyres \TP08	Job Added From Invoice		24 Jan 2016	0	0			Completed		Albury Workshop		
Tyres \TP09	Job Added From Invoice		12 Jan 2016	569904	0			Completed		Albury Workshop		
Tyres \TP09	Job Added From Invoice		12 Jan 2016	0	0			Completed		Albury Workshop		
Tyres \TP09	Job Added From Invoice		12 Jan 2016	0	0			Completed		Albury Workshop		
DrivLine \UNI JOINTS	yoke & seal		31 Dec 2015			completed		Completed		Myrtleford Workshop	TWIN CITY TRUCK CENTRE - 4 - OLD	
DrivLine \TAIL SHAFT	fit 2nd hand jack shaft		31 Dec 2015	569980		completed	completed	Completed		Myrtleford Workshop		
Susp \AIR LEAK	repair air leak		31 Dec 2015	569980		completed	completed	Completed		Myrtleford Workshop		
DrivLine \OIL LEAK	replace thru shaft yoke & s...		31 Dec 2015	569980		completed	completed	Completed		Myrtleford Workshop		
VehService \AS	Service As Per Attached Che... more		29 Dec 2015	569842		completed		Completed		Myrtleford Workshop		113 missed ▶
Brakes	Record Check Results As Att... more		29 Dec 2015	569842		completed		Completed		Myrtleford Workshop		
Elect \ELECT P&W	fit 2 new driving lights		24 Dec 2015	569548		completed	completed	Completed		Myrtleford Workshop		
Elect \ELECT P&W	led lamps mae		24 Dec 2015					Completed		Myrtleford Workshop	MYRTLEFORD AUTO ELECTRICS - 3	
Brakes \BRAKE ADJ	adjust brakes + grease		22 Dec 2015	569047		completed	completed	Completed		Myrtleford Workshop		
Susp \HCV	check ride height		22 Dec 2015	569047		completed	completed	Completed		Myrtleford Workshop		
Susp \SPRNG HANG	fit new rhf spring hanger		22 Dec 2015	569047		completed	completed	Completed		Myrtleford Workshop		
DrivLine \WHL HUB	fit 2nd hand hub to rhf drive		22 Dec 2015	569047		completed	completed	Completed		Myrtleford Workshop		
Body \MOUNTS	repair bullbar bolt		22 Dec 2015	569047		completed	completed	Completed		Myrtleford Workshop		
Tyres \TP02	Job Added From Invoice		17 Dec 2015	0	0			Completed		Albury Workshop		
Chassis \WHL HUB	10 styd hubs uni tr wreck		11 Dec 2015			completed		Completed		Myrtleford Workshop	UNIVERSAL TRUCK WRECKERS - 3	
Susp \SPRNG HANG	2 spring hangers+booster+pa... more		10 Dec 2015			completed		Completed		Albury Workshop	TWIN CITY TRUCK CENTRE - 4 - OLD	
Susp \SPRNG HANG	replace broken spring hange... more		10 Dec 2015	568350		completed	completed	Completed		Myrtleford Workshop		
Tyres \DAMAGE	check slow leak front tyre		10 Dec 2015	568350		completed	completed	Completed		Myrtleford Workshop		
Steering \PWR STEER	check power steeiring fluid... more		10 Dec 2015	568350		completed	completed	Completed		Myrtleford Workshop		
Susp \SPRNG HANG	tighten lhr u bolts		10 Dec 2015	568350		completed	completed	Completed		Myrtleford Workshop		
Brakes \BOOSTER	replace lhf drive brake boo... more		10 Dec 2015	568350		completed	completed	Completed		Myrtleford Workshop		
DrivLine \DIFF OIL	replace diff oils		10 Dec 2015	568350		completed	completed	Completed		Myrtleford Workshop		

Code\SubCode	Description	Completed By	Completed	DistanceDone	HourDone	Completion Comment	Manager Comment	State	WO#	Supplier	PoSuppliers	Missed
Chassis \CROSS MBR	replace crossmember & gusse... more		8 Dec 2015	568114		completed	completed	Completed		Myrtleford Workshop		
DrivLine \UNI JOINTS	replace worn front tail sha... more		5 Dec 2015	568114		completed	completed	Completed		Myrtleford Workshop		
Body \SUSPENSION	sway bar mount cmv		27 Nov 2015			completed		Completed		Albury Workshop	CMV TRUCK AND BUS PTY LTD - 3	
DriCabRep \DAMAGE	repair broken steering whee... more		25 Nov 2015	567495		completed	completed	Completed		Myrtleford Workshop		
Body \SUSPENSION	1 uhf 1 spring pack		21 Nov 2015			completed		Completed		Albury Workshop	TWIN CITY TRUCK CENTRE - 4 - OLD	
Chassis \CROSS MBR	1 cross member + bolts Uni... more		21 Nov 2015			completed		Completed		Albury Workshop	UNIVERSAL TRUCK WRECKERS - 4	
Tyres \TP08	Job Added From Invoice		21 Nov 2015	566752	0			Completed		Albury Workshop		
Tyres \TP08	Job Added From Invoice		21 Nov 2015	566752	0			Completed		Albury Workshop		
Tyres \TP08	Job Added From Invoice		21 Nov 2015	566752	0			Completed		Albury Workshop		
Chassis \SUSPENSION	fit new spring to rh rear ... more	Chris Mortimer	21 Nov 2015	567221		completed	completed	Completed		Myrtleford Workshop		
Susp \SUSPENSION	replace shocker lhm drive ... more		17 Nov 2015	566752		completed	completed	Completed		Albury Workshop		
Tyres \TP08	Job Added From Invoice		11 Nov 2015	0	0			Completed		Albury Workshop		
Susp \SHOCK ABS	2 drive shockers tctc		6 Nov 2015			completed		Completed		Myrtleford Workshop	TWIN CITY TRUCK CENTRE - 4 - OLD	
Tyres \TP01	Job Added From Invoice		27 Oct 2015	565232	0			Completed		Albury Workshop		
Tyres \TPS1	Job Added From Invoice		27 Oct 2015	0	0			Completed		Albury Workshop		
Tyres \TPS1	Job Added From Invoice		27 Oct 2015	565465	0			Completed		Albury Workshop		
Brakes \BRK O/HAUL	replace brake pressure switch		20 Oct 2015	568356		completed		Completed		Albury Workshop		
Susp \SHOCK ABS	repalce left rear shocker +... more		19 Oct 2015	565465		completed		Completed		Albury Workshop		
Body \MOUNTS	repair boom mounts		9 Oct 2015			completed		Completed		Myrtleford Workshop	RINLATECH ENGINEERING - 4	
VehService \BS	Job Added From Invoice		25 Sept 2015	0	0			Completed		Albury Workshop		
Susp \SUSPENSION	repair crack in a frame fi... more		23 Sept 2015	564632		completed	completed	Completed		Myrtleford Workshop		
Elect \ELECT P&W	fit lh middle side light		23 Sept 2015	564632		completed	completed	Completed		Myrtleford Workshop		
VehService \BS	Service As Per Attached Che... more		23 Sept 2015	564632		completed		Completed		Myrtleford Workshop		