EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	ManagerComment	DateDone	HourDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
P29	Wodonga - Workshop	Workshop|GRANGE	Operate forklift while Rapid remove boom cans.				10/08/2021		Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Wodonga Workshop	PRENTICE
P29	Tumut - Workshop	Chassis|HOUSEKEEP	prep and weld cracks in boom				01/09/2021	5533	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Tumut Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis|GRANGE	disassemble grab and all components, swap entire grab for v-P14 grab and build up from old P29 components replace all hoses (rubber rotor)				30/09/2021	9063	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|PUMP	replace triple pump				30/09/2021	9063	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|OIL/FILTER	top up hydraulic oil, clean down loader and bed. All good				30/09/2021	9063	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis|GRANGE	assist disassemble arc.assemble+etc.				30/09/2021	9063	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|GRANGE	check boom hand a.long		called out to bush, broken leg ram pin, replaced and greased	called out to bush, broken leg ram pin, replaced and greased	08/09/2021	9063	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis|GRANGE	hydraulic fitter assist				28/09/2021		Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|OIL/FILTER	hydraulic fitter assist remove and and inspect rods. been serviceable new rails in chock not correct				29/09/2021	9063	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DriCabReq|RADIO	start reinstallation. ran out of time				30/09/2021	5672	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DriCabReq|RADIO	finish re-installation and test out/adjustment mechanism				02/09/2021	5672	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Albury - Workshop	Engine|FILTERS	supply filters				28/09/2021		Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Albury Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis|TRL LEGS	RHR ram leg pin broken		replace RHR leg ram lower pin	replace RHR leg ram lower pin	17/09/2021	8714	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle|GEN	Service/Due				12/09/2021	8697	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Myrtleford - Workshop	Hydraulic|RAM	LHR leg ram leaking R12168. LHR leg ram leaking		replace LHR leg ram R11323	replace LHR leg ram	10/09/2021	8652	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Rosewood - Workshop	DriCabReq|WASTER WIP	turn on heater taps for loader				06/09/2021	8613	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis|HOUSEKEEP	grease loader and check over				27/09/2021	8576	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Body|WORKBENCH	clean up residule oil mess from earlier repairs now we have a foaming gun				27/09/2021	8576	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine|FILTERS	blew out outer air filter replace blown LHF leg ram hose replace nuve blown LHF leg ram hose clean up mess of the oil				27/09/2021	8576	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|HOSES	Make up & replace hydraulic Hoses				28/09/2021	8597	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|HOSES	Make up & replace hydraulic Hoses				28/09/2021	8597	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Myrtleford - Workshop	Hydraulic|OIL LEAK	oil/leak in grab still not fixed R&R 121911				16/02/2021		Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Rosewood - Workshop	Electr|WORK LIGHT	no lights on outer beam, strip wires Find fault cut off add new wire cable tie to hydraulic lines solder joints shrink tube				25/02/2021	8533	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Electr|WORK LIGHT	test lights all ok		R&R 122911 outer boom lights not working fit new light, straighten up hydraulic lines at buckle run new wire cable tie off check lights ok	R&R122911 outer boom lights not working fit new light, straighten up hydraulic lines at buckle run new wire cable tie off check lights ok	25/02/2021	8533	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Electr|WORK LIGHT	outer boom light not working				25/02/2021	8533	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|RAM	LHR leg ram leaking				25/02/2021	8533	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|OIL/FILTER	top up hydraulic fluid				25/02/2021	8533	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Tumut - Workshop	Vehicle|GEN	B Service travel from Wagga to meet Wayne to collect new grab motor and return to Rosewood to fit R&R grab motor major clean up	Vehicle|GEN			25/02/2021	8511	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Tumut Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|MOTOR	rotor motor check off. All about I was in Wagga when called to meet Wayne and get grab rotator motor met at Olympic Hwy fit new grab motor and test				19/02/2021	8511	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|MOTOR	clean up loader and truck				19/02/2021	8688	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle|WL	Serviced by Toppo safety light failing off	Vehicle|WL			19/02/2021	8688	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Tumut - Workshop	Electr|WORK LIGHT	static down as mounts in static have broken				19/02/2021	8607	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Tumut Workshop	PRENTICE
P29	Tumut - Workshop	Body|WORKBENCH	clean up grapple				19/02/2021	8644	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Tumut Workshop	PRENTICE
P29	Tumut - Workshop	Hydraulic|HYD LEAKS	check for oil leaks				19/02/2021	8644	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Tumut Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|HYD LEAKS	check grab oil leak, needs new rotator motor				12/02/2021	8219	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Tumut - Workshop	Electr|ALTERNATOR	remove pulley from old alternator				11/02/2021	8660	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Tumut Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|RAM	left rear leg ram leaking pin				29/01/2021		Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DriCabReq|RADIO	LHF not moving distant signal				29/01/2021		Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DriCabReq|SEAT	seat runners not required				29/01/2021		Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|HYD LEAKS	hydraulic leak out of controls under cabin				29/01/2021		Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|HYD LEAKS	check oil leak at LHR leg ram				28/01/2021	8301	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|RAM	needs exchange leg ram fitting				28/01/2021	8301	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|GRANGE	loader grapple pin coming out tag to hold it in broken. loader grapple pin coming out tag to hold it in broken		fix grapple pin tag weld up drill out broken bolt weld new one in place	fix grapple pin tag weld up drill out broken bolt weld new one in place	22/01/2021	8261	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|OIL/FILTER	low on hydraulic oil.take800 liters		top up oil tank	top up oil tank	22/01/2021	8261	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis|HOUSEKEEP	prepare and weld grapple				22/01/2021		Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Electr|WORK LIGHT	outer boom lights not working		broken wire find fault solder joint wrap use tie-up	broken wire find fault solder joint wrap use tie-up	21/01/2021		Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|RADIO	oil/leak in grab still not fixed grapple pin rag broken off pin came out refit pin bolt broken off in head holding				21/01/2021		Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis|GRANGE	prep and weld bolt prep and weld tag on				19/01/2021		Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis|GRANGE	R&R 121806 outer boom lights not working strip wiring loom back find faults moulder tape up loom cable tie				19/01/2021		Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Electr|WORK LIGHT	called out to Wanagh, belt thrown again				19/01/2021		Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine|BOOST HOSE	suzanne belt in stuck. removed old belt.debris and and it to fold as. back to Workshop further check of stock revealed no belt. t ordered more stock and requested shorter belt as per fetch pod ordered to prevent slippage and heating/breaking				20/01/2021	8251	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine|BOOST HOSE	travel to and home				20/01/2021	8251	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Electr|WORK LIGHT	outer boom lights not working				19/01/2021		Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|MOTOR	oil/leak in grab still not fixed				19/01/2021		Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle|WL	Service/Due	Vehicle|WL	B Service	B Service	19/01/2021	8237	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis|HOSES LEAKS	LHR rear leg pin		called out to Wanagh, broken LH rear leg ram pin	called out to Wanagh, broken LH rear leg ram pin	14/01/2021	8203	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Electr|WORK LIGHT	diagnose and repair shorts/ suspect shorts (multiple) in boom light wiring prepare cracks in grapple for welding				13/01/2021	8193	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis|HOUSEKEEP	grease and thorough check over				08/01/2021	8173	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis|HOUSEKEEP	reduce overall stroke on loader				31/12/2020	8123	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine|FAULT CODE	engine light on found water in fuel code, found wiring unplugged and separator		broken bolt in ram on grapple call out to bush breakdown turn pin refit pin fitted new bolt grease check ok	broken bolt in ram on grapple call out to bush breakdown turn pin refit pin fitted new bolt grease check ok	31/12/2020	8123	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis|HYDRAULICS	broken bolt pin grapple				30/12/2020	8118	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Electr|WORK LIGHT	lights flashing on and off				11/12/2020	8023	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Tumut - Workshop	DriCabReq|SEAT PREW	broken wires in boom on digger arm				11/12/2020		Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Tumut Workshop	PRENTICE
P29	Myrtleford - Workshop	Hydraulic|RAM	check hydraulic leak,going over airbags deck and tyres				30/12/2020	7600	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|OIL LEAK	diagnose oil leak and tighten to be monitored check grab leak. Rotator suspect tighten hoses				02/12/2020	7563	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|OIL LEAK	steerear and clean up				02/12/2020	7563	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|OIL/FILTER	check hydraulic oil level				02/12/2020	7563	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Myrtleford - Workshop	Engine|FAULT CODE	check engine open set to high				01/12/2020	7916	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Engine|FAULT CODE	engine light coming on. Spoke to Wayne they need cummins		low coolant code sensor very high in header tank		24/11/2020	7855	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle|WL	B Service and jobs R10359/R10425	Vehicle|WL			21/11/2020	7851	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine|BELTS/TENS	call out broken fan belt		called out to Rosewood	called out to Rosewood	20/11/2020	7845	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis|GRANGE	broken RHS rear leg pin		broken main drive belt. Replaced and checked	broken main drive belt. Replaced and checked	20/11/2020	7845	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DriCabReq|INSTSAUGE	no light in gauges in loader		found broken LHR lower leg pin and replaced	found broken LHR lower leg pin and replaced	20/11/2020	7817	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle|WL	Service/Due	Vehicle|WL			18/11/2020	7817	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle|WL	loader service 217 hr overdue check engine for oil coming on	Vehicle|WL			18/11/2020	7817	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine|FAULT CODE	toowet ua coolant no obvious leaks				17/11/2020	7737	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine|CODES LEAKS	flashed codes out. was a low coolant code set				12/11/2020	7737	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|RAM	replace rh main lift ram. Old one leaking around the bottom mounting point				07/11/2020	7707	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|OIL/FILTER	top up hydraulic oil				03/11/2020		Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|OIL/FILTER	top up hydraulic oil		top up hydraulic oil		02/11/2020	7698	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis|GRANGE	weld grapple		top broken off grapple R&R prepare cut ubolts to suit weld ubolt to tie	top broken off grapple R&R prepare cut ubolts to suit weld ubolt to tie	22/10/2020	7524	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DriCabReq|INSTSAUGE	no light in gauges in loader				16/10/2020		Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DriCabReq|SEAT PREW	repair suspension dash lights				16/10/2020		Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle|WL	Service/Due	Vehicle|WL			16/10/2020		Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle|WL	B Service	Vehicle|WL			14/10/2020	7415	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine|FAULT CODE	engine light coming on. Spoke to Wayne they need cummins				29/09/2020	7271	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle|WL	B Service loader reabsorb air filters ibuchi	Vehicle|WL			29/09/2020	7271	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Rosewood Workshop	PRENTICE
P29	Myrtleford - Workshop	Electr|WORK LIGHT	check lights on end of boom they have been chorting/would not play up for me				28/09/2020	7207	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Hydraulic|LEAKS	check hydraulic pressure on grab				12/09/2020	7116	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Unknown|TOWING	check hydraulic pressure on slide boom				12/09/2020	7116	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Hydraulic|HYD LEAKS	fit seal kit to grab swivel				12/09/2020	7116	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Unknown|GRANGE	make up new grab link from grab to boom				12/09/2020	7116	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Engine|BELTS/TENS	tighten a/c belt				11/09/2020	7116	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Engine|HOSES|BOOST	top up coolant				11/09/2020	7116	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Chassis|HOUSEKEEP	fill grease nipples to big pins - grease loader legs				05/09/2020	7116	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Engine|HOSES|BOOST	top up coolant and check hoses				05/09/2020	7116	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Engine|VEHICLE	fit new cap to exhaust				05/09/2020	7116	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	DriCabReq|INSTSAUGE	check horn and washer#7727				05/09/2020	7116	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Hydraulic|HYD LEAKS	fit grab hose swivel kit				05/09/2020	7116	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Chassis|GRANGE	fit new link between outer boom and grab				05/09/2020	7116	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Body|CANOPY/BOOT	wash loader				05/09/2020	7116	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Instg|WINDSCR	fit fire ext and bracket				05/09/2020	7116	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	DriCabReq|INSTSAUGE	check dash bulbs washer bottle cap fit washer jet				05/09/2020	7116	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	DriCabReq|WIPERS	fit wiper blades				05/09/2020	7116	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Electr|WORK LIGHT	fit new work light				05/09/2020	7116	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Electr|SELECT PREW	fit air warning horn				05/09/2020	7116	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Body|WORKBENCH	slew linkage				22/08/2020	7115	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Body|PANELS	side cover laser engine cover ~replace allbolts/washers on engine covers				22/08/2020	7115	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Body|PANELS	~redo rear engine door				22/08/2020	7110	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Hydraulic|HYD LEAKS	bad oil/leak from oil cooler needs repair ASAP		replace o-ringing on cooler pipes (Cummins)		22/08/2020		Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Chassis|HOUSEKEEP	points on grab are to sharp		never ooder mounts		22/08/2020		Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Hydraulic|HOSES	Make up & replace hydraulic Hoses				22/08/2020	7110	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Hydraulic|OIL/FILTER	Change Hydraulic Oil and Filters		fit seal kit to grab swivel	fit seal kit to grab swivel	22/08/2020	7114	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Engine|PRO RIBLD	Fit New Engine Hoses and Belts and Engine Mounts RR936				19/08/2020	7114	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Cooling|RADIATOR	Clean Out Radiator				19/08/2020	7114	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Hydraulic|HYD LEAKS	Repair Hydraulic Oil Cooler Leaks RR939				19/08/2020	7114	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Body|WINDSHIELD	Repair Hydraulic Oil Cooler Mounts				19/08/2020	7114	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LN9855	Myrtleford Workshop	PRENTICE
P29	Albury - Workshop	Elec|BATTERY	refit loader battery help Dan from Cummins dro blow by test and diagnose engine unserviceable				11/08/2020		Repair	Completed	GreenFreight Logging NSW

P29	Rosewood - Workshop	Elec\TJDRIE LIGHT	boom lights going out					01/03/2020 6093	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Chassis\HYDRAULICS	RHS back leg pin broken		fully grease & check over		fully grease & check over	01/03/2020 6093	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Chassis\HOUSEKEEP	points on grab are to sharp		replace missing grease nipples on both front leg pivots			01/03/2020 6093	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Chassis\HOUSEKEEP	need grease nipples in front legs					01/03/2020 6093	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Hydraulics\CDL LEAK	oilmark up in grab rotator? letting oil over windscreen very dangerous					01/03/2020 6093	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Engine\FILTERS	remove and blow out outer air filter					01/03/2020 6093	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Vehicle\ute\JBL	Service+overhaul	VehServ\ute\JBL	B Service		B Service	01/03/2020 6093	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Hydraulics\DRAGGE	rear RHS ram pin oiling broken		change broken lug ram pin		change broken lug ram pin	01/03/2020 6976	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Tumut - Workshop	Elec\BATTERY	remove and replace battery					21/03/2020 6275	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Tumut Workshop		PRENTICE	
P29	Tumut - Workshop	Elec\SPARE\SEDWIN	pick up in Tumut ticket to Rosewood fit batteries					22/03/2020 6275	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Tumut Workshop		PRENTICE	
					call out to rigging waters, loader not starting voltage was 12.6v at rest. Cracked but not start hooked up jumper leads and loader started charging at 14 volts discussed with MitchfromCummins, due to slow speed fuel solenoid wont open. Will organise new battery		call out to rigging waters, loader not starting voltage was 12.6v at rest. Cracked but not start hooked up jumper leads and loader started charging at 14 volts discussed with MitchfromCummins, due to slow speed fuel solenoid wont open. Will organise new battery									
P29	Rosewood - Workshop	Elec\SPARE\SEDWIN	loader wouldn't start call Gordo out to rippo		reserve fuel transfer asme temporarily while out there		reserve fuel transfer asme temporarily while out there	21/03/2020	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Chassis\HOUSEKEEP	check over					19/03/2020 6245	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Elec\TJDRIE LIGHT	diagnose and repair short in boom light wiring at fly boom pivot area					19/03/2020 6245	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Chassis\HYDRAULICS	replace missing hydraulic pipe keeper and repair another Broken Bolt On Grab Rails Pin					19/03/2020 6245	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Chassis\HOUSEKEEP	Replace No Pins Missing - VIDEO					19/03/2020 6245	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Chassis\HOUSEKEEP	grease loader check over loader blow air filter out					31/03/2020 6190	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Engine\HOUSEKEEP	B Service					30/03/2020 6190	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Vehicle\ute\JBL	Service+overhaul	VehServ\ute\JBL				29/03/2020 6193	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Body\WELD\NTS	light bracket broken on boom - needs replacing		straighten work light bracket and weld back on boom		straighten work light bracket and weld back on boom	31/03/2020 6102	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Elec\SPARE\SEDWIN	called out to Rigging waters all booms and top light not working tracked power failure to blown fuse at battery i had an auto re-set circuit breaker of my own in my vehicle, i installed this and observed loader operating for a short while, no more trouble					27/03/2020 6093	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Elec\TJDRIE LIGHT	sealants dandfit operator Hobie. no antidemo		replace leaking hydraulic hose to bottom of RHSfit ram on main boom		replace leaking hydraulic hose to bottom of RHSfit ram on main boom	28/03/2020 6093	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Hydraulics\HYD LEAKS	leaking hose on right hand lift cylinder short hose Semorloop up fluids grease	VehServ\ute\JBL	Bluddrit new hose to be made to hydraulic		Bluddrit new hose to be made to hydraulic	28/03/2020 6093	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Tumut - Workshop	Vehicle\ute\JBL	inspect	VehServ\ute\JBL				07/03/2020 5964	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Tumut Workshop		PRENTICE	
P29	Myrtleford - Workshop	Body\PINTACTORS	Fit tipe to loader					19/02/2020 5791	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Workshop\SMOVE ASSIST	take to Hindmish and pick up also					13/02/2020 5782	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Hydraulics\VALVES	Remove main spool bank and fit a complete seal kit and test					13/02/2020 5782	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Hydraulics\HYD LEAKS	inspect hyd oil leaks under cab					06/02/2020 5782	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Hydraulics\VALVES	Fit ends to valve bhe spool					06/02/2020 5782	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Hydraulics\HYD LEAKS	Tidy up all hydraulic hose leaks and clew valve leaks					29/02/2020 218217	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Chassis\HOUSEKEEP	UHF radio doesn't					26/02/2020 5773	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Hydraulics\PUMP	fuel leak at pump (servo)					26/02/2020 5773	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Vehicle\ute\JBL	Service+Over	VehServ\ute\JBL				26/02/2020 5773	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Dirt\ARep\GROUNDS	RH servo needs new bolts		bolts in L RH servo		bolts in L RH servo	24/02/2020 5773	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Dirt\ARep\SWEEPERS	short circuit in wiper wiring		check loader wiper motor wire wirma			26/02/2020 5773	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Engine\CDL LEAK	wash down servo pump and repair hyd servo pump leak					26/02/2020 5773	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Dirt\ARep\CAB\LIGHTS&USB	replace all dash lights wash swivel pump					26/02/2020 5773	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Hydraulics\PUMP	fit radial to bel swivel valve					28/02/2020 5773	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Vehicle\ute\JBL	Service As Per Attached Checklist diagnosed and washed oil. loaded area in Turret.	VehServ\ute\JBL	replaced 1x mud flap			24/02/2020 5773	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Albury - Workshop	Engine\CDL LEAK	filled hyd dusk reservoir. Worked machine to diagnose leaks found motor leak at skid centre housing couldn't see rotation could in Turret to leak					29/03/2020	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Albury Workshop		PRENTICE	
P29	Rosewood - Workshop	Chassis\HOUSEKEEP	grease and check over					18/03/2020 5732	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Dirt\ARep\HOUSEKEEP	make dash panel bolts/brackets					18/03/2020 5732	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Dirt\ARep\ELEVECT P&W	fit new electromagnetic solenoid to pilot system					18/03/2020 5727	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Dirt\ARep\ELEVECT P&W	insert hydraulic bush to set up					18/03/2020 5727	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Hydraulics\CDL/TILTER	top up oil (hydraulic)					18/03/2020 5727	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Hydraulics\HYD LEAKS	clean under loader and around fittings					18/03/2020 5727	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Workshop\SMOVE ASSIST	thorough 'dot' run, all good					18/03/2020 5727	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Dirt\ARep\ELEVECT P&W	lost electric valve on hydraulics		intermittent low oil pysiticks repaired several wiring faults near foot controls, still playing up. Found burned out electric solenoid on control circuit.			18/03/2020 5722	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Dirt\ARep\ELEVECT P&W	replace hyd solenoid		discussed with Kev in Albury and made temporary bypass to system			18/03/2020 5722	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Hydraulics\BREAKDOWN	called out at 19:00 to Tuffels. Blown plug out of joystick. returned to Rosewood after "patching it up"		hooked to vent. awaken.wood. Should vern Vaucha			18/03/2020 5722	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Hydraulics\HYD LEAKS	tasked thehydrolink houses and fitted at down belt cassier washer					18/03/2020 5722	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Hydraulics\HYD LEAKS	several leaks starting to appear, grounded loader until permanent repairs can be carried out					16/03/2020 5722	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Hydraulics\HYD LEAKS	called back out on way home to bush sight oil leak and some noise					16/03/2020 5722	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Hydraulics\BREAKDOWN	call out to loader blown main hose under loader		replacement hose slightly to short fitted longer hose for temp repair ordered correct hose plus a spare			23/12/2019	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Hydraulics\HOSES	replace main hose from earlier breakdown to correct length hose		top up oil 5 litres			23/12/2019	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Chassis\HOUSEKEEP	clean down loader check over and grease					23/12/2019	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Elec\TJDRIE LIGHT	LHS load light needs tightening under step					17/12/2019 5651	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Body\WELD\NTS	tidy up weld jobs					06/12/2019	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Body\WELD\NTS	hydraulic oil cooler mount's are broken and needs welding					23/12/2019 5551	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Myrtleford - Workshop	Engine\GRADUST	cut down exhaust and fit rain cap					03/12/2019 5551	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Elec\TJDRIE LIGHT	blocker light not working		completed reear sort in wirma for slobe lehti in cab			29/11/2019 5551	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Dirt\ARep\CAB\LIGHTS&USB	Control panel in cab not unserted at bottom		completed found support stands jacked up removed bracket sent for repair removed replacinf eng mount rubber got bracket back refitted redrawbelt,all good reabsed other 5 rear mount rubbers			29/11/2019 5551	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Engine\MOUNTS	Engine mount brackets cracked					29/11/2019 5551	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Engine\ABOUT HOSE	Hose broken from hose bracket into timing cover		blew down around bracket reinserted found bolts are broken back inside timing case need to removed bracket			29/11/2019 5551	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Hydraulics\CDL LEAK	Various hydraulic leaks		bolt P-29 for hyd leaks ok			29/11/2019 5551	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Engine\ENGINE	Engine is blowing shaft seal		welded in rotund shaft			29/11/2019 5551	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Body\CHASSIS	Cab cracked		welded in chassis cracks			29/11/2019 5551	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Chassis\CHASSCRACK	Chassis cracked at hydraulic tank		replaced hydraulic tank mount bolts			29/11/2019 5551	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Body\CRANAGE	Jimmy gun holder damaged					29/11/2019 5551	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Body\TRI LEGS	Leg pins loose in bass					29/11/2019 5551	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Engine\STARTMOTR	Starter motor required		checked and is ok			29/11/2019 5551	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Engine\FUEL TANK	Diesel leak at secondary filter to pump		test run eng and check for leaks			29/11/2019 5551	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Engine\COOLSCAMS	Coolant leak to bottom heater tap hose clamp		turn tap on expected for leaks, tighten hose clamp no leaks found			28/11/2019 5551	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Body\PINT CORP	rear oversize flag been hit with fag ripped and holders bent and cracked		WO check its been repaired and not signed off		WO check its been repaired and not signed off	29/11/2019 5551	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Hydraulics\HYD LEAKS	oilleak in grab		test hyd grab leak ok		test hyd grab leak ok	29/11/2019 5551	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Body\PANELS	no door on loader motor very loud					29/11/2019 5551	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Elec\TJDRIE LIGHT	boom lights LHS not working		repaired bent light bracket		repaired bent light bracket	29/11/2019 5551	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Vehicle\ute\JBL	B Service As Per Attached Checklist	VehServ\ute\JBL	drained rest of hyd oil cleaned and replaced servo filter refitted with new oil fattten tank mount bolts			29/11/2019 5551	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Hydraulics\RAM	fit RHF and LHF leg ram seal kits					26/11/2019	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Chassis\HOUSEKEEP	replace all 4 leg foot pins and fit bosc to leg foot					26/11/2019	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Body\PANELS	replace arm nuts					13/11/2019 5500	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Body\PAINT/RUST	paint rear engine cover					13/11/2019 5500	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Body\PANELS	replaced front engine bay door handles					13/11/2019 5500	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Body\CRANAGE	repair or fit RHS guards					13/11/2019 5500	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Chassis\CRANAGE	repair front grab stand					11/11/2019 5500	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Chassis\CRANAGE	make up new grab support bar					13/11/2019 5500	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Chassis\CRANAGE	make up new grab stand					13/11/2019 5500	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Dirt\ARep\DOOR LOCK	Fit drop locks to front engine cover					13/11/2019 5500	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Body\MOUNTS	make up grease gun holder					13/11/2019 5500	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Chassis\CRANAGE	replace pins and bushes on all 4 leg feet					11/11/2019 5500	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Hydraulics\VALVES	adjust grab pressures					13/11/2019 5500	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Chassis\CRANAGE	repair cracks in grab					11/11/2019 5500	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Dirt\ARep\GENS COVER	Rear engine door missing					08/11/2019 5549	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Body\PANELS	Fabricate Engine Cover					18/10/2019 5549	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Hydraulics\RAM	Rebuild Grab Ram					11/10/2019	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Rosewood - Workshop	Elec\TJDRIE LIGHT	boom lights LHS not working					06/10/2019 5484	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Engine\BREAKDOWN	CALL OUT TO BUSH LOADER BLOWN HOSE ENGINE AREA					02/10/2019 5651	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Engine\ABOUT HOSE	REMOVED HOSE PLUS ANOTHER?? MACHEEN RUNNING OK ,COME BACK TO WORK SHOP & WATCH UP! (TOOK A HOSE BUT I WAS GIVN WRONG INFO ON WHICH ONE WAS BLOWN)					02/10/2019 5651	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Workshop\SMOVE ASSIST	TRANS BACK TO WORKSHOP WITH HOSE & PIT ,ADD OILTO OIL					02/10/2019 5651	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Body\WELD\SHEEP	Stop for Un-side of loader					20/09/2019	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Hydraulics\HYD LEAKS	clew motor seal leaking					20/09/2019	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Myrtleford - Workshop	Dirt\ARep\CAB\LIGHTS&USB	amp gauge flickering up and down					20/09/2019	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Body\MOUNTS	WORK LIGHT ON RHSDR MOUNT BENT					20/09/2019	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Hydraulics\CDL LEAK	oilleak on rotor motor on grab somewhere					20/09/2019	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Hydraulics\HYD LEAKS	RHS rear lift ram leaking					20/09/2019	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Chassis\CHASSCRACK	paint broken on double					20/09/2019	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Dirt\ARep\DOOR LOCK	latch on door					20/09/2019	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Myrtleford - Workshop	Body\SPARGE	rip on grab missing					20/09/2019	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Myrtleford Workshop		PRENTICE	
P29	Rosewood - Workshop	Chassis\CHASSCRACK	deck cracked LHS					20/09/2019	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Engine\CDL LEAK	oilleak front of motor					20/09/2019	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Hydraulics\HYD LEAKS	hydraulic leak above clew motor					17/09/2019	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Body\PINTACTORS	grease tipe pin coming out					16/09/2019	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Hydraulics\RAM	grab ram leaking					16/09/2019	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Chassis\CHASSCRACK	LHS deck cracked					16/09/2019	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Hydraulics\HYD LEAKS	clew valve leaking					16/09/2019	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood - Workshop	Hydraulics\MOTOR	new hinge pins for door on motor					16/09/2019	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUS	LNSW01	Rosewood Workshop		PRENTICE	
P29	Rosewood

P29	Albury - Workshop	Engine|MEDIATOR	need thermostat motor running, cold					16/07/2019 4648	Fault	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Rosewood - Workshop	Body|HOUSEKEEP	De-grease dew & control valve					30/06/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|RAM	Weld cracks in grab		"Note" Grab has excessive cracks, possible replacement required soon			02/06/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle|JBS	8 Service Loader	VehicleLoad|JBS	removed old bolts from door hinge	removed old bolts from door hinge		30/06/2019	Service	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
					replaced with larger bolts	replaced with larger bolts											
					replaced door latch striker pin	replaced door latch striker pin											
P29	Albury - Workshop	DrivCab|Reg|DOOR LOCK	alana out 8:30 am		removed and replaced lower bracket on	removed and replaced lower bar spout on		07/06/2019 4354	Fault	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Hydraulic|OIL FILTER	Hydraulic oil filter 10 micron 1000cc					07/06/2019 4354	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
			loose hose engine rpm rises														
P29	Albury - Workshop	Body|MOUNTS	[illegible]														
			repaired fuel oil leaks on boom														
			replaced 2 fuel hoses at outer boom knuckle														
			replaced o-rings in fittings on boom														
P29	Albury - Workshop	Hydraulic|HYD LEAKS	replaced rotorua valve clamps					17/05/2019 4222	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Engine|HOUSEKEEP	degreased and washed					17/05/2019 4222	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Workshop|CLEAN	cleaned up after job					17/05/2019 4222	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	DrivCab|Ref|HEATER REP	check heater unit					17/05/2019 4222	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Engine|COOLLEAKS	coolant leak - replaced bottom heater tap					16/05/2019 4215	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
			topped up engine oil - 4 liters														
			topped up coolant														
			diagnosed and washed engine														
P29	Albury - Workshop	Engine|HOUSEKEEP	surveed started motor					16/05/2019 4215	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Workshop|CLEAN	cleaned up mess after job from coolant leak					16/05/2019 4215	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Engine|HEATER TAP	heater tap					16/05/2019 4215	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Elec|START MOTR	starter motor (solenoid playing up)					16/05/2019 4215	Fault	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Hydraulic|HYD LEAKS	hydraulic oil leak on top of main boom					16/05/2019 4215	Fault	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Elec|WORK LIGHT	front work lights missing					16/05/2019 4215	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
			removed and serviced - Picked up new parts at Arkaro														
P29	Albury - Workshop	Elec|START MOTR	replaced solenoid					12/05/2019 41864	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
			travel to and from work (do off Monday Rd														
			Removed broken bolts at front of engine														
			turned off heater taps and tightened clamps														
			filled radiator														
P29	Albury - Workshop	Engine|HEATER TAP	[illegible]					11/05/2019 4189	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
			removed leaking fuel line- secondary filter to injection pump made new line														
P29	Albury - Workshop	Engine|FUEL TANK	fitted, bled and tested					11/05/2019 4189	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
			diagnosed faulty started motor solenoid														
P29	Albury - Workshop	Elec|START MOTR	trained exercitor to start with lumo wire					11/05/2019 4189	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Engine|START MOTR	Starter motor required					10/05/2019 4178	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Hydraulic|OIL LEAK	Repaired hydraulic leaks at slew motor		Diagnosed & washed slew motor			10/05/2019 4178	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Hydraulic|OIL LEAK	Various hydraulic leaks					10/05/2019 4178	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Hydraulic|OIL LEAK	Slew motor leaking shaft seal					10/05/2019 4178	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Elec|WORK LIGHT	Strobe light not working					10/05/2019 4178	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Drivcab|Ref|TAILGATE	Control panel scale not returned at bottom					10/05/2019 4178	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Engine|MOUNTS	Engine mount brackets cracked					10/05/2019 4178	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Body|DRAWBAR	Drawbar bent					10/05/2019 4178	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Chassis|CHASSIS RACK	Chassis cracked at hydraulic tank					10/05/2019 4178	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
			Rear engine door missing														
P29	Albury - Workshop	DrivCab|Reg|FIRE COVER	Front motor door latch mounted					10/05/2019 4178	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Body|DRAWBAR	Simon gun holder damaged					10/05/2019 4178	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Body|TRLERS	Leg pins loose in boss					10/05/2019 4178	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Vehicle|JBS	8 Service as per attached checklist	VehicleLoad|JBS				10/05/2019 4178	Service	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Engine|FUEL TANK	Diesel leak at secondary filter to pump					10/05/2019 4178	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Engine|COOLLEAKS	Coolant leak to bottom heater tap hose clamp					10/05/2019 4178	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Engine|WEIDEMANN	Bolts broken boost hose bracket into timing cover					10/05/2019 4178	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
			strike pin door latch loader														
P29	Albury - Workshop	DrivCab|Reg|DOOR LOCK	attorney-in-exam off the short					02/05/2019 4130	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
			bolts broken outer boom pins														
P29	Albury - Workshop	Body|RADIO	steel size outer boom bracket					02/05/2019 4130	Fault	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
			rear lag back grease nipple missing														
P29	Albury - Workshop	DrivCab|Reg|DRAWBAR	NAS outer boom retainer					02/05/2019 4130	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Rosewood - Workshop	Engine|OIL LEAK	slew motor leaking oil going on airbags					30/04/2019 4105	Fault	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle|JBS	Service Due	VehicleLoad|JBS				30/04/2019 4105	Service	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DrivCab|Reg|RADIO	UHF beep getting static					26/04/2019 4068	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Elec|SECT PWM	boom light missing					26/04/2019 4068	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle|JBS	Service Due 300hrs	VehicleLoad|JBS				26/04/2019 4068	Service	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Albury - Workshop	DrivCab|Ref|AIR CON	diagnose heater fan not operating. Burning smell in cab		diagnose heater fan not operating. Burning smell in cab			17/04/2019 4052	Fault	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
			disconnected heater assembly, found debris in fan, broken blades														
P29	Albury - Workshop	Drivcab|Ref|SECT PWM	[illegible]					17/04/2019 4052	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
			diagnose and repair wiring and switch's														
P29	Albury - Workshop	DrivCab|Ref|SECT PWM	test allowed					17/04/2019 4052	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Rosewood - Workshop	Engine|OIL LEAK	oilleak on slew motor hose fittings					09/04/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine|HEATER TAP	heater tap new to oil filter leaking (replace)					09/04/2019	Fault	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Body|HOSES	change short hose between 85 cylinders					09/04/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DrivCab|Ref|SCALES	check wire loom for scales, Scales not working no numbers on screen					09/04/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DrivCab|Reg|RADIO	external speaker for UHF in loader					09/04/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine|HEATER TAP	replace both heater taps					04/04/2019 3938	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DrivCab|Reg|HOUSEKEEP	grease loader weld mar lag pin					04/04/2019 3938	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle|JBS	carry out 8 Service	VehicleLoad|JBS				04/04/2019 3938	Service	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle|JBS	Service Due	VehicleLoad|JBS				04/04/2019 3938	Service	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Elec|WORK LIGHT	no work light on outer boom right side					27/03/2019	Fault	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
			adjusted alternator belts														
			and checked over														
P29	Albury - Workshop	Engine|AUT	loosed up hub and oiled checked for leaks					21/03/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Body|HOUSEKEEP	diagnosed and washed					20/03/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
			replaced rotorua coupling on grapple														
			repaired and bled scale lock														
P29	Albury - Workshop	Hydraulic|VALVES	Hydraulic oil leak at valve section					19/03/2019 3827	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Rosewood - Workshop	Elec|WORK LIGHT	remove damaged boom light, none in stock, re-order					14/03/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|RAM	replace outer boom ram					14/03/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Albury - Workshop	Hydraulic|AIR FITTIN	changed piping and fittings on cylinder					01/03/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Engine|BELTS/TENS	REPLACE FAN BELT					01/03/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
			XB 117656														
			fit new hydraulic tank bolts tighten														
			weld cracks in tank legs														
P29	Rosewood - Workshop	Hydraulic|DRAWBAR	weld retainna bolt in adace rear lea					27/02/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|RAM	RIGHT REAR LEG RAM LEAKING					27/02/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Air Con|AIR CON	BELTS FOR AIR CON SLIPPING					27/02/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Albury - Workshop	Workshop|MOVE ASSET	pick up parts from TOTC					26/02/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
					DIAGNOSE SLIPPING BELT WHEN A/C ON, WAS ACTUALLY THE MAIN BELT THE A/C RUNS OFF OF.												
					REMOVE + INSPECT WATER PUMP. ALL GOOD.												
					CONNECT BELT. (SAME AS ONE FITTED) WAS TO LONG AND WOULDN'T GRIP PROPERLY												
					TRIED SEVED DTTM BELTS, NO GOOD												
					NOW IS SENDING LUNDSONS BELT. SAME AS ABOVE ONE USUALLY ONE OF THEM TOGETHER												
P29	Rosewood - Workshop	Air Con|AIR CON	Air Conditioning		CLEAN CONDENSER AND REMOVE FROM THOROUGHLY			25/02/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine|HOUSEKEEP	Housekeeping		0 MOUSE HOUSE PLASTIC, OK			22/02/2019 3685	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine|BELT PULL	Idler Pulley					22/02/2019 3685	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle|JBS	8000hr remove drum in 10hrs	VehicleLoad|JBS	8 SERVICE COMPLETED	8 SERVICE COMPLETED		22/02/2019 3685	Service	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Albury - Workshop	Air Con|AIR CON	AC NOT WORKING					08/02/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
			called out to loader at Tumut yard, broken fan belt														
			came via Rosewood to get belt if in stock, none available														
			removed belts from P26 and fitted to P29														
			coolant level on P29 sub low, and upon filling I noticed a bad leak														
			bottom radiator hose was split, possibly from excess pressure and had when belt broke														
			I took loan from P26 and fitted to P29, filled with coolant and tested														
			returned loaner from call up														
P29	Rosewood - Workshop	Cooling|RADIATOR	Found 2 broken bolts in the slew motor. Replace broken bolts an re-tighten bolts					28/01/2019	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|MOTOR	found 2 broken bolts in the slew motor. Replace broken bolts an re-tighten bolts	VehicleLoad|JBS				11/01/2019 3620	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle|JBS	Service Due	VehicleLoad|JBS				10/01/2019 3608	Service	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Air Con|AIR CON	assco in loader not working		set up - pack up for sublet a/c repairs	set up - pack up for sublet a/c repairs		09/01/2019 3357	Fault	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine|BELTS/TENS	retension a/c belts tecked ok					28/12/2018 3623	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Albury - Workshop	Engine|FUEL TANK	identify fuel line for ordering		Cummins went and repaired fuel issues			20/12/2018	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
			fan noisy in cab. Disassembled and "padded" vibrating panels. Fitted missing screws in cover														
			- checked slew operation. Appears ok														
P29	Rosewood - Workshop	Engine|ENG FAN	- check grease law to slew for sleeveuse association ok					18/12/2018 3527	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|HOSES	grapple hose		replace grab hose	replace grab hose		31/12/2018 3516	Fault	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|HOSES	replace grapple hose damaged by log strike					31/12/2018	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|RAM	change fittings in the outer boom ram and replace with new o'rings fit up second hand ram tested all functions to make sure then boom didn't over extend tested ok					31/12/2018 3254	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Albury - Workshop	Engine	cab dubbed from invoice					08/12/2018 0	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
					remove cam eye bearing on fly boom												
					replace exhaust cam cap												
					replace worn a/c and main belt												
					0/3/18 Replace cam eye bearing grease bearing take loader to the top of the yard function loader and re-												
P29	Rosewood - Workshop	Hydraulic|HYD LEAKS	bearing in outer boom cam rod end slew leaking		grease bearing tecked ok			06/12/2018 3230	Fault	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle|JBS	Service Due	VehicleLoad|JBS				06/12/2018 3230	Service	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Elec|BATTERY	Battery		replaced battery			13/11/2018 3082	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|VALVES	check slew fittings					13/11/2018 3082	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Albury - Workshop	Vehicle|JBS	8 SERVICE	VehicleLoad|JBS				11/11/2018	Service	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Albury - Workshop	Elec|BATTERY	SUPPLY BATTERY TO ROSEWOOD TO FIT.					10/11/2018	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Wodonga - Workshop	Engine|OIL LEAK	oilleak slew block fittings					10/11/2018	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Wodonga Workshop	PRENTICE
P29	Wodonga - Workshop	Elec|BATTERY	Battery					10/11/2018	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Wodonga Workshop	PRENTICE
P29	Rosewood - Workshop	Workshop|JBS	8 Service		8 service completed			09/11/2018 2993	Service	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
					replace blower slew, hydraulic line replace hose, re-fill hydraulic tank 160lts tested ok												
P29	Rosewood - Workshop	Hydraulic|HOSES	Hoses		replace 2x hydraulic hose in the middle of boom			06/11/2018 2993	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Body|WASH	Truck or Trailer wash		wash down deck of loader			06/11/2018 2993	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
					check all light plug tested ok												
P29	Rosewood - Workshop	Elec|WORK LIGHT	chorting out all blown lights					01/11/2018 2955	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Elec|WORK LIGHT	lights on boom and scale not working		check for any rubbed wires users us wireless replacement out ride and found where wires have been rubbin	check for any rubbed wires open up wire box replace burnt out rely and found where wires have been rubbing and possible chorting out		27/10/2018 2933	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Body|DRAWBAR	re-weld new tips on grab					27/10/2018 2933	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DrivCab|Reg|FIRE COVER	repair engine cover					12/10/2018	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine|DRAWBAR	repair dipstick fitting					29/10/2018	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
					no work lights on boom	no work lights on boom											
P29	Rosewood - Workshop	Elec|WORK LIGHT	boom lights not working		tested and check relay's and fuses in the pannel box tested ok track wire back to a fuse holder check fuse	tested and check relay's and fuses in the pannel box tested ok track wire back to a fuse holder check fuse and box 30amp blown replace		18/10/2018 2865	Fault	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Body|DRAWBAR	tip on grab broken off		and box 30amp blown replace fuse tected ok	fuse tected ok		18/10/2018 2865	Fault	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
			oilleak possibly from seal motor		re-weld new tips on grab	re-weld new tips on grab											
			engine cover keeps falling off very bad														
			oilleak under cab slew control area														
P29	Rosewood - Workshop	Surg|OIL LEAK	oilleak slew motor					18/10/2018 2865	Fault	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Body|DRAWBAR	left deck cracked inboard when walked on		re-weld up cracks up on the deck off the loader	re-weld up cracks up on the deck off the loader		18/10/2018 2865	Fault	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Albury - Workshop	Engine	cab dubbed from invoice					18/10/2018 0	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Albury Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle|JBS	Service Due	VehicleLoad|JBS				11/10/2018 2803	Service	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Body|DRAWBAR	tip on grab missing					11/10/2018 2803	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis|CHASSIS RACE	deck cracked LHS					11/10/2018 2803	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine|OIL LEAK	oilleak front of motor					11/10/2018 2803	Repair	Completed	GreenFreight Logging NSW	LOADSHEET	Rosewood	AUR	LIVERIS	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulic|DRAWBAR	replace joystick R/H/S					11

								cell out		cell out													
								replace broken bolt in cam pin on grab		replace broken bolt in cam pin on grab													
								drill and out broken bolt		drill and out broken bolt													
P29	Rosewood - Workshop	Hydraulics/ARM	bolt broken on grapple cam					replace bolt		replace bolt		05/07/2018 2286	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics/BRAKEDOWN	call out/breakdown									05/07/2018 2286	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle/cat/JB	Service Due				Vehicle/cat/JB					28/06/2018	Service	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Albury - Workshop	Hydraulics/HOSES	SUPPLY HOSE AS PER SAMPLE									27/06/2018	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	Engine/FUEL TANK	BROKE FUEL CONNECTOR MANIFOLD.					replace return line used second hand parts				21/06/2018 21540	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	Engine/FUEL FILTER	Service hydraulic oil									21/06/2018 21540	Service	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle/cat/JB	Service Due 6hrs									06/06/2018 2011	Service	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine/OIL LEAK	oil comp									06/06/2018 2011	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine/OIL LEAK	oil leaks									06/06/2018 2011	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine/MOUNTS	engine mounts									06/06/2018 2011	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle/cat/JB	8 Service Log Loader				Vehicle/cat/JB					06/06/2018 2011	Service	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
			repair engine bay door																				
P29	Rosewood - Workshop	DrillCabReq/ENG COVER	weld new bottom louvlure vent									02/06/2018 1984	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Air Con/AIR CON	tighten a/c belt									31/05/2018	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Elec/12VOLT P&W	replaced broken light bracket									24/05/2018 1860	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Elec/12VOLT P&W	replaced work light. Not working									24/05/2018 1860	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Elec/12VOLT P&W	required work has been sent thru Paul and Wayne 19/04									24/05/2018 1860	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics/VALVES	Rimrock lift, tripple pump, leg swivel valve, slew valve and grab swivel swapped back									24/05/2018 1860	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle/cat/JB	8 Service				Vehicle/cat/JB					24/05/2018 1860	Service	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
								coolant leak		coolant leak													
								found bottom radiator hose clamp broken		found bottom radiator hose clamp broken													
P29	Rosewood - Workshop	Cooling/COOLLEAKS	coolant leak bottom radiator hose					replaced clams and top up coolant		replaced clams and top up coolant		22/05/2018 1851	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Workshop/MOVEMENT	travel to Wyuna rd Cundooi (pick and travel)									22/05/2018 1851	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
			Return to Rosewood																				
P29	Rosewood - Workshop	Workshop/MOVEASSET	35kms									22/05/2018 1851	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine/MOUNTS	engine mount rubbers									27/04/2018 1603	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle/cat/JB	8 Service				Vehicle/cat/JB					26/04/2018 1595	Service	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
								grab oil leak		grab oil leak													
P29	Rosewood - Workshop	Hydraulics/OIL LEAK	oilleak in or around grab rotor getting oil over windscreen					arab swivel leakinal		arab swivel leakinal		20/04/2018 1550	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
								weld top double prong on grab		weld top double prong on grab													
P29	Rosewood - Workshop	Body/DAMAGE	end bolster off one side of grab prong leg keep falling out					swiss out grab swivel valve off PLS		swiss out grab swivel valve off PLS		20/04/2018 1550	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Albury - Workshop	Engine/MOUNTS	ENGINE MOUNT x/s									06/04/2018 1600	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis/CHASSTRACK	paint broken on double frame									04/04/2018 1600	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics/VALVES	slew control valve leaking (requires fitting)									04/04/2018 1600	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics/VALVES	leg swivel valve leaking (requires fitting)									04/04/2018 1600	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics/OIL LEAK	tripple pump leaking out input seal									04/04/2018 1600	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics/OIL LEAK	R/H main lift cylinder leaking									04/04/2018 1600	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
			requires orig. Mounts																				
P29	Rosewood - Workshop	Body/MOUNTS	u/80116102R									04/04/2018 1600	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle/cat/JB	Service Due				Vehicle/cat/JB					04/04/2018 1600	Service	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle/cat/JB	Service				Vehicle/cat/JB					04/04/2018 1600	Service	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics/HOSES	replace"90" fitting and hose					travel to panel crack pulled out ram to pull off hose and replace 90° fitting in ram test ok		travel to panel crack pulled out ram to pull off hose and replace 90° fitting in ram test ok		27/03/2018 1393	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Body/DAMAGE	grab and leg pin not getting grease by other operator									21/03/2018 1310	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Elec/12VOLT P&W	light in cab not working									21/03/2018 1310	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DrillCabReq/RADIO	AM-FM radio need one									21/03/2018 1310	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics/OIL LEAK	oilleak on rotor motor on grab somewhere									21/03/2018 1310	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics/VHD LEAKS	RHS main lift ram leaking seal									21/03/2018 1310	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis/CHASSTRACK	LHS deck cracked									21/03/2018 1310	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Albury - Workshop	Workshop	Job Added from Invoice									17/03/2018 0	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	Hydraulics/HOSES	SUPPLY HOSES									17/03/2018 1302	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Rosewood - Workshop	Body/MOUNTS	left rear buttress leg pin					replace broken leg pin		replace broken leg pin		13/03/2018 1192	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Albury - Workshop	Hydraulics/HOSES	REMOVE RUBBER HOSE BETWEEN MAIN AND OUTER BOOM.					OPERATOR BLEW HOSE ON SHIFT. TO LAZY TO FIT UP AND SECURE. DROPPED LOADER OF AND ASKED WORK		OPERATOR BLEW HOSE ON SHIFT. TO LAZY TO FIT UP AND SECURE. DROPPED LOADER OF AND ASKED WORKSHOP TO REMOVE BLOWN HOSE.		08/03/2018 1206	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	Vehicle/cat/JB	8 SERVICE DUE				Vehicle/cat/JB					08/03/2018 1206	Service	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
								CROSSED WIRE SET.		CROSSED WIRE SET.													
P29	Albury - Workshop	DrillCabReq/RADIO	RADIO DOES NOT WORK AM/FM																				
P29	Albury - Workshop	DrillCabReq/RADIO	AM FM RADIO NOT WORKING					Fit radio and interior light		Fit radio and interior light		07/03/2018 1192	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	DrillCabReq/RADIO	WIRES FOR RADIO HANGING OUT BEHIND SET. BEEN PULLED OUT.									07/03/2018 1192	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	Body/MOUNTS	RHF MOUNTING BOLT THAT HOLD LOADER ON IS LOOSE					try to tighten bolt had to cut welded nut apply heat to nut and tighten				02/03/2018	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	Engine/MANIFOLD	REPLACE MANIFOLD					replace exhaust elbow				02/03/2018	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	Engine/EXHAUST	REPLACE EXHAUST ELBOW AT REAR OF ENGINE.					Replace exhaust elbow				22/02/2018	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
			Loose washer on oil cooler					Check over radiator to try and find loose washer well catch up with operator tomorrow.		Check over radiator to try and find loose washer well catch up with operator tomorrow.													
P29	Rosewood - Workshop	Cooling/RADIATOR	Rubbing on core					Tightened frame around radiator.		Tightened frame around radiator.		20/02/2018 1054	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
								repair engine bay cover		repair engine bay cover													
P29	Albury - Workshop	Body/PANELS	ENGINE BAY COVER NEEDS REPAIR					weld broken tee on tower		weld broken tee on tower		15/02/2018 11022	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
								remove elbow (damaged) from exhaust		remove elbow (damaged) from exhaust													
								tighten bolts on radiator/cooler		tighten bolts on radiator/cooler													
P29	Albury - Workshop	Vehicle/cat/JB	8 SERVICE				Vehicle/cat/JB	blow out radiator		blow out radiator		15/02/2018 11022	Service	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
			leaking grab ram																				
			remove leaking cylinder																				
			TV/cb																				
P29	Rosewood - Workshop	Hydraulics/VHD LEAKS	test ok									09/02/2018 994	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Albury - Workshop	Hydraulics/VHD LEAKS	change grapple cylinder									09/02/2018 994	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
								weld lock tab on grab pin		weld lock tab on grab pin													
P29	Albury - Workshop	Body/MOUNTS	tab on grapple cam					weld new tab on arab		weld new tab on arab		19/01/2018 826	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
			8 SERVICE																				
P29	Albury - Workshop	Vehicle/cat/JB	Water coolant leak				Vehicle/cat/JB					18/01/2018 810	Service	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	Hydraulics/SCALES	SCALES NOT WORKING					BLEED SCALES		BLEED SCALES		11/01/2018 755	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
								REPAIR TIPS ON GRAB.		REPAIR TIPS ON GRAB.													
								REPAIRED BY RDB TOPPIN.		REPAIRED BY RDB TOPPIN.													
P29	Albury - Workshop	Body/HOUSINGS	tips on grab to sharp					Replaced bac on arab.		Replaced bac on arab.		11/01/2018 755	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	Chassis/HOUSINGS	TIPS ON GRAB.					AS PER 116668		AS PER 116668		11/01/2018 755	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	Chassis/HOUSINGS	TIPS ON GRAB.SAMA WELDS LOOS					AS PER 116668		AS PER 116668		11/01/2018 755	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	Body/PANELS	replace tips on grab									11/01/2018 755	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
								REPOWER AUTO ELECT REPAIRED RELAY BASE.		REPOWER AUTO ELECT REPAIRED RELAY BASE.													
								Repower auto elect.		Repower auto elect.													
								Check & test alt + aides. Replaced base. Replay.		Check & test alt + aides. Replaced base. Replay.													
P29	Albury - Workshop	Air Con/AIR CON	AIR CON NOT WORKING					Check & test alt + aides		Check & test alt + aides		09/01/2018 767	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics/OIL LEAK	hydraulic oil l on grab					hydraulic oil leak - tighten hose fittings grab		hydraulic oil leak - tighten hose fittings grab		05/01/2018	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis/HOUSINGS	replace missing bolt on R/R leg foot. replace missing bolt on R/L leg foot					chassis housekeeping - replaced missing bolt in leg foot R/R		chassis housekeeping - replaced missing bolt in leg foot R/R		05/01/2018	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Body/BRAKEDOWN	call out/breakdown									03/01/2018	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
			travel to pisces/crk. From tumut																				
			replace grab hose																				
P29	Rosewood - Workshop	Body/HOSES	return to Tumba									03/01/2018	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
			check power to scale unit																				
			remove dash and check wiring. Replaced power source																				
			test ok																				
P29	Rosewood - Workshop	Elec/12VOLT P&W	refit dash									14/12/2017 595	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Albury - Workshop	Hydraulics/HOSES	SUPPLY HYD. HOSES									15/12/2017 595	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	DrillCabReq/SWITCHLIGHT	REPLACE IGNITION SWITCH					rewired and replaced switch		rewired and replaced switch		14/12/2017 595	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	DrillCabReq/RADIO	REPAIR UHF UNIT.					diamond mcomo centre am in boat. Ordered replacement. Reasond for temoval:rx use. Reasoned mounts. re				14/12/2017 595	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	Vehicle/cat/JB	8 SERVICE				Vehicle/cat/JB					14/12/2017 595	Service	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	DrillCabReq/DOOR LOCK	replace key barrel									14/12/2017 595	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Rosewood - Workshop	Body/HOUSINGS	gauge console delete cut pumped up with stick					repair dash console		repair dash console		12/12/2017 582	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Body/HOUSINGS	tips on grab to sharp									02/12/2017	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Elec/12VOLT P&W	cable need cut					replace transducer fitting and bleed		replace transducer fitting and bleed		02/12/2017	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DrillCabReq/INSTGAUGE	amp guage flickering up and down					requires volt guage requires replacing				02/12/2017	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Albury - Workshop	Engine/EXHAUST	REPLACE MUFFLER CAP ON EXHAUST									30/11/2017 554	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	Engine/BELTS/TENS	REPLACED TENSIONER AND BELT									22/11/2017 633	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	Engine/FUEL TANK	Fuel tank leaking - fuel cut valve									22/11/2017	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	TURKIT HYDRAULIC SERVICES - 6 - CLCD	PRENTICE
P29	Rosewood - Workshop	Hydraulics/HOSES	Hydraulic Hose					6 x Hydraulic Hoses.				18/11/2017	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	TURKIT HYDRAULIC SERVICES - 6	PRENTICE
P29	Albury - Workshop	DrillCabReq/RADIO	UHF doesn't pick up very good only picks up over very short distances wasnt then truck					AS PER ATTACHED INVOICE		Completed		18/11/2017 603	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	DrillCabReq/RADIO	only short distance remote on UHF							Completed		18/11/2017 603	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	Elec/ALT/ DR	REPLACE ALTERNATOR									18/11/2017 603	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
								test & check alternator															
P29	Rosewood - Workshop	Drivetrain/ALT	check alternator guage up and down too on grab to sharp need new tips					clean out radiator blocked				16/11/2017 600	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DrillCabReq/RADIO	pin fm radio need putting in properly									16/11/2017 600	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehicle/cat/JB	8 Service				Vehicle/cat/JB					12/11/2017 610	Service	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
								REPLACED MISSING BOLTS IN COVER															
P29	Albury - Workshop	Body/HOUSINGS	REPLACE BOLTS ON COVER FOR RADIATOR AND OIL COOLER					replaced missing bolts out of radiator/cooler assist		REPLACED MISSING BOLTS IN COVER		31/10/2017 330	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics/HOSES	hose has hole in main lift ram cnsidle over lift hose hose rect to it					replace 3 hydraulic hoses		replace 3 hydraulic hoses		07/09/2017 200	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics/HOSES	Replace pressure hoses									07/09/2017	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Tumut - Workshop	Body/DYNAMOMS	Repair broken pin in main lift cylinders of prentice log loader crane									05/09/2017	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Tumut Workshop	PRENTICE
P29	Tumut - Workshop	Engine/FILTERS	lube filter					Swin city - 685110				25/08/2017	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Tumut Workshop	PRENTICE
P29	Tumut - Workshop	Engine/BELTS/TENS	fan belt broken									25/08/2017	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Tumut Workshop	PRENTICE
P29	Tumut - Workshop	Engine/FUEL TANK	header tank split									23/08/2017	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Tumut Workshop	PRENTICE
P29	Tumut - Workshop	Engine/COOLLEAKS	needs socket									23/08/2017	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Tumut Workshop	PRENTICE
P29	Tumut - Workshop	Engine/FILTERS	lube filters.					Twincity - 682219				01/08/2017	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Tumut Workshop	PRENTICE
P29	Tumut - Workshop	Hydraulics/MOTOR	REPLACE SWING PINION GEAR									25/07/2017	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Tumut Workshop	PRENTICE
P29	Tumut - Workshop	Elec/12VOLT P&W	TRAVELLED TO SITE. CHECKED LOADER OPERATION NO FAULT FOUND REMOVED DASH PANELS. CHECKED IGNITION SWITCH WIRING. CHECKED OVER CHASSIS HARNESS. CHECKED MAIN CONNECTORS. CHECKED ENGINE HARNESS. FOUND AND REPAIRED. FAULTY CONNECTION AT CONNECTOR IN ENGINE HARNESS. TESTED. RIGHT PANS					AS PER INVOICE - SS172209				24/06/2017	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Tumut Workshop	PRENTICE
P29	Tumut - Workshop	Engine/MOUNTS	engine mounts									23/06/2017 6690	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Tumut Workshop	PRENTICE
P29	Tumut - Workshop	DrillCabReq/RADIO	only short distance remote on UHF									23/06/2017 6690	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Tumut Workshop	PRENTICE
P29	Tumut - Workshop	Engine/AIR CONR	REPLACE MISSING AIR CLEANER CAP.									19/05/2017	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Tumut Workshop	PRENTICE
P29	Tumut - Workshop	Air Con/AIR CON	aircondition not working									19/05/2017 6608	Fault	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Tumut Workshop	PRENTICE
								REMOVED COOLER FROM PCO.															
P29	Albury - Workshop	Hydraulics/OIL LEAK	HYDRAULIC COOLER LEAKING AGAIN					SENT IT TO ALDRIDGE AND TO HAVE IT MODIFIED TO FIT. REQUIRED PIPE EXTENSIONS MADE TO SUIT.				09/05/2017	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	Engine/FAULT CODE	ENGINE FAULT CODE.					AS PER ATTACHED INVOICE.				21/04/2017 9824	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
P29	Albury - Workshop	Hydraulics/HOSES	SUPPLY HYDRAULIC HOSE									08/04/2017	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
			washed leaking oil cooler																				
			removed excess internal oil																				
P29	Albury - Workshop	Engine/OIL LEAK	diseased oil at Wodonga enviromental for repair									06/04/2017	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Albury	AUR	UNREG	Albury Workshop	PRENTICE
			pull out oil cooler																				
P29	Rosewood - Workshop	Workshop/BETA MAINT	wash down loader									05/04/2017 9249	Repair	Completed	Green Freight Logging NSW	LOADPRINT	Rosewood	AUR	UNREG	Rosewood Workshop	PRENTICE
P29	Albury - Workshop	Engine/BELTS/TENS	REPLACE FAN BELTS									24/03/2017	Repair	Completed	Green Freight Log

							manufacture eng cover												
P29	Albury - Workshop	Body\WO\5588309	Engine cavert missing				repaired broken bonnet sections		22/09/2016 8020	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Albury Workshop	PRENTICE
P29	Albury - Workshop	Body\WO\5675	Prentice mount bolts loose				Tightened bolts		15/09/2016 8020	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Albury Workshop	PRENTICE
P29	Rosewood - Workshop	Vehiservice\JBL	Service As Per Attached Checklist		Vehiservice\JBL				16/09/2016 7200	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine\YE7595	replace engine oil filter						17/09/2016	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehiservice\JBL	Service As Per Attached Checklist		Vehiservice\JBL				12/09/2016 7739	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DIC\ARM\VIXEN RBF	remove repair heater fan assembly				Turned auto electrics completed repairs		29/07/2016	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Body	single prong on grab tip broken off						24/07/2016	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Body	double prong to sharp damaging logs						24/07/2016	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DIC\ARM\p	UHF doesn't pick up very good						24/07/2016	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehiservice\JBL	Service As Per Attached Checklist		Vehiservice\JBL				23/07/2016	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehiservice	service due 47611						11/07/2016 7611	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Body	grab need tips attendant to						12/07/2016 7611	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics	loader & Replace hydraulic return change pilot filter drain & replaced all hydraulic oil						05/07/2016 7216	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics	hydraulics clog working						02/07/2016	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Body	grabsaat loader						26/06/2016	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehiservice	service due						08/06/2016 7195	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Elec\	repair buzzin light wiring						31/05/2016	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehiservice\JBL	Service As Per Attached Checklist		Vehiservice\JBL				08/05/2016 6892	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehiservice\JBL	Service As Per Attached Checklist		Vehiservice\JBL				26/04/2016 6798	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Albury - Workshop	Vehiservice	service due in 215ml.				service was completed 23/04/2016 @ 6798 HRS		service was completed 23/04/2016 @ 6798 HRS	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Albury Workshop	PRENTICE
P29	Rosewood - Workshop	Elec\TAYORK LIGHT	boom light not working						15/04/2016 6699	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Elec\TAYORK LIGHT	RHS outer boom light hooked up wrong way						13/04/2016 6699	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics\226.1AM	grease line 6 on slew has hole in						09/04/2016 6623	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine\YE7595	b service						30/03/2016	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehiservice\JBL	Service As Per Attached Checklist		Vehiservice\JBL				25/03/2016 6103	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics\HO565	repair leaking hyd hose to valve bank						10/03/2016 6404	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics\HO565	repair hydraulic hose to pump						09/03/2016	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics\HYD 130KS	repair hydraulics leak						09/03/2016	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics	replace grease line to slew leaking						29/02/2016	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehiservice\JBL	Service As Per Attached Checklist		Vehiservice\JBL				18/02/2016 6217	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine\YE7595	b service						18/02/2016	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Elec\	scale not working hose brom no oil						12/02/2016 6176	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehiservice\JBL	Service As Per Attached Checklist		Vehiservice\JBL				26/01/2016 6000	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics\226.1TILTER	replace hydraulic oil / replace hyd filters						26/01/2016 6000	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics\226.1AM	grease pipe for slew bearing has hole in pipe not greasing bearing needs repairing						19/01/2016	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
			engine filter																
P29	Tumut - Workshop	Engine\YE7595	b service				completed		26/12/2015	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Tumut Workshop	PRENTICE
			aricon fan																
P29	Tumut - Workshop	Air Con\AIR CON	fan				COMPLETED		29/12/2015	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Tumut Workshop	PRENTICE
P29	Rosewood - Workshop	Vehiservice\JBL	Service As Per Attached Checklist		Vehiservice\JBL				20/12/2015 5860	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Body	job created to register W&R						20/12/2015 5860	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
			repair scale display																
P29	Tumut - Workshop	Elec\DAVCT P&W	aricon				completed		15/12/2015	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Tumut Workshop	PRENTICE
P29	Tumut - Workshop	Engine\YE7595	filters				COMPLETED		05/12/2015	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Tumut Workshop	PRENTICE
			grab hoses																
P29	Tumut - Workshop	Hydraulics\HO565	tumut hyd				completed		03/12/2015	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Tumut Workshop	PRENTICE
P29	Rosewood - Workshop	Hydraulics\226.1AM	bad oil leak slew					Completed	02/12/2015 5675	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehiservice\JBL	Service As Per Attached Checklist		Vehiservice\JBL				29/11/2015 5654	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Elec\	scales not working					Completed	27/11/2015	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Body	tip on grab missing					Completed	27/11/2015	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Body\WIPERS	windscreen wiper not working						27/11/2015 5860	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DIC\ARM\TAKEKO	UHF not picking up very good						27/11/2015 5660	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Elec\DAVCT P&W	scales not working						20/11/2015	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
			tumut																
P29	Tumut - Workshop	Engine\YE7595	b&c				completed		19/10/2015	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Tumut Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis	grab tine sharp badly damaging logs						21/10/2015	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DIC\ARM\p\WIPERS	windscreen wiper not working						21/10/2015	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehiservice\JBL	Service As Per Attached Checklist		Vehiservice\JBL				18/10/2015 5266	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Myrtleford - Workshop	Vehiservice\JBL	oil filter		Vehiservice\JBL		completed		14/10/2015	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Elec\DAVCT P&W	switch				completed		14/10/2015	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Myrtleford Workshop	PRENTICE
P29	Myrtleford - Workshop	Engine\MERCEDES MOB	boom hoses - tumut hyd				completed		14/10/2015	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Myrtleford Workshop	PRENTICE
P29	Rosewood - Workshop	DIC\ARM\p\WIPERS	wiper not working						14/10/2015 5187	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Chassis	single prong on grab needs grinding to sharp						13/10/2015 5187	Fault	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehiservice\JBL	Job Added From Invoice		Vehiservice\JBL				02/10/2015 0	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	DIC\ARM\JOANNE	Job Added From Invoice						01/10/2015 0	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine\ENG TUNE	Job Added From Invoice						29/09/2015 0	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Engine\ENG TUNE	Job Added From Invoice						29/09/2015 0	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Tumut - Workshop	Body\DARRAGH	Service Job Added From Invoice						08/09/2015 0	Repair	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Tumut Workshop	PRENTICE
P29	Rosewood - Workshop	Vehiservice\JBL	Service As Per Attached Checklist		Vehiservice\JBL				03/09/2015 5052	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE
P29	Rosewood - Workshop	Vehiservice\JBL	Vehiservice\JBL		Vehiservice\JBL				02/09/2015 1	Service	Completed	GreenFreight Logging NSW	LOADSPRINT	Rosewood	AUR	LN8931	Rosewood Workshop	PRENTICE